



# Inspection of Old Retaining Walls

**Dan Eschenasy P.E. F.SEI**  
**Department Chief Structural Engineer**



# CONDITION ASSEMENT -Objectives

---

- Classification of retaining walls.
- Basic elements of a visual inspection of a retaining wall.
- Issues related to the assessment of old masonry retaining walls.

# Older Building Codes - Retaining Wall

---

- A wall designed to prevent the lateral displacement of soil or other materials
- Too Broad
  - Basement Walls
  - Tunnel Walls
  - Pools

# Short History

---

- The early building codes used the term – retaining wall – mainly to refer to basement walls.
- 1915 Building Code used the term closer to present day meaning and also required to be designed for water pressure.
- There was no significant requirement or reference to retaining walls in the 1938 Code –
- The 1968 code introduced the factor of safety of 1.5 for overturning.



## 2014 Code Definition

---

- **RETAINING WALL.** A wall that resists lateral or other forces caused by soil, rock, water or other materials, thereby limiting lateral displacement and the movement of the supported materials. Basement walls and vault walls that are parts of buildings and underground structures, including but not limited to utility vault structures, tunnels and transit stations, are not considered retaining walls.

# What Height?

---



# Supporting Roads or Building Lots

---





# NAVFAC CLASSIFICATION

---

- Gravity
- Semigravity
- Flexible
- Counterfort

# Gravity Walls

---

- Gravity walls resist overturning and sliding by the weight of the wall itself. These walls are usually constructed of solid concrete or rock rubble mortared together. These walls are not usually reinforced with steel since the massive nature of these walls develops little or no tension in the mass. Gravity walls are seldom constructed any more...
- The vast majority of retaining walls were gravity walls.

# Fill Wall


---

- Earth retaining structure supporting **specified soil or aggregate backfill**. Fill walls are typically located below roadway grade on the outboard side of the roadway or parking area, but may also exist above travelway grade in locations commonly associated with cut walls.
- Were there “specifications” for the backfill of the old wall.
- Were they compacted or thrown down?



# Causes Unsatisfactory Retaining Walls

43% backfill clay  
on foundation clay



b. Foundation and backfill material of unsatisfactory retaining walls (Ireland 1964)

From EM-1110-2

# Cut Walls

---



- Earth retaining structure directly supporting natural ground; either constructed directly against the excavated soil/rock mass, or against a minor volume of drainage backfill.

# Cut Walls

---


Cut walls are constructed in areas where the finished grade will be substantially below existing grade. Cut walls are constructed with a top down construction sequence, which eliminates the need for temporary shoring...





# Tiedback Walls or Deadman Anchored Walls

Bars or cables which pass through the face of the wall which are anchored to a large object buried behind the wall referred to as a "deadman, " which is usually either concrete or sheet piling. The force holding the wall back is generated by passive soil pressures acting on the deadman. The deadman must be located far enough behind the wall so that the active failure zone and the passive resistance wedge in front of the deadman do not overlap.




When excavating on top – protect deadmen and cables !

# Waterfront Structures – retain or protect

---

## Old Bulkhead on Hudson Sea Wall




# Revetment – retains fill



## Riprap


Is this a wall?





# Is this a retaining wall?

---





# Dry Retaining Wall –no mortar

---



# Rockery Installation

---



[http://flh.fhwa.dot.gov/innovation/td/geotech/rockeries/documents/09\\_Chapter\\_6\\_Construction\\_Inspection.pdf](http://flh.fhwa.dot.gov/innovation/td/geotech/rockeries/documents/09_Chapter_6_Construction_Inspection.pdf)



# Mortared Retaining Wall – Rubble Masonry

---





????? Ashlar it is a veneer


---





# Bearing Masonry Construction Requires Headers

---



????

---



# Rubble wall

---





# WIP – Wall Types

Publication No.  
FHWA-CFL/TD-10-003


RETAINING WALL INVENTORY AND  
CONDITION ASSESSMENT PROGRAM (WIP)  
National Park Service Procedures Manual

Wall Function Codes		
[FW] Fill Wall	[CW] Cut Wall	
[BW] Bridge Wall	[SW] Switchback Wall	[HW] Head Wall
		[SP] Slope Protection
		[FL] Flood Wall
Wall Type Codes		
[AH] Anchor, Tieback H-Pile	[CC] Crib, Concrete	[MG] MSE, Geosynthetic Wrapped Face
[AM] Anchor, Micropile	[CM] Crib, Metal	[MP] MSE, Precast Panel
[AS] Anchor, Tieback Sheet Pile	[CT] Crib, Timber	[MS] MSE, Segmental Block
[BC] Bin, Concrete	[GB] Gravity, Concrete Block/ Brick	[MW] MSE, Welded Wire Face
[BM] Bin, Metal	[GC] Gravity, Mass Concrete	[SN] Soil Nail
[CL] Cantilever, Concrete	[GD] Gravity, Dry Stone	[TP] Tangent/ Secant Pile
[CP] Cantilever, Soldier Pile	[GG] Gravity, Gabion	[OT] Other, User Defined
[CS] Cantilever, Sheet Pile	[GM] Gravity, Mortared Stone	[NO] None
Architectural Facing Type Codes		
[BV] Brick Veneer	[PF] Planted Face	[SS] Simulated Stone
[CO] Cementitious Overlay	[SC] Sculpted Shotcrete	[SV] Stone Veneer
[FF] Fractured Fin Concrete	[SH] Shotcrete (nozzle finish)	[TI] Timber
[FL] Formlined Concrete	[SM] Steel/Metal	[OT] Other, User Defined
[PC] Plain Concrete (float finish or light texture)	[SO] Stone	[NO] None

# WIP Design Criteria

---

The engineer should be knowledgeable of AASHTO wall design standards and *aware of historic construction practices and workmanship sufficient to select from one of the following levels of applied design criteria:*

- *None: Does not meet any known design standards or systematic construction methods commonly used at the time of construction;*
  - *Non-AASHTO: Does not meet AASHTO design standards , but is consistent with other structures of its type and period of construction exhibiting established construction workmanship and good performance; or*
  - *AASHTO: Appears to meet AASHTO geometric, design, materials, and construction*
- 



# WIP Consequence of Failure – NOT NYC

---

- Low – No loss of roadway, no to low public risk, no impact to traffic during wall repair/replacement
- Moderate – Hourly to short-term closure of roadway low-to-moderate public risk, multiple alternate routes available
- High – Seasonal to long-term loss of roadway, substantial loss-of-life risk, no alternate routes available.


# WIP Data Reliability – NOT NYC

---


- Estimate **of how well observed conditions** represent wall performance and if additional investigations may be warranted.
  - **1-Poor Conditions cannot be sufficiently observed to rate element(s)**, warranting additional investigations to better define element performances and/or to determine the cause(s) or poor performance.
  - 2-Good Observed conditions are sufficient to rate the conditions of wall element(s); however, additional investigations would be useful to better understand element performance.
  - 3-Very Good Observed conditions clearly describe wall performance. Additional investigations are not needed.

# Castle Village

---



# Wall Displacement –Castle Village




Displacement evolution in time of several points of wall on same vertical.

**EVERY MONITORING NEEDS PREESTABLISHED ACTION PLANS**






*Figure 1*  
The above drawing represents a cross section of the Castle Village retaining wall after construction.



*Figure 2*  
The darker outline in this drawing shows how the Castle Village retaining wall had moved and the deformed shape it had taken in the months prior to its collapse.



*Figure 3*  
This drawing shows the lower portion of the wall once the bulging front face has been removed and illustrates how the wall was in imminent danger of collapse without that support.

## Important lessons

---

- Monitoring has to have a plan that include limits that will trigger immediate protective actions.
- Call 311 in case of emergencies

# Sections through wall

---



# Back of Face Wythe



---





# Method of Construction


---



New layer backfill.  
Compacted?  
Dropped?  
Engaging  
headers?

Backfill is dry to support construction operation. Less pressure originally.

# Collapse after Noreaster ( water from the top)





# Gabion vs Placed Stone

---



# Slope Failure After Sandy ( water at base)

---






# General Burgoyne's Experiments 1853


Dry walls with same volume of stone.

Walls type C & D collapsed at 15 ft


Type A – INCLINED WALL & FACE BATTER MOST STABLE




A. Learning Wall  
Opposite Sides Equal & Parallel  
Lean or Slope 1/5 of Height




B. Sloping Wall  
Slope in front 1/5 of Height




C. Counter Sloping Wall  
Slope in Rear 1/5 of Height



The form the counter sloping wall assumed when falling



D. Rectangular Wall



The form the rectangular wall assumed when falling

# Empirical Methods –English Rule

---

- **547 English Rule.** “Experience has shown that a wall [to sustain earth having a level top surface], whose thickness is one fourth of its height, and which batters 1 or 2 inches per foot on the face, possesses sufficient stability when the backing and foundation are both favorable. This allows a factor of safety of about two to cover contingencies. It has also been proved by experience that under no ordinary conditions of surcharge or heavy backing is it necessary to make a retaining wall on a solid foundation more than double the above, or one half of the height in thickness. Within these limits the engineer must vary the strength according to the conditions affecting the particular case. Outside of these limits, the structure ceases to be a retaining wall in the ordinary acceptance of the term. ....the thickness of retaining walls in ground of an average character equal to one third of the height from the top of the footings.


# Empirical Methods - Trautwine Proportions

Retaining-Walls 261

**Table III. Proportions of Retaining-Walls**  
(Thickness of wall at the base in parts of the height, *AB*, Fig. 16)

Total height of the earth compared with the height of the wall above ground	Wall of cut stone in mortar	Wall of rubble or brick, good mortar	Wall of good, dry rubble
1'	0.35	0.40	0.50
1.1	0.42	0.47	0.57
1.2	0.46	0.51	0.61
1.3	0.49	0.54	0.64
1.4	0.51	0.56	0.66
1.5	0.52	0.57	0.67
1.6	0.54	0.59	0.69
1.7	0.55	0.60	0.70
1.8	0.56	0.61	0.71
2	0.58	0.63	0.73
2.5	0.60	0.65	0.75
3	0.62	0.67	0.77
4	0.63	0.68	0.78
6	0.64	0.69	0.79
14	0.65	0.70	0.80
25	0.66	0.71	0.81
or more	0.68	0.73	0.83


# Engineering calculations based on theories





# Graphic Analysis

---



# Historic Data

- Coef. Friction
- Angle of Repose
- Allowable Pressure
  - foundation
  - masonry

COEFFICIENTS OF FRICTION.

Materials.	Coefficients.	Materials.	Coefficients.
Dry masonry on dry masonry.....	0.6 to 0.7	Masonry on dry clay.....	0.5 to 0.6
Masonry on masonry with wet mortar.....	0.75	Masonry on moist clay.....	0.33
Timber on stone.....	0.4	Earth on earth.....	0.25 to 1.0
Iron on stone.....	0.3 to 0.7	Hard brick on hard brick.....	0.7
Timber on timber.....	0.2 to 0.5	Concrete blocks on concrete blocks.....	0.65

TABLE II.  
ANGLES OF REPOSE,  $\phi$ , FOR MATERIALS.

Materials.	$\phi$	Materials.	$\phi$
Earth, loam.....	30° to 45°	Clay.....	25° to 45°
Sand, dry.....	25° to 35°	Gravel.....	30° to 40°
Sand, moist.....	30° to 45°	Cinders.....	25° to 40°
Sand, wet.....	15° to 30°	Coke.....	30° to 45°

TABLE III.  
ALLOWABLE PRESSURE ON FOUNDATIONS.

Material.	Pressure in Tons per Sq. Ft.
Soft clay.....	1 to 2
Ordinary clay and dry sand mixed with clay.....	2 to 3
Dry sand and clay.....	3 to 4
Hard clay and firm, coarse sand.....	4 to 6
Firm, coarse sand and gravel.....	6 to 8
Bed rock.....	15 and up.



TABLE IV.  
ALLOWABLE PRESSURE ON MASONRY.

Materials.	Pressure in Tons per Sq. Ft.
Common brick, Portland cement mortar.....	12
Paving brick, Portland cement mortar.....	15
Rubble masonry, Portland cement mortar.....	12
Sandstone, first class masonry.....	20
Limestone, first class masonry.....	25
Granite, first class masonry.....	30
Portland cement concrete, 1-2-4.....	25
Portland cement concrete, 1-3-6.....	20

# Old Drainage Systems –

---

Influence of water pressure on failures has been recognized at least since 1900.



# Present Day Theories

---

## **Rankine Theory**

The Rankine Theory is based on the assumptions that the wall introduces no changes in the shearing stresses at the surface of contact between the wall and the soil. It is also assumed that the ground surface is a straight line (horizontal or sloping surface) and that a plane failure surface develops.


## **Coulomb Theory**

An inherent assumption of the Rankine Theory is that the presence of the wall does not affect the shearing stresses at the surface of wall contact. However, since the friction between the retaining wall and the soil has a significant effect on the vertical shear stresses in the soil, the lateral stresses on the wall are actually different than those assumed by the Rankine Theory. Most of this error can be avoided by using the Coulomb Theory, which considers the changes in tangential stress along the contact surface due to wall friction.




# Bursting or Bulging

---



# Shear Displacement along the Bed


---



# Buckling Under Compression

---

- FACE OF STONE MIGHT SEPARATE –largest compression is on exterior wall







# Plane of sliding

---

- Sliding is not possible




- Rotation of stones and movement creates a plane where sliding is possible




# Improper Place Triangular Stones Under Compression

---

AT FACE -  
DISLODGES




INTERIOR STONE  
BULGES



# Resistance to sliding – friction ++

---



# Failures Modes of Retaining Walls

---

- Sliding
- Rotating
- Crushing
- General Sliding of the Soil



# Possible Modes Sliding Failures

---

- Sliding along a slip surface that cuts through the wall.
- Sliding along a slip surface that runs behind and beneath the wall.
- Sliding along the base of the wall.

# Sliding at base – visuals

---

**Sliding** failure is a failure at the soil at the base.

**Buckling or swelling of soil at the bottom** of RW usually accompanies it.

In some cases there is a **separation of soil at top of the wall**.

Sliding of portions of the wall will be accompanied by **warping of the RW face**.

Note that sliding can occur also by rupture of surface of the bottom of the wall itself.

# Rotation - Collapse by overturning - Visuals.

---


**Rotation** of the RW could occur inward or outward as the wall is overcome by passive or active earth pressure. Bearing failure of the underlying soil usually precedes it.

- **OUTWARD** rotation is preceded and accompanied by **sink holes and tensions cracks at the top of the wall**. At the bottom of the wall one could observe **swelling and sloping towards the wall**.
- **INWARD** rotation could be accompanied also by **swelling at top of RW**. Observation of the alignment of the top of the wall can indicate rotation of wall segments. It will also allow clarify any confusion between walls built with batter or walls inclined inward.

# General Failure & Loss of Stability

---


- **General loss of stability** describes a failure where the general area that includes soil and retaining wall fails. It is very much similar to a loss of slope stability



Heaving at base /  
Settlement on top



# Unsatisfactory Behavior



Progressive outward

# Crushing

---

**Crushing** is a traditional terms for RW failure that covers failure of RW **structural components** due to stresses exceeding the carrying capacity. Such failures could be the result

- of design errors,
- stresses due to loads greater then those considered at design time
- or reduction of the carrying capacity of the RW caused by aging,
- exposure to corrosive atmosphere, etc.

Increase in loads can be due to

- unexpected water accumulation behind the wall,
- traffic and vibrations from traffic,
- undesired pressure from improper backfill -especially clay.

# Crushing

---

Reduction in bearing capacity can be the result of

- loss or separation of interlock,
- loss of mortar,
- corrosion of cables of anchors,
- corrosion of reinforcement.

Many of the distress symptoms such as cracking are the same as to those of concrete, masonry and stone building walls or facades.


Gravity walls fail usually in shear –horizontal or vertical. Observation of cracks on the face of RWs can often indicate the type of crushing.

Note that rotations of anchored RWs are often preceded by punching or cracks around the area of the anchor attachment to the stem.

# Settlement (Wall Dropping) Reverses Friction

---

Resultant may change direction





# Slope Failure after Rush Flood

---





# Slope Failure

---



# Slope Failures

---

## Water Related Causes

- Intense rainfall
- Perched water table
- Rapid draw-down
- Flood
- Extreme infiltration
- Seepage

## Geological Causes

- Erosion
- Weathered materials
- Weak materials
- Contrast in permeability
- Contrast in stiffness

# Slope Failures Human Causes


---

- Excavation of slope at it's toe
- Loading of slope at it's crest
- Irrigation
- Deforestation
- Artificial vibration (blasting, piling, etc.)
- Water leakage from utilities



# Causes Unsatisfactory Retaining Walls

33% missing or inadequate drainage systems



a. Causes of failure of rigid concrete retaining walls (Techeng and Iseux 1972)

From EM-1110-2

## Inspection Instructions for Rockeries

---

- Each rock is in contact with at least two rocks below it.
- The first contact point between an upper rock and a lower rock is located within 150 mm (6 in) of the face of the rockery.
- There are no “columns” of rocks; i.e., no continuous vertical seams exist.
- There are no continuous horizontal planes in the rockery.
- Rocks are inclined back into the slope.
- Rocks are free of obvious signs of distress, including significant weathering, fracturing, or disintegration.

[http://flh.fhwa.dot.gov/innovation/td/geotech/rockeries/documents/09\\_Chapter\\_6\\_Construction\\_Inspection.pdf](http://flh.fhwa.dot.gov/innovation/td/geotech/rockeries/documents/09_Chapter_6_Construction_Inspection.pdf)

# Inspection Instructions for Rockeries

---

- All voids greater than 150 mm (6 in) are chinked.
- Chink rocks, where present, cannot be removed by hand.
- There are no loose cap rocks or rocks that can otherwise be moved by hand.
- There is no soil spalling or piping through the voids in the face of the rockery.
- Base rocks are larger than upper rocks






# Limitations of the Visual Inspection of Retaining Walls

---

- When the RW has a **veneer**, in most cases the condition of the backup cannot be observed. On the positive side experience shows that usually veneers deteriorate faster than the backups.
- Many RWs were built on plies. (The literature shows that even rubble RW's could have been placed on pile foundations). The presence or condition of piles cannot be observed.

# Backfill & Foundation Materials



# Vegetation

---

Hides condition RW



Actually deteriorates RW




# Wall thickness? Fill?

---







# Various accidents

---





# More

---





# Effect of Vegetation


---





# Mortar Condition

---



# Cracks

---





# Wall Movement - Corner Condition

---





# Crest symptoms


---





# Crest symptoms

---



# Tension Cracks

---





# Stone Fragments at Base of Wall

---



# SINKHOLES

---





# Out of Plumb

---



# Bulging

---





# Irregularities at coping level

---



# Stone Spalling

---





# Stone Masonry RW - Form Rapid Assessment

<input type="checkbox"/> Rubble	<input type="checkbox"/> Coursed	<input type="checkbox"/> Random	<input type="checkbox"/> Rough	<input type="checkbox"/> Dry [no mortar]
<input type="checkbox"/> Cutstone	<input type="checkbox"/> Coursed	<input type="checkbox"/> Random	<input type="checkbox"/> Rough	<input type="checkbox"/> Dry [no mortar]
<input type="checkbox"/> Counterfort	<input type="checkbox"/> Don't Know	<input type="checkbox"/> No	<input type="checkbox"/> Yes	
<input type="checkbox"/> Buttressed [w. piers]				
<input type="checkbox"/> Tiedback [anchored] wall	<input type="checkbox"/> Rock Anchor		<input type="checkbox"/> Deadman	
<input type="checkbox"/> RW on piles	<input type="checkbox"/> Don't Know	<input type="checkbox"/> No	<input type="checkbox"/> Yes	
<input type="checkbox"/> RW foundation on soil type	_____	<input type="checkbox"/> Don't Know		

EXAMPLE

# I. Structural Condition Assessment continued...

EXAMPLE

<input type="checkbox"/> CMU Retaining Wall			
<input type="checkbox"/> Brick Retaining Wall			
<input type="checkbox"/> Veneers on Concrete	<input type="checkbox"/> Ashlar	<input type="checkbox"/> Brick	<input checked="" type="checkbox"/> CMU
<input type="checkbox"/> Ashlar Veneer on Rubble			
<input type="checkbox"/> Veneer on Natural Rock			
<input type="checkbox"/> Counterfort	<input type="checkbox"/> Don't Know	<input type="checkbox"/> No	<input type="checkbox"/> Yes
<input type="checkbox"/> Buttressed [w. piers]			
<input type="checkbox"/> Tiedback [anchored] wall	<input type="checkbox"/> Rock Anchor	<input type="checkbox"/> Deadman	
<input type="checkbox"/> RW on piles	<input type="checkbox"/> Don't Know	<input type="checkbox"/> No	<input type="checkbox"/> Yes
<input type="checkbox"/> Steel Reinforced	<input type="checkbox"/> Don't Know	<input type="checkbox"/> No	<input type="checkbox"/> Yes
<input type="checkbox"/> RW foundation on soil type	_____	<input type="checkbox"/> Don't Know	
<b>During the course of the Visual Inspection, the condition of the back-up structure was:</b>			
<input type="checkbox"/> Reliably Assessed <input type="checkbox"/> Partially Assessed <input type="checkbox"/> Not Assessed			

# I. Structural Condition Assessment

EXAMPLE

S1	Top of Wall Outward	<input type="checkbox"/>	No	<input type="checkbox"/>	Out of plumb/height_____			Note # _____		
S2	Top of Wall Inward	<input type="checkbox"/>	No	<input type="checkbox"/>	Out of plumb/height_____			Note # _____		
S3	Bulging/Warping of Wall	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S4	Top of Wall Aligned	<input type="checkbox"/>	No	Note # _____		Desc. _____				
S5	Tiebacks	<input type="checkbox"/>	No	<input type="checkbox"/>	Loose	<input type="checkbox"/>	Corroded	<input type="checkbox"/>	Missing % _____	Note # _____
S6	Settlement of Wall	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S7	Displaced Large Stone	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S8	Displaced Small Stone	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S9	Horizontal Cracks	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S10	Vertical Cracks	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S11	Diag. Cracks at Mortar Joint Only	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S12	Diag. Cracks through Joint & Stone	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S13	Cracked Stones	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S14	Spalled Stone	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
S15	Condition of Mortar	<input type="checkbox"/>	Good	<input type="checkbox"/>	Sandy	Missing pct. _____				
S16	Coping of Wall	<input type="checkbox"/>	None	<input type="checkbox"/>	Sound	<input type="checkbox"/>	Deteriorated	<input type="checkbox"/>	Displace	Note # _____
S17	Corner Cracks	<input type="checkbox"/>	No	<input type="checkbox"/>	Both Sides	<input type="checkbox"/>	One Side	<input type="checkbox"/>	Mortar	Mortar & Stone Note # _____
S18	Previous Repair	<input type="checkbox"/>	None Visible	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Major	Failed Note # _____
S19	Other	_____								



# I. Structural Condition Assessment continued...

EXAMPLE

<b>BB1</b>	Top of Wall Outward	<input type="checkbox"/>	No	<input type="checkbox"/>	Out of plumb/height_____			Note # _____		
<b>BB2</b>	Top of Wall Inward	<input type="checkbox"/>	No	<input type="checkbox"/>	Out of plumb/height_____			Note # _____		
<b>BB3</b>	Bulging/Warping of Wall	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB4</b>	Top of Wall Aligned	<input type="checkbox"/>	No	Note # _____	Desc. _____					
<b>BB5</b>	Tiebacks	<input type="checkbox"/>	No	<input type="checkbox"/>	Loose	<input type="checkbox"/>	Corroded	<input type="checkbox"/>	Missing % _____	Note # _____
<b>BB6</b>	Settlement of Wall	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB7</b>	Expansion Construction Joint	<input type="checkbox"/>	None	<input type="checkbox"/>	Sound	<input type="checkbox"/>		Deteriorated % Det. _____	Note # _____	
<b>BB8</b>	Horizontal Crack	<input type="checkbox"/>	None	<input type="checkbox"/>	Sound	<input type="checkbox"/>		Deteriorated % Det. _____	Note # _____	
<b>BB9</b>	Vertical Cracks	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB10</b>	Corner Crack	<input type="checkbox"/>	No	<input type="checkbox"/>	Both Sides	<input type="checkbox"/>	One Side	<input type="checkbox"/>	Mortar Jt. Mortar Jt. & Blk.	Note # _____
<b>BB11</b>	Stepped Cracks at Mort. Jnt. only	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB12</b>	Stepped Crack through Jnts & Blk	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB13</b>	Crack Due Steel Corrosion	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB14</b>	Steel Reinforcement Exposed	<input type="checkbox"/>	No	<input type="checkbox"/>	Rusted	<input type="checkbox"/>	Sect. Loss	Note # _____		
<b>BB15</b>	Displaced Blocks/Bricks	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB16</b>	Spalled Brick/Block	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB17</b>	Conditions of Mortar	<input type="checkbox"/>	Sound	<input type="checkbox"/>	Sandy	<input type="checkbox"/>		Missing % _____		
<b>BB18</b>	Freeze/Thaw Damage [crazing]	<input type="checkbox"/>	No	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Severe	Note # _____
<b>BB19</b>	Efflorescence/Calcium/Chloride	<input type="checkbox"/>	Yes	<input type="checkbox"/>		Description _____				
<b>BB20</b>	Veneer Not Attached Back-up	<input type="checkbox"/>	None	<input type="checkbox"/>	Sound	<input type="checkbox"/>	Deteriorated	<input type="checkbox"/>	Displaced	Note # _____
<b>BB21</b>	Veneer Separated Back-up	<input type="checkbox"/>	None	<input type="checkbox"/>	Sound	<input type="checkbox"/>	Deteriorated	<input type="checkbox"/>	Displaced	Note # _____
<b>BB22</b>	Coping of Wall	<input type="checkbox"/>	None	<input type="checkbox"/>	Sound	<input type="checkbox"/>	Deteriorated	<input type="checkbox"/>	Displaced	Note # _____
<b>BB23</b>	Previous Repair	<input type="checkbox"/>	None Visible	<input type="checkbox"/>	Minor	<input type="checkbox"/>	Moderate	<input type="checkbox"/>	Major Failed	Note # _____
<b>BB24</b>	Other									

## II. Condition Assessment of Soil / Pavement Adjoining Wall

EXAMPLE

1. Buckling of Road Sidewalk at Bottom     No     Minor     Moderate     Severe    Note # \_\_\_\_\_
  
2. Tension Cracks in Soil at Top     Yes – Width of Crack \_\_\_\_\_
  
3. Sink Holes in Soil/Pavement     Yes – Dimensions \_\_\_\_\_
  
4. Soil/Pavement at Base of Wall     Acceptable     Defective Describ. \_\_\_\_\_
  
5. Soil/Pavement at Top of Wall     Acceptable     Defective Describ. \_\_\_\_\_
  
6. Spoil Separating from Back of Wall     No – Width of Separation \_\_\_\_\_
  
7. Other \_\_\_\_\_

# III. Condition Assessment of Water Management Area Surrounding Wall

EXAMPLE

- 1. Weeps  No  Functioning? \_\_\_\_\_
- 2. Erosion of Wall/Soil by Water  No  Describe \_\_\_\_\_
- 3. Water/Silt Filtering through Water  No  Minor  Moderate  Severe **Note #** \_\_\_\_\_
- 4. Area Drains/Piping Present  No  Functioning? \_\_\_\_\_
- 5. Drywell Catch Basin  No  Describe \_\_\_\_\_
- 6. Hydrant  No  Describe \_\_\_\_\_
- 7. Downspouts/adj/ Buildings  No  Describe \_\_\_\_\_
- 8. Soil Drains Away from Wall  No  Describe \_\_\_\_\_
- 9. Other \_\_\_\_\_



EXAMPLE

# IV. Attachments to Wall

- 1. Balustrade/Handrail  No  Describe \_\_\_\_\_  Condition \_\_\_\_\_
- 2. Ramp/Steps  No  Describe \_\_\_\_\_  Condition \_\_\_\_\_
- 3. Tunnels  No  Describe \_\_\_\_\_  Condition \_\_\_\_\_
- 4. Light Structure (shed/garage)  No  Functioning? \_\_\_\_\_
- 5. Fence  No  Describe \_\_\_\_\_
- 6. Trees/Vegetation  No  Describe \_\_\_\_\_
- 7. Equipment/Storage at near Top of Wall  No  Describe \_\_\_\_\_
- 8. Other \_\_\_\_\_

# Stabilization -Shoring

---



# Bibliography

---

- Naval Facilities Engineering Command (1967) Design Manual: Structural Engineering : NAVFAC DM-2 Dec. 1967 Department of the Navy
- Trautwine J., (1886) The Civil Engineer's Pocket-Book -Revised, New York, John Wiley
- Baker Ira, (1905) A Treatise of Masonry Construction, 9th ed. New York , John Wiley
- Paaswell G., (1920) Retaining Walls: Their Design and Construction, New York, McGraw Hill
- FHWA-CFL/TD-10-003 (2010) Retaining Wall Inventory and Condition Assessment Program ( WIP) National Park Service Procedures Manual, Lakewood, CO
- Chan Y C (1996). Study of Old Masonry Retaining Walls in Hong Kong. Geo Report No 31. Hong Kong: Geotechnical Engineering Office
- K. C. Brady, J. Kavanagh, (2002) Analysis of the Stability of Masonry-faced Earth Retaining Walls, Transport Research Laboratory (Great Britain), Transport Research Foundation (Great Britain)
- New York State Department of Transportation, (2014) Bridge Inspection Manual
- Federal Highway Administration, (2012) Bridge Inspector's Reference Manual FHWA NHI 12-049

---

- Questions?