
APPENDIX 11:

NATURAL RESOURCES SITE PHOTOGRAPHS



Facing south at tennis facility



Facing north at beach area and sewer outfall to water taxi landing (low tide)



Facing east from beach area (low tide)




View of north peninsula and beach area facing southwest (high tide)



Facing southwest on north peninsula




Facing west on north peninsula



View of north peninsula facing north





View of north peninsula and the floating bridge



View of the south peninsula from the floating bridge cove area facing west



View from south peninsula facing north peninsula and floating bridge



North point of south peninsula

11



Black locust trees on south peninsula facing Newtown Creek

12



Shoreline of south peninsula point facing Newtown Creek






View of black locust trees on south peninsula point on Newtown Creek facing west



Shoreline of Newtown Creek from south peninsula point facing east



Along Newtown Creek facing west from the area near Anheuser-Busch Facility



Facing west on Newtown Creek next to Anheuser-Busch Facility



South peninsula facing southwest



South penisula interior facing southeast toward Newtown Creek



Interior of Site A facing east to 54th Avenue