APPENDIX 11.1:


NATURAL RESOURCES SITE PHOTOGRAPHS



Facing south at tennis facility 1



Facing north at beach area and sewer outfall to water taxi landing (low tide) 2



Facing east from beach area (low tide) 3




View of north peninsula and beach area facing southwest (high tide) 4




Facing southwest on north peninsula 5



Facing west on north peninsula 6



View of north peninsula facing north 7



View of north peninsula and the floating bridge 8



View of the south peninsula from the floating bridge cove area facing west 9



View from south peninsula facing north peninsula and floating bridge 10



North point of south peninsula 11



Black locust trees on south peninsula facing Newtown Creek 12



Shoreline of south peninsula point facing Newtown Creek 13




View of black locust trees on south peninsula point on Newtown Creek facing west 14



Shoreline of Newtown Creek from south peninsula point facing east 15



Along Newtown Creek facing west from the area near Anheuser-Busch Facility 16



Facing west on Newtown Creek next to Anheuser-Busch Facility 17



South peninsula facing southwest 18



South penisula interior facing southeast toward Newtown Creek 19



Interior of Site A facing east to 54th Avenue 20