

AGENDA

SECTION I: FISP REPORT CLARIFICATIONS

- OWNERSHIP INFORMATION
 CAVITY WALL PROBES

- PLOT PLAN
- FINAL INSPECTIONS
- BUILDING CONDITIONS

SECTION 2: UNSAFE FILING PRACTICES

- UNSAFE CONDITIONS
 PARTIAL SHED REMOVAL REQUEST
- UNSAFE REPORT REMINDERS
- TIME EXTENSION REQUESTS

SECTION 3: TERRA COTTA

SECTION 4: OTHER COMMON ISSUES

SECTION 5: CIVIL PENALTIES

- FAILURE TO FILE
- FAILURE TO CORRECT


LATE FILINGS

DISCUSSION





INTRO







TR6/FISP REPORT CLARIFICATIONS

OWNERSHIP INFORMATION

PLOT PLAN

MAPPING OF BUILDING CONDITIONS

CAVITY WALL PROBES

FINAL INSPECTIONS



OWNERSHIP INFORMATION

Owner registration on all FISP submissions must match the Department of Finance (DOF) record otherwise, the submission will be marked incomplete.

DPL-I forms are valid for I year. Submissions with expired DPL-I are marked incomplete and returned.




PLOT PLAN

The number of drops required:

Length of Facade Elevation Fronting	Minimum # of Physical
Public Right of Way (L)	Examinations
L < 60'-0"	1
60'-0"≤ L<120'-0"	2
120'-0" ≤ L < 180'-0"	3
$180'-0" \le L < 240'-0"$	4
240'-0" \le L < 300'-0"	5
300 '-0" $\leq L < 360$ '-0"	6

For every additional 60'-0" of length of facade, one additional close-up inspection is required.








MAPPING OF BUILDING CONDITIONS

FISP REPORT CLARIFICATIONS

- List of conditions MUST
 MATCH photos keyed in
- Describe, classify and map each condition
- Describe water-tightness of exterior surfaces
- Report must document conditions using
 - key plans
 - key elevations
 - locator drawings
 - labeled, high resolution, close-up photos



1 Cracked Terra-cotta above window

2 Cracked Terra-cotta Windowsill

3 Cracked and shifted brick

4 Cracked Terra-Cotta water table.




CAVITY WALL PROBES

DEFINITION

Cavity wall construction is an exterior wall system consisting of an exterior veneer with a backup wall whereby the exterior veneer relies on a grid of metal ties to the backup wall for lateral stability. The two layers of wall are separated by an air cavity which may or may not be filled with insulation.

CODE REQUIREMENTS*

- Starting with the ninth cycle, probes must be performed on all cavity wall construction, and, at a minimum, during every subsequent odd- numbered cycle.
- QEWIs must choose to probe an area of sufficient size and quantity to report the presence, condition, and spacing of wall ties.
 - Selected probe areas cannot be previously renovated.
- At least one probe must be completed along each required close-up inspection interval.
- FISP report must indicate location & size of probe, wall cross section inside probe, measurements of space between wall ties (vertical & horizontal), close-up photos of wall tie type & installation, any other conditions related to soundness of the wall ties, relieving angle, substrate and other cavity wall elements.



FINAL INSPECTIONS

I RCNY §103-04(c)(viii): QEWI must conduct a final physical examination to determine that the building conditions as described in the report are consistent with the actual conditions. Such final inspection must, at a minimum, include an actual visual examination and a walk around with binoculars or other inspectorial equipment. A drive by inspection is not acceptable.







UNSAFE FILINGS

- UNSAFE NOTIFICATION
- SAFETY MEASURES
- TIME EXTENSIONS
- PARTIAL SHED REMOVAL





REPORTING UNSAFE CONDITIONS











If a <u>registered Design Professional</u>* or <u>QEWI</u> observes UNSAFE façade conditions, he or she should:

Immediately:

- Identify location of the unsafe condition(s)
- Call 311 to report the condition or 911 if condition is immediately hazardous
- Notify the owner of the building
- Advise the owner on the appropriate protective measures to be taken and ensure they are installed
- File a FISP 3 form on DOB NOW Safety and include <u>recommended type and location</u> of <u>public protection</u>

Follow up:

- File an UNSAFE report (TR6) on DOB NOW Safety
- File an amended report once repairs are completed

- Unsafe report must contain at least one unsafe condition
- Do not submit unsafe report to avoid administrative or technical problems. Contact Facades
- It is permitted to file Unsafe in two consecutive cycles
- In the report and/or FISP3 describe in detail required public protective measures and their locations
- Public protection must remain in place at buildings with an UNSAFE status until Amended report is accepted or Partial Shed Removal request is granted
- Amended report can be filed at any time even outside of the filing cycle. Amended report must be filed on the most recent unsafe.



FISPI & 2TIME EXTENSION REQUESTS





- Time extensions must be filed in the cycle with the most recent accepted Unsafe report
- Time extensions cannot be granted past the unsafe completion date
- In order to change that date a Subsequent report must be filed
- Time extensions must reference the Initial Unsafe report
- Enter the entire name of the Initial Unsafe Report (TR6-123456-I1) in DOB NOW Safety Extension Request



PARTIAL SHED REMOVAL REQUEST



A **Partial Shed Removal** (**PSR**) request may be filed to remove public protection where repairs were completed on at least one building elevation but work remains in other areas.

The PSR filing requires QEWIs to submit:

- QEWI's signed & sealed detailed justification letter attesting for safe conditions of facades and removal of all defects
- List of unsafe defects removed and remaining scope of work
- A statement with the date the work will be completed and when amended report will be filed
- Plot/site plan showing portions of shed to remain and to be removed
- Before & after pictures
- Façade Elevation photos depicting shed installed

Do not file a PSR if:

- All repair work is completed
- Amended report is filed
- Only partial elevation is repaired

File combined PSR for all elevations where work will be completed within a short period of time

REPORT REQUIREMENTS FOR TERRACOTTA REPAIR



All reports involving terracotta repairs must include:

- before and after repair photos
- as-built details

If terracotta was patched the report must include:

• an explanation for the decision to repair vs. replace

If terracotta was pinned, the report must include:

an explanation of how material was evaluated for pinning



OTHER COMMON ISSUES

- PREVIOUSLY REPAIRED CONDITIONS
- REPORTS W/O CLOSE UP INSPECTION
- FISP REPORTS AND PIPE SCAFFOLDING
- RESPONSE LETTER IN RESUBMISSIONS
- FIRE ESCAPE ISSUES
- VIOLATION STATUS
- SECTION K RECOMMENDATIONS
- TR-6 (#5) IT IS IMPORTANT TO PROVIDE COMPREHENSIVE & CORRECT LIST OF WALL TYPES
 & MATERIALS
- PROVIDE CONTROL AND BIN NUMBERS WHEN MAKING INQUIRIES





ENGINEERING REPORTS



The purpose of an engineering report is to:

- I. Remedy DOB violation
- 2. Identify the cause of the façade failure
- 3. Identify and map defective façade elements
- 4. Provide recommendations for corrective work and justification for how such work may prevent a similar failure in the future



CIVIL PENALTIES

- "Failure to File" an acceptable inspection report is \$5,000 per year
- Late filing \$1,000 per month
- Failure to correct SWARMP conditions is \$2,000
- Failure to correct an unsafe condition is based on the table below:

YEAR	BASE PENALTY	PLUS
1	\$1000/month	NA
2	\$1000/month	\$10/linear foot (l.f.) of shed/month
3	\$1000/month	\$20/I.f. shed/month
4	\$1000/month	\$30/I.f. shed/month
5	\$1000/month	\$40/I.f. shed/month





WAIVER REQUESTS

Acceptable justifications

- Owner status
 - A new owner of a property previously owned by a government entity
 - A new owner who receives violation after the transfer of ownership
- Bankruptcy
- State of emergency
- Demolition (must be signed off before the filing deadline)





DISCUSSION

Any Questions?

Don't even think about it, you must have none after such a comprehensive presentation.

