

Columbus Park Pavilion Reconstruction

Between Baxter and Mulberry Street, in the Borough of Manhattan.

PDC Preliminary presentation July, 2024 Fabián Guerra, NYC Parks

Project Size: 3.23 ac


4,650 SF, Pavilion












Site 250 FT







Proposed Work

Pavilion

- Improve the functionality and durability of the building by:
 - Creating a program space at the basement floor by relocating operations.
 - Repairing existing lift.
 - · Addressing water infiltration.
 - Replace basement entrance doors.
 - Repair stone steps at south entrance.
- Prevent unlawful use of the pavilion at night.








1- Pavilion - South Facade

2 - Pavilion - North Facade













3- Pavilion ground floor view - Guardrails

4- Pavilion ground floor view - South Stairs

5- Pavilion ground floor view - Interior












6- Pavilion ground floor view - Interior

7- Pavilion ground floor view - Interior

8- Pavilion ground floor view - Interior






Gates precedent:


A new iron folding gate was erected at the entrance to the pavilion so that the building might be properly closed at night.

Department of Parks City of New York Annual Report 1908



PAVILION GROUND FLOOR - PROPOSED





Legend

Proposed fix panels

Relocated guardrail

New foliage

Tables and benches

Tree canopy

Hexagonal


asphalt pavers

Park Light pole


Drinking Fountain

Concrete pavement


Proposed hinge doors



PAVILION SOUTH FACADE (NORTH FACADE SIMILAR) - EXISTING CONDITIONS




Pavilion 1st floor - Proposed panels






Pavilion 1st floor - Proposed South entrance doors





















Square post top rail connection - Section

Fix panel connections



Square post bottom connection - Section

Fix panel connections




Square post bottom plate - Plan

Fix panel connections




Square post top connection - 3D View Fix panel connections




Square post bottom connection - 3D View

Fix panel connections









SOLID PORTION. NO 3" 2" HOLLOW METAL
DOOR 2" FRAME


"S S MESH "X"
DETAIL

SS WOVEN MESH, TYPE 316, (0.8"

X 0.8" MAX. OPENING) ABOVE
65% OPEN AREA

1 1 FRAME U-ENDING OR FLAT BAR FRAME
W/ BOLT HOLES FOR ATTACHMENT OF

MESH PANELS TO FENCE




Entrance doors - Interior view open doors

South facade entrance door




Entrance doors - Interior view closed doors
South facade entrance door




Entrance doors mesh - Details South facade entrance door






Pavilion ground floor - Fix panels & Doors **Option A**






Pavilion ground floor - Fix panels & Doors **Option B**






Pavilion ground floor - Fix panels & Doors **Option C**





Pavilion ground floor - Fix panels & Doors **Option D**





1- Pavilion exterior view - Fix panels South facade









1- Pavilion ground floor view - Fix panels

2- Pavilion Interior view - Fix panels



PAVILION WEST FACADE - AREAS WHERE PEOPLE CAN ACCESS THE BUILDING. NO SECURITY MEASURES NEEDED





PAVILION EAST FACADE - AREAS WHERE PEOPLE
CAN ACCESS THE BUILDING. SECURITY MEASURES
NEEDED








PAVILION EAST FACADE - AREAS WHERE PEOPLE CAN ACCESS THE BUILDING. SECURITY MEASURES NEEDED











1- Pavilion Interior view - East and West wings

