

ncident Date		Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2019	Bronx	4215	PARK AVENUE	0	1 A DOB inspector reported that a worker in the cellar fell	ECB Violation	35367408M	010319CE06WG01			Other Construction Related Incidents	NOT ON FILE	JOY CONSTRUCTION CORP
					approximately five feet from a ladder. The worker was sent to a hospital. An ECB Violation was issued for the improper use of a ladder.								
019	Queens	147-40	ARCHER AVENUE	0		No Dispatch			NEW BUILDING	420654508	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	CNY CONSTRUCTION LLC
					was preparing to pull wires through a pipe when he stepped backwards on the same floor and lost his								
					balance. The electrician cut his left hand while trying to								
					reach for something to grab to prevent himself from								
					falling. The worker went to an urgent care center on his own to receive treatment.								
/2019	Persident	1797	BROADWAY			FCB Violation	35374959Y	010318CNEGS01	NR.	32156883	Excavation/Soil Work	1797 REALTY ASSOCIATES	W Developmen Over
2019	Brooklyn	1/9/	BROADWAY	0	piles into place when a pile shifted and the worker	ECB Violation	35374959Y	010318CNEGS01	NB	32156883	Excavation/Soil Work	1797 REALTY ASSOCIATES	W Developers Corp
					suffered an injury to his right leg. The worker was in stable condition and was taken to an area hospital. The								
					extent and severity of the worker's injuries were not								
					known as of the time of inspection. An Aggravated								
					Level 2 ECB Violation was issued for a failure to								
					safeguard. A full Stop Work Order (FSWO) and a DOB Violation were also issued.								
2019	Brooklyn	778	DRIGGS AVENUE		3 A DOB inspector reported that there were three workers	ECR Violation	35354419P 35354420M	010319CE01CV01,02	ALT-3	321674675	Material Fell	OKUNIEWSKI MARIAN	ART-B CONSTRUCTION
.019	Біоокіун	176	DRIGGS AVENUE		on a sidewalk shed that were attempting to lift up a	ECB VIOIALION	33334419F 33334420W	010319CE01CV01,02	ALI-S	321674675	iviateriai reii	ORUNIEWSKI WARIAN	AKT-B CONSTRUCTION
					suspended scaffold platform. While the workers were lifting the suspended scaffold platform above the								
					sidewalk shed parapet wall, the parapet wall gave way,								
					and all three workers fell down onto the sidewalk. One								
					of the workers suffered a twisted ankle, and one of the								
					workers suffered a twisted finger. There was no information available regarding the injuries suffered by								
					the third worker. All three injured workers were taken to								
					a hospital by an ambulance. Two ECB Violations were								
					issued: one violation for a failure to safeguard persons and property, and one violation for the sidewalk shed								
					not being built according to code specifications. A								
					partial Stop Work Order (PSWO) and two DOB								
					Violations were also issued.								
2019	Brooklyn	982	WILLOUGHBY AVENUE	0	The Construction Superintendent reported that a worker was using a piggy-back to deliver material onto the	No Dispatch			NB	321183937	Other Construction Related Incidents	982 WILLOUGHBY AVENUE LLC	BROOKLYN
					street when the piggy-back overturned and the worker								
					suffered injuries to his arm and legs. The worker was								
					found conscious and an ambulance was called to transport the worker to a hospital.								
					transport trie worker to a nospital.								
2019	Manhattan	110	CHARLTON STREET	0	A DOB inspector reported that a worker was guiding a concrete pump hose during a concrete pouring	ECB Violation	35376880K	010319CE02MH03			Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	PLAZA CONSTRUCTION LLC
					operation when concrete splashed into his eye. The								
					worker was sent to a hospital. An ECB Violation was								
					issued for a failure to maintain safe operations. A partial Stop Work Order (PSWO) was issued for concrete								
					pouring operations. A DOB Violation was also issued.								
2019	Manhattan	500	WEST 33 STREET	0	The Site Safety Manager reported that a worker was	No Dispatch			NB	121186251	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION
					standing on an "A"-Frame ladder when he fell off of the ladder. The worker was not seriously injured but was								
					taken to a hospital by an ambulance. This incident								
					occurred as the result of a worker's error.								
019	Manhattan	601	WASHINGTON STREET	0	The Site Safety Manager reported that there was an unenclosed ladder inside of the building that was	No Dispatch			NB	122931845	Other Construction Related Incidents	HADSW LLC	TITANIUM CONSTRUCTION SER
					knocked over by a gust of wind. The ladder hit a worker.								
					The worker was not seriously injured but was taken to a								
					hospital by an ambulance.								
2019	Manhattan	615	10 AVENUE	0	A DOB inspector reported that during a stripping operation for the underside of the fifth floor, shoring	ECB Violation	35376875X/79N	010319CE04MH01/02	NB	121190889	Worker Fell	HUDSON 888 OWNER LLC	LEEDING BUILDERS GROUP LL
					was removed from an opening, and a piece of plywood								
					was placed over the opening. A worker performing								
					housekeeping work on the sixth floor stepped on the								
					piece of plywood, slipped, and fell to the fifth floor. The worker was found conscious and did not suffer any								
					broken bones. The worker was transported to a hospital								
					for further evaluation. The plywood was not secured, and a Controlled Access Zone (CAZ) was not								
					and a Controlled Access Zone (CAZ) was not maintained during the stripping operation. A pre-shift								
					safety meeting did not take place before the stripping								
					operation began. Two ECB Violations were issued: one								
					violation for the failure to institute safety measures, and one violation for the failure to conduct a pre-shift safety								
					one violation for the failure to conduct a pre-shift safety meeting. A partial Stop Work Order (PSWO) was								
					issued on stripping operations. Two DOB Violations								
					were also issued. A Means and Methods for safe operations to prevent a similar incident from occurring								
					going forward must be provided.								
			-				_					_	-



cident Date		Address Number		Fatalities Injuries E		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2019	Manhattan	58	WEST 39 STREET	en an Ti fa vi vi	DOB inspector reported that debris fell into a worker's while the worker was cleaning threaded rods. An mbulance took the worker to a hospital for a check up. there ECB Violations were issued: one violation for the illustre to conduct a pre-shift safety meeting, one cladion for the obstruction of the sidewalk, and one cladion for the obstruction of the sidewalk, and one cladion for the performance of work that was no informing to the approved plan. Three DOB Violations ere also issued.	ECB Violation	35376926R / 27Z / 28K	010419CE05JK01/02/03			Other Construction Related Incidents	H HOTEL LLC	CROSSCITY CONSTRUCTION CO
2019	Brooklyn	4813	9 AVENUE	el	he Construction Superintendent reported that an ectrical worker tripped, fell, and hurt his fingers. The	No Dispatch			NB	320592970	Worker Fell	MAIMONIDES MEDICAL CENTER	AMERICON CONSTRUCTION INC
2019	Manhattan	211	EAST 70 STREET	0 1.A control of the	orker went to a City M.D. by himself.  DDB Impactor reported that there were mast imbern being used at all four appearse of a thirty-four you existing building in order to perform facade repair rock. At the roof level, a worker lost control of a rocket soft and the desired so that the roof level, a worker lost control of a rocket, and then struck another worker in the log desired were assent in congesting in the leg ingo desired reviews and in congesting the lost produced to the log desired the resident of real fallers to safeguard persons and property fected by construction operations, as there was no notificat Acoss Sone (CAZ) on the deck while the verthead operation was in progress, there was no entered the construction operations, as there was no adderer were no safeguards for falling in place, a second claim for the absence of a guardraid along the inner specific process. The construction and the control of the construction operation was being sorted along the inner specific soft and the control of the construction operation was being sorted along the inner specific soft of the construction operation was being sorted along the inner specific soft of the construction operation was being sorted along the inner specific soft of the construction operation was being sorted along the inner specific sorted and the specific sorted and specific sorted and	ECB Violation	35377002L, 35377003M & 35377004P		ALTERATION	122993485	Material Fell	211 EAST 70TH STREETL.P.	E & A RESTORATION INC
019	Manhattan	22	NORTH LOOP ROAD	st fii w	he Site Safety Manager reported that a worker was ripping formwork on the third floor when he cut his nger with a nail while trying to hold the nail. The orker walked to an urgent care center on his own to ceive treatment and will return to work.	No Dispatch			NEW BUILDING	121203697	Other Construction Related Incidents	NOT ON FILE	HUNTER ROBERTS CONST. GRP
019	Manhattan	15	EAST 30 STREET	w in in	he Site Safety Manager reported that there were two orkers picking up a pipe that was ten feet long and six ches in diameter when one of the workers felt a pop his back. This worker was experiencing pain and ent to an off-site clinic.	No Dispatch					Other Construction Related Incidents	MADISON 30 31 OWNER LLC	MADISON 30 31 OWNER LLC
019	Queens	147-40	ARCHER AVENUE	h	he Site Safety Manager reported that a worker cut his and while using a drill to install metal studs. The orker went to a walk-in clinic.	No Dispatch			nb	420654508	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	cny construction
2019	Brooklyn	244	HOWARD AVENUE	O 1 A drift of the control of the co	DOB inspector reported that a worker was injured uring a partial collapse of the roof and third and fourth or point. The worker was transported to a hospital with non-life threatening injuries. The collapse appeared to the result of the overdeading of the floor joist with border threatening injuries. The collapse appeared to the result of the overdeading of the floor joist with birds and the presence of structural cold-formed steel at was not conforming to the approved plans. A DOB collation was issued for failure to safeguard. A full Stop fork Order (FSVIQ) was also issued. As of January 20, 2019, the Construction Safety Enforcement Unit is switch the construction Safety Enforcement Unit is switch to the construction Safety Enforcement Unit is within the construction Safety Enforcement Unit is within the construction Safety Enforcement Unit is the construction Safety Enforcement Unit is the construction of the Safety Enforcement Unit is the construction of the Safety Enforcement Unit is within the construction Safety Enforcement Unit is within the construction of the Safety Enforcement Unit is within the Construction of the Safety Enforcement Unit is within the Construction Safety Enforcement Unit is safety to the Construction Safety Saf	DOB Violation		010e19CE0305BG	ALTERATION-1	321646918	Material Fell	244 HOWARD AVE LLC	Y&Z DEVELOPERS INC
2019	Manhattan	1	WALL STREET	pi hi ai	he Site Safety Manager reported that a worker was ulling out a mini dumpster when he turned, fell, and hit his big right toe. The worker went to a clinic. An mbulance was not called. This incident occurred as the result of a worker's error.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2019	Manhattan	22	NORTH LOOP ROAD	0 1 Ti pr er to	he Site Safety Manager reported that a worker was erforming grinding work when a particle fell behind his ye gear and went into his eye. The worker was taken a clinic to have his eye flushed out. An ambulance as not called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	



ncident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2019	Manhattan	550	WEST 34 STREET	1 The Site Safety Manager report worker was shocked while work ceiling. The worker was found to a hospital by ambulance. At to the incident and reported the as the result of a worker's error was deemed necessary.	ing on the fifth floor conscious and was taken OB inspector responded the incident occurred . No enforcement action			N/A	N/A	Other Construction Related Incidents	ONE HUDSON YARDS OWNER LLC	
10/2019	Brooklyn	11	HOYT STREET	1 A DOB inspector reported that blown off from an anchor point of fence then struck a pedestrix examined the pedestrian and secreed to revoke treatment. Three ECB one vidiation for a failure to saff properly affected by the consist properly and the properly and the second properly and t	in on her leg. A medic in the tro a clinic to  (Viciations were lissued:  superior and discount of the control of the  red and was blown off  in, one viciation for not  drawing for the fence  to all Engineer (PE), and  discount Engineer (PE), and  discount Engineer (PE), and  and the perior of the  superior of the  superior of the  superior of  and  and  and  and  and  and  and  and	35351511Y, 12X AND 13H		ALTERATION -1	321197058	Scaffold/Shed/Fence/Shoring/Installation	11 HOYT PROPERTY OWNER, L.P.	TRITON CONSTRUCTION CO.,
0/2019	Bronx	600	BERGEN AVENUE	The Site Safety Manager report his back while lifting a piece of EMS.	ed that a worker pulled No Dispatch steel. The worker called			NEW BUILDING	220151868-01-NB	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
/11/2019	Manhattan	639	WEST 59 STREET	The Site Safety Manager repor on ice at the roof level. An arm the worker to a hospital. A DOG the incident and issued an ECE maintain work at the roof area. also issued.	inspector responded to Violation for a failure to	35376811R	011119CE07DH01	NB	123308562	Worker Fell	RCB4 NOMINEE LLC	Tishman Construction corp.
/14/2019	Manhattan	627	GREENWICH STREET	1 A DOB inspector reported that was working on a device at the shaftway did not have any scretche mechanic to move between mechanic got his harness cauguthat was between the elevator and an elevator that was right functioning. The mechanical telegrand an ambulance was call leg and an ambulance was call were issued: one violation was of Elevator Device 1R4925 at presence of a broken limit cam issued for a failure to safleguare.	twelth floor. The an protection, allowing the shaftway. The th on the metal angle hat he was working on ext oil, which was rered minor bruises to his dd. Two ECB Violations sisued to cases the use the site due to the and one violation was	3826733H, 38267331Y				Worker Fell	627 GREENWICH OWNER LLC	
15/2019	Brooklyn	281	CUMBERLAND STREET	The Construction Superintende was installing rated the backyard that lead down to the worker fell nine feet into the sh a possible broken leg and was ambidance. The worker was to lead of the office of the control of	basement when the if. The worker suffered aken to a hospital by und to have not been nded to the incident and e vidation for the failure a worker fell during the tion for the possession for the possession of e. A full Stow Work	35377042X,43H,44J	011519CE02BG08,09,10	ALT1	321195103	Worker Fell	SWEENEY, WILLIAM J IV	SMOOTH RENOVATIONS INC
/15/2019	Manhattan	50	WEST 69 STREET	A DOB inspector reported that in the eyes by bethis during the bed-rock breaking operation. B to seek medical attention, An E for a failure to maintain safe op partial Stop Work Order (PSW rock breaking operations. A DC issued.	oth workers left the site CB Violation was issued erations at the site. A D) was issued for bed-	35376899К	011619CE07MH04			Other Construction Related Incidents	ERZULI, LLC	NORDIC CUSTOM BUILDERS IN
17/2019	Brooklyn	340	EVERGREEN AVENUE	The Site Safety Manager repor finger while throwing a piece of The worker was treated on site doctor to receive additional trea	and was then taken to a			NB - NEW BUILDING	321181993-	Other Construction Related Incidents	BUSHWICK REALTY HOLDINGS LLC	Y.N.H. CONSTRUCTION INC
/18/2019	Brooklyn	3491	FORT HAMILTON PARKWA	Y 0 1 A DOB inspector reported that a power saw. An ambulance w Violations were issued: evid to power saw that was contrary to specifications, and one violation provide a pre-shift safety meet Order (FSWO) and two DOB v issued.	ation for the use of a the manufacturer's i for the failure to ng. A full Stop Work	35377064R 35377065Z	011819CE12JK01 / JK02			Other Construction Related Incidents	SNL ORIX FORT HAMILTON, LLC	SNL CONSTRUCTION LLC



Incident Date	Rorough	Address Number	Stroot	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	139	EAST 56 STREET	The Site Safety Manager reported that a worker accidentally hit himself in the lips while swinging a hammer. The worker's foreman took him to a hospital for further observation.	No Dispatch	ECS Violation numbers	DOB VIOLATION NUMBERS	NB	123028810	Other Construction Related Incidents	139 EAST 56TH STREET LANDLORD	HUNTER ROBERTS CONSTRUCTION GROUP
1/22/2019	Bronx	810	RIVER AVENUE	The Sillse Safety Manager reported that a worker was working on duct work when he fell approximately five feet from a ladder. The worker claimed to have suffer injuries to his neck and back and was taken to a hospital to be further examined. A DOB inspector responded to the incident and reported that there were no hazardous conditions observed. No enforcement action was deemed necessary, as it was determined that the injury occurred as the result of a worker's error.	od .					Worker Fell	NOT ON FILE	M. MELNICK & COMPANY INC
1/22/2019	Manhattan	277	PARK AVENUE	The Site Safety Manager reported that a laborer cut hi finger while disposing of material into a mini-container The laborer walked to a MedRite to be further evaluate.				ALT 2 FAÇADE	123164075	Other Construction Related Incidents	277 PARK AVEENUE,LLC	CAULDWELL WINGATE CO LLC
1/25/2019	Manhattan	730	5 AVENUE	A DOB inspector reported that an electrician suffered laceration to this index finger while using a band saw. The worker was taken to a nearby hospital. An ECB Violation was issued for a failure to safeguard. A parti	al	35382611N		Alteration	122751771	Mechanical Construction Equipment	NOT ON FILE	Structure Tone
1/25/2019	Manhattan	560	WEST 33 STREET	The Site Safety Manager reported that a worker slippe and fell approximately two feet off of a ladder. The worker complained about back pain. An ambulance w called, and the worker was taken to Mount Sinai hospital for observation. The worker was released with medication.	as			NB	121192618	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
1/25/2019	Manhattan	233	WEST 125 STREET	A DOB inspector reported that a worker was carrying steel spreader beam when his foot got caught betwee rebar, which caused the worker to drop the steel spreader beam on his left foot. The worker left the sit to seek medical attention. An CSB Violation was issue for a failure to maintain safe operations at the site. A parial Stop Work Order (PWO) was issued for all concrete operations. A DOB Violation was also issued.	d	35382662N	012519CE10MO01			Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
1/28/2019	Brooklyn	85	JAY STREET	0 1 A DOB inspector reported that a worker was bending rebor on a machine when he got his right arm pinched between a rebar and a column. The worker suffered minor injuries and was taken to a nearby hospital. The worker had recently took part in a pre-shit stayfely meeting that was related to princh points. The worker not follow protocol. It was deemined that this inciden cocurred as the result of a worker's ereor and no enforcement action was deemed necessary.	lid			NB	321188415	Other Construction Related Incidents	85 JAY STREET BROOKLYN, LLC	New line structures
1/28/2019	Manhattan	122	EAST 23 STREET	The Site Safety Manager reported that a worker hurt to nose while working on a sprinkler. A co-worker took the injured worker to a hospital.	is No Dispatch					Other Construction Related Incidents	NOT ON FILE	CM and Associates
1/28/2019	Manhattan	532	WEST 20 STREET	The Site Safety Manager recorded that a worker was walking on the site paginated the advise to the walking on the site of the control of the site of the control of the co						Other Construction Related Incidents	DDG 532 WEST 20TH STREET LLC	DDG DEVELOPMENT LLC
1/29/2019	Bronx	600	EAST 156 STREET	1 The Site Safety Manager reported that a worker slippe while coming off of an "A"-Frame ladder. The worker complained that he was experiencing foot pain and we taken to a hospital by ambulance.						Other Construction Related Incidents	600 EAST 156TH STREET HOUSING	
1/29/2019	Manhattan	1	WALL STREET	1 A DOB inspector reported that there were two workers that were transporting twenty-five sheets of metal with an "A"-France cart when the Goad of sheets fell off of the cart and his one of the workers in the leg. The struck worker received cust and rotices on his leg and went a hospital to be further evaluated. The incident was caused by the overloading or misuse of equipment. At ECB Violation was issued for a failure to take advantaged were assures in handling materials. A partial Subp Work Order (FSWO) was issued on all material handling. The contractors at the site are to provide a Means and Methods for safe material handling.	to	35382797k		alteration	121190086	Other Construction Related Incidents	NOT ON FILE	JT Magen
1/30/2019	Manhattan	708	Broadway	A DOB inspector reported that an operation was takin place to fill hollow metal columns in a building with cement in order to support heavy duty mechanical equipment that will be installed on the rod. While the first column was being filled, a pre-diffied play had become distolged, and concrete was spilled oriot the floor of the gym, not a free standing weight machine, and orio a patron. The patron/pedestraten was directed to the column of the patron of t		35374766Н	013019CERJM01	ALTERATION TYPE 2	140598725-01-EW-OT	Material Fell	NEW YORK UNIVERSITY	SKYLINE RESTORATION INC



ncident Date		Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/31/2019	Manhattan	767	5 AVENUE	0 1 A DOB inspector reported that a worker was installing in gift fifter when he cut his right wrist on a piece of metal. The worker was taken to a hospital, where he received seven sitches and was then released. The inspector determined that the incident occurred as the result of a worker's error. No enforcement action was deemed necessary.	No Action Necessary			alteration	123660430	Other Construction Related Incidents	767 FIFTH PARTNERS LLC	Turner construction
2/1/2019	Manhattan	450	WEST 126 STREET	A DOB inspector reported that a worker was walking or a set of rebar when he lost his balance, slipped, and sprained his wrist. The worker left the site on his own it order to seek medical attention. The worker slipped on his own. This incident occurred as the result of a worker's error. No enforcement action was deemed necessary, ECB Violations were issued for infractions that were not related to the incident.	,					Other Construction Related Incidents	TSTY OWNER LLC	LEAND LEASE (US) CONSTRUCTION
2/1/2019	Manhattan	118	WEST 139 STREET	A DOB inspector reported that there were two workers performing interior work inside of apartment SW. While a window frame was being removed, a *f. *8 section of the ceiling collapsed and struck the two workers on their heads and shouldern. Both workers were transported to Harlem Hospital to receive treatment for their injuries. The New York City Fire Department gained access to the apartment and removed the remaining section of the ceiling of the affected area. Ar ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (PSWO) was issued for all work in apartment SW. A DOB Violation was also issued.		35355797H	0201CERDY01			Material Fell	MPLP 6 HOUSING DEVELOPMENT FUN	
/1/2019	Manhattan	108	CHAMBERS STREET	The Site Safety Manager reported that a carpenter cut his wrist on a metal stud while pressing on foam insulation. The worker was treated by the on-site media and then went to a City M.D. to receive stitches.				ALT-1	121193519	Other Construction Related Incidents	108 CHAMBERS STREET OWNER LLC	ROSS & ASSOCIATES
2/4/2019	Brooklyn	2650	OCEAN PARKWAY	1 A DOB inspector reported that a worker was electrocuted. The worker was taken to Coney Island Hospital. Two ECB Violations were issued: one violation for there being no application on file for temporary wiring in the meter room on the first floor, and one violation for the absence of a panel cover from the side of a meter bank at the first floor. Two DOB Violations were also issued.		35359220K & 35359221M	020519EE313FM1 & 020519EE313FM2			Other Construction Related Incidents	NOT ON FILE	
/4/2019	Manhattan	545	WEST 30 STREET	The Site Safety Manager reported that a worker accidentally cut his hand on a hand-held ginder. The ginder was equipped with a safeguard. The worker's injury was not serious and he left the site on his own to have the cut cleaned up.	No Dispatch			ALTERATION TYPE 1	121192397-01-AL	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
2/5/2019	Brooklyn	422	FULTON STREET	A DOB inspector reported that during the installation of reinforcement for a penthouse slab, a worker stepped on a piece of flair-out wire mesh chair, and the tip of the wire mesh penetrated the worker's bot and out his foot. The worker took himself to a nearby urgent care center and was treated with a telanus short to prevent an infection. The worker was released from the urgent care center and went home. Two ECB Violations were issued: one violation for a failure to safeguard, as the contractor failed to install concrete chairs as per the specifications found in the manual, and one violation for the performance of work that did not confirm to the approved Site Safety Plan. as there was a hoist above the tenth floor, which was not on the Site Safety Plan. partial Stop Work. Order (PSWO) to stop all work on the tenth floor, and above. Two DOB Violations were also issued.	r	35382738K 35382739M	02051CE302JT01	alt 1	320908899	Other Construction Related Incidents	NOT ON FILE	Transparent Constrution



	Borough	Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/5/2019	Manhattan	30	EAST 29 STREET	0 10 The New York City Fire Department requested that a	n ECB Violation	35375725X, 26H, 27J	020519CERFC01, 02, 03	General Contractor	121204552-01-NB	Other Construction Related Incidents	RG-29TH STREET OWNER I LLC	GERALD BIANCO
				inspection please be performed, as there were work	ers							
				that had been overcome by carbon monoxide. A DO	3							
				inspector responded to the incident and visited the s	te							
				and reported that there were workers at grade that v	ere							
				shoring formwork for cellar one. The formwork had								
				been completed and approximately fifty percent of the	0							
				top steel was completed, with a pour scheduled for t	ne							
				next day on the north half of the floor, and another p	our							
				scheduled in two days for the remainder. The only								
				opening was the elevator shaft. There were two gas								
				generators at grade under the formwork that emitted								
				adequately ventilated, which caused ten workers to l								
				overtaken by the fumes. Nine of the workers were ta								
				to a hospital, while the tenth worker received treatme								
				at the site. Out of the nine hospitalized workers, six								
				the workers were taken for observation, while two of	the							
				other workers went to Cornell Hospital and the ninth								
				and final worker went to Jacobi Hospital. The worker	s							
				that went to Cornell Hospital and Jacobi Hospital are	in							
				hyperbaric chambers. All of the workers are in stable	.							
				condition. Three ECB Violations were issued: one								
				violation to the General Contractor for a failure to								
				safeguard, one violation to the Site Safety Manager	or							
				the failure to perform his duties, and one violation to	the							
				Fire Safety Manager for the failure to perform his								
				duties. A full Stop Work Order (FSWO) and three D								
				Violations were also issued. The contractor has been	1							
				directed to only make the site safe. Holes were creat	ed							
				in the formwork to ventilate the space.								
5/2019	Queens	69-01	34 AVENUE	0 1 A DOB inspector reported that a lull was deliving an		35376626P	020519CE03MS01			Other Construction Related Incidents	THE NEW YORK CITY SCHOOL CONST	TURNER CONSTRUCTION COMPANY
				eighty pound cement bag to the fourth floor when th								
				bag fell from the lull and struck a worker that was or	a							
				scaffold at the second floor level. The worker went to	a							
				hospital. An ECB Violation was isued for a failure to								
				maintain safety operations at the job site. A full Stop								
				Work Order (FSWO) and a DOB Violation were also								
				issued.								
/7/2019	Manhattan	11	WEST 53 STREET	0 1 A DOB inspector reported that there were contractor	- FOR Violeties			alteration	121190193	Other Construction Related Incidents	W. W. A. LOW, M. A. C. C. A. C.	turner construction
		l.,		that were installing exterior windows at the site. One	of ECB violation	35377189k		alteration	121190193	Other Construction Related incidents	THE MUSEUM OF MODERN ART	turner construction
				that were installing exterior windows at the site. One	of	3537/189K		alteration	121190193	Other Construction Related incluents	THE MUSEUM OF MODERN ART	turner construction
				that were installing exterior windows at the site. One the workers was attached to a life-line on the exterio	of	3537/189K		and anon	121190193	Other Construction Related incidents	THE MUSEUM OF MODERN ART	turiei construction
				that were installing exterior windows at the site. One the workers was attached to a life-line on the exterio leading edge when he hyperextended his elbow whil	of r	3537/189K		alter autori	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	une construction
				that were installing exterior windows at the site. One the workers was attached to a life-line on the exterio leading edge when he hyperextended his elbow whil setting a window. The worker was taken to a nearby	of r	353//189K		andranon	121190193	Other Constitution Related incidents	THE MUSEUM OF MODERN ART	une constitution
		·		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterio leading edge when he hyperextended his elbow whil	of	35.37/189K		cites audi	121190193	Other Constitution Related Incidents	THE MUSEUM OF MODERN ART	unier consucción
				that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow whill setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line that was in place, and the life-line was	of real	353/1199K		ante audi	121190193	Otter Construction Related incidents	THE MUSEUM OF MODERN ART	unie carsucaan
				that were installing exterior windows at the site. One the workers was attached to a life-line on the exterio leading edge when he hyperextended his elbow whil setting a window. The worker was taken to a nearby hospital and was released from the hospital with a	of real	3537/199K		are acci	121190195	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	unier construction
				that were installing exterior windows at the site. One the workers was attached to a life-line on the schorio leading edge when he hyperextended his elbow whill setting a window. The worker was taken to a nest pospital and was released from the hospital with a minor injury. There were no design drawings found the life-line that was in place, and the life-line was found to not be an effective fall arrest system. An EV	of or CB	353/1199K		and and	121190195	Other Construction Related Incidents	THE MUSEUM OF MUDERN ANT	une cossocion
				that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow whill setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line that was in place, and the life-line was	of or CB	3537/199K		and and	121190195	Other Construction Related in Colonia	THE MUSEUM OF MUDERN ANT	une cossicioni
				that were installing exterior windows at the site. One the workers was attached to all fieline on the rectorio leading edge when he hyperextended his elbow whill setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line that was in place, and the life-line was found to not be an effective fall arrest system. An EV Violation was issued for the failure to provide design	of or CB	353/1199K		and and	121190195	Other Construction Related Incidents	THE MUSEUM OF MICDERN ANT	une consucati
				that were installing exterior windows at the site. One the workness was attached to a life-line on the schorio leading edge when he hyperextended his elbow whill setting a window. The workness was taken to a nestry hospital and was released from the hospital with a minor injury. There were no design drawings with out off the life-line was found to not be an effective fall arrest system. An EV Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWV) was issued on all exterior window installations. The contractors are to design a safe design drawing and	of de	3537/199K		arter (Inch	121190195	Other Construction Related in Colonia	THE MUSEUM OF MUDERN ANT	uner consucción
				that were installing exterior windows at the site. One the workers was attached to all fieline on the rectorior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a re- typh hospital and was released from the hospital with a minor injuy. There were no design drawings found the life-line that was in place, and the life-line was found to not be an effective fall arrest system. All Edging Violation was issued for the failure to provide agging drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The	of de	3537/199K		aner and	121190195	Other Construction Related Incidents	THE MUSEUM OF MODERN ANT	une consucati
				that were installing exterior windows at the site. One the workness was attached to a life-line on the schorio leading edge when he hyperextended his elbow whill setting a window. The workness was taken to a nestry hospital and was released from the hospital with a minor injury. There were no design drawings with out off the life-line was found to not be an effective fall arrest system. An EV Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWV) was issued on all exterior window installations. The contractors are to design a safe design drawing and	of de	3537/199K		arter and)	121190193	Other Construction Related in Colonia	THE MUSEUM OF MUDERN ANT	uner consucción
				that were installing exterior windows at the site. One the workness was attached to a life-line on the schorio leading edge when he hyperextended his elbow whill setting a window. The workness was taken to a nestry hospital and was released from the hospital with a minor injury. There were no design drawings with out off the life-line was found to not be an effective fall arrest system. An EV Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWV) was issued on all exterior window installations. The contractors are to design a safe design drawing and	of de	3537/199K		arter and t	121190193	Otter Construction Related Incidents	THE MUSEUM OF MUDERN ANT	une costacion
				that were installing exterior windows at the site. One the workres was attached to a life-line on the schorio leading edge when he hyperextended his elbow whill setting a window. The workrew was taken to a reachy hospital and was released from the hospital with a minor injury. There were no design drawings flound the life-line that was in place, and the life-line was found to not be an effective flat arrest system. An EV Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.	of r o or or							
7/2019	Manhattan	125	GREENWICH STREET	that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow will setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Sign Vibro (Toder (FWW) was contractors are to design a safe design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing the second of the specific or second of the specific or second o	of control	35377279Y, 35377280L, 35377281N, 35377282P		NEW BUILDING	121183799	Worker Fell	VS 125 LLC	PLAZA CONSTRUCTION LLC
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workres was attached to a life-line on the scorior leading edge when he hyperextended his elbow whils setting a window. The workrew was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings flound the life-line that was in place, and the life-line was found to not be an effective flat arrest system. An EV Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.	of of the control of							
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stp Work Order (PSWO) says issued on all exterior window installations. The comrators are to design a sale design drawing and Means and Methods for window installations.	of of the control of	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workres was attached to a life-line on the exterior leading edge when he hyperextended his elbow whils setting a window. The workrew was taken to a setting window. The workrew was taken to a nestably hospital and was released from the hospital with a minor injury. There were no design drawings flound to the life-line was found to not be an effective flat arrest system. An EV violation was issued for the failure to provide design drawings. A partial Stop Violen Green (Fellow) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.	of of the control of	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stp Work Order (PSWO) says issued on all extensive window installations. The commanders were not extensive and design drawings and Means and Methods for window installations.  0 1 A DOB inspector reported that a worker was standing a ladder and stripping formwork when the formwelf ell on the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambilance in a	of core core core core core core core core	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow whils setting a window. The worker was taken to a setting window. The worker was taken to a setting window. The worker was taken to a hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An EV violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formw fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five EOB Violations were issued:	of core core core core core core core core	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stp Work Order (PSWO) says issued on all extensive window installations. The commanders were not extensive and design drawings and Means and Methods for window installations.  0 1 A DOB inspector reported that a worker was standing a ladder and stripping formwork when the formwelf ell on the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambilance in a	of core core core core core core core core	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow whils setting a window. The worker was taken to a setting window. The worker was taken to a setting window. The worker was taken to a hospital with a minor injury. There were no design drawings found to the life-line was found to not be an effective flat arrest system. An EV violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standin on a ladder and stripping formwork when the formw fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued: o violation to the General Contractor for the failure to maintain safety measures.	of core core core core core core core core	35377279Y, 35377280L, 35377281N, 35377282P						
2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the teatric leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and Means and Methods for window installations. The contractors are to design a sale design drawing and Means and Methods for window installation.	of control	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow whils setting a window. The worker was taken to a setting window. The worker was taken to a setting window. The worker was taken to a setting window. The worker was taken to a legislar disciplination of the life-line was found to not be an effective fall arrest system. An EV oliation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standin on a ladder and stripping formwork when the formw fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued: o violation to the General Contractor for the failure to maintain safely measures during a stripping operation as there was no work platform present, one violation the General Contractor for the failure to provide a sit	of core core core core core core core core	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the receipt leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An EV Violation was issued for the failure to provide deligned drawings. A partial Stop Work Order (PSWO) as issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.  O 1 A DOB inspector reported that a worker was standing on a ladder and stroked the worker does not be a leader and knocked the worker does not be a leader and knocked the worker does not be deemed contractor for the failure to maintain safety measures during a stripping operation in a conscious state. The ECB Violations were issued to will be a leader and knocked the worker of the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance in a conscious state. The ECB Violations were issued: o violation to the General Contractor for the failure to maintain safety measures during a stripping operation the General Contractor for the failure to maintain safety measures during a stripping operation the General Contractor for the failure to provide a sit specific select yorientains for the workers, one violation the General Contractor for the failure to provide as it specific select yorientains for the workers, one violation the General Contractor for the failure to provide as it specific select yorientains for the workers, one violation the General Contractor for the the worker was select yorientains for the workers, one violation the General Contractor for the failure to maintain safety measures during a stripping operation to general Contractor for the fa	of core core core core core core core core	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow whils setting a window. The worker was taken to a settly hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective fall arrest system. An EV Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means at the safe of the leader. The worker let approximately him feet he worker was staken to a hospital by ambulance in a conscious state. Five ECB Violations were issued: o violation to the General Contractor for the failure to maintain safely measures during a stripping operatic as there was no work platform present, one violation the General Contractor for the failure to provide a sil specific safety orientation for the workers, one violation the General Contractor for the failure to provide a sil specific safety orientation for the workers, one violation to the Concrete Subcontractor for the failure to portion and the safety and the	g of the control of t	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fieline on the hexacinal leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An EV Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWV) as issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.	of core core core core core core core core	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow whils setting a window. The worker was taken to a setting which the setting a window. The worker was taken to a setting which the life-line was found to not be an effective fall arrest system. An EV violation was issued for the failure to provide display drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing a ladder and stripping formwork when the formwe fell on the ladder and knocked the worker off of the ladder. The worker let growth with the ladder is a conscious state. Five ECB Violations were issued to violation to the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation to the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation to the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation to the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation one violation to the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation one violation to the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation one viola	g of ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fiel-ine on the texterio leading edge when he hyperextended his elbow will setting a window. The worker was taken to a metry hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWV) as issued on all exterior window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a scribe design and the said with the said of the ladder and knocked the worker off of the said of the ladder and knocked the worker of the said of the ladder and knocked the worker of the said of the ladder and knocked the worker of the said of the ladder and knocked the worker of the said of the ladder and knocked the worker of the said of the ladder and knocked the worker of the said of the ladder and knocked the was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued to worker was now knocked price present, one violation to the General Contractor for the failure to pride a pre-task safety meeting before a stripping operation one violation to the General Contractor for the failure to perform a pridorstatic test for the standingle above the stripping operation one violation to the General Contractor for the failure to perform a pridorstatic test for the standingle packove the stripping operation one violation to the General Contractor for the failure to perform a violation to the General Contractor for the failure to perform a viol	g of ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
//2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow wild setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial flop (ViolAttor) Corder (PSWV) associated to the second of the second o	of control	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fiel-ine on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a westly hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standin on a ladder and stripping formwork when the formw fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECW Violations were issued to violation to the General Contractor for the failure to provide as there was no work self-ord my present, one obtains the General Contractor for the vorkers one violation to the General Contractor for the vorkers and supports and the provides a step energy before a stripping operation one violation to the General Contractor for the sladius to the High capital filters and the failure to particle and the provides a	g GK ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow wild setting a window. The worker was taken to a nearty hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) says issued on all exterior window installations. The consuctance of the stop of the	g ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fiel-ine on the texterio leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standin on a ladder and stripping formwork when the formw fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECW Violations were issued to violation to the General Contractor for the failure to price of the was not work will offer a stripping operation one violation to the General Contractor for the vorkers, one violation to the General Contractor for the standing be above the fifty-eighth floor, and one violation to the General Contractor for the standing be suppended scaffording that was not in accordance with the approved plan. Two partial Stop Work Orders (FSWO) were issued to the partial Stop Work Orders (FSWO) were issued to the partial Stop Work Orders (FSWO) were issued to	of control	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the teatric leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The coveractors are to design and design drawings and Means and Methods for window installations. The coveractors are to design as all design drawing and Means and Methods for window installations. The coveractors are to design as all design drawing and Means and Methods for window installations. The coveractors are to design as all design drawing and Means and Methods for window installations. The coveractors are to design as all design drawing and Means are stated as the second of the ladder. The worker (ell approximately nine feet. The worker was taken to a hospital by ambilance in a conscious state. Five ECB Violations were issued to violation to the General Contractor for the failure to maintain safety measures during a stripping operation the General Contractor for the failure to maintain safety measures during a stripping operation one violation to the General Contractor for the failure to partial as there was no work platform present, one violation the General Contractor for the failure to partial and the stripping operation one violation to the General Contractor for the failure to partial and the stripping operation one violation to the General Contractor for the salure to partial stop with the approved plone is stopping operation, and one to stop all forming and stripping operation, and one to stop all forming and stripping operation, and one to stop all the main and one stop all forming and stripping operation, and one to stop all forming and stripping operation, and one to s	g ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fiel-ine on the texterio leading edge when he hyperextended his elbow will setting a window. The worker was taken to a metary hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standin on a ladder and stripping formwork when the formw fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECW Violations were issued. Or violation to the General Contractor for the failure to provide as there was no work jetiform present, one obtains the General Contractor for the vorters one violation to the General Contractor for the standings had provided to the Concrete Subcontractor for the failure to provide a provided to the Concrete Subcontractor for the failure to provide a provided to the Concrete Subcontractor for the failure to provide a provided to the Concrete Subcontractor for the failure to provide step year in the provided to the General Contractor for the sanding before a stripping operation one violation to the General Contractor for the sanding before a stripping operation one violation to the General Contractor for the sand was provided scaffordi	of control	35377279Y, 35377280L, 35377281N, 35377282P						
//2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the testinal leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all extends of the failure to provide size is used on all extends of the size of t	g ECB Violation  nne nn, to ee-	35377279Y, 35377280L, 35377281N, 35377282P						
72019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fiel-ine on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a metry hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standin on a ladder and stripping formwork when the formw fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECW Violations were issued. Or violation to the General Contractor for the failure to provide a step selection of the bid selection of the General Contractor for the vorkers, one obtains the General Contractor for the vorkers, one obtains the General Contractor for the workers, one work provided in the General Contractor for the standing being operation one violation to the General Contractor for the standing being operation one violation to the General Contractor for the said was practiced from the said was not in accordance with the approved plan. Two partial Stop Work Order (FSWO) were issued one stop all forming and stripping operations, and one to stop all work above the sixty-eventh flort. The General Contractor is to provide a Means and Methods for the said	g ECB Violation  nne nn, to ee-	35377279Y, 35377280L, 35377281N, 35377282P						
//2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the testinal leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all extends of the failure to provide size is used on all extends of the size of t	g ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fiel-ine on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a metry hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installations. The contractors are to design a said design drawing and Means and Methods for window installation.  1 A DOB inspector reported that a worker was standin on a ladder and stripping formwork when the formw fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECW Violations were issued. Or violation to the General Contractor for the failure to provide a step selection of the bid selection of the General Contractor for the vorkers, one obtains the General Contractor for the vorkers, one obtains the General Contractor for the workers, one work provided in the General Contractor for the standing being operation one violation to the General Contractor for the standing being operation one violation to the General Contractor for the said was practiced from the said was not in accordance with the approved plan. Two partial Stop Work Order (FSWO) were issued one stop all forming and stripping operations, and one to stop all work above the sixty-eventh flort. The General Contractor is to provide a Means and Methods for the said	g ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The coveractors are to design an aid design drawings and Means and Methods for window installations. The coveractors are to design a said design drawing and Means and Methods for window installations. The coveractors are to design a said design drawing and Means and Methods for window installations. The coveractors are to design a said design drawing and Means are Methods for window installations. The coveractors are to design a said design drawing and Means are taken to a hospital by ambitance in a conscious state. Five ECB Violations were issued to violation to the General Contractor for the failure to maintain safety measures during a stripping operated as there was no work platform present, one violation the General Contractor for the failure to partial as the state of the safety orientation for the workers, one violation the General Contractor for the failure to partial as the safety orientation for the workers, one violation to the General Contractor for the failure to partial and the safety orientation for the workers, one violation to the General Contractor for the failure to partial and the safety orientation for the workers, one violation to the general Contractor for the safety orientation for general contractor for the safety orientation for general contractors or the safety orientation for the safety orientation fo	g ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The coveractors are to design an aid design drawings and Means and Methods for window installations. The coveractors are to design a said design drawing and Means and Methods for window installations. The coveractors are to design a said design drawing and Means and Methods for window installations. The coveractors are to design a said design drawing and Means are Methods for window installations. The coveractors are to design a said design drawing and Means are taken to a hospital by ambitance in a conscious state. Five ECB Violations were issued to violation to the General Contractor for the failure to maintain safety measures during a stripping operated as there was no work platform present, one violation the General Contractor for the failure to partial as the state of the safety orientation for the workers, one violation the General Contractor for the failure to partial as the safety orientation for the workers, one violation to the General Contractor for the failure to partial and the safety orientation for the workers, one violation to the General Contractor for the failure to partial and the safety orientation for the workers, one violation to the general Contractor for the safety orientation for general contractor for the safety orientation for general contractors or the safety orientation for the safety orientation fo	g ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The coveractors are to design an aid design drawings and Means and Methods for window installations. The coveractors are to design a said design drawing and Means and Methods for window installations. The coveractors are to design a said design drawing and Means and Methods for window installations. The coveractors are to design a said design drawing and Means are Methods for window installations. The coveractors are to design a said design drawing and Means are taken to a hospital by ambitance in a conscious state. Five ECB Violations were issued to violation to the General Contractor for the failure to maintain safety measures during a stripping operated as there was no work platform present, one violation the General Contractor for the failure to partial as the state of the safety orientation for the workers, one violation the General Contractor for the failure to partial as the safety orientation for the workers, one violation to the General Contractor for the failure to partial and the safety orientation for the workers, one violation to the General Contractor for the failure to partial and the safety orientation for the workers, one violation to the general Contractor for the safety orientation for general contractor for the safety orientation for general contractors or the safety orientation for the safety orientation fo	g ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all file-line on the exterior leading edge when he hyperextended his elbow will setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found the life-line was found to not be an effective flat arrest system. An Et Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The coveractors are to design an aid design drawings and Means and Methods for window installations. The coveractors are to design a said design drawing and Means and Methods for window installations. The coveractors are to design a said design drawing and Means and Methods for window installations. The coveractors are to design a said design drawing and Means are Methods for window installations. The coveractors are to design a said design drawing and Means are taken to a hospital by ambitance in a conscious state. Five ECB Violations were issued to violation to the General Contractor for the failure to maintain safety measures during a stripping operated as there was no work platform present, one violation the General Contractor for the failure to partial as the state of the safety orientation for the workers, one violation the General Contractor for the failure to partial as the safety orientation for the workers, one violation to the General Contractor for the failure to partial and the safety orientation for the workers, one violation to the General Contractor for the failure to partial and the safety orientation for the workers, one violation to the general Contractor for the safety orientation for general contractor for the safety orientation for general contractors or the safety orientation for the safety orientation fo	g ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						



cident Date		Address Number	Street	Fatalities Injur	ies EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
11/2019	Queens	35-27	30 AVENUE	0	1 A DOB inspector reported that a worker was pulling wire through a conduit when the worker leaned on a pipe clamp, which caused the conduit to give way and hit the worker in the head. The worker was taken to a hospital by an ambulance in order to receive stitches. The inspector determined that the incident was caused by a worker's error, and that no enforcement action wa necessary.	No Action Necessary			ALT-1	420652751	Other Construction Related Incidents	30TH AVE REALTY PARTNERS LLC	WHITE CONSTRUCTION & RENO.
1/2019	Brooklyn	555	4 AVENUE	0	1 The Site Safety Coordinator reported that a worker slipped on the fourth floor due to the presence of ice. The worker refused medical attention and went to a noepital on his own. A DDS inspector responded to the incident and reported that the incident was caused by worker's error, as the worker slipped. The Site Safety Coordinator stated that there was no evidence of the worker's error, as the worker slipped. The Site Safety Coordinator stated that there was no evidence of the worker falling. No enforcement action was necessary.	No Action Necessary			NB	321238264	Other Construction Related Incidents	PARTNERS VII/541-555 FOURTH OW	DYNATEC CONTRACTING
2/2019	Manhattan	76	11 AVENUE	0	1 The Site Safety Manager reported that a worker fell for feet from a baker scaffold and hurt his shoulder. An ambulance was called. A Dol Sinspector responded to the incident and reported that the scaffold did not have outriggers in place and that the worker fell because his place and that the worker fell because his langvard came loose. An ECB Violation was issued for a failure to institute safety measures. A full Stop Work Torder (FSWO) was issued on all baker scaffold and perimeter work. A DOB Violation was site. Sissued. The General Contractor is to provide a Means and Methods and Design Drawings for the anchor poin and to prevent future injuries from occurring.	s	35377206N	021219CE04SK01	NB	121190308	Worker Fell	76 ELEVENTH AVENUE PROPERTY OW	OMNIBUILD CONSTRUCTION INC
3/2019	Manhattan	40	EAST END AVENUE	0	The Site Safety Manager reported that a worker was walking in the basement when he lost his balance, tripped, and hurt his knee. The worker was not carrying anything at the time that he was walking. An ambulanc was called.				NB	121190120	Worker Fell	40 EAST END AVE. ASSOCIATES LL	BRAVO BUILDERS LLC
3/2019	Manhattan	550	WEST 34 STREET	0	A DOB inspector reported that a worker was working of a ladder when he became startled by an electrical arc and a crackling noise, which caused him to fall off of the ladder. The worker was taken to a hospital. The inspector determined that no enforcement action was necessary.	No Action Necessary					Worker Fell	ONE HUDSON YARDS OWNER LLC	
3/2019	Staten Island	55 B	RICHMOND TERRACE	0	The Site Safety Manager reported that a worker was walking in the basement when he lost his balance, tripped, and hurt his knee. The worker was not carrying anything at the time that he was walking. An ambulanc was called.	,					Other Construction Related Incidents	ST. GEORGE OUTLET DEV LLC	EMPIRE OUTLET BUILDERS
k/2019	Manhattan	100	FRANKLIN STREET	0	1 A DOB inspector reported that a worker was using a ginder to grind brick on a exterior wall when the grinder kicked back and cut the worker's left arm. The worker was stransported to New York Downton Hospita by an ambulance to receive stitches. The worker was a possession of a proper ten hour OSHA card and a scaffold training card. However, the worker did not sight the safety training log. An Aggrarated Level 2 ECB Violation was issued for the failure to provide evidence of workers attending a construction and safety course.	i n	35377261M		NB	121185993	Other Construction Related Incidents	DDG 100 FRANKLIN LLC	DDG DEVELOPMENT LLC
/2019	Manhattan	125	GREENWICH STREET	0	1 A DOB inspector reported that a worker was spreading rock sait on a stair in a building where both stairways had ice present at many places between the sixty-third and seventy-fourth floors. The worker slipped on ice and fell on his back. The on-sixt medic checked out th worker and then sent the worker to a hospital to reach can be sent to a hospital by reach and worker and then sent the worker to a hospital to reach an arisk with hadrened cement and tripping hazards present at several places. Two ECB Violations were issued: one violation for a failure to maintain safety measures, as there was ice on the floor that was not removed, and one ECB Violation for a failure to maintain adequate housekeeping. A partial Stop Work Order (FSWO) was issued on all work between the sixty-third and seventy-fourth floors. The General Contractor is to provide a Means and Methods for the safe operation of the job	e e	35296571R, 35296572Z		NEW BUILDING	121183799	Worker Fell	VS 125 LLC	PLAZA CONSTRUCTION LLC
14/2019	Manhattan	250	SOUTH STREET	0	A DOB inspector reported that a pedestrian woman we struck in the face by lumber that was being loaded ont a truck. The woman was examined by the on-site medic. An ambulance was not called. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued for all loading and unloading o materials and debris. A DOB Violation was also issued.	n 1	35377331M	021419CE03JK03			Other Construction Related Incidents	NAME NOT ON FILE	LENDLEASE(US)CONSTRUCTION



	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/2019	Manhattan	500	WEST 33 STREET	0	1 A DOB inspector reported that a worker was installing sheetrock inside of the elevator shaft of the 13 and J2 elevator banks on the forty-lifth floor when a piece of metal stud that was stored near the shaft fell from above and hit the worker on his hard hat. The worker suffered a laceration to his nose and was taken to a hospital by an ambulance to receive treatment. The inspector found that metal studes and debris were also stored near the edge of the shaft. Two ECB Violations were issued: one violation for a failure to maintain safety measures during a construction operation, as a worker was injuried by material that fell from above, and one violation for a failure to institute adequated to worker was injuried by material that fell from above, and one violation for a failure to institute adequated to work the state of the shaft of th		35382749Y, 35382749X				Material Fell	NAME NOT ON FILE	
/2019	Manhattan	501	west 18 street	0	1 The Site Safety Manager reported that a worker on the fourth floor of the west building was hit by a piece of plywood while other workers were bringing stripping consite medic and was then taken to Bellevue Hospital by an ambulance. The worker had already returned to work as of the time of inspection. OSHA Cards, a Tool Box Task, a Site Safety Plan, a daily safety talk, and Site Safety Manager logs were all provided. It was determined that this incident occurred as the result of a worker's error, and that no enforcement action was deemed necessary.				NEW BUILDING	121191147	Material Fell		RELATED CONTRUCTION I.L.C
/2019	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a worker was pushing a mini container. The mini container was tipping, and the worker injured his shoulder while trying to hold the mini container. The injured worker went to a clinic.	No Dispatch			INTERIOR FITOUT	140716839	Other Construction Related Incidents	SMITELL SPONSOR LLC	JT MAGEN & COMPANY INC
/2019	Manhattan	145	WEST 47 STREET	0	1 The Site Safety Manager reported that a worker came to work with a previous foot injury that was not reported. The worker injured the same foot while climbing up a ladder. The worker was limping. The worker's supervisor took him to a doctor.	No Dispatch			NEW BUILDING	121187802	Other Construction Related Incidents	CLARITY 47 LLC	TB USA, L.L.C
i/2019	Brooklyn	10	NEVINS STREET	0	The Site Safety Manager reported that a worker was pushing a mini container and hurt her shoulder while trying to prevent the mini container from tipping over. A co-worker walked the injured worker to a clinic for a check up.	No Dispatch			NEW BUILDING	320915579	Other Construction Related Incidents	NEVINS STREET OWNER LLC	DANYA CEBUS CONSTRUCTION
5/2019	Bronx	556	BERGEN AVENUE	0	1 A DOB inspector reported that during the installation of pro-cast sections on the third flor, an ion worker was hit in the shoulder and then lost his balance and fell. The worker was wearing his Personal Fall Protection (PFP) equipment, which prevented the worker from hitting the ground. However, the fall protection equipment left the worker suspended and bouncing from side to side, and the worker has else column. The worker was taken by an ambulance to Lincoid Hospital to receive treatment. The worker do not suffer any broken bones. An ECB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35377451R		NB	220151859	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONSTR.ADEV.CORP
2019	Manhattan	151	EAST 86 STREET	0	1 A DOB inspector reported that a worker was installing a building storefront at the second floor level when he fell approximately lifteen feet from a sidewalk shed. The worker was tied of listing his harmess, and there were concrete-embedded anchors present to serve as fall protection. The worker fell between the store front and the construction fence, but did not hit the ground, as he was suspended by his Personal Fall Protection (PPP) equipment. The worker was conscious and was taken to a hospital by ambulance. The status of his injuries is not known. An ECB Violation was issued for the failure to provide a pre-shift safety meeting. A partial Slopp Work Order (PSWO) was issued on all store front installations.		353773361		NB	122668648	Worker Fell	NAME NOT ON FILE	Gibane residential
18/2019	Brooklyn	474	FULTON STREET	0	I A DOB inspector reported that a section of sidewalk fence had fallen and struck a pedestrian sidewalk had one had fallen and struck a pedestrian sidewalk had one year. The injured pedestrian was taken to a hospital with unknown injuries. Permits had been issued at the site for interior and exterior work, but no work was being done on the date of the incident. The New York City Fire Department removed the remaining sections of the sidewalk fence and stacked the phywood sections against the building. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard. A	ECB Violation	35375422Z	021819CNEDG01	ALTERATION TYPE 2	321724960-01-EW-OT	Material Fell	NAME NOT ON FILE	TOM RECTENWALD CONSTRUCTI
					partial Stop Work Order (PSWO) was issued for all exterior work. A DOB Violation was also issued.								

cident Date		Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
18/2019	Manhattan	233	WEST 125 STREET	The Site Safety Manager reported that a worker was				NEW BUILDING	121187447-01-NB	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
				handing up material when the material fell back and h the worker on his head. The worker was wearing a ha	rd							
				hat. The worker was transported to a hospital by ambulance.								
9/2019	Bronx	1560	BOONE AVENUE	A DOB inspector reported that a worker was on a bake scaffold that did not have the wheels locked. The worker was performing taping work when the baker		35377653K, 35377654M		NEW BUILDING	220152876	Worker Fell	SAMARITAN-COMPASS III & IV HOU	MONADNOCK CONSTRUCTION IN
				scaffold started to roll and the worker fell approximatel four feet. The worker was found conscious and was taken to a hospital by an ambulance with unknown								
				injuries. The scaffolding was removed from the location before the inspector arrived. Two ECB Violations were issued: one violation for the failure to maintain safety	·							
				measures, as the baker scaffolding that was being us did not conform to the manufacturer's specification, which resulted in an injury to a worker, and one violation for the tampering with the evidence of an incident, as the baker scaffold involved in the accident								
				was removed before the DOB inspector arrived at the site. A partial Stop Work Order (PSWO) was issued to stop the use of baker scaffolding.								
19/2019	Manhattan	505	WEST 43 STREET	0 1 A DOB inspector reported that a worker was carrying	a No Action Necessary			NEW BUILDING	121187456	Worker Fell	1818 NADLAN LLC	NEW LINE STRUCTURES & DEV
				bucket of liquid waterproofing material while walking down the stairs from the fourth floor to the third floor when she either lost her balance, or missed a step, ar fell to the floor. The worker did not appear to have any	d							
				visible injuries, but was taken to a hospital. The stair was dry, there was no ice or water present, and there were no tripping hazards present. No enforcement action was deemed necessary.								
19/2019	Queens	147-40	ARCHER AVENUE	The Site Safety Manager reported that a worker came to work with lower back pain that was not job-related, but did not report the back pain and continued to work	.			NEW BUILDING	420654508	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	CNY CONSTRUCTION LLC
				At lunch time, the worker felt severe pain in his back. co-worker called the ailing worker's son to take him home, and the ailing worker's son called an ambulanc								
21/2019	Manhattan	305	WEST 48 STREET	A DOB inspector reported that there were workers that     were stripping formwork inside of the stair shaft. One     the workers was passing materials to another worker.	of	35377455Y, 35377456X		NEW BUILDING	121203786	Material Fell	BRIGHT MGMT CP	JOY CONSTRUCTION
				The recipient worker was receiving a piece of wood when he lost control of the piece of wood, causing it to fall and hit a worker below on the head. The injured worker was experiencing headaches and was taken to								
				hospital. Two ECB Violations were issued: one violatic for the failure to safeguard persons and property, as a worker was injured during a stripping operation due to	n							
				unsafe material handling, and one violation for the absence of a design drawing for a makeshift work platform that was erected inside of the stair shaft. A partial Stop Work Order (PSWO) was issued on all								
				stripping operations and the use of a makeshift work platform. The General Contractor is to provide a Mear and Methods, along with a safety orientation for workers, for the safe operation of the job.	s							
1/2019	Brooklyn	123	LINDEN BOULEVARD	A DOB inspector reported that there were workers that were working on support of excavation inside of a trench. The workers were dropping materials inside of		35377476N		NEW BUILDING	321208603	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS LLC
				the trench when a piece of wood hit a worker on his foot. The struck worker was taken to a hospital by ambulance. Two ECB Violations were issued: one								
				violation for the failure to safeguard persons and property, as a worker was injured due to unsafe material handling and one violation for the presence o inadequate housekeeping, as ice and snow was not								
				removed from the job area. A partial Stop Work Order (PSWO) was issued on all work inside of the trench and vaults. The General Contractor is to provide a Means and Methods for the safe operation of the job.								



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/22/2019	Manhattan	545	WEST 30 STREET	0	I A DOB inspector reported that a worker was installing electrical conduits and straps when he knocked over a cordiese drill that he was using, causing the drill to hit another worker that was below him in the head. The struck worker was at the bottom of a ladder that was approximately fifteen feet and was not wearing Personal Protection Equipment (P P E) when he was struck. The struck worker sustained an approximate one and a half inch cut to his head. The worker was found conscious and was treated by the medic personnel at the site before he was sent to Mount Sinai Hospital for additional treatment. An EOR Violation was issued for a radiure to provide safety measures. A partial Stop Work Order (PSWO) was issued on conduit installations on the second floor.		3537700Y		NB	121184208	Worker Fell	15 HUDSON YARDS CONDOMINIUM	Hudson Yards Construction
2/25/2019	Manhattan	1250	BROADWAY	0	2 A DOB inspector reported that a two-by-four hit and shattered one window on the twenty-first floor, and two windows on the twentieth floor, before landing on the thriteenth floor set back, where two workers were working. The two workers were struck and sustained wrist and shoulder injuries. It was not clear if the workers were struck by the falling two-by-four or by the glass from the shattered windows. Both injured workers were struck by the falling two-by-four or by the clear two the shattered windows. Both injured workers were sent to a hospital for a check up it could not be determined where the two-by-four fell from. A DOB Violation was issued to the building for the building being in a non-code compliant manner.				ALTERATION	123674737	Material Fell	1250 BROADWAY ASSOCIATES LLC	CAVAN BUILDERS CORP
2/25/2019	Manhattan	47	WEST 86 STREET	0	A DOB inspector reported that a section of parapet wall on the right side of the building was taken down by the wind. The Construction Superintendent at the site, as well as the New York City Police Department, reported that a pedestrian that was walking by suffered a few scratches. However, the object that caused the scratches to the pedestrian could not be verified. An ambulance was not called, and the pedestrian left the steen on his own. Two ECB Voliations were issued: one violation for a failure to safeguard, as the parapet wall was not adequately braced or secured in place, and one violation for a failure to maintain, as there were uncapped protruding botts present.		35353576Y 35353575M				Scaffold/Shed/Fence/Shoring/Installation	47 WEST 86TH STREET C	Viad RESTORATIONS
2/26/2019	Manhattan	545	WEST 30 STREET	0	A DOB inspector reported that a worker was working on the sixth floor, near the secalator on the south side corridor, when he tripped on a piece of phywood that was being used to cover the finished floor. The phywood was not leveled, which created at pripping hazard. The worker's knee was hit. The on-site medic treated the injured worker and sent the worker to urgent care. A similar floor cover was also being used on the second and fourth floors in addition to the sixth floor. The injured worker did not go through the site specific safety orientation that was provided by the Site Safety Manager. Two ECB Violations were issued: one violation for a failure to maintain safety measures, as the worker was injured on a tripping hazard, and one violation for a failure to provide a site-specific safety orientation to the worker on the site. The General Contractor is to provide a Neans and Methods for the safe operation of the site.		36377460Z, 36377461K		ALTERATION-1	121192397	Worker Fell	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
2/27/2019	Brooklyn	535	4 AVENUE	0	A DOB inspector reported that a worker was removing windows from a delivery truck that was parked on the job site when one of the windows fell on his feet. The worker suffered an injury to his ankle and was taken to Methodst Hospatal by an ambulance. An ECB Violation was issued for a failure to safeguard all persons and property. A parial Stop Work Order (PSWO) was issued on all material handling and delivering. The General Contractor is to provide a Means and Methods.		35376771L		NB	320626612	Other Construction Related Incidents	XYZ PROPERTIES INC	DYNATEC CONTRACTING INC
2/28/2019	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker was pulling an "A"-Frame that had sheetrock on it out of an out-of-service elevator when the "A"-Frame tipped over and pinned the worker to a wall. The worker went to a hospital on his own for a checkup.				ALT-2	140716839	Other Construction Related Incidents	SMITELL SPONSOR LLC	JT MAGEN & CO.



Incident Date	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/28/2019	Manhattan	22	EAST 38 STREET	0	1 A DOB inspector reported that at an existing nineteem story alteration building, a worker was torching a boiler shell to cut it when he fell. The worker was taken to a clinic. The incident occurred on February 28, 2016, but was reported on the following day, March 1, 2019. Three CSB Victations were issued: one violation for a failure to maintain safe operations, one violation for the injured worker not attending the pre-shift safely meeting, as the worker's signature was not on the meeting signing sheet, and one violation for the failure by the Site Safety Manager to notify the Department Of Buildings of the incident in a timely manner. A partial Stop Work Order (PSWO) was also issued.	ECB Violation	36363747Z/48K/49M		Alt-1	123432605	Worker Fell	JOLLY HOTELS U.S.A., INC.	Newgrange Construction CO
//28/2019	Manhattan	250	SOUTH STREET	0	1 A DOB inspector reported that a pipe filter/sprinkler worker was climbing a six foot ladder when he hit his head on a door metal frame and suffered a neck injury. The worker had his hard hat on. The worker visited the on-site medic. The medic reported that the injured worker did not have any brusses or apparent injuries, but that the worker stated that he was not feeling well, that his neck was injured, and that he had an existing neck injury. An ambulance was called to take the injured worker to a local hospital. The Site Safety Manager's daily top book was up to date. The area where the incident occurred had been cleaned. It was determined that this incident occurred as the result of a worker's error, and that no enforcement action was deemed necessary.	No Action Necessary			NB	121186528	Other Construction Related Incidents	NAME NOT ON FILE	
/28/2019	Manhattan	542	WEST 22 STREET	0	1 A DOB inspector reported that a worker was using an "A"-Frame cart to move material when the worker sigped on ice and hurt his right knee. The injured worker suffered minor injuries and was taken to a hospital by ambula		35377465Н		nb	122547583	Worker Fell	HELZEN ASSOCIATES ,	Westerman Construction
1/2019	Manhattan	646	11 AVENUE	0	1 A DOB inspector reported that there were workers preparing to start a drilling operation and they were checking and testing the machine as part of preparation. A worker accidentally opened the valve of preparation. A worker accidentally opened the valve of water hose by mistake, and the water hose exploded, hitting him in the stomach and throwing him to the wall. The worker was conscious and was taken to Bellevue Hospital for retainment. The worker was reported to have treatment and doing fine. An ECB Violation was issued for a failure to maintain safety measures, as the worker was injured due to the explosion of a water hose. A partial Stop Work Order (PSWO) was also issued.		35377503.J		NEW BUILDING	121204302	Mechanical Construction Equipment	646 11TH OWNER LLC	CM AND ASSOCIATES CONSTRU
3/1/2019	Manhattan	590	EAST 83 STREET	0	1 A DOB inspector reported that during a delivery operation, a forkilit pushed approximately three to four pieces of sheetrock that fell and struck a worker or his waist. An ambulance was called. The worker's condition was not known as of the time of inspection. An EGD Violation was issued for the failure to maintain safety operations at the site. A partial Stop Work Order (PSWO) was issued for all delivery operations. A DOB Violation was also issued. Additional violations unrelated to the incident were also issued.	ECB Violation	35353580R	030119CE08CV01	NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W HOWELL LLC
3/1/2019	Manhattan	545	WEST	0	The Site Safety Manager reported that a laborer was installing winches in the mechanical room when he misstepped and bended his knew. The worker was treated by the on-site medics and was sent to a hospital for observation. A DOB inspector responded to the incident and reported that this incident occurred as the result of a worker's error. No enforcement action was necessary.						Other Construction Related Incidents		
3/2/2019	Queens	22-18	JACKSON AVENUE	0	1 A DOB inspector reported that during a delivery operation, a forkilit pushed approximately three to four pieces of sheerock that fell and struck a worker or his waist. An ambulance was called. The worker's condition was not known as of the time of inspection. An ECB Violation was issued for the failure to mantain safety operations at the site. A partial Stop Work Order (PSWO) was issued for all delivery operations. A DOB Violation was also issued. Additional violations unrelated to the incident were also issued.	ECB Violation	35377481H	030219CE02MS03			Other Construction Related Incidents	22-12 JACKSON OWNER LLC	BRIT REALTY LLC



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2019	Manhattan	22	NORTH LOOP ROAD	0 1	The Site Safety Manager reported that there were workers using a hammer to perform column form work when a worker was accidentally hit in the eibbow by the hammer. The injured worker went to a hospital on his own. An ambulance was not called.	No Dispatch			NB	121203697	Other Construction Related Incidents	NAME NOT ON FILE	HUNTER ROBERTS CONST
019	Bronx	785	COURTLANDT AVENUE		The Site Safety Manager reported that a worker was moving a plank from a sidewalk shed when it slipped from his hands and landed on his foot. An ambulance was called.	No Dispatch			alt-2	240225788	Other Construction Related Incidents	NYC HOUSING AUTHORITY	neelam Construction Corp
019	Manhattan	215-225	west 28 st		The Site Safety Manager reported that a worker twisted his back while lifting a piece of plywood. The worker was taken to an area hospital by ambulance for observation.	No Dispatch			nb	121185813	Other Construction Related Incidents		HAP Construction LLC
019	Manhattan	36	WEST 66 STREET		The Site Safety Manager reported that a worker tripped and cut his lip. The worker went to a City M.D. An ambulance was not called.	No Dispatch			nb	121190200	Other Construction Related Incidents	WEST 66TH SPONSOR LLC	Lendlease
019	Manhattan	68	SPRING STREET		A DOB inspector reported that a worker stepped on a nail and sustained a puncture wound on his foot. The worker elected to go to a local hospital. No hazardous conditions were found, and all safety measures were in effect. No enforcement action was deemed necessary.						Other Construction Related Incidents	68-70 SPRING PARTNERS LLC	
019	Queens	Mar-50	ST NICHOLAS AVENUE		The Site Safety Manager reported that a worker was carrying a length of curved rebar when the rebar hit the worker in the back. The worker went to a local urgent care center for treatment. This incident occurred at 2:00 PM, but was not reported until later in the day at 5:30 PM				A2 - ALTERATION TYPE 2	421066633	Other Construction Related Incidents	RIDGEWOOD TOWER LLC	AB CAPSTONE BUILDERS CORP
019	Manhattan	2306	3 AVENUE		The Site Safety Manager reported that a worker in the machine room was using equipment when he was shocked by an extension cord. The worker went to a hospital by ambiliance for evaluation. A DOB inspector responded to the incident and reported that there were no unsafe electrical conditions observed. No enforcement action was deemed necessary.	No Action Necessary			NB	121190326	Other Construction Related Incidents	SALVATION ARMY	MEGA CONTRACTING GP LLC
019	Manhattan	461	WEST 34 STREET		The Site Safety Manager reported that a worker tripped over the black hose of a fire extinguisher and twisted his ankle. The worker went to a medical center across the street for treatment. An ambulance was not called.	No Dispatch			nb	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	Atria Builders LLC
2019	Manhattan	86	DELANCEY STREET		A DOB inspector reported that a section of construction persey barrier with the fence fell on the street and hit a pedestrian pizza delivery man. The incident occurred because a gust of wind gushed and knocked the construction jersey barrier onto the street. The fujured pedestrian was wearing a helimet, but the construction equipment studies him in his lower legs. An embulance was neithed at the pedestrian elegs, and embulance was neithed. The GEB Morphoder legs, and embulance was failed, all the GEB with the pedestrian elegation for the pedestrian street, and property, and one violation for the failure to maintain a jersey barrier in a code compliant manner, as the jersey barrier sections were not flied with water. A partial Stop Work Order (FSWO) and a DOB Violation were also issued.	,	35411900j -35411901I	031119ce103cs01	NB	122141351	Material Fell	ORDELA LLC	Town house Builders Inc
2019	Queens	29-23	QUEENS PLAZA NORTH		A DOB inspector reported that a worker was using a ladder to climb out of an approximately twele foot deep hole when the worker slipped and fell off of the ladder. The worker suffered a hip nijury and was taken to an area hospital by an ambulance for observation. Two ECB Violations were issued: one violation for a failure in institute safety measures at the construction site, and one violation for the absence of shoring in the excavated hole. A full Stop Work Order (FSWO) and a DOB Violation were also issued. A Means and Methods, a Tool Box Talk, and shoring for the pit must be provided.	d	35363845M,35363846Y		nb	421490069	Worker Fell	QPP ILC	Hunter Roberts
2/2019	Bronx	600	BERGEN AVENUE		The Site Safety Manager reported that a worker was climbing off of a scaffold when his pinky finger was pinched in a scaffold cross brace. The finger was swelling, and the worker went to a local clinic to receive treatment.	No Dispatch					Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
2019	Manhattan	301	PARK AVENUE	0 1	The Site Safety Manager reported that a worker was exiting a doorway when he hit his head and suffered a minor abrasion. The worker walked to a hospital and received stitches for a minor cut. An ambulance was not called.	No Dispatch			Alt 1	121191245	Other Construction Related Incidents	NAME NOT ON FILE	Tishman Construction Corp
/2019	Manhattan	15	EAST 30 STREET		The Site Safety Manager reported that a plumber was cutting a pipe when he received a cut on his thumb.  The worker walked to a City M.D. on his own to receive				New Builidng	122128679	Other Construction Related Incidents	MADISON 30 31 OWNER LLC	Madison 3031 Owner LLC
/2019	Manhattan	22	NORTH LOOP ROAD		treatment.  The Site Safety Manager reported that an electrician tripped and fell on the nineteenth floor deck and cut his chin on rebar. The electrician walked himself to an urgent care center on his own. An ambulance was not	No Dispatch			New Building	121203697	Other Construction Related Incidents	NAME NOT ON FILE	HUNTER ROBERTS CONST. GRP

Borough			Fatalities Injuries	EOC Final Description		ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
Queens	23-15	44 DRIVE	0	was using a knife to strip insulation from wires when he knee was cut by the knife. The electrician went to	No Dispatch			NEW BUILDING	420655954	Other Construction Related Incidents	BGY CITYVIEW LLC	NEW LINE STRUCTURES & DEV
Manhattan	200	AMSTERDAM AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NB	122887224	Worker Fell	AMSTERDAM AVENUE REDEVELOPMENT	PAVARINI MCGOVERN LLC
Manhattan	\$45	WEST 30 STREET	0	1 The Site Safety Manager reported that a rubber air conditioning shim fell approximately one hundred feet from the above work area, bounced off of a boom lift, and then struck a worker on both of his knees. The worker reportedly went to a local urgent care center, the worker reportedly the modern and the proper and the structure of the structu	No Action Necessary			GENERAL CONTRACTOR	GC 613954	Material Fell	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
Brooklyn	24	BRIDGE PARK DRIVE	0	installing a door at the site. The door that was to be installed was learning against a wall prior to the installation. While a taper/shop steward of the painting contractor at the site was walking by, the door fell on him and struck him on his lower leg and ankle. The struck worker did not have a visible injury, but complained about pain and was transported to a hospital by an ambulance. An ECB Violation was issued.	i.			NEW BUILDING	321189003	Material Fell	NYC DSBS	SUFFOLK CONSTRUCTION COMP
Brooklyn	11	HOYT STREET	0	The Site Safety Manager reported that a plumber was installing sprinkler pipes when he felt dizzy while coming down from a ladder and accidentally hit his head by a bettery operated screw gun. An ambulance was called, and the worker walked to the ambulance and was then taken to a hospital.	No Dispatch			ALTERATIO -1	321197059	Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	TRITON CONSTRUCTION CO.,
Brooklyn	135	EMERSON PLACE	0	was in a garbage truck snapped and a piece of the skid debris fillew out of the truck and his a worker in heack knocking him out. This happened when the crush gate came down on the skid. The worker was dazed and confused. An ambulance was called to the site. A DOB inspector responded to the incident and reported that the garbage truck involved in the incident was not on site, and that there was no evidence of the piece of skid	i i	35363980P 35363979H	031919CE02IH03,02	NB	321183367	Other Construction Related Incidents	PRATT INSTITUTE	TISHMAN CONSTRUCTION CORP.
Manhattan	36	WEST 66 STREET	0	The Site Safety Manager reported that a worker fell on his hand and suffered a cut to his palm. The worker went to a City M.D. for observation.	No Dispatch			NB	121190200	Other Construction Related Incidents	THIRTY SIX WEST THIRTY SIX ASS	Lendlease us Construction
Manhattan	49	CHAMBERS STREET	0	moving heavy packages on a dolly. As the workers wer turning the dolly towards the parking lot at the Chambers Street gate, the workers lost control of the dolly, and all of the packages fell. The packages struck a pedestrian on his elbow and on his feet. The inspecto reported that construction activity had been observed or the first through fifth filtors and that the floors above the fifth floor were occupied. However, it was observed that The transport of the structure of the structure of such as the structure of petiting mind by at the site because the workers were using the Chambers Street entrance, which was for treand use only. Four ECB Violations were issued: one violation for the presence of an inadequate tenant protection plan, one violation for the presence of	o r n o	35403928L, 35403929N, 35403932Y, 35403933Y	032019CE01BG01/02/03/04	ALTERATION-1	121186821	Material Fell	A	NY DEVELOPERS & MANAGEMEN
	Manhattan  Manhattan  Brooklyn  Brooklyn  Brooklyn	Manhattan   200	Queens         23-15         44 DRIVE           Manhattan         200         AMSTERDAM AVENUE           Manhattan         545         WEST 30 STREET           Brooklyn         24         BRIDGE PARK DRIVE           Brooklyn         11         HOYT STREET           Brooklyn         135         EMERSON PLACE           Manhattan         36         WEST 66 STREET	Manhattan   200	Develop	December   23-15   44 EPRINE   0   1   The data Study Manager recorded that an electrical by the study of the control of of	Daniel  August 19	Committee   Comm	Devent 1940 of 1950 of	District	Direct   D	Description



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/19/2019	Queens	36-02	34 AVENUE	0	1 A DOB inspector reported that a worker lost his left thumb while using a masony westsaw machine to cut concrete bricks. The worker was taken to a hospital, where his condition is not known as of this time. The Construction Superintendent at the site stated that the worker had started working on Thursday, March 14, 2019 and that the worker was in possession of an OSHA card, but the Construction Superintendent also stated that he did not know if the worker was trained to operate masonry wetsaw equipment. Two ECB Vollations were issued: one volcation for a failure to provide hands-on equipment training, and one violation for a failure to asseguand. A partial Stop Work Order (PSWO) for all masonny cutting operations and a DOB Violation were also issued.	ECB Violation	35403805L-35403806N	031919CE01RV01	NB	421368166	Worker Fell	ASTORIA ON STAGE, LLC	URBAN ATELIER GROUP LLC
3/20/2019	Bronx	3500	PARK AVENUE	0	1 A DOB inspector reported that a worker was using a pump to pour cement groul into a concrete masonry unit wall when the hose got blocked, which caused pressure to build up inside of the hose. The pressure inside of the hose are sudenly released, and the hose knocked the worker down, hit him in the head, and caused him to fail down approximately two feet from one scaffolding dick to the next level. The worker was taken to a hospital by an ambulance, where he was reported to have been responding to treatment and in be okay condition. The pump was removed from the scane before the inspector arrived at the site. Five CS (Violations were issued: one violation for a failure to safeguard persons and property, as a worker was injured due to defective equipment, equipment that caused the incident, one violation for the presence of sidewalk shed posts on a roadway that were not adequately protected against the accidental impact from moving vehicles, one violation for the presence of sidewalk shed posts on a roadway that were not adequately protected against the accidental impact from moving vehicles, one violation for the presence of violations for poor housekeeping. A full Stop Work Order (FSWO) was also issued. A Means and Methods must be provided for the safe operation of the job.		35403850K, 51M, 52Y, 53X AND 54H.		NEW BUILDING	220152910	Mechanical Construction Equipment	3500 PARK APTS. HOUSING DEVELO	MEGA CONTRACTING GP LLC
3/20/2019	Queens	27-49	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker sustained a foot injury while walking on the construction site. The worker was transported by a co-worker to a local clinic to receive treatment. This incident took place at 12:30 PM, but was not reported until after 4:30 PM, when the site was afready closed for the day.				NB - NEW BUILDING	421324310-01-NB	Other Construction Related Incidents	27-51 JACKSON AVE LLC	DHC CONTRACTING INC
3/21/2019	Brooklyn	76	SCHERMERHORN STREET	T 0	The Site Safety Manager reported that a worker sustained a cut on his foot from a circular saw. The worker was transported to a local hospital to receive treatment. This incident occurred at 3:30 PM, but was not reported until 4:30, after the site was closed.	No Dispatch			NB - NEW BUILDING	321188086-01-NB	Other Construction Related Incidents		NOBLE CONSTRUCTION GR LLC
3/22/2019	Queens	103-16	CORONA AVENUE	0	1 A DOB inspector reported that a pedestrian woman was bending over to pick up an item when she was struck in the face by siding that bleve over and fell from the site. In the face by siding that bleve over and fell from the site and the site of	ECB Violation	35376053R, 35376054Z, 35376055K, 35376056M	032219CERSM01/SM02/SM03/SM04	NB - NEW BUILDING	420994357-01-NB	Other Construction Related Incidents	DANIELLA R. LLC	OCTAVIO RAPOSO
3/23/2019	Manhattan	545	WEST 30 STREET	0	A DOB inspector reported that on the first floor of the community room, a worker was using a bucket to place concrete when he suffered a minor cut to his right hand. The worker went to a local urgent care center. Ne enforcement action was deemed necessary, as it was determined that this incident occurred as the result of a worker's error.				NB - NEW BUILDING	121184208-01-NB	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
3/26/2019	Manhattan	154	WEST 93 STREET	0	The Site Safety Manager reported that a worker twisted his ankle on the street while stepping on a pallet to receive material. The worker was taken to an area	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
					hospital.		Page 14 of 30						

Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/26/2019	Bronx  Manhattan	700	MORRIS AVENUE  WILLIAM STREET	0	1 The Construction Foreman stated that during the cleaning of a dumpster, the door of the dumpster hit a worker's left leg. The struck worker called for an ambulance, and the ambulance took the worker to a hospital. A DOB inspector responded to the incident and attempted to visit the site, but the site was closed, and the inspector could not conduct an inspection. The inspector will conduct a follow up inspection on March 27, 2019.	No Access	363760702	032719CERSM03	EW -OW  NB - NEW BUILDING	220639487 220639487	Other Construction Related Incidents  Worker Fell	NYC HOUSING AUTHORITY  130 WILLIAM STREET ASSOCIATES	NEELAM CONSTRUCTION CORP
3/2//2019	Manhattan	130	WILLIAM SIKEET	U	1 A DOB inspector reported that a worker was installing rebars at the fifty-sight floor for a forming deck. The worker placed a piece of plywood on the working benth at was approximately 10 X 20 in order to remove rebar to continue the operation. The plywood was not adequately secured, and when the worker stepped on the plywood, the worker fell three feet onto a working deck. The worker was experiencing back pain and was taken to Bellevue Hosphati. All workers' CSHA cards were presented and reviewed, as well as a site series yet log. An Aggranated Level 2 ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (PSWO) was issued for the fifty-sixth floor working deck. A DOB Violation was also issued.		363760/102	US2/19/CERSMUS	NB - NEW BUILDING	121192903-01-NB	Worker Fell	130 WILLIAM SIREET ASSOCIATES	GILBANE RESIDENTIAL CONST
3/27/2019	Manhattan	1558	3 AVENUE	0	2 A DOB inspector reported that there were two workers that were taking a large window out of a crate in order to prepare for an installation when both workers lost control of the window, which caused the window to fall on them. One of the workers twisted his ankle while attempting to get out of the way of the window, and the second worker complained of neck and shoulder pain from getting out of the way of the falling window. Both workers were taken to a hospital as a precaution. An ECB Violation was issued for a fallure to institute safety measures for window operations. A partial Stop Work Order (PSWO) on window prep and installation for the entire safe was also lissued. A Means and Methods for the uncreating and installation of windows must be provided.	,	35403718N		NB	121186518	Material Fell	180 EAST 88TH STREET REALTY LL	DDG development LLC
3/27/2019	Manhattan	77	CHARLTON STREET	0	A DOB inspector reported that there were workers lowering plywood when a piece of plywood slipped out of one of the worker's hands. Another worker saw this happen, and when he went to catch the falling plywood the plywood landed on his foot. The plywood caused some bleeding, and the struck worker's contractor drow min to the other plants of the plant	,	35403719P		NB	121187731	Material Fell	TOLL NY II L.P.	TOLL GC LLC
3/27/2019	Queens	97-12	65 ROAD	0	1A DOB inspector reported that there were workers that were moving a construction fence out into the sidewalk with no pedestrian protection in place, when a pedestrian inspect off of the sidewalk. The pedestrian refused medical attention and left the scene of the modern. For ECB Violations were issued: one violatio for a failure to safeguard persons and property, one violation for the failure to comply with a Site Suffery Plain, one violation for the failure to comply with one violation for the failure to comply with partners of Transportation (DOT) regulations, and one violation for the sidewalk. A partial Stop Work DOT permit to close the sidewalk. A partial Stop Work DOT permit to close the sidewalk. A partial Stop Work DOT permit to violation for the installation of new tences. A Means and Methods to safeguard the public during a sidewalk operation must be provided.	n	35148153R,542,55K,56M.		NEW BUILDING	421644420	Other Construction Related Incidents	RB REALTY CAPITAL LLC	FALCON PACIFIC BUILDERS I
3/28/2019	Manhattan	280	BROADWAY	0	1 A DOB inspector reported that a worker missed a step and twisted his knee. An ambulance was called. No enforcement action was taken, as it was determined that this injury occurred as the result of a worker's erro				ALTERATION-2	122644763	Other Construction Related Incidents	DCAS	LO SARDO GENERAL CONTRACT
3/29/2019	Manhattan	1227	BROADWAY	0	I A DOB inspector reported that there were three to four workers <del>that were attempting to pick up a window. While the window was being lifted, the window slipped out of one of the worker's hands and sliced through the glove that he was wearing, cutting through the skin of the top of the palm side of his right middle finger. The injured worker walked to a City M.D. There were no signs of blood found at the incident site. An ECB Violation was sixed for the failure to institute safety equipment measures. A partial Stop Work Order (PSWO) was issued on all window operations at the site. A DOB Violation was also issued. The Means and Method Dro March and the site installation of curtain wall, and the installation and moving of windows, throughout the job site must be modified so that the incident does not reoccur.</del>		35403721Y Page 15 of 30	032919CE06SK01	NB	121191986	Material Fell	YJL BROADWAY HOTEL LLC	FLINTLOCK CONSTR SERV LLC



Incident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/1/2019	Bronx	3	VYSE AVENUE	0	1 A DOB inspector reported that a worker was dismantling 2" X* 4 wooden frames that were being used for window protection when he tripped, fell, and hurt his knee. An ambulance was called. A DOB inspector responded to the incident and reported that he housekeeping of the work area was not adequately maintained, as there was a tripping hazard present. Construction material and debirs created the hazardous conditions. The site featured supported scaffolding, but the netting on the scaffolding was not secured, as it was flying in the air. A design drawing for the ramp leading to the loading dook was not secured, and the ramp was missing a guardrail and a toe board. An ECB Violation was issued for inadequate housekeeping. Additional ECB Violations and two partial Stop Work Orders (FSWO) were also issued for infractions that were not related to the incident.	ECB Violation			NEW BUILDING	220152581	Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	HLS BUILDERS CORP
4/1/2019	Queens	22-44	JACKSON AVENUE	0	1 A DOB inspector reported that there was a worker that had stacked counter tops in an unsafe manner, which caused one of the counter tops to fall on the worker's leg. An ambulance was called. An ECB Violation was issued for a failure to institute and maintain safety measures. A partial Stop Work Order (PSWO) was issued on all material deliveries and handling. A DOB Violation was also issued. The General Contractor is to provide a Means and Methods for the safe handling of all materials.	ECB Violation	35418147K	040119CE01RV01	NB	420651912	Material Fell	G & M REALTY, L.P.	LRC CONSTRUCTION LLC
4/1/2019	Queens	52-41	CENTER BOULEVARD		2 A DOB inspector reported that during the drilling of caissons, there was a compressor hose unming between two workers. During the operation, the hose between two workers. During the operation, the hose between the workers and to the provide the caused or so the workers and to the provide the caused of the workers and the caused of the workers was taken to a hospital, where he received X-rays, and the second worker remained on the site. A hazardous condition was created because the high pressure hose was running through other workers, as opposed to through an isolated area. The job also featured other unsafe conditions. Five ECB Violations were issued: one Aggravated Level 2 violation to the Concrete Subcontractor for the failure to institute safety measures, as a worker was injured during a drilling operation, one violation to the Concrete Subcontractor for the failure to institute safety measures, are to the superiment that was in use, one Aggravated Level 2 violation to the General Contractor for the equipment that was in use, one Aggravated Level 2 violation to the General Contractor for the failure to institute safety measures. As a worker was injured during a drilling operation, one violation to the General Contractor for the profurance of work without a permit. A full Stop Work Order (FSWO) was also issued. The General Contractor is to obtain an updated Site Safety Plan, and one violation to the Safety Plan and an emporary equipment permit and is to provide and was an updated Site Safety Plan and an emporary equipment permit and is to provide and was an updated Site Safety Plan and an emporary equipment permit and is to provide and was an updated operation of the job.		35403942H, 43J, 44L, 45N AND 46P		NEW BUILDING	420663703	Mechanical Construction Equipment	52-41 CENTER LLC	52-41 CENTER GCLLC
4/4/2019	Manhattan	550	WEST 34 STREET	0	1 The Site Safety Manager reported that a worker got his hand caught between scafdolding and a building, and suffered lacerations to his pinky and ring fingers. The worker was treated by the on-site medic, and was then sent to a nearby medical facility. A DOB inspector responded to the incident and determined that the incident occurred as the result of a worker's error. No enforcement action was deemed necessary.	No Action Necessary					Other Construction Related incidents	ONE HUDSON YARDS OWNER LLC	
4/5/2019	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that an HVAC installer was installer was installer was installer safe when the 277-volt temporary lighting system. Acrong occurred, and the acring burned the worker's clothing. The worker went to a hospital for observation. A DOB inspector responded to the incident and issued two ECB Violations: one violation for the presence of unapproved unsalle wiring, as the acring was caused by the presence of wring that was defective due to a damaged or burned installation, and one violation for a failure to provide a covier of naceplate, as covers were not installed on the spice boxes. Two DOB Violations were also issued.	ECB Violation	35359309R & 35359310Y	040519EE105RH1& 040519EE105RH2			Other Construction Related Incidents	SMITELL SPONSOR LLC	

Incident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	n DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/5/2019		148-10	ARCHER AVENUE	0 1 A DOB inspector regor the ninth floor deck wh extension cord that had of rain. The worker rec ambulance was called Jamaica Avenue Hospi was not notified of the the worker that suffere foreman to relax in the ambulance arrived that	and that a worker was working on the trief to plug in an been exposed to water because been exposed to water because leved an electrical shock. An and the worker was taken to lail. The Site Safety Manager incident until 445 PM. because the shock was told by his shamp! It was not until the the Site Safety Manager was dent. No enforcement action was			, comm		Other Construction Related Incidents	BRP JAMSTA TWO TC OWNER LLC	
4/6/2019	Manhattan	111	VARICK STREET	rebar at the sixteenth fl and dislocated his elbo a crane. An ECB Violat	led that a worker was unloading oor deck when he tripped, fell, w. The load was not attached to ion was issued for unsafe trital Stop Work Order (PSWO) are also issued.	35412141M	040619CE02FB10			Other Construction Related Incidents	111 VARICK ARLINGTON OWNER LLC	CM AND ASSOCIATES CONSTRUCTION
4/8/2019	Bronx	2195	MORRIS AVENUE	working in the baseme and a nail went through himself to a hospital. A incident and *eported construction material a a hazardous condition. backyard was also mis accessible from the ad Violations were issued: maintain adequate hou the absence of a panel Stop Work Order (PS) except for the repairing housekeeping, and the adjoining property and	er reported that a worker was the when he stepped on a 2" X 4" his boot. The worker too. DOB Inspector responded to the hat the area has piles of nd debris present, which created A panel of the fence in the sing, which made the site acount property. Two ECB none violation for the failure to sekeeping, and one violation for of fence from the site. A partial (O) was issued on all work of the fence, the maintaining of installation of protection for the sites. The Gerenia Contractor measures before the Stop Work	35403873N, 74P		NEW BUILDING	220546648	Other Construction Related Incidents	GRAND APTS HOUSING DEVELOPMENT	M. MELNICK & COMPANY INC
4/8/2019	Manhattan	1802	2 AVENUE	removing a spool of ele he lost control of the sy forehead. The truck dri went to a hospital. No o	led that a truck driver was ctrical wire from his truck when cod and hit himself in the wer suffered a minor cut and inforcement action was termined that the incident of a worker's error.	ssary		NB	121191361	Other Construction Related Incidents	OHI ASSET NY 2ND AVENUE, LLC	T.G NICKEL
4/8/2019	Manhattan	287	BROADWAY	performing desteror pail seven feet from a scaff the fifth floor. The work and was taken to a hos inspector responded to total ECB Violations: or sign-off inspection for a absence of a daily insp violation for the absenc sidwalk shed, one viol hour user certification that suffered the injury maintain safety measu present near the wall o violation for the presen Superintendent log, on Contractor for the failus Buildings about the inc Construction Superint Department Of Building Stop Work Order (F28)'s supported scaffording.	er reported that a worker was  tring when he fell approximately office when the fell approximately the violation for the absence of a cardidding, one evidation for the action of scarlfolding, one or dan inspection log for the ation for the absence of a lour or the worker on the scaffold one violation for the failure to exe, as there was no guard rail penings on the scaffolding, one or an inadequate Construction violation to the General et or notify the Department of dent, and one violation to the dent, and one violation to the ga about the incident. A partial (O) was issued on all work on the General Contractor is to lethods for the safe operation of	35403964Z, 65K, 66M, 67Y, 68X, 69H, 70P & 71R		ALTERATION-1	121187624	Worker Fell	NEW 379 BRIDGE, LLC	MAR CONSTRUCTION GROUP IN



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	311	EAST 50 STREET		O A DOB inspector reported that there were two workers that were lowering a suspended scaffold platform in order to take their lunch break. The workers were between the sixth and seventh floro level when a piece of coping stone that was under one of the C-Hooks fell onto one of the workers. The struck worker was rescued by the New York City Fire Department through a window and was transported to a local hospital. The struck worker passed away due to his injuries. The second worker was taken to the hospital for observation, and later returned to the site. Both of the workers were in possession of both sisteen-hour training cards and a Certificate OF Fitness to be on the suspended scaffold. The rigger came to the site and was working on lowering the suspended scaffold platform to the sidewalk shed, and was working on securing a lintel where the two workers were working prior to the incident. A DOB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued.	DOB Violation		040819CE0601MH	ALTERATION TYPE 2 - FACADE	123362217	Material Fell	GREAT BAY BLDG CO.	Vlad Restoration LTD
4/8/2019	Manhattan	815	AMSTERDAM AVENUE	0	1 The Site Safety Manager reported that a worker tripped on the roof and fell, and that the worker injured his pair on a steel structure while trying in find his balance. A co-worker took the injured worker to a hospital for a checkup. A DOB inspector responded to the incident and issued five ECB Violations: one violation for the aliure to institute and maintain adequate safety measures, one violation for the improper storage of materials, one violation for the presence of an inadequate guardrail system, one violation for the absence of guardrails and toe boards from the scaffold, and one violation for the part of the state of the sta		35403909X,10N,11P,12R,13Z	040819CE07CV01,02,03,04,05	NB	123305878	Worker Fell	NAME NOT ON FILE	MJM ASSOCIATES CONSTR. LLC
4/9/2019	Queens	22-18	JACKSON AVENUE	0	A DOB inspector reported that a worker tripped on a hoist ramp and hurt his knee. An ambulance was called. As of the time of inspection, the ramp was in place, and there were no tripping hazards present. No enforcement action was deemed necessary.	No Action Necessary			NB	420655838	Worker Fell	22-12 JACKSON OWNER LLC	BRITT REALTY LLC
4/9/2019	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that a worker was walking by a baker scaffold when he was hit in the head by a piece of railing that had fallen off. The worker was wearing his hard hat. The worker walked to a City M.D. An ambulance was not called. A DOB inspector responded to the incident and reported that there was not walked. A DOB inspector of the worker being hit by a piece of so evidence found of the worker being hit by a piece of so workers of the worker had already left the site as of the time of inspection. No enforcement action was necessary.				AALT-1	120996351	Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	PAVARINI MCGOVERN
4/9/2019	Brooklyn	525	ST MARKS AVENUE	0	1 The New York City Fire Department requested that an inspection please be performed because a worker was injured by falling debris. A DOB inspector responded to the incident and reported that the injury to the worker was minor, and that an ambidance was called and the worker was taken to Kings County Hospital. Two ECB Violations were issued: one volation for the fallure by the permit holder at the site to provide inspection access to the ongoing construction, and one violation to the Construction Superintendent for the failure to perform their duties as per code. A full Stop Work Order (FSWO) and two DOB Violations were also issued.	ECB Violation	35407661J, 35407662L	040919CNEGS01/GS01	DM - FULL DEMOLITION	321633639-01-DM	Other Construction Related Incidents	525 SMA OWNER, LLC	XOLLE DEMO LLC
4/10/2019	Brooklyn	1	PIERREPONT STREET	1	O A DOB inspector reported that there were two workers at a thirsen-story building that were performing brick replacement work underneath the water tank when one of the workers fell from the roof to the grade level. The fallen worker souccumbed to his linguiries. The fallen worker was not using any fall protection system. There was no permit for the brick replacement work, and there was not gradef alia for fall protection systems present. As its safety orientation for working on the perhibuse roof was not provided. A DOB Violation was issued to the owner of the building. A full Stop Work Order (FSWO) was also issued.	9		041019CE0201BG	NA NA	NA	Worker Fell	ONE PIERREPONT STREET CORP	NA
4/11/2019	Bronx	600	BERGEN AVENUE	0	The Site Safety Coordinator reported that a worker scraped his shin while performing work on the fifth floor. The injured worker was taken to a medical center by the site's foreman.	No Dispatch			NB - NEW BUILDING	220151868-01-NB	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP

Incident Date	D	Address Nombre	011	Fatalities Injuries EOC Fina	! December	DOB Action	ECB Violation Numbers	DOB Violation Numbers	D!	Permit No	Incident Type	Owner's Name	Contractor Name
4/11/2019		Address Number	CHARLTON STREET	0 1 A DOB in attempting hoist oper could united leaned a s Frame ca someone stanchion operator s worker dr operator v training ca April 11, 2 was date	respector reported that there were workers ng to unload material out of a hoist car. The restator moved out of the way so that the workers sould the hoist materials. One of the workers stain-chion against railing, and used an "A"- art to hold the stanchion in place. However, bumped the "A"-Frame cart, and the suffered a slight house to his foot, and a co- tove him to MD Care. The injured hoist suffered a slight house to his foot, and a co- tove him to MD Care. The injured hoist was in possession of both a 30-hour CSHA card and a site safety orientation certificate for 2019 (the day that the incident courred). It emmined that the incident courred is the result for servor, and that ne oriforcement action was first servor, and that ne oriforcement action was	No Action Necessary	TO TOWN THINGS	The state of the s	Permit NB	121191263	Material Fell	STRATEGIC GREENWICH EQUITY, LL	PLAZA CONSTRUCTION LLC
4/12/2019	Manhattan	217	WEST 57 STREET	jammed h worker lef An ambuli the previo Manager - electrician	Safety Manager reported that an electrician his fingers while performing drilling. The eff the site and went to receive mergency care. Jance was not called. The incident occurred on ous day (April 11, 2019), but the Site Safety rwas not made aware of the incident until the not forman reported the incident to the Site languager at 11:00 AM on April 12, 2019.	No Dispatch			NB	121328205	Other Construction Related Incidents	SMITELL SPONSOR LLC	LEND LEASE
4/12/2019	Manhattan	441	WEST 37 STREET	workers if from a fill and hit a ja ambulance a hospital the incided in conform sidewalk if caused the storage are Six ECB Valuation for injury to a logistics be violation for not follow violation for the abopement to presence to pedeest also issue amended and mandad and man	Safety Manager reported that there were that were unloading materials and equipment attention and the process of 2.7 4° came loose processian that was in the street. An even were the processian that was in the street. An even were the control of for a checkup. A DOB inspector responded to learn and reported that he size legistics were not made of the control of th		35404010M, 11Y, 12X, 12H, 14J & 15L		NEW BUILDING	122865319	Other Construction Related Incidents	WEST 37TH ST LLC	HAPPY LIVING DEVELOPMENT
4/13/2019	Manhattan	570	BROOME STREET	counterwe Liebberr er snagged te caused th resting po fifteen feet worker. Ti the event. The load vi counter the counter of the nore the assert dismantle DOB Viole parial SIG	rispector reported that that while the 7.5 ton weight of a crane was being loaded with manufactured endiese slings, the load dws by the rigging gear after it had landed, which report the counterveight to be pulled up out of its osotion. The counterweight fell approximately excrushing one worker and striking another the worker that was crushed did not survive. It the counterweight also damaged the carrier, was in the eyesight view of the crane operator. Communication was being used as of the time cident. An assembly meeting was held prior to bed, and the site will be cleared by a forkfilt. Two slations, a Casea lose of Cerl (CIU), and a top Work Order (PSWO) were issued. ECB is are pending issuance as of April 17, 2019.		Pending	SW0041319ML02 CU0041319ML01.	CN	223/19	Mechanical Construction Equipment	SOHO BROOME CONDOS LLC	United Crane and rigging



Incident Date		Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/15/2019	Brooklyn	1443	LINCOLN PLACE	0	The Construction Superintendent reported that a worker was unloading delivered materials on the second floor when he tripped and fell through a hole in the floor, deling to the first floor. The worker was taken to a hospital by an ambulance. A DOB inspector responded to the incident and visited the site and reported that the worker was conscious when he was removed from the two floor was conscious when he was removed from the two floor was complaining of pain in his arm. The injured worker was wearing fall protection equipment, the equipment was not hooked on as of the time of the incident. The inspector also reported that the second floor was not floored, as there were joists that were not fully connected, which created the opening that the worker fell through. An ECB Violation was issued for a failure to safeguard, as there was inadequate fall protection present at the site. A full Stop Work Order (FSWO) was also issued. The Construction Superintendent is to provide a Means and Methods, see all as an adequate form of fall protection, in order tuture incidents. The only type of work that will be allowed at the site is housekeeping and safety measure implications. No new work is to be performed, and no new deliveries are to be made, until the Stop Work Order is rescinded.		35412147N		ALTERATION TYPE 1	321148931	Worker Fell	LINCOLN ESTATE HOLDINGS LLC	ALL STARR 1 LLC
1/15/2019	Manhattan	112	EAST 11 STREET	0 1	A DOB inspector reported that a worker hurt himself	FCB Violation	35403836Y		ALT-	123405154	Other Construction Related Incidents	CASTLE PARK HDFC	LEEDING BUILDERS GROUP
		112			while moving a heater in the basement. The worker felt pain in his arm and chest. An ambulance was called. The worker servertually returned to work. An ECB Violation was issued for a failure to institute safety measures. The contractor is removing the heater and Con-Edison is working with an electrician to resolve any problems.						A Service and a Abdition in August 15		
4/16/2019	Manhattan	553	WEST 30 STREET	0	The Site Safety Manager reported that a carpenter entered stair B when he steeped on a screw. The screw went through the worker's shoe and the worker fell down the stairs and hurt his neck. An ambidiance was called, and the worker was taken to Belleuve Hospital. A DOB inspector responded to the incident and reported that there were no witnesses to the incident, and that the injured worker called an ambidiance on his own. The inspector also reported that there were no housekeeping issues present at the site, and that there were handralis in place. No enforcement action was necessary. It was determined that this incident occurred as the result of a worker error.				NB	121184208	Worker Fell		HUDSON YARDS CONSTRUCTION
4/16/2019	Brooklyn	50	BRIGHTON 1 ROAD	0 1	A competent person at the site reported that a worker was injured while erecting a sidewalk shed. The injured worker was taken to an area hospital. This incident took place at 5:00 PM on Monday, April 15, 2019, but was not reported until 5:00 PM on Tuesday, April 16, 2019.				Sidewalk Shed	B00075266-I1-SH	Worker Fell	40-50 BRIGHTON FIRSTROAD APTS	CB EXPEDITING
4/16/2019	Bronx	600	BERGEN AVENUE	0	A DOB inspector reported that a Bobcat was on a roadway, transporting materials from one end of the site to another, when the Bobcat struck a whelice that had a passenger in it. The pedestrian passenger complained about d		35403877K	041619CE01WZ03	NB	220151868	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONSTRUCTION & DEV CORP
4/17/2019	Manhattan	1271	6 AVENUE	0 1	The Site Safety Manager reported that an electrician tripped on a conduit during lunch and pulled his hamstring. An ambulance was called.	No Dispatch			ALT-1	123401835	Worker Fell	ROCKEFELLER CTR NORTH INC	JRM CONSTRUCTION MGMT LLC
4/17/2019	Queens	Mar-50	ST NICHOLAS AVENUE	0 1	namstring. An amoulance was caied. The Site Safety Manager reported that a worker pinched his fingers during lagging operations. The worker went to an emergency room with a co-worker. An ambulance was not called.	No Dispatch			ALT-2	421066633	Other Construction Related Incidents	RIDGEWOOD TOWER LLC	AB CAPSTONE BUILDERS CORP
4/18/2019	Manhattan	73	VARICK STREET	0	A DOB inspector reported that there was a worker that was working off of a six foot high mobile baker scaffold to tape sheetrock. The worker was propelling both himself and the scaffold along a wall when he fell from the scaffold. The New York City Fire Department responded to the incident, placed a neck brace on the injuried worker, and transported the worker to a hospital. There were no guardrails on the baker scaffold, and the baker scaffolds wheels were not locked. An ECB Violation was issued for the failure to maintain safety equipment measures. A partial Stop Work Order (PSWO) was issued on all scaffold use on the fifth floor.		35418214L		ALTERATION TYPE 2 - MODIGC	123158000	Worker Fell	REMAINDERMAN 1 HUDSON SQUARE L	REIDY CONTRACTING GROUP



cident Date		Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
18/2019	Queens	35-27	30 AVENUE	1 A DOB inspector reported that a pedestrian was hit w     a piece of concrete during the installation of a sidewa     The pedestrian was taken to a local hospital, and was     reported to be in stable condition. This indicate took     place on April 17, 2019, but was not reported until Ap     18, 2019. Two CBS Violations were issued for a failu     to notify the Department Of Buildings of the incident:     one violation that was issued to the General Contract,     and one violation that was issued to the Site Safety     Manager. Two DOB Violations were also issued.	k. ril re	35403736K 35403745Z	041819CE01KS01,02	ALT	420652751	Other Construction Related Incidents	30TH AVE REALTY PARTNERS LLC	WHITE CONTR & RENOVATION
3/2019	Bronx	600	BERGEN AVENUE	A DOB inspector reported that a worker was removing plywood from a fourth floor ceiling when he was hit by small piece of plywood. The worker went to a urgent care center. An ambulance was not called. An ECS Violation was issued for a failure to maintain safety measures during formwork stripping operations.	a	35403889H	042319CE01WZ03	NB	220151868	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST
3/2019	Manhattan	200	EAST 21 STREET	The Site Safety Manager reported that a worker was cleaning up broken glass when he mishandled some the glass and cut his wrist. An ambulance was called.	of			NB	121190479	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC
3/2019	Manhattan	441	9 AVENUE	The Site Safety Manager reported that there were fou.  So pieces of sheetrock that were on an "A-Frame The "A-Frame tipped over, and the sheetrock hit a worker on their shin. The struck worker went to an emergency room with a co-worker. An ambulance wa not called.				ALT	120996351	Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	PAVARINI McGOVERN
4/2019	Manhattan	424	5 AVENUE	The Construction Superintendent reported that a worl was pushing a mini buggy when he hurt his back. The injured worker was sent to a hospital for a checkup.	No Dispatch			ALTERATION	123665499	Other Construction Related Incidents	424 FIFTH AVENUE LLC	TECTONIC BUILDERS INC
24/2019	Manhattan	30	EAST 31 STREET	1 A DOB inspector reported that there were iron worker that were hoising a steel tube in place when one of it workers got his finger caught between the steel tube and a steel post, which caused a cut to the worker's right middle finger. The worker was taken to a hospita by an ambulance. All permits at the site were in order and the log books at the site were to to date. The injured worker was in possession of valid thirty-hour OSHA and scalffoll user cards. Three EGW Violations were issued; one violation for the failure to institute or maintain safety measures, one violation for the failure to safeguard persons and property, due to the present of inadequate vertical inetting, and one violation for the presence of pedestrian protection that did not meet code specifications. A partial Stop Work Order (PSW) was issued for work from the rord level to the thirty-th floor and to the feet work from the protecter at vertical netting locations. A Means and Methods for the safe installation of steet bubby at the roof must be provided. The vertical netting from the rord down to the thirty-th floor must be regarded. The Yodock barriers must be maintained as per code.	co c	35418216, 35418217R, 35418218Z		NB	121192681	Other Construction Related Incidents	31ST STREET ZEF LLC	E&T SKYLINE CONSTRUCTION
24/2019	Manhattan	200	PARK AVENUE	1 A DOB inspector reported that there two construction workers were surveying for potential future work in th conceaded ceiling of an adjacent commercial space in the same building when the workers leaned on part of Concrete Masonry built (CMU) block wall. A brick that was on top of the wall fell into an adjacent service passageway and struck a restaurant employee (a pedestrian). The restaurant employee suffered a laceration to the head and was taken to a local hospit by an ambulance. The injured restaurant employee pedestrian was not within the job site when the incident occurred. The incident occurred cutsicle the scope of the field contract, since: It took place approximately 150 feet away from in-progress work. Two ECS Violations were issued: one Agravated Lu 2 violation for the failure to immediately notify the Department Of Buildings of the nicident, and one violation for a failure to safeguard. A DOB Violation walls to safeguard.	e a a al d	35375223X, 35407676M	042419CNEKC01, 042519CERDL01	ALTERATION TYPE 2	123406901-01-EW-OT	Material Fell	200 PARK, L.P.	CLUNE CONSTRUCTION CO LP
4/2019	Brooklyn	800	FLATBUSH AVENUE	The Site Safety Manager reported that a worker hurt her leg. The injured worker went to a clinic on her ow The leg was found to be fine, and the worker returned to work.	n.			NEW BUILDING	321188567-01-NB	Worker Fell	CATON FLATS HOUSING DEVELOPMEN	LETTIRE CONSTRUCTION CORP



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
//24/2019	Broldyn	S35	4 AVENUE	0	A DOB inspector reported that the Construction Superintendent was walking down a wooden stair on the first floor when he stepped on a piece of pipe. The pipe rolled, and the Construction Superintendent let hospital to get a checkup. The job plant interest that the hospital to get a checkup. The job had a housekeeping problem, there was debris, tools, and materials stored in the walking and hallway, which reduced greess and created a hazardous condition. Two ECB Violations were issued: one violation for the failure to maintain adequate housekeeping, and one violation for the absence of a design drawing for the wooden stair. A partial Stop Work Order (PSWO) was issued for all work on the fourth through seventh floors. The General Contractor must maintain housekeeping before the partial Stop Work Order (PSWO) was issued for all work on the fourth through seventh floors. The General Contractor must maintain housekeeping before the partial Stop Work Order will be rescinded.	ECB Violation	35421161Y, 62X		NEW BUILDING	320620612	Worker Fell	XYZ PROPERTIES INC	DYNATEC CONTRACTING INC
4/24/2019	Brooklyn	1630	EAST 102 STREET	0	A DOB inspector reported that a worker was bringing in components of a material hoist when he strained his back while trying to lift the equipment. The worker went to a hospital to get receive a checkup, and then came back to work. The workers foreman then sent the worker home. Facaded and roof repair work was in progress under a valid permit. All design drawings and permits were in place. No enforcement action was necessary.				FAÇADE REPAIR	321748785	Other Construction Related Incidents	NYC HOUSING AUTHORITY	ZORIA HOUSING, LLC
4/24/2019	Bronx	556	BERGEN AVENUE	0	A DOB inspector reported that an installation of precast concrete planks was in progress when a worker bumped into a loose shoring jack that was supporting the steel lintel over the door. The shoring jack fell and in the worker's reack. The worker was transported to a hospital. The Site Safety Manager stated that there was controlled Access Zone (AZQ) on the floor, but that the injured worker did not follow the instructions. Four ECO Violations were lossed one Aggravated Level 2 safeguard persons and property, one violation to the Concrete Subcontractor for a failure to safeguard one violation for the failure of the failure of the injured worker to attend the pre-rest meeting for that day. A full SISO Work Order (FSWO) was issued. Four DOB Violations were also issued.	<b>.</b>	35403890P, 35403891R, 35403892Z, 35403893K	042419CE01WZ01/02/03/04	NEW BUILDING	220151859	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
4/25/2019	Queens	Mar-50	ST NICHOLAS AVENUE	0	The Site Safety Manager reported that a worker stepped on a nail while performing a property survey. The worker went to an urgent cate center.	No Dispatch			alt	421066633	Other Construction Related Incidents	RIDGEWOOD TOWER LLC	AB Capstone Builders Corp
4/26/2019	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a worker misstepped, slipped off of an "A"-Frame ladder, and hurt his knee. The worker was seen by the on-site medic, and was then transported to a hospital by an exhibitors.	No Dispatch			NB	121328205	Worker Fell	SMITELL SPONSOR LLC	LENDLEASE US CONSTR.
4/26/2019	Queens	28-07	JACKSON AVENUE	0	ambulance.  A DOB inspector reported that a worker was attempting to climb a baker scaffold when he fell six feet. The worker was found conscious. An ambulance was called The General Contractor and the Subcontractor provide a thirty-hour OSHA card and a New York City ID card for the worker, but did not provide a four hour supportes scaffold user certificate. Two ECB Violations were issued: on evidation for the failure to provide a scaffold training certification, and one vidation for the failure to adequately restrain the scaffold from tipping, as per code. A partial Stop Work Order (PSWO) was issued for alluse of a baker scaffold. A valid supported scaffold user certification and a toolbox talk for the use and installation of a baker scaffold must be provided.	i. i	35418430X,35418431H		NB	420656873	Worker Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
4/29/2019	Brooklyn	866	PARK AVENUE	0	A DOB inspector reported that a worker was struck in the shoulder by a falling beam during the installation of a sidewalk shot. The worker was found conscious, but was experiencing pain and was taken to a hospital. According to a New York City Howsing Authority architect, an emergency sidewalk shed was being erected due to the presence of an unsafe facade. However, a Cycle 7 report was filed on August 9, 2014. However, a Cycle 7 report was filed on August 9, 2014, and a Cycle 8 report has not yet been filed. Four ECB Violations were issued: one violation for the failure to Safeguard persons and properly, as a worker was injured, one violation for the tampering with the evidence of an incident, as the beam that had fallen was removed, one violation for the erecting of a sidewalk shet whithout a permit, and one violation for the failure to file a Cycle 8 facade report. A partial Stop Work Order (PSWO) was also issued.		35403922K, 23M, 24Y & 35424900M				Scaffold/Shed/Fence/Shoring/Installation	NYC HOUSING AUTHORITY	ROMA SCAFFOLDING



Incident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/30/2019		101-51	107 STREET	1 A DOB inspector reported that a brick stding was in the process of being removed when a section of brick that was approximately 4 X S became disloged and fell onto a driveway at the Exposure 2 ground level. A construction worker suffered a minor injury and was transported to an area hospital. Two Aggravated Level. ECB Violations were issued: one violation for a failure to safeguard, and one violation for the presence of inadequate housekeeping, as there was a large accumulation of construction debris that created a health and fire hazard and obstructed egress to the job site. A full Stop Work Order (FSWO) was issued. Two DOB Violations were also issued.	2	35407100J & 01L	043019CEREP01 & 02	ALTERATION TYPE 2	421620366-01-EW-OT		WAZIM S BACCHUS	ZIM CONSTRUCTION INC
5/1/2019	Brooklyn	130	HUMBOLDT STREET	A worker tripped and fell backwards while working on a roof. The injured worker was transported by ambulance to an area hospital.	No Dispatch			ALTERATION TYPE 2	340641531-01-EW-OT	Worker Fell	NYC HOUSING AUTHORITY	PRO-METAL CONSTRUCTION INC
5/1/2019	Brooklyn	346	43 STREET	O 2 A DOB inspector reported that two workers were performing masonry work on a supported scaffold at the fourth floor fewel. The scaffolding was not exceeded properly, the scaffold was missing a base plate and a mud slide. The pole of the scaffolding brock through a floor deck that was constructed of structural panel board, which caused the scaffolding to collapse toward the wall. Both of the workers lost their balance and fell. One of the workers fell approximately thinly feet to the grade, and the scond worker fell inward to the floor. Both workers suffered non-flet threatening injuries and were taken to a hospital by the New York City Fire Department (FDNY). An ECD Violation was issued for the failure to provide adequate safety measures during a massion generation. A full Sick Work Order (FSWO) and a DOB Violation was issued for	5	35424933Z	050119CE07BG09	NEW BUILDING	321185427	Worker Fell	MCKECHNIE, JOSEPH R JR	REDLINE CONSTRUCTION & MA
5/1/2019	Manhattan	200	AMSTERDAM AVENUE	1 A DOB inspector reported that a carpenter was walking down the stairs from the third floor to the second floor when he slipped and fell approximately six to seven steps. The worker was experiencing pain in his neck, right knee, and hip. An ambulance was called. The stairs were found to be free of any slipping or tripping hazards. No material or debris was stored on the stairs and the hand rails were in place and were adequately illuminated. It was determined that this incident occurred as the result of a worker's error. No enforcement action was deemed necessary.				NEW BUILDING	122887224	Worker Fell	AMSTERDAM AVENUE REDEVELOPMENT	PAVARINI MCGOVERN LLC
5/1/2019	Queens	68-04	TIDES ROAD	The Site Safety Manager reported that a worker was using a pipe to bend rebar back into position when the rebar broke and the pipe that the worker was using hit the worker in the ear. An ambulance was called.	No Dispatch			NB	421305661	Other Construction Related Incidents	NAME NOT ON FILE	ROCKAWAY BEACH BLVD CON. C.
5/2/2019	Manhattan	9	ORCHARD STREET	A DOB inspector reported that an elevator cart was being built on the second floor when an elevator worker cut his hand on an elevator penel that was being installed. The worker went to a local hospital, where he was treated and then released. The Sife Safety Manager at the site stated that the worker had work glowes at the start of the operation. No unsafe conditions were observed in the work area. No enforcement action was necessary.				ALTERATION TYPE 1	121326010-01-AL	Other Construction Related Incidents	NINE ORCHARD PARTNERS, LLC	DNP BUILDERS LLC
5/4/2019	Brooklyn	2619	OCEAN PARKWAY	1 A DOB inspector reported that a rebar at the ground level that was inadequately secured came loose and struck a worker in the face. An ambulance was called, and the worker was transported to a hospital. The worker received treatment and then returned to work at the site. Three ECB Volations were issued one violation for the failure to maintain safely at the site, on violation for the failure to maintain safely at the site, on violation for the failure to maintain safely at the site, on violation for the absence of a concrete safely log book at the site, and one violation for the absence of a second of the site. A partial Stop Work Order (PSWO) was issued for all concrete operations.		35424859J / 60R / 61Z	050419CE13DM02 / DM03 / DM04	NB / EARTH WORK / FOUNDATION	320911171	Other Construction Related Incidents	HEALTH AND HOSPITALS CORP	TURNER CONSTRUCTION COMPANY



Incident Date	Borough	Address Number	Street	Fatalities Injuries EO	C Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/6/2019	Brooklyn	1270	NEW YORK AVENUE	beir fenen sec injuju The Sug the Sug the Built the Viola safe one pose pose library wide Built Built the the fenen pose pose Built	DOB inspector reported that a backhoe vehicle was ng operated by an unauthorized drive inside of the sce area. The backhoe struck a fence, and a 4' X 8' cition of the fence fell onto a female pedestrian. The properties of the fence fell onto a female pedestrian the rared pedestrian was transported to a local hospital, ecollapsed plywood was restored. The Site perintendent was present at the site as of the time of inspection, but did not notify the Department Of lidings of the incident (the incident was reported by New York (bir Fire Department). Four ECB listions were issued: one violation for a failure to eguard, one violation to the General Contractor for failure to possess or maintain a required daily log, evidation for failure to notify the Department Of lidings of an incident that featured a fatality. A full py Work Order (FSWO) was issued.	ECB Violation	039002647N, 48p., 49r, 50y		NEW BUILDING	321751902-01-NB	Mechanical Construction Equipment	1270 NY AVE. LLC	DEVELOPING NY STATE LLC
/6/2019	Brooklyn	85	JAY STREET	sitti pull box wra	e Site Safety Manager reported that a worker was ing on a gang box during a cofee break when he led a wire that was coming out from below the gang x and suffered a cut to his hand. The on-site medic apped the worker's hand and sent the injured worker a hospital for treatment.	No Dispatch			NEW BUILDING	321188415	Other Construction Related Incidents	85 JAY STREET BROOKLYN, LLC	NEW LINE STRUCTURES & DEV
5/6/2019	Manhattan	375	PEARL STREET	load pied The	e site superintendent reported that a worker was ding pieces of glass into a dumpster when one of the ces of glass was dropped and cut the worker's leg. e worker was transported to a local hospital by an abulance to receive treatment.	No Dispatch			ALTERATION	123560976	Other Construction Related Incidents	NAME NOT ON FILE	TURNER CONSTRUCTION COMPA
5/6/2019	Queens	147-40	ARCHER AVENUE	han when fell her An : were the site inju voor the stra Ger for or	DOB inspector reported that a worker was using a nicheld grinder to grind a concrete surface on the roof en the grinder lapped out of the worker's hands and on her right knee. The worker suffered an injury to right knee. The worker suffered an injury to right knee and was sent to an urgent care center, ambulance was not called. Four ECB Violations re issued: one violation for the failure to conduct a result of the stately meeting prior to the commencement of operation, one violation for the failure to provide a spesefic safety orentation to the worker that was ured, as the worker does not speak English, one lation for the failure to provide proof of the worker's serience with using a grinder, and one violation for a failure to provide an inspection record for the safety ap and the improper installation of a safety strap und a sharp-edged metal without a softenter. The nerall Contractor is to provide a Means and Methods the safe operation of the job, including a site-specific ety orientation for all workers, as well as Tool Box lks.		35418400P, 01R, 022 AND 03K		NEW PERMIT	420854508	Mechanical Construction Equipment	HP JAMSTA HOUSING DEV. FUND CO	CNY CONSTRUCTION LLC
5/7/2019	Brooklyn	575	4 AVENUE	wer large title project to the was open pre- open isss:	DOB inspector reported that there were workers that re using a pallet jack and an "A"-Frame to move go grante tiles when the workers lost belance and a ht a worker in the knee. The tiles were not secured perly. The struck worker went to a hospital on his perly. The struck worker went to a hospital on his in. Two EOB Violations were issued: one violation for failure to maintain safety measures, as a worker is rijured during a large-size grante tile moving stration, and one videolon for the laiture conduct a restation, and one videolon for the laiture or conduct a stration. A partial Stop Work Order (PSWO) was used on all material handling. The General Contractor provide a Means and Methods, along with a testral handling plan and a worker's safety orientation, the safe operation of the job.	ECB Violation	354249907P, 35424908R		NEW BUILDING	321042331	Material Fell	575 4TH AVENUE, LLC	TITAN REALTY & CONSTRUCTION
/8/2019	Manhattan	608	WEST 40 STREET	insi debe cau inju pos sitit riug tow issu prere was uses a s i violi con para	NOB inspector reported that a rigger was working lide of a thirty-yact container and was unloading a bris bag from inside of a smaller box when his leg got upth in a pinch point. The rigger stiffered a sewer ury and required medical attention. The rigger had sitioned himself poorly within the pinch point. A teen-hour certification was provided for the injured ger, but the injured rigger din not attend a pre-shift ver crane meeting. Three ECB Violations were used one violation to the General Contractor for the senso of inadequate safety measures, as a crane so perated in an unsafe manner, and one lation for the performance of work that did not reform with approximation and content of the performance of work that did not from with approximation consumers.	DOB Violation	35360898M 35360899Y 35361000L	SW0050819ML01	CN	691/18	Mechanical Construction Equipment	NEW YORK CONVENTION CENTER DEV	Rodgers and Son

ncident Date		Address Number			EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/2019	Manhattan	39	WEST 23 STREET	0	The Site Safety Manager reported that a worker was stripping plywood when the plywood hit his hand. The worker's hand was bleeding so the worker went to an urgent care center. An ambulance was not called.	No Dispatch			NB	121190424	Other Construction Related Incidents		PIZZAROTTI LLC
2019	Manhattan	161	EAST 28 STREET	0	The Site Safety Manager reported that a worker was removing a support jack for concrete when he got his right index finger caught in the bottom lip of the jack support. An ambulance was called.	No Dispatch				123381312	Other Construction Related Incidents	157-161 EAST 28TH STREET LLC	FORKOSH CONSTRUCTION CO
2019	Bronx	600	BERGEN AVENUE	0	The Site Safety Manager reported that a worker was grinding a piece of metal when his hand moved and his thumb was cut. The worker walked over to an emergency room. An ambulance was not called.	No Dispatch			NB	220151868	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST.
2019	Bronx	1870	SCHIEFFELIN AVENUE	0	The Safety Director reported that a worker injured his back when he bent down to pick up a box of tiles. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NYC HOUSING AUTHORIT	
10/2019	Brooklyn	123	LINDEN BOULEVARD	0	The Site Safety Manager reported that a worker fell from a ladder on the Irist floor. The worker was found conscious, and an ambulance was called to take the worker to a hospital. A DOB inspector responded to the incident and visited the site and issued two ECB Violations: one violation for a failure to safeguard, and one violation for the failure to provide a pre-shift safety meeting. The General Contractor is to provide a Means and Methods, a Tool Box Talk, and a pre-shift safety meeting.		35425002P,003R	051019CE17MA01.02	NB	321228603	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS
10/2019	Brooklyn	19	RICHARDSON STREET	0	A DOB inspector reported that a worker was preparing to commence masonry work around a stair shaft when he removed the guard rails from the edges of the shaft. The worker fell nine feet through the shaft to the collar floor and suffered a critical injury. The worker was transported to Believue Hospital. There were no safety measures in place consisting of a Controlled Access Zone (CAZ) and effective fall protection for performing a leading edge operation, and the worker was not using a safety harness or an anchor point. Six ECB Violation for a failure to safeguard persons and property, as there were no safety measures in place for a leading edge operation, one violation for the performance of work that did not conform to the construction document, one violation for the failure to maintain egress that was free of obstructions, one violation for the presence of a job site fence that was swinging outward, one violation for the presence of a broken sidewisk in front of the site that was full of tripping hazards, and one violation to the General Contractor for the failure to notify the Department Of Buildings of an accident that involved an injury to a worker. A full Stop Work Order (FSWO) was also issued. The General Contractor is to provide a Measa and Methods with a worker's orientation for the safe operation of the job site. Additional safety measures may be required upon review before the full Stop Work Order will be rescinded.		35425050J, 51L, 52N, 53P, 54R AND 55Z		new building	321628663	Worker Fell	19 RICHARDSON STREET LLC	AVO CONSTRUCTION LLC
/11/2019	Manhattan	1568 AIR	BROADWAY	0	The Site Safety Manager reported that a worker was moving containers when his finger got pinched between two containers. An ambulance transported the worker to a hospital.				A1 - ALTERATION TYPE 1	121191236-01-AL	Other Construction Related Incidents	TIMES SQUARE HOTEL SUB, LLC	PAVARINI MCGOVERN LLC
13/2019	Brooklyn	10	NEVINS STREET	0	No anospies.  A DOB inspector reported that a worker was using a a grinder with a 4 and 1/2 inch out-off wheel to out metal studie in place when the wheel of the grinder shattered and hit the worker above his upper lip. The worker suffered a laceration and was taken to a hospital, where he was reported to be okay. Six thirty-hour OSHA careful was reported to An ECB Violation was issued for the failure to salleguard all persons and properly. A partial Stop Work Order (FSWO) was issued on metal framing operations and grinding operations on the intellectin floor. A DOB Violation was also issued. A Means and Methods for safe steel stud installations and grinder operations must be provided.	e S	35418559R	051319CE02SK01	NB	320915578	Other Construction Related Incidents	NEVINS STREET OWNER LLC	DANYA CEBUS CONSTRUCTION
/13/2019	Manhattan	365	COLUMBUS AVENUE	0	The Site Safety Manager reported that a worker was draining hydraulic fluid from a line when he was splashed in the eye by the fluid. The worker flushed out his eye, and then went to see an eye doctor. An ambulance was not called.				ALT	121188482	Other Construction Related Incidents	CULTURAL AFFAIRS	BREEZE NATIONAL INC



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
Incident Date 5/14/2019	Borough Brooklyn	Address Number 626	Street 5 AVENUE		EOC Final Description  1 A DOB inspector reported that a worker slid down an open elevator hatch door on the third floor and fell approximately forty feet into a pit. The worker suffered fractured risk and a broken tablome and was taken to Methods: Hospital, where he was reported to be in stable condition. Fourteen total CES Violations were issued: one violation to the General Contractor for a failure to notify the Department Of Buildings of an incident involving a worker injury, one violation to the Construction Superintendent for a failure to notify DOB of an incident involving a worker injury, one violation to the Department of the superindendent for a failure to notify the Construction Supperintendent for a failure to notify DOB of an incident involving a worker injury, one violation for the presence of a supported pipe scafford patiform that was represented of supported pipe scafford patiform that was represented of supported pipe scafford patiform that was represented of supported pipe scafford whele was not in use, no violation for the activation of the failure to institute and maintain safety equipment measures and temporary construction, one violation for the failure to institute and maintain safety equipment measures and temporary construction, one violation for the failure to institute and maintain safety equipment measures and temporary construction one violation for the failure to estend the adjacent property chimney at exposure four, one violation for the failure to promptly oneity ODB of an incident involving damage to an adjoining property, one violation for the failure to promptly oneity ODB of an incident involving damage to an adjoining property, one violation for the failure to perform an installation inspection on the supported pipe scaffolding on the sidewalk shed, one violation for the failure to perform an installation inspection on the supported pipe scaffolding on the sidewalk shed, one violation for the failure to perform an installation inspection on the supported pipe scaffolding on	ECB Violation	ECB Violation Numbers 354227259;26R,27Z,28K,29M,30J,31L,32N,33P,34R,35Z,36K37M,38Y	DOB Violation Numbers See Complaint for Violation Numbers	Permit ALTERATION-1	Permit No 321174279	Incident Type Worker Fell	Owner's Name 435 7TH AVE APTS LLC	Contractor Name ATLAS DEVELOPERS LLC
5/15/2019	Manhattan	300	WEST 122 STREET	0	violation for the failure to provide an installation inspection for the sidewalk shed. Thirteen DOB Violations were also issued.  The Site Safety Manager reported that a worker was lifting rebar when he hit himself in the chin. The worker	No Dispatch			NB	120562284	Other Construction Related Incidents	BESPOKE HARLEM WEST LLC	HAPPY LIVING DEVELOPMENT
					went with his supervisor to an urgent care center. An ambulance was not called.								
5/16/2019	Manhattan	500	WEST 33 STREET	0	1 A DOB inspector reported that five workers were engaged in an operation to install a granite countertop. Four of the workers were lifting up the countertop, and the fifth worker was pulling out an "A-Frame cart, when the worker pulling out the "A-Frame fell on this left leg. The worker suffered scratches and bruises and was taken to Mount Sina' Hoopital. An ECB Vilotion was issued for a failure to maintain safety measures. A partial Stop Work Order (FSWO) was issued on all materiah handling. The General Contractor is to provide a Means and Methods, along with a worker orientation for the safe operation of the job.		35425077J		ALTERATION-2	123334178	Material Fell	NAME NOT ON FILE	STRUCTURE TONE, LLC
i/16/2019	Manhattan	15	EAST 30 STREET	0	I A DGB inspector reported that a worker was using a cart to move his equipment when a vestignatily starmed his left misdle finger between the cart and a wall. The worker went to a local CIM MD. to receive treatment. There were no slipping or tripping hazards present at the sile, and there were no other hazardsus conditions observed. This incident was considered to have occurred as the result of a worker's error. No enforcement action was necessary,	No Action Necessary			NEW BUILDING	122128679	Other Construction Related Incidents	MADISON 30 31 OWNER LLC	MADISON 30 31 OWNER LLC
5/16/2019	Manhattan	130	EAST 82 STREET	0	1 A DOB inspector reported that there was a worker working underneath a sidewalk shed when he was struck by a 4 X B piece of plywood that fell from a gap between the sidewalk shed and the building during a facade operation underway. The worker suffered an injury to his left arm and was transported to a hospital. Two ECB Violations were issued one volutation for the failure to institute and maintain safe operations, and one violation for the presence of a sidewalk shed that was not sealed. A partial Stop Work Order (PSWO) was issued for the use of suspended scaffolds and sidewalk shed deck until all of the gaps are sealed.	ECB Violation	35425065M, 35425066Y		NB	121328027	Material Fell	134 EAST 82 LLC	MC GOWAN BUILDERS INC
5/16/2019	Brooklyn	378	FLUSHING AVENUE	0	A DOB inspector reported that a worker fell from a job site ladder. The worker suffered minor injuries and was taken to an area hospital. An ECB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) and a DOB Violation were also issued.		35407452N	051619CNEEC02	ALTERATION TYPE 2	322023243-01-EW-OT	Worker Fell	LOTUS RESIDENCES LLC	RIVERSIDE DEVELOPERS USA



ncident Date		Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
17/2019	Manhattan	809	BROADWAY	Ü	1 A DOB inspector reported that a worker was walking up the stairs of a supported scaffold while carrying an extension cord in his hand when the end of the extension cord of pot caught on the handrall, which caused the worker's foot to slip between the first and second step and caused the worker to fall against the guardrail. The worker dot not appear to have any visible injuries, but complained of pain. The worker was taken to Lenox Hill Hospital. The facade work that was being performed on exposure three was completed, and the scaffold was in the process of being removed when the scaffold was in the process of being removed when the scaffold was in the process of being removed when the scaffold was in the process of being removed when the scaffold was in the process of being removed when the scaffold were provided. An CES Violation was issued for the failure to institute or maintain safety equipment measures or temporary construction. A partial Stop Work Order (PSWO) for the use and dismantling of a sactfold was also issued. A Means and Measures for the safe use and dismantling of a support scaffold must be provided.		34418568Z		ALTERATION TYPE 1	121236983	Worker Fell	NAME NOT ON FILE	FOUNDATIONS INTERIOR DESI
17/2019	Queens	21-18	44 DRIVE	0	1 A DOB inspector reported that a worker was digging soil in order to allow for foundation waterproofing when he left approximately four feet into a disth. The worker hurt his ankle and was taken to Belleview Hospital by an ambulance. Three EGR Vilotations were issued: one violation for a failure to safeguard, one violation for the railure to notify the Department OF Buildings of an incident that resulted in an injury to a construction worker, and nov ideation for the failure to provide a sidewalk shed or pedestrian protection. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35422804N,35422805P,35422806R		NB	402579759	Worker Fell	21-12 LLC	HARLEY CONSTRUCTION MANAG
18/2019	Manhattan	335	MADISON AVENUE	1	O A DOB inspector reported that a worker was cleaning debris on the scalfolding deck at the fifth floor level when the worker fell from the fifth floor to the second floor. An ambulance took the injured worker to a hospital, where he was pronounced dead. The worker was not using a safety harness, and the scalfolding deck was missing two pieces of planks and did not have any guardrails present. A DOB Violation and a full Stop Work Order (FSWO) was issued. The General Contractor is to provide a Means and Methods for safe operations.			051819CE0501MH	ALTERATION -1	121188204	Worker Fell		SCIAME CONSTRUCTION LLC
20/2019	Bronx	383	EAST 143 STREET	0	1 A DOB inspector reported that there was a suspended scaffold present at the second floor level. The power line of the scaffold was tied to the scaffold's railing. A worker used a ladder to gain access to the scaffold railing and released the scaffold from its hook in order to begin to lower it. However, the scaffold's power line had not been united before the scaffold was lowered, which caused the railing to pop up and hit the worker in the face. The injuried worker was taken to Lincoln Hospital, where he received stitches. Two ECB Violations were sissued: one violation for a falliure to maintain safety measures, and one violation for the falliure to conduct a pre-shift safety meeting. A partial Stop Work Cord' (PSWO) was issued for all use of suspended scaffolding. The General Contractor is to provide a Means and Methods for safe operations, along with a worker's orientation.		35418420M, 21Y		ALTERATION-2/ FAÇADE REI	PAIR 240252383	Scaffold/Shed/Fence/Shoring/Installation	NYC HOUSING AUTHORITY	VIKRANT CONTRACTING & BUI
20/2019	Manhattan	12	EAST 48 STREET	0	The Site Safety Manager reported that an electrician was working on an electrical panel when he was zapped and received exit wounds on his wrist. The worker was conscious. An ambulance was called. A DOB inspector responded to the incident and reported that the entire building used temporary wiring that was not 776 and not properly supported. It appears that the incident as caused by a worker error. Two ECB Violations were issued: one volations for the performance of electrical work without a permit, and one violation for the use of unapproved, unsafe, or unsuitable electrical equipment or wiring. Two DOB Violations were also issued.		35359899X & 35359900Y	52019EE105RID01 & 52019EE105RID02			Other Construction Related Incidents	1248 ASSOCIATES LLC	
21/2019	Brooklyn	516	SCHROEDERS AVENUE	0	The Site Safety Coordinator reported that a machine worker was cleaning glass when his finger got caught between glass and a machine. The worker left the site to see a medic.	No Dispatch			NEW BUILDING	321188905-01-NB	Other Construction Related Incidents	NEHEMIAH SPRING CREEK IV MIXED	MONADNOCK CONSTRUCTION IN



Incident Date	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/21/2019	Manhattan	11	WEST 116 STREET	0	1 A DOB inspector reported that a worker was removing existing beams from the cellar level when the worker got his finger pinched between a scaffold frame and a door jam. The worker was taken to Mount Sinai Hospital. The worker was in possession of an OSHA 32 card and a flow hour supported scaffold user card. The incident took place on May 20, 2019, but a notification of the incident was not received until May 22, 2019.  Two ECB Violations were issued; one to the General Contractor, and one to the Construction Superintendent, for the failure to immediately notify the Department Of Buildings of an accident at a construction or demolition site.	0	35425082Y, 83X		DEMOLITION	123037659	Other Construction Related Incidents	WEST 116 ACQUISITION LLC	VANQUISH GROUP INC
5/21/2019	Manhattan	292	5 AVENUE	0	1 A DOB Inspector reported that there was work being performed on a sidewalk shed prior to running a new service, so a temporary walkway was made in the stree with barriers and a chan-link fence, as permitted by the Department Of Transportation (DOT). A pedestrian was walking in the temporary walkway when the fence moved and hit the pedestrian's backeler. The pedestrian completing that their shoulder has injured pedestrian completing that their shoulder has injured on see any bruises or signs of injury. No hazarous conditions were observed at the site. A scalfold and netting were in place at the front of the building. The fence was removed from barriers. A flag man was in place. No enforcement action was taken.	Unit/City Agency			NEW BUILDING	121184789-01-NB	Scaffold/Shed/Fence/Shoring/Installation	WDSA 5TH AVENUE LLC	PACIFIC RIM
5/22/2019	Manhattan	500	WEST 33 STREET	0	A DOB inspector reported that a worker was working or a 277-volt system when he touched a live current and suffered a shock. An ambulance was called and the worker was taken to a hospital. The worker failed to denergize the system before he begin his work. No enforcement action was necessary.	,					Other Construction Related Incidents	NAME NOT ON FILE	
5/22/2019	Manhattan	500	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was on a ladder and measuring a piece of stone infill under a cancey when the ladder tipped over and felt. The New York City Fire Department (FDNY) called an ambulance. The worker was transported to a hospital, treated for a fractured leg, and then released from a hospital. This incident took place on May 22, 2019, but was not reported to the Site Safety Manager until May 24, 2019. A DOB Inspector responded to the incident, but the job site was closed. A follow up inspection was performed on Tuesday, May 28, 2019, and an ECB Violation was issued for the failure to notify the Department Of Bulldings of the incident.		35422717P	052819CE04JT01	NEW BUILDING	121186251	Worker Fell	NAME NOT ON FILE	TISHMAN CONSTRUCTION CORP
5/23/2019	Brooklyn	37	6 AVENUE	0	1 A DOB inspector reported that there were workers that setting up a rig and adding a section to an auger. One of the workers was cleaning and greasing the bit when the parts moved, and the worker got the fingertips of his manual to the parts of the section of the parts of the injury to a third finger. The worker was taken to a nospital, where he was reported to be in stable condition. An ECB Worklow was issued for unsafe equipment use. A partial Stop Work Order (PSWO) was issued to stop all drilling operations. The General Contractor is to provide a Means and Methods and a worker's orientation for the safe operation of the job.	s	35422809M		FOUNDATION	320909433	Mechanical Construction Equipment	EMPIRE STATE DEVELOPMENT	TISHMAN CONSTRUCTION CORP
5/24/2019	Manhattan	214	WEST 72 STREET	0	1 A DOB inspector reported that at the site, there was a chain link fence present on plastic barriers on the street that were being used for the storage area. The barriers were not continuous. A bus stopped, and a passenger/pedestrain stepped off of the bus. Wind knocked down a section of the fence, and a section of the fence that the pedestrain surpered the pedestrain surfected and the fence that the pedestrain was reported to be under treatment and in pedestrain was reported to be under treatment and in inter condition. Two EGB Violations were issued one violation for a failure to safeguard persons and property as a pedestrain was injured by a fallen section of fence, and one violation for the presence of site logistics that were not as per the approved Site Safety Plan. A partial Stop Work Order (PSWO) was issued to stop all activity on the storage area, including all shipping and deliveries. The General Contractor at the site is to provide a Means and Methods for safe operation, as well as an updated Site Safety Plan.	t	35437150P, 51R		NEW BUILDING	121204516	Scaffold/Shed/Fence/Shoring/Installation	AVENTIS-72ND, LLC	CM AND ASSOCIATES CONSTRU



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Brooklyn	211	HOYT STREET	0 1	A DOB inspector reported that a flag person was walking in front of a forklift with a telescopic boom when the flag person tripped. The forklift operator had the glare of the sun in his eyes, and the forklift accidentally ran over the fallen flag person's leg. The flag person was taken to a hoopital, where he was reported to have suffered a broken femur and internal injuries. The flag person underwent emergency surgery. The General Contractor at the site provided a Flagger Training Course, as well as a 30-Hour OSHA Card of the injuried worker. The forklift operator provided a 1 H injured worker. The forklift operator provided a 1 H injured worker. The forklift operator provided a 2 H injured worker. The forklift operator provided a 2 H injured worker. The forklift operator provided a 2 H injured worker. The forklift operator provided a 3 H injured to 1 H injured worker. The forklift operator provided a 2 H injured worker. The forklift operator provide adequate barriers for the work zone, and a second violation for the failure to provide safety measures for a forklift operation. A partial Stop Work Order (FSWO) was issued on all exterior work and the use of a forklift at the location until adequate safety measures for operations going forward are provided.		35437101Z, 02K		ALTERATION-2	321304539	Mechanical Construction Equipment	NYC HOUSING AUTHORITY	ADAM'S EUROPEAN CONTRACTING
5/28/2019	Manhattan	10	VANDERBILT AVENUE		The Site Salety Manager reported that a carpenter was cutting a wooden stud with a circular saw when the saw bounced and the worker received a cut on his hand. The worker was treated by the on-site medic. The on- site medic sent the worker to a hospital to get stitches.				NEW BUILDING	121189828	Other Construction Related Incidents	ONE VANDERBILT OWNER LLC	TISHMAN CONSTRUCTION CORP
5/29/2019	Queens	21-30	44 DRIVE		A DOB inspector reported that there were workers that were attempting to lower styrofcam from the second floor terrace to the first floor through the opening of a skylight. The skylight was temporarily covered by a tarp that was being held in place by paving blocks. While the tarp from the skylight was being removed, a paving block fell through the skylight to the floor a powing block fell through the skylight to the floor that was standing on the blower floor. The struck worker suffered a leg injury and was sent to a hospital for treatment. There EGB violations were issued, or evidence for a failure to safeguard persons and properly affected by construction operations, as a worker was injured due to unsafe activity, one violation for the improper storage of materials on a setback without securing the materials from wind, and a third violation for the absence of a design drawing for the temporary skylight cover. A partial Slog Work Order (FSWO) was issued for all work on the second floor terrace and skylight. The General Contractor must comply with the Stop Work Order of provide a Means and Methods, as well as a worker's orientation, for the safe operation of the job.		35418590P, 91R AND 92Z		ALTERATION-1	421231893	Material Fell	44TH DRIVE OWNER LLC	CM AND ASSOCIATES CONSTRU
5/30/2019	Brooklyn	1122	MANHATTAN AVENUE		The Construction Superintendent reported that a worker was carrying buckets while attempting to walk off of the job site at the end of the day when he slipped and fell three steps. The worker went to a hospital, where he was reported to have suffered a broken leg. No unsafe conditions observed as of the time of inspection. No enforcement action was necessary.				ALTERATION TYPE 1	320882354-01-AL	Worker Fell	1122 MANHATTAN AVENUE LLC	YELLOW HAT CONSTRUCTION
5/30/2019	Manhattan	40	10 AVENUE		A DOB inspector reported that an electrician was working in the switch gear room when he brushed up against a service bus and was shocked. Another worker knocked him off of the connection. The shocked electrician was taken to a hospital. It was determined that this incident occurred as the result of a worker's error. No enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	40-56 TENTH OWNER LLC	
5/30/2019	Manhattan	646	11 AVENUE		The Site Safety Manager reported that a worker was going down a stair tower when he slipped, fell approximately two steps, and hurt his lower back. The worker complained about pain. A co-worker took the injured worker to a hospital. This incident occurred as the result of a worker error.	No Dispatch					Other Construction Related Incidents	646 11TH OWNER LLC	
5/30/2019	Queens	23-15	44 DRIVE		The Site Safety Manager reported that a worker slipped off of a ladder and fell five feet to the ground. The worker went to a hospital as a precaution.	No Dispatch			NEW BUILDING	420655954-01-NB	Worker Fell	BGY CITYVIEW LLC	NEW LINE STRUCTURES & DEV



Incident Date	Borough	Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/31/2019	Bronx	2568	PARK AVENUE	Olimpetor reported that a scaffolding erector we modifying scaffolding not bet enth floor level when he dropped a drill to the lower level. A carpenter that was performing façade work on the lower level that was no associated with the scaffolding operation was structs to his head and shoulder by the drill. The Site Safety Manager took the injured carpenter to a hospital for observation. Five ECB Violations were issued-one violation for the failure to provide safety measures for r. scaffolding operation, one violation for the failure to maintain a three inch gap between the building and the scaffolding, one violation for the failure to provide a guardrail system, one violation for the presence of inadequate planking on the scaffolding, and one violation for the diavers on the scaffolding. A partial Stop Work Order (EWO) was issued for all scaffolding operations on the scaffolding. A partial Stop Work Order (EWO) was issued for all scaffolding operations on the exterior of the building.		35437164 X / 65 H / 66 J / 67 L @ 68 M	5	NEW BUILDING	220152484	Other Construction Related Incidents	2568 PARK BRONX LLC	THE SWEET CONSTRUCTION GR
5/31/2019	Brooklyn	11	BAY 20 STREET	1 A DOB inspector reported that a worker was working is an elevator shaft removing formwork when he fell sixteen feet into the elevator pt. The workers suffered a broken leg and was transported to a hospital in stable condition. There was no fall protection or safety measures in place. Seven ECB Violations were issued one violation for the failure to institute safery measure for operations, one violation for the failure to provide p shift safety measures for operation, one violation for the failure to provide one violation for the failure to provide now violation for the failure to maintain ence, as required, one violation for the failure to maintain ence, as required, one violation for the failure to maintain weatherproofin for the adjacent property, one violation for the failure to maintain as sanilarly facility, as required, and one violation for the failure to maintain existence of the construction Superintendent to perform their duties. A full Stop Wo Order (FSWO) was also issued.	e-e-e	35418472Y/73X/74H/ 35437125N/ 26P/27R@28Z	7	NEW BUILDING	321192339	Worker Fell	BAY 20TH LLC	RICHMOND CONSTRUCTION INC
5/31/2019	Brooklyn	658	DRIGGS AVENUE	1 A DOB inspector reported that a worker was receiving rebar delivery on the second floor level when the work slipped, fell, and injured himself on rebar that was protruding from the second floor. The worker was take to a hospital in stable condition. Five ECB Violations were issued: one violation for the failure to provide an maintain sidewalk shed as required, one violation for the presence of site conditions that do not conform to approved construction documents, one violation for the failure to provide safety measures for rebar delivery, one violation for the failure to notify the Department Of Buildings prior to the commencement of earthwork, an one violation for the failure of the Construction Superintendent to perform their duties as per code. A full Stop Work Order (FSWO) was also issued.	or n	35437179Z, 80X, 81H, 82J & 83L		NEW BUILDING	321193766	Worker Fell	RS JZ DRIGGS, LLC	FOREMOST CONTRACTING & BU
5/31/2019	Brooklyn	800	FLATBUSH AVENUE	The Site Safety Manager reported that a worker was using a hammer to loosen a drill bit when he accidentally hit his left hand. The worker went to urger care and then returned to work.				NEW BUILDING	321188567	Other Construction Related Incidents	CATON FLATS HOUSING DEVELOPMEN	LETTIRE CONSTRUCTION CORP