

ncident Date	Borough	Address Number	Street	Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2019	Bronx	4215	PARK AVENUE	0	1 A DOB inspector reported that a worker in the cellar fel approximately five feet from a ladder. The worker was sent to a hospital. An ECB Violation was issued for the improper use of a ladder.		35367408M	010319CE06WG01			Other Construction Related Incidents	NOT ON FILE	JOY CONSTRUCTION CORP
/2/2019	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that an electrician was preparing to pull writes through a pipe when he stepped backwards on the same floor and tost hig to balance. The electrician cut his left hand while trying to reach for something to goal but prevent himself from failing. The worker went to an urgent care center on his own to receive treatment.				NEW BUILDING	420654508	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	CNY CONSTRUCTION LLC
3/2019	Brooklyn	1797	BROADWAY	0	A DOB inspector reported that a worker was guiding ples into place when a pile shifted and the worker suffered an injury to his right leg. The worker was in stable condition and was taken to an area hospital. The extent and severity of the worker's injuries were not known as of the time of inspection. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) and a DOB Violation were also issued.		35374959Y	010318CNEGS01	NB	32156883	Excavation/Soil Work	1797 REALTY ASSOCIATES	W Developers Corp
3/2019	Brooklyn	778	DRIGGS AVENUE	0	3 A DOB inspector reported that there were three worker on a sidewalk shed that were attempting to lift up a suspended scalfdol platform. While the workers were lifting the suspended scalfdol platform above the sidewalk shed parapet wall, he parapet wall gave way, and all hiree workers lell down onto the sidewalk. One of the workers suffered a histed ankle, and one of the information available reparafing the injuries suffered by the hithing worker. All three injuried workers were taken to a hospital by an ambulance. Two ECB Violations were issued: one volation for a failure to safeguard persons and property, and one violation for the sidewalk shed not being bull according to code specifications. A partial Stop Work Order (FSWO) and two DOB Violations were also issued.		35354419P 35354420M	010319CE01CV01,02	ALT-3	321674675	Material Fell	OKUNIEWSKI MARIAN	ART-B CONSTRUCTION
3/2019	Brooklyn	982	WILLOUGHBY AVENUE	0	The Construction Superintendent reported that a worke was using a piggy-back to deliver material onto the street when the piggy-back overtured and the worker suffered injuries to his arm and legs. The worker was found conscious and an ambulance was called to transport the worker to a hospital.	n No Dispatch			NB	321183937	Other Construction Related Incidents	982 WILLOUGHBY AVENUE LLC	BROOKLYN
3/2019	Manhattan	110	CHARLTON STREET	0	A DOB inspector reported that a worker was guiding a concrete pump hose during a concrete pouring operation when concrete splaced into his say. The worker was sent to a hospital. An ECB Vollation was issued for a failure to mantain safe operations. A partia Stop Work Order (PSWO) was issued for a force oncrete pouring operations. A DOB Vollation was also assued.		35376880K	010319CE02MH03			Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	PLAZA CONSTRUCTION LLC
3/2019	Manhattan	500	WEST 33 STREET	0	The Site Safety Manager reported that a worker was standing on an "A"-Frame ladder when he fell off of the ladder. The worker was not seriously injured but was taken to a hospital by an ambulance. This incident occurred as the result of a worker's error.	No Dispatch			NB	121186251	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION
3/2019	Manhattan	601	WASHINGTON STREET	0	The Site Safety Manager reported that there was an unenclosed ladder inside of the building that was knocked over by a pust of wind. The ladder hit a worker The worker was not seriously injured but was taken to a hospital by an ambulance.				NB	122931845	Other Construction Related Incidents	HADSW LLC	TITANIUM CONSTRUCTION SER
/3/2019	Manhattan	615	10 AVENUE	0	1 A DOB inspector reported that during a stripping operation for the underside of the fifth floor; shoring was removed from an opening, and a piece of phywood was removed from an opening, and a piece of phywood housekeeping work on the sixth floor stepped on the busekeeping work on the sixth floor stepped on the piece of phywood slipped, and fell to the fifth floor the worker was found conscious and did not suffer any broken bones. The worker was responded to a hospital for further evaluation. The phywood was not secured, and a Controlled Access Zone (CAZ) was not maintained during the stripping operation. A pre-shift safety meeting did not take place before the stripping operation began. Two ECB Violations were issued: on one violation for the failure to institute safety meeting, A partial Slop Work Order (PSWO) safe yield the present of the presen		35376875X/79N	010319CE04MH01/02	NB	121190889	Worker Fell	HUDSON 888 OWNER LLC	LEEDING BUILDERS GROUP LL



cident Date		Address Number		Fatalities Injuries E		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2019	Manhattan	58	WEST 39 STREET	en an Ti fa vi vi	DOB inspector reported that debris fell into a worker's while the worker was cleaning threaded rods. An mbulance took the worker to a hospital for a check up. there ECB Violations were issued: one violation for the illustre to conduct a pre-shift safety meeting, one cladion for the obstruction of the sidewalk, and one cladion for the obstruction of the sidewalk, and one cladion for the performance of work that was no nortorming to the approved plan. Three DOB Violations ere also issued.	ECB Violation	35376926R / 27Z / 28K	010419CE05JK01/02/03			Other Construction Related Incidents	H HOTEL LLC	CROSSCITY CONSTRUCTION CO
2019	Brooklyn	4813	9 AVENUE	el	he Construction Superintendent reported that an ectrical worker tripped, fell, and hurt his fingers. The	No Dispatch			NB	320592970	Worker Fell	MAIMONIDES MEDICAL CENTER	AMERICON CONSTRUCTION INC
2019	Manhattan	211	EAST 70 STREET	0 1.A control of the	orker went to a City M.D. by himself.  DDB inspector reported that there were mast imbern being used at all four appearse of a thirty-four you existing building in order to perform facade repair rock. At the roof level, a worker lost control of a rocket soft of the deck, and then struck another worker in the role level, and worker lost control of a rocket, and then struck another worker in the log of the resident of the select, and then struck another worker in the log of the resident of the role of the select of the select one close to the role of the	ECB Violation	35377002L, 35377003M & 35377004P		ALTERATION	122993485	Material Fell	211 EAST 70TH STREETL.P.	E & A RESTORATION INC
019	Manhattan	22	NORTH LOOP ROAD	st fii w	he Site Safety Manager reported that a worker was ripping formwork on the third floor when he cut his nger with a nail while trying to hold the nail. The orker walked to an urgent care center on his own to ceive treatment and will return to work.	No Dispatch			NEW BUILDING	121203697	Other Construction Related Incidents	NOT ON FILE	HUNTER ROBERTS CONST. GRP
019	Manhattan	15	EAST 30 STREET	w in in	he Site Safety Manager reported that there were two orkers picking up a pipe that was ten feet long and six ches in diameter when one of the workers felt a pop his back. This worker was experiencing pain and ent to an off-site clinic.	No Dispatch					Other Construction Related Incidents	MADISON 30 31 OWNER LLC	MADISON 30 31 OWNER LLC
019	Queens	147-40	ARCHER AVENUE	h	he Site Safety Manager reported that a worker cut his and while using a drill to install metal studs. The orker went to a walk-in clinic.	No Dispatch			nb	420654508	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	cny construction
2019	Brooklyn	244	HOWARD AVENUE	O 1 A drift of the control of the co	DOB inspector reported that a worker was injured uring a partial collapse of the roof and third and fourth or point. The worker was transported to a hospital with non-life threatening injuries. The collapse appeared to the result of the overdeading of the floor joist with border threatening injuries. The collapse appeared to the result of the overdeading of the floor joist with birds and the presence of structural cold-formed steel at was not conforming to the approved plans. A DOB collation was issued for failure to safeguard. A full Stop fork Order (FSVIQ) was also issued. As of January 20, 2019, the Construction Safety Enforcement Unit is switch that the presence of construction safety Enforcement Unit is within the construction of the safety of the s	DOB Violation		010e19CE0305BG	ALTERATION-1	321646918	Material Fell	244 HOWARD AVE LLC	Y&Z DEVELOPERS INC
2019	Manhattan	1	WALL STREET	pi hi ai	he Site Safety Manager reported that a worker was ulling out a mini dumpster when he turned, fell, and hit his big right toe. The worker went to a clinic. An mbulance was not called. This incident occurred as the result of a worker's error.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2019	Manhattan	22	NORTH LOOP ROAD	0 1 Ti pr er to	he Site Safety Manager reported that a worker was erforming grinding work when a particle fell behind his ye gear and went into his eye. The worker was taken a clinic to have his eye flushed out. An ambulance as not called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	



Incident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2019	Manhattan	550	WEST 34 STREET	The Site Safety Manager reported that an electrical worker was shocked while working on the fifth floor ceiling. The worker was found conscious and was to a hospital by ambulance. A DOB inspector resport to the incident and reported that the incident occur as the result of a worker's error. No enforcement a was deemed necessary.	No Action Necessary	EGO Violation Numbers	DUD From the Indianaers	N/A	N/A	Other Construction Related Incidents	ONE HUDSON YARDS OWNER LLC	Contactor rease
/10/2019	Brooklyn	11	HOYT STREET	A DOB inspector reported that a panel of a fence we blown off from an anchor point by the wind. The part of fence them struck a pediestrian on her leg. A meet examined the pedestrian and sent her to a clinic to receive treatment. Three EOS Violations were issue one violation for a failure to safeguard persons and property affected by the construction operation, because the fence was not secured and was blown by the wind, injuring a pedestrian, one violation for being in possession of a design drawing for the ferr that was approved by a Professional Engineer (PE) one violation for the performance of work that was contrary to the approved size Safety Plan. The General Contractor is to clothain an amended Site S Plan and provide a means and methods for the safe operation of the job.	sel d:  c  d:  off tot   see   and   e  fety	35351511Y, 12X AND 13H		ALTERATION -1	321197058	Scaffold/Shed/Fence/Shoring/Installation	11 HOYT PROPERTY OWNER, L.P.	TRITON CONSTRUCTION CO.,
/10/2019	Bronx	600	BERGEN AVENUE	The Site Safety Manager reported that a worker pu his back while lifting a piece of steel. The worker ca FMS.	ed No Dispatch			NEW BUILDING	220151868-01-NB	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
1/11/2019	Manhattan	639	WEST 59 STREET	The Site Safety Manager reported that a worker slip on ice at the roof level. An amulance was called to the worker to a hospital. A DOB inspector responds the incident and issued an ECB Violation for a failu maintain work at the roof area. A DOB Violation wa also issued.	ake d to e to	35376811R	011119CE07DH01	NB	123308562	Worker Fell	RCB4 NOMINEE LLC	Tishman Construction corp.
/14/2019	Manhattan	627	GREENWICH STREET	O 1 A DOB inspector reported that an elevator compen was working on a delove at the welfth floor. The shaftway did not have any screen protection, allow the mechanic to move between the shaftway. The mechanic got his harness caught on the metal ang that was between the elevator that he was working and an elevator that was right neat to it, which was functioning. The mechanic suffered minor busiese leg and an ambulance was called. Two ECB Violati were issued: one violation was issued to cease the of Elevator Device (149825 at the site due to the presence of a broken limit cam, and one violation was issued to ease the site due to the presence of a broken limit cam, and one violation was issued for a failure to safeguard.	ng a on o his ns use	3826733H, 38267331Y				Worker Fell	627 GREENWICH OWNER LLC	
1/15/2019	Brooklyn	281	CUMBERLAND STREET	1 The Construction Superintendent reported that a w was installing railing around the shaft of the stairs is backyar that lead down to the basement when the worker fell nine feet into the shaft. The worker suff, a possible broken leg and was taken to a hospital b ambulance. The worker was found to have not bee tel off 1. A DOB inspector responded to the incident issued three ECS Violations: one violation for the it to institute safely measures, as a worker fell during installation of railings, one violation for the possess of an experted General Contractor license by the Ge Contractor, and a third violation for the possession expired worker's comp insurance. A full Stop Work Order (FSWO) and three DOB Violations were also issued.	red and litre the con nertal	35377042X,43H,44J	011519CE02BG08,09,10	ALT1	321195103	Worker Fell	SWEENEY, WILLIAM J IV	SMOOTH RENOVATIONS INC
/15/2019	Manhattan	50	WEST 69 STREET	A DOB inspector reported that two workers were st in the eyes by detric during the exposuration phase of bed-rock breaking operation. Both workers left the to seek medical attention. An ECB Violation was is for at fallure to maintain safe operations at the site. partial Stop Work Order (PSWO) was issued for br crock breaking operations. A DOB Violation was also issued.	a ite ued A d-	35376899К	011619CE07MH04			Other Construction Related incidents	ERZULI, LLC	NORDIC CUSTOM BUILDERS IN
/17/2019	Brooklyn	340	EVERGREEN AVENUE	The Site Safety Manager reported that a worker cu finger while throwing a piece of metal into a dumps The worker was treated on site and was then taken doctor to receive additional treatment.	er.			NB - NEW BUILDING	321181993-	Other Construction Related Incidents	BUSHWICK REALTY HOLDINGS LLC	Y.N.H. CONSTRUCTION INC
1/18/2019	Brooklyn	3491	FORT HAMILTON PARKWAY	Y  1 Å DOB inspector reported that a worker cut his leg a power saw. An ambulance was called. Two ECB Vlotations were issued: one volication for the Use of power saw that was contrary to the manufacturer's specifications, and one violation for the failure to provide a pre-shift safety meeting. A full Stop Work Order (FGSWO) and two DOB Violations were also issued.	1	35377064R 35377065Z	011819CE12JK01 / JK02			Other Construction Related incidents	SNL ORIX FORT HAMILTON, LLC	SNL CONSTRUCTION LLC



Incident Date	Rorough	Address Number	Stroot	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	139	EAST 56 STREET	The Site Safety Manager reported that a worker accidentally hit himself in the lips while swinging a hammer. The worker's foreman took him to a hospital for further observation.	No Dispatch	ECS Violation numbers	DOB VIOLATION NUMBERS	NB	123028810	Other Construction Related Incidents	139 EAST 56TH STREET LANDLORD	HUNTER ROBERTS CONSTRUCTION GROUP
1/22/2019	Bronx	810	RIVER AVENUE	The Sills Safety Manager reported that a worker was working on duct work when he fell approximately five feet from a ladder. The worker claimed to have suffer injuries to his neck and back and was taken to a hospital to be further examined. A DOB inspector responded to the incident and reported that there were no hazardous conditions observed. No enforcement action was deemed necessary, as it was determined that the injury occurred as the result of a worker's error.	od .					Worker Fell	NOT ON FILE	M. MELNICK & COMPANY INC
1/22/2019	Manhattan	277	PARK AVENUE	The Site Safety Manager reported that a laborer cut hi finger while disposing of material into a mini-container The laborer walked to a MedRite to be further evaluate.				ALT 2 FAÇADE	123164075	Other Construction Related Incidents	277 PARK AVEENUE,LLC	CAULDWELL WINGATE CO LLC
1/25/2019	Manhattan	730	5 AVENUE	A DOB inspector reported that an electrician suffered laceration to this index finger while using a band saw. The worker was taken to a nearby hospital. An ECB Violation was issued for a failure to safeguard. A parti	al	35382611N		Alteration	122751771	Mechanical Construction Equipment	NOT ON FILE	Structure Tone
1/25/2019	Manhattan	560	WEST 33 STREET	The Site Safety Manager reported that a worker slippe and fell approximately two feet off of a ladder. The worker complained about back pain. An ambulance w called, and the worker was taken to Mount Sinai hospital for observation. The worker was released with medication.	as			NB	121192618	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
1/25/2019	Manhattan	233	WEST 125 STREET	A DOB inspector reported that a worker was carrying steel spreader beam when his foot got caught between rebar, which caused the worker to drop the steel spreader beam on his left foot. The worker left the sit to seek medical attention. An CSB Violation was issue for a failure to maintain safe operations at the site. A parial Stop Work Order (PWO) was issued for all concrete operations. A DOB Violation was also issued.	d	35382662N	012519CE10MO01			Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
1/28/2019	Brooklyn	85	JAY STREET	0 1 A DOB inspector reported that a worker was bending rebor on a machine when he got his right arm pinched between a rebar and a column. The worker suffered minor injuries and was taken to a nearby hospital. The worker hard necestly took part in a pre-shit staylerly meeting that was related to princh points. The worker not follow protocol. It was deemined that this inciden courred as the result of a worker's ereor and no enforcement action was deemed necessary.	lid			NB	321188415	Other Construction Related Incidents	85 JAY STREET BROOKLYN, LLC	New line structures
1/28/2019	Manhattan	122	EAST 23 STREET	The Site Safety Manager reported that a worker hurt to nose while working on a sprinkler. A co-worker took the injured worker to a hospital.	is No Dispatch					Other Construction Related Incidents	NOT ON FILE	CM and Associates
1/28/2019	Manhattan	532	WEST 20 STREET	The Site Safety Manager recorded that a worker was walking on the site paginated the advise to the walking on the site of the control of the site of the control of the co						Other Construction Related Incidents	DDG 532 WEST 20TH STREET LLC	DDG DEVELOPMENT LLC
1/29/2019	Bronx	600	EAST 156 STREET	1 The Site Safety Manager reported that a worker slippe while coming off of an "A"-Frame ladder. The worker complained that he was experiencing foot pain and we taken to a hospital by ambulance.						Other Construction Related Incidents	600 EAST 156TH STREET HOUSING	
1/29/2019	Manhattan	1	WALL STREET	1 A DOB inspector reported that there were two workers that were transporting twenty-five sheets of metal with an "A"-France cart when the Goad of sheets fell off of the cart and his one of the workers in the leg. The struck worker received cust and rotuses on his leg and went a hospital to be further evaluated. The incident was caused by the overloading or misuse of equipment. At ECB Violation was issued for a failure to take advantaged were assures in handling materials. A partial Supp Work Order (FSWO) was issued on all material handling. The contractors at the site are to provide a Means and Methods for safe material handling.	to	35382797k		alteration	121190086	Other Construction Related Incidents	NOT ON FILE	JT Magen
1/30/2019	Manhattan	708	Broadway	A DOB inspector reported that an operation was takin place to fill hollow metal columns in a building with cement in order to support heavy duty mechanical equipment that will be installed on the rod. While the first column was being filled, a pre-diffied play had become distolged, and concrete was spilled oriot the floor of the gym, not a free standing weight machine, and orio a patron. The patron/pedestraten was directed to the column of the patron of t		35374766Н	013019CERJM01	ALTERATION TYPE 2	140598725-01-EW-OT	Material Fell	NEW YORK UNIVERSITY	SKYLINE RESTORATION INC

Incident Date		Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/31/2019	Manhattan	767	5 AVENUE	0 1 A DOB inspector reported that a worker was installing a light fidure when he cut his right wrist on a piece of metal. The worker was taken to a hospital, where he received seven sitches and was the rreleased. The inspector determined that the incident occurred as the result of a worker's error. No enforcement action was deemed necessary.	No Action Necessary			alteration	123660430	Other Construction Related Incidents	767 FIFTH PARTNERS LLC	Turner construction
2/1/2019	Manhattan	450	WEST 126 STREET	A DOB inspector reported that a worker was walking or a set of rebar when he lost his balance, slipped, and sprained his wrist. The worker left the site on his own in order to seek medical attention. The worker slipped on his own. This incident occurred as the result of a worker's error. No enforcement action was deemed necessary, ECB Violations were issued for infractions that were not related to the incident.						Other Construction Related Incidents	TSTY OWNER LLC	LEAND LEASE (US) CONSTRUCTION
2/1/2019	Manhattan	118	WEST 139 STREET	A DOB inspector reported that there were two workers performing interior work inside of apartment SW. While a window frame was being removed, a 4° x8' section of the clean of the section of the clean of the section of the reads and shoulders. Both workers on their heads and shoulders. Both workers were transported to Harlem Hospital to receive treatment for their injuries. The New York City Fire Department gained access to the apartment and removed the remaining section of the ceiling of the affected area. An ECB Violation was issued for all failure to safeguard. A partial Slop Work Order (PSWO) was issued for all work in apartment SW. A DOB Violation was also issued.		35355797Н	0201CERDY01			Material Fell	MPLP 6 HOUSING DEVELOPMENT FUN	
2/1/2019	Manhattan	108	CHAMBERS STREET	The Site Safety Manager reported that a carpenter cut his wrist on a metal stud while pressing on foam insulation. The worker was treated by the on-site medic and then went to a City M.D. to receive stitches.				ALT-1	121193519	Other Construction Related Incidents	108 CHAMBERS STREET OWNER LLC	ROSS & ASSOCIATES
2/4/2019	Brooklyn	2650	OCEAN PARKWAY	1 A DOB inspector reported that a worker was electrocuted. The worker was taken to Coney Island Hospital. Two ECB Violations were issued: one violation for there being no application on file for temporary wiring in the meter room on the first floor, and one violation for the absence of a panel cover from the side of a meter bank at the first floor. Two DOB Violations were also issued.		35359220K & 35359221M	020519EE313FM1 & 020519EE313FM2			Other Construction Related Incidents	NOT ON FILE	
/4/2019	Manhattan	545	WEST 30 STREET	The Site Safety Manager reported that a worker accidentally cut his hand on a hand-held grinder. The grinder was equipped with a safeguard. The worker's injury was not serious and he left the site on his own to have the cut cleaned up.	No Dispatch			ALTERATION TYPE 1	121192397-01-AL	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
2/5/2019	Brooklyn	422	FULTON STREET	0 1 A DOB inspector reported that during the installation of reinforcement for a penthouse slab, a worker stepped on a piece of filat-out wire mesh chair, and the tip of the wire mesh penetrated the worker's boot and cut his foot. The worker took himself to a nearby urgent care center and was treated with a tetanus shot to prevent an infection. The worker was released from the urgent care center and went home. Two ECB Violations were issued: one violation for a failure to safeguard, as the contractor failed to install concrete chairs as per the specifications found in the manual, and one violation for the performance of work that did not conform to the approved Site Safety Plan. as there was a hoist above the tenth floor, which was not on the Site Safety Plan. partial Site Work Chode (PSWC) to stop all work on the tenth floor and above. Two DOB Violations were also issued.	r A	35382738K 35382739M	02051CE302JT01	at 1	320908899	Other Construction Related Incidents	NOT ON FILE	Transparent Constrution



Incluent Date	Borough	Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/5/2019	Manhattan	30	EAST 29 STREET	0 10 The New York City Fire Department requested that a	ECB Violation	35375725X, 26H, 27J	020519CERFC01, 02, 03	General Contractor	121204552-01-NB	Other Construction Related Incidents	RG-29TH STREET OWNER I LLC	GERALD BIANCO
				inspection please be performed, as there were worke	s							
				that had been overcome by carbon monoxide. A DOE								
				inspector responded to the incident and visited the sit	9							
				and reported that there were workers at grade that we	re							
				shoring formwork for cellar one. The formwork had								
				been completed and approximately fifty percent of the								
				top steel was completed, with a pour scheduled for the	9							
				next day on the north half of the floor, and another po	ur							
				scheduled in two days for the remainder. The only								
				opening was the elevator shaft. There were two gas								
				generators at grade under the formwork that emitted								
				adequately ventilated, which caused ten workers to b	.							
				overtaken by the furnes. Nine of the workers were tal								
				to a hospital, while the tenth worker received treatme								
				at the site. Out of the nine hospitalized workers, six o								
				the workers were taken for observation, while two of	he							
				other workers went to Cornell Hospital and the ninth								
				and final worker went to Jacobi Hospital. The workers								
				that went to Cornell Hospital and Jacobi Hospital are	n							
				hyperbaric chambers. All of the workers are in stable								
				condition. Three ECB Violations were issued: one								
				violation to the General Contractor for a failure to								
				safeguard, one violation to the Site Safety Manager for	r							
				the failure to perform his duties, and one violation to	ne							
				Fire Safety Manager for the failure to perform his								
				duties. A full Stop Work Order (FSWO) and three DO	В							
				Violations were also issued. The contractor has been								
				directed to only make the site safe. Holes were create	d							
				in the formwork to ventilate the space.								
5/2019	Queens	69-01	34 AVENUE	0 1 A DOB inspector reported that a lull was deliving an		35376626P	020519CE03MS01			Other Construction Related Incidents	THE NEW YORK CITY SCHOOL CONST	TURNER CONSTRUCTION COMPANY
				eighty pound cement bag to the fourth floor when the								
				bag fell from the lull and struck a worker that was on	1							
				scaffold at the second floor level. The worker went to	a							
				hospital. An ECB Violation was isued for a failure to								
				maintain safety operations at the job site. A full Stop								
				Work Order (FSWO) and a DOB Violation were also								
				issued.								
/7/2019	Manhattan	11	WEST 53 STREET									It was a second week and the
					ECB Violation	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	
		''	WEST SS STREET	A DOB inspector reported that there were contractors that were installing exterior windows at the site. One	ECB Violation	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	turner construction
		"	WEST 33 STREET	that were installing exterior windows at the site. One	f	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	turner construction
			WEST SS STREET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior	f	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	turner construction
		"	WEST 33 STREET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while	f	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	turner construction
			WEST SS STREET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior	f	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	turner construction
		ľ	WEST 33 STREET	that were installing exterior windows at the site. One the workers was attached to all fieline on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings rate of	4	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	turner construction
		ľ	WEST SSCREET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found to the life-line that was in place, and the life-line was	r	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	turner construction
		"	WEST SS STICELY	that were installing exterior windows at the site. One the workers was attached to all fieline on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings rate of	r	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	turner construction
			WEST SOURCET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his ebow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found if the life-line hat was in place, and the life-line was found to not be an effective fall arrest system. An EG	r	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	aumer construction
			WEST SOURCET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found to the life-line that was in place, and the life-line was	r	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	aumer construction
			WEST SOURCE!	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found for the life-line hat was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design	r	35377189k		alteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	aumer construction
			WEST STORIES	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his ebow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line hat was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Creder (FSWO) wis issued on all exterior window installations. The contractors are to design a safe design drawing and the contractors are to design a safe design drawing and the safe drawing and the safe drawing and the safe design drawing and the safe drawing and th	r 3	35377189k		atteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	aumer construction
			WEST STORMET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injuy. There were no design drawings found for the life-line hat was in place, and the fille-line was found to not be an effective fall arrest system. An EC Violation was issued for the fallure to provide design drawings. A partial Stop Work Crider (FSWO) was issued on all exertior window installations. The	r 3	35377189k		atteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	aumer construction
			WEST STORMET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his ebow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line hat was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Creder (FSWO) wis issued on all exterior window installations. The contractors are to design a safe design drawing and the contractors are to design a safe design drawing and the safe drawing and the safe drawing and the safe days drawing and the safe drawing and the	r 3	35377189k		atteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	aumer construction
		ï	WEST STORMET	that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his ebow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line hat was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Creder (FSWO) wis issued on all exterior window installations. The contractors are to design a safe design drawing and the contractors are to design a safe design drawing and the safe drawing and the safe drawing and the safe days drawing and the safe drawing and the	r 3	35377189k		atteration	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	aumer construction
				that were installing exterior windows at the site. One the workers was attached to all fieline on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line hat was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the fallure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and it Means and Methods for window installation.	d							
7/2019	Manhattan	125	GREENWICH STREET	that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found if the life-line has was in place, and the life-line was found in onto the an effective half arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Sign Work Order (FSWO) was considered to the state of the	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P		atteration  NEW BUILDING	121183799	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	plaza construction LLC
7/2019	Manhottan	125		that were installing exterior windows at the site. One the workers was attached to all fieline on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line that was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the fallure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and al Means and Methods for window installation.  0 1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwo	ECB Violation							
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found if the life-line has was in place, and the life-line was found in onto the an effective fail arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.  0 1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwe fiel on the ladder and Nortock the worker of of the	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fieline on the exterior leading edge when he hyperextended his ebow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line that was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Crefer (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and all Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwo fell on the ladder and knocked the worker off of the ladder. The worker fell approximately nine feet. The	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found if the life-line has was in place, and the life-line was found in on the an effective fall arrest system. An EC Violation was issued for the faiture to provide design drawings. A partial Slop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.  0 1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwork fell on the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance in the worker was taken to a ho	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exderior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line that was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and a Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwo fell on the ladder and knocked the worker off of the ladder. The worker fell approximately hin efset. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued or	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found if the life-line hat was in place, and the life-line was found in ont be an effective fail arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Order (PSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and Means and Methods for window installation.  0 1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formworker life in the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued or violation to the General Contractor for the failature to violation to the General Contractor for the failature to violation to the General Contractor for the failature to violation to the General Contractor for the failature to violation to the General Contractor for the failature to violation to the General Contractor for the failature to violation to the General Contractor for the failature to violation to the General Contractor for the failature to	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fieline on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line that was in place, and the life-line was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and it Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwo fell on the ladder and knocked the worker off of the ladder. The worker fell approximately hin efset. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued: or violation to the General Contractor for the failure to maintain safety measures during a stripping operation	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found if the life-line was found in onto be an effective fall arrest system. An EC Violation was issued of the fallure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and in death of the safe of t	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fieline on the exderior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial 5top Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and a design drawing and all exterior window installations. The contractors are to design a safe design drawing and a design drawing and all exterior window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwor fell on the ladder and knocked the worker off of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECS Woldstons were issued: or violation to the General Contractor for the failure to provide a sitt here was no work platform present, one violation the General Contractor for the failure to provide a sitt	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital end with the life-line was found in on the an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a stafe design drawing and in Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwor fell on the ladder. The worker left approximately hine feet. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued or violation to the General Contractor for the failure to maintain safety measures during a stripping operation to the General Contractor for the failure to provide a sit specific safety crientation for the worker, one violation to the worker was now one/ laddrom present, one volotion to the worker was now one/ laddrom present, one volotion the Seneral Contractor for the failure to provide a sit specific safety crientation for the workers, one violation the Seneral Contractor for the failure to provide a sit specific safety crientation for the workers, one violation the Seneral Contractor for the failure to provide a sit specific safety crientation for the workers, one violation the Seneral Contractor for the failure to provide a sit specific safety crientation for the workers, one violation the Seneral Contractor for the failure to provide a sit specific safety crientation for the workers, one violation the Seneral Contractor for the failure to provide a sit specific safety crientation for the workers, one violation the Seneral Contrac	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was found to to be an effective till all arrest system. An EC Violation was issued for the failure to provide design drawings. A partial 5top Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and it was a sale of the sale with a sale design drawing and it was a sale design drawing and it was a sale of the sale of the sale with a sale design drawing and it was a sale of the sale with a sale design drawing and it was a sale of the sale was s	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital end was released from the hospital window. The worker was found in on the an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a stale design drawing and in the contractors are to design a stale design drawing and in the stale of the ladder. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued to violation to the General Contractor for the failure to provide a site specific safety orientation for the workers, one violation to the General Contractor for the failure to provide a site specific safety orientation for the workers, one violation to the General Contractor for the failure to provide a site specific safety orientation for the workers, one violation the General Contractor for the failure to provide a site specific safety orientation for the workers, one violation the General Contractor for the failure to provide a site of a pre-task safety meeting before a stripping operation a present one violation to general contractor for the failure to period a pre-task safety meeting before a stripping operation and the province and the p	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital with a minor injury. There were no design drawings found it the life-line that was in place, and the life-line was found to not be an effective till all arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and at Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formwo fell on the ladder and knocked the worker orl of the ladder. The worker fell approximately hin efset. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued: or violation to the General Contractor for the failure to maintain safety measures during a stripping operation as there was no work platform present, one violation the General Contractor for the failure to period as there was no work platform present, one violation the General Contractor for the failure to period as the contractor of the failure to period a pre-task safety meeting before a stripping operation one violation to the General Contractor for the failure	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Sign Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a safe design drawing and in the fall of the safe design drawing and in the safe of the safe design drawing and in the ladder and stripping formwork, when the formwork and in the ladder and vincelular laws where of of the worker was taken to a hospital by ambulance in a conscious state. The ECB Violations were issued to violation to the General Contractor for the failure to maintain safety measures during a stripping operation the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation to the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation to the General Contractor for the failure to provide a sit specific safety orientation for the workers, one violation the General Contractor for the failure to period a pre-take safety meeting before a stripping operation one violation to the General Contractor for the failure to period a pre-take safety meeting before a stripping operation one violation to the General Contractor for the failure to period a pre-take safety meeting before a stripping operation one violation to the General Contractor for the failure to period a pre-take safety meeting before a stripping operation one violation to the General Contractor for the failure to period a pre-take safety meeting before a stripping operation one violation to the General Contractor for the standing be above the	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital end was released from the hospital window. The worker was found to not be an effective fall arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Sign Work Order (FSVO) was contractors are to design a safe design drawing and indexed and the work of the worker was standing on a ladder and stripping formwork when the formwork offen of the ladder. The worker feel approximately nine feet. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued: or violation to the General Contractor for the failure to provide as there was nowely failure to the maintain safety measures during a stripping operation the General Contractor for the failure to provide a step of the standing of the stripping operation the General Contractor for the failure to provide a stage of the standing and the standing and the stage of the standing and the standing an	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was found to not be an effective fall arrest system. An EG Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the sale of the	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital end was released from the hospital window. The worker was found in on the an effective fail arrest system. An EC Violation was issued for the failure to provide design drawings. A partial Sign Work Order (PSWO) was issued on all exterior window installations. The consideration of the provide was installed to the consideration of the provide was installed to the consideration of the provide was installed to the consideration. The consideration of the provide was and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formworker of the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance of the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance to maintain safety measures during a stripping operation of violation to the General Contractor for the failure to provide a strength of a pre-task safety ineating before a stripping operation as there was no work platified or a stripping operation of a pre-task safety ineating before a stripping operation of a pre-task safety ineating before a stripping operation of the failure to provide a pre-task safety ineating before a stripping operation of the failure to provide a pre-task safety ineating before a stripping operation of the failure to provide a pre-task safety ineating before a stripping operation of the failure to provide a pre-task safety ineating before a stripping operation of the failure to provide a pre-task safety ineating before a stripping operation of the failure to provide a pre-task safety ineating b	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to a life-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was found to not be an effective fall arrest system. An EG Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the sale of the	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital end was released from the hospital window. The worker was found in on the an effective fall arrest system. An EC Violation was issued on the an effective fall arrest system. An EC Violation was issued on all exterior window installations. The connicions are no design at sale design discovering and in Means and Methods for window installation. The connicions are no design at sale design discovering and in Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formworker in a ladder and stripping formwork when the formworker in a conscious stake, the A beging a ladder in a conscious stake, the A beging is a parabulance or violation to the General Contractor for the fallure to the maintain safety measures during a stripping operation as there was no work platform present, no violation the General Contractor for the fallure to provide a sit specific adeptive dates of the contractor for the fallure to provide a sit specific adeptive fallows and the provide plan. Two partial Stop Work Orders (PSWO) were issued one stop all forming and stripping operations, and one to	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
7/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was found to not be an effective fall arrest system. An EG Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the sale of t	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
///2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a hospital window. The worker was found in on the an effective fall arrest system. An EC Violation was issued for the fall-rel arrest system. An EC Violation was issued on all exterior window installations. The contractors are no easy as a fall edging maximing and individual contractors are no easy as and edging conting and individual contractors are no easy as and edging contract and edging contractors are no easy as and edging contract and edging or an edge of the ladder. The worker was taken to a hospital by ambidance of all the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambidance in a conscious state. Five ECB Violations were issued to violation to the General Contractor for the fall-ret to maintain safety measures during a stripping operation as there was no work platform present, no violation the General Contractor for the fall-ret to provide a sits specific adeptive or an experiment of the fall-ret or provide as the specific agreed position to the General Contractor for the fall-ret of the fall-ret of the contractor for the contractor for the nearest contractor for the contractor for the nearest contractor for the contract of the contractor for the nearest contractor f	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was found to not be an effective fall arrest system. An EG Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the sale of t	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
//2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a hospital window. The worker was found in on the an effective fall arrest system. An EC Violation was issued for the fall-rel arrest system. An EC Violation was issued on all exterior window installations. The contractors are no easy as a fall edging maximing and individual contractors are no easy as and edging conting and individual contractors are no easy as and edging contract and edging contractors are no easy as and edging contract and edging or an edge of the ladder. The worker was taken to a hospital by ambidance of all the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambidance in a conscious state. Five ECB Violations were issued to violation to the General Contractor for the fall-ret to maintain safety measures during a stripping operation as there was no work platform present, no violation the General Contractor for the fall-ret to provide a sits specific adeptive or an experiment of the fall-ret or provide as the specific agreed position to the General Contractor for the fall-ret of the fall-ret of the contractor for the contractor for the nearest contractor for the contractor for the nearest contractor for the contract of the contractor for the nearest contractor f	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was taken to a nearby hospital and was released from the hospital window. The workers was found to not be an effective fall arrest system. An EG Violation was issued for the failure to provide design drawings. A partial Stop Work Order (FSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the contractors are to design a sale design drawing and in the sale of t	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
/2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a hospital window. The worker was found in on the an effective fall arrest system. An EC Violation was issued on the an effective fall arrest system. An EC Violation was issued on all exterior window installations. The contractors are to design at sale design drawings. A partial Slop Work Ordor (PSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and it Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formworker of the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued or violation to the General Contractor for the fallative to maintain safety measures during a stripping operation as there was no work platform present, no violation the General Contractor for the fallative to principle approach of a pre-task safety meeting before a stripping operation one violation to the General Contractor for the fallative to principle and the provided as the provided of a pre-task safety meeting before a stripping operation or work olds to the General Contractor for the fallative to principle or a stripping operation or work olds to the General Contractor for the latification of the General Contractor for the latification of the General Contractor for the vorkers, one violation to plant. Two partial Stop Work Drofers (PSWO) were issued one stop all works above the sixty-eventh floor. The General Contractor is to provide a stripping operations, and one to stop all works, an order to comply with the issued Contracto	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
2019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a hospital window. The worker was found in on the an effective fall arrest system. An EC Violation was issued on the an effective fall arrest system. An EC Violation was issued on all exterior window installations. The contractors are to design at sale design drawings. A partial Slop Work Ordor (PSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and it Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formworker of the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued or violation to the General Contractor for the fallative to maintain safety measures during a stripping operation as there was no work platform present, no violation the General Contractor for the fallative to principle approach of a pre-task safety meeting before a stripping operation one violation to the General Contractor for the fallative to principle and the provided as the provided of a pre-task safety meeting before a stripping operation or work olds to the General Contractor for the fallative to principle or a stripping operation or work olds to the General Contractor for the latification of the General Contractor for the latification of the General Contractor for the vorkers, one violation to plant. Two partial Stop Work Drofers (PSWO) were issued one stop all works above the sixty-eventh floor. The General Contractor is to provide a stripping operations, and one to stop all works, an order to comply with the issued Contracto	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
019	Manhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a hospital window. The worker was found in on the an effective fall arrest system. An EC Violation was issued on the an effective fall arrest system. An EC Violation was issued on all exterior window installations. The contractors are to design at sale design drawings. A partial Slop Work Ordor (PSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and it Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formworker of the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued or violation to the General Contractor for the fallative to maintain safety measures during a stripping operation as there was no work platform present, no violation the General Contractor for the fallative to principle approach of a pre-task safety meeting before a stripping operation one violation to the General Contractor for the fallative to principle and the provided as the provided of a pre-task safety meeting before a stripping operation or work olds to the General Contractor for the fallative to principle or a stripping operation or work olds to the General Contractor for the latification of the General Contractor for the latification of the General Contractor for the vorkers, one violation to plant. Two partial Stop Work Drofers (PSWO) were issued one stop all works above the sixty-eventh floor. The General Contractor is to provide a stripping operations, and one to stop all works, an order to comply with the issued Contracto	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						
2019	Marhattan	125		that were installing exterior windows at the site. One the workers was attached to all fill-line on the exterior leading edge when he hyperextended his elbow while setting a window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a nearby hospital and was released from the hospital window. The worker was taken to a hospital window. The worker was found in on the an effective fall arrest system. An EC Violation was issued on the an effective fall arrest system. An EC Violation was issued on all exterior window installations. The contractors are to design at sale design drawings. A partial Slop Work Ordor (PSWO) was issued on all exterior window installations. The contractors are to design a sale design drawing and it Means and Methods for window installation.  1 A DOB inspector reported that a worker was standing on a ladder and stripping formwork when the formworker of the ladder. The worker fell approximately nine feet. The worker was taken to a hospital by ambulance in a conscious state. Five ECB Violations were issued or violation to the General Contractor for the fallative to maintain safety measures during a stripping operation as there was no work platform present, no violation the General Contractor for the fallative to principle approach of a pre-task safety meeting before a stripping operation one violation to the General Contractor for the fallative to principle and the provided as the provided of a pre-task safety meeting before a stripping operation or work olds to the General Contractor for the fallative to principle or a stripping operation or work olds to the General Contractor for the latification of the General Contractor for the latification of the General Contractor for the vorkers, one violation to plant. Two partial Stop Work Drofers (PSWO) were issued one stop all works above the sixty-eventh floor. The General Contractor is to provide a stripping operations, and one to stop all works, an order to comply with the issued Contracto	ECB Violation	35377279Y, 35377280L, 35377281N, 35377282P						



cident Date		Address Number	Street	Fatalities Injur	ies EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
11/2019	Queens	35-27	30 AVENUE	0	1 A DOB inspector reported that a worker was pulling wire through a conduit when the worker leaned on a pipe clamp, which caused the conduit to give way and hit the worker in the head. The worker was taken to a hospital by an ambulance in order to receive stitches. The inspector determined that the incident was caused by a worker's error, and that no enforcement action wa necessary.	No Action Necessary			ALT-1	420652751	Other Construction Related Incidents	30TH AVE REALTY PARTNERS LLC	WHITE CONSTRUCTION & RENO.
1/2019	Brooklyn	555	4 AVENUE	0	1 The Site Safety Coordinator reported that a worker slipped on the fourth floor due to the presence of ice. The worker refused medical attention and went to a noepital on his own. A DDS inspector responded to the incident and reported that the incident was caused by worker's error, as the worker slipped. The Site Safety Coordinator stated that there was no evidence of the worker's error, as the worker slipped. The Site Safety Coordinator stated that there was no evidence of the worker falling. No enforcement action was necessary.	No Action Necessary			NB	321238264	Other Construction Related Incidents	PARTNERS VII/541-555 FOURTH OW	DYNATEC CONTRACTING
2/2019	Manhattan	76	11 AVENUE	0	1 The Site Safety Manager reported that a worker fell for feet from a baker scaffold and hurt his shoulder. An ambulance was called. A Dol Sinspector responded to the incident and reported that the scaffold did not have outriggers in place and that the wind blew the scaffold over. The inspector also reported that the worker fell because his langvard came loose. An ECB Violation was issued for a failure to institute safety measures. A full Stop Work Torder (FSWO) was issued on all baker scaffold and perimeter work. A DOB Violation was aside sissued. The General Contractor is to provide a Means and Methods and Design Drawings for the anchor poin and to prevent future injuries from occurring.	s	35377206N	021219CE04SK01	NB	121190308	Worker Fell	76 ELEVENTH AVENUE PROPERTY OW	OMNIBUILD CONSTRUCTION INC
3/2019	Manhattan	40	EAST END AVENUE	0	The Site Safety Manager reported that a worker was walking in the basement when he lost his balance, tripped, and hurt his knee. The worker was not carrying anything at the time that he was walking. An ambulanc was called.				NB	121190120	Worker Fell	40 EAST END AVE. ASSOCIATES LL	BRAVO BUILDERS LLC
3/2019	Manhattan	550	WEST 34 STREET	0	A DOB inspector reported that a worker was working of a ladder when he became startled by an electrical arc and a crackling noise, which caused him to fall off of the ladder. The worker was taken to a hospital. The inspector determined that no enforcement action was necessary.	No Action Necessary					Worker Fell	ONE HUDSON YARDS OWNER LLC	
3/2019	Staten Island	55 B	RICHMOND TERRACE	0	The Site Safety Manager reported that a worker was walking in the basement when he lost his balance, tripped, and hurt his knee. The worker was not carrying anything at the time that he was walking. An ambulanc was called.	,					Other Construction Related Incidents	ST. GEORGE OUTLET DEV LLC	EMPIRE OUTLET BUILDERS
k/2019	Manhattan	100	FRANKLIN STREET	0	1 A DOB inspector reported that a worker was using a ginder to grind brick on a exterior wall when the grinder kicked back and cut the worker's left arm. The worker was stransported to New York Downton Hospita by an ambulance to receive stitches. The worker was a possession of a proper ten hour OSHA card and a scaffold training card. However, the worker did not sight the safety training log. An Aggrarated Level 2 ECB Violation was issued for the failure to provide evidence of workers attending a construction and safety course.	i n	35377261M		NB	121185993	Other Construction Related Incidents	DDG 100 FRANKLIN LLC	DDG DEVELOPMENT LLC
/2019	Manhattan	125	GREENWICH STREET	0	1 A DOB inspector reported that a worker was spreading rock sait on a stair in a building where both stairways had ice present at many places between the sixty-third and seventy-fourth floors. The worker slipped on ice and fell on his back. The on-sixt medic checked out th worker and then sent the worker to a hospital to reach can be succeeded by the statement of the sent to a hospital by reach and wooden han rails with hadrened cement and tripping hazards present at several places. Two ECB Violations were issued: one violation for a failure to maintain safety measures, as there was ice on the floor that was not removed, and one ECB Violation for a failure to maintain adequate housekeeping. A partial Stop Work Order (FSWO) was issued on all work between the sixty-third and seventy-fourth floors. The General Contractor is to provide a Means and Methods for the safe operation of the job	e e	35296571R, 35296572Z		NEW BUILDING	121183799	Worker Fell	VS 125 LLC	PLAZA CONSTRUCTION LLC
14/2019	Manhattan	250	SOUTH STREET	0	A DOB inspector reported that a pedestrian woman we struck in the face by lumber that was being loaded ont a truck. The woman was examined by the on-site medic. An ambulance was not called. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued for all loading and unloading o materials and debris. A DOB Violation was also issued.	n 1	35377331M	021419CE03JK03			Other Construction Related Incidents	NAME NOT ON FILE	LENDLEASE(US)CONSTRUCTION



Address		Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/2019 Manhattan 217 5/2019 Manhattan 145 5/2019 Brooklyn 10 6/2019 Bronx 556	500	WEST 33 STREET		A DOB inspector reported that a worker was installing sheetrock inside of the elevator shalf of the 11 and J2 elevator banks on the forty-fifth floor when a piece of metal stud that was stored near the shalf tell from above and hit the worker on his hard hat. The worker suffered a laceration to his nose and was taken to a hospital by an ambulance to receive treatment. The inspector found that metal studs and debris were also stored near the edge of the shalf. Two ECB Violations were issued: one violation for a failure to maintain safety measures during a construction operation, as a worker was injured by material that fell from above, and one violation for a failure to institute adequated one violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequated by the violation for a failure to institute adequate and the violation for a failure to institute adequate and the violation for a failure to institute adequate and the violation for a failure to institute adequate and the violation for a failure to institute adequate and the violation for a failure to maintain and the violation for and violation for a failure to maintain and violation for and violation for and violation for and violat		35382748Y, 35382749X				Material Fell	NAME NOT ON FILE	
	501	west 18 street		The Site Safety Manager reported that a worker on the fourth floor of the weat building was hit by a pice of plywood while other workers were bringing stripping forms up to the need floor. The worker was seen by the on-site medic and was then taken to Selevue Hospital by an ambulance. The worker had alseay returned to work as of the time of inspection. OSHA Cards, a Tool Box Talk, a Site Safety Plana, a daily safety talk, and Site Safety Manager logs were all provided. It was determined that this incident occurred as the result of a worker's error, and that no enforcement action was deemed necessary.				NEW BUILDING	121191147	Material Fell		RELATED CONTRUCTION LLC
Brooklyn	217	WEST 57 STREET		The Site Safety Manager reported that a worker was pushing a mini container. The mini container was tipping, and the worker injured his shoulder while trying to hold the mini container. The injured worker went to a clinic.	No Dispatch			INTERIOR FITOUT	140716839	Other Construction Related Incidents	SMITELL SPONSOR LLC	JT MAGEN & COMPANY INC
/2019 Bronx 556	145	WEST 47 STREET		The Site Safety Manager reported that a worker came to work with a previous foot injury that was not reported. The worker injured the same foot while climbing up a ladder. The worker was limping. The worker's supervisor took him to a doctor.	No Dispatch			NEW BUILDING	121187802	Other Construction Related Incidents	CLARITY 47 LLC	TB USA, L.L.C
i/2019 Manhattan 151	10	NEVINS STREET		The Site Safety Manager reported that a worker was pushing a mini container and hurt her shoulder while trying to prevent the mini container from tipping over. A co-worker walked the injured worker to a clinic for a check up.	No Dispatch			NEW BUILDING	320915579	Other Construction Related Incidents	NEVINS STREET OWNER LLC	DANYA CEBUS CONSTRUCTION
	556	BERGEN AVENUE		A DOB inspector reported that during the installation of pre-cast sections on the third floor, an iron worker was hir in the shoulder and then lost his balance and fell. The worker was warning his Personal Fall Protection (PFP) equipment, which prevented the worker from hitting the gound. However, the fall protection equipment left the worker suspended and bouncing from side to side, and the worker hit a steel column. The worker was taken by an ambulance to Lincold Hospital to receive treament. The worker did not suffer any troken bones. An ECB Vidation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35377451R		NB	220151859	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONSTR.ADEV.CORP
2019 Brooklyn 474	151	EAST 86 STREET		A DOB inspector reported that a worker was installing a building storeform at the second floor level when he tell approximately fifteen feet from a sidewalk ched. The worker was tell off using his harness, and there were concrete-embedded anchors present to serve as fall protection. The worker fell between the store front and the construction fence, but did not hit the ground, as he was suspended by his Personal Fall Protection (FP) equipment. The worker was conscious and was taken to a hospital by ambulance. The status of his injuries is not known. An ECB Violation was issued for the failure to provide a pre-shift safety meeting. A partial Story Work Order (PSWO) was issued on all store front installations.		35377336i		NB	122668648	Worker Fell	NAME NOT ON FILE	Gibane residential
	474	FULTON STREET		A DOB inspector reported that a section of sidewalk fence had fallen and struck a pedestrian sidewalk hot dog vendor. The injured pedestrian was taken to a hospital with unknown injuries. Permits had been issued at the site for interior and exterior work, but no work was being done on the date of the incident. The New York City Fire Department removed the remaining sections of the sidewalk fince and stacked the phywod sections against the building. An Aggravated Level 2 ECB Violation was issued for a faultive to safeouard. A	ECB Violation	35375422Z	021819CNEDG01	ALTERATION TYPE 2	321724960-01-EW-OT	Material Fell	NAME NOT ON FILE	TOM RECTENWALD CONSTRUCTI



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/18/2019	Manhattan	233	WEST 125 STREET	0	The Site Safety Manager reported that a worker was handing up material when the material fell back and hit the worker on his head. The worker was wearing a hard hat. The worker was transported to a hospital by ambulance.				NEW BUILDING	121187447-01-NB	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
2/19/2019	Bronx	1560	BOONE AVENUE	0	I A DOB inspector reported that a worker was on a baker scaffold that did not have the wheels locked. The worker was performing taping work when the baker scaffold started to roll and the worker fell approximately four feet. The worker was found conscious and was taken to a hospital by an ambulance with unknown injuries. The scaffoldsing was removed from the location before the inspector arrived. Two LGB Violations before the inspector arrived. Two LGB Violations were issued: one violation for the failure to maintain safely measures, as the baker scaffolding that was being used did not conform to the manufacturer's specification, which resulted in an injury to a worker, and one violation for the tampering with the evidence of an incident, as the baker scaffold involved in the accident was removed before the DOB inspector arrived at the stake. A partial Stop Work Order (PSWO) was issued to stop the use of baker scaffolding.	ı	35377653K, 35377654M		NEW BUILDING	220152876	Worker Fell	SAMARITAN-COMPASS III & IV HOU	MONADNOCK CONSTRUCTION IN
2/19/2019	Manhattan	505	WEST 43 STREET	0	A DOB inspector reported that a worker was carrying a bucket of liquid waterproofing material while walking down the stairs from the fourth floor to the third floor when she either lost her balance, or missed a step, and fell to the floor. The worker did not appear to have any visible injuries, but was taken to a hospital. The stair was dry, there was no ice or water present, and there were no tryping hazards present. No enforcement action was deemed necessary.				NEW BUILDING	121187456	Worker Fell	1818 NADLAN LLC	NEW LINE STRUCTURES & DEV
2/19/2019	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker came to work with lower back pain that was not job-related, but did not report the back pain and continued to work. At lunch time, the worker felt severe pain in his back. A co-worker called the ailing worker's son to take him home, and the ailing worker's son called an ambulance.				NEW BUILDING	420654508	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	CNY CONSTRUCTION LLC
2/21/2019	Manhattan	305	WEST 48 STREET	0	A DOB inspector reported that there were workers that were stripping formwork inside of the stars shaft. One of the workers was passing materials to another worker. The recipient worker was receiving a pece of wood when he lost courted of the piece of wood, causing it to fall and hit a worker below on the head. The injured worker was experiencing headaches and was taken to a hospital. Two EOB Violations were issued one violation for the fallure to safeguard persons and property, as a worker was injured during a stripping operation due to unsafe material handling, and one violation for the absence of a design drawing for a makeshift work platform that was recected inside of the stair shaft. A partial Stop Work Order (PSWO) was issued on all will be a stripping of the star shaft. A partial Stop Work Order (PSWO) was issued on all violation. The General Contractor is to provide a Means and Methods, along with a safety orientation for workers, for the safe operation of the job.		35377455Y, 35377456X		NEW BUILDING	121203786	Material Fell	BRIGHT MGMT CP	JOY CONSTRUCTION
2/21/2019	Brooklyn	123	LINDEN BOULEVARD	0	I A DOB inspector reported that there were workers that were working on support of excavation inside of a trench. The workers were droping materials inside of the trench when a piece of wood hit a worker on his foot. The struck worker was taken to a hospital by ambulance. Two ECB Violations were issued one violation for the failure to safeguard persons and property, as a worker was injured due to unsafe material handling and one violation for the presence of inadequate housekeeping, as ice and snow was not removed from the job area. A partial Stop Work Order (PSWO) was issued on all work inside of the trench and vaults. The General Contractor is to provide a Means and Methods for the safe operation of the job.		35377476N		NEW BUILDING	321208603	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS LLC



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/22/2019	Marhattan	545	WEST 30 STREET		A DOB inspector reported that a worker was installing electrical condults and straps when he knocked over a cordless drill that he was using, causing the drill to hit another worker that was below him in the head. The struck worker was at the bottom of a ladder that was approximately filteen feet and was not wearing Personal Protection Equipment (P.P.E.) when he was struck. The struck worker sustained an approximate one and a half inch cut to his head. The worker was found conscious and was treated by the medic personnel at the site before he was sent to Mount Sinai Hospital for additional treatment. An ECB Violation was issued for a clairure to provide safety measures. A partial Stop Work Order (PSWO) was issued on conduit installations on the second floor.	ECB Violation	3537700Y		NB	121184206	Worker Fell	15 HUDSON YARDS CONDOMINIUM	Hudson Yards Construction
2/25/2019	Manhattan	1250	BROADWAY	0	A DOB inspector reported that a two-by-four hit and shattered one window on the twenty-first floor, and two windows on the twentieft floor, before landing on the thirineenth floor set back, where two workers were working. The two workers were struck and sustained wrist and shoulder injuries. It was not clear if the workers were struck by the falling two-by-four or by the glass from the shattered windows. Both injured workers were sent to a hospital for a check up. It could not be determined where the two-by-four fell from. A DOB Violation was issued to the building for the building being in a non-code compliant manner.				ALTERATION	123674737	Material Fell	1250 BROADWAY ASSOCIATES LLC	CAVAN BUILDERS CORP
2/25/2019	Manhattan	47	WEST 86 STREET	0	A DOB inspector reported that a section of parapet wall on the right side of the building was taken down by the wind. The Construction Superintendent at the site, as well as the New York City Police Department, reported that a pedestrian that was walking by suffered a few scratches. However, the object that caused was cratches to the pedestrian could not be verified. An ambulance was not called, and the pedestrian left the site on his own. Two ECB Violations were issued: one violation for a failure to safeguard, as the parapet wall was not adequately braced or secured in place, and one violation for a failure to maintain, as there were uncapped protruding botts present.		35353576Y 35353575M				Scaffold/Shed/Fence/Shoring/Installation	47 WEST 86TH STREET C	Vlad RESTORATIONS
2/26/2019	Manhattan	545	WEST 30 STREET	0	A DOB inspector reported that a worker was working on the sisth floor, near the secialator on the south side corridor, when he tripped on a piece of phywood that was being used to cover the finished floor. The phywood was not leveled, which created at fripping hazard. The worker's knee was hit. The on-site medic treated the injured worker and sent the worker to urgent care. A similar floor cover was also being used on the second and fourth floor in addition to the sight floor. The injured worker did not go through the site specific safety orientation that was provided by the Site Safety Manager. Two ECB Violations were issued: one violation for a failure to markinal safety measures, as the worker was injured on a tripping hazard, and one violation for a failure to provide a site-specific safety orientation to the worker on the site. The General Contractor is to provide a Neens and Methods for the safe operation of the site.		35377460Z, 35377461K		ALTERATION-1	121192397	WorkerFell	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
2/27/2019	Brooklyn	535	4 AVENUE	0	I A DOB inspector reported that a worker was removing windows from a delivery truck that was parked on the job site when one of the windows fell on his feet. The worker suffered an injury to his ankle and was taken to Methodist Hospital by an ambulance. An ECB Violation was issued for a failure to safeguard all persons and property. A parial Stop Work Order (PSWO) was issued on all material handling and delivering. The General Contractor is to provide a Means and Methods.		35376771L		NB	320626612	Other Construction Related Incidents	XYZ PROPERTIES INC	DYNATEC CONTRACTING INC
2/28/2019	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a worker was pulling an "A"-Frame that had sheetrock on it out of an out-of-service elevator when the "A"-Frame tipped over and pinned the worker to a wall. The worker went to a hospital on his own for a checkup.				ALT-2	140716839	Other Construction Related Incidents	SMITELL SPONSOR LLC	JT MAGEN & CO.



Incident Date		Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
28/2019	Manhattan	22	EAST 38 STREET	0	1 A DOB inspector reported that at an existing nineteem story alteration building, a worker was torching a boiler shell to cut it when he fell. The worker was taken to a clinic. The incident occurred on February 28, 2019, but was reported on the following day, March 1, 2019. Three CSB Victotines were issued: one violation for a failure to maintain safe operations, one violation for the injured worker not attending the pre-shift safely meeting, as the worker's signature was not on the meeting signing sheet, and one violation for the failure by the Site Safely Manager to notify the Department Of Buildings of the incident in a timely manner. A partial Stop Work Order (PSWO) was also issued.	ECB Violation	36363747Z/48K/49M		Alt-1	123432605	Worker Fell	JOLLY HOTELS U.S.A., INC.	Newgrange Construction CO
//28/2019	Manhattan	250	SOUTH STREET	0	1 A DOB inspector reported that a pipe filter/sprinkler worker was climbing a six foot ladder when he ht his head on a door metal frame and suffered a neck injury. The worker had his hard hat on. The worker visited the on-site medic. The medic reported that the injured worker did not have any bruises or apparent injuries, but that the worker stated that he was not feeling well, that his neck was injured, and that he had an existing neck injury. An ambulance was called to take the injured worker to a local hospital. The Site Safety Manager's daily log book was up to date. The area where the incident occurred had been cleaned. It was determined that this incident occurred as the result of a worker's error, and that no enforcement action was deemed necessary.	No Action Necessary			NE	121185528	Other Construction Related Incidents	NAME NOT ON FILE	
/28/2019	Manhattan	542	WEST 22 STREET	0	1 A DOB inspector reported that a worker was using an "A"-Frame cart to move material when the worker slipped on ice and hurth is right knee. The injured worker suffered minor injuries and was taken to a hospital by ambulane. Ice was observed at exposure four of the fifth floor. An ECB Violation was issued for a raillarie to maintain housekeeping. A partial Stop Work Order (PSWO) was issued to stop all work within the refer of exposure four on the fifth floor, which is where there was ice present. The contractors are to remove all ice.		35377465H		nb	122547583	Worker Fell	HELZEN ASSOCIATES .	Westerman Construction
///2019	Manhattan	646	11 AVENUE	0	1 A DOB inspector reported that there were workers preparing to star a dilling operation and they were checking and testing the machine as part of preparation. A worker accidentally opened the valve of a water hose by mistake, and the water hose exploded, thitting him in the stomach and throwing him to the wall. The worker was conscious and was taken to Bellevue Hospital for treatment. The worker was reported to have treatment and doing fine. An ECB Violation was issued for a failure to maintain safely measures, as the worker was injured due to the explosion of a water hose. A partial Stop Work Order (PSWO) was also issued.	ECB Violation	35377503J		NEW BUILDING	121204302	Mechanical Construction Equipment	646 11TH OWNER LLC	CM AND ASSOCIATES CONSTRU
71/2019	Manhattan	590	EAST 83 STREET	0	A DOB inspector reported that electrical work was being performed from a man lift that was at the twenty four foot high ceiling level when a tectum panel/ceiling tile fell and injured a worker. The worker was taken to a hospital for medical attention. An ECB Violation was issued for the failure to maintain safety measures, as there were inadequate safety measures in place while work was being performed on a man lift. A partial Stop Work Crder (PSWO) was issued to stop all overhead operations. A DOB Violation was also issued. A Means and Methods to prevent a similar incident from occurring in the future must be provided.		36353590R	030119CE08CV01	NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W HOWELL LLC
1/2019	Manhattan	545	WEST	0	The Site Safety Manager reported that a laborer was installing whiches in the mechanical room when he misstepped and bended his knee. The worker was treated by the on-site medics and was sent to a hospital for observation. A DOB inspector responded to the incident and reported that this incident occurred as the result of a worker's error. No enforcement action was necessary.						Other Construction Related Incidents		
/2/2019	Queens	22-18	JACKSON AVENUE	0	1 A DOB inspector reported that during a delivery operation, a forkilit pushed approximately three to four pieces of sheetock that fell and struck a worker or his waist. An ambulance was called. The worker's condition was not known as of the time of inspection. An ECD Violation was issued for the failure to maintain safety operations at the site. A partial Stop Work Order (PSWO) was issued for all delivery operations. A DOB Violation was also issued. Additional violations unrelated to the incident were also issued.	ECB Violation	35377481H	030219CE02MS03			Other Construction Related Incidents	22-12 JACKSON OWNER LLC	BRIT REALTY LLC



cident Date	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2019	Manhattan	22	NORTH LOOP ROAD	0	The Site Safety Manager reported that there were workers using a hammer to perform column form work when a worker was accidentally hit in the elbow by the hammer. The injured worker went to a hospital on his own. An ambulance was not called.	No Dispatch			NB	121203697	Other Construction Related Incidents	NAME NOT ON FILE	HUNTER ROBERTS CONST
2019	Bronx	785	COURTLANDT AVENUE	0	The Site Safety Manager reported that a worker was moving a plank from a sidewalk shed when it slipped from his hands and landed on his foot. An ambulance was callet.	No Dispatch			alt-2	240225788	Other Construction Related Incidents	NYC HOUSING AUTHORITY	neelam Construction Corp
019	Manhattan	215-225	west 28 st	0	The Site Safety Manager reported that a worker twisted his back while lifting a piece of plywood. The worker was taken to an area hospital by ambulance for observation.				nb	121185813	Other Construction Related Incidents		HAP Construction LLC
2019	Manhattan	36	WEST 66 STREET	0	1 The Site Safety Manager reported that a worker tripped and cut his lip. The worker went to a City M.D. An ambulance was not called.	No Dispatch			nb	121190200	Other Construction Related Incidents	WEST 66TH SPONSOR LLC	Lendlease
2019	Manhattan	68	SPRING STREET	0	A DOB inspector reported that a worker stepped on a nail and sustained a puncture wound on his foot. The worker elected to go to a local hospital. No hazardous conditions were found, and all safety measures were in effect. No enforcement action was deemed necessary.	No Action Necessary					Other Construction Related Incidents	68-70 SPRING PARTNERS LLC	
019	Queens	Mar-50	ST NICHOLAS AVENUE	0	The Site Safety Manager reported that a worker was carrying a length of curved rebar when the rebar hit the worker in the back. The worker went to a local urgent care center for treatment. This incident occurred at 2:00 PM, but was not reported until later in the day at 5:30 PM.				A2 - ALTERATION TYPE 2	421066633	Other Construction Related Incidents	RIDGEWOOD TOWER LLC	AB CAPSTONE BUILDERS CORP
2019	Manhattan	2306	3 AVENUE	0	1 The Site Safety Manager reported that a worker in the machine room was using equipment when he was shocked by an estension cord. The worker went to a hospital by ambulance for evaluation. A DOB inspector responded to the incident and reported that there were no unsafe electrical conditions observed. No enforcement action was deemed necessary.	No Action Necessary			NB	121190326	Other Construction Related Incidents	SALVATION ARMY	MEGA CONTRACTING GP LLC
019	Manhattan	461	WEST 34 STREET	0	The Site Safety Manager reported that a worker tripped over the black hose of a fire extinguisher and twisted his ankle. The worker went to a medical center across the street for treatment. An ambulance was not called.	No Dispatch			nb	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	Atria Builders LLC
/2019	Manhattan	86	DELANCEY STREET	0	1 A DOB inspector reported that a section of construction jersey barrier with the fenne fell on the street and hit a pedestrian pixed aelivery man. The incident occurred because a gust of with pushed and knocked the construction jersey barrier onto the street. The highred pedestrian was wearing a helmet, but the construction equipment struck him in his lower legs. An ambulance was called, and the hijured pedestrian was transported was called, and the hijured pedestrian was transported to a hospital. Two BCBV foliations were issued: one violation for a failure to safeguard the public and property, and one violation for the failure to maintain jersey barrier in a color compliant manner, as the jersey barrier sections were not filled with water. A partial Stop Work Order (PSWO) and a DOB Violation were also issued.		35411900j -35411901I	031119ce103cs01	NB	122141351	Material Fell	ORDELA LLC	Town house Builders Inc
2019	Queens	29-23	QUEENS PLAZA NORTH	0	1 A DOB inspector reported that a worker was using a ladder to climb out of an approximately twelve foot deep hole when the worker slipped and fell off of the ladder. The worker sulped and fell off of the ladder. The worker sulfered a hip injury and was taken to an eara hospital by an ambulance for observation. Two ECB Violations were issued: one violation for a failure in institute safety measures at the construction site, and one violation for the absence of shoring in the excavated hole. A full Stop Work Order (FSWO) and a DOB Violation were also issued. A Means and Methods, a Tool Box Talk, and shoring for the pit must be provided.		35363845M,35363846Y		nb	421490069	Worker Fell	OPP LLC	Hunter Roberts
2/2019	Bronx	600	BERGEN AVENUE	0	The Site Safety Manager reported that a worker was climbing off of a scaffold when his pinky finger was pinched in a scaffold cross brace. The finger was swelling, and the worker went to a local clinic to receive treatment.	No Dispatch					Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
2019	Manhattan	301	PARK AVENUE	0	treatment.  The Site Safety Manager reported that a worker was exiting a doorway when he hit his head and suffered a minor abrasion. The worker walked to a hospital and received stitches for a minor cut. An ambulance was not called.	No Dispatch			Alt 1	121191245	Other Construction Related Incidents	NAME NOT ON FILE	Tishman Construction Corp
/2019	Manhattan	15	EAST 30 STREET	0	not called.  The Site Safety Manager reported that a plumber was cutting a pipe when he received a cut on his thumb.  The worker walked to a City M.D. on his own to receive treatment.	No Dispatch			New Builidng	122128679	Other Construction Related Incidents	MADISON 30 31 OWNER LLC	Madison 3031 Owner LLC
2019	Manhattan	22	NORTH LOOP ROAD	0	treatment.  The Site Safety Manager reported that an electrician tripped and fell on the nineteenth floor deck and cut his chin on rebar. The electrician walked himself to an urgent care center on his own. An ambulance was not called.	No Dispatch			New Building	121203697	Other Construction Related Incidents	NAME NOT ON FILE	HUNTER ROBERTS CONST. GRP



ncident Date		Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
14/2019	Queens	23-15	44 DRIVE	0	1 The Site Safety Manager reported that an electrician	No Dispatch			NEW BUILDING	420655954	Other Construction Related Incidents	BGY CITYVIEW LLC	NEW LINE STRUCTURES & DEV
					was using a knife to strip insulation from wires when he knee was cut by the knife. The electrician went to urgent care for treatment.	'							
2019	Manhattan	200	AMSTERDAM AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NB	122887224	Worker Fell	AMSTERDAM AVENUE REDEVELOPMENT	PAVARINI MCGOVERN LLC
					laying rebar for a forming deck when the worker slipped while walking on rebar. The worker fell and hurt his								
					wrist. The worker went to an urgent care center on his								
					own.								
2019	Manhattan	545	WEST 30 STREET	0	The Site Safety Manager reported that a rubber air conditioning shim fell approximately one hundred feet	No Action Necessary			GENERAL CONTRACTOR	GC 613954	Material Fell	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
					from the above work area, bounced off of a boom lift,								
					and then struck a worker on both of his knees. The								
					worker reportedly went to a local urgent care center. A DOB inspector responded to the incident and reported								
					that there were no rubber air conditioning shims located	1							
					at the job, and that there was fine mesh debris netting present throughout the above work area. No unsafe								
					conditions were found at the site. No one at the job								
					witnessed the item fall, and no evidence of the reported incident was found. No enforcement action was								
					necessary, as it was determined that the incident								
					occurred as the result of a worker's error.								
2019	Brooklyn	24	BRIDGE PARK DRIVE	0	A DOB inspector reported that there were carpenters installing a door at the site. The door that was to be	ECB Violation			NEW BUILDING	321189003	Material Fell	NYC DSBS	SUFFOLK CONSTRUCTION COMP
					installed was leaning against a wall prior to the								
					installation. While a taper/shop steward of the painting contractor at the site was walking by, the door fell on								
					him and struck him on his lower leg and ankle. The								
					struck worker did not have a visible injury, but complained about pain and was transported to a								
					hospital by an ambulance. An ECB Violation was issued								
					for a failure to maintain safety measures, as the worker was injured due to the improper storage of elements								
					during the installation.								
2019	Brooklyn	11	HOYT STREET	0	The Site Safety Manager reported that a plumber was installing sprinkler pines when he felt dizzy while.	No Dispatch			ALTERATIO -1	321197059	Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	TRITON CONSTRUCTION CO.,
					installing sprinkler pipes when he felt dizzy while coming down from a ladder and accidentally hit his								
					head by a battery operated screw gun. An ambulance was called, and the worker walked to the ambulance								
					and was then taken to a hospital.								
2019	Brooklyn	135	EMERSON PLACE	0	The Site Safety Manager reported that skid debris that	ECB Violation	35363980P 35363979H	031919CE02IH03,02	NB	321183367	Other Construction Related Incidents	PRATT INSTITUTE	TISHMAN CONSTRUCTION CORP.
					was in a garbage truck snapped and a piece of the skid debris flew out of the truck and hit a worker in the neck,								
					knocking him out. This happened when the crush gate	'							
					came down on the skid. The worker was dazed and confused. An ambulance was called to the site. A DOB								
					inspector responded to the incident and reported that								
					the garbage truck involved in the incident was not on site, and that there was no evidence of the piece of skid	.							
					debris at the site. Two ECB Violations were issued: one								
					violation for the failure to institute safe operations, and								
					one violation for the tampering with the evidence of the incident. A partial Stop Work Order (PSWO) for all								
					garbage removal, as well as two DOB Violations, were								
					also issued.								
2019	Manhattan	36	WEST 66 STREET	0	The Site Safety Manager reported that a worker fell on his hand and suffered a cut to his palm. The worker went to a City M.D. for observation.	No Dispatch			NB	121190200	Other Construction Related Incidents	THIRTY SIX WEST THIRTY SIX ASS	Lendlease us Construction
2019	Manhattan	49	CHAMBERS STREET	0	1 A DOB inspector reported that there were workers	ECB Violation	35403928L, 35403929N, 35403932Y, 35403933Y	032019CE01BG01/02/03/04	ALTERATION-1	121186821	Material Fell	A	NY DEVELOPERS & MANAGEMEN
					moving heavy packages on a dolly. As the workers were turning the dolly towards the parking lot at the								
					Chambers Street gate, the workers lost control of the								
					dolly, and all of the packages fell. The packages struck a pedestrian on his elbow and on his feet. The inspector								
					reported that construction activity had been observed on	n							
					the first through fifth floors and that the floors above the fifth floor were occupied. However, it was observed that								
					the Tenant Protection Plan was not adequate, or was								
					not being maintained, as workers and tenants were getting mixed up at the site because the workers were								
					using the Chambers Street entrance, which was for								
					tenant use only. Four ECB Violations were issued: one violation for the presence of an inadequate tenant								
					protection plan, one violation for the presence of								
					inadequate safety measures, as workers were not using a fall protection system, one violation for the failure to								
					adequately contain or control the dust near the public								
					walkway of the sidewalk, and one violation to the Site Safety Manager for the failure to notify the department								
					of an incident involving an injury to a pedestrian, as it								
					was the injured pedestrian himself that reported the incident. Two partial Stop Work Orders (PSWO) and								
					four DOB Violations were also issued.								
							D 12 -f 16						



Part	Incident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Descri	ption	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
Second   Part   Part	3/19/2019				0 1 A DOB inspector thumb while using concrete bricks. The where his condition Construction Supe worker had started 2019 and that the OSHA card, but the stated that he did of operate masonry w Violations were iss provide hands-on e for a failure to safe (PSWO) for all may	eported that a worker lost his left a masony westaw machine to cut he worker was taken to a hospital, in in ork known as of this time. The intendent at the site stated that the unkning on Thursday, March 14, worker was in possession of an e Construction Superintendent also not know if the worker was trained to wetsaw equipment. Two ECB used: one violation for a failure to quapital that support the quapital stop Work Order soony cutting operations and a DOB				NB			ASTORIA ON STAGE, LLC	URBAN ATELIER GROUP LLC
Institute   Inst	3/20/2019	Bronx	3500	PARK AVENUE	pump to pour cemu unit wall when the pressure to build u inside of the hose is knocked the worke caused him to fall one scaffolding dee taken to a hospital reported to have be be okay condition. scene before the in Violations were its safeguard persons injured due to defe caused the inciden the evidence of the involved in the incident of the presence of the involved in the incident of the presence of the involved in the incident of the presence of the involved in the incident of the presence of the involved in the incident of the presence of the involved in the incident of the presence of the involved in the incidence of the involved in th	ent grout into a concrete masonry hose got blocked, which caused p inside of the hose. The pressure was suddenly released, and the hose of the hose to the hose of the hose of the hose of down, approximately two feet from ck to the next level. The worker was been responding to treatment and in The pump was removed from the spector arrived at the site. Five ECB used: now lodiation for a failure to and property, as a worker was ctucke equipment, equipment that it, one violation for the tampering with incident, as the concrete pump dent was removed from the site one violation for the presence of a to an arradway that were not de against the accidental impact from eviolation for the absence of a log for the sidewalk shed, and one ousekeeping. A full Stop Work Order suseu. A Means and Methods must	ECB Violation	35403850K, 51M, 52Y, 53X AND 54H.		NEW BUILDING	220152910	Mechanical Construction Equipment	3500 PARK APTS. HOUSING DEVELO	MEGA CONTRACTING GP LLC
Supplement   Sup	3/20/2019	Queens	27-49	JACKSON AVENUE	sustained a foot inj site. The worker w local clinic to receiv at 12:30 PM, but w	jury while walking on the construction as transported by a co-worker to a ve treatment. This incident took place vas not reported until after 4:30 PM,	No Dispatch			NB - NEW BUILDING	421324310-01-NB	Other Construction Related Incidents	27-51 JACKSON AVE LLC	DHC CONTRACTING INC
bunding own book in the first by skip the first wave on the first bunding in the first bunding own book in the first by skip the first wave of the first bunding own book in the first bun	3/21/2019	Brooklyn	76	SCHERMERHORN STREET	sustained a cut on worker was transpo treatment. This inc	his foot from a circular saw. The orted to a local hospital to receive cident occurred at 3:30 PM, but was	No Dispatch			NB - NEW BUILDING	321188086-01-NB	Other Construction Related Incidents		NOBLE CONSTRUCTION GR LLC
community noom, a worker was using a bucket to place concrete when he suffered a minor cut be his right hand. The worker went to a local urgent care center. No enforcement action was determined that this incident occurred as the result of a worker's error.    Yeb   West 93 Street   0   1 The Site Safety Manager reported that a worker twisted his anile on the street while stepping on a pallet to receive material. The worker was taken to an area	3/22/2019	Queens	103-16	CORONA AVENUE	bending over to by identify the face by siding it. The pedestrian sall and was taken to a Superintendent for and went to the sit. Construction Supe the sating that fall is sking fell because secured or discard one violation for a the failure to noistly incident in a timely of the Construction discharge responsiabsence of safety! Order (FSWO) and	Ix up an item when she was struck in that blew over and fell from the site. Ifered a laceration to he forehead hospital. The Construction the site responded to the incident e. A walkthrough of the site with the intendent gave the indication that came from the roof, and that the of materials and debris was not del. Four ECB Violations were issued: failure to safeguard, one violation for the Department of Buildings of the imanner, one violation for the failure Superintendent to properly libitities, and one violation for the logs at the site. A full Stop Work		35376053R, 35376054Z, 35376055K, 35376056M	032219CERSM01/SM02/SM03/SM04	NB - NEW BUILDING	420994357-01-NB	Other Construction Related Incidents	DANIELLA R. LLC	OCTAVIO RAPOSO
his ankle on the street while stepping on a pallet to receive material. The worker was taken to an area of the control of the worker was taken to an area.	3/23/2019	Manhattan	545	WEST 30 STREET	community room, a concrete when he hand. The worker v enforcement action determined that thi	a worker was using a bucket to place suffered a minor cut to his right went to a local urgent care center. No n was deemed necessary, as it was	No Action Necessary			NB - NEW BUILDING	121184208-01-NB	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
	3/26/2019	Manhattan	154	WEST 93 STREET	his ankle on the str	reet while stepping on a pallet to	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	



Incident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/26/2019	Bronx	700	MORRIS AVENUE	1 The Construction Foreman stated that during the cleaning of a dumpster, the dorn of the dumpster hit aworker's left leg. The struck worker called for an ambulance and the ambulance took the worker to a hospital. A DOB inspector responded to the incident and attempted to visit the site, but the site was closed and the inspector could not conduct an inspection. This inspector will conduct a follow up inspection on March 27, 2019.	No Access			EW-OW	220639487	Other Construction Related Incidents	NYC HOUSING AUTHORITY	NEELAM CONSTRUCTION CORP
3/27/2019	Manhattan	130	WILLIAM STREET	1 A DOB inspector reported that a worker was installing rebars at the fifty-sisht floor for a forming dock. The worker placed a piece of physocol on the working bene that was approximately 10 X2 in order to remove rebar to continue the operation. The physocol was not adequately secured, and when the worker stepped on the physocol, the worker fell three feet onto a working dock. The worker was experiencing back plain and was taken to Bellewue Hospital. All worker SOHA cards were presented and reviewed, as well as as a stady log. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard. A parial Stop Work of CPSWO) was issued for the fifty-sisht floor working dock. A DOB Violation was also issued.	h	363760702	032719CERSM03	NB - NEW BUILDING	121192903-01-NB	Worker Fell	130 WILLIAM STREET ASSOCIATES	DILDANE RESIDENTIAL CONST
3/27/2019	Manhattan	1558	3 AVENUE	2 A DOB inspector reported that there were two worker that were taking a large window out of a crate in order to prepare for an installation when both workers lost control of the window, which caused the window to far on them. One of the workers twisted his anxiety while attempting to get out of the way of the window, and the second worker complained of neck and shoulder pain from getting out of the way of the failing window. Both workers were taken to a hospital as a precaution. An ECB Violation was issued for a failure to institute safe measures for window operations. A partial Stop Work Order (PSWO) on window prep and installation for the entire site was also issued. A Means and Methods for the uncrating and installation of windows must be provided.	l e	35403718N		NB	121186518	Material Fell	180 EAST 88TH STREET REALTY LL	DDG development LLC
3/27/2019	Manhattan	77	CHARLTON STREET	1 A DOB inspector reported that there were workers lowering plywood when a piece of plywood slipped out of one of the worker's hands, Another worker saw this happen, and when he went to catch the falling plywood the plywood landed on his toot. The plywood caused some bleeding, and the struck worker's contractor der him to a hospital. An EGS Violation was issued for a failure to institute safety measures. A full Stop Work O'rder (FSVO) was also issued. A Means and Measures for the safe handling of construction materials must be provided.	d,	35403719P		NE	121187731	Material Fell	TOLL NY II L.P.	TOLL GC ILC
3/27/2019	Queens	97-12	65 ROAD	O 1 A DOB inspector reported that there were workers the were moving a construction fence out into the stew with no pedestrian protection in place, when a pedestrian singled off of the sidewalk. The pedestrian produced medical attention and left the scene of the incident. Four EOB Violations were issued on the violation of a failure to basfeguard persons and property, cone violation for the failure to comply with a Ste Safety Plan, one violation for the failure more property in the person of the person of the person of the person one violation for the performance of work without a DOT permit to close the sidewalk. A parial Stoylov O'crider (PSWO) was issued for the installation of new fences. A Means and Methods to safeguard the public during a sidewalk operation must be provided.	on	35148153R,54Z,55K,56M.		NEW BUILDING	421644420	Other Construction Related Incidents	RB REALTY CAPITAL LLC	FALCON PACIFIC BUILDERS I
3/28/2019	Manhattan	280	BROADWAY	1 A DOB inspector reported that a worker missed a step and twisted his knee. An ambulance was called. No enforcement action was taken, as it was determined that this injury occurred as the result of a worker's err				ALTERATION-2	122644763	Other Construction Related Incidents	DCAS	LO SARDO GENERAL CONTRACT
3/29/2019	Manhattan	1227	BROADWAY	A DOB inspector reported that there were three to four workers that were-stitempting to pick up a window. What let window was being illed, the window slipper out of one of the worker's hards and sliced through if the property of the property of the worker's hards and sliced through if the property of	i de	35403721Y Page 15 of 46	032919CE05Sk01	NB	121191986	Material Fell	YJL BROADWAY HOTEL LLC	FLINTLOCK CONSTR SERV LLC



Incident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/1/2019	Bronx	3	VYSE AVENUE	0	1 A DOB inspector reported that a worker was dismantling 2" X* 4 wooden frames that were being used for window protection when he tripped, fell, and hurt his knee. An ambulance was called. A DOB inspector responded to the incident and reported that he housekeeping of the work area was not adequately maintained, as there was a tripping hazard present. Construction material and debirs created the hazardous conditions. The site featured supported scaffolding, but the netting on the scaffolding was not secured, as it was flying in the air. A design drawing for the ramp leading to the loading dook was not secured, and the ramp was missing a guardrail and a toe board. An ECB Violation was issued for inadequate housekeeping. Additional ECB Violations and two partial Stop Work Orders (FSWO) were also issued for infractions that were not related to the incident.	ECB Violation			NEW BUILDING	220152581	Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	HLS BUILDERS CORP
4/1/2019	Queens	22-44	JACKSON AVENUE	0	1 A DOB inspector reported that there was a worker that had stacked counter tops in an unsafe manner, which caused one of the counter tops to fall on the worker's leg. An ambulance was called. An ECB Violation was issued for a failure to institute and maintain safety measures. A partial Stop Work Order (PSWO) was issued on all material deliveries and handling. A DOB Violation was also issued. The General Contractor is to provide a Means and Methods for the safe handling of all materials.	ECB Violation	35418147K	040119CE01RV01	NB	420651912	Material Fell	G & M REALTY, L.P.	LRC CONSTRUCTION LLC
4/1/2019	Queens	52-41	CENTER BOULEVARD		2 A DOB inspector reported that during the drilling of caissons, there was a compressor hose unming between two workers. During the operation, the hose between two workers. During the operation, the hose between the workers and to the provide the caused or so the workers and to the provide the caused of the workers and the caused of the workers was taken to a hospital, where he received X-rays, and the second worker remained on the site. A hazardous condition was created because the high pressure hose was running through other workers, as opposed to through an isolated area. The job also featured other unsafe conditions. Five ECB Violations were issued: one Aggravated Level 2 violation to the Concrete Subcontractor for the failure to institute safety measures, as a worker was injured during a drilling operation, one violation to the Concrete Subcontractor for the failure to institute safety measures, are to the superiment that was in use, one Aggravated Level 2 violation to the General Contractor for the equipment that was in use, one Aggravated Level 2 violation to the General Contractor for the failure to institute safety measures. As a worker was injured during a drilling operation, one violation to the General Contractor for the profurance of work without a permit. A full Stop Work Order (FSWO) was also issued. The General Contractor is to obtain an updated Site Safety Plan, and one violation to the Safety Plan and an emporary equipment permit and is to provide and means and Methods for the safe operation of the job.		35403942H, 43J, 44L, 45N AND 46P		NEW BUILDING	420663703	Mechanical Construction Equipment	52-41 CENTER LLC	52-41 CENTER GCLLC
4/4/2019	Manhattan	550	WEST 34 STREET	0	1 The Site Safety Manager reported that a worker got his hand caught between scafdolding and a building, and suffered lacerations to his pinky and ring fingers. The worker was treated by the on-site medic, and was then sent to a nearby medical facility. A DOB inspector responded to the incident and determined that the incident occurred as the result of a worker's error. No enforcement action was deemed necessary.	No Action Necessary					Other Construction Related incidents	ONE HUDSON YARDS OWNER LLC	
4/5/2019	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that an HVAC installer was installer was installer was installer safe when the 277-volt temporary lighting system. Acrong occurred, and the acring burned the worker's clothing. The worker went to a hospital for observation. A DOB inspector responded to the incident and issued two ECB Violations: one violation for the presence of unapproved unsalle wiring, as the acring was caused by the presence of wring that was defective due to a damaged or burned installation, and one violation for a failure to provide a covier of naceplate, as covers were not installed on the spice boxes. Two DOB Violations were also issued.	ECB Violation	35359309R & 35359310Y	040519EE105RH1& 040519EE105RH2			Other Construction Related Incidents	SMITELL SPONSOR LLC	



Incident Date	Borough	Address Number	Street	Estalitice Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Queens	148-10	ARCHER AVENUE	0 1	A DOB inspector reported that a worker was working on the ninth floor dock when he tried to plug in an extension cord that had been exposed to water because of rain. The worker received an electrical shock. An ambulance was called and the worker was taken to Jamaica Avenue Hospital. The Site Safety Manager was not notified of the incident until 445 PM, because the worker that suffered the shock was told by his foreman to relain, in the sharty. It was not until the ambulance arrived that the Site Safety Manager was made aware of the incident. No enforcement action was necessary.	No Action Necessary	CO Violation Autober 5	SOUTHWARD NAME OF THE PROPERTY		Tallia to	Other Construction Related Incidents	BRP JAMSTA TWO TC OWNER LLC	Constitution
4/6/2019	Manhattan	111	VARICK STREET		A DOB inspector reported that a worker was unloading rebar at the sixteenth floor deck when he tripped, fell, and dislocated his elbow. The load was not attached to a crane. An ECB Violation was issued for unsafe material handling. A partial Stop Work Order (PSWO) and a DOB Violation were also issued.	ECB Violation	35412141M	040619CE02FB10			Other Construction Related Incidents	111 VARICK ARLINGTON OWNER LLC	CM AND ASSOCIATES CONSTRUCTION
4/8/2019	Bronx	2195	MORRIS AVENUE		The Site Safety Manager reported that a worker was working in the basement when he stepped on a 2". X 4" and a nail went through his boot. The worker took himself to a hospital. A DOB inspector responded to the incident and -eported that the area has piles of construction material and debirs present, which created a hazardous condition. A panel of the fence in the backyard was also missing, which made the site accessible from the adjacent property. Two ECB Violations were issued: one violation for the failure to maintain adequate housekeeping, and one violation for the absence of a panel of fence from the site. A partial Stop Work Order (PSWO) was issued on all work except for the repairing of the fence, the maintaining of housekeeping, and the installation of protection for the adjoining properly and holds: The General Contractor must ensure all safety measures before the Stop Work Order is lifted.		35403873N, 74P		NEW BUILDING	220546648	Other Construction Related Incidents	GRAND APTS HOUSING DEVELOPMENT	M. MELNICK & COMPANY INC
4/8/2019	Manhattan	1802	2 AVENUE		A DOB inspector reported that a truck driver was removing a spool of electrical wire from his truck when he lost control of the spool and hit himself in the forehead. The truck driver soffered a minor cut and went to shoppilal. We development action was not popular to the control of the control of popular to the control of the control of coursed as the result of a worker's error.	No Action Necessary			NB	121191361	Other Construction Related Incidents	OHI ASSET NY 2ND AVENUE, LLC	T.G NICKEL
4/8/2019	Manhattan	287	BROADWAY		The Site Safety Manager reported that a worker was performing exterior painting when he fell approximately seven feet from a scaffold, falling from the sidh floor to the fifth floor. The worker suffered possible broken ribs and was taken to a hospital by an ambulance. A DOB inspector responded to the incident and issued eight total CES Violations: one violation for the absence of a sign-off inspection for scaffolding, one violation for the absence of a sign-off inspection for scaffolding, one violation for the absence of a sing-off inspection for scaffolding, one violation for the absence of a four hour user certification for the absence of a fail vingerion of scaffolding, one violation for the absence of a failure to hour service of the scaffold that suffered the injury, one violation for the scaffolding, one violation for the presence of an inadequate Construction Superintendent (go, one violation to the General Contractor for the failure to notify the Department Of Buildings about the incident. A partial Stop Work Order (PSWO) was issued on all work on supported scaffolding. The General Contractor is to provide a Means and Methods for the safe operation of the job.		35403964Z, 65K, 66M, 67Y, 68X, 69H, 70P & 71R.		ALTERATION-1	121187624	Worker Fell	NEW 379 BRIDGE, LLC	M&R CONSTRUCTION GROUP IN



ncident Date	Borough	Address Number		Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
V8/2019	Manhattan	311	EAST 50 STREET	1	O A DOB inspector reported that there were two workers that were lowering a suspended scaffold platform in order to take their funch break. The workers were between the sixth and seventh floor level when a piece of coping stone that was under one of the C-Hooks fell onto one of the workers. The struck worker was rescued by the New York City Fire Department through a window and was transported to a local hospital. The struck worker passed away due to his injuries. The second worker was taken to the hospital for observation, and later returned to the site. Both of the workers were in possession of both sidenen-hour training carchs and a Certificate Of Fitness to be on the suspended scaffold. The rigger came to the site and was working on lowering the suspended scaffold platform to the incident. A DOB Violation was issued for a failure to safequand. A full Stop Work Order (FSWO) was also issued.	DOB Violation		Q40819CE0801MH	ALTERATION TYPE 2 - FACADE	123362217	Material Fell	GREAT BAY BLDG CO.	Vlad Restoration LTD
W/8/2019	Manhattan	815	AMSTERDAM AVENUE	0	The Site Safety Manager reported that a worker tripped on the roof and fell, and that the worker injured his pair on a steel structure while trying to find his balance. A co-worker took the injured worker to a hospstal for a checkup, A DOB respector responded to the incident and the street of the index		35403909X,10N,11P,12R,13Z	040819CE07CV01,02.03,04,05	NB	123305878	Worker Fell	NAME NOT ON FILE	MJM ASSOCIATES CONSTR. LLC
9/2019	Queens	22-18	JACKSON AVENUE	0	A DOB inspector reported that a worker tripped on a hoist ramp and hurt his knee. An ambulance was called. As of the time of inspection, the ramp was in place, and there were no tripping hazards present. No enforcement action was deemed necessary.	No Action Necessary			NB	420655838	Worker Fell	22-12 JACKSON OWNER LLC	BRITT REALTY LLC
/9/2019	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that a worker was waiking by a baker scaffold when he was hit in the head by a piece of railing that had fallen off. The worker was wearing his hard hat. The worker walked to a City M.D. An ambulance was not called. A DOB inspector responded to the incident and reported that there was no evidence found of the worker being hit by a piece of railing, and that the scaffold was in a Controlled Access Carol (CAS_years. The injured worker had affectedly left that the scaffold was in a Controlled Access to the Case of the piece of railing and that the scaffold was in a Controlled Access that the Case of the piece of the	1			AALT-1	120996351	Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	PAVARINI MCGOVERN
/9/2019	Brooklyn	525	ST MARKS AVENUE	0	1 The New York City Fire Department requested that an inspection plaase be performed because a worker was injured by falling debris. A DOB inspector responded to the incident and reported that the injury to the worker was milor, and that an ambulance was called and the worker was taken to Kings County Hospital. Two ECB Violations were issued: one violation for the failure by the permit holder at the site to provide inspection access to the ongoing construction, and one violation to the Construction. Superintendent for the failure to perform their culties are per code. A full Stop Work Order (FSWO) and two DOB Violations were also issued.		35407661J, 35407662L	040919CNEGS01/GS01	DM - FULL DEMOLITION	321633639-01-DM	Other Construction Related Incidents	525 SMA OWNER, LLC	XOLLE DEMO LLC
/10/2019	Brooklyn	1	PIERREPONT STREET	1	O A DOB inspector reported that there were two workers at a thirteen-story building that were performing brick replacement work underneath the water tank when one of the workers fell from the roof to the grade level. The fallen worker soucumbed to his juries. The fallen worker was not using any fall protection system. There was no permit for the brick replacement work, and there were no guard rails or fall protection systems present. Sets eastley orientation for working on the penthouser dos was not provided. A DOB Violation was issued to the owner of the building. A full Stop Work Order (FSWO) was also issued.	a L		041019CE0201BG	NA NA	NA	Worker Fell	ONE PIERREPONT STREET CORP	NA
/11/2019	Bronx	600	BERGEN AVENUE	0	The Site Safety Coordinator reported that a worker scraped his shin while performing work on the fifth floor. The injured worker was taken to a medical center by the site's foreman.	No Dispatch			NB - NEW BUILDING	220151868-01-NB	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/11/2019	Manhattan		CHARLTON STREET	0 1		No Action Necessary			NB NB	121191263	Material Fell	STRATEGIC GREENWICH EQUITY, LL	PLAZA CONSTRUCTION LLC
4/12/2019	Manhattan	217	WEST 57 STREET		The Site Safety Manager reported that an electrician jammed his fingers while performing drilling. The worker left the site and went to receive emergency care. An ambulance was not called. The incident occurred on the previous day (April 11, 2019), but the Site Safety Manager was not made aware of the incident until the electrician's foreman reported the incident to the Site Safety Manager at 11:00 AM on April 12, 2019.				NB	121328205	Other Construction Related Incidents	SMITELL SPONSOR LLC	LEND LEASE
	Manhattan		WEST 37 STREET		workers that were unloading materials and equipment from a flatabet funck when a piece of 2" X 4" came loose and hit a pedestrian that was in the street. An ambulance was called, and the pedestrian was taken to a hospital for a checkup. A DOB inspector responded to he incident and reported that the istel logistics were not in conformance with the Site Safety Plan, and that the incident and expended that the istel logistics were not in conformance with the Site Safety Plan, and that the indewalk had been closed inside of the jobsite, which caused the pedestrian to have to walk through the storage area on the street, which caused the incident. Six ECB Violations were issued: one violation for the singuity to a pedestrian, one violation for the order of the presence of underpinning work that was not following the sequence of the approved plan, one violation for the presence of a ramp that was leading to excavation that was missing a guardrail, one violation for the absence of a valid Department OT Transportation permit to close the sidewalk, and one violation for the presence of a valid Department OT Transportation permit to close the sidewalk, and one violation for the presence of a valid Department OT Transportation permit to close the sidewalk, and one violation for the presence of an inadequal sign for Corter (FWM) was alreaded Site Safety Plan and provide Meens and Methods for the safe operation of the job.		35404010M, 11Y, 12X, 12H, 14J & 15L		NEW BUILDING	122865319	Other Construction Related Incidents	WEST 37TH ST LLC	HAPPY LIVING DEVELOPMENT
4/13/2019	Manhattan	570	BROOME STREET		A DOB inspector reported that that while the 7.5 ton counterweight of a crane was being loaded with Leibert manufactured endess sings, the load was snagged by the rigging pear after it had landed, which caused the counterweight to be polled up out of its resting position. The counterweight left approximately motivated to the counterweight pear to be considered to the counterweight and the survive the event. The counterweight also damaged the carrier. The load was in the eyesight were of the rose operator. No rado communication was being used as of the time to the incident. An assembly menting was held prior to the assembly of the crane. The crane is going to be dismantled, and the site will be cleared by a forklift. Two DOB Violations, a Cease Use Order (CUO), and a partial Stop Work Order (EWO), were issued. ECB Violations are pending issuance as of April 17, 2019.		Pending	SWO041319ML02 CUO041319ML01.	CN	223/19	Mechanical Construction Equipment	SOHO BROOME CONDOS LLC	United Crane and rigging



Incident Date	Borough	Addrage Number	Stroot	Estalities Injuries EOC Final Description	DOR Action	ECR Violation Numbers	DOR Violation Numbers	Pormit	Pormit No	Incident Type	Owner's Name	Contractor Name
ncident Date V15/2019	Borough Brooklyn	Address Number 1443	Street LINCOLN PLACE	Fatalities Injuries EOC Final Description  1 The Construction Superintendent reported that a wor was unloading delivered materials on the second floc when he tripped and fell through a hole in the floor, failing to the first floor. The worker was unloading to the first floor. The worker was used to a hospital by an ambulance. A DOB inspector respond to the the noticent and visited he site and reported that it worker was considered that the site and reported that worker was considered that the site and reported that worker was considered that the site and reported that the second that the second in the site of the incident of the construction Superintendent, it equipment was not hooked on as of the time of the incident. The inspector also reported that the second floor was not floored, as there were joist that where rully connected, which created the opening that the worker fell through. An ECB Violation was issued for failure to safleguard, as there was inadequate fall protection present at the site. A full Stop Work Order (FSWO) was also issued. The Construction Superintendent is to provide a Means and Methods, well as an adequate form of fall protection, in order to prevent tuture incidents. The only type of work with at the allowed at the site is housekeeping and safety measure implications. No new work is to be performed and no new deliveries are to be made, until the Stop Work Order is rescribed.	od ee e e e e e e e e e e e e e e e e e	ECB Violation Numbers 35412147N	DOB Violation Numbers	Permit ALTERATION TYPE 1	Permit No 321148931	Incident Type Worker Fell	Owner's Name LINCOLN ESTATE HOLDINGS LLC	Contractor Name ALL STARR 1 LLC
4/15/2019	Manhattan	112	EAST 11 STREET	1 A DOB inspector reported that a worker hurt himself while moving a heater in the basement. The worker pain in his arm and chest. An ambulance was called. The worker eventually returned to work. An ECB Violation was issued for a failure to institute safety measures. The contractor is removing the heater and Con-Edoon is working with an electrician to resolve a problems.	olt	35403836Y		ALT-	123405154	Other Construction Related Incidents	CASTLE PARK HDFC	LEEDING BUILDERS GROUP
4/16/2019	Manhattan	553	WEST 30 STREET	The Site Safety Manager reported that a carpenter entered stair B when he stepped on a screw. The scr went through the worker's show and the worker fell down the stairs and hurt his neck. An ambulance wa called, and the worker was taken to Belleuve Hospital DOB inspector responded to the incident and reporte that there were no witnesses to the incident, and that the injured worker called an ambulance on his own. inspector also reported that there were no housekeeping issues present at the site, and that the were handralis in place. No enforcement action was necessary. It was determined that this incident occur as the result of a worker error.	a. A d he			NB	121184208	Worker Fell		HUDSON YARDS CONSTRUCTION
4/16/2019	Brooklyn	50	BRIGHTON 1 ROAD	A competent person at the site reported that a worke was injured while erecting a sidewalk shed. The injur worker was taken to an area hospital. This incident to place at 500 PM on Monday, April 15, 2019, but was not reported until 5:00 PM on Tuesday, April 16, 201	ed ok			Sidewalk Shed	B00075266-I1-SH	Worker Fell	40-50 BRIGHTON FIRSTROAD APTS	CB EXPEDITING
4/16/2019	Bronx	600	BERGEN AVENUE	1 A DOB inspector reported that a Bobcat was on a roadway, transporting materials from one end of the to another, when the Bobcat struck a which lesh has passenger in it. The pedestrian passenger complaine about diz-rioses and was transported to a hoppital. The pedestrian was released from the hospital. Certified flaggers were in piace at the site as of the time of the incident. An ECB Violation was issued for a failure to institute safety measures. A partial Skop Work Order (PSWO) was issued to stop all use of a Bobcat. A Violation was also seased. A Means and Methods to prevent a similar incident from occurring must be provided.	itte a d e	35403877K	041619CE01WZ03	NB	220151868	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONSTRUCTION & DEV CORP
4/17/2019	Manhattan	1271	6 AVENUE	The Site Safety Manager reported that an electrician tripped on a conduit during lunch and pulled his hamstring. An ambulance was called.	No Dispatch			ALT-1	123401835	Worker Fell	ROCKEFELLER CTR NORTH INC	JRM CONSTRUCTION MGMT LLC
4/17/2019	Queens	Mar-50	ST NICHOLAS AVENUE	The Site Safety Manager reported that a worker pinched his fingers during lagging operations. The worker went to an emergency room with a co-worker An ambulance was not called.	No Dispatch			ALT-2	421066633	Other Construction Related Incidents	RIDGEWOOD TOWER LLC	AB CAPSTONE BUILDERS CORP
4/18/2019	Manhattan	73	VARICK STREET	1 A DOB inspector reported that there was a worker th was working off of a six foot high mobile baker scaff to tape sheetrock. The worker was propelling both himself and the scaffold along a wall when he fell for the scaffold. The New York City Fire Department responded to the incident, placed a neck brace on the injured worker, and transported the worker to a hosp There were no guardrails on the baker scaffold, and baker scaffold of wheels were not locked. An ECB Violation was issued for the failure to maintain safely equipment measures. A parial Stop Vork Order (PSWO) was issued on all scaffold use on the fifth fi	n al.	35418214L		ALTERATION TYPE 2 - MOD/G(	123158000	Worker Fell	REMAINDERMAN 1 HUDSON SQUARE L	REIDY CONTRACTING GROUP



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Queens	35-27	30 AVENUE		A DOB inspector reported that a pedestrian was hit with a piece of concrete during the installation of a sidewalk. The pedestrian was taken to a local hospital, and was reported to be in stable condition. This incident took piace on April 17, 2019, but was not reported until April 18, 2019. Two ECB Violations were issued for a failure to notify the Department Of Buildings of the incident one violation that was issued to the General Contractor, and one violation that was issued to the Site Safety Manager. Two DOB Violations were also issued.		35403736K 35403745Z	041819CE01KS01,02	ALT	420652751	Other Construction Related Incidents	30TH AVE REALTY PARTNERS LLC	WHITE CONTR & RENOVATION
4/23/2019	Bronx	600	BERGEN AVENUE	0	A DOB inspector reported that a worker was removing plyword from a fourth floor ceiling when he was hit by a small piece of plywood. The worker went to an urgent care center. An ambulance was not called. An ECB Vollation was sused for a failure to maintain safety measures during formwork stripping operations.		35403889H	042319CE01WZ03	NB	220151868	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST
4/23/2019	Manhattan	200	EAST 21 STREET	0	The Site Safety Manager reported that a worker was cleaning up broken glass when he mishandled some of the glass and cut his wrist. An ambulance was called.	No Dispatch			NB	121190479	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC
4/23/2019	Manhattan	441	9 AVENUE	0	The Site Safety Manager reported that there were four 4 X 8 pieces of sheetrock that were on an 'A'-Frame. The 'A'-Frame tipped over, and the sheetrock hit a worker on their shin. The struck worker went to an emergency ro	No Dispatch			ALT	120996351	Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	PAVARINI McGOVERN
4/24/2019	Manhattan	424	5 AVENUE	0	The Construction Superintendent reported that a worker was pushing a mini buggy when he hurt his back. The injured worker was sent to a hospital for a checkup.	No Dispatch			ALTERATION	123665499	Other Construction Related Incidents	424 FIFTH AVENUE LLC	TECTONIC BUILDERS INC
4/24/2019	Manhattan	30	EAST 31 STREET		A DOB inspector reported that there were iron workers that were hosting a setel tube in place when one of the workers got his finger caught between the steel tube and a steel pook, which caused a cut to the worker's right middle finger. The worker was taken to a hospital by an ambulance. All premiss at the site were not by an ambulance. All premiss at the site were not cause, and the log books at the site were up to date. The injuried worker was in possession of valid thirty-hour OSHA and scaffold user cards. Three ECB Violations were issued: one violation for the failure to maintain safety measures, one violation for the failure to callequare persons and property, due to the presence of inadequate vertical netting, and one violation for the presence of possessinal protection that did not meet code specifications. A partial Stop Work Order (PSWO) was issued for work from the roof level to the thirty-third floor and ten feet away from the parimeter at vertical netting locations. A Means and Methods for the safe installation of steel tubing at the roof must be provided. The vertical netting from the roof down to the thirty-third floor must be repaired. The Yodock barriers must be maintained as per code.		35418216, 35418217R, 35418218Z		NB	121192681	Other Construction Related Incidents	31ST STREET ZEF LLC	E&T SKYLINE CONSTRUCTION
4/24/2019	Manhattan	200	PARK AVENUE	0	A DOB inspector reported that there two construction workers were surveying for potential future work in the concealed ceiling of an adjacent commercial space in the same building when the workers learned on part of a Concrete Masonry Unit (CMU) block wall. A brick that was on tog of the wall fell into an adjacent service passageway and struck a restaurant employee (a pedestrian). The restaurant employee suffered a laceration to the head and was taken to a local hospital by an ambulance. The injured restaurant employee/pedestrian was not within the job site when leniched nocurred. The incident occurred outside of the scope of the filed contract, since-it took place approximately 150 feet away from in-progress work. Two ECB Violations were issued: one Aggravated Level 2 violation for the failure to immediately notify the Object of the Stope of the filed contract, since and one violation for a failure to safeguard. A DOB Violation was also issued.		35375223X, 35407676M	042419CNEKC01, 042519CERDL01	ALTERATION TYPE 2	123406901-01-EW-OT	Material Fell	200 PARK, L.P.	CLUNE CONSTRUCTION CO LP
4/24/2019	Brooklyn	800	FLATBUSH AVENUE	0	The Site Safety Manager reported that a worker hurt her leg. The injured worker went to a clinic on her own. The leg was found to be fine, and the worker returned to work.	No Dispatch			NEW BUILDING	321188567-01-NB	Worker Fell	CATON FLATS HOUSING DEVELOPMEN	LETTIRE CONSTRUCTION CORP



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
//24/2019	Broldyn	S35	4 AVENUE	0	A DOB inspector reported that the Construction Superintendent was walking down a wooden stair on the first floor when he stepped on a piece of pipe. The pipe rolled, and the Construction Superintendent let hospital to get a checkup. The job plant interest that the hospital to get a checkup. The job had a housekeeping problem, there was debris, tools, and materials stored in the walking and hallway, which reduced greess and created a hazardous condition. Two ECB Violations were issued: one violation for the failure to maintain adequate housekeeping, and one violation for the absence of a design drawing for the wooden stair. A partial Stop Work Order (PSWO) was issued for all work on the fourth through seventh floors. The General Contractor must maintain housekeeping before the partial Stop Work Order (PSWO) was issued for all work on the fourth through seventh floors. The General Contractor must maintain housekeeping before the partial Stop Work Order will be rescinded.	ECB Violation	35421161Y, 62X		NEW BUILDING	320620612	Worker Fell	XYZ PROPERTIES INC	DYNATEC CONTRACTING INC
4/24/2019	Brooklyn	1630	EAST 102 STREET	0	A DOB inspector reported that a worker was bringing in components of a material hoist when he strained his back while trying to lift the equipment. The worker went to a hospital to get receive a checkup, and then came back to work. The workers foreman then sent the worker home. Facaded and roof repair work was in progress under a valid permit. All design drawings and permits were in place. No enforcement action was necessary.				FAÇADE REPAIR	321748785	Other Construction Related Incidents	NYC HOUSING AUTHORITY	ZORIA HOUSING, LLC
4/24/2019	Bronx	556	BERGEN AVENUE	0	A DOB inspector reported that an installation of precast concrete planks was in progress when a worker bumped into a loose shoring jack that was supporting the steel lintel over the door. The shoring jack fell and in the worker's reach. The worker was transported to a hospital. The Site Safety Manager stated that there was controlled Access Zone (AZQ) on the floor, but that the injured worker did not follow the instructions. Four ECO Violations were lossed one Aggravated Level 2 safeguard persons and property, one violation to the Concrete Subcontractor for a failure to safeguard one violation for the failure of the failure of the injured worker to attend the pre-rest meeting for that day. A full SISO Work Order (FSWO) was issued. Four DOB Violations were also issued.	<b>.</b>	35403890P, 35403891R, 35403892Z, 35403893K	042419CE01WZ01/02/03/04	NEW BUILDING	220151859	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
4/25/2019	Queens	Mar-50	ST NICHOLAS AVENUE	0	The Site Safety Manager reported that a worker stepped on a nail while performing a property survey. The worker went to an urgent cate center.	No Dispatch			alt	421066633	Other Construction Related Incidents	RIDGEWOOD TOWER LLC	AB Capstone Builders Corp
4/26/2019	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a worker misstepped, slipped off of an "A"-Frame ladder, and hurt his knee. The worker was seen by the on-site medic, and was then transported to a hospital by an exhibitors.	No Dispatch			NB	121328205	Worker Fell	SMITELL SPONSOR LLC	LENDLEASE US CONSTR.
4/26/2019	Queens	28-07	JACKSON AVENUE	0	ambulance.  A DOB inspector reported that a worker was attempting to climb a baker scaffold when he fell six feet. The worker was found conscious. An ambulance was called The General Contractor and the Subcontractor provide a thirty-hour OSHA card and a New York City ID card for the worker, but did not provide a four hour supportes scaffold user certificate. Two ECB Violations were issued: on evidation for the failure to provide a scaffold training certification, and one vidation for the failure to adequately restrain the scaffold from tipping, as per code. A partial Stop Work Order (PSWO) was issued for alluse of a baker scaffold. A valid supported scaffold user certification and a toolbox talk for the use and installation of a baker scaffold must be provided.	i. d	35418430X,35418431H		NB	420656873	Worker Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
4/29/2019	Brooklyn	866	PARK AVENUE	0	A DOB inspector reported that a worker was struck in the shoulder by a falling beam during the installation of a sidewalk shot. The worker was found conscious, but was experiencing pain and was taken to a hospital. According to a New York City Howsing Authority architect, an emergency sidewalk shed was being erected due to the presence of an unsafe facade. However, a Cycle 7 report was filed on August 9, 2014. However, a Cycle 7 report was filed on August 9, 2014, and a Cycle 8 report has not yet been filed. Four ECB Violations were issued: one violation for the failure to Safeguard persons and properly, as a worker was injured, one violation for the tampering with the evidence of an incident, as the beam that had fallen was removed, one violation for the erecting of a sidewalk shet whithout a permit, and one violation for the failure to file a Cycle 8 facade report. A partial Stop Work Order (PSWO) was also issued.		35403922K, 23M, 24Y & 35424900M				Scaffold/Shed/Fence/Shoring/Installation	NYC HOUSING AUTHORITY	ROMA SCAFFOLDING



Incident Date		Address Number	Street	Fatalities Injuries EOC	C Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/30/2019	Queens	101-51	107 STREET	proc was onto cons tranan ECE to ss inada accc heal	OB inspector reported that a brick siding was in the sess of being removed when a section of brick that approximately 4" X 5" became dislodged and fell a aprivately at the Exposure 2 ground level. A struction worker suffered a minor injury and was sported to an area hospital. Two Aggravated Level 2 Violations were issued: one violation for a failure afleguard, and not violation for the presence of equate househeeping, as there was a faire foregular than the violation for the presence of equate househeeping, as there was a faire of the presence of the p		35407100J & 01L	043019CEREP01 & 02	ALTERATION TYPE 2	421620366-01-EW-OT	Material Fell	WAZIM S BACCHUS	ZIM CONSTRUCTION INC
5/1/2019	Brooklyn	130	HUMBOLDT STREET	roof.	orker tripped and fell backwards while working on a . The injured worker was transported by ambulance n area hospital.				ALTERATION TYPE 2	340641531-01-EW-OT	Worker Fell	NYC HOUSING AUTHORITY	PRO-METAL CONSTRUCTION INC
5/1/2019	Brooklyn	346	43 STREET	0 2 A Departs four prop mud floor boars the v One grad Bottle were Departs for a min of the floor boars and bottle were the floor fl	To the encoupse.  To deep companies to the companies of t		35424933Z	050119CE07BG09	NEW BUILDING	321185427	Worker Fell	MCKECHNIE, JOSEPH R JR	REDLINE CONSTRUCTION & MA
5/1/2019	Manhattan	200	AMSTERDAM AVENUE	dow whe step right stair haze and illum occu	OB inspector reported that a carpenter was walking in the stairs from the third floor to the second floor in he slipped and fell approximately six to seven in he slipped and fell approximately six to seven is. The worker was experiencing pain in his neck, knee, and hip. An ambulance was called. The swere found to be free of any slipping or tripping arts. No material or debris was stored on the stairs, the hand rails were in place and were adequately initiated. It was determined that this incident urred as the result of a worker's error. No orcement action was deemed necessary.	No Action Necessary			NEW BUILDING	122887224	Worker Fell	AMSTERDAM AVENUE REDEVELOPMENT	PAVARINI MCGOVERN LLC
5/1/2019	Queens	68-04	TIDES ROAD	usin reba	Site Safety Manager reported that a worker was g a pipe to bend rebar back into position when the ar broke and the pipe that the worker was using hit worker in the ear. An ambulance was called.	No Dispatch			NB	421305661	Other Construction Related Incidents	NAME NOT ON FILE	ROCKAWAY BEACH BLVD CON. C.
5/2/2019	Manhattan	9	ORCHARD STREET	bein cut t insta was Man glov conc	OB inspector reported that an elevator cart was gb uilt on the second floor when an elevator worker his hand on an elevator panel that was being alled. The worker went to a local hospital, where he treated and then released. The Site Safety ager at the site stated that the worker had work es at the start of the operation. No unsafe ditions were observed in the work area. No occement action was necesary.	No Action Necessary			ALTERATION TYPE 1	121326010-01-AL	Other Construction Related Incidents	NINE ORCHARD PARTNERS, LLC	DNP BUILDERS LLC
5/4/2019	Brooklyn	2619	OCEAN PARKWAY	level struv and work the viola viola at th desis part	OB inspector reported that a rebar at the ground that was inadequately secured came loose and that was inadequately secured came loose and called, the worker was transported to a hospital. The terreceived treatment and their returned to work at site. Three ECB Violations were issued: one state that the state of the secure of of	ECB Violation	35424959J / 60R / 61Z	050419CE13DM02 / DM03 / DM04	NB / EARTH WORK / FOUNDATION	320911171	Other Construction Related incidents	HEALTH AND HOSPITALS CORP	TURNER CONSTRUCTION COMPANY



Incident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/6/2019	Brooklyn	1270	NEW YORK AVENUE	1 A DOB inspector reported that a backhoe vehicle we being operated by an unaumbrized drive insolated to it fence area. The backhoe struck a farce, and a 4 x section of the fence all con a female pedestrian. In injured pedestrian was transported to a local hospital The collapsed plywood was restored. The Site Superintendent was present at the site as of the time the inspection, but did not notly the Department Of Buildings of the incident (the incident was reported to the New York City Fire Department). For ECB Violations were issued: one violation for a failure to safeguard, one violation to the General Contractor from the failure to possess or maintain a required daily to one violation for the property owner for the failure to possess or maintain a required daily to one violation for failure to notly the Department Of Buildings of an incident that featured a fatality. A full Stop Work Order (FSWO) was issued.	ECB Violation  8' 8' 10 11 11 11 11 11 11 11 11 11 11 11 11	039002647N, 48p, 49r, 50y		NEW BUILDING	321751902-01-NB	Mechanical Construction Equipment	1270 NY AVE. LLC	DEVELOPING NY STATE LLC
5/6/2019	Brooklyn	85	JAY STREET	The Site Safety Manager reported that a worker was stiting on a gang box during a cofee break when he pulled a wire that was coming out from below the gabox and suffered a cut to his hand. The on-site med wrapped the worker's hand and sent the injured wor to a hospital for treatment.	ng ic			NEW BUILDING	321188415	Other Construction Related Incidents	85 JAY STREET BROOKLYN, LLC	NEW LINE STRUCTURES & DEV
5/6/2019	Manhattan	375	PEARL STREET	The site superintendent reported that a worker was loading pieces of glass into a dumpster when one of pieces of glass was droped and cut the worker's let.  The worker was transported to a local hospital by an ambulance to receive treatment.	the g.			ALTERATION	123560976	Other Construction Related Incidents	NAME NOT ON FILE	TURNER CONSTRUCTION COMPA
5/6/2019	Queens	147-40	ARCHER AVENUE	1 A DOB inspector reported that a worker was using a handheld grinder to grind a concrete surface on the when the grinder slipped out of the worker's hands at fell on her right knee. The worker suffered an injury her right knee and was sent to an urgent care center an ambulance was not called. Four ECB Violations were issued: one violation for the failure to conduct pre-shift safety meeting prior to the commencement the operation, one violation for the failure to provide site-specific safety orentation to the worker that was injured, as the worker does not speak English one violation for the failure to provide proof of the worker experience with using a grinder, and one violation to the failure to provide a proof of the worker experience with using a grinder, and one violation to the failure to provide an inspection record for the safe strap and the improper installation of a safety strap around a sharp-edged metal without a softenter. The General Contractor is to provide a Means and Whith for the safe operation of the job, including a site-spe safety orientation for all workers, as well as Tool Bos Talks.	roof and to fr. a of a o	35418400P, 01R, 02Z AND 03K		NEW PERMIT	420654508	Mechanical Construction Equipment	HP JAMSTA HOUSING DEV. FUND CO	CNY CONSTRUCTION LLC
5/7/2019	Brooklyn	575	4 AVENUE	A DOB inspector reported that there were workers it were using a pallel jack and an 7-Frame to move large granten ties when the workers lost belance and the hit a worker in the knee. The tiles were not secul properly. The struck worker went to a hospital on his own. Two ECB Volations were issued, one violation the failure to maintain safety measures, as a worker was injured during a large-size granite tile moving operation, and one volation for the failure to conduct pre-shift meeting before the commencement of the pre-shift meeting before	d a red in the state of the sta	354249907P, 35424908R		NEW BUILDING	321042331	Material Fell	575 4TH AVENUE, LLC	TITAN REALTY & CONSTRUCTION
5/8/2019	Menhatten	608	WEST 40 STREET	A DOB inspector reported that a rigor war working inside of a thirty-pard container and was unloading a debris bag from inside of a smaller box when his legic acupit in a pirch point. The rigogs suffered as positioned himself poorly within the pinch point. A sixteen-hour certification was provided for the injury rigger, but he injuried rigger did not attend a pre-shift tower crane meeting. Three ECB Violations were issued: one violation to the General Contractor for the presence of inadequate safety measures, as a crane was operated in an unsafe manner, and violation to the user for the presence of inadequate safety measures as a crane was operated in an unsafe manner, and violation for the performance of work that did not conform with approved construction documents. A partial Stop Work Order (PSWO) and a DOB Violation were also issued.	got d t t ee b h s, nne	35360898M 35360899Y 35361000L	SW0050819ML01	CN	691/18	Mechanical Construction Equipment	NEW YORK CONVENTION CENTER DEV	Rodgers and Son



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/8/2019	Manhattan	39	WEST 23 STREET	0	The Site Safety Manager reported that a worker was stripping plywood when the plywood hit his hand. The worker's hand was bleeding so the worker went to an urgent care center. An ambulance was not called.				NB	121190424	Other Construction Related Incidents		PIZZAROTTI LLC
8/2019	Manhattan	161	EAST 28 STREET	0	The Site Safety Manager reported that a worker was removing a support jack for concrete when he got his right index finger caught in the bottom lip of the jack support. An ambulance was called.	No Dispatch				123381312	Other Construction Related Incidents	157-161 EAST 28TH STREET LLC	FORKOSH CONSTRUCTION CO
3/2019	Bronx	600	BERGEN AVENUE	0	The Site Safety Manager reported that a worker was grinding a piece of metal when his hand moved and his thumb was cut. The worker walked over to an emergency room. An ambulance was not called.	No Dispatch			NB	220151868	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST.
/2019	Bronx	1870	SCHIEFFELIN AVENUE	0	The Safety Director reported that a worker injured his back when he bent down to pick up a box of tiles. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NYC HOUSING AUTHORIT	
/10/2019	Brooklyn	123	LINDEN BOULEVARD	0	1 The Site Salety Manager reported that a worker fell from a ladder on the first floor. The worker was found conscious, and an ambulance was called to take the worker to a hospital. A DOB inspector responded to the incident and visited the site and issued two ECB Violatons: one violation for a failure to safeguard, and one violation for the failure to provide a pre-shift safety meeting. The General Contractor is to provide a Means and Methods, a Tool Box Talk, and a pre-shift safety meeting.	9	35425002P,003R	051019CE17MA01,02	NB	321228603	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS
/10/2019	Brooklyn	19	RICHARDSON STREET	0	1 A DOB inspector reported that a worker was preparing to commence masonry work around a stair shalf when he removed the guard rails from the edges of the shalf. The worker fell nine feet through the shalf to the cellar throughout the shalf through through the shalf throughout the shalf through through the shalf through the shalf through the shalf through	g g g g g g g g g g g g g g g g g g g	35425050J, 51L, 52N, 53P, 54R AND 55Z		new building	321628663	Worker Fell	19 RICHARDSON STREET LLC	AVO CONSTRUCTION LLC
5/11/2019	Manhattan	1568 AIR	BROADWAY	0	The Site Safety Manager reported that a worker was moving containers when his finger got pinched between two containers. An ambulance transported the worker	n			A1 - ALTERATION TYPE 1	121191236-01-AL	Other Construction Related Incidents	TIMES SQUARE HOTEL SUB, LLC	PAVARINI MCGOVERN LLC
/13/2019	Brooklyn	10	NEVINS STREET	0	to a hospital.  A DOB inspector reported that a worker was using a grinder with a 4 and 1/2 inch cut-off wheel to cut metal studs in place when the wheel of the grinder shattered and hit the worker above his upper lip. The worker stuffered a laceration and was taken to a hospital, when he was reported to be okay. Six thirty-hour OSHA card were provided. An ECB Violation was issued for the failure to safeguard all persons and property. A partial Stop Work Order (PSWIV) was issued on metal framin operations and grinding operations on the nineteenth litor. A DOB Violation was also issued. A Means and Methods for safe steel stud installations and grinder operations must be provided.	re s	35418559R	051319CE02SK01	NB	320915578	Other Construction Related Incidents	NEVINS STREET OWNER LLC	DANYA CEBUS CONSTRUCTION
5/13/2019	Manhattan	365	COLUMBUS AVENUE	0	The Site Safety Manager reported that a worker was draining hydraulic fluid from a line when he was splashed in the eye by the fluid. The worker flushed ou his eye, and then went to see an eye doctor. An ambulance was not called.				ALT	121188482	Other Construction Related Incidents	CULTURAL AFFAIRS	BREEZE NATIONAL INC



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
Incident Date 5/14/2019	Borough Brooklyn	Address Number 626	Street 5 AVENUE		EOC Final Description  1 A DOB inspector reported that a worker slid down an open elevator hatch door on the third floor and fell approximately forty feet into a pit. The worker suffered fractured risk and a broken tablome and was taken to Methodst Hospital, where he was reported to be in stable condition. Fourteen total ECB Violations were issued: one violation to the General Contractor for a failure to notify the Department OF Buildings of an incident involving a worker injury, one violation to the Construction Superintendent for a failure to notify DOB of an incident involving a worker injury, one violation to the Construction Superintendent for a failure to notify DOB of an incident involving a worker injury, one violation to the presence of a supported pipe scalled platform that was presence of a supported pipe scalled platform that was presence of debtric and material on the supported pipe scalfold while it was not in use, one violation for the absence of vertical netting at the perimeter of the building, one violation for the failure to institute and maintain safety equipment measures and temporary construction, one violation for the presence of temporary construction equipment on site with an expired permit, one violation for the failure to institute and maintain safety equipment on site with an expired permit, one violation for the failure to the streage 2, one violation for the failure to promptly only DOB of an incident involving damage to an adjoining property, one violation for the failure to promptly only DOB of an incident involving damage to an adjoining property, one violation for the failure to promptly only DOB of an incident involving damage to an adjoining property, one violation for the failure to promptly only DOB of an incident involving damage to an adjoining property, one violation for the failure to promptly only DOB of an incident involving damage to an adjoining property, one violation for the failure to promptly only DOB of an incident involving damage to an adjoining property, one	ECB Violation	ECB Violation Numbers 35422725F,26R.27Z, 28K, 29M, 30J, 31L, 32N, 33P, 34R, 35Z, 36K37M, 38Y	DOB Violation Numbers See Complaint for Violation Numbers	Permit ALTERATION-1	Permit No 321174279	Incident Type Worker Fell	Owner's Name 435 7TH AVE APTS LLC	Contractor Name ATLAS DEVELOPERS LLC
5/15/2019	Manhattan	300	WEST 122 STREET	0	violation for the failure to provide an installation inspection for the sidewalk shed. Thirteen DOB Violations were also issued.  The Site Safety Manager reported that a worker was lifting rebar when he hit himself in the chin. The worker	No Dispatch			NB	120562284	Other Construction Related Incidents	BESPOKE HARLEM WEST LLC	HAPPY LIVING DEVELOPMENT
					went with his supervisor to an urgent care center. An ambulance was not called.								
5/16/2019	Manhattan	500	WEST 33 STREET		1 A DOB inspector reported that five workers were engaged in an operation to install a granite countertop. Four of the workers were lifting up the countertop, and the fifth worker was pulling out an "A-Frame cart stopped backwards and tripped and the "A-Frame feel not his left leg. The worker suffered scratches and bruises and was taken to Mount Sinal Hooplail. An ECB Vilotion was issued for a failure to maintain safety measures. A partial Stop Work Order (FSWO) was issued on all materiah handling. The General Contractor is to provide a Means and Methods, along with a worker orientation for the safe operation of the job.		35425077J		ALTERATION-2	123334178	Material Fell	NAME NOT ON FILE	STRUCTURE TONÉ, LLC
i/16/2019	Manhattan	15	EAST 30 STREET	0	I A DGB inspector reported that a worker was using a cart to move his equipment when we sidentially start med his led inside the cart and a wall. The worker went to a local City M.D. to receive treatment. There were no slipping or tripping hazards present at the sile, and there were no other hazardsu conditions observed. This incident was considered to have occurred as the result of a worker's error. No enforcement action was necessary.	No Action Necessary			NEW BUILDING	122128679	Other Construction Related Incidents	MADISON 30 31 OWNER LLC	MADISON 30 31 OWNER LLC
5/16/2019	Manhattan	130	EAST 82 STREET	0	1 A DOB inspector reported that there was a worker working underneath a sidewalk shed when he was struck by a 4 X B piece of plywood that fell from a gap between the sidewalk shed and the building during a facade operation underway. The worker suffered an injury to his left arm and was transported to a hospital. Two ECB Violations were issued one violation for the failure to institute and maintain safe operations, and one violation for the presence of a sidewalk shed that was not sealed. A partial Stop Work Order (PSWO) was issued for the use of suspended scalfolds and sidewalk shed deck until all of the gaps are sealed.	ECB Violation	35425065M, 35425066Y		NB	121328027	Material Fell	134 EAST 82 LLC	MC GOWAN BUILDERS INC
5/16/2019	Brooklyn	378	FLUSHING AVENUE	0	A DOB inspector reported that a worker fell from a job site ladder. The worker suffered minor injuries and was taken to an area hospital. An EVB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) and a DOB Violation were also issued.		35407452N	051619CNEEC02	ALTERATION TYPE 2	322023243-01-EW-OT	Worker Fell	LOTUS RESIDENCES LLC	RIVERSIDE DEVELOPERS USA



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	809	BROADWAY		IA DOB inspector reported that a worker was walking up the stairs of a supported scaffold while carrying an extension cord in his hand when the end of the extension cord of oct acapit on the handrail, which caused the worker's foot to slip between the first and second step and caused the worker to fall against the guardrail. The worker did not appear to have any visible injuries, but complained of pain. The worker was the injuries, but complained of pain. The worker was the performed not exposure three was completed, and the scaffold was in the process of being removed when the incident occurred. Design drawings for the scaffold, a ten hour OSHA card, and a log book and daily log for the scaffold was in the scaffold was in the scaffold was in the scaffold was in some size of the process of the scaffold was selected to the failure to institute or maintain safety equipment measures or temporary construction. A partial Slop Work Order (PSWO) for the use and dismantling of a scaffold was as iso sizeed. A Means and Measures for the safe use and dismantling of a support scaffold must be provided.		344185682		ALTERATION TYPE 1	121236983	Worker Fell	NAME NOT ON FILE	FOUNDATIONS INTERIOR DESI
5/17/2019	Queens	21-18	44 DRIVE		I A DOB inspector reported that a worker was digging soll in orde to allow for foundation waterprofing when he fell approximately four feel into a ditch. The worker hur his ankle and was taken to Belleview Hospital by an ambulance. Three ECB Violations were issued: one violation for a failure to safeguard, one violation for the failure to notify the Department Of Buildings of an incident that resulted in an injury to a construction worker, and one violation for the failure to notify the department of Buildings of an incident that resulted in an injury to a construction worker, and one violation for the failure to provide a sidewalk shed or pedestrian protection. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35422804N,35422805P,35422806R		NB	402579759	Worker Fell	21-12 LLC	HARLEY CONSTRUCTION MANAG
5/18/2019	Manhattan	335	MADISON AVENUE		A DOB inspector reported that a worker was cleaning debris on the scalfolding deck at the fifth floor level when the worker fell from the fifth floor to the second floor. An ambulance took the injured worker to a hospital, where he was pronunced dead. The worker was not using a safety harness, and the scalfolding deck was missing two pieces of planks and did not have any guardralis present. A DOB Violation and a full Stop Work Order (FSWO) was issued. The General Contractor is to provide a Means and Methods for safe operations.	DOB Violation		051819CE0501MH	ALTERATION -1	121188204	Worker Fell		SCIAME CONSTRUCTION LLC
5/20/2019	Bronx	383	EAST 143 STREET		A DOB inspector reported that there was a suspended scaffold present at the second floor level. The power line of the scaffold was fied to the scaffold's railing. A worker used a ladder to gain access to the scaffold and released the scaffold are his hook in order to begin to lower it. However, the scaffold and was lowered, which caused the railing to pop up and hit the worker in the face. The injured worker was taken to Lincoln Hospital, where he received stiftches. Two ECB Violations were issued: one violation for a failure to maintain safely measures, and one violation for the failure to conduct a pre-shift safely meeting. A parial Stop Work Order (PSWO) was issued for all use of suspended (PSWO) was issued for all use of suspended when and Methods for safe operations, along with a worker's orientation.	ECB Violation	35418420M, 21Y		ALTERATION-2/ FAÇADE REPAIF	240252383	Scaffold/Shed/Fence/Shoring/Installation	NYC HOUSING AUTHORITY	VIKRANT CONTRACTING & BUI
5/20/2019	Manhattan	12	EAST 48 STREET		The Site Safety Manager reported that an electrician was working on an electricial panel when he was zapped and received ead wounds on his wrist. The worker was conscious. An ambulance was called. A DOB inspector responded to the incident and reported that the entire building used temporary writing that was not 7/6 and not properly supported. It appears that the incidient was caused by a worker error. Two ECB Violations were issued: on evidiations for the performance of electrical work without a permit, and one violation for the use of unapproved, unafe, or unsuitable electricial equipment or wiring. Two DOB Violations were also issued.	ECB Violation	35359899X & 35359900Y	52019EE105RID01 & 52019EE105RID02			Other Construction Related Incidents	1248 ASSOCIATES LLC	
5/21/2019	Brooklyn	516	SCHROEDERS AVENUE		The Site Safety Coordinator reported that a machine worker was cleaning glass when his finger got caught between glass and a machine. The worker left the site to see a medic.	No Dispatch			NEW BUILDING	321188905-01-NB	Other Construction Related Incidents	NEHEMIAH SPRING CREEK IV MIXED	MONADNOCK CONSTRUCTION IN



	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	11	WEST 116 STREET	0	1 A DOB inspector reported that a worker was removing existing beams from the cellar level when the worker got his finger pinched between a scaffold frame and a door jam. The worker was taken to Mount Sinal Hospital. The worker was in possession of an OSHA 30 card and a four hour supported scaffold user card. The incident took place on May 20, 2019, but a notification of the incident was not received until May 22, 2019. Two ECB Violations were issued; one to the General Contractor, and one to the Contraction. Superintendent, for the Tailure to immediately notify the Department Of Duildings of an accident at a construction or demoliticin sile.		35425082Y, 83X		DEMOLITION	123037659	Other Construction Related Incidents	WEST 116 ACQUISITION LLC	VANQUISH GROUP INC
/21/2019	Manhattan	292	5 AVENUE	0	1 A DOB Inspector reported that there was work being performed on a sidewalk shed prior to running a new service, so a temporary walkway was made in the strew with barriers and a chain-link fence, a permitted by the Department Of Transportation (DOT). A pedestrian was walking in the temporary walkway when the fence moved and hit the pedestrian's shoulder. The pedestrian complained that their shoulder was injured and called an ambulance. The Site Safety Manager did not see any phruises or signs of injury. No hazardous conditions were observed at the site. A scaffold and netting were in place at the front of the building. The fence was removed from barriers. A flag man was in place. No enforcement action was taken.				NEW BUILDING	121184789-01-NB	Scaffold/Shed/Fence/Shoring/Installation	WDSA 5TH AVENUE LLC	PACIFIC RIM
22/2019	Manhattan	500	WEST 33 STREET	0	I A DOB inspector reported that a worker was working on a 277-volt system when he touched a live current and suffered a shock. An ambulance was called and the worker was taken to a hospital. The worker failed to denergize the system before he began his work. No enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	NAME NOT ON FILE	
/22/2019	Manhattan	500	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was on a ladder and measuring a piece of store infill funder a cancipy when the ladder slipped over and fell. The New York City File Department (FDNY) called an ambulance. The worker was transported to a hospital, and the ladder of a fractured leg, and then released from a reseted for a fractured leg, and then released from a reseted for a fractured leg, and then released from a was not expended to the Site Site of Wally 24, 2019, but was not expended to the Site Site of Wally 24, 2019, and so the Site of the Site of Wally 24, 2019, and so the Site of the Site of Wally 24, 2019, and an ECB Violation was best of the failure to notify the Department Of Buildings of the incident.	ECB Violation	35422717P	052819CE04JT01	NEW BUILDING	121186251	Worker Fell	NAME NOT ON FILE	TISHMAN CONSTRUCTION CORP
/23/2019	Brooklyn	37	6 AVENUE	0	1 A OD6 inspector reported that there were workers that setting up a rig and adding a section to an auger. One of the workers was cleaning and greasing the bit when the parts moved, and the worker got the fingertips of his middle and pointer fingers cut off and also suffered an injury to a third finger. The worker was taken to a hospital, where he was reported to be in stable condition. An ECB Violation was issued for unsafe equipment use. A partial Stop Work Order (PSWO) as issued to stor paid alfilling operations. The General Contractor is to provide a Means and Methods and a worker's orientation for the safe operation of the job.		35422809M		FOUNDATION	320909433	Mechanical Construction Equipment	EMPIRE STATE DEVELOPMENT	TISHMAN CONSTRUCTION CORP
/24/2019	Manhattan	214	WEST 72 STREET	0	A DOB inspector reported that at the site, there was a chain link tenor present on plastic barriers on the steet that were being used for the storage area. The barriers were not continuous. A bus stopped, and a passenger/pedestrian stepped off of the bus. Wind knocked down a section of the fence, and a section of the fence hit the pedestrian. The pedestrian sulfrend an injury and was taken to Mount Sinal Hospital, where the pedestrian was reported to be under treatment and in fine condition. Two ECB Violations were issued one violation for a failure to safeguard persons and property, as a pedestrian was injured by a fallen section of fence, and one violation for the presence of site logistics that were not as per the approved Site Safety Plan. A partial Stop Work Order (PSWO) was issued to stop all activity on the storage area, including all shipping and deliveries. The General Contractor at the site is to provide a Means and Methods for safe operation, as well as an updated Site Safety Plan.		35437150P, 51R		NEW BUILDING	121204516	Scaffold/Shed/Fence/Shoring/Installation	AVENTIS-72ND, LLC	CM AND ASSOCIATES CONSTRU



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/24/2019	Brooklyn	211	HOYT STREET	0 1	IA DOB inspector reported that a flag person was walking in front of a forklift with a telescopic borm when the flag person tripped. The forklift operator had the glare of the sum in his eyes, and the forklift accidentally ran over the fallen flag person's leg. The flag person was taken to a hospital, where he was reported to have suffered a broken femur and internal injuries. The flag person underwent emergency surgery. The General Contractor at the site provided a Flagger Training Course, as well as a 30-Hour OSHA Card for the injuried worker. The forklift operator provided a V11 Rough Terrain Operator training certification and a 30-Hour OSHA Card. Two EGB Violations were issued: one violation for the failure to provide safety means for a forklift operation. A partial Stop Wrink Corter (PSWO) was issued on all exterior work and the use of a forklift a the location until adequate safety means a stelly means the provided.	ECB Violation	35437101Z, 02K		ALTERATION-2	321304539	Mechanical Construction Equipment	NYC HOUSING AUTHORITY	ADAM'S EUROPEAN CONTRACTING
5/28/2019	Manhattan	10	VANDERBILT AVENUE		The Site Safety Manager reported that a carpenter was cutting a wooden stud with a circular saw when the saw bounced and the worker received a cut on his hand. The worker was treated by the on-site medic. The on- site medic sent the worker to a hospital to get stitches.				NEW BUILDING	121189828	Other Construction Related Incidents	ONE VANDERBILT OWNER LLC	TISHMAN CONSTRUCTION CORP
5/29/2019	Queens	21-30	44 DRIVE		A DOB inspector reported that there were workers that were attempting to lower styrofcam from the second floor terrace to the first floor through the opening of a skylight. The skylight was temporarily cowered by a tarp that was being held in place by paving blocks. While the tarp from the skylight was being removed, a paving block fell through the skylight to the floor, and hit the floor of a worker that was standing on the block fell through the skylight to the floor, and hit the floor of a worker that was standing on the blower floor. The struck worker suffered a leg injury and was sent to a hospital for treatment. There ECB Violations were issued, or evidence of the struck worker suffered a leg injury and was sent to a hospital for treatment. There ECB Violations were issued, or port affected by construction operations, sea a worker was injured due to unsafe activity, one violation for the improper storage of materials from wind, and as third violation for the absence of a design drawing for the temporary skylight cover. A partial Stop Work Order (FSWO) was issued for all work on the second floor terrace and skylight. The General Contractor must comply with the Stop Work Order of provide a Means and Methods, as well as a worker's orientation, for the safe operation of the job.		35418590P, 91R AND 92Z		ALTERATION-1	421231893	Material Fell	44TH DRIVE OWNER LLC	CM AND ASSOCIATES CONSTRU
5/30/2019	Brooklyn	1122	MANHATTAN AVENUE		The Construction Superintendent reported that a worker was carrying buckets while attempting to walk of the lob site at the end of the day when he slipped and fell three steps. The worker went to a hospital, where he was reported to have suffered a broken leg. No unsafe conditions observed as of the time of inspection. No enforcement action was necessary.				ALTERATION TYPE 1	320882354-01-AL	Worker Fell	1122 MANHATTAN AVENUE LLC	YELLOW HAT CONSTRUCTION
5/30/2019	Manhattan	40	10 AVENUE		A DOB inspector reported that an electrician was working in the switch gear room when he brushed up against a service bus and was shocked. Another worker knocked him off of the connection. The shocked electrician was taken to a hospital. It was determined that this incident occurred as the result of a worker's error. No enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	40-56 TENTH OWNER LLC	
5/30/2019	Manhattan	646	11 AVENUE		The Site Safety Manager reported that a worker was going down a stair tower when he slipped, fell approximately two steps, and hurt his lower back. The worker complained about pain. A co-worker took the injured worker to a hospital. This incident occurred as the result of a worker error.	No Dispatch					Other Construction Related Incidents	646 11TH OWNER LLC	
5/30/2019	Queens	23-15	44 DRIVE		The Site Safety Manager reported that a worker slipped off of a ladder and fell five feet to the ground. The worker went to a hospital as a precaution.	No Dispatch			NEW BUILDING	420655954-01-NB	Worker Fell	BGY CITYVIEW LLC	NEW LINE STRUCTURES & DEV

111	BAY 20 STREET	O 1 4 6 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	EOC Final Description  A DOB inspector reported that a scalfolding erector was modifying scalfolding on the tenth floor level when he dropped a dill to the lower level. A carpenter that was performing façade work on the lower level that was not associated with the scalfolding operation was struck on his head and shoulder by the drill. The Site Safety Manager took the injured carpenter to a hospital for observation. Five ECB Violations were issued: one violation for the failure to provide safety measures for a scaffolding operation, one violation for the failure to provide safety measures for a scaffolding, one violation for the failure to provide a guardrail system, one violation for the failure to provide a guardrail system, one violation for the failure to provide a guardrail system, one violation for the presence of inadequate planking on the scaffolding, and one violation for the absence of pins on the scaffolding. A partial Stop Work Order (PSWO) was issued for all scaffolding operations on the exterior of the building.  A DOB inspector reported that a worker was working in an elevator shaft removing formwork when he fell sixteen teet into the elevator pit. The worker suffered a broken leg and was transported to a nospital in steried ab tooken leg and was transported to a nospital in steried ab tooken leg and was transported to a nospital in steried ab evolution for the failure to institute safety measures for operations, one violation for the failure to involide pre-shift safety measures for operation, one violation for the failure to involide pro-shift safety measures for operation, one violation for the failure to involide pro-shift safety measures for operation, one violation for the failure to involide pro-shift safety measures for operation, one violation for the failure to invalidue. A full Stop Work was the province and the construction violation for the failure to promise during and an evidence and the failure to provide pre-violation for the failure to provide pre-violation for the failure to pro	ECB Violation	35437164 X / 65 H / 66 J / 67 L @ 68 M  35418472Y/73X/74H/ 35437125N/ 26P/27R@28Z	7	NEW BUILDING	220152484	Incident Type Other Construction Related Incidents  Worker Fell	2568 PARK BRONX LLC  BAY 20TH LLC	THE SWEET CONSTRUCTION GR
658	BAY 20 STREET	s b c c c c c	an elevator shaft removing formwork when he fell sixteen feet into the elevator pit. The worker suffered a broken leg and was transported to a hospital in stable ordination. There was no fall protection or safety measures in place. Seven ECB Violations were issued: one violation for the failure to institute safety measures for operations, one violation for the failure to provide pre-shift safety measures for operation, one violation, one violation, one violation, one violation, one violation, one violation, one violation from the failure to maintain fence, as required, one violation for the failure to maintain fence, as required, one violation for the failure to maintain weatherproofing for the adjacent property, one violation for the failure to maintain a sanitary facility, as required, and one violation for the failure of the Construction.		35418472Y/73X/74H/ 35437125N/ 26P/27R@28Z	7	NEW BUILDING	321192339	Worker Fell	BAY 20TH LLC	RICHMOND CONSTRUCTION INC
658			Order (FSWO) was also issued.								
	DRIGGS AVENUE	s t t f f	A DOB inspector reported that a worker was receiving a rebar delivery on the second floor level when the worker slipped, fell, and injured himself on rebar that was protrucing from the second floor. The worker was taken protrucing from the second floor. The worker was taken to a hospital in stable condition. Five ECB Violations were issued: one violation for the failure to provide and maintain sidewalks thed as required, one violation for the presence of site conditions that do not conform to approved construction documents, one violation for the failure to provide safety measures for rebar delivery, one violation for the failure to provide safety measures for rebar delivery, one violation for the failure to the Construction out violation for the failure to the Construction Superintendent to perform their duties as per code. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35437179Z, 80X, 81H, 82J & 83L		NEW BUILDING	321193766	Worker Fell	RS JZ DRIGGS, LLC	FOREMOST CONTRACTING & BU
800	FLATBUSH AVENUE	l a	The Site Safety Manager reported that a worker was using a hammer to loosen a drill bit when he accidentally hit his left hand. The worker went to urgent care and then returned to work.	No Dispatch			NEW BUILDING	321188567	Other Construction Related Incidents	CATON FLATS HOUSING DEVELOPMEN	LETTIRE CONSTRUCTION CORP
1043	HALSEY STREET	0 1 / 2 / 3 / 3 / 3 / 3 / 3 / 3 / 3 / 3 / 3	A DOB inspector reported that a worker was working on guard rail system that was around a stainwell opening when he fell through the stainwell opening from the second story floor level to the first story concrete slab. The worker was taken to a hospital by an ambulance in a conscious and responsive state. The workers at the active were in possession of ten-hour C9F4A cards. Five ECB Violations were issued: one violation for the failure to maintain safety measures, one volation for the failure to notify the Department of Buildings of the accident, one violation for the failure to provide task-specific orientation or training, one violation for the failure to have the Construction Superintendent or a Competent Person on the site, and one violation for the failure to have the Construction Superintendent or a Competent Person on the site, and one violation for the failure to provide a log book for construction operations. A full Stop Work Order (FSWO) and five DOB Violations were also issued.		35422822R, 35422823Z, 35422824K, 35436850L, 35436851N	060319CE04CV05	NB	320912811	Worker Fell		FIVE HORSEMEN LLC
	PARK AVENUE	e H H S S	eight foot tall 'A'-Frame ladder and was about four feet high when he lost his balance, fell, and suffered an highly to his right leg. The worker was taken to a hospital. Two ECB Viotations were issued: one violation for a failure to safeguard, and one violation for the failure to maintain or provide a Site Safety Plan. A full Stop Work Order (FSWO) and two DOB Violations were also issued. The General Contractor is to provide a Means and Methods for safe operations moving	ECB Violation	35436753J, 754L	060319cs02)(02,03	ALT	321405957	Worker Fell	369 PARK AVENUE LLC	GUB MAINTENANCE INC
	9	9 PARK AVENUE	9 PARK AVENUE 0 1	ECB Violations were issued: one violation for the flature to maintain safety measures, one violation for the failure to notify the Department OF Buildings of the decident, one violation for the failure to provide task-specific orientation or training, one violation for the failure to prave the Construction Superimendent or a Competent Person on the site, and one violation for the failure to pravide a lag book for construction operations. A full Stop Work Order (FSWO) and five DOB Violations were also issued.	ECB Violations were issued: one violation for the failure to maintain safety measures, one violation for the failure to maintain safety measures, one violation for the failure to notify the Department Of Buildings of the accident, one violation for the failure to provide a task-specific orientation or training, one violation for the failure to provide a log book for osubqueriendent or a Competent Person on the site, and one violation for the failure to provide a log book for construction operations. A full Stop Work Order (FSWO) and five DOB Violations were also issued.  9 PARK AVENUE  0 1 A DOB inspector reported that a worker was using an ecipit foot tall "A"-Frame ladder and was about four feet high when he lost his balance, fell, and suffered an injury to his right leg. The worker was taken to a hospital. Two ECB Violations were issued one violation for a failure to safequard, and one violation for the failure to maintain or provide a Site Safety Pan. A full Stop Work Forder (FSWO) and Woo DOB Violations were also issued. The General Contractor is to provide a Means and Methods for safe operations moving	ECB Violations were issued: one violation for the failure to maintain safety measures, one violation for the failure to notify the Department Of Buildings of the accident, one violation for the failure to provide task-specific orientation or training, one violation for the failure to have the Construction Supprintendent or a Competent Person on the site, and one violation for the failure to have do a log book for construction operations.  A full Stop Work Order (FSWO) and five DOB  Violations were also issued.  1 A DOB inspector reported that a worker was using an eight foot tall "A"-Frame ladder and was about four feet high when he lost his balance, fell, and suffered an injury to his right flug. The worker was taken to a hospital. Two ECB Violations were issued: one violation for a failure to a sefiguart, and now violation for the failure to maintain or provide a Site Safety Plan. A full Stop Work Order (FSWO) and two DOB Violations were also issued. The General Contractor is to provide a Means and Mehotos for safe operations moving forward, as well as a Site Safety Plan.	ECB Violations were issued: one violation for the failure to maintain asidely measures, one violation for the failure to norify the Department Of Buildings of the accident, one violation for the failure to provide task-specific orientation or training, one violation for the failure to provide a log book for construction operations.  A full Stop Work Order (FSWO) and five DOB  Violations were also issued.   1 A DOB inspector reported that a worker was using an eight foot tall "A-F-rame ladder and was about four feet high when he lost his bilance, fell, and suffered an injury to his right flag. The worker was taken to a hospital. Two ECB Violations were issued: one violation for a failure to safeguard, and now violation for the failure to maintain or provide a Ste Safety Plan. A full Stop Work Cref (FSWO) and two DOB Violations were also issued. The General Contractor is to provide a Means and Methods for safe operations moving forward, as well as a Site Safety Plan. A full Stop Work Core (FSWO) and two DOB Violations were also issued. The General Contractor is to provide a Means and Methods for safe operations moving forward, as well as a Site Safety Plan.	ECB Violations were issued: one violation for the failure to maintain asidely measures, one violation for the failure to norify the Department Of Buildings of the accident, one violation for the failure to provide task-specific orientation or training, one violation for the failure to provide a log book for construction operations.  A full Stop Work Order (FSWO) and five DOB  Violations were also issued.   DARK AVENUE  O  1 A DOB inspector reported that a worker was using an eight foot tall "A-F-rame ladder and was about four feet high when he lost his bilance, fell, and suffered an injury to his right leg. The worker was taken to a hospital. Two ECB Violations were issued cone violation for a failure to safeguart, and now violation for the failure to maintain or provide a Site Safety Plan. A full Stop Work Creft (FSWO) and two DOB Violations were also issued. The General Contractor is to provide a Means and Methods for safe operations moving forward, as well as a Site Safety Plan.	ECB Violations were issued: one violation for the failure to maintain safety measures, one violation for the failure to notify the Department Of Buildings of the accident, one violation for the failure to notify the Department of Buildings of the accident, one violation for the failure to provide task-specific orientation or training, one violation for the failure to provide a log book for construction operations. A full Stop Work Order (FSWO) and five DOB Violations were also issued.  9 PARK AVENUE  0 1 A DOB Inspector reported that a worker was using an eight foot tall "A"-Frame ladder and was about four feet high when he lost his balance, fell, and suffered an injury to his right lag. The worker twas taken to a nospital. Two ECB Violations were issued one violation for the failure to maintain or provide a Site Safety Plan. A full Stop Work Order (FSWO) and two DOB Violations were also issued. The General Contractor is to provide a Means and Methods for safe operations moving forward, as well as a Site Safety Plan.	ECB Violations were issued-con violation for the failure to maintain safety measures, not violation for the failure to make the Construction Operation of the failure to make the Construction operation of the failure to provide a logistic for the failure to a fa	ECB Violations were issued: on evident for the failure to maintain safety measures, on evidation for the failure to mostly the Department Of Buildings of the accident, one violation for the failure to provide task-specific orientation or training, one widelition for the accident, one violation for the failure to provide task-specific contration for the failure to have the Construction Supermined for or the failure to have the Construction Supermined for or the failure to have the Construction Supermined for an experiment of the failure to have the Construction Supermined for the failure to have the construction of the failure to the fail



D	Db	Address Monthes	011	Foreithing Indicators FOO Flord December 1	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	to all done Town	Owner's Name	Contractor Name
Incident Date 6/3/2019	Manhattan	Address Number	VANDERBILT AVENUE	Fatalities Injuries EOC Final Description  1 A DOB inspector reported that a worker was stripping formwork on the fifty-fifth floor when a piace of formwork in the fifty-fifth floor when a piace of formwork hit the ground, bounced, and struck the worker's foot. The worker was checked on site, and then requested an ambunace. An EOE Violation was issued for a failure to safeguard. A full Stop Work On (FSWO) was also issued.	ECB Violation	039003690N		NEW BUILDING	121189828-01-NB	Incident Type Worker Fell	ONE VANDERBILT OWNER LLC	TISHMAN CONSTRUCTION CORP
5/3/2019	Manhattan	29	11 AVENUE	A DOB inspector reported that a worker was pushing mini-container of debris, up a ramy when the mini-container started to tip. The worker tried to prevent th mini-container from falling and suffered acut to his arm. The worker went to a hospital by ambulance, where he received wenty statches. This incident occurred on June 3, 2019, but was not reported by th Construction Superintendent until June 4, 2019. An ECB Violation was issued for a failure to notify the Department Of Bulldings of the incident. A DOB Violation was also issued.	9	35437112Y	060419CE045K01	ALT-1	121235350	Other Construction Related Incidents	NYS PARKS & RECREATION	HUNTER ROBERTS CONST. CORP
/4/2019	Brooklyn	181	18 STREET	1 The Site Safely Manager reported that there were two workers carrying a 4 X B pipe when one of the work slipped and hurt his shoulder. The injured worker were to see the on-site medic and then went on its own to urgent care center that was near the job site.	rs t			NB	321195229	Other Construction Related Incidents	SOUTH SLOPE BLISS, LLC	DANYA CEBUS CONSTRUCTION
5/4/2019	Manhattan	1271	6 AVENUE	On 1 A DOB inspector reported that a worker was taking measurements to install the design ceiling on the lifth floor when he fell off of the fourth rung of a six foot a ladder and was impaled in his side by a siny that was his tool belt. The worker was taken to Comell Hospital where he underwent immediate surgery. There were unsafe conditions observed at the site as of the time inspection. No enforcement action was necessary.	I in , no			ALTERATION TYPE 1	123401835-01-AL	Worker Fell	ROCKEFELLER CTR NORTH INC	JRM CONSTRUCTION MGMT LLC
4/2019	Manhattan	140	WEST 28 STREET	0 1 A DOB inspector reported that a worker was walking with stilts and was lifting a few metal studs when he I his balance and fell to the floor. The worker complain about pain on his knee and requested medical attentif The worker was taken to a hospital. No enforcement action was necessary.	ost ed			NEW BUILDING	121190950-01-NB	Worker Fell	140 WEST 28 OWNER LLC	OMNIBUILD CONSTRUCTION INC
/4/2019	Manhattan	1619	BROADWAY	1 A DOB inspector reported that there were sign hange using a man lift to install a new sign on a façade whe debris fell through a small gap in the sidewalk shed's parapet and struck a child in the head. The child suffered a small cut, but no stitches were required. The sign hanger left the man lift and the site. The sign company row eventually returned to the site and removed the man lift from the sidewalk shed deck. Yt ECB Violations were issued: one Aggraved Level 2 ECB Violation for a failure to safeguard, and one violation for the presence of pedestrain protection that did not meet code requirements. A partial Sign View of the code of the c		35437113X, 35437115J	060419CE075K02/03	SIGN	122482884	Material Fell	1619 BROADWAY REALTY LLC	NORTH SHORE NEON SIGN CO
5/2019	Bronx	1560	BOONE AVENUE	1 The Site Safety Manager reported that a worker injury his finger while installing shoe moldings. The worker walked to an urgent care center. An ambulance was re called.				NEW BUILDING	220152876	Other Construction Related Incidents	SAMARITAN-COMPASS III & IV HOU	MONADNOCK CONSTRUCTION IN
/6/2019	Manhattan	207	WEST 40 STREET	A DOB inspector reported that during a concrete cleaning operation at the grade level, concrete residue became dislodged and spilled onto the opposite side of the street, hitting and injuring a pedestrian. The pedestrian went to a local urgent care center, where she was diagnosed with a concussion. Seven ECB Violations were issued one violation to the main General Contractor at the site for a failure to safeguat the public, one violation to the Concrete General Contractor at the site for a failure to safeguat the public, one violation to the Concrete General Contractor at the site for a failure to safeguard the public, one violation for the tampering and cleaning up of the area of an accident, one violation for the performance of work that does not conform the failure performance of work that does not conform the failure provides window protection, one violation to the permit hoter for the failure to notify the Department Of Buildings of an incident, and one violation to the Concrete Safety Manager for the failure to notify the Department Of Buildings of an incident. A full Stop Work Order (FSWO) was also issued.	d d	35437251Y, 35437252X, 35437253H, 35437254J, 35437256L, 35437266N, 35437257P	060719CE05MH01/02/03/04, 060719CE05/06/07	NB	121192949	Mechanical Construction Equipment	560 SEVENTH AVENUE OWNER PRIMA	FLINTLOCK CONSTR SERV LLC



ncident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
V6/2019	Manhattan	611	WEST 56 STREET		1 A DOB inspector reported that a concrete truck driver was washing out the truck when he tripped and scepe his left ear on the stair tower of the funck. Paramedics were called, and he truck driver was taken to a clad hospital. All permits at the site were valid, and no violating conditions were found. It was determined that this incident occurred as the result of a worker's error. No enforcement action was deemed necessary.	No Action Necessary		NA	NB	121190585	Worker Fell	611 W 56TH STREET PROPERTY LLC	FOUNDATIONS GROUP I, INC
5/2019	Queens	163-03	89 AVENUE	0	1 A DOB inspector reported that a worker fell approximately the feet off a ladder and suffered a provimately the feet off a ladder and suffered a broken arm. The injured worker was taken to Jamaica Hospital. Two ECB Violations were issued: One violation for a failure to notify the Department Of Buildings of an incident, and one violation for the ladence of protection for life lines and suspended ropes. A partial Stop Work Order (PSWO) was also issued.	ECB Violation	35437277M. 35437278y		ALT-2 FAÇADE	421952514	Worker Fell	LINCOLN COURT APTS INC	SAHARA CONTRACTIN CORP
3/2019	Queens	23-15	44 DRIVE	0	A DOB inspector reported that a worker cut his finger while using a skill saw. The worker went to seek medical statention in order to be further examined. The material that the worker was using the tool on was not secured as per the manufacturer's specifications. Two ECB Violations were issued: one violation for the failure in institute or maintains asfety at the site, and one violation for the tampering with the site of the incident. A partial Stop Work Order (PSWO) and two DOB Violations were issued.		35422602P / 35422603R	060819CE02LR03 / LR04			Other Construction Related Incidents	BGY CITYVIEW I.LC	NEW LINE STRUCTURES & DEV
0/2019	Manhattan	424	5 AVENUE	0	The Site Safety Manager reported that a worker was pushing a mini-debris cart when he cut his finger on material. The worker went to an urgent care center. An ambulance was not called.				ALT	122847376	Other Construction Related Incidents	424 FIFTH AVENUE LLC	4 star contracting
0/2019	Manhattan	139	EAST 56 STREET	0	ambulance was not called.  The Site Safety Manager reported that iron workers were rolling tube steel for a curtain wall installation when one of the workers got his finger pinched and lost a finger nail. The worker was taken to a hospital by an ambulance.				NB	123028810	Other Construction Related Incidents	139 EAST 56TH STREET LANDLORD	HUNTER ROBERTS CONST.
111/2019	Sronx	246	ECHO PLACE	0	2A DOB inspector reported that workers were litting cement bearies on the seventh life? "C"-loists from the boom truck. There was no floor deck present on the seventh floor, and the "C"-loists were not secured or braced. The "C"-loists rolled over, became twisted, and were taken to a hospital by an ambulance. One worker received four stitches to his head, and the other worker suffered a back injury. The sixth floor framing that was below the collapse and the fifth and sixth floors were the second of the property, one violation for the failure to be second the second to the second the second the second the second to the second the second to the second the	1	35404029M, 30J, 31L, 32N & 33P		NEW BUILDING	220620610	Material Fell	246 ECHO DEVELOPMENT LLC	SKF GENERAL CONTRACTORS,
/11/2019	Brooklyn	85	JAY STREET	0	The Site Safety Manager reported that two workers were putting up decking when one of the workers accidentally hit the hand of the other worker while harmmening. The on-site medic evaluated the injured worker's hand, and the worker then went to a clinic.	No Dispatch			NEW BUILDING	321188415-01-NB	Other Construction Related Incidents	85 JAY STREET BROOKLYN, LLC	NEW LINE STRUCTURES & DEV



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/11/2019	Menhattan	10	VANDERBILT AVENUE	0	1 A DOB inspector reported that are elevator installer had used a doly to move elevator rais to the thirtieft floor elevator shaft. The elevator installer was stacking out the rails by himself when he lost his balance and got his fingers crushed between a rail and a concrete floor slab. An ambulance was called. Two ECB Violations were issued on evidation was issued for the failure to maintain safety measures, due to improper material handling, and one violation for the unlawful performance of the Site Safety Manager's responsibilities, as the Site Safety Manager's incense had expired. A partial Sicp Work Order (PSWO) was issued on all elevator installation work. The General Advanced on all elevator installation work. The General Methods for safe material handling, as well as a worker orientalion.		35436601K, Q2M		NEW BUILDING	121189828	Other Construction Related Incidents	ONE VANDERBILT OWNER LLC	TISHMAN CONSTRUCTION CORP
6/11/2019	Manhattan	42	WEST 39 STREET	0	1 A DOB inspector reported that a coping stone fell from the eighteenth floro, bounced off of a seventeenth floor setback, and then landed onto the street. The coping stone exploded of insamiler pieces upon contract with the ground. A female pedestrian was impacted by the debris. She did not stoffer any lacerations, but was taken to a hospital for observation. A second pedestrian, a male companion of the female, was not nipured, but went to a hospital to be evaluated. A suspended scaffold platform that was harging from the C*1-box was ownered to the fifteenth floor setback and was secured. The rigging equipment at the eightneith floor setback was removed. Six ECB Violations were issued: one Aggravated Level 2 Violation for the use of safeguard persons and property, one violation for the use of suspended scaffold wire one history one violation for the sea violation for the failure to perform a safe and proper inspection of a suspended scaffold, one violation for the failure to comply with the manufacturer's specifications for standoff branches, and one violation for the failure to provide protection from shap edges for lifetimes and cables. A partial Stop Work Corder (PSWO) was issued for the use of suspended scaffolding. Six DOB Violations were also issued.		35437355Z, 35437356N, 35437356Y, 35437356Y, 35437359X, 36437360N	061119CE05SK01/02/03/04 061119CE05SK05/06	FAÇADE	123393265	Material Fell	45-52 WEST 39 STREET .	Cercone Extr. Rest. Corp
6/12/2019	Manhattan	140	WEST 24 STREET	0	The Site Safety Manager reported that a worker was pulling in horizontal nets for jumping when he hurt his back. An ambulance was called.	No Dispatch			NB	121204106	Other Construction Related Incidents	NY 24TH STREET VI LLC	omnibuild constr.
5/12/2019	Manhattan	53	WEST 53 STREET	0	The Site Safety Manager reported that an iron worker was using a magnetic drill when his glove got caught in the drill and the tip of his thumb was cut. An ambulance was called.	No Dispatch			NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	lend lease us constr.
/12/2019	Manhattan	531	6 AVENUE	0	1 The Site Safety Manager reported that a worker was putting an oxygen tank into a cage when he dropped the bottom edge on his toe. The worker went to urgent care on his own. An ambulance was not called.				FO	123174803	Other Construction Related Incidents	531-539 SIXTH AVENUE LLC	new line structures
5/13/2019	Brooklyn	260	KNICKERBOCKER AVENUE	0	1 A DOB inspector reported that a worker was installing vertical safety retting near the stair shaft on the first floor when he tell into the basement and landed on gravel. The worker was found conscious and was taken to Elimburst Hospital by ambulance. Three ECB Vlolations were issued: one violation for the failure to maintains adely measures, as there was no fall protection in place during a leading edge operation, one violation for the failure to maintain apre-shift safety orientation, and one violation for the failure to perform a hydrostatic test on a standpie, a full Slop Work Order (FSWO) was also issued. The General Contractor is to provide a Means and Methods with a worker orientation for the safe operation of the job.	ECB Violation	35436862Z, 63K, 64M, 65Y		ALTERATION-1	320595799	Worker Fell	CENTRAL BAPTIST CHURCH	WMCM LLC
5/13/2019	Manhattan	207	WEST 40 STREET	0	The Site Safety Manager reported that a pedestrian tripped and fell on a Con Edison plate that was undemeath a sidewalk shed. An ambulance was called. A DOB inspector responded and reported that metal plates were in place over the Con Edison Vault on the sidewalk in front of the job site, and that the edge of the plate was not marked with high visibility paint, not set slooped to reduce a tripping hazard. An ECB Violation was issued for the failure to maintain that the areas used by the public were free from a slipping or tripping hazard.	ECB Violation	35437390H		NEW BUILDING	121192949	Other Construction Related Incidents	560 SEVENTH AVENUE OWNER PRIMA	FLINTLOCK CONSTR SERV LLC
/13/2019	Manhattan	441	9 AVENUE	0	The Site Safety Manager reported that a worker was fixing a fan on the roof when he slipped and hurt his arm and ear. The worker went to a City MD on his own. An ambulance was not called.	No Dispatch			alt-1	120996351	Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	Pavarini Mcgovern



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Queens	161-11	132 AVENUE	0	I A DOB inspector reported that a mason worker was using a power jack to move a mini-container when he got his finger caught between the power jack and the unit-container. RSV was called, and the worker was transported to a hospital. The worker did not sulfer a life-threatening injury. The worker did not sulfer a life-threatening injury. The worker did not have a preshift safety meeting for the day, and his last safety orientation was on April 15, 2019. Three ECB Violations were issued: one violation for the failure to have a preshift safety meeting on the day of the incident, one violation for the absence of guardrails on the roof, which left the workers without fall protection, and one violation for the presence of a supported scaffold that does not meet the building code, as the scaffold was missing guard rails and had pless of brick stored at different levels. A partial Stop Work Order (PSWO) was sussed for the use of supported scaffolds and work on the roof.		35437337P, 35437338R, 35437339Z		NB	420663776	Mechanical Construction Equipment	NORTHEASTERN CONF. HOUSE ANNEX	
		911	ERSKINE STREET	0	IA DOB inspector reported that a worker was dismanting scatfolding from the suiding and was using a rope and pulley to lower the scaffolding elements when the rope got stuck. When the worker frield to release the rope, the pulley came loose, fell, and hit the worker on his hard hat, causing a cut to his head and shoulder. The worker was taken to a hospital by an FDNY ambulance in a conscious state. The worker was expected to receive stitches and be released from the hospital state no during the day. Four ECB Violations were issued: one violation for the failure to institute safety measures, one violation for the failure to have a competent person on the site, as per code, and one violation for the failure to thave a Competent person on the site, as per code, and one violation for the failure to the Violation Superintendent to perform their duties. A full Stop Work. Order (FSWO) was also issued.		35437408N, 35437409P, 35437410M, 35437411Y		SCAFFOLD	B00042553-I1-SF	Material Fell		DONNREILL, LLC
6/18/2019	Brooklyn	85	JAY STREET	0	I A DOB inspector reported that a worker was standing on a frame of formwork while performing a stripping operation on formwork that was on the wall in the second basement when he slipped. When the worker tried to prevent his fall, he grabbed a temporary electric line and was shocked. The worker was able to walk from the place where the incident took place to the on-site medic's office. The medic chocked out the worker, said that he was fine, and then sent him to the hospital for further evaluation. The worker's safety harness was not tied off to a safe anchor point. Four ECB Violations were issued: on evidation for the failure to maintain safety measures, as there was no adequate fall protection present for the worker that was working on the frame of formwork, one violation for the presence of a power outlet that was without a cover and electrical cables that were running in water, which readed as hazardous condition, and one violation for the presence of a power outlet that was without a cover and electrical cables that were running in water, which readed as hazardous condition, and one violation for the presence of a power outlet that was without a cover and electrical cables that were running in water, which readed as hazardous condition, and one violation for the presence of a power outlet that was without a cover and electrical cables that were running in water, which readed as hazardous condition, and one violation for the presence of a power outlet that was without a cover and electrical cables that were running in water, which readed hazardous condition, and one violation for the presence of a power outlet that was without a cover and electrical cables that were running in water, which readed hazardous condition, and one violation for the presence of a power outlet that was approximately two feet of water on the floor at the work area, one violation for the temporary wring was not installed and the temporary wring on the floor was not protected from physical damage. One DOB Violation was also issued. A	ECB Violation	35437377J, 35437378L, 35437379N, 36423755K	61919EE302RH1			Mechanical Construction Equipment	85 JAY STREET BROOKLYN, LLC	
6/18/2019	Manhattan	12	EAST 48 STREET	0	A DOB inspector reported that a worker at the cellar level was in the process of moving ducts that were stored over a sump pit when the worker stepped on a plank. The plank was not secured, and the worker stepping on the unsecured plank caused the plank to shift, which then caused the worker to fall over into the stored plank. The worker suffered a cut to his forearm and was taken to a local hospital for treatment. An ECB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was issued because of the presence of inadequate protection at the pump room.	ECB Violation	35432694K		NEW BUILDING	121190816-01-NB	Worker Fell	1248 ASSOCIATES LLC	ANTHONY T. RINALDI LLC



Incident Date	Parauah	Address Number	Parant	Catalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	1227	BROADWAY	0 1			35436609P/10M	061819CE05DM01 / 02	NEW BUILDING	121191986	Other Construction Related Incidents	YJL BROADWAY HOTEL LLC	FLINTLOCK CONSTR SERV LLC
6/19/2019	Bronx	3120	PARK AVENUE		A DOB inspector reported that a worker was unloading metal angles from a flathed truck when his left hand was pinned between the metal angles. The worker was taken to a hospital by a co-worker and received three stitches on his write before being released. Five ECB Violations were issued: one violation for the failure to maintain safely measures, as a worker was higher to maintain safely measures, as a worker was on the leading edge with no fall protection, as a worker was on the leading edge with no fall protection in place, one violation for the unsate storage of materials near the sidewalk, one violation for the presence of inadequate, warning slay, no fight around the material stored on the street of the steme of the street of the		35404038Y, 39X, 40N, 41P & 42R		NEW BUILDING	220601999	Other Construction Related Incidents	HP PARK AND ELTON APARTMENTS H	D.P. GROUP GENERAL CONTRA
6/19/2019	Bronx	600	BERGEN AVENUE		A DOB inspector reported that there were workers relocating scaffolding platform planks when a plank sipped out of a worker's hand, fell to the next level, and hit another worker. The injured worker was ckay, but was taken to an urgent care center for a checkup because he was complaining about pain. The scaffolding was found to have more planked levels than allowed by the approved plan, and also contained hazardous housekeeping issues. Three ECB Violations were issued: one violation for the failure to maintain safety measures, as a worker was injured during a scaffolding most diffication, one violation for the failure to maintain safety difficient gas per code, and one violation for the failure to Stop Work Order (FSWO) was also issued. The General Contractor is to provide a Means and Methods for the safe operation of the job before the Stop Work Order will be lifted.		35436768M, 69Y & 70L		NEW BUILDING	220151868	Scaffold/Shed/Fence/Shoring/Installation	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
6/19/2019	Brooklyn	3030	SURF AVENUE		A DOB inspector reported that a female pedestrian was walking her dog when she slipped and fell on a temporary ramp that was outside of the building. An armbulance was called to the site. This incidence on Wednesday, June 19, 2019, but was not reported until Thursday, June 19, 2019, but was not reported until Thursday, June 20, 2019. Two ECB Violations were issued: one violation for the failure to notify the Department Of Buildings of an incident that featured an injury or fatality in a timely manner, and one violation for the failure to institute safety measures or temporary construction, as there were no handrails present. A partial Stop Work Order (PSWO) was issued at exposure one.	1	35421294H, 35421295J	062019CE13EC01, 062019CE13EC02	ALTERATION-2	321457892	Other Construction Related Incidents	NYC HOUSING AUTHORITY	ADAMS EUROPEAN CONTRACTI



Incident Date	Borough	Address Number	Street	Estalitice Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/20/2019	Brooklyn	7	BOERUM PLACE	0	A DOB inspector reported that a worker was working on the ground level when he got his right middle finger plinched when another worker was passing down rebar. The injured worker was taken to the Brooklyn Hospital Center. The workers at the site were in possession of current OSHA cards, and a pre-shift safety meeting was conducted. Two ECB Violations were issued: one violation for a failure to safeguard, and one violation for the failure to provide formwork design drawing for the foundation. A partial Stop Work Order (PSWO) was issued on middle area 18 to stop rebar and concrete work. Two DOB Violations were also issued.		35436772P, 35436773R	062019CE92JT01, 062019CE92JT02	NEW BUILDING - FOUNDATION EARTHWORK	320912394	Excavation/Soil Work	ONE BOERUM DEVELOPMENT PARTNER	
6/20/2019	Manhattan	53	WEST 53 STREET	0	The Site Safety Manager reported that a worker was dismantling a hoist platform and was stacking beams when a beam rolled over and the worker suffered a cut to his leg. The on-site medic checked the worker and sent the worker to a clinic to receive treatment. The worker was expected to return to work.	No Dispatch			NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
6/20/2019	Queens	28-07	JACKSON AVENUE	0	A DOB inspector reported that a worker fell off of an "A" Frame ladder while working on HVAC ducts. The worker claimed to be suffering from back pain and was taken to Elmhurst Hospital. An ECB Violation was taken to Elmhurst Hospital. An ECB Violation was issued for the failure to institute and maintain safe operations. A DOB Violation was also issued. A partial Stop Work Order (FSWO) was issued on the use of an "A"-Frame ladder. A Means and Methods must be provided.	- ECB Violation	35437240Z	062019CE02MH01	NB	420656873	Worker Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
6/20/2019	Queens	40-31	82 STREET	0	A DDB inspector reported that a worker sligped off of the modular stairs at the site and fell approximately six feet. The worker sligped because of rain. The injured necessary of the slight of the slight s	ECB Violation	35425036N , 35425037P	062019CE04MA03, 062019CE04MA04	NB	421485805	Worker Fell	AA 304 GC TIC LLC	RYDER CONSTRUCTION INC
6/21/2019	Brooklyn	25	NAVY STREET	0	A DOB inspector reported that two workers that were receiving electrical supplies, a pipe and a kindorf, at the grade level. One of the workers abruptly released the pipe, which caused the other worker to lose control and injure himself. The injure worker to lose control and was taken to a hospital by a foreman, where he received stitches and was allowed to go home after treatment. Two ECB Violations were issued; one violation for the failure to maintain safely measures for operation. A partial Stop Work Order (PSWO) for all deliveries to the site and Methods for safe operation where so worked with the provided.		35437477R/78Z	062119CE02DG01,02	NEW BUILDING	321183633	Other Construction Related Incidents	NYC DSBS	ZDG, LLC
6/21/2019	Marhattan	407	LENOX AVENUE	0	A DOB inspector reported that a worker was working on a supported pipe scaffold to perform masonny work on the third floor level when a wooden scaffolding plank broke and the worker fleft three feet and six riches. The worker landed on his right wrist and injured himself. The injured worker was taken to a hospital by a foreman, where he received treatment and was then released. Four ECB Violations were issued: one violation for a faultre to institute and maintain safety measures, one violation for the absence of a sier certificate for scaffolding use, one violation for the absence of a siedwalk shed where required, and one violation for a beasence of a siedger drawing for overhead protection. A full Stop Work Order (FSWO) and four DOB Violations were also issued.	ECB Violation	35404045M 35404046Y 35404047X 35404049J	062119CE10WZ01/02/03/04	NEW BUILDING	121187660	Worker Fell	407 LENOX HOUSING DEVELOPMENT	D.P. GROUP GENERAL CONTRA
6/22/2019	Queens	28-07	JACKSON AVENUE	0	I A DOB inspector reported that a worker was putting on stilts in order to perform spackle work when he slipped, lost balance, and out his arm on duct work. The worker was taken to a hospital by an ambulance. There were no tripping or slipping hazards observed at the site. It was determined that this incident occurred as the result of a worker's error, and no enforcement action was taken.	No Action Necessary					Other Construction Related Incidents	LIC SITE B-1 OWNER, LLC.	NEW LINE STRUCTURES & DEVELOPMENT



Incident Date	Borough	Address Number	Stroot	Estalitice Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/22/2019	Queens	24-16	QUEENS PLAZA SOUTH		A DOB inspector reported that during a delivery at the ground level, an "A"-Frame that was loaded with sheetrock tipped and injured a worker's foot. The worker was taken to a hospital by an ambulance. An ECB Violation was issued for a failure to maintain safety at the site. A partial Stop Work Order (PSWO) was issued for a failure to maintain ECB Violations were issued for infractions that were not related to the incident. A DOB Violation was also issued	ECB Violation	35422999Z	062219CE02JK05	AFTER HOURS VARIANCE	421214901	Other Construction Related Incidents	NAME NOT ON FILE	ROSS & ASSOCIATES LLC
6/22/2019	Manhattan	880	ST NICHOLAS AVENUE	1	A DOB inspector reported that a worker removed his harness and came down from a pipe scaffold before he returned to the scaffold to pick up a meal of his. The worker stumbled and fell from the second level onto the sidewalk (approximately 12-14 feet). The worker succumbed to his injuries from the fall. The pipe scaffold erected at the site was approximately fifty feet in height. There were no permits for the erection for the scaffold present on the site. An Aggravated Level 2 ECB Violation was issued for the performance of work without a permit. A DOB Violation and a full Stop Work Order (FSWO) were also issued.		35373813L	062219CNEMR003			Worker Fell	880 ST NICHOLAS, LLC	
6/22/2019	Brooklyn	3514	SURF AVENUE	0	A DOB inspector reported that a worker was using an "A-Frame dolly to move decking material when he fell from a makeshift ramp and got jnmed between the "A-Frame dolly and the building. The worker was taken to a hospital by an ambulance. Two ECB Violations were issued: one violation for the failure to institute safety and for unsale material handling, and one violation for the absence of a design drawing for the makeshift ramp. A partial Stop Work Order (PSWO) and two DOB Violations were also issued.		35439600M / 35439601Y	062219CE13NG06 / NG07			Other Construction Related Incidents	RED APPLE SURF REALTY III LLC	HUDSON MERIDIAN
5/24/2019	Bronx	1216	BURKE AVENUE	0	A DOB Inspector reported that a worker was standing on top of the dumpster at the grade level and was pulling the rope line of a bucket that was full of debris from a hoist when he lost his balance and fell on the ground level. The worker suffered injuries to his wrist and knee and was taken to a hospital by an ambulance. The General Contractor at the site possessed a permit for 1210 Burke Avenue, but did not possess a permit for 1216 Burke Avenue, which is where the incident took place. An ECB Violation was issued for a failure to provide safety measures, as a worker was injured use to improper action. A full Stop Work Order (FSWO) and a DOB Violation were also issued.		35425038R	062419CE11MA01	NO PERMIT	NA	Worker Fell	NYC HOUSING AUTHORITY	ROMA SCAFFOLDING INC
6/25/2019	Bronx	556	BERGEN AVENUE	0	The Site Safety Manager reported that a plumber was unloading materials when he slipped and cut his finger on material while attempting to brace his fall. The worker went to an urgent care center. An ambulance was not needed.	No Dispatch			NB	220151859	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV. CORP.
6/25/2019	Manhattan	51	WHITE STREET	0	The Site Safety Superintendent reported that a worker that had his shoelaces united was on a ten foot tall ladder installing insulation on a wall when the worker tripped on a ladder and fell about five feet. The worker complained of pain in his back and was taken to a hospital.	No Dispatch			ALTERATION TYPE 1	122913062-01-AL	Worker Fell	51 WHITE STREET LLC	AVF DEVELOPMENT CORP
6/26/2019	Brooklyn	651	EAST 108 STREET	0	A safety person reported that a worker was receiving a bucket of cement from another worker on a scissors lift when he got his back twisted. The worker was experiencing pain and went to a hospital for a checkup.	No Dispatch			ALTERATION	340136356	Other Construction Related Incidents	NYC HOUSING AUTHORITY	APS CONTRACTORS INC
6/26/2019	Queens	21-22	45 ROAD	0	A DOB inspector reported that while a supported scaffold was being dismantled at exposure four, a plank was being passed down when the plank hit a worker on the head. The worker was wearing a hard hat and did not suffer a laceration. An ambulance was called, and the struck worker walked to the ambulance and was transported to a local hospital for observation. All workers at the site were in possession of 10-hour OSHA cards and 22-hour Supported Scaffold Training cards. An ECB Violation was issued for a failure to safeguard persons and properly involved in construction activity. A partial Stop Work Order (PSWO) was issued on all supported scaffolds until a Means and Methods to prevent future incidents is provided.		35437322M		NB	421393548	Scaffold/Shed/Fence/Shoring/Installation	SALM PROPERTIES LLC	1 OAK CONTRACTING LLC



Incident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/27/2019	Manhattan	28	HUBERT STREET	0 1 A DOB inspector reported that a worker was inspeciel mock-up of mortar samples at the building façade, a when he stepped up onto the scaffold frame rung to g a photo, he slipped off of the scaffold frame and fell approximately two feet into the sidewalk shed dock. TI worker suffered a broken wrist and a concussion. The New York City Fire Department rescued him from the sidewalk shed and the worker was taken to a local hospital. The proper paperwork was present at the sist and the worker was in proper proper training cards. It was determined that this incident outcome at the result of a worker error. An ECB Violation was issued for the failure to notify the Department Of Buildings of the incident.	et et e.e.	35347526Y		ALTERATION TYPE 2 - FACADE	123662349	Worker Fell	28 HUBERT ST CORP	BULADO GENERAL CONTRACTOR
27/2019	Queens	14-55	31 AVENUE	A DOB inspector reported that a worker was using an "A"-Frame ladder to remove the bands from material carton that windows were packed in. When the worker cut the bands, the windows fell out of the carton and knocked the worker for the "A"-Frame ladder. The worker hurt his arm and an ambulance was called. Ar ECB Violation was issued for a failure to institute safe operations during material delivery. A partial Stop Wo Order (PSWO) was issued on all material deliveries. DOB Violation was also issued. A Means and Method for safe material delivery operations must be provided.	r k k	35440151Y	062719ce01mh01	NB	420967421	Other Construction Related Incidents	CENTENNIAL ASTORIA LLC	MILESTONE CONSTRUCTION
/28/2019	Bronx	1531	UNIVERSITY AVENUE	A Contractor Project Manager on a NYCHA (New Yor City Housing Authority) building reported that a works slipped down from a ladder. The worker sustained injuries and was taken to a hospital. The Contractor Project Manager notified the NYCHA Project Manage of the incident.						Worker Fell	NYC HOUSING AUTHORITY	
5/28/2019	Manhattan	509	WEST 34 STREET	The Site Safety Manager reported that a worker was walking on a third floor Q-Deck when he tripped and twisted his knee. An ambulance was called.	No Dispatch			NB	122885422	Worker Fell	509 W 34, L.L.C.	TRNER CONSTRUCTION
5/30/2019	Brooklyn	243	4 AVENUE	O 3 A DOB inspector reported that at a twelve story masonry New Building job site, pipe scaffolding at the roof buildhead level that was approximately 60 lineal fe and 3 sections high partially collapsed into the courty of a one story commercial premise that was located a 249 4th Avenue. The scaffolding partially collapsed because there were no the backs in place. There do a serious head injury, and two makes suffered minor injuries. All three hijver pedestrians were transported to Methodist Hospital. The scaffolding company was the some and was making repairs to make safe a section of scaffolding that was hanging over the exposure four wall. Four ICE OV foliations were issued: one violation for a failure to safeguard the public and property, one violation for the absence of an elevator i readiness, one Aggravated Level 2 violation for the presence of pipe scaffolding that did not meet the posted code requirements, and one Aggravated Level ECB Violation for the absence of logs and record keeping. A full Stop Work Order (FSWO) and a full Vacate Order were issued. Four DOB Violations were also issued. A DOB Violation vas issued at 249 4th Avenue for the presence of structure that was render non-compliant, due to a scaffold striking the roof and falling to grade.	et et rid :: : : : : : : : : : : : : : : : : :	35432734X 35432737L 35432736J 35432736N	06302019CERJM02, M03, M04, M05		320909228-01-NB			WERIZE INC
7/1/201	9 Queens	17-11	FRANCIS LEWIS BOULEVARD	A DOB inspector reported that a worker was trying to something on an escavator when he excavator's signs tank exploided. The worker suffered a minor injury to I face. The worker was taken to a hospital and will have full recovery from his injuries. The General Contractor had already let the site before the inspector visited his site. Five ECB Violations were issued: one violation to the General Contractor for the failure to notify the Department of Buildings of the incident, now violation to the General Contractor for the failure to post a "No Smoking" sign at the demonlition site, one violation to General Contractor for the tampering with the exhibition of Ceneral Contractor for the tampering with the exhibition of the tens to evolve the exhibition of the contractor of the	is a a a a a a a a a a a a a a a a a a a	35437517M, 18Y, 19X, 20N, 21P		DEMOLITION	42168012	21 Other Construction Related Incidents	17-11 FRANCIS LEWIS REALTY LLC	EXCAVATION CONSULTANTS OF



ident Date Borough	Address Numbe		Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/2/2019 Manhattan		1776 BROADWAY	0	1 The Site Safety Manager reported that a worker was moving a debris box when he cut his forearm on material from the box. The worker went to a doctor on his own. An ambulance was not called. The worker returned to work.						Other Construction Related Incidents	ILLERTISSEN HOLDINGCORP	
7/2/2019 Manhattan		1790 BROADWAY	0	1 The Site Safety Manager reported that a worker injured his leg while transferring sheetrock. The worker went to a doctor on his own. An ambulance was not called.	No Dispatch			ALT-1	122672704	Other Construction Related Incidents	1790 BROADWAY ASSOC. LLC	VEMA GROUP
7/2/2019 Manhattan		410 EAST 105 STREET	0	1 A contractor on a NYCHA (New York City Housing Authority) building reported that a worker was splitting a cable when he cut off the tip of his finger. The worker was taken to a hospital and was released.						Worker Fell	NYC HOUSING AUTHORITY	
7/2/2019 Manhattan		455 5 AVENUE	0	1 The Sile Safety Manager reported that a worker was using an "A-Frame to move steel angles when he lost his balance and a steel angle fell on his leg. The worke suffered a cut to his left leg and went to an urgent care center. A DoS inspector responded and reported that an OSHA Card, a Todbox Talk, and Weekly Safety Meeting were provided, and than to unsafe conditions were found. It was determined that this incident occurred as the result of a worker's error. No enforcement action was necessary.				ALTERATION-1	123313726	Other Construction Related Incidents	NEW YORK PUBLIC LIBRARY	TISHMAN CONSTRUCTION CORP
7/2/2019 Manhattan		461 WEST 126 STREET	0	A DOB inspector reported that a worker was on an extension ladder that was four feet high when the ladder was kicked out from under him and the worker fell. The worker suffered a cut to his right hand and hul his shoulder. An ambulance was called.	No Dispatch			alt-1	121629023	3 Other Construction Related Incidents	HARLEM GREEN LLC	mikot construction inc
7/3/2019 Bronx		140 WEST 174 STREET	0	The Site Safety Manager reported that a worker was cutting floor paper near an elevator when he cut his hand with a razor blade. The worker went to an urgent care center with a co-worker. An ambulance was not called.	No Dispatch			alt-3	240207735	Other Construction Related Incidents		zoria housing lic
7/3/2019 Manhattan		147 EAST 86 STREET	0	The Site Safety Manager reported that a worker was using a razor blade to clean off his trowel when he cut his leg. The worker went to an urgent care center on hi own. An ambulance was not called.				NB	122668648	Other Construction Related Incidents	NAME NOT ON FILE	GILBANE RESIDENTIAL CONST.
7/3/2019 Manhattan		1790 BROADWAY	0	1 The Site Safety Manager reported that a worker was pushing an "A'-Frame that had sheetrock on it when it tipped and hurt the worker's leg. The worker was fine, but an ambulance was called as a precaution.	No Dispatch			alt-1	122672704	Other Construction Related Incidents	1790 BROADWAY ASSOC. LLC	vema group ;;c
7/3/2019 Manhattan		441 9 AVENUE	0	1 The Site Safety Manager reported that a worker was coming off of an "A-Frame ladder when he hit an air conditioner and suffered a cut to his forearm. The worker went to an urgent care center on his own. An ambulance was not called.	No Dispatch			ALT-1	120996351	Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	pavarini mcgovern
7/3/2019 Manhattan		641 LEXINGTON AVENUE	0	1 The Construction Superintendent reported that a worke put an "A"-Frame ladder in an elevator with his materia for painting when the ladder fell forward and hit him in the shoulder. The worker is fine, but an ambulance was called, and the worker was transported to a hospital by the ambulance.						Other Construction Related Incidents	FIRST LEXINGTON CORPORATION	
7/5/2019 Brooklyn		16 AVENUE	0	A DOB inspector reported that at the roof level, there were workers on two approximately 600-pound scrapping machines that were in an approximately 10' 3rea. One worker was riding on one of the machines, and another worker was pushing another one of the machines, when approximately 8' of reinforced concrete siba collapsed through into an empty classroom below. One worker suffered an injury and was brought to a hospital in a conscious state. Two Aggravated Level 2 ECB Violations were issued: one violation for a failure to safeguard, and one violation for the performance of work that did not conform to plans. A full Stop Work Order (FSWO) and two DOB Violations were also issued.		039005078X & 039005079H	070519CERDE01, 070519CERDE02	ALTERATION TYPE 2	302582685-01-EW-OT	Material Fell	DEPARTMENT OF EDUCATION	CIVIL CONTRACTING CORP
7/8/2019 Manhattan		15 EAST 30 STREET	0	A DOB inspector reported that workers were unloading plumbing pipes from a truck. When the band on a palled of pipes was cut, the pipes rolled over and fell on the ankled of one of the workers. The injured worker went to an urgent care center. Two ECW locitations were issued one volation to the General Contractor for no pre-shift worker orientation before the commencement of a hazardous operation, and one violation to the plumbing company for no pre-shift worker orientation before the commencement of a hazardous operation. A partial Stop Work forcet (PSWO) was also issued. The General Contractor is to provide a Means and Methods with a worker orientation for the safe operation of the job.		35440208X, 09H		NEW BUILDING.	122128675	Other Construction Related Incidents	MADISON 30 31 OWNER LLC	MADISON 30 31 OWNER LLC



ident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit		Incident Type	Owner's Name	Contractor Name
7/10/2019	Queens	147-40	ARCHER AVENUE	0	1 A DOB inspector reported that a ladder fell onto a worker's leg. The worker went to a clijs M.D. The ladder that fell was stored in an unsafe condition on a column. An ECB Violation was issued for unsafe material storage on the second floor. A partial Stop Viork Order (PSWO) was issued on the second floor.	ECB Violation	35437563N		NB	420654508	Material Fell	HP JAMSTA HOUSING DEV. FUND CO	CNY CONSTRUCTION LLC
7/11/2019	Brocklyn		52 GARFIELD PLACE	0	A DOB inspector reported that there were vortices demolishing the stoop in front of a building when the demolishing the stoop in front of a building when the demolishing the stoop in force feel, and this is worker in the shoulder. An ambiduance took the worker to a hospital. The worker did not suffer any cuts or broken bones. Four ECB Violations were issued: one violation for the failure to safeguard persons and property, as a worker was injured by a structurally dislosdged element, one violation for the failure to provide a sidewalk shed, one violation for the failure to provide overhead protection for the adjacent property in exposures 2 and 4, and one violation for the absorbed overhead protection for the adjacent property in exposures 2 and 4, and one violation for the absorbed or a bepartment Of Transportation (DOT) permit for the storage of a dumpster in the readway. A full Slov Work Order (FSWO) was also issued. The General Contractor is to provide a Professional Engineer's report on the structural integrity of the building, as well as a Means and Methods for the safe operation of the job.		35439908Z, 09K, 10H, 11J		ALT-1	321791744	Material Fell	52 GARFIELD NY LLC	IFATHOM CONSTRUCTION CORP
7/11/2019			115 NAGLE AVENUE		1 A DOB inspector reported that a worker was replacing the rotten plants of a sidewalk shed deck when he stepped on corrugated thin metal. The corrugated thin metal gave way, and the worker fell approximately ten feet through an opening. The worker complained of pain on his shoulders. The New York City Fire Departmet (FDNY) responded, and an ambulance transported the worker to a local hospital. The worker was conscious. Three ECB Violations were issued: one violation for the presence of a sidewalk shed with an expired permit, on violation for the presence of a sidewalk shed was missing parapets and was not sealed at open areas, and one violation for a failure to a safequant A, partial Stop Work Order (PSWO) was also issued, and will be in effect, until a Means and Methods for the reperior of the sidewalk shed is renewed.		35440407Z, 35440408K, 35440409M		ALT-3 EQ SHED		Worker Fell	NYC HOUSING AUTHORITY	ROMA SCAFFOLDING INC
7/11/2019	Manhattan	,	532 WEST 20 STREET	0	1 A DOB inspector reported that a worker was cutting a column's rebar in order to start a Concrete Massonry Unit (CMU) wall when he got his hand ginched between the column and a rebar cutter. The worker suffered a minor injury and went to an urgent care center by himself. The workers at the site were in possession of OSHA cards, and there was a pre-task safety meeting it was determined that this incident occurred as the result of a worker error. No enforcement action was necessary in response to the incident. Two ECB Violations, a partial Stop Work Order (PSWO), and two DOB Violations were issued for issues that were not related to the incident.				NB	121190601	Other Construction Related Incidents	DDG 532 WEST 20TH STREET LLC	DDG DEVELOPMENT LLC
7/12/2019	Bronx	21	568 PARK AVENUE	0	A DOB inspector reported that a laborer on the ninth floor was showling garbage into a container when his wrist was cut by a steel stud that was sticking out of the dumpster. The worker was taken to a hospital, where he received one stitch before leaving for home. All permits at the site were valid. An ECB Violation was issued for unsafe material handling.		35437447X		NB	220152484	Other Construction Related Incidents	2568 PARK BRONX LLC	THE SWEET CONSTRUCTION GR
7/12/2019	Manhattan	17	790 BROADWAY	0	1 A DOB inspector reported that an electrician was on a ladder installing an electrical fixture on the celling when another fixture came loose, fell approximately one foot, and hit the electricians, causing a cut to the electricians fohin. The electrician was in stable condition and was taken to a hospital by a co-worker for observation. It was determined that this incident occurred as the result of a worker's error. No enforcement action was necessary.				ALT-2	123333320	Other Construction Related Incidents	1790 BROADWAY ASSOC. LLC	JT Magen Co. Inc.



Incident Date	Borough	Address Number	Street	Fatalities	Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/12/2019	Manhattan	42	4 5 AVENUE	0	1	A DOB inspector reported that there were workers removing walls and suffix on the seventh floor stainway in order to locate asbestos on the walls when the suffix collapsed and hit a worker on the head. The worker was waaring a hard hat. The worker was taken to Bellevue Hospital in stable and alert condition, and was speaking. There was no site specific orientation for the operation, and there was no asbestos assessment report provided in the construction does absent or a failure to stainway. An ECO Violation was issued for a failure to stainway, an ECO Violation was issued for a failure to (ESVIO) and a DOB Violation was issued for the failure to Stopping or the stainway of the	ECB Violation	35440455N	071219ce05sk01	ALT-2	140827078	Material Fell	424 FIFTH AVENUE LLC	Archtone Builders
	Manhattan		WEST 33 STREET	0		A DOB inspector reported that a worker was driving a scissor lift down a ramp when the scissor lift tipped over and the worker feel out of it. The worker had a hip operation performed on him in the past, and complained of pain in his right leg. The New York City Fire Department (FPNV) responded and the worker was transported to a hospital. Three ECB Violations were issued: one violation for a failure to safeguard, one violation for the absence of design drawings for the ramp, and one violation for the failure to provide a scarfold trianing certificate. A partial Stop Work Order (PSWO) was issued for the use of scissor lifts and the use of a ramp. A Means and Methods and design drawings for the ramp must be provided.		• 35437571N .• 35437572P .• 35437573R		ALTERATION TYPE 2 - GEN. CONSTR		Worker Fell		TISHMAN CONSTRUCTION CORP
7/13/2019	Brooklyn	30	IO CADMAN PLAZA WEST	0		A DOB inspector reported that a worker on the second floor was on a baser scaffold performing painting work. The worker tried to move the baker scaffold while he was on it, and the scaffold tipped over. The worker fell off of the scaffold, and the worker's head hit the concrete floor. The worker was conscious and alert and was transported to Methodist Hospital by an ambulance. There was no After Horu Variance to allow work to take place after hours under the permitted job application for the site. An Aggravated Level Z ECB Violation was issued for a failure to safeguard. A full SOR Work of the CROWN of the CR	ECB Violation	039005475J		ALTERATION TYPE 2	321939925-01-EW-MH	Worker Fell	FOREST CITY PIERREPONT ASSSOC	R.P.BRENNAN GENERAL.CONTR
7/16/2019	Manhattan	1568 A	BROADWAY	0		A DOB inspector reported that there was timber material being delivered on the ninth floor. Five workers were placing the timber material citot an "A"-Frame. The material being the properties of the five workers hands and landed on the "A"-Frame to the owner may be workers hands and landed on the "A"-Frame to the power and hit one of the workers in the head. The injured worker was teasing a hard hat. The injured worker was taken to a hospital, where he received treatment and was then sent home. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order ("B"WO) for all timber operations and a DOB Violation were also issued. A Means and Methods for the operation must be provided.	ECB Violation	35407503Y	07162019CERSM03	ALTERATION TYPE 1	121191236-01-AL	Worker Fell	TIMES SQUARE HOTEL SUB, LLC	PAVARINI MCGOVERN LLC
7/17/2019	Queens	138-24	233 STREET	0		A DOB inspector reported that at a two story detached home, a worker was performing roof and sheeting replacement work and was rolling sheeting on the roof edge when he slipped and fell from the second floor. The worker sustained a severe head injury and was taken to Jamaica Hospital, where he underwent surgery. The worker was not ted off and did not have a harness. Five of the six workers that had ernained on site did have safety harnesses in place. However, there was no anchor point observed at the roof, and there was no evidence of hard hats. No permits were issued for sheeting replacement. An office manager from the contracting company visited the site in order to supervise the other workers at the site in the securing of the site from weather, as the forecast had called for heavy rains. After the site was secured, two DOB Volations were issued for a fallure to safeguard persons and property: one violation was issued to the building owner. A full Stop Work Order (FSWO) was also issued.	DOB Violation		071719CER01JG/071719CER02JG			Worker Fell	ALLEYNE, OSBORNE	
7/17/2019	Manhattan	24	9 EAST 50 STREET	0		A DOB inspector reported that a worker was stripping plywood from the ceiling when a piece of plywood hit him in the back. The worker walked on his own to an urgent care center across the street. The plywood was being held up by jacks. It was determined that this incident occurred as the result of a worker's error. No enforcement action was necessary.	No Action Necessary	Page 41 of 46		NB	121191129	Material Fell	50 TUN TRUST	PRO-H DEVELOPMENT INC



ident Date Boro		Address Number Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/17/2019 Man	nhattan	1912 1 AVENUE	0	1 A DOB inspector reported that a worker tripped over some masonite and injured his leg. The worker was taken to a hospital for observation.	No Dispatch					Other Construction Related Incidents	HEALTH AND HOSPITALS CORPORATI	Procida Construction Corp
7/17/2019 Mani	nhattan	1776 BROADWAY	0	A DOB inspector reported that a sprinkler worker was cutting a pee on the first floor when he cut his finger with a battery band saw. An ambulance was dispatched and the worker was transported to Mourul Sinal Hospital, where he received a few stitches in his finger The Sites Safety Manager had failed to provide an OSH- card for the injured worker as of the time of inspection. However, he provided a union work authorization letter with thirty hours of completed OSHA training, as well a a worker orientation letter from the General Contractor. An Aggravated Level 2 ECB Violation was issued for a failure to safequard the public and property. A partial Stop Work Order (PSWO) was issued on all sprinkler work.	i A		039005796K	A2 - ALTERATION TYPE 2	140717669-01-EW-SP	Other Construction Related Incidents	ILLERTISSEN HOLDINGCORP	RAEL AUTOMATIC SPR.CO INC
7/17/2019 Man	nhattan	15 EAST 30 STREET	0	1 A DOB inspector reported that during a delivery operation, a worker was using an "A"-Frame to move sheatrock when the "A"-Frame, with the sheatrock on i tilled and collapsed onto the worker. The worker suffered a possible broken leg. An ambulance was called, and the worker was taken to a hospital in stable condition. An ECB Violation was issued failure to institute and maintain safety measures. A partial Stop Work Order (PSWO) was issued of rail material handling. A DOB Violation was also issued. The General Contractor was also issued a recommendation to provide adequate safety measures with a countyrehensive detail of trades on site, with a focus on material handling procedures and safety protocol for workers and personnel on the site.		35440431Z	071719CE05MH02	NEW BUILDING	12212867	9 Other Construction Related Incidents	MADISON 30 31 OWNER LLC	MADISON 30 31 OWNER LLC
7/17/2019 Broo	ooklyn	350 CLARKSON AVEN	O O	1 A DOB inspector reported that there were workers using a Bobcat to load debris into a dumpster. One of the workers was in the process of placing debris into the bucket of the Bobcat when the Bobcat's operator pushed the worn plutton, which caused the bucket to go downward onto the worker's right feet as opposed to lifting the bucket to worker in light of the worker was taken to a hospital by an ambulance. The worker was taken to a hospital by an ambulance. The worker was reported to be in fine condition. The operator of the Bobcat did not have the certification or training to operate the machine. An ECB Violation was issued for a failure to maintain safe operations. A partial Stop Work. Order (PSWO) was issued for all material handling, including receiving, deliveries, and onsite equipment use. The General Contractor is to provide a Means and Methods for safe operation of the job.		35436778X		NEW BUILDING	32090876	4 Mechanical Construction Equipment	SANDY 350 LLC	MCALPINE CONTRACTING CO
7/17/2019 Broo	ooklyn	157 WILSON STREET	0	1 A DOB inspector reported that an excavator had just completed drilling a soil test pit with an auger when the arm of the excavator struck a worker. The worker was taken to Methodist Hospital Trauma Center by an ambulance, where he was reported to be in stable condition. The work that was being performed was being performed at the front on the sidewalk in a fence off area that was closed to the public. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (PSWO) was issued for all accevation operations. A DOB Violation was assued.		35432756R	071719CERFC01	Alteration Type 3-SOE	30258506	7 Excavation/Soil Work	DEPARTMENT OF EDUCATION	Armstrong Roofing Corporation
7/18/2019 Broo	ocklyn	29 WALTON STREET	0	A DDB inspector reported that a carpenter was working on the lifth force in shall framing for the walls and was trying to adjust the leaser for measuring his height when he lost his balance. The carpenter grabbed a media stu to prevent his fall and suffered a cut to his hand. The carpenter was taken to a hospital to get stitches. There is no record of a pre-shift safely meeting site or-specific safety orientation for any worker for the entire job. An ECB Violation was issued for the absence of a site-specific safety orientation. Aff US Stop Work Order (FSWQ) was also issued. The General Contractor is to provide a Neans and Methods for the safe operation of the job, as well as proof of a safety orientation for all workers.	1	35436783K		ALT-1	32158512	9 Worker Fell	LEE REALTY LLC	YEDID BUILDERS INC



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/18/2019			HUDSON STREET		A DOB inspector reported that a worker used a piggback forklift to pick up two bundles of rebar. The piggback laped forward from the excessive weight, and the rebar fell approximately four feet onto the sidewalk. When the rear of the forklift dropped back to the ground, the worker/forklift driver's head jerked forward and struck the carriage assembly of the piggback. The worker solfered a cractact to his forestead that produced a very small amount of blood. An ambulance was called, and the worker was taken to New York Presbyterian Hospital. It was determined that this inclient occurred as the result of a worker's error. No enforcement action was necessary.	No Action Necessary			NB		Other Construction Related Incidents	HUDSON CANAL LLC	Express Builders JB Inc.
7/19/2019	Manhattan	200	AMSTERDAM AVENUE	0	A DOB inspector reported that a carpenter was working on metal studs when he cut his forearm. The worker went to an emergency room on his own. An ambulance was not called.						Other Construction Related Incidents	AMSTERDAM AVENUE REDEVELOPMENT	
7/20/2019	Manhattan	1166 6	S AVENUE	0	A DOB inspector reported that a worker was installing botts through the deck to the back a hoist. The worker grabbed a five floot ladder from the relight levelutor and climbed and stood on the top step of the ladder. The worker was reaching into the ceiling when he fell from the ladder and landed on his tailbone. The worker was reaching into the ceiling when he fell from the ladder and landed on his tailbone. The worker was ore, but he left the site under his own power and visited a City M.D. The worker did not follow safe practices and did not use the ladder that was provided by Safe-way, which has a bull-in platform to stand on that allows for safe work. It was determined that this incident occurred as the result of a worker's error. No enforcement action was necessary.				A3 - ALTERATION TYPE 3	140805458	Worker Fell	NAME NOT ON FILE	SAFWAY ATLANTIC, LLC
7/22/2019	Manhattan	351 \	WEST 38 STREET	0	A DOB inspector reported that a worker was installing angles around the windows on the fourth floor when he cut this elbow by the edge of an angle. A foreman took the worker to Mount Sinal Hospital by a tasi, where the worker received treatment and then returned to work. There is a record off the worker receiving a site-specific safety orientation, and a pre-shift meeting was held before the start of the operation. The worker was also in possession of necessary OSHA certification. It was determined that this incident occurred as the result of a worker's error, and that no enforcement action was necessary.	n			NEW BUILDING	121289435	Other Construction Related Incidents	QUADRUM 38 LLC	LEEDING BUILDERS GROUP LL
7/22/2019	Brooklyn	98 F	FRONT STREET	0	The Site Safety Manager reported that a worker was tightening a pipe when he turned wrong and injured his shoulder. The worker was taken to an urgent care center for evaluation.	No Dispatch			NEW BUILDING	321191839-01-NB	Worker Fell	80 ADAMS PROPERTY OWNER, LLC	TRITON CONSTRUCTION CO.,
7/23/2019	Bronx	1932 E	BRYANT AVENUE	0	A DOB inspector reported that a worker dropped a masonry block on his leg after cutting the block on a wet saw. The worker's glows were wet, which caused him to drop the block. The worker was taken to an urgent care center. The worker returned to work on the following day and was performing light duties. It was determined that this incident occurred as a result of a worker's error. No enforcement action was necessary.	No Action Necessary			NEW BUILDING	220152750	Other Construction Related Incidents	BOSTON BRYANT HOUSING DEVELOPE	MONADNOCK CONSTRUCTION IN
7/23/2019	Manhattan	222 \	WEST 23 STREET	0	The Site Safely Coordinator reported that a worker sloped into a trench that was approximately eighteen inches deep and suffered a heisted ankle. The worker that fell was taken to an urgent care center for observation. An ambulance was not called. A DOB impactor responded and reported that the worker was injured because unsecured phywood was covering the singular to the steep with bruising on his leg. The worker was walking with the aid of a cane, and was instructed to not work for three days. Two ECB Violations were issued: one violation for a failure to institute astery measures in the cellar area, and one violation for the failure to provide a stee orientation for the worker worked in the incident. A partial Slop Work Order (PSWO) for all cellar work and work DOB Violations were also issued. A Means and Methods for future operations and safety measures for work in the cellar must be provided. All site safety logs at the time of reinspection must also be provided.		35440558X/59H	072319CE04DG03/04			Worker Fell	CHELSEA HOTEL OWNER LLC	vema groupl lic
7/23/2019	Manhattan	887 1	LEXINGTON AVE	0	The Site Safety Manager reported that a worker was using a grinder on a Concrete Masonry Unit (CMU) block when the grinder kicked back and cut the worker's forearm. The worker was taken to a hospital by an ambulance in order to receive stitches for his forearm.				NB	302141778	Other Construction Related Incidents	1262 BROADWAY EQUITIES LLC	THE SLCE GROUP



dent Date Borough	Address Number Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No Incident Type	Owner's Name	Contractor Name
7/24/2019 Manhattan	388 PEARL STREET	0 1 The Site Safety Manager reported that a worker was using a grinder on a door frame when the grinder kicked back and cut the worker's arm. An ambulance was called to take the worker to hospital to get stitche	No Dispatch			ALT-2	140683721 Other Construction Related Incidents	NYC CITY HSG AUTRHORITY	NEELAM CONSTR. CORP
7/25/2019 Manhattan	22 NORTH LOOP ROAD	1 A DOB inspector reported that a worker was using an "A"-Frame to move sheetrock when the "A"-Frame tipped over and the sheetrock fell on the worker's foot The worker suffered an injury to his ankle and was taken to a hospital by an ambulance. An ECB Wolatio was issued for the unsafe handling of materials. A partial Stop Work Order (PSWO) was issued for all material handling, including material deliveries. The General Contractor is to provide a Neans and Method for the safe operation of the job.	1	35438607K		NEW BUILDING	121203697 Material Fell	NAME NOT ON FILE	HUNTER ROBERTS CONST. GRP
7/26/2019 Manhattan	442 WEST 33 STREET	The Site Safety Manager reported that a worker injure his finger while unloading pipes from a truck. The worker was seen by the on-site medic and was then taken to a hospital by a co-worker for observation. An ambulance was not callance was not callance.	d No Dispatch			nb	121187713 Other Construction Related Incidents	BROOKFIELD PROPERTIES W 33RD C	Pavarini Mcgovern LLC
7/26/2019 Manhattan	424 S AVENUE	1 A DOB inspector reported that a laborer was moving materials stored in the basement when she hit her shoulder against a pile that was part of the overhead protection. The worker suffered minor injuries and wa taken to a locat City Nh. The Site Saffety Manger provided OSHA training cords and a safety meeting attendance record for the laborer. It was determined that this incident occurred as the result of a worker's error. No enforcement action was necessite.				ALTERATION TYPE 2 - GEN. CONSTR	140827078 Other Construction Related Incidents	424 FIFTH AVENUE LLC	ARCHSTONE BUILDERS LLC
7/28/2019 Manhattan	40 TRINITY PLACE	A DOB inspector reported that workers on the sevent floor were attempting to move crated curtain wall pan with an electrical forklift, and were passing between doorway openings, when the forklift got stuck on plywood. The plywood three due to the weight of the forklift, and the crated curtain wall panels stilled and pinned a worker between the curtain wall panels self the exterior wall a short time. The worker was in stable condition, but suffered bruises and was in a lot of pair. The worker was taken to a hospital. The plywood that the forklift got caught on was plywood that the forklift got caught on was plywood that was being used as hole covers on the floor. An attempt was mad to remove the plywood when the forklift lited. Two EC Violations were issued, one to the General Contractor and one to the Sub-Contractor, for the presence of inadequate safety measures. There was no orientation for the operation. A partial Stop Work Corter (FSWO) was issued for all material and equipment handling or site. Two DOB Violations were also issued.	ds de la companya de	35440560P/61R	072619CE01DG01/02	NB	121191021 Other Construction Related Incidents	TPHGREENWICH OWNER LLC	GILBANE RESIDENTAL CONST
7/26/2019 Manhattan	251 WEST 117 STREET	1 The Site Safety Manager reported that a worker was walking behind a plumber that was carrying a copper pipe when the plumber stopped and the worker walke into the pipe, which caused out below the worker's ey The worker was taken to an urgent care center to get medical attention. An ambulance was not called.	i			nb	121204053 Other Construction Related Incidents	117TH STREET EQUITIES LLC	Artimus Construction inc
7/26/2019 Brooklyn	11 HOYT STREET	1 A DOB inspector reported that a worker on the forty-seventh floor partially fell through a covered 5' X 10' opening in the floor. The worker suffered injuries to hir gift lieg and left knee cap. The worker was transport to NYU Langhorne Methods thospital. An Aggravatec Level 2 ECB Violation was issued for a failure to institute the posted adequate safety measures. A part Stop Work Order (PSWO) was issued for all work on the forty-seventh floor. A DOB Violation was also issued.	s d	35407912P		ALTERATION TYPE 1	321197058-01-AL Worker Fell	11 HOYT PROPERTY OWNER, LP.	TRITON CONSTRUCTION CO.,
7/27/2019 Brooklyn	554 COZINE AVENUE	1 A DOB inspector reported that there were two forklift machines being used to set a steel beam in place at the floor level. The beam shifted slightly during placement, causing a worker that was in a manift that was attempting to make the connection to slip. The beam then fell from the forklift and struck a worker or the ground level, causing a laceration the worker's rig leg. The worker was taken to a hospital by an ambutance in a conscious state. Five ECV lotations were issued: one violation for a failure to safeguard, one violation for the sort of the forklift contrary to the manufacturer's specifications, one violation for the two contrary to the absence of a Construction Superintendent or r competent person at the site, one violation for the presence of an inadequate log book, and one violation for the absence of an inadequate log book, and one violation for the absence of an inadequate log book, and one violation for the absence of an inadequate log book, and one violation for the absence of an inadequate log book, and one violation for the absence of an inadequate log book, and one violation for the absence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of an inadequate log book, and one violation for the sabsence of the contract of the contract of the contra	on the state of th	35439964N / 65P / 66R / 67Z / 69M	072719CE05FC06 /07 /08 /09 /10	NB	321383267 Other Construction Related Incidents	BROOKLYN LOGISTICS CENTER LLC	MARCH ASSOC. CONSTRU. IN



ident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/27/2019	Queens	27-47	NORTHERN BLVD	0	1 A DOB inspector reported that a pedestrian woman was walking in the pedestrian walksway, past the job site, when she slipped on a sheet of plywood that was covering an opening. The plywood was wet and slippery due to water that was running from a hose in the storage area in the roadway that was not turned off. The woman was taken to a hospital by an ambulance. An ECB Violation was issued for a failure to safeguard the public. A DOB Violation was also issued.		35439940Y	072719CE01JK02	NB	421513749	Other Construction Related Incidents	NAME NOT ON FILE	HUNTER ROBERTS
7/29/2019	Bronx	(	600 BERGEN AVENUE	0	The Site Safety Manager reported that a worker cut his arm while carrying a piece of sheet metal. The worker went with a co-worker in a cab to go to a nearby hospital.	No Dispatch			NEW BUILDING	220151868-01-NB	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
7/29/2019	Brooklyn		422 FULTON STREET	0	1 The Site Safety Manager reported that a worker was lifting duct work when he felt a pop in his right shoulder. The worker was experiencing pain. The on-site medic sent the worker to a City M.D. for a checkup.	No Dispatch			ALTERATION - 1	320908899	Other Construction Related Incidents	NAME NOT ON FILE	TRANSPARENT CONSTRUCTION
7/29/2019 I	Manhattan		16 WEST 39 STREET	0	I A DOB inspector reported that an electrical worker was coming down from the second floor to the first floor when he missed the top step and began to fall. The first floor when he missed and instead grabbed a metal stud on a bracing connection. The worker suffered a cut to his wrist and was taken to an area hospital by paramedics. The Sibs Safeky Manager at the site was able to provide a copy of a thirty-hour OSHA training card and a safety orientation meeting record for the injured worker. No enforcement action was necessary.	No Action Necessary			NB	121190317	Worker Fell	GENERAL PUBLIC	OMNIBUILD CONSTRUCTION IN
7/29/2019	Manhattan		720 LENOX AVENUE	0	The Site Safety Manager reported that a worker hit his finger with a hammer while nailing a 2 X 6. The worker was taken to a nearby urgent care center.	No Dispatch			ALTERATION TYPE 2	123495958-01-EW-OT	Worker Fell	ESPLANADE GARDENS INC.	AM&G WATERPROOFING LLC
7/30/2019	Bronx		53 W FORDHAM ROAD	0	1 A DOB inspector reported that a worker was installing sheetrock on a ceiling when a drain pipe fell from the ceiling/rot and struck the worker in the shoulder and head. The worker was taken to New York Presbyterian Hospital by a foreman. Two EGB Violations were issued: one violation for a failure to maintain safety, and non violation for a failure to maintain adequate housekeeping. A full Stop Work Order (FSWO) was issued.		35440578N, 35440579P		Alt 2	240240832	Material Fell		FOREVIEW CONTRACTING INC
7/30/2019	Queens	42-20	27 STREET	0	I A DOB inspector reported that during a curtain wall operation, hydraufic hidu feaked out of manifit that was being used. The fluid spilled out ont the street and the sidewalk adjacent to the operation. A pedestrian slipped on the fluid and fell. The pedestrian did not suffer an injury. An ambulance was called, but the pedestrian refused medical attention. Two CED Violations were issued: one violation for a failure to safeguard public and property, and one violation for a failure to institute and maintain safety measures. A partial Stop Work Order (PSWO) and two DOB Violations were also issued.	ECB Violation	35438609Y/35438610L	073019CE02MH01/02	NEW BUILDING	421079013	Mechanical Construction Equipment	CRESCENT & 27 LLC	GALAXY DEVELOPERS LLC
7/30/2019 (	Queens	68-04	TIDES ROAD	1	O A DOB inspector reported that a 3,100 pound pre- flabricated panel that was suspended by a crane on the flourth floor was forcibly moved into position by riggers. This caused the suspended panel to make contact with an existing panel that was temporarily fastened to the floor. This caused the temporarily fastened panel to fall onto a worker. The worker was taken to a hospital, where he was pronounced dead The deceased worker was glying signals at the time of the incident. However, the worker did not possess certifications for rigping or signaling, and there was no riging plan present. A DOB Violation was issued for a failure to safeguard people and property. A full Stop Work Order (FSWO) was also issued.	DOB Violation		073019CE1403DG, CONTROL # 316177	7 CN	1248/18	Material Fell	BENJAMIN BEECHWOOD TIDES LLC	Extreme Construction Inc
7/31/2019 I	Manhattan		641 LEXINGTON AVENUE	0	1 A DOB inspector reported that a worker was walking down a hallway when he stepped on a small piece of national piece of national piece of the piec				ALT 2	123665827	Other Construction Related Incidents	FIRST LEXINGTON CORPORATION	HUNTER ROBERTS



Incident Date	Borough	Address Number	Street	Fatalities	Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/31/2019	Manhattan	36	2 WEST 125 STREET			A DOB inspector reported that a hose clogged during a concrete pumping operation. Someone opened the hose clamp, and a worker was splashed in the face and had his glasses knocked off. The Concrete Safety Manager took the worker to receive treatment. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (PSWO) was issued for all concrete operations.		35432907H		NEW BUILDING	123035624-01-NB	Other Construction Related Incidents	CVRE 125TH STREET, LLC	NOBLE CONSTRUCTION GR LLC
7/31/2019	Manhattan	33	8 WEST 39 STREET			A DOB inspector reported that a worker was using mini- contains to remove debris from the job site when he fell and wissted his andle. An ambulance was called. The area where the worker fell was adequately maintained, and there were no unsafe conditions observed. There was no enforcement action taken in response to this incident. However, an ECB Violation was issued for a failure to maintain pedestrian visibility on the undersize of the sidewalk shed. A partial Stoy Work Order (PSWO) and a DOB Violation were also issued.		35438613R	073119CE04MH01	NEW BUILDING	121189659	Other Construction Related Incidents	338 WEST 39TH STREET LLC	BARONE MANAGEMENT LLC
7/31/2019	Manhattan	30	5 WEST 48 STREET	(		The Site Safety Manage rreported that a worker hurt his hand while unbading a pallet from the truck. The worker did not suffer a cut, and there was no blood from the hand injury. The worker was driven to Mount Sinai Hospital West to receive treatment. An ambulance was not called.				NB	121203786	Other Construction Related Incidents	BRIGHT MGMT CP	JOY CONSTRUCTION CORP