PROJECT LOCATION:

541 BROADWAY

NEW YORK, NY.

DATE:

FEBRUARY 08, 2017

DOCKET #: 011068

APPLICATION FOR:

- ENTRANCE ACCESSIBILITY RAMP INSTALLATION & ASSOCIATED STOREFRONT ALTERATIONS
- FLAGPOLE LEGALIZATION
- DIAMOND PLATE LEGALIZATION
- INTERCOM LEGALIZATION

PRESENTATION:

LANDMARKS
PRESERVATION
COMMISSION CERTIFICATE
OF APPROPRIATENESS
APPLICATION



112 MERCER STREET



541 BROADWAY



SoHo-Cast Iron





1910

Courtesy Cathy Weis Projects http://www.c athyweis.org /weisacres/a bout/









2013 – **BEFORE** RESTORATION WORK



2017 – **AFTER** RESTORATION WORK















EXTENSIVE RESTORATION THROUGOUT BUILDING IN 2013


































BUILDING SECTION SHOWING MECHANICAL ROOM AND VAULT AREA UNDER BROADWAY FAÇADE AND RETAIL ENTRY


MECHANICAL ROOM CEILING AREA
















NEW DIAMOND PLATE TO BE UNIFISHED STEEL TO MATCH EXISTING.

NEW TUBULAR STEEL HANDRAIL TO BE SIMILAR TO STYLE SHOWN IN PHOTOGRAPH AND PAINTED DARKER SHADE OF EXISTING BUILDING STOREFRONT.



541 BROADWAY – EXISTING CONDITIONS



50 WOOSTER ST. – EXAMPLE OF STEEL HANDRAIL STYLE SIMILAR TO PROPOSED



45 CROSBY ST.



49 MERCER ST.



35 MERCER ST.



50 HOWARD ST.





STREET VIEW: SIDEWALK VAULT – AFTER COLLAPSE IN JULY 2001 – NOTE DAMAGED LIGHTS AND STEPS

VAULT VIEW: SIDEWALK VAULT AFTER COLLAPSE IN JULY 2001 – NOTE DAMAGED LIGHTS



STREET VIEW: SIDEWALK VAULT – AFTER REPAIRS TO DIAMOND PLATE

VAULT VIEW: SIDEWALK VAULT AFTER REPAIRS





541 BROADWAY - LOOKING SOUTH


541 BROADWAY - LOOKING NORTH








MERCER STREET ENTRY AS SEEN FROM CORNER OF MERCER & SPRING STREETS (111 FT FROM CORNER) NOTE: NO ACCESS TO 541 RETAIL STORE VIA MERCER ST. ENTRY



112 MERCER STREET ENTRANCE INTERCOM AS CURRENTLY INSTALLED



PROPOSED RELOCATION OF INTERCOM





115 MERCER STREET

125 MERCER STREET

