RESCINDED BY BUILDINGS BULLETIN 2023-007

THE CITY OF NEW YORK

HOUSING AND DEVELOPMENT ADMINISTRATION DEPARTMENT OF BUILDINGS

DIPARTMENTAL MEMORANDUM

DATE: September 23, 1974

TQ:

Chief Boiler Inspector, Patrick Dillan

FROM:

Director of Operations. Thomas V. Burke, P.E.

SUBJECT:

High Pressure Boilor Operating Engineer License and Fire Department Certificate of Fitness

C26-1402.3 (a) requires every oil burning installation that is not fully automatic or requires proheating shall be operated by or under the direct supervision of a person holding a Cortificate of Fitness issue.

Rule 15.2 of the New York City Brand of Standards and Appeals Oil Burner Rules 217-21 S.R. reads the same way. It provides however that a person holding a Cortificate of Qualification as a licensed engineer or as a licensed fireman issued May 1, 1941 need not obtain a Cortificate of Fitness.

The Division of Fire Provention of the New York City Fire
Department is not requiring a Cortificate of Fitness for Licensed
engineer in accordance with Rule 15.2.

Accordingly, planso advise your parsonnel, that they are not to advise licensed stationary engineers (high pressure boiler operating engineers) to go to the Fire Department to obtain a Cortificate of Fitness to operate an oil burner.

Thomas V. Burko, P.E. Director of Operations

TVB:LR:rur

ce: Comissioner J.T.Walsh
Doputy Comissioner, A.J.Jonkins
Aco't. Comissioner, B.Parascandola
Porcuyà Superintendents

Ecretifi Superintendents Executive Chief Engineer, I.Minkin 912