

cident Date	Borough	Address Numbe	r Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2018	Manhattan	13	EAST 7 STREET	0	1 The New York CitP Police Department reported that an exterminator fell into a six for deep excavation in the basement. A DOB inspector reported that the worker Hospital and that there was unpermitted excavation work being performed in the basemitted excavation work being performed in the basemitted excavation asteguard and work without a permit. A full Stop Work Order was issued.	ECB Violation	35309613X		No Permit	No Permit	Worker Fell	TRIAD CAPITAL, LLC	No Permit
2018	Manhattan	269		0	1 The Site Safety Manager reported that a worker was cleaning a platform from a multipoint scaffold when he sipped and fell five feet onto the ground, hitting his right elbow. An ambulance was on site. Four ECB Violations and a partial Stop Work Order were issued.		35285606Y, 35285607X, 35285608H, 35285609J				Worker Fell	RIVERVIEW OPERATING CO., LLC	Leeding Builders Group LLC
2018	Manhattan	430	EAST 58 STREET	0	 The Site Safety Manager reported that a worker got his hand stuck between a steel plate and a frame and got two of his fingers crushed. The worker was sent to Bellevue Hospital. 	No Dispatch					Other Construction Related Incidents	SUTTON 58 HOLDING COMPANY LLC	
2018	Manhattan	1681	3 AVENUE	0	 The Site Safety Manager reported that a worker was loading garbage into a truck when he slipped on snow and hurt his arm. The worker walked to urgent care. 	No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
/2018	Manhattan	301	FREEDOM PLACE SOUTH	0	1 The Site Safety Coordinator reported that a worker was unloading glass from a crate when a piece of glass fell and injured his leg. The worker was taken to a hospital. The extent of the worker's injuries was not known.	No Dispatch			NEW BUILDING	121192501-01-NB	Worker Fell	301 FREEDOM PLACE SOUTH, LLC	SCIAME CONSTRUCTION LLC
2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker on the whenty fourth thoo slipped on a patch of ice and hust his shoulder. An ambulance was called to the site. A DOB impector responded to the incident and reported that diamond plates on the outside of a hoist had water and ice on them, which caused the worker to slip. An ECB Violation and a DOB Violation were issued.	ECB Violation	35301051R	010818BS02DH03			Worker Fell	G & M REALTY, LP.	
2018	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that a worker slipped on a second floor concrete deck, landed on his back, and hurt his shoulder. The worker slipped because of snow. The worker walked to a City MD. A DOB inspector wisted the site and confirmed that the deck was covered with snow, which caused the worker to fall. An ECB Violation, a DOB Violation, and a partial Stop Work Order were issued.	r	35301164N	010918BS02VP01			Worker Fell	40-56 TENTH OWNER LLC	
2018	Manhattan	400	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was handing down a screw-jack to another worker when the screw-jack lighted out of his hands and hit the other worker. The worker saffered a minor injury and went to a site of the strength of the strength of the strength of the sissed an EC Volation, a DOB Violation, and a partial Stop Work Order.		35301055Y	010918BS04DH03			Material Fell	BOP NE LLC	
//2018	Staten Island	55	RICHMOND TERRACE	0	1 The Site Safety Manager reported that a worker slipped on ice. An ambulance was called. A DOB inspector reported that the worker slipped on ice that was located in an area that was closed off and where there was no work in progress. No enforcement action necessary.	No Action Necessary					Worker Fell	ST. GEORGE OUTLET DEV LLC	
/2018	Queens	27-17	42 ROAD	0	1 The Side Safety Manager reported that a worker was installing sheet rock when he cut his left hand on a metal duct. The worker went to urgent care with another worker	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
0/2018	Manhattan	130	EAST 82 STREET	0	1 The Site Safety Coordinator reported that an electrician was pulling cables in a box when he pulled his hand back and cut it on a piece of Chicago Bar. The incident occurred on 1/10/2018, but was not reported until 1/11/2018. The worker went to a doctor on his own.	No Dispatch			NEW BUILDING	121328027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
0/2018	Manhattan	118	FULTON STREET	0	1 A DOB inspector reported that a worker attempted to move an 'A'-Frame cart that was loaded with about twenny flat stock metal sheets when the metal sheets fell onto his leg. The worker may have possibly suffered a broken leg. An EUT was on site. An EOB Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Methods for safe operations.		35300526R				Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	
1/2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager and a DOB inspector reported that a cargenter was standing on an "A" Frame ladder to remove the door frame from an electrical closed on the 51st floor when a piece of plywood hat was behind the door frame carne closes and hit him in the shoulder, door frame carne closes and hit him in the shoulder, complianed of back pain and was transported to a hospital by ambundance. A DOB inspector reported that there were no unsafe or hazardous conditions at the working area. No enforcement action was necessary.	No Action Necessary			New Building	121333440	Worker Fell	CP V TS FULTON OWNER, LLC	CP V TS FULTON OWNER LLC
1/2018	Manhattan	151	MAIDEN LANE	0	1 A DOB inspector reported that a worker was using an "A"-Frame cart to move scaffolding elements when he wristed his wrist while pulling the cart. The worker did not want to go in an ambulance and went to see a doctor on his own. There were no unsafe of hazardous conditions at the work area. No enforcement action was necessary.	No Action Necessary			New Building	121186769	Other Construction Related Incidents	151 MAIDEN LLC	PIZZAROTTI IBC LLC



Permit No 420993740 121185635-01-NE	NEW BUILDING	Worker Fell Other Construction Related Incidents		
		3740 Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	
		3740 Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	
		3740 Other Construction Related Incidents	s NEWTOWN RESIDENCE LLC	
121185635-01-NE	NEW BUILDING			DISANO DEMOLITION CO, INC
121185635-01-NE	NEW BUILDING			
121185635-01-NE	NEW BUILDING			
121185635-01-NE	NEW BUILDING			
		5635-01-NB Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	N GILBANE RESIDENTIAL CONST
121190987				
121190987	Alt 1 NB	0987 Other Construction Related Incidents	s THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
121327224	alt 1 NB	7224 Other Construction Related Incidents	s THE MUSEUM OF MODERN ART	LEND LEASE (US) CONSTRUCT
121325027	alt 1 NB	5027 Other Construction Related Incidents	s 134 EAST 82 LLC	MC GOWAN BUILDERS INC
121020021	ut Hb			
		Other Construction Related Incidents	s NYC HHC	_
			in of the	
		Other Construction Related Incidents	s VS 125 LLC	
121186849	NEW BUILDING	6849 Mechanical Construction Equipment	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
420651912	NEW BUILDING	1912 Other Construction Related Incidents	s G & M REALTY, L.P.	G & M REALTY L.P
		Other Construction Related Incidents	s KINGSWAY REALTY LLC	
122887224	NB	7224 Mechanical Construction Equipment	AMSTERDAM AVENUE REDEVELOPME	-NT Marc Depaul
			AND TERES AN AVENUE REDEVELOPME	
		Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
				_
		Other Construction Related Incidents	CARE REALTY CORR	
		Other Construction Related Incidents	s CARE REALTY CORP.	
		Other Construction Related Incidents	s CARE REALTY CORP.	
122887224	NB	7224	Mechanical Construction Equipment Other Construction Related Incidents	Mechanical Construction Equipment AMSTERDAM AVENUE REDEVELOPME Other Construction Related Incidents 650 FIFTH AVENUE COMPANY



cident Date	Borough	Address Numb		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
19/2018	Brooklyn	3003	WEST 21 STREET	0	1 The Site Safety Manager reported that a worker twisted her ankle while pushing a mini-dumpster. An ambulance was called and took the worker to a hospital.						Other Construction Related Incidents	CONCERN SURF VETS PLACE HOUSIN	
2018	Brookiyn	19	KENT AVENUE	0	1 The Site Safety Manager reported that a worker was setting up a mobile crane when his finger got pinched between the hook of the crane and a road barrier, causing the finger to detach. A co-worker took him to a hospital. Five CEX Violations and a partial Stop Work	ECB Violation	3505625p, 26r, 27z, 28k, 29m		CRANE NOTICE	871 17	Mechanical Construction Equipment	19 KENT ACQUISITION LLC	ALL ISLAN MASONRY & CONCRETE
2018	Bronx	16	EAST 204 STREET	0	Order were issued. 1 The Site Safety Manager reported that a worker slipped	No Dispatch					Worker Fell	HP VILLA GARDENS HDFC. INC.	
					and hurt his back at the job site. An ambulance was called and took the worker to a hospital.								
/2018	Manhattan	26	ANN STREET	0	1 The Site Safety Manager reported that a worker hurt his hand while taping and spackling on the ninteenth floor. The worker went to urgent care.	No Dispatch					Worker Fell	143 FULTON STREET DEVELOPMENT	
/2018	Queens	29-22	NORTHERN BOULEVARD	0	1 A DOB inspector reported that a worker was pushing an 7k-Frame can that was loade with shore when the cart overturned, causing stone to fall onto the worker's foot and possibly preaking the foot. An EMT was on site. An ECB Violation and a partial Stop Work order were issued. The General Contractor is to provide a Means and Methods and a Tool Box Taik.	ECB Violation	35289063P				Material Fell	OSB NORTHERN LLC	
/2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a worker cut his finger while cutting a piece of rebar. EMS was called. The worker was found conscious and was taken to an area hospital.	No Dispatch			ALTERATION TYPE 1	321185953-01-AL	Worker Fell	THE SALVATION ARMY	SD BUILDERS AND CONSTRUCT
3/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker was doing form work with while he had his peligan hook attached to himself. When the worker was climbing down a ladder, the peligan hook fell and hit his right ear. The worker went to a City Mb. An ambulance was not called. This incident was the result of a worker error.	No Dispatch					Other Construction Related Incidents	NYC HPD	
3/2018	Manhattan	111	EAST 24 STREET	1	0 A DOB inspecor reported that an elevator foreman was working on a platform for installing an elevator inside the diffing upwards uncontrollably and would not stop. The worker tried to jump to the machine room on the other platform at the inith floor, but held backwards down the shaft to the cellar floor, where he succurbed to his injuries. The elevator foreman did not have a safety harmes on and was not tied to anything. There were no safety lines floor at the site. A DOB Violation and a full Stop Work. Order were issued.	DOB Violation		012318BS0501BG	NB	121192798	Worker Fell	DEMETRIOS & FANIA SAMUEL, LLC	TRINITY BUILDERS INC
/2018	Queens	62-98	SAUNDERS STREET	1	O The New York City Felice Department reported that a worker was standing on a window sill of a sinh floor apartment when he fell from the sixh floor to the ground. The worker was transported to North Schore University Hospital, but was found dead on arrival by the NYFD. A DOB inspector inspected the sile and reported that there was work present that consisted of a gut renovation to the bathroom, the installation of new electrical winng and box, and the installation of new electrical winng and box, and the installation of new electrical winng and box, and the installation of DOB Violations, and a Stop Work Order were issued.		35308671J, 35308670H	012318CERTQ01, 02			Worker Fell	NOT ON FILE	
/2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker got concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
W2018	Manhattan	280	PARK AVENUE	0	1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 42, 42018, but the Department of Buildings was not notified until January 29, 2018. An EGB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued.	ECB Violation	35312686Y	012018EE106FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
4/2018	Manhattan	233	WEST 125 STREET	0	 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle. The driver did not want to listen to the flagger. The flagger was okay, but was taken to a hospital by an ambulance for a checkup. 	No Dispatch					Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	
/2018	Manhattan	2	PARK PLACE	0		No Dispatch			ALTERATION TYPE 1	121333413-01-AL	Worker Fell	NOT ON FILE	CNY CONSTRUCTION LLC
/2018	Manhattan	102	West 186 Street	0	1 A DOB inspector reported that a worker was climbing up an 'A -Frame ladder from the first floor to the second floor when a rung on the ladder snapped, causing the worker to fall ten fest and land on his back. The worker was found concisious and was taken to the hospital by EMT personnel. An ECB Violation and a full Stop Work. Order were issued. The site will received a full audit due to site conditions.		35310351n		ALT	122917503	Worker Fell		allba services
/2018	Manhattan	44	UNION SQUARE	0	The Site Safety Manager reported that a worker at a concrete truck had a miscommunication with the driver and the shoot came down and hit the worker on the hand. The worker suffered a minor injury and an ambulance was called.	No Dispatch					Other Construction Related Incidents	READING TAMMANY OWNER LLC	



cident Date	Borough	Address Number		Fatalities Injuries E			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/2018	Manhattan	450	WEST 33 STREET	0 1 4 c d f f a	DOB inspector reported that during a demolition peration on the first floor of the HVAC conduits and titlities lines, a construction worker was cleaning emolition debris on the first floor when a pipe section all approximately four feet and hit the worker in the each. The pipe section fell because another worker cut strap pipe that was holding the pipe section. The orker who was holding the pipe section initially refused	ECB Violation	35310356M		Alteration 2	140188767	Material Fell	450 PARTNERS LLC	Tishman Construction Corp
				n h v s	hedical attention, but wasn't feeling well after a few ours and called EMS. The worker was taken to a ospital by ambidance. A Construction Superintendent as not required at the site. An ECB Violation and a full topy Work Order were issued. The General Contractor ust provide a Means and Methods for the demolition of the remaining HVAC conduits.								
2018	Manhattan	500	WEST 33 STREET	р 16 11 11 11 11 11 11 11 11 11 11 11 11	DOB inspector reported that an electrician was in the rocess of erecting a shartly while climbing an eight toot dider when he missed a rung of the ladder and fell ree feet. The worker was taken to Bellevue Hospital. A OB inspector visited the site and reported that no nforcement action was deemed necessary.	No Action Necessary			NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
/2018	Brooklyn	404	11 STREET		DOB inspector reported that workers were receiving a soil of oncrete meanory unit (CM) bick on the third cor when the third floor C-Joists towards the rare of a reverter of the second second second to the extension particulty colapse due to excessive weight of because the C-Joists were not properly secured to the CMU wells. The collapse site could the second nd first floors to collapse into could the second nd first floors to collapse into could the second nd first floors to collapse into could be the stabilized in the second the second aliare to safeguard. A sidewalk shed has been aliare to safeguard. A sidewalk shed has been aguested to be investig. We reliable the selevalk shed a stabiled. The safe well be refering to DOB is interior emolition chargineting unit for audit and approval of all merginary bornig.	ECB Violation	35310458N		Alteration	321190858	Other Construction Related Incidents	404 11TH ST NY CORP	SUN SUN Contracting
2018	Brooklyn	422	FULTON STREET	t fi t v	he Site Safety Manager reported that a worker fell mough the interior opening for a tower crane installation on the ninth floor to the eighth floor. The worker was ken to a hooptlat, where he was everycullar yealeased with no injuries. The worker did attend a safety ceretation meeting at the start of his shift. A DOB spector visited the site and reported that there was roper signage and a proper guarding system present at	No Action Necessary					Worker Fell	NOT ON FILE	
2018	Manhattan	209	EAST 19 STREET	0 1 T	the perimeter of the slab opening, but that the worker isregarded all astep measures provided to prevent alling hazards. No enforcement action was necessary. The Site Safety Manager reported that a worker was sing a grinder to cut an angle when the grinder jumped nd cut his richt lead above the knee. The cut was a	No Dispatch			ALTERATION TYPE 1	121724946-01-AL	Worker Fell	227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
2018	Manhattan	500	WEST 33 STREET	0 1 1	ninor cut. The worker walked to Beth Israel Hospital on is own. The Site Safety Manager reported that a worker tripped n the curb for the machine room and hurt his arm. An	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
				a	mbulance was called.								
/2018	Manhattan	20	BROAD STREET	P b b	he Site Safety Manager reported that a worker was ushing a debris cart when one of the wheels of the cart roke off and clipped the worker's foot. The worker went o the emergency room. An ECB Violation and a partial top Work Order were issued.	ECB Violation	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
1/2018	Brooklyn	138	WILLOUGHBY STREET	v ff f f t v v v v v v	DOB inspector reported that a team of two workers as installing form work at the second flow for a third cor column. One worker was positioned below the cound worker, holding him in place will be was stalling a clamp. While securing the clamp, and hit the blow worker in the flow. The worker was aken to a hospital, where it was reported that the order suffered a scatch, but not a concusion. The order was held overnight for observation. No inforcement action was deemed necessary, as this jury occurred due to a worker error.	No Action Necessary					Material Fell	NYC HPD	
/2018	Manhattan	1283	YORK AVENUE	a	he Site Safety Manager reported that a worker was on ladder when he tripped on the fourth step, lost his alance, and fell on his rear. The worker walked to a it/w MD for a check up.	No Dispatch					Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	
2018	Manhattan	209	EAST 19 STREET	0 1 T fi	In the Site Safety Manager reported that a worker hurt his nger while unloading pipes from a delivery truck. The worker went to a City MD on his own.	No Dispatch					Other Construction Related Incidents	227 EAST 19TH STREET OWNER, LL	
/2018	Manhattan	435	EAST 13 STREET	p p	he Construction Superintendent reported that a third arty inspector missed the last step on his way down a ermanent flight of stairs and hurt his foot. An mbulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/2018	Manhattan	532	WEST 33 STREET	0 1 T c ji	Inculated was called. The Site Safety Manager reported that a worker slipped in ice meit pellets that were on the ground floor of the bo site in an area where ice meit had been put down to helt ice. The worker hurt his wrist and his hip. The order went to see the onsite medic before going to see n offsite medic on his own.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
							Page 4 of 47						



31/2018	Borough	Address Number		Fatalities In	uries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	550	WEST 29 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder when the blade caught his glove and	No Dispatch					Other Construction Related Incidents	550 WEST 29TH STREET LLC	
					caused a cut to his hand. An ambulance was called.								
2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
		1000	Briton Britin	Ű	pinky finger while putting away his band-saw tool. The	no biopatori						110 1000 0101010111, 220	
					band-saw was unplugged. The worker went to a clinic. An ambulance was not called								
2018	Manhattan	328	EAST 62 STREET	0	1 The Construction Superintendent reported that a worker	No Dispatch			Alt 1 - NB	121189846	Other Construction Related Incidents	YYY 62ND STREET LLC	JOY CONSTRUCTION CORP
					was installing pour stops when he slipped into the side of rebar and injured his shoulder. The worker left the sit								
					in a cab.								
/2018	Manhattan	591	THIRD AVENUE	0	 The Site Safety Manager reported that a painter was carrying down supplies when he lost hs balance on the 	No Dispatch					Other Construction Related Incidents	587-91 THIRD OWNER LLC	
					carrying down supplies when he lost hs balance on the fourth step and fell, hurting his leg. An ambulance was								
					called and the ambulance took the worker to a hospital.								
/2018	Brooklyn	1	FLATBUSH	0	1 The Site Safety Manager reported that a worker was	No Dispatch	-				Other Construction Related Incidents		
					removing debris when a four inch pipe that was about three feet long fell on his foot. The worker went to a								
					hospital.								
5/2018	Bronx	869	EAST 147 STREET	0	1 The Site Safety Manager reported that a worker complained about lower back pain while pulling a stud	No Dispatch					Other Construction Related Incidents	HP MLK PLAZA HOUSING DEVELOPME	
					complained about lower back pain while pulling a stud during carpentry work. The worker went to urgent care.								
					An ambulance was not called.								
/2018	Brooklyn	1	FLATBUSH AVENUE	0	1 The Site Safety Manager reported that a worker was doing taping work while on an "A"-Frame ladder when he	No Dispatch					Other Construction Related Incidents	ONE FLATBUSH AVENUE PROPERTY L	
					mis-stepped and fell two feet. The worker suffered a								
					minor injury and an ambulance was called.								
/2018	Brooklyn	37	BLUE SLIP	0	1 The Site Safety Manager reported that a worker got his	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT G LLC	
					thumb pinched between a window and a rack during a delivery. The worker went to urgent care on his own.								
5/2018	Manhattan	10	RIVERSIDE BOULEVARD	0	1 The Site Safety Manager reported that a worker hurt his	No Dispatch					Other Construction Related Incidents	RCB3 NOMINEE LLC	
					back while lifting a reel of wire into a box. An ambulance was called.								
5/2018	Manhattan	24	2 AVENUE	0	1 The Site Safety Manager reported that a worker was putting away his tools at the end of the day when he	ECB Violation	35299721R	020618BS03GD02			Material Fell	24 SECOND AVENUE OWNER LLC	
					putting away his tools at the end of the day when he opened a sliding glass door on the eighth floor. The								
					glass door came off of its track and hit the worker. The								
					incident took place on 2/5/2018, but was not reported until 2/6/2018. An ambulance was not called, but the								
					worker said that he was going to see a doctor to be								
					checked out. An ECB Violation and a DOB Violation were issued. A partial Stop Work Order on the use and								
					installation of all balcony sliding doors was issued. The								
					General Contractor is to provide a Manufacturer's Specification on all door tracks and the reason for the								
					door falling off its track.								
5/2018	Manhattan	260	WEST 40 STREET	0	1 A DOB inspector reported that a worker was trying to	ECB Violation	35285826Y		NB	121187394	Material Fell	PORT 40TH PARKING CORP	ZDG LLC
					reach for something on the platform of a baker scaffold when he moved the baker scaffold, causing it to strike								
					the left shoulder of another worker. Both workers were								
					on the floor and not using the scaffold. The injured worker was sent to a Med-Rite Clinic for a check up.								
					The injured worker did not suffer a major injury. An ECE								
					The injuled worker did not surler a major injury. An EGE								
					Violation was issued.								
\$/2018	Staten Island	546	GULEAVENUE	0	Violation was issued.	No Dispatch					Other Construction Related Incidents	STATEN ISI AND GLOBAL LOGISTIC	
5/2018	Staten Island	546	GULF AVENUE	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con-	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
6/2018	Staten Island	546	GULF AVENUE	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison box. The worker wort to Staten Island Hospital	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
6/2018	Staten Island Manhattan	546	GULF AVENUE	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison box. The worker went to Staten Island Hospital on his own for a check up.				NEW BUILDING	121190166-01-NB	Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	TOLL GC LLC
		546 91		0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison box. The worker went to Staten Island Hospital on iso own for a check up. 1 The Site Safety Manager reported that a worker tripped fell, and out is hand. Effits was called. The worker was				NEW BUILDING	121190166-01-NB			TOLL GC LLC
		546		0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison box. The worker went to Staten Island Hospital on his own for a check up.				NEW BUILDING	121190166-01-NB			TOLL GC LLC
/2018		546 91 91		0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edion Dox. The worker went to Saten Island Hospital on his own for a check up. 1 The Site Safety Manager reported that a worker tripped fell, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital. 1 A worker tripped on a small piece of pipe in the				NEW BUILDING	121190166-01-NB			TOLL GC LLC
3/2018	Manhattan	546 91 91	LEONARD STREET	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison box. The worker want to Staten Island Hospital on is som for a check up. 1 The Site Safety Manager reported that a worker trigger fell, and out is hand. EMS and a source trigger conscious and was taken to an area hospital. 1 A worker trigged on a small piece of pie in the mechanication and and the jointy finger. The worker	No Dispatch			NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
V2018	Manhattan	546 91 91 2395	LEONARD STREET	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison box. The worker went to Staten Island Hospital on iss own for a check up. 1 The Site Safety Manager reported that a worker was conscious and was taken to an area hospital. 1 A worker report on a areal piece of pie in the mechanicat room and cut his pink finger. The worker went of a hospital by ambulance. 1 A DOB insector room of duth a worker was in the	No Dispatch No Dispatch ECB Violation	35289390M		NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
3/2018 3/2018	Manhattan Manhattan	91	LEONARD STREET	0	Violation was issued. I The Site Safety Manager reported that an electrician from Local 3 sipped in an solated area by a Con- Edison Door. The worker went to Saten Island Hospital on his own for a check up. I The Site Safety Manager reported that a worker tripped fell, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital. I A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker went of a hospital by ambulance. I A DOB inspector reported that a worker was hin the head with a piece of timber that was donped by anothe	No Dispatch No Dispatch ECB Violation	35289390M		NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC	TOLL GC LLC
V2018	Manhattan Manhattan	91	LEONARD STREET	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 sipped in an isolated area by a Con- Edion Door. The worker went to Saten Island Hospital on his own for a check up. 1 The Site Sitely Manager reported that a worker tripped fell, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital. 1 A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker went of a hospital by ambulance. 1 A DOB inspector reported that a worker was hin the head with a piece of timber that was donped by anothe worker during a stripping operation. The worker worker worker during a stripping operation.	No Dispatch No Dispatch ECB Violation	35289390M		NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC	TOLL GC LLC
/2018 //2018	Manhattan Manhattan	91	LEONARD STREET	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Ection bot. The worker went to Sisten Island Hospital on his own for a check up. 1 The Site Safety Manager reported that a worker wiped fell, and cut is hand. EMB was called. The worker was conscious and was taken to an area hospital. 1 A worker trigopad on a semal piece of piec in the mechanical form and out his was checked by a worker was went of a hospital by ambulance. 1 A DOB imports reported that a worker was his the A body imports reported hat a worker was worker with a piece of imber compliand of a stiff nexe. A body and the piece of imber compliand of a stiff nexe worker who was hit by the piece of imber compliand of a stiff nexe. B body and the a body of the CB Woldshow was	No Dispatch No Dispatch ECB Violation	35289390M		NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC	TOLL GC LLC
/2018 /2018	Manhattan Manhattan	91	LEONARD STREET	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 sipped in an isolated area by a Con- Edion Door. The worker went to Saten Island Hospital on his own for a check up. 1 The Site Sitely Manager reported that a worker tripped fell, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital. 1 A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker went of a hospital by ambulance. 1 A DOB inspector reported that a worker was hin the head with a piece of timber that was donped by anothe worker during a stripping operation. The worker worker worker during a stripping operation.	No Dispatch No Dispatch ECB Violation	35283390M		NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC	TOLL GC LLC
/2018 /2018 /2018	Manhatan Manhatan Manhatan	91 91 2395	LEONARD STREET	0	Violation was issued. I The Site Safety Marager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edion local 3 slipped in an isolated area by a Con- Edion local. The worker went to Slaten Island Hospital on his own for a check up. I The Site Safety Manager reported that a worker tripped fell, and cut his hand EMS was called. The worker was conscious and was taken to an area hospital. I A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker went of a hospital by ambulance. I A DOB inspector reported that a worker was hin the head with a piece of timber that was dropped by anothe worker during a stripping operation. The worker worker and was sent to a hospital. An ECB Violation was issued, as well as a partial Story Vork Order on all concrete work. A Means and Methods must be provided	No Dispatch No Dispatch ECB Violation			NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN	TOLL GELLE
/2018 /2018 /2018	Manhattan Manhattan	91	LEONARD STREET	0	Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison bor. The worker went to Staten Island Hospital on is own for a check up. 1 The Site Safety Manager reported that a worker typed fel, and oru is hand. EMS was called. The worker was conscious and was taken to an area hospital. 1 A worker tripped on a small piece of pie in the mechanical room and cut his pink (finger. The worker went of a hospital by ambulance. 1 A DOB inspector reported that a worker was issued, as well as a partial Stop Work forder on al issued, as well as a partial Stop Work forder on al issued, as well as a partial Stop Work forder on al is on to a hospital.	No Dispatch No Dispatch ECB Violation	35289390M 352893907R		NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC	TOLL GC LLC
/2018 /2018 /2018	Manhatan Manhatan Manhatan	91 91 2395	LEONARD STREET	0 0 0 0	Violation was issued. I The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison bot. The worker went to Sitare Island Hospital on is own for a check up. The Site Safety Manager reported that a worker wised fiel, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital. A worker trigped on a small piece of pie in the mechanical room and cut his gring Hanger and the worker was remet of a hospital y ambulance. A boDe inspector sported that a worker was his the head with a piece of imber complianed of a stiff next and was sited to a hospital by ambulance. A boDe inspector sported that a worker was issued, as well as a partial Stop Work forder on all concrete work. A Manars and Methods must be provider The Site Safety Manager reported that a worker was moving an "X-Frame obly that was loaded with wenty arefure obly tagets when the doily tippet	No Dispatch No Dispatch ECB Violation			NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN	TOLL GC LLC
/2018 /2018 /2018	Manhatan Manhatan Manhatan	91 91 2395	LEONARD STREET	0	Violation was issued. I The Site Safety Marager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edion Local 3 slipped in an isolated area by a Con- Edion Local 3 slipped in an isolated area by a Con- intervention of a check up. I The Site Safety Marager reported that a worker tripped fell, and cut his hand EMS was called. The worker was conscious and was taken to an area hospital. I A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker wert of a hospital by ambulance. I A DOB inspector reported that a worker was hin the head with a piece of timber that was dropped by anothe worker during a stripping operation. The worker worker during a stripping operation. The worker worker and was sent to a hospital. An ECB Vollation was issued, as well as a partial Story Volk Order or all concrete work. A Means and Methods must be provided in the Site Safety Manager reported that a worker was morvig an 'X-Frame doily thread that worker work to and morking an 'X-Frame doily thread that a worker was morking an 'X-Frame doily worker work to an in the Site Safety Manager reported that a worker was the safety Manager reported that a worker was morking an 'X-Frame doily worker work to an in Safety Manager reported that a worker was the safe	No Dispatch No Dispatch ECB Violation			NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN	TOLL GC LLC
/2018 /2018 /2018	Manhatan Manhatan Manhatan	91 91 2395	LEONARD STREET	0	Violation was issued. In the Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Cron- Edison box. The worker went to Staten Island Hospital on his own for a check up. The Site Safety Manager reported that a worker typed fel, and cut his hand. EMS was called. The worker went of a hospital by ambulance. A DOB inspector reported hat a worker typed worker during a stripping operation. The worker went of a hospital by ambulance. A DOB inspector reported hat a worker was hit in the head with a piece of timber that was droped by ambulance. A DOB inspector reported hat a worker was hit in the head with a piece of timber that was droped by another worker during a stripping operation. The worker was inspect, as well as a partial Drop ViolA Order on al iscencete work. A Meana and Methods must be provide The Site Safety Manager reported that a worker was moving an "X-Frame doily that was lacaded with twenty method is A do amount place where the doily oped mergency room that was across the street from the site. A TeSE Violation and a partial SIDE ViolA Orde Order	No Dispatch No Dispatch ECB Violation			NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN	TOLL GC LLC
v2018 v2018 v2018 v2018	Manhattan Manhattan Manhattan Manhattan	91 91 2395	LEONARD STREET LEONARD STREET FREDERICK DOUGLAS BOULEVARD YORK AVENUE	0	Violation was issued. Violation was issued. I The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Editon bot. The worker went to Sitane Island Hospital on is own for a check up. The Site Safety Manager reported that a worker was conscious and was taken to an area hospital. A worker trigped on a small piece of pie in the mechanical room and on this grain flash worker was conscious and was taken to an area hospital. A worker trigped on a small piece of pie in the mechanical room and on this pink flash. A worker trigped on a small piece of pie in the mechanical room and on this pink flash. A worker trigped on a small piece of pie in the mechanical room and on this a worker was the to the hospital by ambulance. A bod inspector sported that a worker was issued, as well as a partial Stop Work Order on all concrete work. A Means and Methods must be provide. The Site Safety Manager reported that a worker was moving an "A-Frame doily that was loaded with twenty sheets of 4.8 diamond pieces when the doily tipped and hit her anke. The injured worker was moving an the site injured worker went to an emergency room that was actions the street from the stel. An ECB Violation site from the stel.	No Dispatch No Dispatch ECB Violation	35209067R		NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN THE NEW YORK AND PRESBYTERIAN	TOLL GC LLC
v2018 v2018 v2018 v2018	Manhatan Manhatan Manhatan	91 91 2395	LEONARD STREET	0 0 0 0 0	Violation was issued. Violation was issued. I The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edition box. The worker went to Staten Island Hospital on his own for a check w. The Site Safety Manager reported that a worker typed fel, and cut his hand. EMS was called. The worker went of a brackup, and the solated and the solated fell, and cut his hand. EMS was called. The worker went of a hospital by ambulance. A DOB inspector sported that a worker was hi in the head with a piece of imber that was droped by ancher worker during a atipping operation. The worker was hit by the piece of imber complianted of a stiff neck issued, any will as a partial Step Work Order on all concrete work. A Means and Methods must be provide to a State Via Amager reported that a worker wate the reade. The Site Safety Manager reported that a worker wate and mith a piece of thems chance with herein provide or 3-Frame odit here inside with herein provide the solate. The worker with an endite the solation of a X B diamod plates when the odity tipped and hit her andik. The injure of worker work to an emergency room that was accoss the street from the site. A rESE Vialsion and a partial Slop Work Order were issued.	No Dispatch No Dispatch ECB Violation		0208188505HM01,02	NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN	TOLL GC LLC
	Manhattan Manhattan Manhattan Manhattan	91 91 2395	LEONARD STREET LEONARD STREET FREDERICK DOUGLAS BOULEVARD YORK AVENUE	0 0 0 0 0	Violation was issued. Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Cran- from Local 3 slipped in an isolated area by a Cran- Edison box. The worker went to Staten Island Hospital on is own for a check up. 1 The Site Safety Manager reported that a worker typed fel, and oru is hand. EMS was called. The worker was conscious and was taken to an area hospital. 1 A worker tripped on a small piece of pie in the mechanical room and cut his piky finger. The worker went of a hospital by ambulance. 1 A DOB inspector reported that a worker was and with a piece of imber that was droped by another worker during a stripping operation. The worker was inspect, as well as a partial Site y ViolA Order on al iscencete work. A Meana and Methods must be provide 1 The Site Safety Manager reported that a worker was moving an "A-Frame doily that was lacaded with wently sheets of A S diamond plases when the doily oped emergency room that was accoss the street from the site. A refee Violation and a partial Site y ViolA Order were issued. 1 The Site Safety Manager reported that a worker was moving an "A-Frame doily that was lacaded with wently emergency room that was accoss the street from the site. A refee Violation and a partial Site y ViolA Order were issued. 1 The Site Safety Manager reported that a worker was moving an the remainder of work of plase that wance accounted with the site. 1 The Site Safety Manager reported that a worker was moving an the remainder of work of plase that wance accounted were the site. 1 The Site Safety Manager reported that a worker was moving an the site of the site of the site. 1 The Site Safety Manager reported that a worker was mover issued. 1 The Site Safety Manager disported that a worker was	No Dispatch No Dispatch ECB Violation	35209067R	020618BS05HM01.02	NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN THE NEW YORK AND PRESBYTERIAN	TOLL GC LLC
v2018 v2018 v2018 v2018	Manhattan Manhattan Manhattan Manhattan	91 91 2395	LEONARD STREET LEONARD STREET FREDERICK DOUGLAS BOULEVARD YORK AVENUE	0 0 0 0 0 0	Violation was issued. Violation was issued. I The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison bot. The worker went to Siten Island Hospital on isa own for a check up. The Site Safety Manager reported that a worker rigot fiel, and cut is hards. EMB was called. The worker was conscious and was taken to an area hospital. N How for trigoted on a semal piece of piec in the mechanical from and cut its provide that a worker was conscious and was taken to an area hospital. N How for trigoted on a semal piece of piec in the mechanical from and cut his provide that a worker was added the piece of imber complianed of a stift from worker with a piece of imber complianed of a stift from worker with a piece of imber complianed of a stift from worker with a barrier to a hospital. A to EGB Violation was issued, as well as a partial Stop Work Order on all concrete work. A Means and Methods must be provide the area for a St 6 diamond pieces the stress the street from here and ka 5 diamond pieces that a worker was mere graphy come that was class the street from here and ka 5 diamond pieces the stress that the top is piece and his be ranke. The lighted worker went to an emergency room that was access the street from here were access the street from the street. The Site Safety Manager reported that a worker was contrigot the remainder diversed the time in the worker contrigot the remainder divect piece that a worker was approximately four freet. While cuting one of the piece.	No Dispatch No Dispatch ECB Violation ECB Violation	35209067R	020818BS05HM01.02	NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN THE NEW YORK AND PRESBYTERIAN	TOLL GC LLC
v2018 v2018 v2018 v2018	Manhattan Manhattan Manhattan Manhattan	91 91 2395	LEONARD STREET LEONARD STREET FREDERICK DOUGLAS BOULEVARD YORK AVENUE	0 0 0 0 0	Violation was issued. Violation was issued. 1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison box. The worker went to Staten Island Hospital on is own for a check up. 1 The Site Safety Manager reported that a worker typed fel, and oru his hand. EMS was called. The worker was conscious and was taken to an area hospital. 1 A worker tripped on a small piece of pipe in the mechanical room and out his pile (Hist) and Worker was conscious and was taken to an area hospital. 1 A worker tripped on a small piece of pipe in the mechanical room and out his pile (Hist) and With a piece of timber that was droped by another worker during a stripping operation. The worker was issued, as well as a partial Stop Work Order on al iscance work. A Means and Methods must be provide 1 The Site Safety Manager reported that a worker was moving an X-X-frame doily that was loaded with werity is thes do i A da damon plante when the doily tipped and rung rung room. The winder was moving an X-X-frame doily that was loaded with werity is the Site A da damond plante when the doily tipped and rung rung room. The winder was moving an X-X-frame doily that was loaded with werity is the site A 2 damond plante when the doily tipped and rung rung room. The winder owned to alk of the doily tipped and rung rung room and a partial Stop Work Order were issued. 1 The Site Safety Manager reported that a worker was moving an X-X-frame doily that was loaded with were to a more issued. 1 The Site Safety Manager reported that a worker was moving and X-X-frame doily that was loaded with were to a more issued. 1 The Site Safety Manager reported that a worker was moving an X-X-frame doily that was loaded with were its a the A Tee Si Violation and a partial Stop Work Order were issued. 1 The Site Safety Manager reported that a worker was perpending to rung the top that a store was perpending to rung the top that a store was perpending to rung that the take the moke doily that the take the the doil	No Dispatch No Dispatch ECB Violation ECB Violation	35209067R	020918BS05HM01,02	NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN THE NEW YORK AND PRESBYTERIAN	TOLL GCILC
2018 2018 2018 2018	Manhattan Manhattan Manhattan Manhattan	91 91 2395	LEONARD STREET LEONARD STREET FREDERICK DOUGLAS BOULEVARD YORK AVENUE		Violation was issued. Violation was issued. I The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison bot. The worker went to Staten Island Hospital on Is own for a check up. The Site Safety Manager reported that a worker typed fell, and oru is hand. EMS was called. The worker was conscious and was taken to an area hospital. A worker tripped on a small piece of pie in the mechanication and on the piece of the worker was conscious and was taken to an area hospital. A worker tripped on a small piece of pie in the mechanication oron and ot the jointy finger. The worker went of a hospital by ambulance. A DOB inspector reported that a worker was issued, as well as a partial Stop Work Order on all concrete work. A Means and Methods must be provide that the site of the right worker was moving an "A'-Frame doily that was loaded with twenty abels of A S diamond pieces when the doily tipped and hit her anke. The injured worker was counting a tripping operates them the site. A EGD Volation worker that memogency from that was access the site time the site. At EGD Volation and a partial Stop Vork Order were issued, as well as a partial Stop Vork Order or all The Site Safety Manager reported that a worker was moving an the right work piece of the site worker was cutting the remainder of word piles that were approximately four fielt. While cutting one of the piece, 26/2018, but was not reported that a worker was cutting the remainder of word piles that were approximately four fielt. While cutting one of the piece, 26/2018, but was not reported that a morker the an EGE Volation was issued to a failure to notify the	No Dispatch No Dispatch ECB Violation ECB Violation	35209067R	0206188505HM01.02	NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN THE NEW YORK AND PRESBYTERIAN	TOLL GC LLC
/2018 /2018 /2018	Manhattan Manhattan Manhattan Manhattan	91 91 2395	LEONARD STREET LEONARD STREET FREDERICK DOUGLAS BOULEVARD YORK AVENUE	0 0 0 0 0	Violation was issued. Violation was issued. I The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison bor. The worker went to Staten Island Hospital on Iso om for a check up. The Site Safety Manager reported that a worker typed fel, and oru is hand. EMS was called. The worker was conscious and was taken to an area hospital. A worker tripped on a small piece of pie in the mechanical room and out his piece first piece of the worker was conscious and was taken to an area hospital. A worker tripped on a small piece of pie in the mechanical room and out his piece first piece of the worker was conscious and was taken to an area hospital. A worker tripped on a small piece of piece in the mechanical room and out his piece first piece of the worker was subject or sported that a worker was his the piece of timber that was droped by another worker during a stripping operation. The worker was issued, as well as a partial Stop Work Order or all concrete work. A Means and Methods must be provide the strip or own that was cause the strippied on the strippied on the strippied on the strippied on the strippied worker water to a moning an Y-k-Frame doily that was loaded with twenty and hit her anke. The injured worker was moving an Y-k-Frame doily that was loaded with twenty and hit her anke. The injured worker was moving an Y-k-Frame doily that was loaded with twents the piele fiel floward and hit hum in the head. The worker approximately four hert. While cutting one of the piece, the piele fiel floward and hit hum in the head. The worker was to a hospital A worker was particularly down free. While cutting one of the piece, ECG Violation was issued one failure to notify the Department Of Buildings of the incident, as well as a partial Stop Work. Order for the indived piece they the Department Of Buildings of the incident, as well as a partial Stop Work. Order for the indived piece they the Department Of Buildings of the incident, as well as a pareal Stop Work. Order f	No Dispatch No Dispatch ECB Violation ECB Violation ECB Violation	35209067R	020818B505HM01,02	NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN THE NEW YORK AND PRESBYTERIAN	TOLL GC ILC
2018 2018 2018 2018	Manhattan Manhattan Manhattan Manhattan	91 91 2395	LEONARD STREET LEONARD STREET FREDERICK DOUGLAS BOULEVARD YORK AVENUE	0 0 0 0 0	Violation was issued. Violation was issued. I The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison bot. The worker went to Staten Island Hospital on Is own for a check up. The Site Safety Manager reported that a worker typed fell, and oru is hand. EMS was called. The worker was conscious and was taken to an area hospital. A worker tripped on a small piece of pie in the mechanication and on the piece of the worker was conscious and was taken to an area hospital. A worker tripped on a small piece of pie in the mechanication oron and ot the jointy finger. The worker went of a hospital by ambulance. A DOB inspector reported that a worker was issued, as well as a partial Stop Work Order on all concrete work. A Means and Methods must be provide that the site of the right worker was moving an "A'-Frame doily that was loaded with twenty abels of A S diamond pieces when the doily tipped and hit her anke. The injured worker was counting a tripping operates them the site. A EGD Volation worker that memogency from that was access the site time the site. At EGD Volation and a partial Stop Vork Order were issued, as well as a partial Stop Vork Order or all The Site Safety Manager reported that a worker was moving an the right work piece of the site worker was cutting the remainder of word piles that were approximately four fielt. While cutting one of the piece, 26/2018, but was not reported that a worker was cutting the remainder of word piles that were approximately four fielt. While cutting one of the piece, 26/2018, but was not reported that a morker the an EGE Volation was issued to a failure to notify the	No Dispatch No Dispatch ECB Violation ECB Violation ECB Violation	35209067R	0206188505HM01.02	NEW BUILDING	121190166-01-NB	Worker Fell Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	353-357 BROADWAY LLC 353-357 BROADWAY LLC HP 2395 FDB HOUSING DEVELOPMEN THE NEW YORK AND PRESBYTERIAN	TOLL GCILC



cident Date	Borough	Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Brooklyn	540	FULTON STREET	0	1 The Site Safety Manager reported that during a drilling operation for the backs, a carpenter that was assisting the drill operator stepped onto an equipment insert and the clamp obsed down on his left toot. The worker was taken to a hospital by emergency personnel. Two ECB Violation, were issued, as well as full Saf DV Work Order. The contractor has been directed to provide the manufacture's specifications for the drilling equipment, as well as the required training for the personnel operation.		35309900Z 35309901K		NB	321185828	Mechanical Construction Equipment	540 FULTON ASSOCIATES	PAV-LAK CONTTRACTING INC
2018	Manhattan	460	PARK AVENUE SOUTH	0		No Dispatch					Other Construction Related Incidents	460 PARK AVENUE SOUTH ASSOCIAT	
2018	Queens	27-17	42 ROAD	0	1 The Site Safety Manager reported that a worker lacerated his hand with a utility knife during a stripping operation when the utility knife slipped. The worker went to a hospital on his own.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
2018	Brooklyn	810	FULTON STREET	0	1 The Site Safety Manager reported that a worker was performing stripping work on the eleventh floor when he pulled down a piece of plywood and the aluminum leg of the formwork hit the worker in the face and spit his lip. An ambulance was called. An ECE Violation was issued for a failure to provide safety measures. A DOB Violation was also issued. A Tool Box Talk will be issued before the start of stripping operations.	r	35300050K	020818BS02EP06			Material Fell	GREENPOINT-GOLDMAN CORP.	
2018	Manhattan	388	GREENWICH STREET	0	1 The Site Safety reported that a worker hurt his foot while using a chipping gun. The worker took a cab to urgent	No Dispatch			ALTERATION TYPE 1	121190503-01-AL	Other Construction Related Incidents	CITIGROUP TECHNOLOGY, INC.	TISHMAN CONSTRUCTION CORP
2018	Queens	34-11	BEACH CHANNEL DRIVE	0	care. 1 The Site Safety Manager reported that a worker was dismantling a scaffold when the plank he was standing on broke and fell six feet. The worker went to a hospital by ambulance. An ECB Violation for a failure to safeguard all persons and property affected by construction operations was issued.	ECB Violation	35285811N		NB	421094283	Worker Fell	NOT ON FILE	Chateau GC LLC
2018	Queens	160-08	JAMAICA AVENUE	0	1 The Site Safety Manger reported that a vehicle struck the flagman in the street. The Police Department responded to the incident. The worker wss taken to Jamaica Hospital.	No Dispatch					Other Construction Related Incidents	160 JAMAICA, LLC	
2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that an electrician was pulling his cart from the hoist when the handle on the cart became loose and the worker fell backwards to the floor, hurting his back. An ambulance was called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
2018	Brooklyn	500	GATES AVENUE	0	1 The Super reported that a mason was using a grinder for brick cutting when the grinder kicked back and the grinder's butt end (not the blade) hit the mason in the face. The mason suffered a bruise to his face and felt a little dizzy. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PCMH 500 GATES HOUSING DEVELOP	
018	Brooklyn	340	EVERGREEN AVENUE	0	1 The Fire Department reported that a worker was hit in the head with a piece of rebar. Four ECB Violations and four DOB Violations were issued. A partial Stop Work Order was also issued. A Means and Methods and a Tool Box Talk must be provided.		35300117X,118H,120R,121Z	020918BS04DH01,02,04,05			Material Fell	BUSHWICK REALTY HOLDINGS LLC	
2/2018	Bronx	2568	PARK AVENUE	0	1 The Site Safety Manager reported that a worker cut his knee while walking by rebar. The worker was taken to an area medical facility by a co-worker.	No Dispatch				220152484	Other Construction Related Incidents	2568 BRONX PARK LLC	STEVEN ALESSIO
2/2018	Brooklyn	135	EMERSON PLACE	0	1 The Site Safety Manager reported that during a stripping operation, a worker fell down from the sixth floor and landed on top of the sidewalk shead. The worker was found unconscious, but breathing. The worker was taken to a hospital by ambulance. An ECB Violation and a full Stop Work Order were issued. Three additional ECB Violations/OATH Summonses and three partial Stop Work Orders were issued by the Concrete Enforcement Unit.		35300065N				Worker Fell	PRATT INSTITUTE	
2/2018	Manhattan	11	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker was working in a man lift when he moved his body and twisted his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	THE MUSEUM OF MODERN ART	
2/2018	Manhattan	200	EAST 95 STREET	0	1 The Site Safety Manager reported that a worker pinched his finger while moving a steel beam on an "A"-Frame. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents		
2/2018	Manhattan	461	WEST 34 STREET	0	The worker went to urgent care. The Site Safety Manager reported that a worker cut his left hand on metal studs. The worker was taken to an area hospital and received several stitches.	No Dispatch			ALT 1	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	EDWARD M GRUNWALD
3/2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manager reported that a worker entered the site from the outside of the mall area by the dirt parking area side, fell in ice that was mixed with dirt, and hurt his ankle. The worker went to urcent care.						Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	



ncident Date	Borough	Address Number		atalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/13/2018	Queens	80-08	135 STREET	0 2) The General Contractor reported that two workers we injuried while grouting when a purp hoses got clogged with grout and blew into the worker's faces. The work tireid to un-clog the purp while twas in use. The two workers were taken to a hospital for treatment. An EC Violation and a partial Stop Work Order were issued.	rs	35309854r		ALT 1	420652378 AL	Mechanical Construction Equipment	BRIARWOOD MP LLC	PAV-LAK CONTRACTING INC
/13/2018	Queens	45-57	UNION STREET	0 1 A DOB impactor reported that a worker was using the actificity statist to bring rebars one a floor when are actificity statist to bring rebars one a floor when are worker down. The worker was experiencial packs in his body and went to a clinic the next day. This incident took place on February 13, 2018. Use building was a five story build with no permanent statisr. An EOS Vortation and at UII Site Worker Order were issued for inadequate ingress/egress, an adequate supported scaffold, and fact of internal statisr.	ng	35299830L				Worker Feil	DEPARTMENT OF EDUCATION	
15/2018	Brooklyn	1060	CLARKSON AVENUE	0 1 The Site Safety Manager reported that a worker cut hi arm with a saw while cutting wood. The worker was taken to a hospital by ambulance.	No Dispatch			ALTERATION TYPE 2	302581347-01-EW-OT	Worker Fell	DEPARTMENT OF EDUCATION	ANSU CONSTRUCTION INC
2/15/2018	Manhattan	101	WEST 57 STREET	0 1 A DOB inspector reported that contractors were attempting to remove a tempered pairs paired when the panel shattered. A small price of glass field to the strete level while the remainder of the shattered panel was the terace. A woman was injured and taken to a hospital by ambulance. The vomens' highly was attrabuted to the difference of the stratesting. An Aggravated Level 2 ECB Violation, and pair 80 Violation, at power difference of the shared bare was an and projectly during construction operations.	t n	35306906P	021518CERDY04			Material Fell	101 WEST 57TH STREET HOTEL INV	
2/15/2018	Manhattan	42	WEST 33 STREET	0 1 The Site Safety Manager reported that a worker was climbing off of a scaffold when he slipped and fell approximately two feet, injuring his shoulder. An ambulance was called.	No Dispatch					Worker Fell	38-46 WEST 33 STREET, LLC	
2/15/2018	Queens	30-35	COLLEGE POINT BOULEVARD	ancuance was called. 0 1 DOB inspector reported that a painter was on a scissor iff painting the area next to a roll down door sensor when he activated the door, which caused another worker to get hit by the door. The worker had the wind knocked out of him and was sent to a hospital An ECB Violation and a partial Stop Work Order were insued for the failute to maintain set operations. The General Contractor at the site is to provide a Means a Methods.		35317705N				Other Construction Related Incidents	FEINSTEIN CP REALTY LLC	
2/16/2018	Manhattan	217	WEST 57 STREET	0 1 The Site Safety Manager reported that a concrete worker was carrying a Doka form that was about 2 X 5 feets and 100 pounds when he signed and fell. The worker complained of back pain. A DOB inspector responded to the incident and reported that no enforcement action was necessary, as the injury occurred as the result of a worker error.	No Action Necessary	,				Other Construction Related Incidents	SMITELL SPONSOR LLC	
2/16/2018	Manhattan	233	WEST 125 STREET	0 1 The Site Safety Manager reported that a worker was lifting a piece of rebar when he claimed to have hurt h back. The worker walked up to an ambulance and the ambulance took him to a hospital.	s			NEW BUILDING	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTRUCTION SERVICES L
//6/2018	Manhattan	38	HOWARD STREET	0 2 Å DOB inspector reported that an inspector from Cole NY was performing an inspection of the building for facade local aw While inspection the building, the inspector stepped out onto the fire escape on the seventh floor, and a step of the fire escape became dislodged and fell to the ground, striking two pedestrians. One of the pedestrians suffered a file threatening injury, and the second pedestrian was in serious condition. The inspector fell slightly through a opening, but not all the way down. EMS was called. A ECG Violation, a DOB Violation, and an Immediate Emergency Declaration were issued.		35308908Z	021618CERDY01			Material Fell	434 BROADWAY PROPERTY INVESTOR	CANY Architecture & Engineering, DPC.
//16/2018	Queens	71-17	ROOSEVELT AVENUE	I A DOB inspector reported that were four workers unbacking bundles of rebort that were approximately for five feet from a Babed truck when one of the workers load and the Babed truck when the bundles of the sectors of another that the the sector sector and the sector of another the injured worker authered a bundle into the another the injured worker authered a bundle inglit log and was taken to a hospital. An EOB Violatio and a partial SDV Work Order were issued of a failur to maintain the safe operations and to stop all materia handling, including deliveries. The General Contractor to provide a safe Means and Methods, including equipment and Tool Box talks.	ng N			NEW BUILDING	420653000	Material Fell	ROOSEVELT PARC LLC	BRAVO BUILDERS LLC
2/19/2018	Manhattan	200	EAST 21 STREET	0 1 The Site Safety Manager reported that a worker dislocated his left shoulder when he lifted a bag of concrete onto it. The worker was taken to Mount Sina Hospital by ambulance.	No Dispatch			NEW BUILDING	121190479-01-NB	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC



ncident Date	Borough	Address Number	Street	Fatalities Injur	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
19/2018	Brooklyn	805	WASHINGTON AVENUE	0	1 A DOB inspector reported that a worker was waking close to a Boota while an I-Beam was on the forks attached to the Bobcat when the I-Beam moved and the worker's hand got caught between the I-Beam and the Bobcat track. The worker suffered a fractured hand and was taken to an area hospital. The worker or peraing the Bobcat was not trained by the employer, which created this situation and intersubled in an injury to another work. This incident occurred on 2/19/2018, but the Site Safety Manager was on informed of the incident until 2/20/2018. Four ECB Work and a partial stop Work order were issued.		35317732Z, 35317733K AND 35317736K		NEW BUILDING	321478548	Mechanical Construction Equipment	805 WASHINGTON AVE LLC	HAPPY LIVING DEVELOPMENT
9/2018	Brooklyn	211	SCHERMERHORN STREET	0	1 The Site Safety Manager reported that a worker rolled his ankle while moving material. The worker was taken	No Dispatch			FRANK HEALEY	321196200-01-NB	Other Construction Related Incidents	211 SCHERMERHORN DEVELOPMENT L	OESTREICHER CONSTRUCTION
20/2018	Manhattan	115	DELANCY STREET	0	to Brooklyn Hospital by EMS. 1 The Site Safety Manager reported that a worker cut his finger while using a grinder. The worker went to urgent care	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
20/2018	Manhattan	425	PARK AVENUE	0	1 The Site Safety Manager reported that a worker fell from the fourth step of an 'A'-Frame ladder. The worker complained of back pain. An ambulance was called.	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
/21/2018	Brooklyn	5718	2 AVENUE	0	ADOB inspector reported that a worker was pulling on one of the clips of a outrigger scaffold in noder to install is properly. The worker pulled that cip hard, which caused the worker work to be end by a scaffold in and scale. The worker work to be emergency room across the street and then werk home. The formwork and costiggers were all built as provided in the formwork and costiggers were all built as provided in the formwork and costiggers were all built as provided in the form the minimum occurred as the result of a worker error.	No Action Necessary			ALTERATION-1	321192702	Worker Fell	NYU HOSPITALS CENTER	HUNTER ROBERTS CONSTRUCTION
21/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager has reported that a worker was climbing down an 'A'-Frame ladder when he slipped and fell about four feet. An ambulance took the worker to a hospital. The worker suffered a possible fractured elbow.	No Dispatch					Worker Fell	SMITELL SPONSOR LLC	
21/2018	Queens	131-11	FOWLER AVENUE	0	1 The Site Safety Manager reported that a worker twisted his right wrist while bending rebars. A co-worker took him to a clinic.	No Dispatch					Other Construction Related Incidents	131-05 HOLDING LLC	
21/2018	Queens	38-01	QUEENS BOULEVARD	0	The Site Safety Coordinator reported that a worker tripped on tape on a scaffold platform, which caused him to fail and twish tisk nee. The worker was taken to urgent care. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard all persons and property.	ECB Violation	35285820P		NB	421387626	Worker Fell	CURBCUT QUEENS BLVD LLC	Sordoni Construction Comp
22/2018	Staten Island	35 a	BAY STREET	0	1 The Site Safety Manager reported that a rebar installer slipped on a rebar floor and twisted his ankle. An ambulance was on site.	No Dispatch					Other Construction Related Incidents		
22/2018	Staten Island	2655	RICHMOND AVENUE	0		No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
/22/2018	Manhatlan	122	LEXINGTON AVENUE	0	The Police Department reported that two workers were making a delivery to the roof area of the structure when one of the workers fiel approximately eight to the feet through an opening in the roof that was covered with a tarp. The worker felt to the third floor. The worker suffered injuries to his back and neck and was neck the structure when the structure when injuries. A full Sogi Work Order had baen issued to the building on 4222015 and a Vacate Order was issued on 1222/2017. Two EGB Vollations, and two DOB Violations were issued for the unlawful continuation of work while on the notice of a Stop Work Order and for a failure to safeguard.	ECB Violation	35308661K & 35308960Z	022218CERTQ01 & 022218CERTQ02			Worker Fell	122-24 LEXINGTON AVEOP	
22/2018	Brooklyn	19	KENT AVENUE	0	 The Site Safety Manager reported that a worker walked into a pile of plywood and then felt discomfort in his upper torso and chest. An ambulance was called and the worker was transported to a hospital. 	No Dispatch			NEW BUILDING	320591944-01-NB	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
22/2018	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker cut his finger while handling rebar. The worker was seen by the on-site medic and was sent to City M.D./urgent care.	No Dispatch					Other Construction Related Incidents	NYC HPD	
//23/2018	Queens	83-09	35 AVENUE	0	1 A DOB inspector reported that workers at apartment number B42 were lowering a piece of plywood that was approximately 2 X 5 from the fourth floor fire escape to the ground using a heavy thick rope in front of the building. According to the Project Manager at the site and a bystander, the plywood slipped off of the rope and form the failen wood can still be seen on the ground. Marks from the failen wood can still be seen on the ground where I landed. The seen on the ground where the base of the theory of the seen on the ground where I landed. The seen on the ground was transferred to New York Presbyterian Hospital of Queres with injurious to the side of her head. Three Aggrovated used for work not conforming to plains, and for working without a permit. 3 DOB Violations,and a full Stop Work Order were also issued.		35309174N, 35309325L & 3530932EN	022318CERKC03, 022318CERKC04 & 022318CERKC05	ALTERATION TYPE 2	421548999-01-EW-OT	Material Fell	83-09 36TH REALTY LLC	MNR GROUP INC



cident Date	Borough	Address Number	Street	Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/2018	Manhattan	545	WEST 30 STREET	0	1 A DOB inspector reported that workers were using a lul to unload window panels of of a truck. While the lull was being taken into the building, one of the panels slid off of the lull and hit a worker's ankle. An ambulance took the worker to a hospital. An ECB Violation for a failure to maintian safe operations and a partial Stop Work Order were issued or all deliveries and material handling. The General Contractor is to provide a Means and Methods.	ECB Violation	35317717K				Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
7/2018	Manhattan	685	FIRST AVENUE	0	1 The Site Safety Manage reported that a worker was working in a building when a couple of pieces of sheetrock fell over and onto his leg. An ambulance was called to the site.	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
28/2018	Manhattan	1227	BROADWAY	0	1 A DOB inspector reported that a tower crane was engaged with leading a four too ince of scaffolding material on top of a traiter within the job site. After the load was lowered into place, a worker began unbooking the rigging gear so that the crane could proceed with the next tilt. The gear was detached from the load and the crane hoisted up to clear the traiter and the loaded scaffolding when, ubeknowns to the worker, the rigging gear anagged the corner of the load that had just landed, which caused the load to flip over the side of the traiter and bring the worker down, injuring him in the process. The worker was found belending, but conscious and was taken to a hospital by ambulance. The injuries that the worker sustained are suspected to be non-life threatening. Three ECB Violations and a partial Stop Work Order were issued.		35225172L 35225171J & 35225172L		CN	CN 913/16	Mechanical Construction Equipment	YJL BROADWAY HOTEL LLC	BMNY CONTRACTING CORP
8/2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that a worker got dust in his eye. The worker went to a hospital for treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/2018	Brooklyn	391	HOOPER STREET	1	A DOB inspector reported that heavy gauge 2.X10 colling joints were delivered and placed on top of the DOB inspector of the DOB inspector of the DOB inspector of the DOB inspector of the colling joints together, which lead to the joints collapsing and knocking the worker off of the scaffold to the ground. The joints founded on top of the worker as well. The worker was found ead on arrival. A DOB Violation and a full Stop Work Order were issued.	DOB Violation		0301188501A501			Other Construction Related Incidents	E&D MANAGEMENT GROUP LLC	
/2018	Queens	28-02	JACKSON AVENUE	0	1 A DOB inspector reported that a panel of phyword that was about 8 X if fell from the paraget of a addewak was about 8 X if fell from the paraget of a addewak inferred an injury in the shoulder. Dut device padaetrian was seen by the on-site modile, but device turther medical attention and let the scene. An Aggrowited Level 2 EOB Violation was issued for a fallware to safeguard public and property affected by construction operations. A second EOB Violation was also issued for a fallware to maintain an inspection log for the sidewalk shed. A partial Stop Work Order was also issued. The sidewalk shed company was sent to the site for repair work.		35318106Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, LP.	TURNER CONSTRUCTION COMPA
/2018	Manhattan	685	1 AVENUE	0	1 The Site Safety Manager reported that a worker was pushing a mini container when the gate on the bottom of a ramp swung and lacerated his right hand. The on-site medic put a band aid on the cut. An ambulance took the worker to a hospital.						Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
2018	Manhattan	260	WEST 40 STREET	0	1 The Site Safety Manager reported that a worker was using a lade and cut his finger. The worker was patched up on-site, but then went to City M.D. where he received two to three stitches.				NB - NEW BUILDING	121187394	Other Construction Related Incidents	PORT 40TH PARKING CORP	ZDG, LLC
2018	Manhattan	150	EAST 23 STREET	0	1 The Site Safety Manager reported that workers were carrying steel plates when one of the plates slipped and pinched one of the worker's left middle finger. The worker was transported to a hospital by ambulance.				NB	121981748	Other Construction Related Incidents	154 EAST 23 LLC	W & L GROUP CONSTRUCTION
2018	Manhattan	1912	1 AVENUE	0	1 The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the worker was transported to a hospital.	No Dispatch			NB	122879233	Worker Fell		PROCIDA CONSTRUCTION CORP
2018	Manhattan	396	BROADWAY	0	1 The Site Safety Manager reported that a worker dropped a piece of plywood on his foot. The worker left the site in an ambulance.	No Dispatch			A1 - ALTERATION TYPE 1	120786417	Other Construction Related Incidents	BRIDGETON 396 BROADWAY FEE LLC	ANTHONY T. RINALDI
2018	Manhattan	425	WEST 18 STREET	0	1 The Site Safety Manager reported that a worker hurt his back while picking up a cement bag. An ambulance was called and the worker was transported to a hospital.	No Dispatch			NB	122736762	Other Construction Related Incidents	NOT ON FILE	ARTIMUS CONSTRUCTION INC
/2018	Brooklyn	10	HURON STREET	0	1 The Site Safety Manager reported that there were two workers that were doing sheetrock work together when one of the workers lost hai ging on a piece of sheetrock that landed on the other worker's finger, causing a cut. The second worker lift the site and went to City M.D. to get stitches on his linger. This incident occurred on \$352018, but was not reported to the Site Safety Manager or Construction Superintendent until 38/2018.						Other Construction Related Incidents	10 HURON FS CONDO LLC	



cident Date	Borough	Address Numbe	r Street F	atalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/2018	Queens	45-57	UNION STREET		ECB Violation	35317909P				Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
				swung out and hit a pedestrian that was walking by. The								
				pedestrian was a student that was approximately seven								
				years old. The student was evaluated by a nurse.								
18	Manhattan	2255	BROADWAY	0 1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	2255 HOLDING LLC	
				lifting a 2 X 3 X 10 wooden beam in the elevator pit when he hit himself in the face with the wooden beam.								
				The worker went to urgent care and then went to a hospital. This incident occurred as a result of a worker								
				error.								
018	-	2395	FREDERICK DOUGLASS BLVD	0 1 The Site Safety Manager reported that a pedestrian in a		35300487N	030618BS10VP06			Other Construction Related Incidents		
J18	Bronx	2395	FREDERICK DOUGLASS BLVD	 I ne Site Safety Manager reported that a pedestrian in a wheelchair fell over in a walkway due to a tripping 	ECB violation	35300487N	03061885107P06			Other Construction Related Incidents		
				hazard around a Con-Ed sewer cap. The pedestrian								
				went to a hospital by ambulance. A DOB inspector								
				responded to the incident, visited the site, and issued an ECB Violation. The tripping hazard was corrected as of								
				the time that the inspector was at the site.								
018	Brooklyn	416	KENT AVENUE	 The Site Safety Manager reported that a worker slipped, fell, and hurt his arm. The worker was taken to a 	No Dispatch				320622616	Other Construction Related Incidents	420 KENT AVENUE LLC	ZDG, LLC
				hospital for a check up.								
2018	Manhattan	1681	3 AVENUE	0 1 The Site Safety Manager reported that an electrician	No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
				was running a wire when he tripped on a piece of plywood and skinned his right shin. The electrician went								
				to a City M.D. for assistance.								
2018	2	147-40			No Brook							
018	Queens	147-40	ARCHER AVENUE	0 1 The Site Safety Manager reported that a piece of plywood slid and hit a worker on the left knee while the	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
				worker was stocking plywood on the floor. The worker								
				went to a clinic.								
2018	Queens	28-07	JACKSON AVENUE	0 1 A DOB inspector reported that there were two	ECB Violation	35318121Y-FAIL TO SAFEGUARD	030818BS02KA01	NB	420656873	Material Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
				electricians working on a scissor lift at the basement								
				level when a temporary light fixture was accidentally								
				bumped and dislodged, causing it to fall approximately								
				five feet and strike a worker that was passing by on the								
				head and back. The electricians were working without a controlled access zone below. The worker was found								
				controlled access zone below. The worker was found alert, but complained of head pain and went to urgent								
				care. An ECB Violation for a failure to safeguard was								
				issued, as well as a partial Stop Work Order for the								
				installation of electrical lighting work. A Means and								
				Methods must be provided.								
018	Staten Island	546	GULF AVENUE	1 The Site Safety Manager reported that a worker slid and	No Dispatch					Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	
.010	Statemisiand	340	GOEI AVENOE	0 1 The Site Safety Manager reported that a worker slid and hit his left knee as he was taking the stairs to his trailer.	NO Dispatch					WORKELLER	STATEN ISEAND GEOBRE EUGISTIC	
				The worker was taken to a hospital for a check up.								
2018	Manhattan	1059	3 AVENUE	0 1 The Site Safety Manager reported that a worker was	ECB Violation	35300269P	030918BS08MH01			Material Fell	63RD & 3RD NYC LLC	
				carrying a few formwork clamps that weight approximately 10-15 pounds and are about 18 feet long								
				approximately 10-15 pounds and are about 18 feet long								
				in length up the third floor steps when one of the clamps								
				fell from his grip and hit the wrist of a mason that was working in the basement, possibly breaking the mason's								
				wrist. An ambulance was called. An ECB Violation and a								
				partial Stop Work Order were issued for the unsafe								
				handling of materials. A DOB Violation was also issued.								
				A Means and Methods will be provided for the safe								
				handling of form work materials.								
018	Manhattan	217	WEST 57 STREET	0 1 The Site Safety Manager reported that a worker as	ECB Violation	35286419N				Worker Fell	SMITELL SPONSOR LLC	
				carrying equipment when he slipped and fell. The worker								
				hit the back of his head and blacked out. The worker								
				was sent to Mount Sinai Hospital. A DOB inspector								
				responded and visited the site and reported that the								
				worker slid on what look like an ice patch on the floor,								
				even through there was ice melt spread throughout the are. An ECB Violation was issued for a failure to								
				maintain safe operations.								
				mantani sure operatione.								
					N. Brand							
2018	Manhattan	29	11 AVENUE	0 1 The Site Safety Manager reported that an iron worker was attempting to move a steel beam onto a dolly on his	NO Dispatch					Other Construction Related Incidents	NYS PARKS & RECREATION	
				was attempting to move a steel beam onto a dolly on his own when the beam slid and hit his left knee. 911 was								
				called and the worker was taken to a hospital.								
2018	Manhattan	701	7 AVENUE	0 1 The Site Safety Manager reports that a worker pinched	No Dispatch					Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	
				his finger while cutting a Formica board with a circular								
				saw. The worker went to the emergency room on his								
				own.								
/2018	Manhattan	500	WEST 33 STREET	0 1 The Site Safety Manager reported that an ironworker	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
				hurt his right index finger while prying a cross brace.								
				The worker was transported to Bellevue Hospital by								
				ambulance.								
/2018	Manhattan	125	GREENWICH STREET	0 1 A DOB inspector reported that a worker was lifting up a	No Action Necessary					Material Fell	VS 125 LLC	
				four foot section of form work when the worker								
				mishandled the form work, causing the form work to fall								
				on his knee. An ambulance was called. It was determined that the incident happened as a result of a								
				determined that the incident happened as a result of a worker error and that no enforcement action was								
				necessary.								
2018			GREENWICH STREET	-	N. Brand					W	VS 125 LLC	
U18	Manhattan	125	GREENWICH STREET	0 1 The Site Safety Manager reported that a worker was handling a roll of felt paper when he slipped backwards	NO Dispatch					Worker Fell	VS 125 LLC	
				handling a roll of feit paper when he slipped backwards and suffered a laceration to the left side of his forehead.								
				The worker did not want an ambulance to be called and								
				went to a City M.D. instead.								



naidant D	Bergunk	Address Mund	Chront	Established Internet	EOC Final Description	DOB Action	ECD Vielation Numbers	DOB Violation Numbers	Dormit	Permit No	Incident Type	Ownerie Neme	Contractor Name
cident Date 12/2018	Borough	Address Number	Street EAST HOUSTON STREET	Fatalities Injurie			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Other Construction Related Incidents	Owner's Name 255 EAST HOUSTON OWNER LLC	Contractor Name
2/2010	mainiaitáll	255	Chai Houston street	0	1 The Site Safety Manager reported that a worker's finger got caught between two beams while he was pushing forwards beams on a truck. The worker was sent to Bellevue Hospital.	NO DISPARCI					Galer Construction Related incidents	235 EAST HOUSTON OWNER LLC	
3/2018	Queens	150-13	89 AVENUE	1	pelievue nospital. O A DOB inspector reported that a worker was riding on the back of a fork iff during a placement of bundle windows in the storing garage. The bundle was 10 X 5' X 6' and bounced up and down due to its size and weight. The driver of the forkill heard a sound and then saw that the worker who was riding on the back was on the floor. The worker was bound dead. There were no witnesses to the incident, and the incident is currently under police investigation. The driver of the fork it was found to be not certified to operate a fork it mas found to be not certified to operate a fork it. The driver was in a traumatized state and were to a hospital. A DOB Violation for a failure to safeguard and a Stop Work Order were issued. ECB Violations are being	DOB Violation		031318BS1201MC			Other Construction Related Incidents	88TH AVENUE OWNER LLC	
/2018	Brooklyn	3617	13 AVENUE	0	prepared to be served. A DOB inspector reported that a worker lacenside his food while drive a served to a worker lacenside his food while drive the worker work to a contained an EGB Violation was issued, as well as a partial Stop Work Order on the use of the waik-behind saw.	ECB Violation	35318355R				Other Construction Related Incidents	37TH STREET HOLDINGS LLC	
4/2018	Manhattan	220	CENTRAL PARK SOUTH	0	Manufacturer specifications must be provided. 1 The Site Safety Manager reported that an iron worker pinched his index finger while unloading a cart of steel. The worker went to a clinic to receive stitches for his	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
15/2018	Brooklyn	225	4 AVENUE	0	Inger: The second secon	ECB Violation	355092B4H	031518CERDM01	NB	310086554	Material Fell	225 4TH AVENUE PROPERTY OWNER	TRM Construction
6/2018	Queens	21-30	44 DRIVE	0	¹ The Site Safety Manager reported that a piece of piyocot fail from the first foor to the calling due to the then fell ords a worker, hurting the worker's shoulder. This incident occurred on March 16, 2018, but the Department Of Building was not notified until March 19, 2018, because the Construction Superintendent claimed that he called the office on 216/2018 after 4:00 PM and that he called the office on 216/2018 after 4:00 PM and that he called the office on 216/2018 after 4:00 PM and that no one answered the phone. An ECB Violation was issued for a failure to safeguard for not securing materials during a weather advisory. A DOB Violation and a partial Stoy Work Order of all form work were also issued. A Means and Methods for the securing of materials during a weather advisory must be provided.		35318143P	031918BS02KA04			Material Fell	44TH DRIVE OWNER LLC	
/2018	Manhattan	501	WEST 18 STREET	0	A DOB inspector reported that during excavation work, a worker was torching a hole in two steel "IP piles and was laying able by side in order to sling and right pile when the excavator that was being used moved, which caused the worker's lay to become pinched between two piles. The Sile steely Manager stated that the worker was okay, as the suffered minor injuries to his less the steet of the sub-transfer that the steel of the partial Sile york. Other was asked to stop all movement and preparation of steel piles. The contractor is to provide a Means and Methods for the said movement of steel around the construction site.	ECB Violation	35314141N		New Building	121191147	Excavation/Soil Work	18TH HIGHLINE ASSOCIATES, L.L.	Related Construction LLC
5/2018	Manhattan	220	CENTRAL PARK SOUTH	0	The Site Safety Manager reported that a worker on the second floor was using a powered pallel jack to move bags of centre down a ramy when the powered pallel jack moved on its own and ran over the worker's lat toot. The worker went to Roosevel Hospital. A DOS impactor responde to the insident and issued an ECO ODE Videoten want is provided by Work Order for all work bage quipment to transport loads as the second terr oright of the Bold and the second terr powerd pallet jack was found to have no inspection logs. An orientation and a partial Strate sand Methods must be provided. The BEST Squad must be contacted for a re- inspection.		EOB#35318284L FAILURE TO MAINTAIN UNSAF	E 031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
16/2018	Brocklyn	416	KENT AVENUE	0	The Site Safety Manager reported that at a twenty-two story new building under construction, a worker that was on stills performing plastering work on the eightmenth back, suffered a twisted knee, and complained of head pain. An ambulance was called and the worker was transported to Bellevue Hospital. The worker was and alert.				NB	320622616	Worker Fell	420 KENT AVENUE LLC	ZDG, LLC



cident Date		Address Numbe		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
19/2018	Brooklyn	1277	EAST 14 STREET	0 1 A competent person at the construction site reported that a worker slipped on supported scriptiol and fell approximately six feet, along with a few planks. The worker's foreman stated that the worker drove to see a doctor on his own. A DOB inspector responded and did not contom to cose appendix status, as the scription was not huly plaked, the planks were not tied down, non a guard rail system was missing from multiple locations Two ECB Violatons and a partial Stop Work Order for a supported scription years.	1	35285912M,35285913Y		NB	320597127	Worker Fell	1277 HOLDINGS LLC	Ray Builders Inc.
9/2018	Manhattan	40	CLERMONT AVE	0 1 The Site Safety Manager reported that a carpenter was working on an "A"-Frame larder when he missed the	No Dispatch					Worker Fell		
				fifth step of the ladder and fell. An ambulance came and took the worker to a hospital.								
/2018	Manhattan	590	EAST 83 STREET	0 1 The Site Safety Manager reported that a worker tripped and jammed his finger. An ambulance took the worker t a hospital.	No Dispatch			NEW BUILDING	121190987-01-NB	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
0/2018	Brooklyn	10	MONTIETH STREET	0 1 The Site Super reported that a worker attempted to jum over a fence and fell. The worker was taken to a hospite by ambulance.	4			NEW BUILDING	320622750-01-NB	Worker Fell	BUSHWICK HOLDINGS I LLC	GALAXY DEVELOPERS LLC
/2018	Manhattan	108	EAST 89 STREET	0 1 The Site Safety Manage reported that a worker hurt his shoulder while installing a pipe scaffold. The worker went to a City M.D. to get checked.	No Dispatch			ALTERATION TYPE 1	122988623-01-AL	Worker Fell		E.W. HOWELL CO, LLC
20/2018	Queens	43-12	HUNTER STREET	0 1 A DOB inspector reported that contractors were in the process of lifting a section of steel casisson in order to set at on a dril reg when a worker had his hand pinched between the caisson and at sete hock. The worker was allert and awake and was taken to a nearby hospital by; taxi. The extent of the injury to the worker's hand was not known as of the time of inspection. An ECB Volabilio for a failure to safeguard and an a ECB Volabilio for the failure to safeguard and an a ECB Volabilio for the being no logs on site were issued, as well as a full Stop Work Order for the entire is. The contractor at the site was instructed to provide a Means and Methods for safe pile installation.	a	36314356z 36314356k		NB	420659530	Mechanical Construction Equipment	43-12 HUNTER LLC	Judy y Lee
2018	Bronx	2028	CRESTON AVENUE	0 1 The Site Safety Manager reported that at an eleven storp new building under construction, a worker was handling concrete out of a mixer when cement splasher into the worker's right year. The worker was eleft and awake and was taken to Lincoln Hospital for treatment.	No Dispatch			NB	220392858	Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MNGMT
/2018	Manhattan	650	5 AVENUE	0 1 The Site Safety Manager reported that a worker was working with temporary electrical wiring on the second floor when a 480-volt wire touched an Fleaem, which caused an ARC flash. The worker suffered an rigury to his eyes and was taken to a hospital. A DoB inspector determined that there was no enforcement acton necessary.	No Action Necessary			Electrical	M00016968	Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
2018	Brooklyn	1835	STERLING PLACE	0 1 The Construction Superintendent reported that a works sipped of of an "A-Frame ledder while coming down from the ledder. The worker suffered a minor lecention to the head. The worker was found conscious and an ambulance was called.	No Dispatch					Worker Fell	NOT ON FILE	
3/2018	Manhattan	115	DELANCY STREET	0 1 TThe Site Safety Manager reported that a worker was cleaning around a Con Edision vault when he lifted an unmarked piece of phyword that was covering the vault, feet. The worker suffered a cut to his ankle. The worker was alert and awake and was taken to Edienvie Hospital. An ECB Violation for a failure to safeouard we issued, as well as a DOB Violation and a partial Stop Work Order for all exterior work at the ground floor at exposure there. Protections around the vaults at the ground level must be provided. An updated Means and Methods and Tool Box Talk must be provided.		ECB#35317775Z -FAIL TO SAFEGUARD	032318BS03GD01	NB	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
3/2018	Manhattan	40	10 AVENUE	0 1 The Site Safety Manager reported that an electrician was climbing up the rebar cage to reach the electricial conduit when he slipped, fell two feet, and landed on his right ankle. The electrician was sent to a clinic.						Worker Fell	40-56 TENTH OWNER LLC	
/2018	Manhattan	1865	BROADWAY	0 1 The Site Safety Manager reported that a worker was cutting metal studies when he cut the top of his hard with a chop asw. The worker went to the emergency room with another worker. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
/2018	Brooklyn	19	INDIA STREET	0 1 The Site Safety Manager reported that a worker was moving windows when he tripped, fell three steps, and hit the back of his neck on a cinderblock. The worker was alert and responsive and was taken to Bellevue Hospital.	No Dispatch			NEW BUILDING	310234207-01-NB	Worker Fell	145 WEST STREET LLC	NOBLE CONSTRUCTION GR LLC
/2018	Brooklyn	101	PENNSYLVANIA AVENUE	1 The Construction Superintendent reported that a worker was testing a refrigerant line when the line burst, causing disconflort to the worker's ears. A co-worker drove the injured worker to a hospital.	No Dispatch			Alt 1	320622894	Other Construction Related Incidents	ATLANTIC 2644, LLC	CAULDWELL WINGATE CO LLC



ident Date	Borough	Address Number	r Street			DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	250	SOUTH STREET		1 A DOB inspector reported that a worker was bringing a scaffold down when a gust of wind moved the platform out of the building. The worker stuck his hand out to prevent the impact against the building, but hurt his shoulder and back in the process. The worker was taken to a hospital where he was in stable condition. It was determined that no enforcement action was necessary.				NB	121185528	Scaffold/Shed/Fence/Shoring/Installation		Lend Lease (US) Construct
					as the suspended scatfold was found to be in compliance with approed drawings, the current notification and installation letter from the engineer was onsite, and all logs were in order.								
018	Manhattan	420	EAST 54 STREET	0	1 The Site Safety Manager reported that the building owner's personal driver had his toot struck by a forkfit. The injured person was taken to a hospital. A DOB inspector reported that only one flag person was used when moving the forkfit and that the injured person walked into a controlled no access zone when he had his foot struck by the forkfit. An EGB Violation was issued for a failute to safeguard. A DOB Violation and a partial Stop Work Order were also issued A Maena and Methods and TOB Bor Talks will be provided by the General Contractor at the site for safe delivery operations and for the proper amount of flaggers.	ECB Violation	35317780N	032618BS66GD01			Other Construction Related Incidents	RIVER TOWER OWNER, LLC	
2018	Manhattan	432	EAST 14 STREET	0	1 The Construction Superintendent reported that a worker was pushing a mini container when she slipped and hit her knee. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	EAST 14TH STREET OWNERS LLC	
3/2018	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that a worker got his hand jammed between two stripping panels. A foreman took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
3/2018	Brooklyn	505	PACIFIC STREET	0	 The Site Safety Manager reported that a worker slipped with a grinder and cut his face. An ambulance transported the worker to a hospital. 	No Dispatch			NEW BUILDING	320909004-01-NB	Other Construction Related Incidents	PVII HSC ATLANTIC LLC	TRITON CONSTRUCTION CO.,
0/2018	Manhattan	265	WEST 114 STREET	0		ECB Violation	35286045H		Alt 1	121189668	Material Fell	TRINITY WEST HARLEM PHASE TWO	Mega Contracting Gp LLC
018	Queens	22-06	31 STREET	0	1 A competent person at the site reported that a worker that was coming into the site slipped on snow and injured his knee. The worker went to see his doctor for a check up. There was a snowstorm in progress as of the time of the incident.						Other Construction Related Incidents	DITMARS 31ST STREET ASSOCIATES	
018	Staten Island	2655	RICHMOND AVENUE	0	1 A DOB inspector reported that there were workers that were moving a wooden ramp that was about 4 X 8 X 207. When the ramp was in a vertical position, one 2 X 4 fell onto the hand of one of the workers. The worker went to urgent care. An ECB Violation and a partial Stop Work Order (PSWO) were issued for all use of ramps. A Means and Methods and the design drawing must be provided.		35327352X				Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
2018	Bronx	2681	MARION AVENUE	0	1 A DOB inspector reported that a flagger was signaling for deliveries for traffic on the street when a cab driver inicid to manevever around a convert the flagger's foot. The flagger went to a hospital with a co- worker in an ambulance. The inspector determined that there was no enforcement action necessary, as the flagger was certified and a delivery Means and Methods was at the site.	No Action Necessary					Other Construction Related Incidents	PCMH MARION AVENUE HOUSING DEV	
2018	Bronx	2760	BRIGGS AVENUE	0	1 The Site Safety Manager reported that a worker slipped on plywood that had snow on it. The worker claimed to have hun the suits while trying or borace himself after incident occurred in the morning, but the worker wated until the afternoon to report the incident and go to a doctor. A DOB inspector valied the site and reported that there was no sign of snow or any tripping hazrds in the area that the worker was working. A cause of the site could not be determined. Because of this, no enforcement action was deemed necessary.						Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker slipped on a wet surface and fell on his hand. The worker went to a City M.D.						Worker Fell	NYC HPD	
/2018	Brooklyn	422	FULTON STREET	0	 The Site Safety Manager reported that a security guard tripped and fell. The security guard was taken to a hospital as a precaution. 	No Dispatch			ALT 1	320908899	Other Construction Related Incidents	NOT ON FILE	TRANSPARENT CONSTRUCTION



NIM American Ameri American American Ameri American American Amer	Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
NUM Aussis Image: Second	4/4/2018	Brooklyn	5615	7 AVENUE	0	performed because a construction fence fell at the site. A DOB inspector responded and wiskel the site and reported that the job site funce at exposure one had collapsed onto the public sidewalk. There were two injuries reported, a mother and a daughter. The mother and daughter were both taken to an eas hospial. All made safe against the wind. An Aggravated Level 2 EGB Violation and a full Stop Work Order were also issued. This incident was reported under Incident Number 25737. Incident Number 25737 was deleted by accident, and Incident Number 25737 was deleted by		35323275N	040418CERCM02	Alteration 1	320516152	Other Construction Related Incidents	SIU PING.	GUO Z HUANG/NEWLAND CONSTRUCTION
with the second of the seco	4/4/2018	Manhattan	500	WEST 33 STREET	0	hit her tailbone while getting off of a scissor lift. An ambulance was called and transported the worker to a hospital. A DOB inspector visited the site and issued an ECB Violation and a partial Stop Work Order on all use of scissor lifts. The General Contractor is to provide		35327428N				Other Construction Related Incidents	NOT ON FILE	
Image: Control in the state in the state in the state in the state is a state in the	4/5/2018	Manhattan	4	WEST 37 STREET	0	found dead on the fourth floor of a framed out empty room. There were no tools and no ladder found on the scene. A DOB inspector responded to the incident and visited the site, and reported that the worker sulfered a possible heart attack and was revived with a faint pulse.						Other Construction Related Incidents	4 WEST 37TH STREET LLC	
Abelie Pair Pair Pair Constrained as a set of the pair of t	4/6/2018	Manhattan	125	GREENWICH STREET	0	himself in the face while stripping forms. The worker	No Dispatch			NEW BUILDING	121183799-01-NB	Other Construction Related Incidents	VS 125 LLC	PLAZA CONSTRUCTION LLC
Image: Second	4/9/2018	Brooklyn	231	ANSLE STREET	0	that was at the site, the owner of the construction company at the site was on a pipe scaffold inspecting brick work that was done when he lost his balance and tried to grab a bike nak on the rear of the scaffold. The bike rack was not properly secured and gave way, causing the owner to fall eight net from the pipe scaffol that was on top of the sidewalk shed dick. The owner was transported to an area hospital with serious injuries There was some debris found on the sidewalk shed may any strain the sidewalk and the sidewalk shed pipe strain the sidewalk shed dick. The owner there was some debris found on the sidewalk shed of the sidewalk shed the sidewalk shed all persons and property, for the supported scaffold on top of the shed not being matinized as per code, for work without permit being performed, and for brick exterior work that exceeded the rare that does not	d .t	35323246y	040913CERDF03 & 040918CERDF04			Worker Fell	ST OONO DE TEGGIANO C	
482018 Markatan 11 MEST 53 STREET 0 11 N Degach N Degach N Degach 12110183 Other Construction Related Hooders THE MUSEUM OF MODERN ART TUBRER CONSTRUCTION CO 4482018 Markatan 15 N EST 25 STREET 0 10 Object Construction Selected Hooders S522475H Object Construction Related Hooders THE MUSEUM OF MODERN ART TUBRER CONSTRUCTION CO 4482018 Markatan 15 N EST 25 STREET 0 0 S522475H Object Construction Related Hooders THE MUSEUM OF MODERN ART TUBRER CONSTRUCTION CO 4482018 Markatan 15 N EST 25 STREET 0 0 S522475H Object Construction Related Hooders THE MUSEUM OF MODERN ART TUBRER CONSTRUCTION CO 4482018 Markatan 15 N EST 25 STREET 0 0 S522475H Object Robit S522475H	4/9/2018	Brooklyn	420	KENT AVENUE	0	his finger while putting coupling on a pipe. 911 was called and the worker was taken to a hospital by	No Dispatch					Other Construction Related Incidents	420 KENT AVENUE LLC	
hole saw that jammed. The Construction Superintendent unuplaged that a loss what jammed. The Construction Superintendent of unuplaged that an injury. An ECB Violation, and base that here were no guardiais installed. hole saw that jammed. The Construction Superintendent of unuplaged that a hole starw was plugged back in the saw swarm garound and public the term is supported back. The construction Superintendent is now stable, but suffered a back injury. An ECB Violation, and base that here were no guardiais installed. Image: Construction Superintendent for term is supported back in the saw swarm garound and public the same swarm garound garound and public the same swarm garound and public the same swarm garound and public the same swarm garound gar	4/9/2018	Manhattan	11	WEST 53 STREET	0	1 The Construction Superintendent reported that a worker was on a scissor lift and was trying to gain access into a plenum. The worker's hand was on the handrail of the scissor lift and his hand got pinned between the handrai and the hanging door of the plenum. The worker's hand	1			ALTERATION-1	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	TURNER CONSTRUCTION CO
got the tip of his finger crushed while working on the	4/9/2018	Manhattan	15	WEST 25 STREET	0	hole saw that jammed. The Construction Superintendent unplugged the tool nad straightened it out. When the hole saw was plugged back in, the saw swung around and pushed the Construction Superintendent down, causing him to fall approximately eleven feet. The Construction Superintendent was taken to a hospital in serious condition. The Construction Superintendent is so with suffered a brain ingry. An ECB Violation, a DOB Violation, and a full Stop Work Order (FSWO) were issued for a failure to saleguard during construction operations, as the Construction Superintendent foil in a location where there were no	DOB Violation	35323475H	040918CERND01	ALTERATION TYPE 2	123203069-01-EW-OT	Worker Fell	ST SAVA CATHEDRAL	G.P.J. O'DONOGHUE CONTRAC
hoist when the nate came drawn. The worker was taken	4/9/2018	Manhattan	25	PARK ROW	0	1 The Site Safety Manager reported that a hoist installer got the tip of his finger crushed while working on the hoist when the gate came down. The worker was taken						Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	



ncident Date		Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/9/2018	Manhaitan	420	EAST 54 STREET	0	1 A DOB inspector reported that there were three workers working on the thirly sevent floor doing interior demolition work and removing debris. There was an approximate 27 X 27 opening in the floor that was not properly covered, as a door from the demolition work was used to cover the hole and the hole was not properly marked or secured. One of the workers picked up the door, unaware of the hole underneath it, and fell through the opening to the thirty sight floor. The worker was sent to a hospital for a checkup. Follow up information regarding the injured worker is not currently available. Two ECB Volations were issued for the failure to maintain safety measures and hor inadequate housekeeping. A full SNO WOR Order was also issued. The GC is to provide a Means and Methods for the safe operation of the job, including the protection of empty shafts and floor openings.		35317792K, 35317793M		ALTERATION 2	122938367	Worker Fell	RIVER TOWER OWNER, LLC	VECTOR BUILDING CORP
/9/2018	Queens	123-30	ROOSEVELT AVENUE	0	1 The Site Safety Manager reported that a worker tripped on a curb and twisted his ankle while carrying a panel.	No Dispatch					Other Construction Related Incidents	NYC PARKS	
/9/2018	Queens	147-40	ARCHER AVENUE	0	An ambulance was called. 1 The Site Safety Manager reported that a worker stepped on a tie-wire that was used for rebar work and the tie- wire punctured his boot and foot. The worker went to see a detor on his own	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/10/2018	Manhattan	150	5 AVENUE	0	see a doctor on his own. 1 The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taker to a hospital by an ambulance.	No Dispatch			ALTERATION TYPE 1	122700292-01-AL	Worker Fell	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
1/11/2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that a worker was on a six foot ladder when he missed the second rung of the ladder while coming down from it and fell backwards and hit his head. The worker went to a hospital with his shop steward.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
/11/2018	Queens	147-40	ARCHER AVENUE	0	snop stewaro. 1 The Site Safety Manager reported that a worker was stripping form work when a dust particle got between his safety glasses and irritated his eye. The worker went to a nearby City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/12/2018	Bronx	600	BERGEN AVENUE	0	a rearry Cuy III.2 The Site Safety Manager reported that a worker was pumping grout to tie backs when the hose clarges to clean the hose, the worker opend up the hose clarges to clean the hose, the worker got grout in his eyes. The worker did not realize that pressure had built up when he removed the hose clamps. The worker was taken to a City M.D. and was then transferred to an emergency room at Lincoln Hospital.	ECB Violation	35314470y		NB	220151868	Mechanical Construction Equipment	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST.DEVELP.
12/2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker was walking on the second floor when he stepped on a nail. The worker went to get a tetanus shot.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/12/2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manger reported that a worker twisted his knee while climbing down from a machine. The worker was driven to the emergency room.	No Dispatch			NEW BUILDING	520135675-01-NB	Worker Fell	MACY'S RETAIL HOLDINGS, INC.	AURORA CONTRACTORS INC
/13/2018	Bronx	2044	WESTCHESTER AVENUE	0	1 The Project Manager at the site reported that a masonry worker was laying cinderblocks when he fell off a supported scatfold that was approximately three feet in height. The worker landed on his back and appeared to be in stable condition, but relaxed to task to anyone until Medical Center, A DOB Inspector responded and visible the site and determined that no enforcement action was necessary, as the supported scatfold was found to be structurally sound with a guard rail system in place.	,	NA		NB	220152572	Worker Fell	HP WESTCHESTER MEWS HOUSING DE	Procida Construction Corp
13/2018	Manhattan	20	BROAD STREET	0	1 The Site Safety Manager reported that a worker was pushing a mini-container through a wall opening when he pinched his pinky finger. The worker left the site to see a doctor for treatment.	No Dispatch					Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.	
	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was cutting boxes with a box cutter when he cut his left thumb. The worker walked to urgent care.	No Dispatch			ALTERATION TYPE 1	121324343-01-AL	Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	
4/14/2018	Brooklyn	50	COURT STREET	0	3 DOR's Emergency Response Team was informed that is sidewalk sheaf was in the process of being dismantled when a partial collapse occurred at the corner of Court Street and Joankernon Street, Approximately twenty linear feet of the sidewalk shed collapsed. Two pedestrians and one worker suffered non-file threatening injuries and were sent to Lutheran Hospital. The remaining unafficidal parts of the sidewalk shed replaced the cross wak light at the site. An Apgravated Lavel 2 ECB Violation was issued for a failure to safeguard all persons and property affected by construction operations. A DOB Violation was also issued.	ECB Violation	35323276P	041418CERCM01	An 3 - SH	321426774	Scaffold/Shed/Fence/Shoring/Installation	50 COURT STREET ASSOCIATES	NEW FORCE CONSTRUCTION CO
4/17/2018	Manhattan	130	EAST 82 STREET	0	1 The Site Safety Manager reported that a worker accidentally ran a screw into his hand while screwing screws during duct work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	134 EAST 82 LLC	
/17/2018	Brooklyn	856	WASHINGTON AVENUE	0	1 The Site Safety Manager reported that a worker was drilling a core hole in a deck slab when the drill kicked back and the base of the drill hit him on the side of his	No Dispatch					Other Construction Related Incidents	856 WASHINGTON OWNER LLC	



cident Date	Basavak	Address Numbe	. Chungh	Fatalitian Iniurian	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
17/2018	Brooklyn	63	FLUSHING AVENUE	ratainties injuries	1 The Site Safety Manager reported that a worker slipped		ECB Violation Numbers	DOB Violation Numbers	Fernit	Permit No	Other Construction Related Incidents	NYC DSBS	Contractor Name
	cionyi				while going down the stairs. There were no witnesses to the worker slipping, and the stairs were free of debris. An ambulance was called. The worker was okay, but	no oropatori							
					walked to the ambulance when the ambulance arrived at the site and went to a hospital.								
17/2018	Brooklyn	1900	PARK PLACE	0	 The Site Safety Manager reported that a worker strained his lower back while picking up a cement block. An ambulance was called. 	No Dispatch					Other Construction Related Incidents	HABITAT FOR HUMANITY LATENT TH	
18/2018	Brocklyn	25	EAST 19 STREET	0	1 The Site Safety Manager reported that a worker was passing an Heam down from a diskwalk shad when he lost his footing and fell about sixteen feet to the ground. The worker was wearing a harmess that as not attached to anything. The worker was found awake and speaking and was taken to a hospital. An CE Violation was issued for a failure to safeguard persons and property.		35323790H		Alt	340452520	Worker Fell	EBE HOLDING LLC	CS Bridge Corp
18/2018	Manhattan	220	CENTRAL PARK SOUTH	0	The Site Safety Manager reported that a worker cut his finger when another worker closed a door on his hand by accident. A co-worker took the injured worker to a hosnital	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
18/2018	Queens	71-17	ROOSEVELT AVENUE	0		No Dispatch					Other Construction Related Incidents	ROOSEVELT PARC LLC	
18/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker hurt his shoulder when he picked up a bundle of threaded rods. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
19/2018	Queens	147-40	ARCHER AVENUE	0	 The Site Safety Manager reported that a worker was conducting a survey and was wearing proper footwear when he stepped onto a nail that punctured his foot. The worker went to urgent care for a tetanus shot. 						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
19/2018	Manhattan	70	VESTRY STREET	0	1 The Site Safety Manager reported that a worker was installing 3' X 6" stone at the base of a building when his knee gave out, causing the worker to fall onto his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	BRIDGE LAND VESTRY LLC	
19/2018	Manhattan	112	WEST 25 STREET	0	1 The Site Safety Manager reported that a subcontractor was carrying a door from a truck when the door fell and leaned on the subcontractor's right knee. The worker did not suffer a visible injury, but was in pain. An ambulance transported the worker to a hospital for a check up.				NEW BUILDING	121187214	Material Fell	LAM GEN 25 LLC	FLINTLOCK CONSTR SVCS INC
19/2018	Brooklyn	422	FULTON STREET	0	 The Site Safety Manager reported that a worker was performing demolition work on the roof of a building when he felt pain in his back while lifting a barrel. An ambulance was called. 	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
19/2018	Bronx	545	EAST 196 STREET	1	0 The New York City Police Department reported that a worker was hit by a hoit. A worker was on the eighth floor securing a piece of wingwall when he steeped up onto a bucket to look over the gate while trying to securing plywood. The hoist was on the floor above the worker and the hoist came down at the same time that the worker was learning over the gate. The worker was struck in the head and succumbed to his injuries. An Aggravated Level 2 ECB Violation was issued for the unsale or improper use of hoist equipment.	ECB Violation	38259262J	042018E2607B01			Mechanical Construction Equipment	545 E. 166TH STREET HDFC	
20/2018	Manhattan	45	PARK PLACE	0	1 The Site Safety Manager reported that a carpenter foreman was securing a formwork panel for the shear wall and was repositioning his retractable device with both hocks in one anchor point when the insert gave way, causing the foreman to fail about ten feet backwards. The foreman nas taken to a hospital.	ECB Violation	35326676H		NEW BUILDING	121185635	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
20/2018	Manhattan	560	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was climbing up a baker's scaffold when he load his grip on the socker of the safety of the safety of the safety of the The worker offed over onto a baket and suffered an niguy to his ribs. A DOB inspector responded and wilden the site and reported that no enforcement action was necessary, as the necessary safety measures were provided at the site. It was determined that the incident occurred due to a worker's error.	No Action Necessary			NB	1211192618	Worker Feil	ERY NORTH TOWER RHC TENANT LLC	Roger & Sons Conctrete Inc
	Manhattan	400	WEST 61 STREET	0	1 The Site Safety Manager reported that at a thrity eight story new building under construction, a plumber was placing a pipe into hangers when the plumber fell off of a ladder. There were no witnesses to the height of the all, and the plumber claimed to have failen approximately between five and seven feet. The plan in his his, The plumber was taken to St. Luke's Hospital by ambulance. A DOB inspector responded and visited the site and determined that there was no enforcement action necessary, as the fall occurred as the result of a worker's error.				121193181	NB	Worker Fell	RCB1 NOMINEE LLC	TISHMAN CONSTRUCTION CORP
	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker on the first floor bumped his knee on a reshore tripod. The worker went to a City M.D.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
24/2018	Brooklyn	540	FULTON STREET	0	 The Site Safety Manager reported that an iron worker pinched his finger while unloading steel rebar from a truck. The worker left to go to a clinic. 	No Dispatch	Page 16 of 4	7			Other Construction Related Incidents	540 FULTON ASSOCIATES	



ident Date	Borough	Address Number	Street	Fatalities Injur	ies EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/2018	Manhattan	461	WEST 34 STREET	0	1 The Site Safety Manager reported that a worker was on the twenty eighth floor of a twenty nine story new building and was cutting sheetrock and metal stud for electrical work when he suffered a cut to his hand. A reciprocal Bade jammed and the worker's hand got caught. The worker was found awake and alert and was taken to a nearby hospital.	No Dispatch			NB	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	ATRIA BUILDERS LLC
5/2018	Manhattan	225	BOWERY	0	1 It was reported that there were workers that were moving materials on the roof. When the workers moved	No Dispatch				121862751	Worker Fell	VNAA BOWERY LLC	AEH-VSLV, LLC
					a metal piece together, one of the worker's right hand got caught in the pinch point. The worker suffered a scrape to his right hand. An ambulance was called to the site. The worker received stitches at Mount Sinai Hospital.								
2018	Manhattan	22	NORTH LOOP ROAD	0	1 The Site Safety Manager reported that a worker hit his left hand with a hammer. The worker went to urgent car	No Dispatch a.					Other Construction Related Incidents		
2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that at a fifty seven story building that was under construction, a worker was cutting metal with a grinder when he cut his left shin. The worker was conscious and alert and walked to New York Presbyterian Hospital.	No Dispatch				121290085	Other Construction Related Incidents	NOT ON FILE	AHEARN-HOLTZMAN, INC
2018	Manhattan	1681	3 AVENUE	0	The Site Safety Manager reported that a worker was coming down the stairs on a scaffold when he slid dowr the stair riser. The worker went to a City M.D.	No Dispatch					Worker Fell	95TH AND THIRD LLC	
/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that during concrete operations, a laborer was removing concrete key when his finger got scratched between rebar. The worker was working alone and scratched his finger while reaching into formwork. The worker went to a City M.D. and returned to work in two days.				NB	321197478	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker struck his left thumb with a hammer while hammering a nail. The worker took himself to a City M.D.	No Dispatch				_	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a worke was shaking out steel at the street level when he pinched his finger between a two by four and a steel beam. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	THE SALVATION ARMY	
2018	Manhattan	1059	3 AVENUE	0	1 The Site Salety Manager reported that a pedestrian went over a ramp in front of the site, slipped/tripped on pilipury to her lie above and west taken to a hooptal. A DOB respector reported and visited the site and reported that the General Contractor at the site failed to maintain the pedestrian valiway that caused the incident. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued on all activities in the occupied lane next to the sidewalk to ensure that it is free of all tripping hazards.	ECB Violation	25318046N				Other Construction Related Incidents	69RD & 3RD NYC LLC	
2018	Manhattan	130	WILLIAM STREET	0	1 The Bia Safety Manager reported that a worker was attempting to help a sagnetized when the accidentially walked into the sweig radius of a harmore and goth tin the forehead by the harm. The worker was taken to New York Presbytenian Hospital and was in stable condition. ADB inspector responded and visited the site and determined that no enforcement action was necessary, as the incident occurred as a result of a worker's error.	No Action Necessary			NB	121192903	Other Construction Related Incidents		GILBANE RESIDENTIAL CONST
V2018	Manhattan	425	PARK AVENUE	0	1 A DOB inspector reported that measure were finishing concrete pouring pads on the sixteenth floor when a floor protection and feel apportunity by the file of the floor protection and feel apportunity thirteen feel from the sixteenth floor to the filterand the filterand the filterand neck pain. The worker was taken to Comell University Hospital for observation. Two CED Violations were issued for there being no design drawings for floor openings present and for the failure to maintain safety operations. Two partial Stop Work Orders (FSWO) were issued on all work within the field all floor coverings of all floors and for the floor covering being not properly secured. Two DGB Violations were also issued. A Means and Methods for the installation of floor coverings must be provided.	a	35326636N / 37P	043018BS05GD01/02			Worker Fell	T-C 425 PARK AVENUE, LLC	
2018	Manhattan	540	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker suffere	d No Dispatch			NEW BUILDING	121191968-01-NB	Other Construction Related Incidents	CLINTON HOUSING DEVELOPMENT	MEGA CONTRACTING GP LLC
2018	Manhattan	390	MADISON AVENUE	0	a cut finger. An ambulance was called. The Site Safety Manager reported that a worker on the first floor stepped up on a few concrete masonry unit blocks when he fiell approximately three feet off of the blocks and landed on a metal plate. EMS was called and transported the worker to a hospital. 	No Dispatch					Worker Fell	COMPTROLLER OF NY STATE	
2018	Manhattan	222	EAST 41 STREET	0	1 The Site Safety Manager reported that a worker was installing metal trim when a cut piece fell down and lacerated his wrist. The worker was sent to a hospital.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	



2/2018	Borough	Address Number	Street	Fatalities	Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Brooklyn	1277	EAST 14 STREET	0	1 The Construction Superintendent reported that a plumber was cutting a metal stud to get to a pipe whe	No Dispatch					Other Construction Related Incidents	1277 HOLDINGS LLC	
					plumber was cutting a metal stud to get to a pipe whe he cut his arm on the stud. An ambulance was called.								
18	Brooklyn	63	FLUSHING AVENUE	0	 The Site Safety Manager reported that a worker was walking back from a coffee truck when he trpped, fell, 	No Action Necessary			NB	321190563	Other Construction Related Incidents	NYC DSBS	GILBANE BUILDING COMPANY
					and hit his head. The worker was found conscious and								
					alert. An ambulance was called. A DOB inspector								
					responded to the incident and visited the site and four no evidence of debris or tripping hazards, as well as n	d							
					violating conditions. No enforcement action was								
					necessary.								
018	Manhattan	10	VANDERBILT AVENUE	0	1 The Site Safety Manager reported that a latherer was coming down from a rebar cage when he missed his I	No Action Necessary					Worker Fell	ONE VANDERBILT OWNER LLC	
					step, fell backwards, and hurt his ankle. The worker	ist							
					went to a hospital by ambulance. It was reported that	he							
					worker suffered a broken ankle. A DOB inspector responded and visited the site and reported that the								
					worker misstepped during a rebar operation, and that								
					the operation was proceeding according to the site pla No enforcement action was deemed necessary.	n.							
					No enforcement action was deemed necessary.								
018	Manhattan	320	EAST 43 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	FORD FOUNDATION	
					cleaning near the dumpster in the basement C-Level area when he hit his lower leg on a dumpster. The								
					worker was cut, but the bleeding was stopped. The								
					worker does not know how he hurt himself. An ambulance was called								
018	Brooklyn	10	HURON STREET		1 The Site Safety Manager reported that a worker cut th	N. Discussion					Other Construction Related Incidents	10 HURON FS CONDO LLC	
10	DIOONIYI	10	INNON STREET	0	skin of his finger on a table saw. The worker went to a	e no Dispatori					Curer Construction Related incidents	IO HORON PO CONDO LEC	
		546			hospital with a co-worker.							STATEN ISLAND GLOBAL LOGISTIC	
018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker got a spark in his eye under his safety glasses during a						Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
					grinding operation. The worker went to a hospital on h	is							
018	Queens	36-18	MAIN STREET	0	own. 1 The Site Safety Manager reported that a worker was	No Dispatch					Worker Fell	134-22 35TH AVE., LLC	
010	queens	0010	and officer	Ŭ	coming down off of a ladder when he lost his balance							104 22 00111112., 220	
					and grabbed onto a metal stud, causing a cut to two on his fingers. The worker went to urgent care.	F							
018	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that a worker sliper on rebar and hurt his wrist. The worker went to a City	No Dispatch					Other Construction Related Incidents	40-56 TENTH OWNER LLC	
					on rebar and hurt his wrist. The worker went to a City M.D.								
018	Manhattan	308	WEST 133 STREET	0	1 The Site Safety Manager reported that a worker was	ECB Violation	35323933X, 35323934H		NB	122620333	Worker Fell	308 WEST 133RD STREET LLC	Happy Living Development
					caulking a window when he fell from a baker scaffold								
					and hurt his left leg. The worker was taken to a hospit A DOB inspector responded and visited the site and	а.							
					reported that the worker was not tied off when he fell.								
					Two ECB Violations were issued for a failure to safeguard and for a failure to provide a four hour user								
					training card. A partial Stop Work Order was issued or	1							
					baker scaffolds until a Means and Methods is provide	i.							
018	Brooklyn	810	FULTON STREET		2 The Site Safety Manager reported that two workers w	TCD Vieleties	35323694H,35323695J		ND	320597083	Worker Fell	GREENPOINT-GOLDMAN CORP.	Bradway Construction
018	Brookiyn	810	FULTON STREET	0	trying to install a pipe on top of a baker scaffold when		35323694H,35323695J		NB	320597083	vvorker Fell	GREENPOINT-GOLDMAN CORP.	Bradway Construction
					both of the workers leaned towards the same side of t	ne							
					scaffolding, which caused the baker scaffold to collap The two workers fell approximately four feet and lande	d							
					on the floor. An ambulance was called. A DOB inspec	tor							
					responded and visited the site. Two ECB Violations were issued: one violation for there being no personne								
					on site with proper documentation, which would be for	n Ir							
					hour user cards, and a second ECB Violation for a								
					failure to safeguard all persons and property affected construction operation. A partial Stop Work Order has	by .							
					been issued on baker scaffolds until a Means and								
					Methods is provided.								
018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker was	ECB Violation	35318496K	050418BS02JJ01			Material Fell	NYC DSBS	
				Ū	unloading a pallet of glass that was approximately 2' >	8'							
					when the pallet of glass tiped over onto him and pinne him against the wall of the truck. The worker went to a	d							
					hospital by ambulance. A DOB inspector responded a	nd							
					visited the site and issued an Aggravated Level 2 EC	3							
					Violation for a failure to safeguard, as there was no Means and Methods for delivery operations available	or							
					the previous delivery operations that happened at the								
					site. A partial Stop Work Order was issued on all deliveries. A Means and Methods for safe delivery								
					operations and Tool Box Talks must be provided.								
						d No Dispotch					Other Construction Related Incidents	NYC HPD	
119	Brocklan	120	WILLOUGHRY STREET		1 The Site Safety Manager reported that a well-						Surier Construction Related incidents		
18	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker slippe on rebar and cut his right thumb. The worker walked to								
				0	on rebar and cut his right thumb. The worker walked to the ER.				55	00045	Market and Table		
	Brooklyn Bronx	138	WILLOUGHBY STREET BERGEN AVENUE	0	on rebar and cut his right thumb. The worker walked to the ER. 1 The Site Safety Manager reported that a welder was performing Support Of Excavation (SOE) work when h	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & development
2018				0	on rebar and cut his right thumb. The worker walked to the ER. 1 The Site Safety Manager reported that a welder was performing Support Of Excavation (SOE) work when h picked up a steel plate that was 12 x 12 and 38 thid	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & developme
				0	on rebar and cut his right thumb. The worker walked the ER. 1 The Site Safety Manager reported that a welder was performing Support Of Excavation (SOE) work when the picked up a steel plate that was 12 X 12 and 38 thick when he injured his back. A co-worker took the worke	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & developme
				0	on rebar and cut his right thumb. The worker walked the ER. 1 The Site Sately Manager reported that a welder was performing Support OF Exavation (SOE) work when 1 picked up a steel plate that was 12 X 12 and 38 thick when he injured his back. A co-worker took the worke to a City M.D., where a physician recommended medication for pain and res for three days. A DOB	No Action Necessary			FO	220151868	Worker Feil	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & developme
				0	on rebar and cut his right thumb. The worker waked to the ER. 1 The Site Safety Manager reported that a welder was performing Support Of Excavation (SGC) work when picked up a steel plate that was 12 X 12 and 38 third when he nijured his back. A co-worker took the worke to a City MD, where a physician recommended medication for pain and rest for three days. A DOB inspector responded to the incident and visited the sit	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & developm
				0	on rebar and cut his right thumb. The worker waked to the E.R. 1 The Site Safety Manager reported that a welfer was performing Support OF Execution (SOE) work when 1 picked up a steel plate that was 12 X 12 and 38 thus when he injuried his back. A co-worker took the worker to a City M.D., where a physician recommended medication for pain and rest for three days. A DOB inspector responded to the incident and visited the ail and reported that there were no unsafe conditions to	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & developm
				0	on rebar and cut his right thumb. The worker waked the ER. 1 The Site Safety Manager reported that a wedler was performing Support OF Execution (SOE) work when 1 picked up a steej plate that was 12 X 12 and 38 thick when he injuriser his back. A co-worker took the worker to a City MD, where a physician recommended medication for pain and rest for three days. A DOB inspector responded to the incident and visited the ail and reported that three were no unsafe conditions fou and that all of the workers at the site had ten hour OSHA cards. No enforcement action was deemed	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & developm
				0	on rebar and cut his right thumb. The worker waked t the ER. 1 The Site Satety Manager reported that a welfer was performing Support Of Exavation (SOE) work when 1 picked up a steel plate that was 12 X 12 and 38 thus the a City M.D., where a physician recommended to a City M.D., where a physician recommended in a City and the set of the set of the set of the interpret of the set of the set of the set of the set of the and reported that three were no unsafe conditions for and that of the workers at the set had then hour	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Construction & developm



cident Date	Borough	Address Numb		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Brooklyn	2085	ROCKAWAY PARKWAY	0	1 The Construction Superintendent reported that a worker	No Dispatch			ALTERATION TYPE 3	340451308-01-EQ-SH	Worker Fell	NYC HOUSING AUTHORITY	SKYWORX CONTRACTING INC
					from the sidewalk shed company fell four feet while descencing from a baker scaffold. An ambulance took								
3			BEDFORD AVENUE		the worker to a hospital.	ECB Violation	35327578Z					814 PARK LLC	
	Brooklyn	814	BEDFORD AVENUE	0	1 The New York City Emergency Management Department and the New York City Fire Department	ECB Violation	35327578Z				Worker Fell	814 PARK LLC	
					reported that a worker was stripping concrete form work								
					for the first floor deck when the worker fell approximately								
					fifteen feet into the cellar and landed on capped rebar.								
					The worker was taken to a hospital and was accompanied by another worker. The injured worker did								
					accompanied by another worker. The injured worker did not suffer any life-threatening injuries. An ECB Violation								
					for the failure to maintain safe operations was issued. A								
					full Stop Work Order (FSWO) was also issued.								
					Additional safety violations will be issued.								
в	Queens	24-02	49 AVENUE	0	1 The Site Safety Manager reported that a worker at the	ECB Violation	35326893Y	050718BS02DH01	ALT1	421518566	Worker Fell	LIC 73 OWNER, LLC	UNITY CONSTRUCTION GROUP
					fourth floor level was struck by duct work that was approximately ten feet high while on a ladder that was								
					approximately left leet high. The duct work had came								
					loose, swung down, and struck the worker, which								
					caused him to fall off of the ladder. The worker suffered								
					a broken leg and was taken to a nearby hospital. A DOB inspector responded and visited the site and issued an								
					ECB Violation for a failure to safeguard. A DOB								
					Violation and a full Stop Work Order (FSWO) were also								
					issued.								
3	Manhattan	250	BRADHURST AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch				_	Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
					finger on a table saw while cutting zinc clips for a façade								
					connection. The worker went to a hospital by ambulance to receive stitches on his finger.								
3	Brooklyn	535	4 AVENUE		1 The Site Safety Manager reported that a hoist mechanic	No Dispatch					Other Construction Related Incidents	XYZ PROPERTIES INC	
~	Diooniyi	355	A AVENUE	U U	lacerated his finger while cutting a piece of plastic away	no Dispatori					outor construction related incluents	ATE I NOT ENTIES ING	
					from a hoist. A co-worker took him to a hospital.								
8	Brooklyn	11	HOYT STREET	0	1 The Site Safety Manager reported that a worker was working on a rebar wall when he was struck in the neck	ECB Violation	35331175X				Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	
					working on a rebar wall when he was struck in the neck by dislodged shoring. A DOB inspector responded and								
					visited the site and reported that reshores were installed								
					contrary to the approved plan. An ECB Violation and a								
					partial Stop Work order (PSWO) on all concrete work were issued.								
8	Manhattan	115	DELANCEY STREET	0	1 The Site Safety Manager reported that at a twenty six	No Dispatch			NB	121191646	Other Construction Related Incidents		T.G. NICKEL & ASSOCIATES
					story new building under construction, a worker was coming back on site when he stepped on loose concrete								
					coming back on site when he stepped on loose concrete masonry and turned his ankle. The worker was found								
					alert and awake. The on-site medic issued ice for on-								
					site treatment and the worker went to a nearby urgent								
					care center to receive further treatment.								
18	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager reported that a worker jammed	No Dispatch			NEW BUILDING	121333440-01-NB	Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	RNC INDUSTRIES LLC
					his finger while drilling into concrete. The worker walked to the emergency room.								
18	Manhattan	560	WEST 33 STREET	0	1 The Site Safety Manager reported that an electrician	No Dispatch					Other Construction Related Incidents	ERY NORTH TOWER RHC TENANT LLC	
					was walking down stairs when he hurt his ankle on permanent stairs. An ambulance was called.								
018	Queens	54-17	101 STREET	0	2 New York City Emergency Management reported that	ECB Violation	35313352Z 35313353K				Other Construction Related Incidents	HANAC CORONA HOUSING DEV. FUND	
10	decino	0411	ior officer		two workers that were working on wires on the bulkhead	LOD HOLDON							
					when they experienced electric shocks. The workers								
					were able to make it down from the bulkhead and were transported to a hospital. A DOB inspector responded to								
					the incident and visited the site and issued two ECB								
					Violations for the equipment ground not being provided								
					and for the exposed wires at the bulkhead area not being properly terminated, secure, and protected around								
					the HVAC air handler unit. A partial Stop Work Order								
					(PSWO) was also issued for electrical work.								
18	Manhattan	80	EAST10 STREET	0	1 The Site Safety Coordinator reported that a worker was	No Action Necessary			NB	121193476	Other Construction Related Incidents		CCNY CONSTRUCTION INC
					moving pallets of concrete block around when some of								
					the concrete block fell off and struck the worker's right leg. An ambulance was called and the worker went to a								
					hospital for treatment. A DOB inspector responded and								
					visited the site and reported that the worker pulled the								
					stationary part of the pallet jack while pulling the								
					concrete block onto himself. It was determined that this incident occurred as the result of a worker's error, and								
					that no enforcement action was necessary.								
)18	Manhattan	7	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker felt	No Dispatch					Other Construction Related Incidents	7 WEST 57TH STREET REALTY COMP	
					discomfort in his shoulder during stripping operations. The worker took a cab to a clinic on his own.								
18	Manhattan	515	WEST 36 STREET	0	1 The Site Safety Manager reported that a worker was	ECB Violation	35331118J			_	Other Construction Related Incidents	FIRST ST MARKS LLC	
		515	TEOL OF OTHEET		pushing a cart when he tripped on planks that were	_ SE TRADUM					Construction related incluents		
					covering a hole. The worker suffered a cut to his right								
					hand and went to a hospital. A DOB inspector								
					reconnected to the incident and visited the site and incured								
					responded to the incident and visited the site and issued an ECB Violation for the improper covering of holes.								



Incident Date		Address Numbe		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/10/2018	Manhattan	424	EAST 34 STREET	U	1 The Site Safety Manager reported that a tapper tried to move an "A"-Frame with masonite on it out of his way by	No Dispatch					Other Construction Related Incidents	NYU HOSPITALS CENTER	
					himself when he tipped the "A"-Frame and was hit in the								
					right shin by both the "A"-Frame and the masonite. An								
					ambulance was called.								
/10/2018	Brooklyn	0	NEVINS STREET	0	1 The Site Safety Manager repoted that a worker was	CCD Vieleties	35326856P	051018BS02JJ01			Material Fell	NEVINS STREET OWNER LLC	
5/10/2018	Bioukiyn	8	NEVING STREET	U	stripping form work on the eighteenth floor when a post	ECB VIOlation	33326636F	05101883023301			Material Pell	NEVINS STREET OWNER LLC	
					fell forward and hit him in the back. The worker								
					experienced back pain and an ambulance was called. A								
					DOB inspector responded and visited the site and reported that another worker had leaned a stripping post								
					against a wall instead of stacking the post and the post								
					slid from an upright position and hit the injured worker.								
					An ECB Violation was isued for a failure to institute/follow safety measures for stripping operations.								
					A DOB Violation was also issued.								
5/10/2018	Bronx	1410	STORY AVENUE	0	1 A DOB inspector reported that a worker was sitting on	CCD Vieleties	35327286R 35327285P	051018BS09VP01,02			Worker Fell	BR-2012 REALTY LLC	
5/10/2018	BIOIX	1410	STORTAVENDE	U	top of a beam setting joists on the second floor of a new	ECB VIOlation	3332/200R 3532/200P	05101883097F01,02			WORKER PER	BR-2012 REALTY LLC	
					building. He was setting joists and had just landed a joist								
					when the signal man signalled to the crane operator to hoist up with steel chokers (no load) on the hook. While								
					hoisting up, one of the chokers snagged the joist and								
					picked it up. The worker who had landed the joist tried to	d							
					get out of the way from the joist, but lost his balance and								
					fell two stories to the ground. The worker was not tied								
					off. Other workers at the site reported that the injured worker was bleeding from the mouth and was								
					experiencing severe pain in his legs, but was conscious.								
					The worker was taken to Lincoln Hospital by ambulance.								
					The Hoist Machine Operator (H.M.O.) at the site stated								
					that he was standing next to the crane operator's cab as of the time of the incident and was given the okay to								
					hoist up via radio. The lift director's logs were filled out								
					and were on site. However, the lift director was not on								
					site as of the time of inspection, because he had gone to the hospital with the injured worker. Two ECB								
					Violations for a failure to safeguard were issued to the								
					General Contractor and the crane operator. A full Stop								
					Work Order (FSWO) was issued or there being no								
					Construction Superintendent on site as of the time of inspection, as well as a partial Stop Work Order								
					(PSWO) for the unsafe placement of steel members/roof								
					joists. A designated Construction Superintendent on a								
					PW2 application form and a Means and Methods for the								
					safe operations of steel placement must be provided.								
5/11/2018	Staten Island	2655	RICHMOND AVENUE			No. Brianda					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
5/11/2018	Staten Island	2655	RICHMOND AVENUE	U	1 The Site Safety Manager reported that a worker cut his right thumb while installing duct work. The worker went	No Dispatch					Other Construction Related incidents	MACY'S RETAIL HOLDINGS, INC.	
					to urgent care. An ambulance was not called.								
5/11/2018	Manhattan	553	WEST 30 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
					using a grinder and suffered a cut to his right leg when								
					the grinder kicked back. The worker was taken to a hospital by an ambulance.								
5/11/2018	Manbattan	425	PARK AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
3/11/2010	Walifatali	425	ANTAVENDE	0	finger while using a band saw and suffered a minor gash	No Dispatch					Other Construction Related Incidents	1-0 423 FARRAVENDE, EEC	
					to his finger. An ambulance was called.								
5/11/2018	Manhattan	357	EAST 57 STREET	0	1 A DOB inspector reported that façade work was	ECB Violation	35245543J	051118CERJM01	ALTERATION TYPE 2	123179951-01-EW-OT	Material Fell	357 EAST 57 STREET CONDOMINIUM	EDRAS GROUP CORP
					underway at exposure floor on the sixteenth floor when a section of brick veneer dislodged and fell onto the								
					sidewalk shed. A pedestrian at the street level suffered								
					a minor injury, but refused medical attention. Th								
					company that erected the sidewalk shed was onsite to								
					repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard.								
					A DOB Violation was also issued. A full Stop Work								
					Order (FSWO) was also issued.								
5/11/2018	Manhattan	305	WEST END AVENUE	0	1 The Construction Superintendent reported that an	ECB Violation	35331190Y				Material Fell	305 WEST END PROPERTY, LLC	
		000		Ŭ	electrician was working on the emergency lighting of the								
					seventh floor permanent stairs when he was hit in the								
					head from a tape measure that fell from above. The electrician was taken to a hospital. A DOB inspector								
					electrician was taken to a hospital. A DOB inspector responded and visited the site and issued an ECB								
					Violation for the failure to maintain safe operations and								
					a partial Stop Work Order (PSWO) for all work next to								
					openings. The General Contractor is to provide a Means and Methods and a Toolbox Talk.								
5/11/2018	Paral la seconda de la seconda d	70	NORTH 6 TH STREET			No. Brianda					Other Construction Related Incidents		
Jr 1 1/2018	Brooklyn	/6	NUKING INSIKEEI	0	 The Construction Superintendent reported that a worker was cleaning a paint gun when his finger was injured by 	NO Dispatch					outer Construction Related Incidents		
					the pressure from the nozzle. The worker went home to								
					see his doctor due to pain in his finger.								
5/12/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker twisted	No Dispatch			NEW BUILDING	121186849-01-NB	Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
					his knee on Saturday, May 12, 2018. This incident took place on May 12, 2018. but was reported on Monday.								
					May 14, 2018. The worker walked himself to a hospital.								
					, , , , , , , , , , , , , , , , , , ,								
										1	A second s		



ncident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/12/2018	Manhattan	500	WEST 26 STREET	0	1 The Site Safety Managor reported that workers were removing material from the grade level at the leading edge when two pieces of caisson pilings that were approximately two feel tong were cut in half. The pieces of caisson pilings fell approximately fifteen feet and struck a worker that was in the excavation pit in the leg. The worker went to a hospital. The status of the worker injuries is unknown. A DOB inspector responded and visited the site and issued four ECB Violations for the absconce of too boards at the guardrails, the prescence of inadequate vertical netting, the prescence of an inadequate vertical netting, the prescence of a partial Stop Work Order (FSWO) on a four DOB Violations were also issued. The contractor is to provide a Means and Methods and a Toobox Talk for the safe continuation of work.	s	35331325M/26Y/27X/28H	051218BS04PK01/02/03/04			Other Construction Related Incidents	500 W25TH OWNER LLC	
4/2018	Brookiyn	211	72 STREET	0	 The New York City Fire Department reported that a worker was walking on a scaffold on the second level when he tripped and hurt his knee. The worker was 	No Dispatch			A2 - ALTERATION TYPE 2	302579662	Worker Fell	DEPARTMENT OF EDUCATION	KG CONSTRUCTION SERVICES
14/2018	Brooklyn	7	WHIPPLE STREET	0	taken to an area hospital. 1 The Construction Superintendent reported that workers worker fell from the second floor when a worker fell from the second floor moth the first floor deck The worker was found conscious and was transported believue Hospital. Additional information regarding the injuries was not available. The Construction Superintendent was not on site as of the time that the incident occurred. An DDB inspector responded and visited the site and issued an ECB Violation to the General Contractor for a failure to safeguard. A DDB Violation and a full Stop Work Order (FSWO) was also issued.		36308771R	051418CNEDG01	Air 1 / NB	321285275	Worker Fell	WHIPPLE PROPERTIES LLC	SUNSHINE CONSTR USA INC
/14/2018	Manhattan	150	FIFTM AVENUE	0	1 A DOB inspector reported that there were workers moving steel beams with an electric hoist through a haftway for an alteration on a twelve story building. The workers moved the beams by pipe rollers on the ground to be stacked. One of the workers was adjusting the stack when he was struck by two other workers that when he was struck by two other workers that right hand curved between two beams and was taken to Beth Israel Hospial for treatment. An EGB Violiton for a failure to stelguard was issued. A partial Stop Work Order (PSWO) was issued on all work in shtway hosting materials. A Means and Methods and a Toobo Talk must be provided.		35331133H-FAIL TO SAFEGUARD.		ALT1	122700292	Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
5/2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was on the roof setback setting roof pavers when he stapped in a hole with the roof pavers that he was working on and hit his right shin. The worker was conscious and alert and walked to a City M.D. to be checked out.				ALT1	121324343	Worker Fell	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
5/2018	Manhattan	627	GREENWICH STREET	0	1 The Site Safety Manager reported that a plumber slipped off of the fourth step of a ladder that he was working on and suffered a sprained ankle. An ambulance was called.	No Dispatch					Worker Fell	627 GREENWICH OWNER LLC	
15/2018	Manhattan	500	WEST 33 STREET	0	A DOB inspector reported that materials that were stored in the staging area were blown away due to wind Annong the stored materials was a piece of styroleam that was approximately 87.33 X3 that struck a security guard in the back. The security guard complained of pain and was taken to a hospital in a conscious state with an unknown injury, An ECG Violation was issued, as well as a partial Stop Work Order (PSWO) for all work in the stating area due to a failure to secure stores material. The General Contractor is to provide a Means and Methods for a safe storage procedure.	d	35326800X				Other Construction Related Incidents	NOT ON FILE	
15/2018	Manhattan	20	BROAD STREET	0	1 The Site Safety Manager reported that a worker tripped on debra and fell on the back. An ambulance was been approximately and the safety of the safety of the and reported that on enforcement action was necessary as the incident occurred as the result of a worker error. The worker was okay and was reported to have returned to work the following day.	,					Worker Fell	NY STOCK EXCHANGE BLDG. CO.	
15/2018	Manhattan	100	EAST 104 STREET	0	2 The New York Cay Police Department reported that debreis was fulling from the building. A DOB inspector responded and visited the site and reported that at the filterent flore statesk, sections of location and phywood became separated due to high winds and feel to the street level along Park Avenue, stifting two individuals. One of the individuals that was struck was taken to a local hospital. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued.	s	35309499H	051518CNEGS02	NEW BUILDING	121192887-01-NB	Matarial Fell	TERRACE ON THE PARK LLC	GLENWOOD CONSTRUCTION



Incident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/15/2018	Doroga Manhatan	1	WALL STREET	0		ECB Violation	36327019M				Other Construction Related Incidents	MP ONE WALL STREET ACQUISITIO	
5/15/2018	Brooklyn	626	SHEEPSHEAD BAY ROAD	0	1 The Project Manager reported that a painter was on a ladder on the third floor when he misused the ladder and slipped off. The worker fell approximately six fee and hurt his shoulder. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NEPTUNE SOUTH COMMERCIAL LLC	
5/15/2018	Brooklyn	416	KENT AVENUE	0	2 A DOB inspector reported that approximately 50°-0" linear feet of sidewalk shed deck and parapet deck enclosure had blown off of a sidewalk shed and onto the street, injuring two pedestrians. The two pedestrians were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A parail Slop Work Order (PSWO) was issued on all crane and exterior operations, except for work to make safe the installation of a sidewalk shed.		36322610R	051518CERSM05	NEW BUILDING	320622616-01-NB	Material Fell	420 KENT AVENUE LLC	ZDG, LLC
5/15/2018	Bronx	1017	HOME STREET	0	1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall fell, hit a generator, and then bounced of the generator and landed on the worker's leg. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that safety measures were not in place for a bearing wall installation. An ECB Violation and a DOB Violation were issued, as well as a partial Stop Work Order (FSWO) on all bearing wall installations. A Means and Methods and safety measures for bearing wall installations must be provided		35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
5/16/2018	Manhattan	44	UNION SQUARE EAST	0	1 A competent person at the site reported that a worker was removing a vertical shoring post when his finger gol caught between the safety pin and the plate. The worker suffered a swollen finger and went to a hospital on his own.	t ·					Other Construction Related Incidents	READING TAMMANY OWNER LLC	
5/16/2018	Manhattan	76	11 AVENUE	0	1 The Site Safety Manager reported that a foreman was hanging an eight inch steel pipe when he lost control of the pipe. The foreman was then knocked off of a ladder by the pipe. An ambulance was called. A DOB inspector respond and visited the site and reported that the anchor from which the pipe was to be hung from failed. An ECB Violation was issued for a failure to maintain safe operations.		35331136N				Other Construction Related Incidents	76 ELEVENTH AVENUE PROPERTY OW	
5/16/2018	Queens	45-07	COURT SQUARE	0	1 The Site Safety Coordinator reported that a worker was using a four inch grinder when the grinder kicked back and cut the worker's left arm. The handle and grinder guard were in place. The worker was conscious and awake and went to Mount Sinai Hospital for treatment.	No Dispatch			NB	420902410	Mechanical Construction Equipment	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
5/17/2018	Queens	2100	49 AVENUE	0	1 The Construction Superintendent reported that an electrician was re-adjusting a ladder when he fell approximately five feet off of the ladder. The worker complainted of back pain and was taken to Elmhurst Hospital. The worker was alert and awake.	No Dispatch			ALT1	420656686	Worker Fell	2100 49TH AVENUE OWNER, LLC	ARCHSTONE BUILDERS LLC
5/17/2018	Queens	101	PENNSYLVANIA AVE	0	1 The Construction Superintendent reported that while working on a seven story new building, a project manager picked up a sheet metal that cut his finger. The project manager went to urgent care.	No Dispatch			NB	320622894	Other Construction Related Incidents		CAULDWELL WINGATE CO LLC
5/17/2018	Manhattan	112	EAST 11 STREET	0	1 The Site Barky Menager reported that a worker was troming down is any barker within he signed on the bark step of the ladker and fell three hert. The worker complained of back pain, An ambulance was called A DOB inspector responded and visited the site and found no unsafe conditions present as of the time of inspection. No enforcement action was necessary.	No Action Necessary					Worker Fell	UD-DEV ASSOCIATES LLC	
5/17/2018	Brooklyn	138	WILLOUGHBY STREET	0	2 A DOB inspector reported that a signalman had landed a banded bad on the top deck with a tower crane. The rigging was released after the load was landed, and the load shifted and startied another worker that was carrying pieces of rebar. The worker tripped, fell, and hurt his ankle. The worker was laken to a hospital for X- rays. The signalman suffered a cut to his finger from the banding after releasing the rigging and went to a City M.D. for iteratment. There were no witnesses to the it was determined that the signalman suffered a cut due to a worker error.	5			CN	773/17	Worker Fell	NYC HPD	Trident General Contracting, GC lend lesse



ncident Date	Borough	Address Numb	er Street	Fatalities Injuries EOC Final Des	cription	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
17/2018	Bronx	1903	WEST FARMS ROAD	0 1 The Site Safety	Manager reported that a worker was			1			Material Fell	SAMARITAN-COMPASS V HOUSING DE	
				performing insu	lation work behind a stud wall when she								
				pushed a stack wall, which cau	of sheetrock that was leaning against a sed the boards to fall forward and hit her								
				in the leg. An a	mbulance was called.								
2018	Brooklyn	101	PENNSYLVANIA AVENUE	0 1 The Site Safety	Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	ATLANTIC 2644, LLC	
				finger on a piec	e of sheet metal. The worker went to								
			FULTON STREET	urgent care.					CN	80/17		NOT ON FILE	FJM- Ferro Inc
2018	Brooklyn	422	FULTON STREET	0 1 A DOB inspecti	or reported that a crane was making a steel I-Beam from a trailer bed in the	No Action Necessary			CN	80/17	Mechanical Construction Equipment	NOT ON FILE	FJM- Ferro Inc
				street to the roo	of. The beam was rigged up and the								
				signal man gav	e the crane operator the signal to come								
				up with the load	d. The crane had lifted the load								
				approximately t	wo feet off of the bed of the trailer when attemped to steady the load to keep the l-								
				Beam from swa	aying. When the iron worker did this, he								
				had out his lea	inhetween the moving load and a								
				stationary bean	n on the flatbed truck. When he did this,								
				the worker crea	ated a pinch point, and the moving load er's leg and caused a cut. The worker								
				was taken to a	hospital with non-life threatening injuries.								
				The DOB inspe	ector found no violating conditions during								
				his inspection,	as all of the workers at the site had the								
				slings were fou	or 32 hour rigging certification cards, the nd tagged and adequate, the lift director								
				had logs, and the	he signal man had his card. No								
				enforcement ac	ction was necessary.								
2018	Brooklyn	578	COZINE AVENUE	0 1 A DOR	or repored that a worker was performing	ECB Violation	35322901R 35322902Z	051818CERRJ03 051818CERRJ04	Abatement		Worker Fell	NYBC REALTY LLC	GSC Services Corp
010	D. OKIYII	5/6	SOLINE AVENUE	ashestos abate	ment work on the roof when he fell	COD VIOIatION	SUSEL OUTR SUSEEBUEL	0010100ENN300 0010100ERR304	Abatement			ALSO REALT LED	CCC dervices colp
				approximately t	wenty feet through the roof. The worker rookdale Hospital. The abatement work								
				was taken to Br	rookdale Hospital. The abatement work								
				Was being perfo	ormed as per the posted notice. Two vel 2 ECB Violations for a failure to								
				safeguard were	issued to the abatement company and								
				building owner.	A partial Stop Work Order (PSWO) was								
				issued for all w	ork at the roof level. The contractor at the e a Means and Methods for the safe								
				removal of mate	erial from the roof level.								
2018	Brooklyn	6	METROTECH	0 1 A New York Cit	Police Officer reported that a plumber	No Action Necessary			PLUMBING	321562288	Mechanical Construction Equipment	NEW YORK UNIVERSITY	VITO M. GIACHETTI
				was working on	a pipe on the fifth floor when the pipe								
				burst and hit the	e plumber in the chest and chin. An								
				ambulance was the incident and	s called. A DOB inspector responded to d visited the site and determined that								
				there was no er	nforcement action necessary, as the job								
				had on-site acti	ive Department Of Buildings permits and								
				approved techn	nical plans.								
/2018	Manhattan	130	WILLIAM STREET	0 1 The Site Safety	Manager reported that a ten feet long hat was standing vertically and was to be	ECB Violation	35331400N				Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	
				piece of rebar t installed fell on	a worker that was standing on the								
				ground, hitting I	him in the side of his hard hat. The								
				worker went to	a City M.D. A DOB inspector responded								
					site and issued an ECB Violation for a ain safe operations, as well as a partial								
				Stop Work Ord	er (PSWO) for all concrete operations.								
				The General Co	ontractor at the site is to provide a Means								
				and Methods a	nd a Tool Box Talk.								
2018	Bronx	2865	CRESTON AVENUE	0 1 The Site Safety	Manager reported that a worker was	ECB Violation	35327296K, 35327297M, 98, 99X, 3531840OR, 01Z				Worker Fell	10 MINERVA PLACE HOUSING DEVEL	
				putting up form	s on a column when he fell about six to injured his foot. The worker was sent to								
				a hospital. A De	OB inspector responded and visited the								
				site and found t	that a book that was holding form up was								
				damaged, whic	h may have possibly caused the worker Violation for the failure to maintain safety								
				to fall. An ECB	Violation for the failure to maintain safety issued, as well as a partial Stop Work								
				Order (PSWO)	for all concrete work. Additional ECB								
				Violations were	also issued for infractions that were not								
				related to the in	ncident.								
/2018	Bronx	4215	PARK AVENUE	0 1 The Site Safety	Manager reported that a worker fell from	No Dispatch			NEW BUILDING	220157700-01-NB	Worker Fell	TREMONT RENAISSANCE HOUSING DE	JOY CONSTRUCTION CORP
				the top of a hoir worker suffered	st that was stopped on the first floor. The I minor injuries and was transported to a								
				hospital by amb	pulance.								
2018	Manhattan	247	WEST 87 STREET	0 2 The New York	City Police Department reported that two	ECB Violation	35324011Y - 35324012X		N/A		Worker Fell	KSB BROADWAY ASSOCIATES	Jerrick Associates Inc
				workers were in	the process of installing a supported								
				scaffold when t	hey slipped and fell from three frames of he workers suffered scrapes and bumps								
				to their bands a	ne workers suffered scrapes and bumps and legs and were taken to St. Luke's								
				Hospital. A DO	B inspector responded to the incident								
				and visited the	site and issued two Aggravated Level 2								
				ECB Violations	. The first violation was issued for the								
				removal or alter General Control	ration of the supported scaffold by the actor before the inspector's arrival, which								
				is the removal of	of equipment, structural material, or								
				evidence that is	s related to an incident. The second								
				violation was is	sued for a failure to promptly notify the Buildings of the incident, as the incident								
				Department Of was reported by	punuings of the incident, as the incident v the NYPD.								
				was reputed by	,								
2018	Queens	30-02	39 AVENUE	0 1 The Cite Cefet	Manager reported that a worker was	No Dispatch		-			Other Construction Related Incidents	30-02 ASSOCIATES LLC	
10	Queens	30-02	38 AVENUE	cutting a metal	stud when he cut his hand. An	No Dispatch					Galer Construction Related incidents	JU-02 ADDUCIATED LLC	
				ambulance was	s called.								
				and the second se			Page 23 of 47	the second s			the second s		



cident Date	Borough	Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
23/2018	Staten Island	149	PROVIDENCE STREET	0 1 The New York City Office Of Emergency Management reported that a worker for 16 mm the structure. EMS transported the worker to a hospital. A DOB inspector responded to the incident and visited the site two ECB Violations for the failure to safeguard and for the failure to notify the Department Of Buildings of the incident. A full Stop Work Order (FSWO) was also issued.		35322904M/05Y	052318CERRJO1/02	ALT 1	520323212	Worker Fell	PERRI, ALFONSO	A. FONTANA & SONS LLC
2018	Manhattan	76	11 AVENUE	0 1 The Site Safety Manager reported that a worker was building the walk-out for a tower crane and was standin on the cranes the back beam when he slipped off of the beam and fell. The worker was wearing fail protection equipment. The worker did not suffer an injury, but was taken to a hospital for procursionary observation. A DO inspector responded to the incident and visited the site and reported that no enforcement action was necessary	9 B					Worker Fell	76 ELEVENTH AVENUE PROPERTY OW	SBF Construction
/2018	Manhatlan	26	1 AVENUE	0 1 A New York City Police Officer reported that a worker feil approximately live stories or fifty feet from an unguarded section of pipe scaffied. The worker was in critical condition and was taken to Believue Hospital. A bile and reported that i could not be determined what caused the worker to fall, as the people that the inspector interviewed claimed to have not seen or know about the incident. Four ECB Violations were issued fo the failure to safeguard. for the presence of a supported scaffold that was not built according to code and was missing guardrails, missing to boards, and was not ful decked, for the absence of plans, drawings, and logs o sate, and for the failure to provide a four hour supported scaffold uder card upon request. A partial Stop Work Order (PSWO) was also issued.	e r Iy	35324057J, 35324058L, 35324059N, 35324060K		Alt	140761995	Worker Fell	DROBENKO NICHOLAS	Lime-Light Construction Co
/2018	Brooklyn	2837	WEST 8 STREET	The Project Manager at the site reported that during the installation of concrete panel around a bulkhead, a panel cracked, field, and caused a minor cut to a worker hands. The worker went to a clinic and then cause back to the site on the following day. A DCB impactor responded to the incident and value days and the protect of the at a hear and therhods was in pleased and the protect of the site	is i i n					Material Fell	AISD CORP.	
2018	Brooklyn	41	BLUE SLIP	0 1 The Site Safety Manager reported that the driver of a concrete truck was washing out his truck when he hopped off of a ladder and turned his ankie. EMS was called and the worker was sent to a nearby hospital.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT F LLC	
4/2018	Brocklyn	420	EAST 21 STREET	The New York City Fire Department requested that an inspection please be performed due to a retaining wall collapse. A DOB inspectro responded and visited the sale and reported that the building owner was performing work on the retaining wall that was aspectaning 420 and 412 East 21 Street when a section of the retaining wall has well be appeared to the sale of the sale sale sale of the sale of the sale sale sale sale sale sale sale sal	9 e k	35322725R, 35423726Z	052418CNESC04, 05, 052418CNE01SC			Other Construction Related Incidents	HOSSAIN, GOLAM	
4/2018	Brooklyn	84	CARLTON AVENUE	0 1 A competent person at the site reported that a worker was installing roof protection when the worker tripped a piece of phywood and fell. The worker was sent to a hospital for a check up.	n					Other Construction Related Incidents	NYC HOUSING AUTHORITY	
2018	Manhattan	233	WEST 125 STREET	0 1 The Site Safety Manager reported that a worker slipper while coming down from a ladder. The worker was take to a hospital by EMS.	n			NEW BUILDING	121187447-01-NB	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
5/2018	Manhattan	24	2 AVENUE	0 1 The Site Safety Manager reported that a worker cut his arm with a sheetrock knife while cutting sheetrock. The worker went to a nearby urgent care facility to receive medical attention.	No Dispatch					Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	



ncident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/25/2018	Queens	28-07	JACKSON AVENUE	0	1 A DDB inspector reported that there was a six man team that was diamating support columns when one of the columns was released before one of the workers had a hold of the column. The column struck this worker to the ground. The worker was warring his Personal Protection Equipment (PPE) and was found alert and responsive. The worker did not stuffer a serious injury, but was taken to a hospital wanbulance as a procession. One and the series of the series of the series of the series attended a pre-job meeting and that the worker was up to date with duty pre-task haracraft alerly meetings that are designed to avoid such incidents. The inspector determined that no enforcement action was necessary and that the incident occurred as the result of a worker error.	No Action Necessary			ALT 1 NB	420656873	Material Fol	UC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
5/26/2018	Manhātian	217	WEST 57 STREET		0 A DOB Professional Engineer (PE) reported that at a isity-seven story new building that was under construction, as security guard wave waking from the front to the rear on the first floor of the building when an approximate 16 X 8, 2.300 period that security guard undersaft. The security guard undersaft is several workers guard. The security guard variant seal is several workers guard. The security guard variants is the first floor of the building when an approximate 16 X 8, 2.300 period that security guard diversaft. The security guard variants is the nort first period that the lass and the security guard variant set is the first security guard variant that the local X and X		35322814Y	052618CERSM01	ALT 1 NB	121328205	Material Fell	SMITELL SPONSOR LLC	LEND LEASE (US) CONSTRUCT
/26/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	2 The New Yok City Fire Department requested that a structural stability inspection please be performed because a construction french and partially colloped. A DOB inspector responded to the incident and visited the site and reported that there was approximately 100 feet later on errors of the term of the approximately 100 feet perspectations and a four foot chain link fonce that had plance your on a pedestrian away and injured two pedestrians. The two pedestrians were not transported by EMS to receive off-site medical assistance. The barriers were found to have inadequate water levels. Two ECBV violations were isaued or a failure to safeguard and for a defective job site fence. Two DOB Violations were also issued.	ECB Violation	35323583P, 35323584R	052518CERFC02,03	ALT 1 NB	320622894	Material Fell	SPRINGER, JEAN E	CAULDWELL WINGATE CO LLC
/29/2018	Bronx	220	EAST 178 STREET	0	¹ The Site Safety Coordinator reported that while working on a twelve story New Building that was at the Support of Excavation (SCE) stage, a hose from the fire hydant that was across the sidewal was being used when a female pedestrain tripped and fell over the hose. The pedestrain was found after and awake and was laken to a nearby hospital by ambulance. A DOB inspector responded to the incident and visited the site and reported that the pedestrain sidewalk was clear to any obstructions as of the time of inspection. Two ECB Violations for the presence of port housekeeping and for the presence of tripping hazards. A full Stop Work Older (FSWO) was issued for the entire site.	ECB Violation	35332113P 35332114R		New Building	220546620	Excavation/Soll Work	GRAND APTS HOUSING DEVELOPMENT	M. Melnick & Company Inc
/29/2018	Manhattan	15	BRIDGE PARK DRIVE	0	The Site Safety Manager reported that a worker was unloading an air handler when he lacerated his middle finger on a sharp edge of the air handler. The worker went to a local clinic.	No Dispatch					Other Construction Related Incidents		
5/29/2018	Manhattan	151	MAIDEN LANE	0	The Site Sates Managor reported that workers were moving a netlypication unit when it toppied over onto one of the workers. The injured worker was taken to a hospital. A DOB inspector responded to the incident and visited the site and insued an ECB Violation for the failure to maintain safe operations, as well as a partial Stop Work Order (PSWO) on material handling on the ground level at the exposure. The General Contractor is to provide a Means and Methods.		35335852H				Other Construction Related Incidents	151 MAIDEN LLC	



ncident Date	Borough	Address Number	Street	Fatalities Injuri	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
29/2018	Queens	45-57	UNION STREET	0	1 The Sate Safety Menager reported that a worker was on baker safeloid at the second floor when the worker fell from the scaffold. The worker was found conscious, but compainted or pain in his shoulder and leg. The worker walked to a nearby hospital. A DOB inspector responded to the incident and visited the site and issued one ECB Violation for a scaffold platform that was not fully planked and for the presence of planks that were not tied down. A partial Stop Work Order (PSWO) for the use of a supported scaffold was also issued.	ECB Violation	35323972Z - 35323973K		NB	402898959	Worker Fell	DEPARTMENT OF EDUCATION	Leon D. Dematteis Construction
29/2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that an electrician tripped while walking and suffered an injury to his rlbs. The worker went to urgent care.	No Dispatch					Worker Fell	DEPARTMENT OF EDUCATION	
30/2018	Brooklyn	2550	3 AVENUE	0	 The Site Safety Coordinator reported that a worker's foo came into contact with a piece of pipe that was in a pile of garbage that was to be picked up. The worker suffered a foot laceration and was sent to a hospital. 	No Dispatch					Other Construction Related Incidents		
31/2018	Brooklyn	107	COLUMBIA HEIGHTS	0	1 The Site Safety Coordinator reported that four workers were carrying havey mechanical equipment down the statis when equipment fell on one of the workers. The worker was sent to a hospital for a check up. A DOB inspector responded to the incident and visited the site and issued an ECS Violation for the failure to maintain safe operations and a partial Stop Work Order (FSWO) on the handling of heavy material. The General Contractor is to provide a Means and Methods.	ECB Violation	35326963N				Other Construction Related Incidents	CLIPPER 107 CH LLC	
31/2018	Manhattan	360	EAST 80 STREET	0	A DOB inspector reported that a worker was sorting and moving glass window panels when one of the panels shifted and hit the worker in the log. The worker was taken to a hospital by ambulance for evaluation. An ECC Violation and a parialis Bop Work Order (PSWO) was issued for the failure to maintain safely measures, as the worker was injured due to improper material handling. The General Contractor is to provide a Means and Methods for safe material handling in order to prevent future incidents.		35318415J		NEW BUILDING	121186242	Material Fell	1711 LLC	RYDER CONSTRUCTION INC
31/2018	Queens	51-35	REEDER STREET	0	 The Construction Superintendent reported that a worker strained his back while lifting a crate onto a dolly. An ambulance was called and the worker was transported to a hospital. 	No Dispatch			NEW BUILDING	420812446-01-NB	Worker Fell	85-15 QUEENS BLVD. REALTY, LLC	STRUCTURAL LAND MANAGEMEN
31/2018	Queens	546	GULF AVENUE	0	 The Site Safety Manager reported that a worker cut his finger while using a box cutter. The worker went to a clinic. 	No Dispatch					Other Construction Related Incidents		
1/2018	Manhattan	701	7 AVENUE	0	The Site Safety Manager reported that two workers were loading glass panels that were approximately 5 X 3 onto a cart when the glass came into contact with a metal part of the cart, which caused the glass to break into pieces. One of the workers suffered a minor liceration to his left hand. The injured worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	20 TSQ GROUNDCO LLC	
/1/2018	Manhatlan	49	CHAMBERS STREET	0	¹ The Site Safety Manager reported that a worker was laring to move a dolly that was carrying a machine motor for an exterior elevator: up the samp of the loading dock when he lost his balance and the machine motor tipped over, causing the worker to fail face down. The worker suffared cuts and bruises to the face and was taken to a hospital for treatment. A DOB imspector responded to the incident and visited the site and issued an ECB Violation and a partial Stop Whot Order (FSWO) to stop all deliveries and material handling. The General Contractor at the site is to provide a Means and Methods for safe operation.		35335925Y		ALTERATION 1	121186821	Material Fell	49-51 CHAMBERS LLC	NY DEVELOPERS & MANAGEMEN
1/2018	Brooklyn	18	SPENCER STREET	0	1 The Site Safety Manager reported that a worker was working on a twelve story new building and suffered a cut to his arm while carrying 2 X 4's and sharp edge metal track material. The worker went to a nearby doctor for treatment and received a few stitches.						Other Construction Related Incidents	LL 18 SPENCER HOLDINGS LLC	
4/2018	Manhattan	10	VANDERBUILT AVE	0	1 The Site Safety Manager reported that an iron worker was climbing down the stairs when he slipped and fell about three feet. The worker complained of a sprained back. An ambulance was called.	No Dispatch					Worker Fell		
/4/2018	Manhattan	108	LEONARD STREET	0	The Site Safety Manager reported that a steamfitter was working on a scissor lift and was installing sprinkler system anchors between pipse that were installed by other plumbers. One of the anchors failed and a pipe fall and landed on one of the steamfitter's hands, taking a to of his hand off. A DOB inspector responded to the incident and visited the site and issued a DOB Violation and a partial Sitep Work Order (PSWO) on all overhead installations. The General Contactor is to provide a Means and Methods and a Tool Box Taik.		35327073N				Material Fell	CIVIC CENTER COMMUNITY GROUP B	



cident Date	Borough	Address Numbe	er Street	Fatalities Injuri	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was stripping concrete form work on the first floor when he slipped and fell approximately four feet from the platform. The worker was found conscious and without a visible injury, but was taken to a hospital for a check up.		35327077K, 78M, 79Y		NEW BUILDING	121187447	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
					A DOB inspector responded to the incident and visited the site and reported that the worker was not using any type of fall arrest system, that the working area was not illuminated with lights, and that there was water on the floor that created a slipping hazard. Three ECB Violations and a full SSQ bWOrk Order (FSWO) were issued. The General Contractor at the site is to provide a Means and Methods for the sate operation of the job.								
2018	Brooklyn	4813	9 AVENUE	0	1 The Construction Superintendent reported that a worker	No Dispatch					Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
					was unloading a metal track when the track slid and cut his thumb. The worker went to urgent care for treatment.								
018	Manhattan	241	WEST 62 STREET	0	1 The Project Manager at the site reported that a worker was carrying a 2 X 4 when he accidentally dropped the 2 X 4 onto the foot of another worker. The injured worker was sent to a hospital for a check up and returned to the site afterwards.						Other Construction Related Incidents	NYC HOUSING AUTHORITY	
018	Manhattan	500	WEST 33 STREET	0	 The Site Safety Manager reported that an electrician was moving his equipment when he hurt his back. An ambulance was called. 	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker twisted his left ankle while installing rebar. The worker went to a clinic and then returned to the site.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
2018	Manhattan	1059	3 AVENUE	0	¹ The Site Safety Manager reported that during the construction of a tiltry story new balding, a worker inget toot. The worker continued to work, but the Site Safety Manager noticed that he was not doing well and that the worker was still in pain. The worker was taken to Cornell Hospital for treatment.	No Dispatch					Other Construction Related Incidents	63RD & 3RD NYC LLC	
018	Manhattan	110	UNIVERSITY PLACE	0	 The Site Safety Manager reported that a plumber was installing a pipe when a piece of debris fell into his eyes. The plumber went to a doctor. 	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
018	Manhattan	455	5 AVENUE	0	1 A Project Manager at the site reported that during the installation of floor opening protection, a worker lost control of a plank that hit him in the nose. The worker walked to a clinic.	No Dispatch					Other Construction Related Incidents	NEW YORK PUBLIC LIBRARY	
2018	Staten Island	35 a	BAY STREET	0	 The Site Safety Manager reported that a worker hurt his arm while removing formwork. The injured worker walked to urgent care. 	No Dispatch			NEW BUILDING	520138379-01-NB	Other Construction Related Incidents		HOLLISTER CONSTRUCTION SE
018	Manhattan	209	EAST 19 STREET	0	1 The Site Safety Manager reported that an elevator mechanic hurt his lift leg on roll wire that was nudged by a forklift. The worker worked most of the rest of the day before he walked to urgent care on his own.	No Dispatch			NB	121958480	Other Construction Related Incidents	VISUAL ARTS HOLDING CORP	GRAMERCY SQUARE LLC
2018	Manhatian	15	EAST 30 STREET	0	The Site Safety Manager reported that a worker fell down from the first floor supporting deck to the ground and suffered a very bach head injury. The worker was found conscious and was taken to a hospital by amblainac. The worker was reported to be in stable condition. A DOB inspector responded to the incident and visited the site and reported that the worker was waiking along the re-shores and may have possibly fainted or tipped and it hit is head on one of the re- shores. No enforcement action was deemed necessary, as the inspector did not doeser way hozardous conditions during the time of inspection.	No Action Necessary					Worker Fell	MADISON 30 31 OWNER LLC	
018	Manhattan	122	EAST 23 STREET	0	A DOB Inspector reported that an electrical worker at the collar level was on a twelve fool ladder installing with a seven destination of the seven and the seven and the six to seven dest. The worker was not wearing a barness and was taken to a nearby hospital. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (PSWO) was also assued for all work at cellar levels that requires ladders. A Means and Methods and a Tool Box Talk must be provided.		3532074P		NB	121 190157	Worker Fell	NOT ON FILE	CM AND ASSOCIATES CONSTRU
2018	Manhattan	111	LEROY STREET	0	1 The Site Safety Coordinator reported that a worker injured his middle finger while using a pallet-jack. The worker was sent to urgent care.	No Dispatch					Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
2018	Brooklyn	4813	9 AVENUE	0	worker was sent to urgent care. 1 The Construction Superintendent reported that a worker was carrying a few metal studs when he came into contact with a pipe scaffold tieback and twisted his knee. The worker was taken to urgent care.	No Dispatch					Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
2018	Brooklyn	123	LINDEN BOULEVARD	0	 The Site Safety Manager reported that a worker hurt his arm while moving formwork. The worker was transported to a hospital by another worker. 	No Dispatch			NEW BUILDING	321228603-01-NB	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS LLC



ncident Date	Borough	Address Numbe		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/8/2018	Manhattan	60	GREENE STREET	0	A DOB inspector reported that a worker on the first floor was leaving the bathroom when he walked toward a temporary alumirum stair system that he thought was in place and secured. The stairway collapsed and the worker fell to the basement stab below. The worker suffered possible injuries to the neck and head and was able to stand on his own power. The worker received treatment in the emergency course of a nearly hospital, and eventually returned to the site to pick up his tools. ECB Violations were issued for a failure to safeguard, for there being no plans on site for ongoing construction work, and for there being no plans available for a temporary staircase. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35314346r 35314347z		AL	123172217	Worker Fell	NOT ON FILE	SHAWNMUT WOODWORKING & SUP
/8/2018	Manhattan	767	5 AVENUE	0	1 The Site Safety Manager reported that a worker was doing waterproofing work in a tree pit on the plaza area. When the worker was walking away, he walked into a metal object that was on the wall. The worker went to a clinic for a check up on his own and will be reporting back to work.	No Dispatch			ALTERATION 1	122970721	Other Construction Related Incidents		TURNER CONSTRUCTION COMPA
5/9/2018	Brooklyn	242	EAST 45 STREET	0	2 A DOB inspector reported that two workers were working on the eave and gutters of the root while on pump packs when the workers eliad leaproximately twenty feet. One of the workers sustained injuries to his wrist, while the other worker sustained a head injury and was in critical condition. Both workers were transported to Kings Courty Hospital by ambufunez. An ECB Violation, a DOB Violation, and a full Stop Work Order (FSWO) were issued for work being performed without a permit.		35322879R	060918CERMR05			Worker Fell	PRINCE, LINCOLN	
3/9/2018	Manhattan	200	EAST 59 STREET	0	2 A DOB inspector reported that there were two electricians that were working in the utility room on the fourteenth foor with their foreman costs. The workers were working on a panel board when they de-mergized the upper half of the panel board. However, the lower half of the board remained live and was not insulated. Both workers were electrocouted and suffered burns, and both workers were electrocouted and suffered burns, and 2 ECB Violations were issued: one to the General Contractor, and one to the Electrical Subcontractor, for failure to maintain safety measures. A partial Stop Work Order (FSWU) was also issued: Two other ECB Violations were issued for infractions not related to the incident.		35335066K, 35335967M		NEW BUILDING	121192012	Other Construction Related Incidents	MIPA 59/THIRD OWNER LLC	GILBANE RESIDENTIAL CONST
/11/2018	Manhattan	45	BROAD STREET	0	1 A DOB inspector reported that a worker was holding a pin that was to be used to set the auger on a drill rg when another worker it his inspect with a harmer. The struck worker was taken to a nearby hospital and was latter released with a bruised input. An EOB Volation was issued for a failure to sateguard. A partial Stop methods is not a sate to sateguard. A partial Stop The General Contractor is to provide a Marea and Methods for the safe installation of an auger.		36332161J		NB	121190772	Excavation/Soil Work	MADISON 45 BROAD DEVELOPMENT L	pizzarotti LLC
/11/2018	Manhattan	138	EAST 38 STREET	0	The Site Safety Manager reported that an iron worker was cutting a tie wire with a utility knile when the knile slipped out of his hand and cut his forearm. The worker was transported to a hospital by ambulance for treatment.	No Dispatch			NB	121186028	Other Construction Related Incidents	TATHAM HOUSE,	TISHMAN CONSTRUCTION CORP
6/11/2018	Brooklyn	41	BLUE SLIP	0	process of climbing down an eight foot ladder when he missed a thread at three feet high and fell to the floor. The worker complained of shoulder pain and was taken to a hospital for evaluation. The inspector found no defects to the ladder or the area where the work was being performed. No enforcement action was deemed necessary.	No Action Necessary			Alt 1	320597449-01-NB	Worker Fell	BOP GREENPOINT F LLC	T.G. NICKEL & ASSOCIATES
/11/2018	Bronx	988	EAST 180 STREET	0	 The Site Safety Manager reported that a worker was cutting water proofing with a sheetrock knife when he accidentally cut his thumb. The worker was taken to urgent care for treatment. 	No Dispatch			NB	220152233	Other Construction Related Incidents	988 EAST 180 STREET HOUSING DE	MONADNOCK CONSTRUCTION IN
/12/2018	Manhattan	300	LAFAYETTE STREET	0	1 The Construction Superintendent reported that there were four workers that were moving a crate of glass on a dolly when the doll igned and caused the crate of glass to slide and hot nor of the workers in the chest. The struck worker fell to the floor and suffered a back injury. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that the glass was being moved on a makeshift dolly, and that a design drawing for the makeshift dolly, and that a design drawing for the makeshift dolly was not available. An ECB Visition was issued for the failure to maintain safe operations, as well as a partial Stop Work Order (PSWOI for material handling, A design drawing with load capacity for the makeshift dolly must be provided.		35335881L				Other Construction Related Incidents	LVC 288, LLC	



cident Date		Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Queens	28-30	JACKSON AVENUE	0 1 A DOB inspector reported that an electrician was working on a PVC junction box in the floor with glue. The box had live electrical wires, and the wires got touched as the electrician itref to push them down into the box, which created a spark that set the glue on fire. The electrician isreflered a second degree burn and was taken to a hospital, where he was reported to be in stable condition. An Aggravated Level 2 ECE Violation was issued for the failure to maintain safety measures will working on two electrician wires. A partial Stop Work Order (PSWO) was also issued to stop all electrical work.	ECB Violation			NEW BUILDING	420652886	Other Construction Related Incidents	LIC DEVELOPMENT OWNER, L.P.	HUDSON MERIDIAN CONSTRUCT
3/2018	Manhattan	15	EAST 57 STREET	0 1 The Site Safety Manager reported that a worker was using a grinder to cut steel when he lost control of the grinder, which caused a small laceration to his foremar The worker went to a local hospital.	No Dispatch					Other Construction Related Incidents	15 EAST 57TH ST.ASSOC.	
/2018	Manhattan	701	7 AVENUE	0 The Site Statey Manager reported that a cargorier new control of the Site Statey Manager reported that a cargorier new control states with a site with the cargorithm of the scattering card bis forearm. The worker's forement took him to a CM M.D. for treatment. The worker's expected to return to work.	у			ALTERATION 1	121324343	Other Construction Related Incidents	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
3/2018	Queens	42-20	27 STREET	0 1 The Site Safety Manager reported that a worker was lifting up the pipe frames of a supported scaffold with a pulley when the worker burned his hands on the tope and dropped the pipe frames of a supported scaffold. The worker was taken to a nearby hospital by a forema for treatment. A DOB inspector responded to the incident and visited the site and reported that the deall of how the incident occurred were not known. Twe ECE Violations were issued for the failure to perform a the failure to provide a support a samfind envector card, A partial Stop Work Order (PSWO) for the installation o supported scaffolds was also issued.	n 5	35324229R - 35324230Y		SF	Q00040613-11-SF	Material Fell	CRESCENT & 27 LLC	Classic Consulting Group
\$/2018	Staten Island	2589	RICHMOND AVENUE	0 1 The Site Safety Manager reported that a water pipe wa damaged by a worker on the second floor, which causs a flood on the first floor. One of the store workers at the address slipped and fell. An ambulance was called. A DOB inspector responded to the incident and visited th site and determined that there was no enforcement action necessary, as the work that was being performe was approved under a DOB issued permit.	a			SPRINKLER	540138929	Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	PATRICK BOWE
1/2018	Manhattan	532	WEST 33 STREET	0 1 The Site Safety Manager reported that a roof worker complained of pain in the left side of his chest while lifting waterprofing materials. The worker was alert an awake and was taken to Bellevue Hospital by ambulance for treatment.	No Dispatch			NB	121191183	Other Construction Related Incidents	NOT ON FILE	TISHMAN CONSTRUCTION CORP
4/2018	Brooklyn	210	CLASSON AVENUE	0 1 A DOB inspector reported that during a stripping operation that was taking place between the elevator shaft and north stainwell on the fifth litor, an 'ULMA' formwork beam that was approximately situaten feet ion struck a worker in the head while the worker was attempting to remove the beam. The worker was transported to a hospital, where it was reported that he had suffered a concursion. The worker was silent and stable in the hospital. An ECB Violation was lissued for failure to maintain safe operations. A partial Stop Work Order (PSWO) was also issued on all concrete work. The General Contractor is to provide a Means and Methods for safe operations.	a	35336020Y				Other Construction Related Incidents	PRATT INSTITUTE	
/2018	Brooklyn	1	CLINTON STREET	0 1 The Site Safety Manager reported that a worker was walking down from the second floor when he missed hi step and fell down. The worker hurt his knee and went a City M.D.	3					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
/2018	Bronx	600	BERGEN AVENUE	0 1 The Site Safety Manager reported that a worker was carrying a piece of lumber that was 4 X 10 X 7 when th worker sitpped, which caused the lumber to fall onto another worker's hand. The injured worker went to a Ci M.D.	e					Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	
4/2018	Bronx	600	BERGEN AVENUE	0 1 The Site Safety Manager reported that a worker hit his foot while unloading a beam. The worker's foreman too him to a first med.	No Dispatch k			NEW BUILDING	220151868-01-NB	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
14/2018	Bronx	1812	VYSE AVENUE	0 1 A DOB inspector reported that a worker was taking the devicey of a Concrete Mascoury Unit (CMU) block that was being delivered by a lul when his fingering sequence. The worker's foreman took him to a hospital for treatment. An EGB violation was issued for the failure to maintain safety measures. A partial Stop Work Order (PSWO) was issued on all material handling, including delivere A second partial Stop Work Order (PSWO) was size on all material handling, including delivere A second partial Stop Work Order (PSWO) was size on all material handling, including delivere A second partial Stop Work Order (PSWO) was size on all material handling, including delivere A second partial Stop Work Order (PSWO) was size at the required height. The General Contraction is to provide a Means and Methods and a worker's orientation before the first stop work order will be rescinded.	e	36318423J		NEW BUILDING	220152851	Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	HLS BUILDERS CORP



cident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
18/2018	Brookyn	15	WASHINGTON AVENUE	0	1 The Site Safety Manager reported that during the final pressure testing inspection of a stundpipe, the regulator let the air out of the standpipe, which caused another worker to hit avail. He worker complained of a back ache and an ambulance was called. A DOB inspector responded to the incident and visited the site, and reported that no enforcement action was deemed necessary, as the incident occurred as the result of a worker error.	No Action Necessary					Other Construction Related Incidents	NYC DSBS	
18/2018	Manhattan	110	UNIVERSITY PLACE	0	1 The Site Safety Manager reported that an electrician was using a sheet rock knile to try to cut a conduit when he sliced his left index finger. The worker was escorted to the emergency room at Beth Israel Hospital with another co-worker to receive treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/19/2018	Brooklyn	276	KENTAVENUE	0	1 A DOB inspector topotent that a worker was forming a suited floor deck when a reinstrative languid device for a suited floor deck when a reinstrative languid evice. The deck was not huly plankes was lift on locse plavaod. The deck was not huly planked and had gaps in it. The worker stepped on the locse plavaod, causing the locse plavaod to slip As a result of this, the transchale languid device fell to the second floor and hit another worker in the back. The worker was in a conscious state and was transported to a hospital with no visible injuries. An ECB Volation was controlled access zone in place. A partial Stop Work Order (PSWO) was also issued to stop al forming operations. The General Contractor is to provide a Means and Methods and a worker orientation for safe operation.	i	35327169H		NEW BUILDING.	320916407	Material Fell	DOMINO A LLC	280 KENT CONSTRUCTION LLC
/19/2018	Brooklyn	306	NORTH HENRY STREET	0	1 A DOB inspector reported that a contractor had overloaded joist girters that expanded night eight feet with eight burdles of corrugated stell decking that were area on the joist girden. However, the joist girdens were not properly installed, as they were only temporarily installed with one 34 th boit that eventually sheared off and collapace. This collapse caused the worker to fail forty feet to the ground. EMS was called and the worker was found altert and responsive when EMS arrived. The worker suffered a broken shoulder and possible back injuries and was taken to a nearby hospital. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard, as well as a full Sop Work Order (FSWO).		35336227L		EW-OT	340499080	Worker Feil	300 NORTH HENRY LLC	R, KING WINDOW CORP
19/2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that a worker was removing a kitchen cabinet when he was hit in the head by the cabinet when it became lose. The worker suffered a cut bh is face. The worker went to a City M.D. to receive treatment and will return to work.	No Dispatch			NEW BUILDING	121191913	Material Fell	95TH AND THIRD LLC	GILBANE RESIDENTIAL CONST
19/2018	Queens	36-18	MAIN STREET	0	1 The Site Safety Manager reported that an elevator company worker was putting down counter weights when his finger got pinched between the weights. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	134-22 35TH AVE., LLC	
/19/2018	Queens	37-09	COLLEGE POINT BOULEVARD	0	¹ A DOB inspector reported that a worker was installing guardralis on the pairwater of the job elia when he was saked to help install Q-decking at the second floor. When the worker went to get a torch to help tim the deck, the worker stepped on a loose sheet of decking and fell approximately fitteen on thewnly feet. The worker suffered injuries to his ankles, knees, and head. The worker was found consolva and was taken to Flushing Hospital by ambulance. An ECB Violation was issued to a failur to stageguard, as well as a partial Stop Work Order (PSWO) on building two on all steel erection and deck layout. A site specific Means and Methods for the prevention of further decking accidents must be provided. A Tool Box Tak and an adeguare ite off procedure for controlled deck zones must also be provided.		ECB#35327475X		NB	420653607	Worker Fell	NOT ON FILE	TOP 8 CONSTRUCTION CORP
/20/2018	Manhattan	328	EAST 62 STREET	0	A DOB inspector reported that there were workers that were getting ready to cit out and remove a raker sector that was connected to the Support Of Excavation (SOE) water and protruing through the foundation walls. The Construction Superintendent at the site stated that the section needed to be removed for the completion of a waterprofing installation. During the process of preparing jackhammers to choice out the concrete around the raker pit, a worker slipped and lell approximately contere grit out the raker beam of the site of the top location of the raker pit and welked to a hospital with a co-worker. The worker received treatment and because there were guard rails missing. An additional ECB Violation was issued for the failure to provide a Means and Methods for the removal of S.O.E. sections. A partial Stop Work Crefer (PSWO) was issued on the removal of S.O.E. sections.	1	355332281Y-35332282X		NB	121189846	Worker Fell	YYY 62ND STREET LLC	Joy Construction corp



	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0/2018	Manhattan	300	LAFAYETTE STREET	0	1 A DOB inspector reported that there were electricians moving spocie down a flight of a tairs when they lost control of one of the spools, which hit one of the worker in the leg. The worker was taken to a hospital by ambulance. An ECB Violation was issued for a failure or maintain safe operations. A partial Stop Wrok Order (PSWO) was also issued for all heavy material handling A Means and Methods must be provided.	5	35331146R				Other Construction Related Incidents	LVC 298, LLC	
20/2018	Manhattan	25	SUTTON PLACE SOUTH	o	1 A DOB inspector reported that a worker was attempting to lower a chipping guin from a not to a settack to another worker when he accidentally dropped the chipping guin prom a setty work feet, hitting the other worker on his hard hat. The struck worker was admitted into Cornell Medical Center, where he received stitches. This incident documed on June 19, 2018, but was not incident and use 20, 2018. Two ECB Violations were issued, an Aggravated Lewel 2 violation for the failure to notify all persons and property and a second violation for the insular to accident were was issued for the issued. A part and Stop Work Order was issued for the lowering of any tools or equipment from a root to a setback without a DOB approved Means and Methods.		353227737Y 35333276Y	062018CNESC01 062018CNEGS01	ALTERATION TYPE 2	122907426-01-EW-OT	Other Construction Related Incidents	CANNON POINT NORTH INC	DNA CONTRACTING LLC
0/2018	Manhattan	1558	3 AVENUE	0	The Site Safety Manager reported that a garbage truck was passing by when it hit a barrier that hit a worker. The worker complained of back pain and walked to urgent care.	No Dispatch					Other Construction Related Incidents	180 EAST 88TH STREET REALTY LL	
0/2018	Manhattan	1227	BROADWAY	0		No Dispatch					Other Construction Related Incidents	YJL BROADWAY HOTEL LLC	
21/2018	Brocklyn	583	LORIMER STREET	0	1 A DDB inspector reported that a worker injured his finger while using a drill during steel erection/modification work because the drill was used contrary to the manufacturer's specifications. The injured worker was sent to a hospital, where he received stitches. This incident occurred on June 21, 2018, but was not reported umil June 22, 2018. Four ECB Violations were issued. These violations include a violation for a failure to maintain sele operations, a violation for a drill contrary to the manufacturer's specifications, and a violation for the failure to notify the Department Of Buildings of the incident in a timely manner.		35331149M, 1450L,1451N, 1452P				Other Construction Related Incidents	583 LORIMER LLC	
1/2018	Brocklyn	77	CLARKSON AVENUE	0	1 A DOB inspector reported that a worker was working on a platform deck when he fell approximately six feet to the lower level. The worker was found conscious and latert and was taken to a nearby hospital. An Aggravated Level 2 ECB Violation was issued for the failure to safeguard. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued for all of the work being conducted at the fifth floor.	1	35309269X	062118CNERWS01	Ait - 1NB	321197771	Worker Fell	CLARKSON BUILC	DAWNY CONSTRUCTION LTD
21/2018	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that an iron worker was working inside an elevator shaft on a man basket when an object fell from above and struck and out the worker's arm. An ambulance transported the worker to a hospital for treatment. A DOB inspector responded to the incident and visited the site and reported that design drawings for working platforms were provided, a certification for the usage of a scaffold was provided, and lighting was being put in place during the time of the failure to rootly the DOB Scaffold Safety Team for the failure to rootly the DOB Scaffold on the site. A partial Stop Work Oddr (PSWO) was issued for all work in an elevator shaft. A Manar and Methods for all safe operations in a shaft must be provided.	1	35331147Z	062118BS04SA01			Material Foll	CBP 441 NINTH AVENUE OWNER, LL	
21/2018	Manhattan	45	BROAD STREET	0	A DOB inspector reported that contractors were transporting material with an excavator when the built of the material with an excavator when the ubuilt (20U) and the adjacent property (55 Broad Street, Manhattan), which is a Cosin restaurant. The impact disloged a small section of concrete block that struck a customer that was eating lunch inside of the restaurant. The customer sufficient of an only or block that struck a customer that was eating lunch inside of the nature of the customer sufficient of an only or block that struck a customer that was eating lunch inside the and was transported to New York Prebyterian Hospital by an ambulance. There were no structural concerns found. However, the restaurant has been closed. The damaged building's enginere will provide a Means and Methods for repairs. An Aggravated Level 2 ECB Violation was issued for a filter to safeguard. A full Stop Work Order (FSWO) was issued for the entire site.	ECB Violation	35332283h		FO	121190772	Material Foll	MADISON 45 BROAD DEVELOPMENT L	Pizzanotti LLC



Matrix Matrix	cident Date	Borough	Address Number	Street	Fatalities Iniurie	EQC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
Image: A startImage: A startImage	22/2018		15		0	1 The Site Safety Manager reported that a worker dropped			SSD VIolation Humbers	rennic	. same no			Consider Name
No Ale A Ale Mark A Ale Mark A Ale Mark						worker suffered a swelled foot and went to urgent care								
Image: Section of the secting of the secting of th	/2018	Manhattan	315	EAST 46 STREET	0	1 The Site Safety Manager reported that a worker bent	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
Image: Section of the section of th						down to plug in an extension cord and hit his head on a								
Image: Second	2018	Manhattan	100	CHURCH STREET	0	1 A DOB inspector reported that at a nineteen story	ECB Violation	35327483X, 84H, 85J, 86L				Material Fell	100 CHURCH FEE OWNER LLC	R&S CONST. CONTRACT. INC
Image: Section of the section of th						building that was having alteration work performed on it,								
Image: Section of the section of th						on the eigth floor utility shaft using a "Jewel Clamp" that								
Image: Section of the section of th						keeps the pipes in position. The "Jewel Clamp" slipped								
Image: Section of the section of th						the shaft. The clamp bounced on the third floor and								
Image: Section of the section of th						landed in the cellar, where it hit another worker on his								
Image: Second						hand. The injured worker suffered cuts and bruises on his arm, but did not suffer a broken bone. The injured								
Image: Section of the section of th						worker was taken to a hospital, where he received								
Image: Section of the section of th														
Image: Section of the section of th						safety measures, a second violation for working on two								
No Note No Note of the second s						levels simultaneously without protection or a Controlled Access Zone (CAZ) in place, a third violation for working								
Image: Section of the section of th						without a permit, and a fourth violation for the absence	'							
Image: Section of the secting of the secting of th						of guardrails at open shafts. A full Stop Work Order								
Image: Section 10 mm Image: Section 10 mm <td< td=""><td></td><td></td><td></td><td></td><td></td><td>the site is to obtain a permit and provide a Means and</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>						the site is to obtain a permit and provide a Means and								
A A						Methods and a workers' orientation for safe operation at								
Image: A constraint of the image: A constrai						the site before the stop work order will be rescribed.								
Image: A constraint of the image: A constrai														
Image: A constraint of the image: A constrai	2018	Queens	5	COURT SQUARE	0	1 The Site Safety Coordinator reported that a construction	No Dispatch			NB - NEW BUILDING	420902410	Worker Fell	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
Main						worker tripped and sustained a minor knee injury. EMS was called and the worker was transported to a local								
Note: Automatical State Automatical St	018	Manhattan	505	WEST 43 STREET	0	1 The Site Safety Manager reported that a worker was	ECB Violation	35300588M		NEW BUILDING	121187456	Worker Fell	NOT ON FILE	NEW LINE STRUCTURES & DEV
N Montaneous Notational interview i						standing on an "A"-Frame ladder while performing a								
Image: Section of the section of th						grinding operation on the fourteenth floor of a concrete wall surface when the ladder slipped, causing the								
M Montoo						worker to fall. The worker was found unconscious. An								
Image: Problem Image						ambulance was called and the worker was transported to a hospital in a conscious state. A DOB inspector								
Image: specific provide sp						responded to the incident and visited the site and issued	1							
Image: Section of the sectin of the section of the						an ECB Violation for the failure to maintain safety measures. A partial Stop Work Order was issued on all								
NBNormalityNo						grinding operations. The General Contractor at the site								
Image:						is to provide a Means and Methods for safe operation.								
Image: Single states Image: Single states <td< td=""><td>2018</td><td>Manhattan</td><td>149</td><td>EAST 125 STREET</td><td>0</td><td>2 A DOB inspector reported that a Jekko crane machine</td><td>ECB Violation</td><td></td><td></td><td>NEW BUILDING</td><td>121192388</td><td>Mechanical Construction Equipment</td><td>NOT ON FILE</td><td>ZDG, LLC</td></td<>	2018	Manhattan	149	EAST 125 STREET	0	2 A DOB inspector reported that a Jekko crane machine	ECB Violation			NEW BUILDING	121192388	Mechanical Construction Equipment	NOT ON FILE	ZDG, LLC
Image: Spectrum set in the spectrum						on the fourth floor was in the process of placing a								
 In the second sec						fell from the fourth floor and two connectors also fell								
Image: Section of Secting of Secting of Secting of Secting of						from the third floor. One worker fell from the third floor to the street and suffered a critical injuny, and a second								
 In the set of the se						worker that was on the third floor was struck by crane								
 I a backy I backy						components and suffered a non-life threatening back								
Image: Section of the secting of the secting of the secting of th						The inspector reported that the injured workers were not								
Image: Section of the section of th						tied off and that the operation was not permitted, as								
Image: service						certifications present. The crane operator did not have								
Image: Rest and rest an						any certifications. The inspector reported that the								
Image: Register of the section of the secting of the secting of the secting of t						overloaded, and that a Means and Methods for hoisting								
Image: Section of the sectin of the section of the section of the						and rigging, for overloading, and for safeguarding was								
Image: Rest and a set of the						not provided. DOB's BEST Squad issued a full Stop Work Order (ESWO) due to the existence of multiple								
Image:						safety issues. DOB's Cranes and Derricks Unit also								
Image: Section of the section of the section issued to both the General coperation, is the distance of coperation, is the linkup to safeguad, for in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to safeguad to in usable coperation, is the linkup to in usable coperation, is the linkup to in usable c						issued a Stop Work Order on all hosting operations. Fight totals ECB Violations were issued as there were								
Image:						separate violations issued to both the General								
Image:						Contractor and the crane user at the site for an unsafe								
Image:						a valid HMO License or certifications, and for not being	·							
Image: Supporting Suppor						in possession of 16 or 32 hour rigging certifications.								
Image: Support in the stand in the stan														
Image: Supporting Suppor														
Image: Section	018	Brooklyn	420	ALBEE SQUARE	0	Superintendent was moving material on a pallet lack by	No Dispatch					Other Construction Related Incidents	JEMB ALBEE SQUARE LLC	
Image: Single						himself when he hit a divet. The Construction								
A Region A Region <th< td=""><td></td><td></td><td></td><td></td><td></td><td>was being moved from falling, but the material fell on his</td><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>						was being moved from falling, but the material fell on his	5							
Image: Section of the section of th		2					N. P							
Image: second	2018	DIOUKIYI		GLINTON STREET	0	picking up a garbage bag when he backed into stacked	NO Dispatch					other Construction Related Incidents	CADMAN ASSOCIATES LLC	
18 Bronx 2028 CRESTON AVENUE 0 1 The Site Salety Manager reported that a worker pulled the advector of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack. The worker of the back while using a pallet jack.						rebars and suffered a scratch to his right calf. The								
Inits back while using a palet jack. The works was called.	018	Bronx	2028	CRESTON AVENUE	0	1 The Site Safety Manager reported that a worker pulled	No Dispatch					Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	
						nis back while using a pallet jack. The worker complained of a back ache. An ambulance was called.								



	Borough	Address Number	er Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NEW BUILDING	321197478-01-NB	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
					fueling a generator when fuel was spilled on his arm. The worker walked to a City M.D. as a precaution.								
					The worker waked to a city m.b. as a precaditori.								
18	Manhattan	1	BEEKMAN STREET	0	1 The Site Safety Manager reported that the diamond	ECB Violation	35342751Z	062618BS01KR01			Other Construction Related Incidents	ONE BEEKMAN OWNER, LLC	
					plate in a hoist car was not secured and that the								
					diamond plate fell over and hit the ankle of a worker that								
					was in the hoist. An ambulance was called. A DOB inspector responded to the incident and visited the site								
					and issued an ECB Violation for the failure to institute								
					safety measures for the diamond plate in the hoist. A								
					DOB Violation was also issued. As of the time of								
					inspction, the diamond plate was made secure.								
2018	Manhattan	1	WEST END AVENUE	0	1 A DOB inspector reported that workers were in the	ECB Violation	35324259H		Shed	M00023179	Worker Fell	NOT ON FILE	Colgate Enterprises Corp
					process of dismantling a fourteen foot high sidewalk shed when one of the workers fell back between the								
					junior beams. The worker was experiencing minor back								
					pain and was taken to a local hospital by ambulance. Ar	1							
					ECB Violation was issued to the sidewalk shed								
					company for the failure to safeguard all persons and property.								
			WEST 61 STREET		1 The Site Safety Manager reported that a worker was							RCB1 NOMINEE LLC	
2018	Manhattan	400	WEST 61 STREET	0	1 The Site Safety Manager reported that a worker was carrying material down a flight of stairs when he missed	No Dispatch					Worker Fell	RCB1 NOMINEE LLC	
					the last step. The worker suffered a shoulder injury and								
					was taken to a hospital by ambulance.								
2018	Manhattan		9 AVENUE		1 The Site Safety Manager reported that a worker was	No Disease 1					Other Construction Related Incidents	G.D.C.L. HOLDINGS LLC	
218	manhattan	61	9 AVENUE	0	1 The Site Safety Manager reported that a worker was doing sheet metal work with a screw gun when he	No Dispatch					Outer Construction Related Incidents	G.D.C.L. HOLDINGS LLC	
					accidentally drilled a screw into his right hand. The								
					worker was transported to a hospital by ambulance.								
018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch				-	Other Construction Related Incidents	NYC DSBS	
				ŭ	going on a break when he opened a box and the lid of	Dispatori							
					the box fell on his hand, causing a laceration to his								
					middle finger. The worker went to a hospital for a check								
2018	Brooklyn	956	WASHINGTON AVENUE	0	1 The Site Safety Manager reported that a section of	ECB Violation	35335899.1	062918BS08PK01			Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
010	Brookiyn	636	WASHINGTON AVENUE	0	sidewalk caved due to a rain storm that occurred on	ECD VIOlation	333356993	0029108300FK01			Other Construction Related incidents	856 WASHINGTON OWNER LEC	
					June 28, 2018. A pedestrian stepped into the caved in								
					section of sidewalk and hurt her ankle, knee, and								
					shoulder. An ambulance was called and the pedestrian was taken to a hospital by ambulance. A DOB inspector								
					responded to the incident and visited the site and								
					reported that there were cracks along the section of								
					sidewalk that caved in during the rain storm, which may								
					have contributed to the cave in. The area was being back filled while the inspector was on site. An ECB								
					Violation was issued for a failue to maintain the sidewal								
2018	Manhattan	111	LEROY STREET	0	1 The Site Safety Manager reported that a window	No Dispatch				_	Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
					installer was taking suction cups off of a window when								
					he pulled his back. An ambulance was called.								
2018	Queens	33-02	30 AVENUE	0	1 A DOB inspector reported that a worker was using a	ECB Violation	35334832K & 35334833M	062918CERRJ01 & 062818CERRJ02	ALTERATION TYPE 1	420474347-01-AL	Worker Fell	ANDREW G GEORGIOU TRUST FUND B	CENTRAL BUILDERS DEVELOPM
					concrete trowel machine when he came upon a floor								
					opening. The worker was using the machine close to the	1							
					exterior wall when he hit the wall, which caused the machine to kick back towards the opening. Both the								
					worker and the machine fell approximately twelve feet								
					into the basement. The New York City Fire Department								
					removed the worker and EMS took the injured worker to								
					a hospital. Two ECB Violations were issued, including one Aggravated Level 2 violation for a failure to								
					safeguard and a second violation for the failure to post a								
					project information panel. Two DOB Violations and a ful								
					project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued.								
					project information panel. Two DOB Violations and a ful								
					project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued.								
18	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
18	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece o	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
18	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWL) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece o concrete. The worker was pushing the piece of concrete with his right for owhen he got his foot caught in the	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
18	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece or concrete. The worker was pushing the piece of concrete with his right foot when he got his foot caught in the shredder of the concrete mixer. One of the worker's toes	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
18	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWU) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to termove a place or with his right for when he got his foor caught in the shredder of the concrete mixer. One of the worker's toes was severed. The General Contractor at the site	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
018	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece or concrete. The worker was pushing the piece of concrete with his right foot when he got his foot caught in the shredder of the concrete mixer. One of the worker's toer was severed. The General Contractor at the site contractes MV or Fire Department ENT personnel, who	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
018	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece o concrete. The worker was pushing the piece of concrets with his right foot when he got his foot caught in the shredder of the concrete mizer. One of the worker's toer was severed. The General Contractor at the site contacted MYC Fire Department ENT personnel, who transported the worker to Jacoby Hospital. An Apagrovated Level 2 ECB Violation was issued to the	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
018	Bronx:	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece o concrete. The worker was pushing the piece of concrete with his right foot when he got his foot caught in the sheeder of thot when he got his foot caught in the sheeder of the domanal Contractor at the site was severed. The General Contractor at the site General Contractor for a failer worker's toest And Statistication was issued to the Aggreyated Level 2 ECB Violation was issued to the	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
018	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece o concrete. The worker was pushing the piece of concrets with his right foot when he got his foot caught in the shredder of the concrete mizer. One of the worker's toer was severed. The General Contractor at the site contacted NYC Fire Department ENT personnel, who transported the worker to Jacoby Hospital. An Agarwated Level 2 ECB Violation was issued to the General Contractor for a failure to safeguard. A partial Stop Work / Order (PSWO) on all concrets and cement	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
018	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece o concrete. The worker was pushing the piece of concrete with his right foot when he got his foot caught in the shredder of the concrete mixer. One of the worker's toer was severed. The General Contractor at the site contacted MYO. File Department ENT personnel, who contacted MYO. File Department ENT personnel, who Contacted MYO. File Department ENT personnel, who General Contractor for a hairve to safeguard. A patrial Stop Work Order (PSWO) on all concrete and cement Stop Work Order (PSWO) on all concrete and cement	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
018	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece o concrete. The worker was pushing the piece of concrets with his right foot when he got his foot caught in the shredder of the concrete mizer. One of the worker's toer was severed. The General Contractor at the site contacted NYC Fire Department ENT personnel, who transported the worker to Jacoby Hospital. An Aggravated Level 2 ECB Violation was issued to the General Contractor for a failure to safeguard. A partial Stop Work / Order (PSWO) on all concrets and cement	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
18	Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove piece o concrete. The worker was pushing the piece of concret with its right for ownen to got his foot caught in the shredder of the concrete mixer. One of the worker's toes was severed. The General Contractor at the site contracted NVC Fire Department EMT personnel, who irransported the worker to Jacoby Hospital. An Aggravated Level 2 ECB Violation was issued to the Stop Work Order (PSWO) on all concrete and cement operations was also issued. The concrete and must provide a Means and Methods for concrete and	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
				0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece o with his right too when he got his foor caught to the shredder of the concrete mixer. One of the worker's toes was severed. The General Contractor at the site contacted NYC Fire Department EMT personnel, who assured to worker to Jacoby Hospital. An Aggravated Level 2 EGB Violation was issued to the general Contractor for a failure to safeguard. A partial Stop Work Order (FSWO) on all concrete and cement operations was also issued. The contractors at the site must provide a Means and Methods for concrete and cement operations.	ECB Violation	35332291h		NB	220151895			L &M Builders Group
18	Bronx Bronx	1520	STORY AVENUE	0 1	project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued. A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove piece o concrete. The worker was pushing the piece of concret with its right for ownen to got his foot caught in the shredder of the concrete mixer. One of the worker's toes was severed. The General Contractor at the site contracted NVC Fire Department EMT personnel, who irransported the worker to Jacoby Hospital. An Aggravated Level 2 ECB Violation was issued to the Stop Work Order (PSWO) on all concrete and cement operations was also issued. The concrete and must provide a Means and Methods for concrete and	ECB Violation	35332291h		NB	220151885	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group



	Borough	Address Number	Street	Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Bronx	764	EAST 152 STREET	0 1	A DOB inspector reported that at the fifth floor, a worker was moving a lose when he became entangled in the hose and fell approximately five feet from a pipe scaffold to the deck on the fifth floor. The worker was taken to a hospital for treatment. Two Aggravited Level 2 EGB Violations were issued: one violation for a failure to notify the Department Of Buildings of the incident. Two DOB Violations and a full Stop Work Order (FSWO) were also issued.		35322847P & 35322848R	070218CERJM02 & 070218CERJM01	NEW BUILDING	220562905-01-NB	Worker Fell	764 EAST 152ND STREET LLC	UA BUILDERS CORP
2018	Brooklyn	350	HENRY STREET	0 1	A DOB inspector reported that a worker was cleaning around a shaftway when he lifed a piece of plywood away from the shaftway and fell approximately fifteen fleet through an opening. The plywood was not secure and the opening was not marked. The worker suffered a possible fractured arm and fractured vertebrase. An ECB Violation was issued for a failure to safeguard. A parial Step Work Orker (FSWQ) was issued on demolition work around shaftways.	ECB Violation	35342F14MFARL TO SAFEGUARD. HOLES NOT SECURE, WORKER CLEANING UP THE SITE FELL THRU TO THE FLOOR		ALT1	320625294	Worker Fell	FPG CH 350 HENRY, LLC	ICS BUILDERS, INC
018	Manhattan	301	PARK AVENUE	0 1	The Site Safety Manager reported that a worker cut the middle finger of his right hand while pushing a mini container. The worker was taken to a clinic to get stitches.	No Dispatch			ALT-11	122978625	Other Construction Related Incidents	THOR 30 PARK AVENUE LLC	TISHMAN CONSTRUCTION CORP
2018	Manhattan	49	CHAMBERS STREET	0 1	The Site Safety Manager reported that a HVAC worker cut his right arm during a duct installation. A DOB inspector happened to be at the site as of the time of the incident and reported that the injury occurred as the result of a worker's error. The worker walked to a hospital. No enforcement action was necessary.						Other Construction Related Incidents	49-51 CHAMBERS LLC	
2018	Manhattan	815	5 AVENUE	0 1	workers that overloaded an "A"-Frame cart, which caused a few 2 X 4 X 4" stones to slide off the cart. One of the stones fell onto a worker's foot. An ambulance was called.	No Dispatch					Other Construction Related Incidents	EIGHT HUNDRED AND FIFTEEN FIFT	
2018	Brooklyn	1	CLINTON STREET	0 1	The Site Safety Manager reported that a worker lost his footing and hurt his leg while pushing garbage in a thirty yard dumpster. An ambulance was called.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
018	Manhattan	1	WALL STREET	0 1	The Site Safety Manager reported that a worker came to the end of his shift when he complained that he strained his testicles while pushing a mini-dumpster. An ambulance was called.	No Dispatch					Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
018	Marihattan	150	5 AVENUE	0 1	A DOB inspector reported that a plumber was running a new line above an existing boliev when he came into contact with a live electrical wire. The plumber's partner pulled him of the wire. Both the worker and his partner were shaken up and were taken to a hooghtal by ambolance for a check up. Ar EGS Volation was listen above. The shaken up and were taken to a hooghtal by terminated were and the context of the shaken the basement. Defective wiring, exposed wires, and not- terminated weres were also cound in the basement boler room. A partial Stop Work Order was issued on work on a confined space by the cellar bolier. A DOB Violation was also issued.		35343112R	070318EE105EFF01			Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	
018	Manhattan	25	PARK ROW	0 1	The Site Safety Manager reported that a worker had pulled off some plywood during a stripping operation when he was hit in the eye by a nail. The worker work to a City M.D. A DOB inspector responded to the incident and visited the aste and reported that the worker was not wearing has safety goggleaPPE (Personal Protection Equipment). A COD Violation was issued for a failure to maintain safe operations.	ECB Violation	35343005L				Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	
2018	Manhattan	392	ASSER LEVY PLACE	0 1	The New York City Police Department reported that an on site works called 911 and reported that he fell from a supported scaffold and sustained injuries. A DOB imspector responded to the inicident and visited the site and reported that the worker was found laying on the ground root fell. The worker total the NYPD, the FDNY, and the responding paramedics that he fell from the second level. On the inisited poly escaffold. The worker suffered a broken right arm and was ainfilted by the FDNY and thensponde to Belweve Hospital by ambulance. The DOB inspector also reported that the contractor at the site was doing lacade pointing work. that did not require a permit, and that the contractor was in possession of DOB-saved sidewish shed and reported scaffold permit. There ECB the scaffold there supported scaffold permit. There ECB the scaffold there was not enclosed, one Aggrested Lavel 2 violation for a failure to safeguied, and a second Aggravited Lavel 2 violation for the abence of a complete guirated rail system. A partial Stop Work Order (PSWO) was also assued on the use of supported scaffolds.		35324344M, 35324345Y,35324346X				Worker Fell	PARKS AND RECREATION (GENERAL)	BQE Industries Inc
018	Manhattan	701	7 AVENUE	0 1	The Site Safety Manager reported that an electrician cut his arm on a metal stud. The electrician went to urgent	No Dispatch					Other Construction Related Incidents		



ncident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Queens	147-40	ARCHER AVENUE	0 1	The Site Safety Manager reported that a worker twisted	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
					his ankle while coming down the stairs. The worker went to a City M.D. This incident occurred on July 5, 2018, but the Site Safety Manager was not notified of the								
					incident until July 6, 2018.								
)18	Manhattan	25	PARK ROW	0 1	The Site Safety Manager reported that a worker on the	No Dispatch			NB	121190610	Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	URBAN ATELIER GROUP LLC
					sixth floor was standing on stilts to install track when he walked into a pipe hanger and fell off of the stilts and to								
					the ground. The worker complained of left arm pain. EMS was called and the worker was taken to a nearby								
18	Manhattan	425	PARK AVENUE	0 1	hospital. A DOB inspector reported that a worker stepped on a	ECB Violation	35342980M 81Y 82X 83H		NEW BUILDING	121333921	Worker Fell	T-C 425 PARK AVENUE 11 C	TISHMAN CONSTRUCTION CORP.
10	Wannattan	425	FARKAVENUE	0	piece of unsecured plywood on the second floor and fell	ECB VIOLALION	35342960Wi,611,62A,63F		NEW BOILDING	121333921	Worker Pell	1-C 425 PARK AVENUE, LLC	TISHMAN CONSTRUCTION CORP
					approximately twenty two feet to the first floor. The								
					worker was taken to a hospital, and its reported to have suffered a dislocated hip. Four ECB Violations were								
					issued: one violation for the presence of floor openings								
					that were not securely covered and marked, a second violation for the presence of very poor housekeeping								
					throughout the building, for the absence of perimter								
					protecting at various places and vertical netting, and for								
					a failure to safeguard persons and property. A full Stop Work Order (FSWO) was also issued.								
					Work Order (PSWO) was also issued.								
18	Manhattan	215	PEARL STREET	0 1	A DOB inspector reported that a worker was using a baker scaffold on the twenty fifth floor to perform tapping	ECB Violation	35331468J		121017559	NEW BUILDING	Worker Fell	LAM PEARL STREET HOTEL LLC	ANTHONY T. RINALDI LLC
					work. The scaffold was not properly erected, the wheels								
					of the scaffold were not properly placed, and there were housekeeping issues present in the work area. As a								
					result, the worker fell approximately six feet off of the								
					scaffold. The worker was found conscious and was taken to a hospital for a checkup. An ECB Violation was								
					issued for the presence of poor housekeeping under the								
					scaffold. A partial Stop Work Order (PSWO) was issued								
					for all work on baker scaffolds. The General Contractor is to provide a Means and Methods for safe operation.								
118	Markana -	1227	BROADWAY			FORMAL	35345150R, 51Z, 52K			121191986	Marcal Part	YJL BROADWAY HOTEL LLC	FLINTLOCK CONSTR SERV LLC
18	Manhattan	1227	BROADWAY	0 1	A DOB inspector reported that a worker was installing rebar inside of column cages on the sixteenth floor. The	ECB Violation	35345150R, 512, 52K		NEW BUILDING	121191986	Material Fell	YJL BROADWAY HOTEL LLC	FLINTLOCK CONSTR SERV LLC
					worker was installing an eighteen foot long.								
					approximately one hundred pound piece of rebar all by himself. When he listed the rebar about three feet, he								
					lost control of the rebar and was thrown to the floor. The								
					worker suffered a dislocated shoulder and was taken to a hospital. Three ECB Violations were issued, including								
					a violation for the failure to maintain safety measures								
					and a violation for the failure to provide a DOB-approved design drawing for climbing form work. A partial Stop								
					Work Order (PSWO) was also issued.								
2018	Bronx	603	JACKSON AVENUE	0 1	The Site Safety Manager reported that a worker fell form	No Dispatch			NEW BUILDING	220151840-01-NB	Worker Fell	HP JACKSON AVENUE HOUSING DEVE	GALAXY GENERAL CONTRACTIN
					a baker scaffold. The worker was experiencing back pain and was taken to a hospital.								
018	Manhattan	111	LEROY STREET	0 1	The Site Safety Manager reported that an electrical	No Dispatch			NB	122622992	Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	PMG CONSTRUCTION GROUP LL
					worker was on the roof and using a band saw when he								
					cut his middle finger one inch deep. The worker was alert and conscious and was taken to a nearby hospital								
					for treatment.								
018	Manhattan	315	EAST 46 STREET	0 1	A DOB inspector reported that a signal man was giving signals to a crane operator that was operating a mobile	No Action Necessary			CN	392/18	Mechanical Construction Equipment	GOVERNMENT OF THE UNITED ARAB	Urban foundation engineering IIc
					crane that had a a load on its hook. While giving								
					signals, the signal man got his glove caught inbetween the crane's main hoist cable and the sheave of a load								
					the crane's main hoist cable and the sheave of a load block. The signal man suffered a severed left pinky								
					finger and was taken to Bellevue Hospital. The inspector								
					reported that the crane operator was in possession of a sixteen hour rigging card and had all required								
					certifications, paper work, and logs on site. The other								
					members of the work crew were also in possession of								
					sixteen hour rigging cards. No enforcement action was deemed necessary, as it was determined that the								
					incident occurred as the result of a worker error.								
018	Queens	36-18	MAIN STREET	0 1	The Site Safety Manager reported that a roofer got	No Dispatch					Other Construction Related Incidents	134-22 35TH AVE., LLC	
					some waterproofing material in his eyes while he was spraying. The roofer walked to an urgent care center.								
2018	Brooklyn	1520	FULTON STREET	0 1	The Site Safety Manager reported that a plumber that	No Dispatch				_	Other Construction Related Incidents	HELLO FULTON LLC	
					was working in the basement slipped on water that was								
					on the floor and hurt his knee. The worker went with another worker by car to see a doctor.								
2018	Brooklyn	170	BUFFALO AVENUE	0 1	The Site Safety Manager reported that a worker fell from	No Dispatch					Other Construction Related Incidents	BUFFALO AVE. REALTY ASSOCIATES	
2010	Drookiyil	170	BOITALO AVENUE	0 1	an "A"-Frame ladder and hurt his ankle. The worker	NO DISPAICH					Other Construction Related incidents	BUT ALU AVE. REALTT ASSOCIATES	
			EAST 70 STREET		went to a hospital by ambulance. The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NY 70TH STREET LLC, A NY LLC,	
2019	Manhattan												
2018	Manhattan	19	EAST /0 STREET	0 1	carrying a pail of sweeping compound on his shoulder	NO Dispateri					Other Construction Related incluents	NT JOIN STREET ELC, A NT ELC,	
018	Manhattan	19	EAST /0 STREET	0 1	The Site Safety Manager reported that a worker was carrying a pail of sweeping compound on his shoulder when he lost control of the pail and the pail fell on his right leg. The worker was sent to a hospital.	NO DISPACT						NT JOIN STREET LLC, ANT LLC,	



Cident Date	Borough	Address Number	r Street	Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0/2018	Manhattan	218	EAST 16 STREET	0 1	The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	SOCIETY OF FRIENDS	
					cutting off a tie-wire from an extension cord when he cut								
					his hand with a cutting knife. The worker had his								
					protective gloves on, but the knife went through the top of the glove, between the thumb and index finger. An								
					ambulance was called.								
018	Manhattan	524	RIVERSIDE DRIVE	1 0	A DOB inspector reported that a piece of the suspended	DOB Violation		071218CER01KC	ALTERATION TYPE 2	122012027-01-EW-OT	Scaffold/Shed/Fence/Shoring/Installation	INTERNATIONAL HOUSE	PRATT CONSTRUCTION & REST
010	Mainatan	524			scaffold system became dislodged at the roof level, fell	DOD VIOIAUOII		0/12/00ER01RC	ALTENATION TITLE 2	122312027-01-200-01	Scalidid Shedri encershoning installation	INTERNATIONAL HOUSE	river construction a rest
					twelve stories, and struck a workder in the head. The								
					worker was taken to the nearest hospital in critical								
					condition, but later succumbed to his injuries. A DOB Violation was issued for a failure to safeguard and a full								
					Stop Work Order (FSWO) were issued.								
					Stop Work Older (1 SWO) were issued.								
/2018	Brooklyn	138	WILLOUGHBY STREET	0 1	A DOB inspector reported that there were workers using	ECD Vieleties	35322622Y	071318CERSM01	NEW BUILDING	321197085-01-NB	Other Construction Related Incidents	NYC HPD	LEND LEASE (US) CONSTRUCT
2018	BIODRIYII	130	WILLOUGHBY STREET	0	chainfalls to move on the ground the collar of a crane in	ECB VIOLALION	333226221	0/1316CER3M01	NEW BUILDING	32119/003-01-IND	Other Construction Related incidents	NTCHED	LEND LEASE (US) CONSTRUCT
					order to position it into a better working position as part								
					of a crane jumping operation. While the collar was being								
					moved, one of the worker's legs was pinned between								
					the collar and a piece of the building. The worker was taken to Methodist Hospital by ambulance. The crane								
					was not being used as of the time of the incident. The								
					inspector reported that incident was caused by the use								
					of inadequate means and methods in rigging by the								
					Master Rigger. An ECB Violation was issued for a failure to safeguard. A DOB Violation was also issued.								
					to sareguard. A DOB violation was also issued.								
_													
/2018	Manhattan	20	WEST 40 STREET	0 1	The New York City Fire Department requested that an inspection please be performed because a construction	ECB Violation	35326871N				Other Construction Related Incidents	NOT ON FILE	
					inspection please be performed because a construction worker suffered a head injury after coming into contact								
					with a grinder. The worker was in stable condition and								
					suffered a broken nose. The worker was transported to								
					a hospital by EMS and received butterfly stitches on his								
					forehead. The worker was released from the hospital after treatment. A DOB inspector responed to the								
					incident and visited the site and reported that the grinder								
					was used contrary to the manufactuer's specifications.								
					An ECB Violation was issued for the failure to maintain								
					safe operations. A partial Stop Work Order (PSWO) was								
					issued on the use of all grinders. A Means and Methods and a Tool Box Talk must be provided.								
					and a Tool Box Talk must be provided.								
		24-16	QUEENS PLAZA SOUTH									24-16 QUEENS PLAZA PROPERTY OW	
6/2018	Queens	24-16	QUEENS PLAZA SOUTH	0 1	The Site Safety Manager reported that a worker on the top of a deck at the twenty third floor was cut on his arm	No Dispatch					Other Construction Related Incidents	24-16 QUEENS PLAZA PROPERTY OW	
					by a circular saw. The worker was taken to a hospital by								
					ambulance.								
5/2018	Manhattan	9	ORCHARD STREET	0 1	The Site Safety Manager reported that a worker hurt his	No Dispatch					Other Construction Related Incidents	NINE ORCHARD PARTNERS, LLC	
					back while placing a chipping gun on the floor. An								
	4				ambulance was called.								
/2018	Manhattan	50	AMSTERDAM AVENUE	0 1	The Project Manager at the site reported that a female worker tripped on a temporary electrical conduit that was	ECB Violation	35343201Z, 35343202K.	71818EE107RID01, 71818EE107RID02			Worker Fell	NYC HOUSING AUTHORITY	
					laying on the roof of the building. The worker suffered								
					bruised knee and a swollen wrist and was taken to a								
					hospital by ambulance. A DOB inspector responded to								
					the incident and visited the site and issued two ECB								
					Violations: one violation for the presence of an unsupported aluminum pipe, and a second violation for								
					there being no equipment ground provided for the								
					disconnect of 200 amps that ran between the basement								
					and the rooftop sub panel. Two DOB Violations were								
					also issued.								
/2018	Manhattan	36	GROVE STREET	1 0	A DOB inspector reported that a worker was performing	ECB Violation	35315697N, 35315698P & 35343200R	71618EE102RID01, 71618EE102RID02 &			Other Construction Related Incidents	LUKE, TIMOTHY	
					an electrical installation on an energized circuit in the			71618EE102RID03					
					bathroom. The worker suffered an 120 volt electrical								
					shock. The worker was taken to Lenox Hill Health Plex, where he was pronounced dead. The inspector reported								
					where he was pronounced dead. The inspector reported that the worker failed to de-energize the circuit before								
					performing the electrical installation. Three ECB								
					Violations were issued: one violation for the presence of								
					unapproved and unsafe wiring that had not been								
					terminated, unsupported boxes, unsecured splice								
					hoves the failure to provide a GECL and the failure to								
					boxes, the failure to provide a GFCI, and the failure to provide a lamp guard for temporary lights, one violation								
					provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one								
					provide a lamp guard for temporary lights, one violation								
					provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one								
					provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage.								
2018	Brooklyn	25	COLUMBIA HEIGHTS	0 1	provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage. The Site Safety Manager reported that an electrician cut						Other Construction Related Incidents	25-30 COLUMBIA HEIGHTS BROOKLY	
/2018				0 1	provide a lamp guard for temporary lights, one violation for the failure to post an electrical apernit, and one violation for the use of an electrical room as storage. The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was driven to a hospital.								
	Brooklyn Manhattan	25	COLUMBIA HEIGHTS GREENWICH STREET	0 1	provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage. The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was driven to a hospital. The Site Safety Manager reported that a worker was						Other Construction Related Incidents Other Construction Related Incidents	25-30 COLUMBIA HEIGHTS BROOKLY VS 125 LLC	
2018				0 1	provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage. The Site Safety Manager reported that an electrician cut his arm while waiking by a sharp object. The worker was driven to a hexplail. The Site Safety Manager reported that a worker was performing a window installation when he flipped over a								
				0 1	provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage. The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was driven to a hospital. The Site Safety Manager reported that a worker was								
				0 1	provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage. The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was driven to a hospital. The Site Safety Manager reported that a worker was performing a window installation when he flipped over a piece of tube stelland got his most finger caught between the tube stelland the floor. The tip of the worker's index finger was crusted. The worker went to a								
2018	Manhattan	125	GREENWICH STREET	0 1	provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage. The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was driven to a hoopfail. The Site Safety Manager reported that a worker was performing a window installation when he flipped over a piece of tube steel and got his index finger caught between the tube steel and the flore. The worker went to a hospital by taxi.	No Dispatch					Other Construction Related Incidents	VS 125 LLC	
				0 1	provide a lamp guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage. The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was driven to a hospital. The Site Safety Manager reported that a worker was performing a window installation when he flipped over a piece of tube stelland got his most finger caught between the tube stelland the floor. The tip of the worker's index finger was crusted. The worker went to a	No Dispatch							



ncident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/18/2018	Brooklyn	422	FULTON STREET	0 1	Course resources in the second						Other Construction Related Incidents	NOT ON FILE	
/18/2018	Manhattan	214	WEST 29 STREET	0 1	A competent person at the site reported that a worker slipped off an "A"-Frame ladder. The worker went to a hospital for a check up.	No Dispatch					Other Construction Related Incidents	WALSAM TWENTY-NINE CO	
/18/2018	Manhattan	24	2 AVENUE	0 1	The Site Safety Manger reported that a worker stepped on a nail. The worker walked to medic care for a check up.	No Dispatch					Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	
/18/2018	Queens	147-40	ARCHER AVENUE	0 1	The Site Safety Manager reported that a worker was walking down a flight of stairs when he lost his balance on the bottom step and hurt his right foot. The worker went to urgent care on his own.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/19/2018	Brooklyn	420	UNION STREET	0 1	The Construction Superintendent reported that an electrician that was working on a School Construction Authority (SCA) project cut his right thumb. The electrician went to an out patient clinic.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
/19/2018	Manhattan	140	ESSEX STREET	0 1	The Construction Superintendent reported that during a drilling operation, a section of a drill bit let all and hit a worker in the back. The worker was awake and conscious and was able to walk, but paramedics put the worker on a strettecher and took him to a hospital. The foreman at the site also went to the hospital to check on the worker. The Construction Superintendent reported that the worker had suffered minor bruises, with no broken bones, and was released from the hospital. A DOB inspector responded to the incident and visited the site and reported that the Construction Superintendent's license had explored. An ECB Volation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued.		353962632		FO	121187642	Material Fell	SITE 8 DSA HOUSING DEVELOPMENT	Essex Site 8 Builders LLC
/19/2018	Manhattan	625	WEST 125 STREET	0 1	The Site Safety Manager reported that a worker was installing a light fixture when he tripped over the light fixture and hurt his knee. The worker went to a hospital hy ambulance	No Dispatch					Other Construction Related Incidents	THE TRUSTEES OF COLUMBIA UNIVE	
/20/2018	Manhattan	30	EAST 31 STREET	0 1	The Site Safety Manager reported that a pedestrian was entering her building when she was hin in the head by a piece of debris that fell from a construction site. The adeblance was called. A DOB inspector responded to the incident and visited the site and and issued an ECB Volation for a failure to safeguard. A partial Stop Work Order (PSWO) on all concrete work operations was also issued. A Mean and Methods for sale operations must be provided.		35342859K				Other Construction Related Incidents	31ST STREET ZEF LLC	
/21/2018	Brooklyn	3514	SURF AVENUE	0 1	A DOB inspector reported that a worker was stripping phycod with twe workers coming from behind him. The worker that was performing the stripping did not notify the other workers that he opened a hole, and the worker that was performing the stripping operation fell two stories through the hole. The worker was found conscious and was taken to an area hospital. The inspector observed that the protocol for a pre-task meeting for stripping operation was not followed up, and that there were house keeping issues present at the top floor that were recorded by the Site Safety Manager. There ECB Violations were issued: one violation for the failure to maintain or institute safety measures for construction operations, and one violation for the failure to maintain or institute safety measures for construction operations, and one violation for the failure to provide a Professional Engineering letter or design drawing for protection at large siab openings. Three DOB Violations were also issued. A partial Stop Work Onder (PSWO) was issued on concrete and stripping operations. A Meens and Methods for the safe continuation of work must be provided.		3534286014613/62/	072118B\$13EP01/02/03			Worker Fell	RED APPLE SURF REALTY III LLC	
/23/2018	Manhattan	545	WEST 30 STREET	0 1	The Site Safety Manager reported that a worker was in the hoist with equipment when he got his foot caught under the equipment. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
/23/2018	Manhattan	401	WEST 31 STREET	0 1	A DOB inspector reported that there was work being advantmed under the strent level for the nervox of of existing Antrak tracks and the installation of new steel of the relocation of an existing sub-station. An inon worker was installing steel desking when he fell approximately ten feet through a gap and suffered a fractured arm. The worker was found in stable condition and with his harmess on, as the harmess had to be cut off by EMS. The worker was taken to a hooghal. An EOB Volation was also issued. A partial Stop Vivo. Ovder (PSWO) was issued for all steel work being performed for the relocation of a sub-station.	ECB Violation	35245391J	072318CNEDB01	A2 - ALTERATION TYPE 2	123091705	Worker Fell	BOP WEST 31ST STREET LLC	JOHN CIVETTA & SONS INC



cident Date	Recourse	Address Number	Street	Entelliting Internet	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/2018	Borougn Manhattan	217	WEST 57 STREET	o 1	EUC Final Description The Site Safety Manager reported that there were workers that were backing up a trailer on the job site with flaggers when a bicyclist went around the flagger, slipped on wet pavement, and hurt his arm. The pavement was wet because of rain. The bicyclist did not hit the trailer. An ambulance was called.	No Dispatch	ELB Violation Numbers	DUB Violation Numbers	Permit	Permit No	Other Construction Related Incidents	SMITELL SPONSOR LLC	
/2018	Manhattan	152	EAST 87 STREET	0 1	A worker fell back and scrapped his arm against a trash chute. The worker went to a hospital for treatment. The worker received two stitches and returned to work.	No Dispatch					Other Construction Related Incidents	ALLAN GARAGE,	
2018	Manhattan	150	EAST 38 STREET	0 5	A DOB inspector reported that contractors were performing interior demolition work on the fourth floor when the wood and plaster certification collapsed and injurce. Five workers. Two of the workers were in serious condition and were taken to Bellewue Hospital. No structural damage was observed. An Aggravated Level 2 ECB Violetion was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued.		35343417H		Alt 1	123254263	Other Construction Related Incidents	SUN, ANGELA	zzz carpentry Inc
/2018	Manhattan	19	EAST 70 STREET	0 1	A DOB inspector reported that during the hoisting of pipe scaffold frames from the fifth floor down to the interior of a stairs shaft, one of the frames got boes and hit the Construction Superintendent in the head on the second floor, knocking him unconscious. The worker was taken to Presbyterian Hospital in stable condition. Two ECB Volations were issue: one violation for a failure to safeguard all persons affected by construction operations, and one violation for work being performed that did not conform to approved plans. A partial Stop Work Norder wai issued for material hoist work and for supported scaffold work.		35324422Z - 35324423K		Ait 1	121944227	Material Fell	NY 70TH STREET LLC, A NY LLC,	Sweeney & Conroy Inc
2018	Manhattan	315	EAST 46 STREET	0 1	The Site Safety Manager reported that a worker performing form work when he got his finger pinched during an installation and suffered a cut to his finger. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
/2018	Queens	43-12	HUNTER STREET	0 1	The Site Safety Manager reported that a worker in the basement cut his right eye while moving rebar. The worker went to a City M.D. with a co-worker.	No Dispatch					Other Construction Related Incidents	43-12 HUNTER LLC	
2018	Staten Island	546	GULF AVENUE	0 1	The Site Safety Manager reported that a worker was experiencing back pain. The worker left the site to go to a hospital on his own.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Staten Island	546	GULF AVENUE	0 1	a hospital of the own. The Site Safety Manager reported that a steel worker was using a chain when the chain slipped out of his hand and pinched his left finger. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
/2018	Manhattan	250	SOUTH STREET	0 1	The Site Safety Menager reported that an into worker was on a mult fland working on a small piace of steel clip that was approximately 27 A4" when he load control of the clip and feel approximately 29 misdle the job site. A DOB inspector responded to the incident and visited the site and reported that the worker suffered a minor ripury to his shoulder from the steel clip when the clip fell. The worker did not report the highly and left the site without letting anyone know. An ambulance was not called. The worker later reported that the went to see a dootor. An ECB Violation was issued for the failure to institute safety messures. A DOB Violation and a partial Stop Work Order (PSWO) were also issued.		35331357R	07261885/03JJ01			Material Fell	NOT ON FILE	
/2018	Manhattan	215	PEARL STREET	0 1	The Site Safety Manager reported that a worker was standing on a ladder that was behind a dosed door when another worker openet the door and knocked the worker off of the ladder. The worker hit his head, and a mubulance was called. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for a failure to institute safety measures. A DOB Violation was also issued. A partial Sop Work Order (FSWO) was issued on all door dosure installations. A Neans and Methods and a safe Controlled Access Zone area for ladder work during an installation must be provided.	ECB Violation	35342769R	072618BS01KR02			Worker Feil	LAM PEARL STREET HOTEL LLC	
/2018	Manhattan	438	WEST 54 STREET	0 1	A DOB inspector reported that a worker was on a truck and receiving planks while dismanting a sidewalk shed when he lost his footing and fell off of the truck and onte a pedestrian. The pedestrian received aid from the onste Sidewalk Shed company. The Borough Scatfolding. The pedestrian requested medical treatiment. The FDW responde to the request and visited the site, and examined both the worker that fell from the truck and the pedestrian. The worker works determined to be okay and returned to work. while the pedestrian as identor to a failure to safeguard to perform a size projectivy, and ne violation for a failure to provide size projective, and ne violation for a failure to provide size size projective, and ne violation for a failure to provide size size projective, and ne violation for a failure to provide size wark shed as required. And Stop Woh Order (FSWO) was also issued.		35324486H - 35324487J		NB	122822605	Worker Fell	15024 EMMUT PROPERTIES LLC	Best Point Mgmt Corp
10/2018	Bronx	1812	VYSE AVENUE	0 1	The Site Safety Manager reported that a worker was moving pipes when his right middle finger got caught between pipes. The worker went to the emergency room with his supervisor. An ambulance was not called.						Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	



ident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0/2018	Bronx	4511	3 AVENUE	0 1	The Site Safety Manager reported that a plumber was	No Dispatch					Other Construction Related Incidents	STB HOUSING DEVELOPMENT FUND C	
					tightening a sprinkler pipe when he hit a stud and cut his finger. The worker walked to urgent care across the street from the job site								
)18	Manhattan	110	UNIVERSITY PLACE	0 1	The Site Safety Manager reported that a worker was on	No Dispatch					Worker Fell	NOT ON FILE	
010					a ladder when he mis-stepped, fell off of the ladder, and pulled his back at. The worker went to urgent care.	no ospaton							
018	Manhattan	122	EAST 23 STREET	0 1	The Site Safety Manager reported that a cleaning person was cleaning the apartments when site went down to the cellar, where there was construction work being performed. The cleaning person stepped walked off of the elevator and hit her foot on a man-fitt hat was left in the basement. The man-fitt was in the basement because it was being used in construction work that was being performed. The cleaning person went to urgent care on her own.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
)18	Manhattan	233	WEST 125 STREET	0 1	SThe Site Safety Manager reported that at a twenty six story new building that was under construction, a worker was cutting rebar with a chop saw when a fragment of the rebar hit him in the face. The worker did not appear to suffer any cuts. The worker went to see a private doctor.				NB	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
2018	Brooklyn	269	4 AVENUE	0 1	The Site Safety Manager reported that at the foundation level of a twelve story new building, a worker was loading in plywood material when he pinched his left pinky finger between plywood. The worker was found alert and conscious and was taken to Lutheran Hospital for treatment.	No Dispatch			NB	320596805	Other Construction Related Incidents	FIRST BUILDING ENTERPRISES LLC	NEW EMPIRE BUILDER CORP
018	Manhattan	26	ANN STREET	0	1 The Site Safety Manager reported that a worker was using a utility knife when he accidentally cut himself by mistake. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	143 FULTON STREET DEVELOPMENT	
/2018	Manhattan	77	WEST 56 STREET	0	1 A DOB inspector reported that there were workers that were in the process of installing as idewalk shed on top of a baker scalid when one of the workers lost his footing and fell. During the fall, the worker lost his hard hat and bumped his forehad on a mud all. The worker was found conscious and was taken to a local hospital. Two ECB Volations were issued to the General Contractor at the site: one violation for a failure to safeguard all persons and property affected by construction operations, as the supported scalidot did not feature any quardrails, and a second violation for a failure to provide a four hour supported scalidot user entiticate. A partial Stop Work Order (PSWO) was also issued.	ECB Violation	35324558H, 35324553Z		Ait	M00050141	Worker Fell	GALLERY HOUSE CONDOMINIUM	Phonex Sutton Str Inc
018	Queens	110	UNIVERSITY PLACE	0	1 A DOB inspector reported that there were workers that were moving an ¹ A-Frame ladder that was overloaded not be higher and that the set of the workers. That the more behaviour and feat of one of the workers. That the west taken to Bellevue Hospital by ambulance for treatment. Two EOB Violations were issued: one violation for the presence of unsafe working conditions and equipment, and a second violation for the absence of manufacture specifications for the "A-Frame. A partial Stop Work Order (PSWO) was issued on all use of 'A'-Frame ladders. A Tool Box Taik and a sequence for the handling of materials must be provided.		35345140N,41P		NB	121187241	Other Construction Related Incidents		CNY CONSTRUCTION LLC
018	Brocklyn	3021	WEST 25 STREET	0	1 A DOB inspector reported that during the alteration of an existing building, a worker was using an excervator to organize piping, while there was another worker that was standing behind the excervator. The excervator backed up without notice, and the worker that was ad by the bucket of the excervator. The worker that was ad by the bucket of the excervator. The worker thans found after and conscious and was taken to a nearby hospital. An ECB Violation was issue for the presence of unsale conditions and equipment. A partial Stop Work Order (PSWO) was issued on handling material and plumbing operations.		EOB#353161125M- UNSAFE CONDITIONS AND EQUIPMENT	080218B\$13KR01	NB	321447243	Excavation/Soil Work	NYC HOUSING AUTHORITY	AWL INDUSTRIES INC
2018	Manhattan	1	WALL STREET	0	1 The Site Safety Manager reported that a worker hit his left eye while removing form work. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
2018	Manhattan	621	GREENWICH STREET	0	The Project Manager at the site reported that a worker was on a scatfold when he slipped and fell while trying to move away from the rain. The worker hurt his shoulder and was taken to a hospital by EMS.	No Dispatch					Worker Fell	PMG LEROY STREET DEVELOPMENT L	



	P		0	Frankling Industry	500 5	DOD 4-41-1	FOR Weiter March 1	DOD Wale for New Loss	B14	Description of the	to at the set The set	a made Name	2
ncident Date //3/2018	Borough Manhattan	Address Number 441	Street 9 AVENUE	Fatalities Injuries	1 The Site Statety Manager and a DOB inspector reported that a worker was working on a dock when he unhooked his fall arrest system, lost his balance, ack when he unhooked his fall arrest system, lost his balance, and the ungent care, and the urgent care center called an ambulance to transport the worker to a hospital. The Site Statety Manager was not informed of the incident until the end incident tempetality to the Dapartment of Buildings because he wanted to have all of the facts of the incident tempetations.		ECB Violation Numbers 35345468RV692/70X/71H/72J	DOB Violation Numbers 0804188504GD03/04/05/06/07	Permit	Permit No	Incident Type Worker Foll	Owner's Name CBP 441 NINTH AVENUE OWNER, LL	Contractor Name
					issued, including one violation for the unsafe storage of accelytien and oxygent tanks, one violation for poor housekeeping, one violation for the presence of unsequer dreshore at the leading adge, and one studies of the incident in a timely manner. Five DOB Violations were also issued.								
/3/2018	Manhattan	110	CHARLTON STREET	0	1 The Site Safety Manager reported that two workers were carrying rebar on the first floor when one of the workers lost his balance and hurt his shoulder. The injured worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	
/3/2018	Manhattan	10	VANDERBILT AVENUE	0	The Site Safety Manager reported that a worker was coming down the stairs when he tripped and fell. The worker suffered a laceration to his back. EMS took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	ONE VANDERBILT OWNER LLC	
/3/2018	Brooklyn	2442	OCEAN AVENUE	0	1 The Site Safety Manager reported that a worker was looking for a shovel when he slipped on form work in the cellar. The worker did not notify the Site Safety Manager of the incident until three hours after the incident occurred. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	2442 OCEAN AVENUE, LLC	
/3/2018	Brooklyn	10	NEVINS STREET	0	The Site Safety Manager reported that a worker was handling duct work when he cut his hand on sheet metal. The worker was found conscious and alert and was taken to Brooklyn Hospital for treatment. The worker required several stitches.	No Dispatch			NB	320915578	Other Construction Related Incidents	NEVINS STREET OWNER LLC	DANYA CEBUS CONSTRUCTION
/3/2018	Bronx	316	EAST 165 STREET	0	2 A DOB impector reported that a side bracket for a supported scaffield collapsed at the third floor level with two workers that were laying bricks. The workers landed on the working level below, suffered minor injuries, and went to Bronx Care Health System Hospital. The collapse was caused by a loose damp for the side bracket. As of the tims of impection, the working level way to back squares that the side bracket. As of the tims of the side bracket. As of the tims of impection, the working level may to back squares that the side bracket and the side part care to the side of the side bracket and the side part. So with the side of the side bracket is a side of the performed that was not in accordance with approved plans, one violation for the failure to you ed the workers involved in the collapse to provide a supported scaffold the side of the supported scaffold being in possession of equipment that was related to the construction incident equipment that was related to the construction incident uncode scaffolds was also issued.	EOB Violation	353448147, 35344815H, 35344816J, 35344817L		NB	220819150	Worker Feil	CG EDUCATIONAL HOLDING CORP.	Hollister Construction Se
/6/2018	Manhattan	2	PARK PLACE	0	The Site Safety Manager reported that at an Alteration 1 job at alffy eight story building, on the twenty-ninth floor, a worker mis-stepped while stepping onto a landing and twisted his ankle. The worker was found conscious and ealert and was taken to New York Prebyterian Hospital for treatment.	No Dispatch			ALT 1	121333413	Worker Fell	NOT ON FILE	CNY CONSTRUCTION LLC
/6/2018	Manhattan	445	WEST 36 STREET	0	1 The Site Staty Manager reported that a worker was reping physical with a tablease when he cut his hand by accident. The worker was taken to a hospital. A DOB inspector responded to the incident and visited the site and reported that the worker was using a cordiess circular saw as per the manufacturer's specifications. Because of this, it was determined that the incident occurred as the result of a worker's error, and that no enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	CARE REALTY CORP.	
/7/2018	Queens	45-57	UNION STREET	0	The Site Safety Manager reported that a worker was moving metal angles around the site when he cut his arm on one of the metal angles. The worker went to an emergency room on his own.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
/7/2018	Manhattan	60	WEST 129 STREET	0	1 A DOB inspector reported that approximately twenty four feet of parapet fell onto a public street. A pedestian suffered an unconfirmed injury. The pedestitan was treated at the scene and released. An ECS Violation was issued for a failure to safeguard. A DOB Violation was also issued.	ECB Violation	35323035Y	080718CERSM01	A2 - ALTERATION TYPE 2	121230382	Scaffold/Shed/Fence/Shoring/Installation	LENOX LLC	D&L DESIGN & BUILD LLC
/7/2018	Manhattan	130	WILLIAM STREET	0	The Site Safety Manager reported that a worker fell and hurt his chin while picking up rebar. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	



ident Date	Borough	Address Number		Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhatlan	108	EAST 89 STREET	0	1 A DOB inspector reporter that a worker was on the wealth floor installing insulations inside of particles He atterngted to move some sheetrook that was behind a stack of heartook that was learning against the wall in order to install insulating material when a stack of sheetrook tell on his anklo. The worker did not appear to have any visible injury, but complained of pain. The worker's forement action was deemed necessary, as it was determined that this incident occurred as the result of worker error.	No Action Necessary				122988623	Material Fell	DALTON SCHOOLS INC	E.W. HOWELL CO, LLC
2018	Brooklyn	277	SOUTH 5 STREET	0	1 The Site Safety Manager reported that a worker was stripping form work in the basement when a piece of plywood hit tim in the shoulder. The worker went to a hospital by ambulance for a check up. The Site Safety Manager also reported that the worker will be returning to work.	No Dispatch					Other Construction Related Incidents	HAVEMEYER OWNER LLC	
/2018	Brooklyn	2401	AVENUE Y	0	1 The Project Manager at the site reported that a worker opened a not horith and fell approximately thirteen and a half feet through an opening. The worker suffered a fractured polysis and ellow. A DOB inspector responded to the incident and visited the site and reported that no quardrails were provided around the opening at the root, which caused the worker to fail. An ECB Violation was issued for the failure to safeguard all persons and/or property affected by construction operations. A full Stop Work Order (FSWO) was also issued.		35350727M	080918BS15LJ06			Worker Feil	PARKS AND RECREATION (GENERAL)	
2018	Brooklyn	555	4 AVENUE	0	The Site Safety Coordinator reported that a worker was moving rebar when he hit himself in the mouth and chipped his tooth. The worker went to a medical office on his own.	No Dispatch					Other Construction Related Incidents	PARTNERS VI/541-555 FOURTH OW	
V2018	Staten Island	546	GULF AVENUE	0	on his own. 1 A DDB inspector reported that a worker was in the process of pulling a rope inside of a pull box that was next to an electrical panel. Three was a knile laying inside of the panel. While the worker was pulling the rope, the vibration caused the knile inside of the panel the electric phases, which caused a short that produced the electric phases, which caused a short that produced the electric and the single of the knile was either receiving an electrical shock or had suffered an injury from the arching. Because of this, the other worker kicked the worker that was nipped by the knile was either receiving machine, rendering him unconscious. The worker was taken to a hospital, where he was kept for observation. No enforcement action was deemed necessary.	No Action Necessary					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Manhattan	787	11 AVENUE	0	1 The Site Safety Manager reported that an electrician was cutting a pipe with a bend saw when he cut his finger tip. The worker went home to see his doctor. A co worker went with him.				ALTERATION-1	121190399	Other Construction Related Incidents	GEORGETOWN ELEVENTH AVENUE OW	CAULDWELL WINGATE CO LLC
W2018	Brooklyn	2527	CHURCH AVENUE	0	1 The Construction Superintendent reported that a worker fell on the first floor. The worker was taken to a hospital by ambulance. A DOB inspector responded to the incident and visited the site and reported that no one at the site know the worker's name, and that there was no report of the incident given. An ECB Violation and a full Stop Work Over (FSWO) were issued for a violation of the responsibility for safety under Building Code Chapter 3301.1.1.		35332476Y				Other Construction Related Incidents	2527-2529 CHURCH GROUP LLC	
2018	Brooklyn	211	MCGUINESS BOULEVARD	0	1 A DOB inspector reported that at the construction of a new rine story realisticitial building, there was a pipe scaffold that was in the process of being removed. While the workers were taking down the sideand end bracket from the subth floor level of the scaffold with a standing on the fourth floor of the scaffold by his had. The struck worker was found conscious and responsive and was taken to a local hospital for a check up. Two ECM Voltations were itsued; one and the scaffold in the scaffold voltations and responsive and was taken to a local hospital for a check up. Two ECM Voltations were issued; one Agravated Level 2 ECM Voltation for a failure to scaffold privation of the installation of node (FSWO) for the dismantling of a supported scaffold was also issued.		35351651X - 35351652H		Ait 3	340442550	Scaffold/Shed/Fence/Shoring/Installation	MCGUINNESS DEVELOPMENT LLC	Rock Group of NY Corp
2018	Bronx	300	HUTCHINSON RIVER PARKWAY	0	1 The Construction Superintendent reported that an electrician at the site was on an "A"-Frame ladder when he missed a step, fell, and hurt his foot. The electrician was taken to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	PARKS AND RECREATION (GENERAL)	



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Bronx	2028	WEST CRESTON AVE	0	1 The Site Safety Manager reported that a worker was using a wire around a pipe when he lost his gipt and the wire stild, hitting him on the side of the head. The Site Safety Manager reported that a worker was using a wire around a pipe when he lost his grip and the wire slid, causing the pipe to hit him on the side of the head. An ambulance was called.						Other Construction Related Incidents		
9/2018	Bronx	1812	VYSE AVENUE	0	1 The Site Safety Manager reported that a worker was moving a cast iron pipe when he twisted his ankle. The worker went to urgent care for treatment.	No Dispatch					Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	
10/2018	Manhattan	115	DELANCY STREET	0	1 The Site Safety Manager reported that a painter had finished his work using a spray gun and went to clean the machine. The worker had taken of his safety glasses when he disconnected the spray gun from the hose. Dirty water went in the worker's eye. The worker was taken to a hospital by ambutance in order to have his eyes cleaned.	No Dispatch			NEW BUILDING	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
10/2018	Manhattan	1465	PARK AVENUE	0	1 The Site Safety Manager reported that a worker was stropping concrete form work. The worker was led off, but his retractable cable did not release, jerking him but his retractable cable did not release, jerking him busies on his back. Thi worker went to a hospital. A DOB inspector responded to the incident and villed the site and issued an EGB Violation for inadequate safety measures. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued for all form work and stripping certaions. A Means and Methods for safe stripping and form work operations, and to check workers' Pensonal Protection Equipment (PPE), must be provided.	ECB Violation	353156424	081018BS11BG04			Worker Fell	LEX GARDENS II TP4 HOUSING DEV	
10/2018	Manhatlan	553	WEST 30 STREET	0	1 A DOB inspector reported that there was an electrician that was divergenting offen offen the stepped on plywood that was used to cover a floor opening for mechanical duct work. The phywood that was used for the floor covering was not in proper condition and was not secured to the floor. The phywod did not have the capacity to carry the worker's load and when the worker stepped on it. the phywod plk into two parts and his leg went through the opening. The worker's lag was cut by a rebar that was protuding from the floor. The worker was runsported to a hospital by marbulance. An EOS Volstion was issued for the failure to maintain safety measures. A partial Stop Work Order and in proxmity of floor openings and shafts.		35350712X		NEW BUILDING	121184208	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
10/2018	Queens	29-22	NORTHERN BOULEVARD	0	1 A DOB inspector reported that there were workers that were moving a diesel fuel container on a doll when they lost balance on the sidewalk, causing the diesel fuel to spitah a pedestrian that was standing on the sidewalk. The cap of the barel was token and was not closed during its transfer out of the construction site. The pedestin are were moving the a bacyteal or RADs. T do not have a Cartificate Of Finess from the Fire Department. The job did not have a Fire Department permit for the storage and use of diesel fuel at the site. Three ECB Violations were issue: One violation for the failure to safeguard persons and property, one violation for the handing of flarmable liquid without an FDNY Cartificate Of Finess, and one violation for the storage and use of flarmable liquid at the site without an FDNY permit. A pantial Stop Work Order (PSWO) was also rssued.	ECB Violation	35356687N, 35356688P, 35356689R		NEW BUILDING	420650398	Other Construction Related Incidents	OSB NORTHERN LLC	LEEDING BUILDERS GROUP LL
13/2018	Queens	28-07	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker was installing an exterior panel when he cut his finger on a metal clip. The worker went to a clinic.	No Dispatch					Other Construction Related Incidents	LIC SITE B-1 OWNER, L.L.C.	
3/2018	Manhattan	817	BROADWAY	0	1 The Site Safety Manager reported that a worker in the basement was removing some debris when he was stuck in the hand by a hypodermic needle. The worker	No Dispatch					Other Construction Related Incidents	817 BROADWAY OWNER LLC	
13/2018	Manhattan	441	9 AVENUE	0	went to a hospital. The Site Safety Manager reported that a worker fell off of an extension ladder on the seventeenth floor and hurt his head and arm. An ambulance was called and took the worker to a hospital. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for a failure to institute safety measures. A DOB Violation was also issued. 	ECB Violation	35332478H	081318BS04DH02			Worker Fell	CBP 441 NINTH AVENUE OWNER, LL	
13/2018	Brooklyn	814	BEDFORD AVENUE	0	1 A DOB inspector reported that at a new building that was under construction, a worker was working in the basement when his heinert was struck by a failing metal post. The worker was taken to a hospital by ambulance, and was released from the hospital without injury. An ECB Volation was issued for a failure to safeguard the public and property during construction operations. A DOB Violation was also issued. A full Stop Work Order (FSWO) was issued to the job site.	ECB Violation	35323079X	081318CNELC01	NEW BUILDING	321362565-01-NB	Other Construction Related Incidents	814 PARK LLC	PARKVIEW BUILDERS LLC



ident Dete	Borough	Address Numb	er Street	Fatalitian Iniuria	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/2018	Brooklyn	Address Number	HURON STREET	ratainties injurie	1 The Site Safety Manager reported that a worker was		ECB Violation Numbers	DOB Violation Numbers	Fernin	Permit No	Other Construction Related Incidents	10 HURON FS CONDO LLC	Contractor Name
	Diousyn		Indicaterizer	Ū	walking down the stairs when he tripped on the last step and bumped his head. The worker went to a City M.D.	no Dispatori							
2018		249										251 WEST 14 STREET, LLC	
018	Manhattan	249	WEST 14 STREET	0	1 The Site Safety Manager reported that a pedestrian in a wheelchair was going over a ramp in the walkway and	ECB violation	35345323X	081418BS04VP04			Other Construction Related Incidents	251 WEST 14 STREET, LLC	
					flipped backwards in the wheelchair. An ambulance was								
					called. A DOB inspector responded to the incident and								
					visited the site and issued an ECB Violation for the								
					presence of a ramp that was inadequate for wheelchair								
					accessibility. A DOB Violation was also issued. A partial								
					Stop Work Order (PSWO) was issued for the use of a								
					hydrant hose covered by a ramp on a pedestrian								
					walkway.								
18	Brooklyn	308	NORTH 7 STREET		1 The New York City Fire Department requested that an	500.10	35351611L - 35351612N		ND	320597074	Worker Fell	N7 OWNER LLC	Britt Realty LLC
•	BIOOKIYII	308	NORTH / STREET	0	inspection please be performed due to a worker falling	ECB VIOLATION	35351611E - 35351612N		INB	320597074	Wolker Pell	N/ OWNER LLC	Bitti Really LLC
					from a scaffold. A DOB inspector responded and visited								
					the site and reported that the General Contractor was in								
					the process of dismantling a supported scaffold. While a								
					truck as being loaded, the parapet panel from the								
					sidewalk shed collapsed, causing the worker to fall. The								
					worker was conscious and was able to move his arms.								
					The worker suffered minor injuries and was taken to a								
					hospital. Two ECB Violations was issued: one violation								
					for a failure to safeguard, as the work area was								
					overstocked, which caused the parapet panel to								
					collapse, and one violation was issued to the								
					Construction Superintendent for the failure to perform								
					duties, as the Construction Superintendent allowed the								
					work area to become overstocked with materials. A								
					partial Stop Work Order (PSWO) was issued on facade								
					work and the removal of a supported scaffold.								
18	Manhattan	110	CHARLTON STREET	0	1 The Site Safety Manager reported that a worker stepped	No Dispatch			NEW BUILDING	121191263-01-NB	Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	PLAZA CONSTRUCTION LLC
					on a nail. The worker went to urgent care.								
8	Manhattan	1558	3 AVENUE	0	1 The Site Safety Manager reported that a worker on the	ECB Violation	35332462N	081518BS08AD01			Material Fell	180 EAST 88TH STREET REALTY LL	
					twenty-eighth floor was getting ready for his work day								
					when a reshore fell from its position and hit him in the								
					shoulder. The worker went to a City M.D. A DOB								
					inspector was on site as of the time of the incident and								
					reported that there was formwork leaning against the								
					reshores, which caused the reshore that struck the worker to fall. An ECB Violation was issued for a failure								
					to institute safety measures. A DOB Violation was also								
					issued. A partial Stop Work Order (PSWO) was also								
					issued.								
018	Manhattan	233	WEST 125 STREET	0	1 A DOB inspector reported that a worker was cutting	ECB Violation	35316082L		NB	121187447	Material Fell	HARLEM URBAN DVLPMNTCP	Flintlock constrcution IIc
					metal straps to remove drill rods of a bundle during a								
					crane footing installation when the metal straps snapped								
					and a drill rod section rolled down and hit the worker's								
					foot. The worker's foreman called EMS and the worker								
					was taken to a hospital for treatment. The worker did not								
					suffer any broken bones. The worker was later released								
					from the hospital. An ECB Violation was issued for a								
					failure to safeguard. A full Stop Work Order (FSWO)								
					was also issued. The General Contractor was directed								
					to provide a Means and Methods for the loading and								
					unloading of drilling and construction material.								
18	Manhattan	555	WEST 22 STREET	0	1 A DOB inspector reported that a female pedestrian was	ECB Violation	35343881L	081518CERMR01	NEW BUILDING	121204366-01-FO	Other Construction Related Incidents	22ND AND 11TH ASSOCIATES, L.L.	RELATED CONTRUCTION LLC
					sprayed in the face by hydraulic oil while waiting for the								
					bus. The pedestrian was taken to an area hospital by								
					ambulance. A hydraulic oil line had ruptured in the auger	·							
					while cutting for a secant pile wall in the northeast								
					corner of the site on the West 23rd Street side, causing								
					hydraulic oil to spray onto the sidewalk and street. An								
					Aggravated Level 2 ECB Violation was issued for the								
					failure to safeguard pedestrians. A DOB Violation was								
					also issued. A partial Stop Work Order (PSWO) was issued. The contractor is to immediately install concrete								
					issued. The contractor is to immediately install concrete barriers along West 23rd Street, as per the Site Safety								
					Plan, in order to protect pedestrians.								
					,								
						N. B							
	2	00.44			1 The Site Safety Manager reported that a worker was on	NO Dispatch					Other Construction Related Incidents	G & M REALTY, L.P.	
18	Queens	22-44	JACKSON AVENUE	0									
8	Queens	22-44	JACKSON AVENUE		stilts doing taping work when he either tripped or lost his balance and fell, hurting his wrist and ribs. An								
					balance and fell, hurting his wrist and ribs. An ambulance was called.								
8	Queens	22-44	JACKSON AVENUE	0	balance and fell, hurting his wrist and ribs. An ambulance was called. 1 The Site Safety Manager reported that while working on	No Dispatch			NB	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
				0	balance and fell, hurting his wrist and ribs. An ambulance was called. 1 The Site Safety Manager reported that while working on a forty-four story new building, a worker got his foot	No Dispatch			NB	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
				0	balance and fell, hurting his wrist and ribs. An ambulance was called. 1 The Site Safety Manager reported that while working on a forty-four story new building, a worker got his foot caught between formwork at the interior staircase that	No Dispatch			NB	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
				0	balance and fell, hurting his wrist and ribs. An ambulance was called. 1 The Site Satery Manager reported that while working on a forty-four story new building, a worker got his foot caught between formwork at the interior staircase that was being formed at the second floor. The worker was	No Dispatch			NB	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
				0	balance and fell, hurting his wrist and ribs. An ambulance was called. 1 The Site Satety Manager reported that while working on a forty-four story new building, a worker got his foot caught between formwork at the interior staticase that was being formed at the second floor. The worker was taken to Elmhurst Hospital by ambulance for treatment.	No Dispatch			NB	420651912	Other Construction Related Incidents	G & M REALTY, LP.	G & M REALTY L.P
				0	balance and fell, hurting his wrist and ribs. An ambulance was called. 1 The Site Satery Manager reported that while working on a forty-four story new building, a worker got his foot caught between formwork at the interior staircase that was being formed at the second floor. The worker was	No Dispatch			NB	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P



ncident Date	Borough	Address Number	Street	Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/16/2018	Brooklyn	1056	MANHATTAN AVENUE	0	1 A DOB inspector reported that during a support of excavation operation, a welder was injured by a 12° X 12° boulder that fell from the support of excavation walter. The welder was approximately four teef from the ground when he was hit in the shoulder by the boulder. The welder was found conscious and was taken to a hospital for treatment. A CAT scan and a sonogram were performed on the worker, but no internal injuries were found. An Aggravated Level 2 EGB Violation was issued for the failur to asfeguard. A full Stop Work Orde (FSWO) was also issued on support of excavation work and welding operations. The construction has been directed to bring the construction documents in for review.	r	35336524N		NB	321211960	Material Feil	MANHATTAN EAGLE LLC	Empire management and const
16/2018	Manhattan	130	WILLIAM ST	0	The Site Safety Manager reported that two workers wer hanging HVAC duct work when one of the workers lost his balance and the duct work hit him in the head. The worker suffered a cut to his forehead. An ambulance was called.						Other Construction Related Incidents		
16/2018	Manhattan	30	HUDSON YARD	0	1 The Site Safety Manager reported that a worker was moving a man lift when he ran over his own foot. The worker felt slight pain and went to see a medic.	No Dispatch					Other Construction Related Incidents		
17/2018	Manhattan	25	PARK ROW	0	The Site Safety Manager reported that a concrete bugg had stalled and rolled over the machine operator's foot while the operator was exiting the machine. The operator was transported to a local hospital.	y No Dispatch			NEW BUILDING	121190610-01-NB	Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	URBAN ATELIER GROUP LLC
/17/2018	Brooklyn	11	HOYT STREET	0	1 The Site Safety Manager reported that a worker was using a circular saw when the saw kicked back and cut the worker's finger. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	
//8/2018	Manhattan	315	PARK AVENUE SOUTH	0	A DOB inspector reported that there were workers that were working on the ninh floor scalidoling at the exteri- tiven a birck came of and hit a goedestina hit was on the roadway at exposure two. The pedestrain hit was on the roadway at exposure two. The pedestrain hit was in stable condition, but may have possibly suffered two the properties of the stable of the pedestrain hit was in enclosed at the ends, with holes in some locations. Debris was not removed at the end of the shift as of the time of inspection. Three ECB Voldations were issued: one Aggravated Level 2 voltation for a failure to safeguard, one voltation for the absence of an approve Site Safety Plan at the site, and one violation for the absence of an Occupant Protection Plan for the freight, halway, and office spaces. Three DOB Voltations were also issued. A Means and Methods for the safe continuation of work must be provided.	3	35350784P / 89Y / 90L	061318ES06BG050607			Other Construction Related Incidents	COLUMBIA REIT - 315 PARK AVENU	
20/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker was on twelve foot high A ⁻² -Trane ladder on the twelth floor performing duct work when he fell from the ladder and hit his head on a ramp. It is not known from what heigh did the worker fall. The worker was conscious and alert and was taken to Cornell Medical Center for treatment.	:			NB	121328205	Worker Fell	SMITELL SPONSOR LLC	LENDLEASE(US)CONSTRUCTION
/20/2018	Manhattan	540	WEST 53 STREET	0	A DOB inspector reported that a worker was doing exterior work at the second floor level at exposure one when he fell through the gap between the top deck of the sidewalk ked and the face of the building, landing on the ground floor. The worker possibly suffered a broken wrist and was taken to a hospital. The sidewalk shed deck was not tight to the structure, as there was a gap that was one covered by a tarry. Two ECB Violations were issued: one Aggravated Level 2 violation for a failure to sideginarit the public and propertly, due to the failure to close the gap between the top deck of the violation for the performance of work that dase not conform to the approved plans, as the scalido was not vertically and horizontally iden to the structure at every second frame. Two partial Stop Work Orders (FSWO) were issued: on PSWO for sector work from the sidewalk shed level, and a second PSWO for the use o a supported scaffold.	,	35344820M - 35344821Y		NB	121191968	Worker Fell	CLINTON HOUSING DEVELOPMENT	Mega Contracting GP LLC



ncident Date	Borough	Address Numbe	r Street	Fatalities Injuries EOC	Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/21/2018	Bronx	600	BERGEN AVENUE	0 1 A DC form heac was a co Agg and the e as fe issue	Frain Description 20 inspector reported that a worker was stripping work at the foundation level when he was hit in the by a piece of metal that fell approximately ten to in feet. The worker was wearing his hard hat and taken to Lincoln thospital, where he was itsued to causate Level 2 workshows were issued: one avaidate Level 2 workshows not continue to safeguard, new violation for where not new not continue to be approximately the safety of the safety and the safety of the safety of the safety of the merick AL NI Service Development of the safety and the safety of the safe		ECS VIOLATUR RUINDURS		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Construction & development
21/2018				bring and form	the construction documents in for review. A Means Methods for the erection and removal of concrete work must be provided.								
	Brooklyn	277	SOUTH 5 STREET	unde was ECB trippi wom	Site Safety Manager reported that a woman tripped ir the sidewalk shed at the job site. An ambulance called. A DOB inspector was on site and issued an Violation for a failure to safeguard, as there was a ing hazard present between a ferce and a tree. The an tripped because there was no clear 5' walkway. DB Violation was also issued.	ECB Violation	35342749J	082118BS01KA01			Other Construction Related Incidents	HAVEMEYER OWNER LLC	
21/2018	Manhattan	115	DELANCEY STREET	close when The trans for a Worl	28 inspector reported that a worker was working to a temporary light hat wasn't properly installed in the came too close and got shocked by five wire. worker did not suiter any visual imjuries, but was uported to a hospital. An ECG Violation was issued failure to maintain safe operations. A partial Stop K Order (FSWO) was issued on work within ten feet mporary lights. A Means and Methods must be kided.	ECB Violation	35316164P				Other Construction Related Incidents	NOT ON FILE	
21/2018	Manhattan	215	PEARL STREET	perfo	Site Safety Manager reported that a worker was prming tile work when he cut his finger on a piece of The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	LAM PEARL STREET HOTEL LLC	
21/2018	Manhattan	316	WEST 88 STREET	0 1 The Depa his fo step. The		No Dispatch					Other Construction Related Incidents	316 WEST 88TH ST, LLC	
21/2018	Manhattan	441	9 AVENUE	grip,	Site Safety Manager reported that two workers were g a power trowel when one of the workers lost his causing the power trowel to fall on his hand. The ser went to urgent care.	No Dispatch					Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
22/2018	Manhattan	100	FRANKLIN STREET	using	Site Safety Manager reported that a worker was g a drill to cut a hole in the wall when he slipped and his hand. The worker left the site and went to a City	No Dispatch					Other Construction Related Incidents	DDG 100 FRANKLIN LLC	
22/2018	Manhattan	1865	BROADWAY	to ha the ti faller	Site Safety Manager reported that a worker claimed we tripped and fell during a plumbing inspection on hirty second floor. The worker claimed to have a around 11:00 AM, but did not report the incident 2:00 PM. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
22/2018	Manhattan	315	EAST 46 STREET	accio	Site Safety Manager reported that an electrician dentally cut his left palm with a razor knife while ng tubing. The worker went to see an off-site medic.	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
/22/2018	Manhattan	688	BROADWAY	tripp walk knee visite had pede time	Site Safety Manager reported that a pedestrian ed on an MTA steel plate that was on a pedestrian way. The pedestrian suffered an injury to their left a A DDB inspector responded to the incident and ed the site and reported that the pedestrian walkway a hipping hazard near the grating, which caused the stifant to trip. The area was being repaired as of the of inspection. An EGB Violation for a failure to guard was issued. A DOB Violation was also issued.	ECB Violation	35345025H	082218BS02KA01			Other Construction Related Incidents	NOT ON FILE	
23/2018	Brooklyn	243	4 AVENUE	that his k	Site Safety Manager reported that a worker claimed a piece of plywood fell on his right hand and bruised nuckle. The worker went to urgent care for ment.	No Dispatch					Other Construction Related Incidents	243 DEVELOPMENT LLC	
25/2018	Manhattan	180	BROOME STREET	0 1 The performance	Site Safety Manager reported that a worker was prining stripping work on the second floor when his arm was punctured by a piece of a nail. The worker taken to Bellevue Hospital.	No Dispatch			NB - NEW BUILDING	121191110	Other Construction Related Incidents	SITE 4 DSA OWNER LLC	T.G. NICKEL & ASSOCIATES
25/2018	Brooklyn	535	4 AVENUE	using of st forea	Site Safety Coordinator reported that a plumber was a cord drill on the second floor when he hit a piece eI. The machine twisted and cout the plumber's right arm. The worker was transported to a hospital by ulance.	No Dispatch			NB - NEW BUILDING	320626612	Other Construction Related Incidents	XYZ PROPERTIES INC	DYNATEC CONTRACTING INC
/28/2018	Brooklyn	535	4 AVENUE	movi and amb	Site Safety Manager reported that a worker was ing a ladder when he slipped on a piece of BX cable fell. The worker suffered an injury to his back. An ulance was called.						Other Construction Related Incidents	XYZ PROPERTIES INC	
/28/2018	Brooklyn	840	FULTON STREET	work	New York City Fire Department reported that a ter fell down the stairs while carrying material. The ser was experiencing back pains and was sported to a hospital by EMS.	No Dispatch	Page 45 of		NEW BUILDING	320596565-01-NB	Worker Fell	840 FULTON, LLC	TITAN REALTY & CONSTRUCTI



cident Date		Address Number		Fatalities Injurie	s EOC Final Description		ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
28/2018	Manhattan	110	CHARLTON STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	
					moving a ladder when he knocked over a reshore that him him in his calve. The worker went to urgent care.								
/2018	Manhattan	264	WEST STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					using a gas saw to cut a granite curb stone when the stone kicked back and lacerated his shoulder. EMS was called.								
2018	Manhattan	301	EAST 117 STREET	0	1 The Site Safety Manager reported that a worker was changing position on a rebar. The worker was wearing his hamess, and removed his harness to be able to move to a different location. The worker misstepped, fel approximately six feet, and suffered injuries to his right man and leg. The worker was solural alert and awake and was taken to Harlem Hospital for treatment. A DOB inspector responded to the incident and visited the site and reported that there was no enforcement action necessary, as the incident occurred as the result of a worker's error.				NB	121190460	Worker Fell	AMP HOLDINGS LLC	TRANS COUNTY CORP
/2018	Brooklyn	170	BUFFALO AVENUE	0	1 A DOB inspector reported that an elevator worker claimed that he was struck by debris that fell from the sighth floor while he was save solving on top of an elevator car at the seventh floor. The worker was transported to a hospital, where he received one stitch and was released. The inspector observed an enclosed elevator core with block and core beard from the cellar to the machine room with no penetrations at the machine room and no active work at other cars. No debris or other materials were found at the top of the ca and elevator. The this expect calso found permits for temporary work for the elevators that were current. No enforcement action was deemed necessary.				A1 - ALTERATION TYPE 1	321482418	Material Fell	BUFFALO AVE. REALTY ASSOCIATES	CFSC MAINTENANCE, LLC
2018	Brooklyn	30	COLUMBIAHEIGHTS	0	1 The Site Safety manager reported that a worker was coming down from the bukhnad to the roof on a lader when holding some objects. The worker massed a step when the source of the source of the source of the worker went home to see a doctor. It was not known what the worker was holding as he was coming down the ladder.				ALTERATION -1	321194346	Worker Fell		ARCHSTONE BUILDERS LLC
2018	Manhattan	425	PARK AVENUE	0	A DOB inspector reported that during a stripping operation on the wall on the cellar floor, a panel of the stripping operation of the self at the stripping operation on the wall on the cellar floor, a panel of this a worker. There was no Controlled Access Zone and no safety measures in place at the lower level while the vortened operation was in progress, which created a hazardous condition. Two ECB Violations were issued: one violation for a work platform that was improped rected. Two partial SAD Work Orders (PSWO) were issued: One for stripping operations, and one for the erection of work platform. The General Contractor is to provide a Means and Methods for the safe operation of the job.	y	33333478K, 79M		NEW BUILDING	121333021	Material Fell	T-C 425 PARK AVENUE, LLC	TISHMAN CONSTRUCTION CORP
/2018	Manhattan	553	WEST 30 STREET	0	1 The Site Safety Manager reported that an electrician tripped on a piece of plywood that was being used to cover a hole on the floor. The electrician injured his lower back. An ambulance took the electrician to the hospital for a check up.	No Dispatch			NEW BUILDING	121184208	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
/2018	Bronx	2760	BRIGGS AVENUE	0	1 The Site Safety Manager reported that a worker had got his finger pinched between a scissor lift cage and a steel beam during the removal of fire retardant material. An ambulance was called						Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
30/2018	Queens	81-10	135 STREET	0	1 A DDB inspector reported that while the double dock platform of a multiple-fixed scaffold that was on top of a sidewalk shed was being assembled, the scaffold platforms folded and hit one of the workers stretching the platform in his hrees. The worker was in the solution of the hospital is the second stretching and the second stretching and the hospital. The worker was in possession of a valid OSHA card and a valid scaffold card. Four ECB Violations were issued: one violation for the failure to notify the Department Of Buildings of the installation that was contrary to the approved plan, one violation for an installation that was contrary to the approved plan, one violation for an equivalence of guard rails and secure pins. Two partial Stop Work Orders (FSWO) were issued: one PSWO for the use of a suppended scaffold, and one PSWO for the use of a suppended scaffold, and one PSWO for the use of a suppended scaffold, scaffold, and one PSWO for the use of a suppended scaffold.	a f	35351752P, 35351753R,35351754Z, 35351755K		Alt 1	429652387	Scaffold/Shed/Fence/Shoring/Installation	BRIARWOOD MP LLC	Pav-Lak Contracting Inc



Incident Date	Borough	Address Number	Street Fa	talities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
8/31/2018	Brookiyn	2007	SURF AVENUE	0	1 A DOB rapactor reported that while workners were assembling and securing a baker scaffold to as steel column, the baker scaffold was pushed by strong wind and struck a worker in the head. The worker was taken down from the building by the New York City Fire Department's emergency tama and transported to Correy Island Hospital by ambulance. All scaffold users at the sate were found to have been in possession of a valid training card. An ECB Violation was issued for a failure to sateguard persons and property. A partial Stop You and Park and Methods must be provided.		35351756M		Alt 2	340190046	Scaffold/Shed/Fence/Shoring/Installation	NYC HOUSING AUTHORITY	Forte Construction Corp
8/31/2018	Manhattan	100	VARICK STREET	0	1 The Site Safety Manager reported that a worker was unloading a shower glass panel when the glass broke and cut the worker's hand and knee. The worker went to urgent care.						Other Construction Related Incidents	BROOME PROPERTY OWNER JV LLC	
8/31/2018	Manhattan	215	PEARL STREET	0	1 The Site Safety Manager reported that a worker was picking up a bag of mortar when he injured his back. EMS was called.	No Dispatch					Other Construction Related Incidents	LAM PEARL STREET HOTEL LLC	