1 RCNY §3500-03

CHAPTER 3500

Referenced Standards

§3500-03. Referenced Standards. Pursuant to Section 28-103.19 of the New York City Administrative Code, delete and replace the following reference standards as follows:

Reference standards ANSI A118.1 and ANSI A118.4 as added by Section BC 3502 of the New York City Building Code, are hereby deleted and new ANSI A118.1 and ANSI A118.4 are added to read as follows:

ANSI	American National Standards Institute 25 West 43rd Street, Fourth Floor New York, NY 10036	
Standard		Referenced
reference		in code
number	Title	section number
A118.1—12	American National Standard Specifications for Dry-Set	
	Cement Mortar	2103.2.3.1
A118.4—12	American National Standard Specifications for Modified	2103.2.3.2,
	Dry-Set Cement Mortar	2103.3.2.4

Reference standard ASABE EP 559.1 as added by Section BC 3502 of the New York City Building Code, is hereby deleted and a new ASBE EP 559.1 is added to read as follows:

ASABE	American Society of Agricultural and Biological Engineers 2950 Niles Road St. Joseph, MI 49085	
Standard reference		Referenced in code
number	Title	section number
EP 559.1-2010	Design Requirements and Bending Properties for Mechanically-Laminated Wood Assemblies	2306.1

Reference standards ASCE/SEI 8, ASCE/SEI 29, and ASCE/SEI 32 as added by Section BC 3502 of the New York City Building Code, are hereby deleted and new ASCE/SEI 8, ASCE/SEI 29, and ASCE/SEI 32 are added to read as follows:

ASCE/ SEI	American Society of Civil Engineers Structural Engineering Institute 1801 Alexander Bell Drive Reston, VA 20191-4400	
Standard reference number	Title	Referenced in code section number
8—02	Specification for the Design of Cold-formed Stainless Steel Structural Members	1604.3.3, 2210.1, 2210.2
29—05	Standard Calculation Methods for Structural Fire Protection	722.1
32—01	Design and Construction of Frost-Protected Shallow Foundations	1809.3.1

Reference standard ASME 17.5 as added by Section BC 3502 of the New York City Building Code, is hereby deleted and a new ASME 17.5 is added to read as follows:

ASME	American Society of Mechanical Engineers Two Park Avenue New York, NY 10016-5990	
Standard reference number	Title	Referenced in code section number
A17.5—2011	Elevator and Escalator Electrical Equipment	3001.2

Reference standard AWPA M4 as added by Section BC 3502 of the New York City Building Code is hereby deleted and a new AWPA M4 is added to read as follows:

AWPA	American Wood Protection Association P.O. Box 361784 Birmingham, AL 35236-1784	
Standard		Referenced
reference		in code
number	Title	section number
M4—15	Standard for the Care of Preservative-Treated Wood	1811.5.2,
	Products	2303.1.9

Reference standard AWS D1.4/D1.4M as added by Section BC 3502 of the New York City Building Code is hereby deleted and a new AWS D1.4/D1.4M is added to read as follows:

AWS	American Welding Society 8669 NW 36 Street, #130 Doral, FL 33166	
Standard reference number	Title	Referenced in code section number
D1.4/D1.4M - 2018	Structural Welding Code—Steel Reinforcing Bars	Table 1705.2, 1705.2.1.3, Table 1705.3, 1903.6.2, 2107.3

Reference standard CPA A208.1 as added by Section BC 3502 of the New York City Building Code is hereby deleted and a new CPA A208.1 is added to read as follows:

СРА	Composite Panel Association 19465 Deerfield Avenue, Suite 306 Leesburg, VA 20176	
Standard reference number	Title	Referenced in code section number
A208.1- 16	Particleboard	2303.1 8, 2303.1.8.1

Reference standard DASMA 115 as added by Section BC 3502 of the New York City Building Code is hereby deleted and a new DASMA 115 is added to read as follows:

DASMA	Door and Access Systems Manufacturers Association International 1300 Summer Avenue Cleveland, OH 44115-2851	
Standard reference number	Title	Referenced in code section number
115- 17	Standard Method for Testing Sectional Doors, Rolling Doors and Flexible Doors: Determination of Structural Performance Under Missile Impact and Cyclic Wind Pressure	1609.1.2.3

Reference standard FM 4474 as added by Section BC 3502 of the New York City Building Code is hereby deleted and a new FM 4474 is added to read as follows:

FM	Factory Mutual Global Research Standards Laboratories Department 1301 Atwood Avenue, P.O. Box 7500 Johnston, RI 02919	
Standard reference number	Title	Referenced in code section number
4474- 2004 (R2010)	American National Standard for Evaluating the Simulated Wind Uplift Resistance of Roof Assemblies Using Static Positive and/or Negative Differential Pressures	1504.3.1, 1504.3.2

Reference standard NAAMM FP 1001 as added by Section BC 3502 of the New York City Building Code is hereby deleted and a new NAMM FP 1001 is added to read as follows:

NAAMM	National Association of Architectural Metal Manufacturers 800 Roosevelt Road, Bldg. C, Suite 312 Glen Ellyn, IL 60137	
Standard reference	T:41a	Referenced in code
number	Title	section number
FP 1001—07	Guide Specifications for Design of Metal Flagpoles	1609.1.1

Reference standard TIA-222-H as added by Section BC 3502 of the New York City Building Code is hereby deleted and a new TIA-222-H is added to read as follows:

TIA	Telecommunications Industry Association 1320 N. Courthouse Road Arlington, VA 22201-3834	
Standard		Referenced
reference		in code
number	Title	section number
TIA-222-H — 2017(R2018)	Structural Standard for Antenna Supporting Structures, Antennas and Small Wind Turbine Support Structures	1609.1.1, 3108.1, 3108.2, 3108.4

Reference standard TMS 216 as added by Section BC 3502 of the New York City Building Code is hereby deleted.