

The current proposal is:

Preservation Department – Item 1, LPC-22-08983

## 113 Warwick Avenue – Douglaston Historic District Borough of Queens


Note: this is a Public Meeting item. No public testimony will be received today as the hearing on this item is closed



# AVE.) Douglas Manar 240-05 O Map No. 1194, 2555 (RICHM C WARWICH *39* 240∙01 (20 @15x (GROSVENOR

## Douglaston Historic District 113 Warwick Avenue









#### **PROPOSED CHANGES**

The proposed exterior changes includes removal of non-historic finishes and replacing existing historic finishes with new appropriate historic finishes.

#### **REMOVALS INCLUDE:**

- 1. Remove all aluminum siding.
- 2. Remove vinyl surface applied shutters
- 3. Remove aluminum clad window casing, soffits, and trim
- 4. Remove synthetic post and rails at all porches
- 5. Remove existing wood double hung windows and aluminum triple track storm and screen sash.

#### **HISTORIC REPLACEMENT FINISHES INCLUDE:**

- 1. New stained western cedar shingle wall siding
- 2. New painted composite soffits and trim
- 3. New painted aluminum clad wood double hung windows and casing
- 4. New painted wood porch posts and rails
- 5. New painted composite exterior wall panels at first floor of side wings
- 6. New painted wood shutters, pin hinges and hold backs per 1940 tax photo

#### **NEW ADDITIONS INCLUDE:**

- 1. Partially enclosed front porch
- 2. Second floor additions at the two side wings
- 3. One-story mud room at rear entrance
- 4. New sliding door & landing at rear from living room




















**EXISTING** 


69.05 11.00 **GARAGE** YARD 20.30 **BRICK PATIO** PROPOSED 13.50 100.00 2 STORY FRAME PROP. 2-STORY W/ ATTIC CENTER DRIVE SO' WIDE EW LOT: 64 BLOCK: 8021 HSE. #:113 WARWICK AVE. CC: 5-A OC: R-1-2 /10.00/ / 9.50 / 1 STO. × 1 8.40 × TERRACE OVER STOOP PAVI **PROPOSED** BRICK LAWN LAWN 81.36 **4**" HEDGE CONCRETE SIDEWALK SIDEWALK CONCRETE TC:36.42 10" BC:36.23 STONE CURB TC 35.91 BC 35.70 **GRASS** BC 35.96 **GRASS** CL:35.97 -CL: 36.61--CL 36.45

 $\frac{\text{WARWICK AVENUE}}{\text{50' WIDE}}$ 


**PROPOSED** 

PROPOSED SITE CHANGES INCLUDE:
NEW ONE STORY FRONT ENTRANCE
PORCH AND VESTIBULE
NEW ONE STORY MUD ROOM AT REAR

Site Plan





EXISTING CONDITIONS CELLAR FLOOR SCALE: 1'-0" = 3/16"



**PROPOSED EXISTING** 


Cellar Plan





**EXISTING** PROPOSED

First Floor Plan




EXISTING CONDITIONS SECOND FLOOR SCALE: 1'-0" = 3/16"

**NEW ROOF DECK & RAIL** FIRST FLOOR ROOF 9'-43/4" MASTER BATH (TILE) MASTER BEDROOM (HARDWOOD) F.A. = 214.38 SF LA = 21.66 SF VA = 10.83 SF (HARDWOOD) F.A. = 96.80 SF LA = 21.66 SF VA = 10.83 SF **NEW ROOF** FIRST FLOOR ROOF **DECK AND** RAIL **NEW 2ND FLR ADDITION** NEW 2ND FLR ADDITION

SECOND FLOOR PLAN

**EXISTING** PROPOSED

Second Floor Plan



ACCESSORY STORAGE

1-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-16

3-12-12-

NEW DORMER WINDOW **NEW DORMER** 

WINDOW


NEW ATTIC ADDITION NEW ATTIC ADDITION

EXISTING CONDITIONS ATTIC FLOOR SCALE: 1'-0" = 3/16"

ATTIC FLOOR PLAN
SCALE: 1'-0" = 1/4"

EXISTING

Attic Plan



EXISTING FINISHES:

EXISTING ALUMINUM SIDING, SOFFITS, AND TRIM


VINYL POST, RAIL, AND PICKET RAILING

VINYL SUFACE FASTENED SHUTTERS

ALUMINUM GUTTERS AND LEADERS

HISTORIC RAKE BOARD EXPOSED LINDER ALUMINUM RAI






WEST ELEVATION



PRIMARY FACADE - SOUTH ELEVATION





**REVISED FOR PUBLIC MEETING** 

#### NEW REPLACEMENT AND SUBSTITUTE MATERIALS INCLUDE:

- STAINED WESTERN RED CEDAR SHINGLE ROYALS
- HISTORIC REPLACEMENT DOUBLE HUNG AND CASEMENT WINDOWS
- PAINTED COLUMNS, WINDOW CASING, TRIM, RAILINGS AND SOFFIT
- PAINTED WOOD HINGED SHUTTERS AND HOLD BACK HARDWARE
- HISTORIC REPLACEMENT FRONT DOOR AND SIDELIGHTS
- PAINTED RECESSED PANEL DETAIL AT SIDE WINGS

Warwick Avenue - Primary Facade




**REVISED FOR PUBLIC MEETING** 

West Elevation

#### **EXTERIOR MATERIAL CHANGES INCLUDE:**

- REMOVING ALUMINUM SIDING, TRIPLE TRACK STORM WINDOWS, WINDOW CASING, TRIM, RAILINGS, AND SOFFITS
- RESTORE WOOD SHINGLE SIDING AND PAINTED COLUMNS, WINDOW CASING, TRIM, RAILINGS, AND SOFFITS
- REPLACE SURFACE APPLIED VINYL SHUTTERS WITH PAINTED WOOD HINGED UNITS PER 1940 TAX PHOTOPHOGRAH
- INSTALL HISTORIC REPLACEMENT WINDOWS AND DOORS
- INSTALL PAINTED RECESSED PANELS AT FIRST FLOOR WINGS

#### **PUBLIC HEARING**




#### **REVISED FOR PUBLIC MEETING**

#### **EXTERIOR MATERIAL CHANGES INCLUDE:**

- REMOVE ALUMINUM SIDING, TRIPLE TRACK STORM WINDOWS, WINDOW CASING, TRIM, RAILINGS, AND SOFFITS
- RESTORE WOOD SHINGLE SIDING AND PAINTED COLUMNS, WINDOW CASING, TRIM, RAILINGS, AND SOFFITS
- REPLACE SURFACE APPLIED VINYL SHUTTERS WITH PAINTED WOOD HINGED UNITS PER 1940 TAX PHOTOPHOGRAH
- INSTALL HISTORIC REPLACEMENT WINDOWS AND DOORS
- INSTALL PAINTED RECESSED PANELS AT FIRST FLOOR WINGS

#### **PUBLIC HEARING**

## Rear / North Elevation



REVISED FOR PUBLIC MEETING

#### EXTERIOR MATERIAL CHANGES INCLUDE:

- REMOVING ALUMINUM SIDING, TRIPLE TRACK STORM WINDOWS, WINDOW CASING, TRIM, RAILINGS, AND SOFFITS
   RESTORE WOOD SHINGLE SIDING AND PAINTED COLUMNS, WINDOW CASING, TRIM, RAILINGS, AND SOFFITS
- REPLACE SURFACE APPLIED VINYL SHUTTERS WITH PAINTED WOOD HINGED UNITS PER 1940 TAX PHOTOPHOGRAH
- INSTALL HISTORIC REPLACEMENT WINDOWS AND DOORS
- INSTALL PAINTED RECESSED PANELS AT FIRST FLOOR WINGS

**PUBLIC HEARING** 

14









**VIEW FROM SOUTHEAST** 

**VIEW FROM SOUTHWEST** 



VIEW EAST FROM INTERSECTION OF WARWICK AVENUE AND WEST DRIVE



VIEW WEST FROM INTERSECTION OF WARWICK AVENUE AND CENTER DRIVE




VIEW OF PREMISES STREETSCAPE FROM WEST DRIVE

VIEW OF PREMISES STREETSCAPE FROM CENTER DRIVE












SHORE ROAD BEWTWEEN WARWICK AVENUE AND GROSVENOR STREET SYMMETRICAL FACADE WITH FLANKING TWO STORY WINGS






7 HOLLYWOOD AVENUE, ARCHITECT JOHN C.W. CADOO


#### EXAMPLES OF TWO STORY WINGS IN THE DOUGLASTON HISTORIC DISTRICT

















Examples of Two-Story Side Wings




RICHMOND ROAD (300 BLOCK)


## SIMILAR 2ND FLOOR DORMER WINDOWS



EAST DRIVE and MANOR ROAD



#### PROPOSED SECTION THROUGH EAST ADDITION




 $\langle \mathsf{K} \rangle$ 

		1			1	<u> </u>		T		I	
NO.	R.O. (W x H)	F.S. (W x H)	TYPE	MANUF.	COLLECTION	MODEL#	U-FACTOR	GLASS TYPE	SHGC	AIR LEAKAGE	NOTES
$\langle A \rangle$	(4) 2'-1" x 4'-7 5/8"	(4) 2'-0" x 4'-7 1/8"	CASEMENT	MARVIN	ULTIMATE	UCA2456	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	4 WINDOWS/UNIT
$\langle B \rangle$	(5) 2'-1" x 4'-7 5/8"	(5) 2'-0" x 4'-7 1/8"	CASEMENT	MARVIN	ULTIMATE	UCA2456	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	5 WINDOWS/UNIT
C	(2) 2'-10 1/4" x 4'-8"	(2) 2'-9 1/4" x 4'-7 1/2"	DOUBLE HUNG	MARVIN	ULTIMATE	UDHG2 2624	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	2 WINDOWS/UNIT
D	(2) 1'-5" x 2'-7 5/8"	(2) 1'-4" x 2'-7 1/2"	CASEMENT	MARVIN	ULTIMATE	UCA1632	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	2 WINDOWS/UNIT
E	1'-0" x 4'-6 5/8"	0'-11" x 4'-6 1/8"	PICTURE	MARVIN	ULTIMATE	CUSTOM	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	CUSTOM
F	2'-2 1/4" x 4'-0"	2'-1 1/4" x 3'-11 1/2"	DOUBLE HUNG	MARVIN	ULTIMATE	UDHG2 2020	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	
G	2'-6 1/4" x 4'-4"	2'-5 1/4" x 4'-3 1/2"	DOUBLE HUNG	MARVIN	ULTIMATE	UDHG2 2422	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	
$\langle H \rangle$	2'-2 1/4" x 3'-8"	2'-1 1/4" x 3'-7 1/2"	DOUBLE HUNG	MARVIN	ULTIMATE	UDHG2 2018	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	
	3'-0 1/4" x 4'-0"	2'-11 1/4" x 3'-11 1/2"	DOUBLE HUNG	MARVIN	ULTIMATE	UDHG2 3020	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	
J	EXISTING	EXISTING	EXISTING	EXISTING	EXISTING	EXISTING	N/A	N/A	N/A	N/A	REPAIR & RESTOR
⟨ĸ⟩	2'-1" x 1'-11 5/8"	2'-0" x 1'-11 1/8"	CASEMENT	MARVIN	ULTIMATE	UCA2424	0.27	DOUBLE PANE WITH LOW E	0.40	≤0.30 cfm/SF	

ALL WINDOWS TO HAVE STONE WHITE CLAD SASH EXTERIOR, PAINTED INTERIOR FINISH - WHITE -

#### DOOR SCHEDULE

	NO.	SIZE (W x H)	TYPE	U-FACTOR	SHGC	REMARKS
SOR.	(C.01)	3'-0" x 6'-8"	HINGE			
?FL	C.02	3'-0" x 6'-8"	HINGE			
<b>CELLAR FLOOR</b>	©.03	2'-6" x 6'-8"	HINGE			
	C.04	3'-0" x 6'-8"	HINGE			
	C.05	2'-0" x 6'-8"	HINGE			
	C.06	2'-4" x 6'-8"	HINGE			
FIRST FLOOR	(1.01)	3'-0" x 7'-0"	HINGE	0.27	0.40	EXTERIOR. SPECIFY BY OWNER
	1.02	3'-0" x 6'-8"	HINGE	0.27	0.40	SPECIFY BY OWNER
	1.03	6'-0" x 6'-10"	DOUBLE HINGE	0.27	0.40	MARVIN MODEL #UIFDG2 6068
	1.04	2'-8" x 7'-0"	HINGE			EXTERIOR. SPECIFY BY OWNER
	1.05	3'-0" x 7'-0"	HINGE			EXTERIOR. SPECIFY BY OWNER
	1.06	2'-8" x 6'-8"	HINGE			SPECIFY BY OWNER
	(1.07)	2'-4" x 6'-8"	HINGE			SPECIFY BY OWNER
	1.08	1'-6" x 6'-8"	HINGE			SPECIFY BY OWNER
	1.09	3'-0" x 6'-8"	HINGE			SPECIFY BY OWNER
	1.10	2'-4" x 6'-8"	HINGE			SPECIFY BY OWNER
	1.11	3'-6" x 6'-8"	DOUBLE HINGE			SPECIFY BY OWNER
	1.12	3'-6" x 6'-8"	DOUBLE HINGE			SPECIFY BY OWNER
	2.01	2'-8" x 6'-8"	POCKET DOOR			SPECIFY BY OWNER
	2.02	2'-8" x 6'-8"	POCKET DOOR			SPECIFY BY OWNER
	2.03	2'-8" x 6'-8"	HINGE			SPECIFY BY OWNER
쏬	2.04	2'-8" x 6'-8"	HINGE			SPECIFY BY OWNER
OND FLOOR	2.05	2'-8" x 6'-8"	HINGE			SPECIFY BY OWNER
QNC	2.06	2'-4" x 6'-8"	HINGE			SPECIFY BY OWNER
SEC	2.07	1'-6" x 6'-8"	HINGE			SPECIFY BY OWNER
	2.08	2'-6" x 6'-8"	HINGE			SPECIFY BY OWNER
	2.09	2'-8" x 6'-8"	HINGE			SPECIFY BY OWNER
	(A.01)	2'-4" x 5'-0"	HINGE			SPECIFY BY OWNER
	A.02	2'-4" x 6'-8"	HINGE			SPECIFY BY OWNER
NO.	(A.03)	2'-6" x 6'-8"	HINGE			SPECIFY BY OWNER
ATTIC FLOOR	(A.04)	2'-4" x 6'-8"	HINGE			SPECIFY BY OWNER
) L	A.05	2'-6" x 6'-8"	HINGE			SPECIFY BY OWNER
4	A.06	2'-4" x 6'-8"	HINGE			SPECIFY BY OWNER
	(A.07)	2'-4" x 5'-0"	HINGE			SPECIFY BY OWNER
	A.08	2'-4" x 5'-0"	HINGE			SPECIFY BY OWNER
	(A.09)	2'-4" x 5'-0"	HINGE			SPECIFY BY OWNER



FRANK J. QUATELA ARCHITECT, P.C.

> 36-07 169th STREET FLUSHING, NY 11358 TEL: 718.886.1600

FRANK@QUATELA-ARCHITECTS.COM WWW.QUATELA-ARCHITECTS.COM

THE ARCHITECT SHALL NOT HAVE CONTROL OR CHARGE OF AND SHALL NOT BE RESPONSIBLE FOR CONSTRUCTION MEANS, METHODS, DEVIATIONS, TECHNIQUES, SEQUENCES OR PROCEDURES, OR FOR SAFETY PRECAUTIONS AND PROGRAMS IN CONNECTIONS WITH THE WORK, FOR THE ACTS OR OMISSIONS OF THE CONTRACTOR, SUBCONTRACTORS OR ANY OTHER PERSONS PERFORMING ANY OF THE WORK, OR FOR THE FAILURE OF THEM TO CARRY OUT THE WORK IN ACCORDANCE WITH THE CONTRACT DOCUMENTS. ALWAYS USE DIMENSIONS AS SHOWN. DRAWINGS ARE NOT TO BE SCALED. FRANK J. QUATELA ARCHITECT, P.C. AND ITS PRINCIPAL/EMPLOYEES WERE NOT RETAINED FOR ANY CONSTRUCTION SUPERVISION.

NO. DATE REVISION


DRAWING TITLE:


WINDOW / DOOR SCHEDULE AND WINDOW ELEVATIONS


PREMISES:

113 WARWICK AVENUE DOUGLASTON MANOR, NEW YORK












VERTICAL DOUBLE HUNG WINDOW SECTION SCALE: 3" = 1'-0"



HORIZONTAL DOUBLE HUNG WINDOW SECTION SCALE: 3" = 1'-0"





FRANK J. QUATELA ARCHITECT, P.C.

> 36-07 169th STREET FLUSHING, NY 11358 TEL: 718.886.1600

FRANK@QUATELA-ARCHITECTS.COM WWW.QUATELA-ARCHITECTS.COM


THE ARCHITECT SHALL NOT HAVE CONTROL OR CHARGE OF AND SHALL NOT BE RESPONSIBLE FOR CONSTRUCTION MEANS, METHODS, DEVIATIONS, TECHNIQUES, SEQUENCES OR PROCEDURES, OR FOR SAFETY PRECAUTIONS AND PROGRAMS IN CONNECTIONS WITH THE WORK, FOR THE ACTS OR OMISSIONS OF THE CONTRACTOR, SUBCONTRACTORS OR ANY OTHER PERSONS PERFORMING ANY OF THE WORK, OR FOR THE FAILURE OF THEM TO CARRY OUT THE WORK IN ACCORDANCE WITH THE CONTRACT DOCUMENTS. ALWAYS USE DIMENSIONS AS SHOWN. DRAWINGS ARE NOT TO BE SCALED. FRANK J. QUATELA ARCHITECT, P.C. AND ITS PRINCIPAL/EMPLOYEES WERE NOT RETAINED FOR ANY CONSTRUCTION SUPERVISION.


NO. DATE REVISION DRAWING TITLE:


WINDOW SECTIONS

PREMISES:

113 WARWICK AVENUE DOUGLASTON MANOR, NEW YORK







FRANK J. QUATELA ARCHITECT, P.C.

> 36-07 169th STREET FLUSHING, NY 11358 TEL: 718.886.1600

FRANK@QUATELA-ARCHITECTS.COM WWW.QUATELA-ARCHITECTS.COM

THE ARCHITECT SHALL NOT HAVE CONTROL OR CHARGE OF AND SHALL NOT BE RESPONSIBLE FOR CONSTRUCTION MEANS, METHODS, DEVIATIONS, TECHNIQUES, SEQUENCES OR PROCEDURES, OR FOR SAFETY PRECAUTIONS AND PROGRAMS IN CONNECTIONS WITH THE WORK, FOR THE ACTS OR OMISSIONS OF THE CONTRACTOR, SUBCONTRACTORS OR ANY OTHER PERSONS PERFORMING ANY OF THE WORK, OR FOR THE FAILURE OF THEM TO CARRY OUT THE WORK IN ACCORDANCE WITH THE CONTRACT DOCUMENTS. ALWAYS USE DIMENSIONS AS SHOWN. DRAWINGS ARE NOT TO BE SCALED. FRANK J. QUATELA ARCHITECT, P.C. AND ITS PRINCIPAL/EMPLOYEES WERE NOT RETAINED FOR ANY CONSTRUCTION SUPERVISION.

DOB:

NO. DATE REVISION DRAWING TITLE:

EXTERIOR DOOR **ELEVATIONS AND SECTIONS** 

PREMISES:

113 WARWICK AVENUE DOUGLASTON MANOR, NEW YORK



10 OF 14



The current proposal is:

Preservation Department – Item 1, LPC-22-08983

## 113 Warwick Avenue – Douglaston Historic District Borough of Queens

Note: this is a Public Meeting item. No public testimony will be received today as the hearing on this item is closed