

Incident Date	t	Address Months	0	Paralleton Industria	FOO First Description	DOD Author	FOR Water Name to an	DOD Water March and	Permit	D'' N-	hadded Toron	Sum and Name	Contractor Name
icident Date	Borougn	Address Number	Street	ratalities injuries	S EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					The New York City Police Department reported that an								
					exterminator fell into a six foot deep excavation in the basement. A DOB inspector reported that the worker								
					suffered minor injuries and was taken to Bellevue								
					Hospital and that there was unpermitted excavation								
					work being performed in the basement. An Aggravated Level 2 ECB Violation was issued for a failure to								
2/2018	Manhattan	13	EAST 7 STREET		safeguard and work without a permit. A full Stop Work 1 Order was issued.	ECB Violation	35309613X		No Permit	No Permit	Worker Fell	TRIAD CAPITAL, LLC	No Permit
2/2018	Mannattan	13	EAST / STREET	0	1 Order was issued.	ECB violation	35309613X		No Permit	No Permit	W Orker Fell	TRIAD CAPITAL, LLC	No Permit
					The Site Safety Manager reported that a worker was								
					cleaning a platform from a multipoint scaffold when he slipped and fell five feet onto the ground, hitting his righ								
					elbow. An ambulance was on site. Four ECB Violations								
/3/2018	Manhattan	269	WEST 87 STREET	0	and a partial Stop Work Order were issued. The Site Safety Manager reported that a worker got his	ECB Violation	35285606Y, 35285607X, 35285608H, 35285609J				Worker Fell	RIVERVIEW OPERATING CO., LLC	Leeding Builders Group LLC
					hand stuck between a steel plate and a frame and got								
/3/2018	Manhattan	430	EAST 58 STREET		two of his fingers crushed. The worker was sent to 1 Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	SUTTON 58 HOLDING COMPANY LLC	
3/2010	Widi II laktai I	430	EAST 30 STREET	0		140 Dispatori					Other Construction Related Incidents	SOTTON SOTTOLDING COMPANT ELC	
					The Site Safety Manager reported that a worker was								
/4/2018	Manhattan	1681	3 AVENUE	0	loading garbage into a truck when he slipped on snow 1 and hurt his arm. The worker walked to urgent care.	No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
					The Site Safety Coordinator reported that a worker was unloading glass from a crate when a piece of glass fell								
					and injured his leg. The worker was taken to a hospital.								
/6/2018	Manhattan	301	FREEDOM PLACE SOUTH	0	1 The extent of the worker's injuries was not known.	No Dispatch			NEW BUILDING	121192501-01-NB	Worker Fell	301 FREEDOM PLACE SOUTH, LLC	SCIAME CONSTRUCTION LLC
					The Site Safety Manager reported that a worker on the								
					twenty fourth floor slipped on a patch of ice and hurt his								
					shoulder. An ambulance was called to the site. A DOB inspector responded to the incident and reported that								
					diamond plates on the outside of a hoist had water and								
/8/2018	Queens	22-44	JACKSON AVENUE	0	ice on them, which caused the worker to slip. An ECB 1 Violation and a DOB Violation were issued.	ECB Violation	35301051R	010818BS02DH03			Worker Fell	G & M REALTY, L.P.	
	-			, i	The state of the s								
					The Site Safety Manager reported that a worker slipped								
					on a second floor concrete deck, landed on his back, and hurt his shoulder. The worker slipped because of								
					snow. The worker walked to a City MD. A DOB								
					inspector visited the site and confirmed that the deck was covered with snow, which caused the worker to								
	L	40			fall. An ECB Violation, a DOB Violation, and a partial						l		
1/9/2018	Manhattan	40	10 AVENUE	0	1 Stop Work Order were issued.	ECB Violation	35301164N	010918BS02VP01			Worker Fell	40-56 TENTH OWNER LLC	
					The Site Safety Manager reported that a worker was								
					handing down a screw-jack to another worker when the								
					screw-jack slipped out of his hands and hit the other worker. The worker suffered a minor injury and went to								
					a hospital by ambulance for a check up. A DOB inspector issued an ECB Violation, a DOB Violaton, an								
1/9/2018	Manhattan	400	WEST 33 STREET	0	a partial Stop Work Order.	ECB Violation	35301055Y	010918BS04DH03			Material Fell	BOP NE LLC	
					The Site Safety Manager reported that a worker slipped on ice. An ambulance was called. A DOB inspector								
					reported that the worker slipped on ice that was located								
1/10/2018	Staten Island	55	RICHMOND TERRACE	0	in an area that was closed off and where there was no 1 work in progress. No enforcement action necessary.	No Action Necessary					Worker Fell	ST. GEORGE OUTLET DEV LLC	
17 10/2010	Citation Island	00	THO INIONE TENTONE		The Side Safety Manager reported that a worker was	140 7 tolion 140000000 y					Tronci i cii	01.020102.001221.024.220	
					installing sheet rock when he cut his left hand on a								
1/10/2018	Queens	27-17	42 ROAD	0	metal duct. The worker went to urgent care with another worker.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
					The Site Safety Coordinator reported that an electrician was pulling cables in a box when he pulled his hand								
					back and cut it on a piece of Chicago Bar. The incident								
1/10/2018	Manhattan	130	EAST 82 STREET	0	occurred on 1/10/2018, but was not reported until 1 1/11/2018. The worker went to a doctor on his own.	No Dienatch			NEW BUILDING	121328027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
710/2010	Williaman	130	EAST 02 STREET	0	1 1/11/2010. The worker werk to a doctor of this own.	140 Dispatori			NEW BOILDING	121320027	Other Construction Related Incidents	154 EAST 62 EEC	WIC GOWAIT BOILDERG INC
					A DOB inspector reported that a worker attempted to								
					move an "A"-Frame cart that was loaded with about twenty flat stock metal sheets when the metal sheets								
					fell onto his leg. The worker may have possibly suffered								
					a broken leg. An EMT was on site. An ECB Violation and a partial Stop Work Order were issued. The								
					General Contractor at the site is to provide a Means and	1							
/10/2018	Manhattan	118	FULTON STREET	0	1 Methods for safe operations.	ECB Violation	35300526R				Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	
					The Site Safety Manager and a DOB inspector reported								
					that a carpenter was standing on an "A" Frame ladder to remove the door frame from an electrical closet on								
					the 51st floor when a piece of plywood that was behind								
					the door frame came loose and hit him in the shoulder, causing him to fall off of the ladder. The worker								
					complained of back pain and was transported to a								
					hospital by ambulance. A DOB inspector reported that there were no unsafe or hazardous conditions at the								
1/11/2018	Manhattan	118	FULTON STREET	0	working area. No enforcement action was necessary.	No Action Necessary			New Building	121333440	Worker Fell	CP V TS FULTON OWNER, LLC	CP V TS FULTON OWNER LLC
					A DOB inspector reported that a worker was using an "A"-Frame cart to move scaffolding elements when he								
					twisted his wrist while pulling the cart. The worker did								
					not want to go in an ambulance and went to see a doctor on his own. There were no unsafe of hazardous								
					conditions at the work area. No enforcement action was								
/11/2018	Manhattan	151	MAIDEN LANE	0	1 necessary. The Site Safety Manager reported that a worker tripped	No Action Necessary			New Building	121186769	Other Construction Related Incidents	151 MAIDEN LLC	PIZZAROTTI IBC LLC
					over a board that was on the floor and twisted his right								
1/11/2018	Manhattan	305	FAST 61 STREET		ankle. An ambulance was called to the site and took the worker to a hospital.	No Dispatch	Page 1 of 13				Worker Fell	305 FAST 61ST STREET GROUP LLC	



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					The Site Safety Manager reported that a pedestrian stepped on a piece of plywood under the upper								
					sidewalk and slipped, injuring his right ankle. The								
018	Manhattan	42	WEST 33 STREET	0	pedestrian went to see a doctor on his own. An ECB 1 Violation was issued.	ECB Violation	35300326M	011118BS05MA03			Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	
					The Site Safety Manager reported that a carpenter was								
					hitting a nail when the nail popped out and hit the worker in the face. The worker has no visible cut or								
018		27-13	21 STREET		injuries. An ambulance transported the worker to a hospital for a check up.	No Dispatch			NEW BUILDING	420993740	Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	DISANO DEMOLITION CO, INC
010	Queens	21-13	ZI SIREEI	0	i nospital for a check up.	NO DISPAICH			NEW BUILDING	420993740	Other Construction Related incidents	NEW TOWN RESIDENCE LLC	DISANO DEMOLITION CO, INC
					The Site Safety Manager reported that a worker was								
					pumping concrete into a wheelbarrow when the concrete pump shifted and snagged his finger between								
					the pump clamp and the concrete cleaning basin,								
					causing a large cut. The worker was taken to a hospital A DOB inspector reported that according to the								
					inspection of the logs, the injured worker did not attend the concrete pre-pump meeting and did not know why								
					he was part of the operations. An Aggravated 2 ECB								
2018	Manhattan	45	PARK PLACE	0	Violation, a DOB Violation, and a partial Stop Work 1 Order were issued.	ECB Violation	35263168X	011218CERMR01	NEW BUILDING	121185635-01-NB	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
					The Site Safety Manager reported that a worker was cutting a piece of aluminum with a saw when the								
2018	Manhattan	130	EAST 82 STREET	0	aluminum got caught in the saw and pierced his hand. 1 The worker took a cab to a hospital.	No Dispatch			alt 1 NB	121325027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
-010	THE RECEI	100	ENOT DE OTREET		The Site Safety Manager reported that a worker pulled	140 Diapaton			uk 11kb	121020027	Card Construction Florage Holder's	104 2701 02 220	INO GOVIVIA DOILDENO INO
018	Manhattan	53	WEST 53 STREET	0	his groin while lifting a pipe. The worker went to a 1 MedRite	No Dispatch			alt 1 NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LEND LEASE (US) CONSTRUCT
010	THE RECEIPT		WEGI GO GINEEI			140 Disputori			uk 11kb	IZ TOZZ ZZZ	Culti Constitution Florida inclusion	THE MIGGEORE OF MIGGEORY IN	ELIND ELINDE (OD) GONOTICOT
					The Site Safety Manager repoted that a worker was performing waterproofing work inside of a high concrete								
					tank. When the worker was using a chemical sealant to								
					waterproof the inside of the tank, he became overwhelmed by the fumes and passed out. The worker								
					was taken to a hospital by an amulance. An ECB Violation, a DOB Violation, and a partial Stop Work								
2018	Manhattan	590	EAST 83 STREET	0	1 Order were issued.	ECB Violation	35294740J	011518CERFC01	Alt 1 NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
					The Cite Cefety Manager separated that a wester was								
					The Site Safety Manager reported that a worker was unloading a piece of pipe scaffold off of a truck when he								
018	Brooklyn	179	THROOP AVENUE	0	lost control of the piece and the section fell onto his left 1 leg. The worker was taken to a hospital by a friend.	No Dispatch					Other Construction Related Incidents	NYC HHC	
					The Site Safety Manager reported that a piece of plywood fell onto a worker's hand during a stripping								
					operation. There were two workers working one above								
					the other, and the piece of plywood fell from above onto the worker below. An ambulance was called. An ECB								
					Violation and a partial Stop Work Order were issued.								
2018	Manhattan	125	GREENWICH STREET	0		ECB Violation	35300553M				Other Construction Related Incidents	VS 125 LLC	
					The Site Safety Manager reported that an iron worker								
					was using a grinder to cut a piece of metal bar when the grinder kicked back and caused a cut to the								
					worker's thumb. The grinder had all of its safety guards in place. The worker went to an urgent care facility for								
2018	Manhattan	42	WEST 33 STREET	0	1 treatment.	No Dispatch			NEW BUILDING	121186849	Mechanical Construction Equipment	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
					The Site Safety Manager reported that a worker was								
					unpacking windows from a crate and was using a 2 X 4								
					piece of wood as a lever to move the crate when the piece of wood snapped and hit him in the head, causing	,							
2018	Queens	22-44	JACKSON AVENUE	0	a scratch. An ambulance was called and the worker walked to the ambulance to go for a check up.	No Dispatch			NEW BUILDING	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
.010	quound	22.44	UNUNCONTACE		Walled to the allibration to go for a direct up.	140 Disputori			NEW BOILDING	420001012	Carlo Construction (Carlo Indicates	O G WINE PET I, E.T.	O W IN TEST CO
					A DOB inspector reported that a vehicle struck a manlif								
					with two workers in it that was parked in an occupied	4							
					lane. The yodocks were not filled with water and a flagger was not present. The manlift was not damaged.								
					but one of the workers complained of leg pain, and the								
					other worker was shook up by the incident. Both of the workers were sent to a hospital for a check up. An ECB								
2018	Brooklyn	1601	KINGS HIGHWAY	0	2 Violation and a partial Stop Work Order were issued.	ECB Violation	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
					The Site Safety Manager reported that a worker was								
					unhooking the chain from an excavator that was lifting oxygen tanks when his gloves got stuck between the								
					chain and the excavator's hook, pinching the worker's								
					finger. The worker was taken to a hospital by a co- worker. Two ECB Violations and a full Stop Work Orde								
					were issued. The contractor at the site was directed by a DOB inspector to provide a Means and Methods to								
018	Manhattan	200	AMSTERDAM AVENUE	0	a DOB inspector to provide a Means and Methods to 1 perform lifting operations.	ECB Violation	3530559M 353055		NB	122887224	Mechanical Construction Equipment	AMSTERDAM AVENUE REDEVELOPMEN	NT Marc Depaul
					The Site Safety Manager reported that a flagger was								
					almost struck by a vehicle in the middle of the street								
2018	Manhattan	650	5 AVENUE	0	and that he twisted his right ankle while moving out of 1 the way. The flagger went to a hospital.	No Dispatch					Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
					The Site Safety Manager reported that a worker slipped and hurt his back at the job site. An ambulance was								
2018	Bronx	16	EAST 204 STREET	0	1 called and took the worker to a hospital.	No Dispatch					Worker Fell	HP VILLA GARDENS HDFC, INC.	
					The Site Safety Manager reported that a worker was setting up a mobile crane when his finger got pinched								
					between the hook of the crane and a road barrier,								
					causing the finger to detach. A co-worker took him to a hospital. Five ECB Violations and a partial Stop Work								
	Brooklyn		KENT AVENUE		1 Order were issued.	ECB Violation	3505625p, 26r, 27z, 28k, 29m		CRANE NOTICE	871 17	Mechanical Construction Equipment	19 KENT ACQUISITION LLC	ALL ISLAN MASONRY & CONCRET



ncident Date	Borough	Address Number	Street	Fatalities Inj	uries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					The Site Safety Manager reported that a worker twis	ted							
19/2018	Brooklyn	3003	WEST 21 STREET	0	her ankle while pushing a mini-dumpster. An 1 ambulance was called and took the worker to a hos	nital No Dispatch					Other Construction Related Incidents	CONCERN SURF VETS PLACE HOUSIN	
0,2010	Diodayii	0000	WESTEROMEET		The Site Safety Manager reported that a worker was						Cital Constraint Related Holdering	CONCENTIONAL VETO LENGE HOSSIN	
					moving a wooden plank while taking down a single frame scaffold when he twisted his knee and								
					complained of pain. The worker went to see a docto	ron							
19/2018	Manhattan	445	WEST 35 STREET	0	1 his own.	No Dispatch					Other Construction Related Incidents	CARE REALTY CORP.	
					A DOB inspector reported that a worker was pushin	g an							
					"A"-Frame cart that was loaded with stone when the cart overturned, causing stone to fall onto the worke	r'e							
					foot and possibly breaking the foot. An EMT was on								
					site. An ECB Violation and a partial Stop Work orde were issued. The General Contractor is to provide a	r							
22/2018	Queens	29-22	NORTHERN BOULEVARD	0	1 Means and Methods and a Tool Box Talk.	ECB Violation	35289063P				Material Fell	QSB NORTHERN LLC	
					The Site Safety Manager reported that a worker hurl hand while taping and spackling on the ninteenth flo	his							
22/2018	Manhattan	26	ANN STREET	0	1 The worker went to urgent care.	No Dispatch					Worker Fell	143 FULTON STREET DEVELOPMENT	
					The Construction Superintendent reported that a wo cut his finger while cutting a piece of rebar. EMS wa	rker							
					called. The worker was found conscious and was ta	ken							
23/2018	Brooklyn	109	2 AVENUE	0	1 to an area hospital.	No Dispatch			ALTERATION TYPE 1	321185953-01-AL	Worker Fell	THE SALVATION ARMY	SD BUILDERS AND CONSTRUCT
					The Site Safety Manager reported that a worker was doing form work with while he had his peligan hook								
					doing form work with while he had his peligan hook attached to himself. When the worker was climbing								
					down a ladder, the peligan hook fell and hit his right	ear.							
3/2018	Brooklyn	138	WILLOUGHBY STREET	0	The worker went to a City MD. An ambulance was r 1 called. This incident was the result of a worker error	. No Dispatch					Other Construction Related Incidents	NYC HPD	
					A DOB inspecor reported that an elevator foreman v	120							
					working on a platform for installing an elevator inside	9							
					the elevator shaft at the sixth floor when the platform started drifting upwards uncontrollably and would no	t							
					stop. The worker tried to jump to the machine room								
					the other platform at the ninth floor, but he fell backwards down the shaft to the cellar floor, where	ne l							
					succumbed to his injuries. The elevator foreman did	not							
					have a safety harness on and was not tied to anythin There were no safety lines found at the site. A DOB	ng.							
3/2018	Manhattan	111	EAST 24 STREET	1	Violation and a full Stop Work Order were issued.	DOB Violation		012318BS0501BG	NB	121192798	Worker Fell	DEMETRIOS & FANIA SAMUEL, LLC	TRINITY BUILDERS INC
					The New York City Police Department reported that	a							
					worker was standing on a window sill of a sixth floor apartment when he fell from the sixth floor to the								
					ground. The worker was transported to North Shore								
					University Hospital, but was found dead on arrival by the NYPD. A DOB inspector inspected the site and	<i>'</i>							
					reported that there was work present that consisted	of a							
					gut renovation to the bathroom, the installation of ne electrical wiring and box, and the installation of new	w							
					sheetrock, without a permit. Two ECB Violations, tv	ro							
23/2018	Queens	62-98	SAUNDERS STREET	1	DOB Violations, and a Stop Work Order were issue The Site Safety Manager reports that a flagger was		35308671J, 35308670H	012318CERTQ01, 02		-	Worker Fell	NOT ON FILE	
					directing traffic when he was side-swiped by a vehic	le.							
					The driver did not want to listen to the flagger. The flagger was okay, but was taken to a hospital by an								
24/2018	Manhattan	233	WEST 125 STREET	0	1 ambulance for a checkup.	No Dispatch					Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	
					The Construction Superintendent reported that an								
					electrician was working on a live splice box when he								
					was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place of	n .							
					January 24, 2018, but the Department Of Buildings	was							
					not notified until January 29, 2018. An ECB Violatio was issued for electrical work being performed with:								
4/2018	Manhattan	280	PARK AVENUE	0	1 a permit. A DOB Violation was also issued.	ECB Violation	35312686Y	012918EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
					The Site Safety Manager reported that a worker got								
4/2018	Staten Island	546	GUI F AVENUE		concrete in his eyes during a concrete pour operation	n.					01-0-1-1-1-1-1-1	STATEN ISLAND GLOBAL LOGISTIC	
24/2018	outen Island	546	GULF AVENUE	0	1 The worker went to a hospital and returned to work.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LUGISTIC	
					The Site Safety Manager reported that a worker was								
25/2018	Manhattan	2	PARK PLACE	0	cutting rebar when he slipped and cut his finger. Th 1 worker drove himself to a first med for precaution.	No Dispatch			ALTERATION TYPE 1	121333413-01-AL	Worker Fell	NOT ON FILE	CNY CONSTRUCTION LLC
					A DOB inspector reported that during a demolition								
					operation on the first floor of the HVAC conduits and utilities lines, a construction worker was cleaning								
					demolition debris on the first floor when a pipe section	on							
					fell approximately four feet and hit the worker in the head. The pipe section fell because another worker	cut							
					a strap pipe that was holding the pipe section. The worker who was hit by the pipe section initially refus								
					medical attention, but wasn't feeling well after a few	eu							
					hours and called EMS. The worker was taken to a hospital by ambulance. A Construction Superintend								
					was not required at the site. An ECB Violation and a	full							
					Stop Work Order were issued. The General Contract	tor							
6/2018	Manhattan	450	WEST 33 STREET	0	must provide a Means and Methods for the demolition of the remaining HVAC conduits.		35310356M		Alteration 2	140188767	Material Fell	450 PARTNERS LLC	Tishman Construction Corp
					The Site Safety Manager reported that a worker at a								
					concrete truck had a miscommunication with the dr and the shoot came down and hit the worker on the								
26/2018	Manhattan		UNION SQUARE		hand. The worker suffered a minor injury and an 1 ambulance was called.	No Dispatch					Other Construction Related Incidents	READING TAMMANY OWNER LLC	



cident Dat	e Borough	Address Number	Street Fat	atalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					A DOB inspector reported that a worker was climbing								
					up an "A"-Frame ladder from the first floor to the second	4							
					floor when a rung on the ladder snapped, causing the worker to fall ten feet and land on his back. The worker								
					was found conscious and was taken to the hospital by								
					EMT personnel. An ECB Violation and a full Stop Work								
26/2018	Manhattan	102	West 188 Street		Order were issued. The site will received a full audit due 1 to site conditions.	ECB Violation	35310351n		ALT	122917503	Worker Fell		allba services
.0/2010	Maintacan	102	West 100 Street	0	i to site conditions.	LOD VIOLEUM	3331033111		ACI	122817303	WORE FEE		aliba services
					A DOB inspector reported that an electrician was in the								
					process of erecting a shanty while climbing an eight								
					foot ladder when he missed a rung of the ladder and fell three feet. The worker was taken to Bellevue Hospital. A								
					DOB inspector visited the site and reported that no								
27/2018	Manhattan	500	WEST 33 STREET	0	1 enforcement action was deemed necessary.	No Action Necessary			NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
					A DOB inspector reported that workers were receiving a								
					load of concrete masonry unit (CMU) brick on the third	1							
					floor when the third floor C-Joists towads the rear of a								
					new extension partially collapse due to excessive weigh and because the C-Joists were not properly secured to	t							
					the CMU wals. The collapse also caused the second								
					and first floors to collapse into the cellar. One worker sustained minor injuries and was taken to Brooklyn								
					Presbyterian Hospital. An Aggravated Level 2 ECB								
					Violation and a full Stop Work Order were issued for a								
					failure to safeguard. A sidewalk shed has been requested to be immediately installed at exposure four.								
					DOB will remain on site until the sidewalk shed is								
					installed. The site will be referring to DOB's Interior								
29/2018	Brooklyn	404	11 STREET	0	Demolition Engineering Unit for audit and approval of al 1 temprary shoring.	ECB Violation	35310458N		Alteration	321190858	Other Construction Related Incidents	404 11TH ST NY CORP	SUN SUN Contracting
		104			,								
					The Site Safety Manager reported that a worker fell								
					through the interior opening for a tower crane								
					installation from the ninth floor to the eighth floor. The worker was taken to a hospital, where he was								
					eventually released with no injuries. The worker did								
					attend a safety orientation meeting at the start of his								
					shift. A DOB inspector visited the site and reported that there was proper signage and a proper guardrail system								
					present at the perimeter of the slab opening, but that								
					the worker disregarded all safety measures provided to prevent falling hazards. No enforcement action was								
29/2018	Brooklyn	422	FULTON STREET	0	1 necessary.	No Action Necessary					Worker Fell	NOT ON FILE	
					The Site Safety Manager reported that a worker was								
					using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut								
					was a minor cut. The worker walked to Beth Israel								
29/2018	Manhattan	209	EAST 19 STREET	0	1 Hospital on his own.	No Dispatch			ALTERATION TYPE 1	121724946-01-AL	Worker Fell	227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
					The Site Safety Manager reported that a worker was								
					pushing a debris cart when one of the wheels of the car	t							
					broke off and clipped the worker's foot. The worker wen	t							
30/2018	Manhattan	20	BROAD STREET	0	to the emergency room. An ECB Violation and a partial 1 Stop Work Order were issued.	ECB Violation	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
		-			The Site Safety Manager reported that a worker tripped								
00/0040		500	WEST 33 STREET		on the curb for the machine room and hurt his arm. An	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
30/2018	Manhattan	500	WEST 33 STREET	0	1 ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					The Site Safety Manager reported that a worker was								
(04 (0040		550	WEST 29 STREET		using a grinder when the blade caught his glove and	N. Birran					Other Construction Related Incidents	550 WEST 29TH STREET LLC	
31/2018	Manhattan	550	WEST 29 STREET	0	1 caused a cut to his hand. An ambulance was called.	No Dispatch					Other Construction Related Incidents	550 WEST 29TH STREET LLC	
					The Site Safety Manager reported that a worker slipped								
					on ice melt pellets that were on the ground floor of the								
					job site in an area where ice melt had been put down to melt ice. The worker hurt his wrist and his hip. The								
					worker went to see the onsite medic before going to see								
31/2018	Manhattan	532	WEST 33 STREET	0	1 an offsite medic on his own.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					The Construction Superintendent reported that a third party inspector missed the last step on his way down a								
					permanent flight of stairs and hurt his foot. An								
/31/2018	Manhattan	435	EAST 13 STREET	0	1 ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					The Site Safety Manager reported that a worker hurt his								
					finger while unloading pipes from a delivery truck. The								
31/2018	Manhattan	209	EAST 19 STREET	0	1 worker went to a City MD on his own.	No Dispatch					Other Construction Related Incidents	227 EAST 19TH STREET OWNER, LL	
					The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, lost his								
					balance, and fell on his rear. The worker walked to a								
31/2018	Manhattan	1283	YORK AVENUE	0	1 City MD for a check up.	No Dispatch					Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	
					A DOD								
					A DOB inspector reported that a team of two workers was installing form work at the second floor for a third								
					floor column. One worker was positioned below the								
					second worker, holding him in place while he was								
					installing a clamp. While securing the clamp, the clamp fell and hit the below worker in the face. The worker	,							
					was taken to a hospital, where it was reported that the								
					was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The								
					was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overnight for observation. No enforcement action was deemed necessary, as this								
/31/2018	Brooklyn	138	WILLOUGHBY STREET	0	was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overnight for observation. No	No Action Necessary					Material Fell	NYC HPD	
1/2018	Brooklyn	138	WILLOUGHBY STREET	0	was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.	No Action Necessary					Material Fell	NYC HPD	
1/2018	Brooklyn	138	WILLOUGHBY STREET	0	was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overnight for observation. No enforcement action was deemed necessary, as this 1 injury occurred due to a worker error. The Site Safety Manager reported that a worker cut his	No Action Necessary					Material Fell	NYC HPD	
31/2018	Brooklyn Menhattan	138	WILLOUGHBY STREET		was taken to a hospital, where it was reported that the worker suffered scratch, but not a concussion. The worker wifered a correct, but not endicatement action was deemed necessary, as this if injury occurred due to a worker error. The Site Safety Manager reported that a worker cut his pinky finger while putting away his band-saw tool. The band-saw was unplupped. The worker went to a clinic.						Material Fell Other Construction Related Incidents	NYC HPD AVB 1865 BROADWAY LLC	



ident Date	Borough	Address Number	Street	Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					The Construction Superintendent reported that a worker was installing pour stops when he slipped into the side								
40	Markatta	328	EAST 62 STREET		of rebar and injured his shoulder. The worker left the	N. Branch			Alt 1 - NB	404400040	Oh O	NAME OF THE PARTY	IOV CONOTRIUCTION CORR
18	Manhattan	328	EAST 62 STREET	0	1 site in a cab.	No Dispatch			Alt 1 - NB	121189846	Other Construction Related Incidents	YYY 62ND STREET LLC	JOY CONSTRUCTION CORP
					The Site Safety Manager reported that a painter was								
					carrying down supplies when he lost hs balance on the fourth step and fell, hurting his leg. An ambulance was								
18	Manhattan	591	THIRD AVENUE	0	1 called and the ambulance took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	587-91 THIRD OWNER LLC	
					The Site Safety Manager reported that a worker was removing debris when a four inch pipe that was about								
					three feet long fell on his foot. The worker went to a								
018	Brooklyn	1	FLATBUSH	0	1 hospital.	No Dispatch					Other Construction Related Incidents		
					A DOB inspector reported that a worker was trying to								
					reach for something on the platform of a baker scaffold								
					when he moved the baker scaffold, causing it to strike the left shoulder of another worker. Both workers were								
					on the floor and not using the scaffold. The injured worker was sent to a Med-Rite Clinic for a check up.								
					The injured worker did not suffer a major injury. An								
18	Manhattan	260	WEST 40 STREET	0	1 ECB Violation was issued.	ECB Violation	35285826Y		NB	121187394	Material Fell	PORT 40TH PARKING CORP	ZDG LLC
					The Oile Out of Management of the American								
					The Site Safety Manager reported that a worker was putting away his tools at the end of the day when he								
					opened a sliding glass door on the eighth floor. The								
					glass door came off of its track and hit the worker. The incident took place on 2/5/2018, but was not reported								
					until 2/6/2018. An ambulance was not called, but the								
					worker said that he was going to see a doctor to be checked out. An ECB Violation and a DOB Violation								
					were issued. A partial Stop Work Order on the use and installation of all balcony sliding doors was issued. The								
					General Contractor is to provide a Manufacturer's								
118	Manhattan	24	2 AVENUE	0	Specification on all door tracks and the reason for the	ECB Violation	35299721R	020618BS03GD02			Material Fell	24 SECOND AVENUE OWNER LLC	
,10	malification	24	T.VATINOT	U	The Site Safety Manager reported that a worker hurt his		5020012 IIX	02001003030002			IVACUIGI I CII	2- SECOND AVENUE OWNER LEG	
018	Manhattan		RIVERSIDE BOULEVARD		back while lifting a reel of wire into a box. An						Other Construction Bulletin I and	RCB3 NOMINEE LLC	
118	Manhattan	10	KIVEKSIDE BUULEVARD	0	1 ambulance was called.	No Dispatch					Other Construction Related Incidents	NOB3 NUMINEE LLC	
					The Site Safety Manager reported that a worker got his								
018	Brooklyn	37	BLUE SLIP		thumb pinched between a window and a rack during a 1 delivery. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT G LLC	
,,,,	Diodujii	, , , , , , , , , , , , , , , , , , ,	DEGE GEII		I delivery. The worker work to digent date of the own.	140 Diopaton					Office Octobroom (Control octobroom)	DOI CILLETTI CITTI CILCO	
					The Site Safety Manager reported that a worker was doing taping work while on an "A"-Frame ladder when								
					he mis-stepped and fell two feet. The worker suffered a								
18	Brooklyn	1	FLATBUSH AVENUE	0	1 minor injury and an ambulance was called.	No Dispatch					Other Construction Related Incidents	ONE FLATBUSH AVENUE PROPERTY L	
					The Site Safety Manager reported that a worker complained about lower back pain while pulling a stud								
018					during carpentry work. The worker went to urgent care.								
)18	Bronx	869	EAST 147 STREET	0	1 An ambulance was not called.	No Dispatch					Other Construction Related Incidents	HP MLK PLAZA HOUSING DEVELOPME	
					The Site Safety Manager reported that a worker was								
					cutting the remainder of wood piles that were approximately four feet. While cutting one of the piles,								
					the pile fell forward and hit him in the head. The worker								
					went to a hospital by ambulance. This incident occurred on 2/6/2018, but was not reported until 2/8/2018. An								
					ECB Violation was issued for a failure to notify the								
					Department Of Buildings of the incident, as well as a partial Stop Work Order for the cutting of all wood piles.								
					A Means and Methods for safe cutting operations with a								
18	Brooklyn	911	ERSKINE STREET	0		ECB Violation	35300547X,49J	020818BS05HM01,02			Material Fell	FOUNTAIN SEAVIEW THREE HOUSING	
					The Site Safety Manager reported that a worker was moving an "A"-Frame dolly that was loaded with twenty								
					sheets of 4 X 8 diamond plates when the dolly tipped								
					and hit her ankle. The injured worker went to an emergency room that was across the street from the								
140	Manhattan	1000	VODE AVENUE		site. An ECB Violation and a partial Stop Work Order	ECD Visit-Visit	25200067D				Other Construction Bulletin I and	THE NEW YORK AND DOCUMENTS	
118	Manhattan	1283	YORK AVENUE	0		ECB Violation	35299967R				Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	
					A DOB inspector reported that a worker was hit in the head with a piece of timber that was dropped by								
					another worker during a stripping operation. The worker								
					who was hit by the piece of timber complained of a stiff neck and was sent to a hospital. An ECB Violation was								
					issued, as well as a partial Stop Work Order on all								
018	Manhattan	2395	FREDERICK DOUGLAS BOULEVA	ARD 0	concrete work. A Means and Methods must be 1 provided.	ECB Violation	35289390M				Other Construction Related Incidents	HP 2395 FDB HOUSING DEVELOPMEN	
					A worker tripped on a small piece of pipe in the								
18	Manhattan	91	LEONARD STREET	0	mechanical room and cut his pinky finger. The worker 1 went ot a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	353-357 BROADWAY LLC	
					The Site Safety Manager reported that a worker tripped, fell, and cut his hand. EMS was called. The worker was								
18	Manhattan	91	LEONARD STREET	0	1 conscious and was taken to an area hospital.	No Dispatch			NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
					The Site Safety Manager reported that an electrician								
					from Local 3 slipped in an isolated area by a Con- Edison box. The worker went to Staten Island Hospital								
18	Staten Island	546	GULF AVENUE	0	1 on his own for a check up.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
					The Site Safety Manager reported that a worker lacerated his hand with a utility knife during a stripping								
					operation when the utility knife slipped. The worker								
18	Queens	27-17	42 ROAD	0	1 went to a hospital on his own.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
					The Site Safety Manager reported that a worker was								
					7								
					opening a crate of window frames when a 5' X 5' tube pipe rolled out and onto his foot. The worker was seen								



Incident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/7/2018			FULTON STREET	0	The Site Safety Manager reported that during a drilling operation for the backs, a carpenter that was assisting the drill operator stepped onto an equipment insert and the clamp closed down on his left flott. The worker was taken to a hospital by genergency personnel. Two ECB Violations, budding an Aggravated Level 2 ECB Violation, were issued, as well as a full Stop Work Order. The contractor has been directed to provide the manufacturer's specifications for the drilling equipment, as well as the required training for the personnel.		35309900Z 35309901K		NB	321185828	Mechanical Construction Equipment	540 FULTON ASSOCIATES	PAV-LAK CONTTRACTING INC
2/8/2018	Brooklyn	350	HENRY STREET	1	The Fire Department reported that a worker was found dead on arrival in the cellar. The Construction Superintendent reported that the deceased party was not a construction worker, but a pedestrian. The predestrian trespassed and gained access to the site the previous eventing and full from the starts to the cellar floor. It is not known how far the trespasser fell. A DOB to the site because the site was not properly socured, as an adequate construction fence was not present. A DOB Violation will fail also be prepared for the site because the site was for properly socured, as the site of			020818BS0601BG	ALTERATION	320625294	Worker Fell	FPG CH 350 HENRY, LLC	ICS BUILDERS, INC
					The Site Safety Manager reported that a worker was performing stripping work on the eleventh floor when he pulled down a piece of plywood and the aluminum gof the formwork hit the worker in the face and split his ip. An ambulance was called. An ECB Violation was issued for a failure to provide safety measures. A DOB Violation was also issued. A TOO Box Talk will be.								
2/8/2018	Brooklyn	810	FULTON STREET	0	issued before the start of stripping operations. The Site Safety reported that a worker hurt his foot.	ECB Violation	35300050K	020818BS02EP06			Material Fell	GREENPOINT-GOLDMAN CORP.	
2/8/2018	Manhattan	388	GREENWICH STREET		while using a chipping gun. The worker took a cab to	No Dispatch			ALTERATION TYPE 1	121190503-01-AL	Other Construction Related Incidents	CITIGROUP TECHNOLOGY, INC.	TISHMAN CONSTRUCTION CORP
					The Site Safety Manager reported that a worker was dismantling a scaffold when the plank he was standing on broke and fell six feet. The worker went to a hospital by ambulance. An ECB Violation for a failure to safeguard all persons and property affected in								
2/8/2018	Queens	34-11	BEACH CHANNEL DRIVE	0	1 construction operations was issued.	ECB Violation	35285811N		NB	421094283	Worker Fell	NOT ON FILE	Chateau GC LLC
2/9/2018	Brooklyn	340	EVERGREEN AVENUE	0	The Fire Department reported that a worker was hit in the head with a piece of rebar. Four ECB Violations and four DOB Violations were issued. A partial Stop Work Order was also issued. A Meens and Methods and a 1 Tool Box Talk must be provided.	ECB Violation	35300117X,118H,120R,121Z	020918BS04DH01,02,04,05			Material Fell	BUSHWICK REALTY HOLDINGS LLC	
					The Super reported that a mason was using a grinder for brick cutting when the grinder kicked back and the grinder's butt end (not the blade) hit the mason in the face. The mason suffered a bruise to his face and felt a								
2/9/2018	Brooklyn	500	GATES AVENUE	0	1 little dizzy. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PCMH 500 GATES HOUSING DEVELOP	
2/9/2018	Manhattan	1865	BROADWAY	0	The Site Safety Manager reported that an electrician was pulling his cart from the hoist when the handle on the cart became loose and the worker fell backwards to 1 the floor, hurting his back. An ambulance was called. The Site Safety Manger reported that a vehicle struck	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
					the flagman in the street. The Police Department responded to the incident. The worker wss taken to								
2/9/2018	Queens	160-08	JAMAICA AVENUE	0	Jamaica Hospital. The Site Safety Manager reported that a worker cut his left hand on metal studs. The worker was taken to an	No Dispatch					Other Construction Related Incidents	160 JAMAICA, LLC	
2/12/2018	Manhattan	461	WEST 34 STREET	0	The Site Safety Manager reported that a worker pinched	No Dispatch			ALT 1	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	EDWARD M GRUNWALD
2/12/2018	Manhattan	200	EAST 95 STREET	0	his finger while moving a steel beam on an "A"-Frame.	No Dispatch					Other Construction Related Incidents		
0/40/05 : -			WEST SO STREET		The Site Safety Manager reported that a worker was working in a man lift when he moved his body and	N. Branch					0.1	THE MINORINA OF A CONTROL OF A	
2/12/2018	Brooklyn	135	WEST 53 STREET EMERSON PLACE	0	The Site Safety Manager reported that during a stripping operation, a worker fell down from the sixth floor and landed on top of the sidewalk shed. The worker was considered for the sixth properties of the worker was considered for the sixth properties of the worker was considered for the was taken to a hospital by ambutance, An ECB Violation and a full Stop Work Order were issued. Three additional ECB Violations/OATH Summoness and three partial Stop Work Orders were issued by the Concrete partial Stop Work Orders were issued by the Concrete partial Stop Work Orders were issued by the Concrete	•	35300065N				Other Construction Related Incidents Worker Fell	THE MUSEUM OF MODERN ART	
					The Site Safety Manager reported that a worker cut his knee while walking by rebar. The worker was taken to								



ncident Date	Borough	Address Number	Street	Fatalities Injur	ies EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/13/2018	Queens	45-57	UNION STREET	0	A DOB inspector reported that a worker was using the scalifold's stairs to bring rebars onto a floor when a reba got caught on the stairs and pulled the same worker down. The worker was experiencing aches in his body and went to a clinic the next day. This incident took place on Frakuray 13, 2019, but was not reported until building with no permanent stairs. An ECB Violation and a full Style Worker Order were issued for inadequate ingress/egress, an adequate supported 1 scalifold, and the lack of interest stairs.	ar	35299630L				Worker Fell	DEPARTMENT OF EDUCATION	
2/13/2018	Queens	80-08	135 STRFFT		The General Contractor reported that two workers were rigined while grouting when a pump hose got clogad with grout and bleve into the worker's faces. The workers trided to un-clog the pump while it was in use. The two workers were taken to a hospital for treatment An ECB Violation and a partial Stop Work Order were 2 issued.	3	35300854r		ALT 1	420652378 AL	Mechanical Construction Equipment	BRIARWOOD MP LLC.	PAV-J AK CONTRACTING INC.
					The Site Safety Manager reported that a worker entered the site from the outside of the mall area by the dirt parking area side, fell in ice that was mixed with dirt,	1			752.7	42002070 AE			The Establishment in the Inc
/13/2018	Staten Island	2655	RICHMOND AVENUE	0	1 and hurt his ankle. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
2/14/2018	Brocklyn	8705	BAY PARKWAY		The Department Of Investigations reported that a worker fell from a makeshift scaffold. This incident cocurred on 21/32/018, but was not reported until 2/14/2018. The worker was taken to Lutheran Hospital, where he succumbed to his injuries. A DOB insport or responded and reported that the worker fell approximately three for our stories, that the makeshift scaffold was of a wooden frame, and that the makeshift scaffold was of a wooden frame, and that the makeshift scaffold was of a wooden frame, and that the makeshift scaffold was of a wooden frame, and that the makeshift scaffold was of a wooden frame, and that the makeshift scaffold was of a wooden frame, and that the makeshift scaffold was not stated and the control of the contr		35300178K	024418CFRDF03			Worker Fall	DAH LEE TRADING CORP.	
714/2010	BIOOKIYII	6705	DAT PARKWAT	'	The Site Safety Manager reported that a worker cut his		33309170K	021410CERDF03		-	Worker Fell	DAN LEE TRADING CORP.	
2/15/2018	Brooklyn	1060	CLARKSON AVENUE	0	arm with a saw while cutting wood. The worker was 1 taken to a hospital by ambulance.	No Dispatch			ALTERATION TYPE 2	302581347-01-FW-OT	Worker Fell	DEPARTMENT OF EDUCATION	ANSU CONSTRUCTION INC
2/15/2018	Monhatan	101	WEST 57 STREET	0	A DOB inspector reported that contractors were attempting to remove a tempered glass panel when the panel shattered. A small piece of glass fell to the street level while the remainder of the shattered panels on the terrace. A woman was injured and taken to a nospital by ambulance. The women's injury was minor and not life threatening. An Aggravated Level 2 ECB Violation, a DOB Violation, and a partial Stop Viol. Order were issued for a failure to safeguard all persons 1 and properly during construction operations.		35008906P	021518CFRDY04			Material Fell	101 WEST 57TH STRFFT HOTEL INV	
710/2010	THE TURNET	101	TEGI SI GILEE		The Site Safety Manager reported that a worker was climbing off of a scaffold when he slipped and fell	LOD VIGUION	333333	ELDIOCENT 104			Machael Cil	IOT WEST STITLE IN	
2/15/2018	Manhattan	42	WEST 33 STREET		approximately two feet, injuring his shoulder. An 1 ambulance was called.	No Dispatch					Worker Fell	38-46 WEST 33 STREET, LLC	
			COLLEGE POINT BOULEVARD		A DOB inspector reported that a painter was on a scissor lift painting the area next to a roll down door sensor when he activated the door, which caused another worker to get hit by the door. The worker had the wind knocked out of him and was sent to a hospital An ECB Violation and a partial Stop Work Order were susued for the failure to maintain safe operations. The General Contractor at the site is to provide a Means an IM Methoris.	l.	35317706N					FEINSTEIN CP REALTY LLC	
2/15/2018	Queens	30-35	COLLEGE POINT BOULEVARD	0	1 Methods.	ECB Violation	35317705N				Other Construction Related Incidents	FEINSTEIN CP REALTY LLC	
2/16/2018	Queens	71-17	ROOSEVELT AVENUE	0	A DOB inspector reported that were four workers unloading bundles of rebar that were approximately for five feet from a flatebot truck when one of the workers tost control of the bundle self of the the flate of the sound self of the the flate of the fl	g			NEW BUILDING	420653000	Material Fell	ROOSEVELT PARC LLC	BRAVO BUILDERS LLC
2/16/2018	Manhattan	38	HOWARD STREET	o	A DOB inspector reported that an inspector from Cole NY was performing an inspection of the building for façade local law. While inspecting the building, the inspector stepped out not to the fire secape on the seventh floor, and a step of the fire secape became dislodged and fall to the ground, striking two pedestrians. One of the pedestrians suffered a life threatening injury, and the second pedestrian was in serious condition. The inspector fall stightly through an opening, but not all the vay down. EMS was called. At ECB Violation, a DOB Violation, and an Immediate 2 Emergency Declaration were issued.		35308908Z	021618CERDY01			Material Fell	434 BROADWAY PROPERTY INVESTOR	CANY Architecture & Engineering, DPC.
					The Site Safety Manager reported that a worker was lifting a piece of rebar when he claimed to have hurt his back. The worker walked up to an ambulance and the								
2/16/2018	Manhattan	233	WEST 125 STREET	0	1 ambulance took him to a hospital.	No Dispatch			NEW BUILDING	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTRUCTION SERVICES LLC



	l		1.		1						1 –		1-
Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					The Site Safety Manager reported that a concrete								
					worker was carrying a Doka form that was about 2 X 9								
					feet and 100 pounds when he slipped and fell. The								
					worker complained of back pain. A DOB inspector								
					responded to the incident and reported that no								
/16/2018	Manhattan	217	WEST 57 STREET	0	enforcement action was necessary, as the injury 1 occurred as the result of a worker error.	No Action Necessary					Other Construction Related Incidents	SMITELL SPONSOR LLC	
10/2010	Widi II dutai I	211	WEST ST STREET	0	The Site Safety Manager reported that a worker rolled						Other Construction Related Incidents	SWITELE ST GROOK EEG	
					his ankle while moving material. The worker was taken								
/19/2018	Brooklyn	211	SCHERMERHORN STREET	0	1 to Brooklyn Hospital by EMS.	No Dispatch			FRANK HEALEY	321196200-01-NB	Other Construction Related Incidents	211 SCHERMERHORN DEVELOPMENT L	OESTREICHER CONSTRUCTION
					A DOB inspector reported that a worker was walking								
					close to a Bobcat while an I-Beam was on the forks attached to the Bobcat when the I-Beam moved and								
					the worker's hand got caught between the I-Beam and								
					the Bobcat track. The worker suffered a fractured hand								
					and was taken to an area hospital. The worker operating	g							
					the Bobcat was not trained by the employer, which created this situation that resulted in an injury to								
					another work. This incident occurred on 2/19/2018, but	:							
					the Site Safety Manager was not informed of the								
/19/2018	Brooklyn	805	WASHINGTON AVENUE		incident until 2/20/2018. Four ECB Violations and a	ECB Violation	35317732Z, 35317733K AND 35317736K		NEW BUILDING	321478548	Mechanical Construction Equipment	805 WASHINGTON AVE LLC	HAPPY LIVING DEVELOPMENT
19/2018	Вгоокіуп	805	WASHINGTON AVENUE	U	The Site Safety Manager reported that a worker	ECB violation	35317732Z, 35317733K AND 35317736K		NEW BUILDING	321478548	Mechanical Construction Equipment	805 WASHINGTON AVE LLC	HAPPY LIVING DEVELOPMENT
					dislocated his left shoulder when he lifted a bag of								
					concrete onto it. The worker was taken to Mount Sinai								
/19/2018	Manhattan	200	EAST 21 STREET	0	1 Hospital by ambulance.	No Dispatch			NEW BUILDING	121190479-01-NB	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC
					The Site Safety Manager reported that a worker cut his								
2/20/2018	Manhattan	115	DELANCY STREET	0	finger while using a grinder. The worker went to urgent 1 care.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
0,_010				0		o Diopartii					2 Constitution Related Includits		
					The Site Safety Manager reported that a worker fell from	n							
100,0040		405	PARK AVENUE		the fourth step of an "A"-Frame ladder. The worker	N. Birran					On a Comment of Bulletin II	T O 405 DADY AVENUE 11 O	
2/20/2018	Manhattan	425	FARR AVENUE	0	1 complained of back pain. An ambulance was called.	INO DISpatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
					The Site Safety Coordinator reported that a worker								
					tripped on tape on a scaffold platform, which caused								
					him to fall and twist his knee. The worker was taken to								
					urgent care. An ECB Violation was issued to the								
2/21/2018	Queens	38-01	QUEENS BOULEVARD	0	General Contractor at the site for a failure to safeguard 1 all persons and property.	ECB Violation	35285820P		NR	421387626	Worker Fell	CURBCUT QUEENS BLVD LLC	Sordoni Construction Comp
021/2010	Queens	30-01	QUEENS BOOLEVARD	0	The Site Safety Manager reported that a worker twisted		332030201		IND	42 1307 020	WORKE FEI	CONDOCT QUEENS BEVD LEC	Stradin Construction Comp
					his right wrist while bending rebars. A co-worker took								
2/21/2018	Queens	131-11	FOWLER AVENUE	0	1 him to a clinic.	No Dispatch					Other Construction Related Incidents	131-05 HOLDING LLC	
					The Site Safety Manager has reported that a worker								
					was climbing down an "A"-Frame ladder when he slipped and fell about four feet. An ambulance took the								
					worker to a hospital. The worker suffered a possible								
2/21/2018	Manhattan	217	WEST 57 STREET	0	1 fractured elbow.	No Dispatch					Worker Fell	SMITELL SPONSOR LLC	
					A DOB inspector reported that a worker was pulling on								
					one of the clips of a outrigger scaffold in order to install it properly. The worker pulled the clip hard, which								
					caused the worker to slide down the plank and twist his								
					ankle. The worker went to the emergency room across								
					the street and then went home. The formwork and								
					outriggers were all built as per design. No enforcement was action necessary, as it was determined that the								
2/21/2018	Brooklyn	5718	2 AVENUE	0	1 injury occurred as the result of a worker error.	No Action Necessary			ALTERATION-1	321192702	Worker Fell	NYU HOSPITALS CENTER	HUNTER ROBERTS CONSTRUCTION
					The Site Safety Manager reported that a worker cut his								
2/22/2018	Brooklyn	138	WILLOUGHBY STREET	0	finger while handling rebar. The worker was seen by th 1 on-site medic and was sent to City M.D./urgent care.	No Dienatch					Other Construction Related Incidents	NYC HPD	
	Droudyll	130	LLOUGHD1 STREET	U		140 Diapatti					Striat Construction Related Incluents		
					The Site Safety Manager reported that a worker walked								
					into a pile of plywood and then felt discomfort in his								
2/22/2018	Brooklyn	19	KENT AVENUE		upper torso and chest. An ambulance was called and	No Dispatch			NEW BUILDING	320591944-01-NB	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
2/22/2018	DIOURIYII	19	NEINI AVENUE	U	1 the worker was transported to a hospital.	INU DISpatch			NEW BUILDING	32U591944-U1-NB	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
					The Delice December to control that the								
					The Police Department reported that two workers were making a delivery to the roof area of the structure when								
					one of the workers fell approximately eight to ten feet								
					through an opening in the roof that was covered with a								
					tarp. The worker fell to the third floor. The worker								
					suffered injuries to his back and neck and was transported to Bellevue Hospital with head and neck								
					injuries. A full Stop Work Order had been issued to the								
					building on 4/22/2015 and a Vacate Order was issued								
					on 12/22/2017. Two ECB Violations, and two DOB								
					Violations were issued for the unlawful continuation of work while on the notice of a Stop Work Order and for	a							
/22/2018	Manhattan	122	LEXINGTON AVENUE	0	1 failure to safeguard.	ECB Violation	35308861K & 35308860Z	022218CERTQ01 & 022218CERTQ02			Worker Fell	122-24 LEXINGTON AVECP	
					The Site Safety Manager reported that a worker was								
					loading sheetrock onto an "A"-Frame when one of the								
/22/2018	Staten Island	2655	RICHMOND AVENUE		boards slid and landed on his right foot. The worker wa	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
122/2018	Stateri Islanu	2000	INIONIWOND AVENUE	U	sent to urgent care. The Site Safety Manager reported that a rebar installer						Oriel Construction Related Incidents	MAGES RETAIL HULDINGS, INC.	
					slipped on a rebar floor and twisted his ankle. An								
	Staten Island		BAY STREET								Other Construction Related Incidents		



	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					A DOB inspector reported that workers at apartment number 842 were lowering a piece of plywood that was approximately 2 X 5 from the fourth floor fire escape to the ground using a heavy thick rope in front of the building. According to the Project Manage at the site and a bystander, the plywood slipped off of the rope and fell from the third floor level, striking a young girt on the add of the heads abdress landing on the ground. Marks did not be seen to the project of the project			022318CERKC03, 022318CERKC04 &					
018	Queens	83-09	35 AVENUE	0	1 Order were also issued.	ECB Violation	35309174N, 35309325L & 35309326N	022318CERKC05	ALTERATION TYPE 2	421548999-01-EW-OT	Material Fell	83-09 35TH REALTY LLC	MNR GROUP INC
					A DOB inspector reported that workers were using a full to unload window penels off of a truck. While the full to unload window penels off of a truck. While the help off of the full and hit a worker's andies. An ambulance took the worker to a hospital. An ECB Violation for a failure to markins alse operations and a partial Stop Work Order were issued or all deliveries and material Andrio, Trider were issued or all deliveries and material and the process of the proces								
2018	Manhattan	545	WEST 30 STREET	0	The Site Safety Manage reported that a worker was	ECB Violation	35317717K				Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
					working in a building when a couple of pieces of sheetrock fell over and onto his leg. An ambulance was								
2018	Manhattan	685	FIRST AVENUE	0	1 called to the site. The Site Safety Manager reported that a worker got	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
2040			DARK BLACE		dust in his eye. The worker went to a hospital for	No Disease					010	NOT ON EU E	
2018	Manhattan	2	PARK PLACE	0	1 treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					A DOB inspector reported that a tower crane was engaged with loading a four foot piece of scalfolding material on top of a trailer within the job site. After the load was lowered into place, a worker began unhooking the right of the site of the site of the site of the the next list. The gear was detached from the load and the crane hosted up to clear the trailer and the loaded scalfolding when, ubelowoms to the worker, the rigging scalfolding when, ubelowoms to the worker, the rigging landed, which caused the load to ligo over the side of the trailer and thing the worker down, injuring him in the process. The worker was found bleeding, but conscious, and was taken to a hospital by ambulance. The injuries that the worker sustained are suspected to be non-life threatening. Three ECB Violations and to								
2018	Manhattan	1227	BROADWAY	0	1 partial Stop Work Order were issued.	ECB Violation	35225172L 35225171J & 35225172L		CN	CN 913/16	Mechanical Construction Equipment	YJL BROADWAY HOTEL LLC	BMNY CONTRACTING CORP
					A DOB inspector reported that heavy gauge 2 X 10 calling joists were delivered and placed on top of the Concrete Masony Unit (CMU, extentor walls of the sixth floor when a worker removed a band that held the calling joists together, which lead to the joists collapsing and knocking the worker off of the scaffold to the ground. The joists landed on top of the worker as well. The worker was found dead on marvial. A DOB Violation								
1018	Brooklyn	391	HOOPER STREET	1	The Site Safety Manager reported that a worker was	DOB Violation		030118BS01AS01			Other Construction Related Incidents	E&D MANAGEMENT GROUP LLC	
					using a lade and cut his finger. The worker was patched up on-site, but then went to City M.D. where he								
018	Manhattan	260	WEST 40 STREET	0	1 received two to three stitches.	No Dispatch			NB - NEW BUILDING	121187394	Other Construction Related Incidents	PORT 40TH PARKING CORP	ZDG, LLC
					The Site Safety Manager reported that a worker was pushing a mini container when the gate on the bottom of a ramp swung and lacerated his right hand. The on-								
018	Manhattan	685	1 AVENUE	0	site medic put a band aid on the cut. An ambulance	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
					A DOB inspector reported that a panel of plywood that was about 8' X 4' fell from the parapet of a sidewalk shed and struck two pedestrians. One of the pedestrians suffered an injury in the shoulder area. The injured pedestrian was seen by the on-site medic, but								
2018	Queens	28-02	JACKSON AVENUE	0	denied further medical attention and left the scene. An Aggravated Levil 2 CEW loidation was issued for a failure to safeguard public and property affected by construction operations. A second ECB Violation was also issued for a failure to maintain an inspection log for the sidewalk shed. A partial Stop Work Order was also issued. The sidewalk shed company was sent to the site	ECB Violation	35318105Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMPA
018	Queens	28-02	JACKSON AVENUE	0	denied further medical attention and left the scene. An Aggravated Level 2 CEB Violation was issued for a failure to safequard public and property affected by construction operations. A second CEB Violation was also issued for a failure to maintain an inspection log for the sidewalk shed. A partial Stop Work Order was also issued. The sidewalk shed company was sent to the site 1 for repair work.	ECB Violation	35318105Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMPA
018	Queens	28-02	JACKSON AVENUE	0	denied further medical attention and left the scene. An Aggravated Level 2 CEB Violation was issued for a failure to safeguard public and property affected by construction operations. A second ECB Violation was also issued for a failure to maintain an inspection log for the sidewells sheet. A paried Slop Work Order was also second to the second second second second to for repair work. The side of the second second second for repair work. The Site Safety Manager reported that workers were carrying setted lates when one of the clates siteoed and second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second	ECB Violation	35318105Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMPA
-	Queens Manhattan	28-02 150	JACKSON AVENUE EAST 23 STREET		denied further medical attention and left the scene. An Aggravated Level z ECB Violation was issued for a failure to safeguard public and property affected by construction operations. A second ECB Violation was also issued for a failure to maintain an inspection log for the sidewalk shed. A partial Stoy Work Order was also issued. The sidewalk shed company was sent to the site 10 rerpair work.	ECB Violation	35318105Y		NEW BUILDING	420652877 121981748	Scaffold/Shed/Fence/Shoring/Installation Other Construction Related Incidents	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMP. W & L GROUP CONSTRUCTION
				0	denied further medical attention and left the scene. An Aggravated Level 2 CBV Violation was issued for a failure to safeguard public and property affected by construction operations. A second CBV Violation was also issued for a failure to maintain an inspection log for the sidewalk shed. A partial Stop Work Order was also issued. The sidewalk shed company was sent to the site or repair work. The Site Safety Manager reported that workers were carrying steel pates when one of the plates slipped and pinched one of the worker's left middle finger. The I worker was transported to a hospital by ambulance. The Site Safety Manager reported that a worker tripped	No Dispatch	35318105Y						
18				0	denied further medical attention and left the scene. An Aggravated Level 2 CEB Violation was issued for a failure to safeguard public and property affected by construction operations. A second CEB Violation was also issued for a failure to maintain an inspection log for the sidewals shed. A partial Stop Work Order was also issued. The sidewals shed company was sent to the site for repair work. The Site Safety Manager reported that workers were carrying steel pales when one of the plates slipped and pinched one of the worker's left middle finger. The I worker was transported to a hospital by ambulance. The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the I worker was transported to a hospital.	No Dispatch	35318105Y						W & L GROUP CONSTRUCTION
	Manhattan	150	EAST 23 STREET	0	denied further medical attention and left the scene. An Aggravated Level 2 CEO Violation was issued for a failure to safeguard public and property affected by construction operations. A second CEO Violation was also issued for a failure to maintain an inspection log for the sidewalk sheet. A partial Stoy Work Order was also issued. The sidewalk sheet, a partial Stoy Work Order was also issued. The sidewalk sheet company was sent to the site 10 rerepair work. The Site Safety Manager reported that workers were carrying steel plates when one of the plates sipped and pinched one of the worker's left middle finger. The 1 worker was transported to a hospital by ambulance. The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the 1 worker was transported to a hospital.	No Dispatch	35318105Y			121981748	Other Construction Related Incidents		
018	Manhattan	150	EAST 23 STREET	0	denied further medical attention and left the scene. An Aggravated Level 2 CEB Violation was issued for a failure to safeguard public and property affected by construction operations. A second CEB Violation was also issued for a failure to maintain an inspection log for the sidewals shed. A partial Stop Work Order was also issued. The sidewals shed company was sent to the site 15 or repair work. The Site Safety Manager reported that workers were carrying steel pates when one of the plates slipped and pinched one of the worker's left middle finger. The 1 worker was transported to a hospital by ambulance. The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the 1 worker was transported to a hospital. The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the 1 worker was transported to a hospital.	No Dispatch	35318105Y			121981748 122879233	Other Construction Related Incidents		W & L GROUP CONSTRUCTION PROCIDA CONSTRUCTION CORP



cident Date	Borough	Address Number	Street	Fatalities Inju	ries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					A DOB inspector reported that a 16' X 8' size gate								
					swung out and hit a pedestrian that was walking by. The pedestrian was a student that was approximately								
18	Queens	45-57	UNION STREET	0	1 seven years old. The student was evaluated by a nurse	e. ECB Violation	35317909P				Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
					The Site Safety Manager reported that there were two workers that were doing sheetrock work together when one of the workers lost his grip on a piece of sheetrock that landed on the other worker's finger, causing a cut. The second worker left the site and went to City M.D. is								
1018	Brooklyn	10	HURON STREET	0	get stitches on his finger. This incident occurred on 3/5/2018, but was not reported to the Site Safety 1 Manager or Construction Superintendent until 3/8/2018	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
					The Site Safety Manager reported that a pedestrian in wheelchair fell over in a walkway due to a tripping hazard around a Con-Ed sewer cap. The pedestrian went to a hospital by ambulance. A DOB inspector responded to the incident, visited the site, and issued an ECB Violation. The tripping hazard was corrected a	а							
018	Bronx	2395	FREDERICK DOUGLASS BLVD	0	1 of the time that the inspector was at the site.	ECB Violation	35300487N	030618BS10VP06			Other Construction Related Incidents		
					The Site Safety Manager reported that a worker was lifting a 2 X 3 X 10 wooden beam in the elevator pit when he hit himself in the face with the wooden beam. The worker went to urgent care and then went to a hospital. This incident occurred as a result of a worker								
2018	Manhattan	2255	BROADWAY	0	1 error.	No Dispatch					Other Construction Related Incidents	2255 HOLDING LLC	
/2018	Brooklyn	416	KENT AVENUE	0	The Site Safety Manager reported that a worker slipped fell, and hurt his arm. The worker was taken to a 1 hospital for a check up.	d, No Dispatch				320622616	Other Construction Related Incidents	420 KENT AVENUE LLC	ZDG, LLC
2018	Manhattan	1681	3 AVENUE	0	The Site Safety Manager reported that an electrician was running a wire when he tripped on a piece of plywood and skinned his right shin. The electrician wer to a City M.D. for assistance.						Other Construction Related Incidents	95TH AND THIRD LLC	
					The Site Safety Manager reported that a piece of plywood slid and hit a worker on the left knee while the								
2018	Queens	147-40	ARCHER AVENUE	0	worker was stocking plywood on the floor. The worker went to a clinic.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
					electricians working on a scissor lift at the basement level when a temporary light future was accidentally bumped and dislodagd, causing it to fall approximately five feet and strike a worker that was passing by on the head and back. The electricians were working without controlled access zone below. The worker was flound afert, but complained of head pain and went to urgent care. An ECB Violation for a failure to safeguard was issued, as well as a partial Stop Work force for the installation of electrical lighting work. A Means and	a a							
2018	Queens	28-07	JACKSON AVENUE	0	1 Methods must be provided.	ECB Violation	35318121Y-FAIL TO SAFEGUARD	030818BS02KA01	NB	420656873	Material Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
					The Site Safety Manager reported that a worker slid an	d							
2018	Staten Island	546	GULF AVENUE	0	hit his left knee as he was taking the stairs to his trailer 1 The worker was taken to a hospital for a check up.	No Dispatch					Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	
					The Site Safety Manager reports that a worker pinched his finger while cutting a Formica board with a circular								
2018	Manhattan	701	7 AVENUE	0	saw. The worker went to the emergency room on his own.	No Dispatch					Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	
					The Site Safety Manager reported that an iron worker was attempting to move a steel beam onto a dolly on his own when the beam slid and hit his left knee. 911								
2018	Manhattan	29	11 AVENUE	0	1 was called and the worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	NYS PARKS & RECREATION	
W2018	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a worker as carrying equipment when he slipped and fell. The worker hit be back of his head and blacked out. The worker was sent to Mount Sinai Hospital. A DOB inspector responded and visited the site and reported that the worker slid on what look like an ice patch on the floor, even through there was ice melt spread throughout the are. An ECB Violation was issued for a 1 failure to maintain safe operations.	ECB Violation	35286419N				Worker Fell	SMITELL SPONSOR LLC	
2018	Menhattan	1059	3 AVENUE		The Site Safety Manager reported that a worker was carrying a few formwork clamps that weight approximately 10-15 pounds and are about 18 feet long in length up the third floor steps when one of the clamps fell from his pip and hit the wrist of a mason that was working in the bearenint, possibly breaking the mason's wrist. An ambulance was called. An ECG the unsafe handing of manafest A DOB Violation was also issued. A Means and Methods will be provided for it the safe handing of fram work materials.	r	35300269P	030918BS08MH01			Material Fell	63RD & 3RD NYC LLC	
2010	ivida in lidit lidi l	1028	JAVENUE	U	The Site Safety Manager reported that an ironworker hurt his right index finger while prying a cross brace.	LOB VIGIATION	33300209F	030310D300NIDU1			Material Fell	OUND & OND INTO ELLO	
	Manhattan	500	WEST 33 STREET	0	hurt his right index finger while prying a cross brace. The worker was transported to Bellevue Hospital by ambulance.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
1/2018													
/2018					A DOB inspector reported that a worker was lifting up a four foot section of form work when the worker mishandled the form work, causing the form work to fa on his knee. An ambulance was called. It was determined that the incident happened as a result of a worker error and that no enforcement action was	п							



													,
Incident Date	Borough	Address Number	Street	Fatalities	njuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
					The Site Safety Manager reported that a worker was								
					handling a roll of felt paper when he slipped backward	ds							
					and suffered a laceration to the left side of his forehea	id.							
3/12/2018	Manhattan	125	GREENWICH STREET		The worker did not want an ambulance to be called a went to a City M.D. instead.	No Dispatch					Worker Fell	VS 125 LLC	
3/12/2016	IVIdI II Idilidi I	125	GREENWICH STREET	- 0	The Site Safety Manager reported that a worker's fing						Worker Fell	V8 125 EEC	
					got caught between two beams while he was pushing	3							
3/12/2018	Manhattan	255	EAST HOUSTON STREET		forwards beams on a truck. The worker was sent to 1 Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	255 EAST HOUSTON OWNER LLC	
3/12/2018	Mannattan	255	EAST HOUSTON STREET	0	1 Believue Hospital.	No Dispatch			-		Other Construction Related Incidents	255 EAST HOUSTON OWNER LLC	
					A DOB inspector reported that a worker was riding or	,							
					the back of a fork lift during a placement of bundle								
					windows in the storing garage. The bundle was 10' X X 6' and bounced up and down due to its size and	5'							
					weight. The driver of the forklift heard a sound and the	en							
					saw that the worker who was riding on the back was the floor. The worker was found dead. There were no	on							
					witnesses to the incident, and the incident is currently	v							
					under police investigation. The driver of the fork lift wa	as							
					found to be not certified to operate a fork lift. The driv was in a traumatized state and went to a hospital. A	er							
					DOB Violation for a failure to safeguard and a Stop								
3/13/2018	Queens	150-13	89 AVENUE		Work Order were issued. ECB Violations are being 0 prepared to be served.	DOB Violation		031318BS1201MC			Other Construction Related Incidents	88TH AVENUE OWNER LLC	
3/13/2018	Queens	150-13	89 AVENUE	1	U prepared to be served.	DOB Violation		031318BS1201MC			Other Construction Related Incidents	881H AVENUE OWNER LLC	
					A DOB inspector reported that a worker lacerated his								
					foot while driving a walk-behind saw to a container in								
					order to park it. The worker was sent to a hospital. A ECB Violation was issued, as well as a partial Stop	an							
					Work Order on the use of the walk-behind saw.								
3/14/2018	Brooklyn	3617	13 AVENUE	0	Manufacturer specifications must be provided.	ECB Violation	35318355R				Other Construction Related Incidents	37TH STREET HOLDINGS LLC	
					The Site Safety Manager reported that an iron worker pinched his index finger while unloading a cart of stee	al							
					The worker went to a clinic to receive stitches for his								
3/14/2018	Manhattan	220	CENTRAL PARK SOUTH	0	1 finger.	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
					A DOB inspector reported that workers were in the process of cleaning brick with an acid base solvent								
					when some of the solvent fell into the eye of a female	.							
					pedestrian. The pedestrian had her eye rinsed out an	d							
					was treated on the site. The pedestrian did not go to hospital. An Aggravated Level 2 ECB Violation for the	the							
					failure to safeguard all persons and property affected	by							
					construction operations was issued, as well as a DOE Violation and a partial Stop Work Order for façade wo								
					It was recommended that the BEST Squad perform a	ork.							
					follow up inspection for compliance and safety								
3/15/2018	Brooklyn	225	4 AVENUE	0	1 measures.	ECB Violation	35309294H	031518CERDM01	NB	310086554	Material Fell	225 4TH AVENUE PROPERTY OWNER	TRM Construction
					The Site Safety Manager reported that a piece of plywood fell from the first floor to the cellar due to the								
					wind. The plywood landed on the cellar floor where it								
					then fell onto a worker, hurting the worker's shoulder. This incident occurred on March 16, 2018, but the								
					Department Of Buildings was not notified until March								
					19, 2018, because the Construction Superintendent								
					claimed that he called the office on 3/16/2018 after 4: PM and that no one answered the phone. An ECB	:00							
					Violation was issued for a failure to safeguard for not								
					securing materials during a weather advisory. A DOB	ı							
					Violation and a partial Stop Work Order for all form work were also issued. A Means and Methods for the								
					securing of materials during a weather advisory must	be							
3/16/2018	Queens	21-30	44 DRIVE	0	1 provided.	ECB Violation	35318143P	031918B\$02KA04			Material Fell	44TH DRIVE OWNER LLC	
					A DOR increases reported that during assessation was								
					A DOB inspector reported that during excavation wor a worker was torching a hole in two steel "H" piles an	d							
					was laying side by side in order to sling and rig the pi	le							
					when the excavator that was being used moved, which caused the worker's leg to become pinched between								
					two piles. The Site Safety Manager stated that the								
					worker was okay, as he suffered minor injuries to his								
					leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A								
					partial Stop Work Order was issued to stop all								
					movement and preparation of steel piles. The contract is to provide a Means and Methods for the safe	ctor							
3/16/2018	Manhattan	501	WEST 18 STREET	0	is to provide a Means and Methods for the safe movement of steel around the construction site.	ECB Violation	35314141N		New Building	121191147	Excavation/Soil Work	18TH HIGHLINE ASSOCIATES, L.L.	Related Construction LLC
		-		0									
					The Site Safety Manager reported that a worker on th	ie							
					second floor was using a powered pallet jack to move	9							
					bags of cement down a ramp when the powered palle jack moved on its own and ran over the worker's left	et							
					foot. The worker went to Roosevelt Hospital. A DOB								
					inspector responded to the incident and issued an EC								
					Violation for a failue to maintain unsafe equipment. A DOB Violation and a partial Stop Work Order for all								
					work using equipment to transport loads as tthe seco								
					floor north of Tower Boulevard were also issued. The								
					powered pallet jack was found to have no inspection logs. An orientation and a Means and Methods must	be							
					provided. The BEST Squad must be contacted for a	re-	ECB#35318264L FAILURE TO MAINTAIN UNSAFE						
3/16/2018	Manhattan	220	CENTRAL PARK SOUTH	0	1 inspection.	ECB Violation	EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/2018	Brocklyn	416	KENT AVENUE	0	The Site Safety Manager reported that at a twenty-two story new building under construction, a worker that was on sitis performing plastering work on the deptetered the core file backwards onto the floor. The worker frunt his back, suffered a twisted knee, and complained of head pain. An ambufance was called not the worker was transported to Bellevue Hospital. The 1 worker was survival and afert.	I No Dispatch			NB	320622616	Worker Fell	420 KENT AVENUE LLC	ZDG, LLC
					A competent person at the construction site reported that a worker slipped on a supported scaffed and fall approximately six feet, along with a few planes. The worker's foreman stated that the worker drove to see a doctor on his own. A DOB inspector responded and visited the site and reported that the supported scaffed did not conform to code specifications, as the scaffold was not fully plaked, the planes were not tied down, and a guard rail system was missing from multiple locations. Two EGO Violations and a partial Stop Work								
018	Brooklyn	1277	EAST 14 STREET	0	Order for a supported scaffold were issued. The Site Safety Manager reported that a carpenter was working on an "A"-Frame ladder when he missed the	ECB Violation	35285912M,35285913Y		NB	320597127	Worker Fell	1277 HOLDINGS LLC	Ray Builders Inc.
2018	Manhattan	40	CLERMONT AVE	0	fifth step of the ladder and fell. An ambulance came and took the worker to a hospital. The Site Safety Manager reported that a worker tripped	No Dispatch					Worker Fell		
2018	Manhattan	590	EAST 83 STREET	o	and jammed his finger. An ambulance took the worker 1 to a hospital.	No Dispatch			NEW BUILDING	121190987-01-NB	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
2018	Brooklyn	10	MONTIETH STREET	0	The Site Super reported that a worker attempted to jump over a fence and fell. The worker was taken to a 1 hospital by ambulance.	No Dispatch			NEW BUILDING	320622750-01-NB	Worker Fell	BUSHWICK HOLDINGS I LLC	GALAXY DEVELOPERS LLC
	<u> </u>				The Site Safety Manage reported that a worker hurt his shoulder while installing a pipe scaffold. The worker								
/2018	Manhattan	108	EAST 89 STREET	0	Includer Writer installing a pipe scentiod. The women't yeart to a City MD. to get checked. A DOB inspector reported that contractors were in the process of litting a section of steel casissors in order to set it on a drift reg when a worker had his hand plinched between the caisson and a steel hook. The worker was attent and awake and was taken to a nearby hospital by taxi. The extent of the injury to the worker's hand was not known as of the time of inspection. An ECB Violation for a failure to safeguard and an ECB Violation for there being no logs on site were issued, as well as a full Stop Work Order for the entire site. The contractor at the site was instructed to provide a Means and				ALTERATION TYPE 1	122988623-01-AL	Worker Fell		E.W. HOWELL CO, LLC
2018	Queens	43-12	HUNTER STREET	0	Methods for safe pile installaiton.	ECB Violation	35314355z 35314356k		NB	420659530	Mechanical Construction Equipment	43-12 HUNTER LLC	Judy y Lee
/2018	Bronx	2028	CRESTON AVENUE	0	The Site Safety Manager reported that at an eleven story new building under construction, a worker was handling concrete out of a mixer when cement splashed into the worker's right eye. The worker was alert and 1 awake and was taken to Lincoln Hospital for treatment.				NB	220392858	Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MNGMT
2018	Manhattan	650	5 AVENUE		The Site Safety Manager reported that a worker was working with temporary electrical wiriting on the second floor when a 480-volt wire touched an I-Bearn, which caused an ARC flash. The worker suffered an injury to his eyes and was taken to a hospital. A DOB inspector determined that there was no enforcement acton 1 necessary.	No Action Necessary			Electrical	M00016968	Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
2018	Brooklyn	1835	STERLING PLACE	0	The Construction Superintendent reported that a worke slipped off of an "A"-Frame ladder while coming down from the ladder. The worker suffered a minor laceration to the head. The worker was found conscious and an 1 ambulance was called.	No Dispatch			Electrical	NUUUTB965	Worker Fell	NOT ON FILE	
					The Site Safety Manager reported that an electrician was climbing up the rebar cage to reach the electrical conduit when he slipped, fell two feet, and landed on								
3/2018	Manhattan	40	10 AVENUE	0	It has right earlier. The electrician was earlier to a clinic. The Site Safety Manager reported that a worker was cleaning around a Con Edision vault when he litted an unmanded piece of plywood that was covering the vault, imped into a shaft, and fell approximately eight to rine feet. The worker safety and up to the a shaft, in the language of the safety of the souther safety of the safety of	No Dispatch					Worker Fell	40-56 TENTH OWNER LLC	
3/2018	Manhattan	115	DELANCY STREET	0	Methods and Tool Box Talk must be provided. The Site Safety Manager reported that a worker was	ECB Violation	ECB#35317775Z -FAIL TO SAFEGUARD	032318BSO3GD01	NB	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
					cutting metal studs when he cut the top of his hand with a chop saw. The worker went to the emergency room with another worker. An ambulance was not								
2018	Manhattan	1865	BROADWAY	0	The Site Safety Manager reported that a worker was moving windows when he tripped, fell three steps, and hit the back of his neck on a cinderblock. The worker	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
2018	Brooklyn	19	INDIA STREET	0	was alert and responsive and was taken to Bellevue 1 Hospital.	No Dispatch			NEW BUILDING	310234207-01-NB	Worker Fell	145 WEST STREET LLC	NOBLE CONSTRUCTION GR LLC
					The Construction Superintendent reported that a worker was testing a refrigerant line when the line burst, causing discomfort to the worker's ears. A co-worker								
	Brooklyn	101	PENNSYLVANIA AVENUE	0	1 drove the injured worker to a hospital.	No Dispatch			Alt 1	320622894	Other Construction Related Incidents	ATLANTIC 2644, LLC	CAULDWELL WINGATE CO LLC



Incident Date	Borough	Address Number	Street	Fatalities	Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/26/2018	Manhattan	250	SOUTH STREET		0	A DOB inspector reported that a worker was bringing a scatfold down when a gust of wind moved the platform out of the building. The worker stuck his hand out to prevenent the impact against the building, but hur his shoulder and buck in the process. The worker was taken to a hospital where he was in state condition. It was determined that no enforcement action was necessally, as the supported scaleful wis found to be notification and installation letter from the engineer was 1 onste, and all logs were in order.		N/A		MB.	121185528	Scaffold/Shed/Fence/Shoring/Installation	MOT ON FILE	Lend Lesse (US) Construct
3/26/2018	Manhattan	420	EAST 54 STREET		0	The Site Safety Manager reported that the building owner's personal driver had his foot struck by a forblitt. The injuried person was taken to a hospital. A DOB inspector reported that only one flag person was used when moving the forblitf and that the injured person walked into a controlled on access zone when he had his foot struck by the forblith. An ESO Violation was issued for a failure to safeguard. A DOB Violation and a partial Stop Work Order were also issued. A Means and Methods and Tool Box Talks will be provided by the General Contractor at the side for side delivery		35317780N	032618BSo6GD01	750	121700000	Other Construction Related Incidents	RIVER TOWER OWNER, LLC	construction (construction)
3/27/2018	Manhattan	432	EAST 14 STREET		0	The Construction Superintendent reported that a worke was pushing a mini container when she slipped and hit 1 her knee. The worker was taken to a hosoital.						Other Construction Related Incidents	EAST 14TH STREET OWNERS LLC	
3/28/2018	Brooklyn	505	PACIFIC STREET		0	The Site Safety Manager reported that a worker slipped with a grinder and cut his face. An ambulance transported the worker to a hospital.	No Dispatch			NEW BUILDING	320909004-01-NB	Other Construction Related Incidents	PVII HSC ATLANTIC LLC	TRITON CONSTRUCTION CO.,
3/28/2018	Manhattan	441	9 AVENUE		0	The Site Safety Manager reported that a worker got his hand jammed between two stripping panels. A foreman 1 took the worker to a hospital.						Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
3/30/2018	Manhattan	265	WEST 114 STREET		0	The Site Safety Manager reported that there was a worker on the second floor scaffold deck carrying a plank. The worker leaned on the plank, which caused the plank to fall and hit a worker that was on the first floor scaffold dock in the am. The higured worker went to a City M.D. for an X-ray. An ECB Violation was 1 sused for the storage of excess materials on a scaffold.	ECB Violation	35286045H		Ait 1	121189668	Material Fell	TRINITY WEST HARLEM PHASE TWO	Mega Contracting Gp LLC