

cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	13	EAST 7 STREET	0	1 The New York City Police Department reported that an exterminator feel lint to as it Yord Geep excavation in the basement. A DOB inspector reported that the worker suffered minor injuries and was taken to Bellevue Hospital and that there was unpermitted excavation work being performed in the basement. An Agravated Level 2 ECB Violation was issued for a failure to safeguard and work without a permit. A full Stop Work Order was issued.	ECB Violation	35309613X		No Permit	No Permit	Worker Fell	TRIAD CAPITAL, LLC	No Permit
2018	Manhattan	269	WEST 87 STREET	0	The Site Safety Manager reported that a worker was cleaning a platform from a multipoint scaffold when he slipped and fell five feet onto the ground, hitting his right elbow. An ambulance was on site. Four ECB Violations and a partial Stop Work Order were issued.		35285606Y, 35285607X, 35285608H, 35285609J				Worker Fell	RIVERVIEW OPERATING CO., LLC	Leeding Builders Group LLC
2018	Manhattan	430	EAST 58 STREET	0	The Site Safety Manager reported that a worker got his hand stuck between a steel plate and a frame and got two of his fingers crushed. The worker was sent to Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	SUTTON 58 HOLDING COMPANY LLC	
/2018	Manhattan	1681	3 AVENUE	0	The Site Safety Manager reported that a worker was loading garbage into a truck when he slipped on snow and hurt his arm. The worker walked to urgent care.	No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
/2018	Manhattan	301	FREEDOM PLACE SOUTH	0	The Site Safety Coordinator reported that a worker was unloading glass from a crate when a piece of glass fell and injured his leg. The worker was taken to a hospital. The extent of the worker's injuries was not known.	No Dispatch			NEW BUILDING	121192501-01-NB	Worker Fell	301 FREEDOM PLACE SOUTH, LLC	SCIAME CONSTRUCTION LLC
/2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker on the twenty fourth floor slipped on a patch of ice and hurth is shoulder. An amoutance was called to the site. A DOS shoulder. An amoutance was called to the site. A DOS diamond plates on the outside of a hoist had water and ice on them, which caused the worker to slip. An ECB Violation and a DOB Violation were issued.	ECB Violation	35301061R	010818BS02DH03			Worker Fell	G & M REALTY, L.P.	
W2018	Manhattan	40	10 AVENUE	0	The Site Safety Manager reported that a worker slipped on a second floor concrete deck, landed on his back and hurt his shoulder. The worker slipped because of snow. The worker walked to a City MD. A DOB inspector wisted the site and confirmed that the deck was covere with snow, which caused the worker to fall. An ECB Violation, a DOB Violation, and a partial Stop Work Order were issued.	,	35301164N	010918BS02VP01			Worker Fell	40-56 TENTH OWNER LLC	
/2018	Manhattan	400	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was handing down a screw-jack to another worker when the screw-jack slipped out of his hands and hit the other worker. The worker suffered a minor injury and went to hospital by ambulance for a cheek up. A DOB inspect hospital by ambulance for a cheek up. A DOB inspect hospital by ambulance for a cheek up. A DOB inspect of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of state of state of state of state stat		35301055Y	010918BS04DH03			Material Fell	BOP NE LLC	
0/2018	Staten Island	55	RICHMOND TERRACE	0	The Site Safety Manager reported that a worker slipped on ice. An ambulance was called. A DOB inspector reported that the worker slipped on ice that was located in an area that was closed off and where there was no work in progress. No enforcement action necessary.	No Action Necessary					Worker Fell	ST. GEORGE OUTLET DEV LLC	
0/2018	Queens	27-17	42 ROAD	0	The Side Safety Manager reported that a worker was installing sheet rock when he cut his left hand on a metal duct. The worker went to urgent care with another worker.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
0/2018	Manhattan	130	EAST 82 STREET	0	If The Site Safety Coordinator reported that an electrician was pulling cables in a box when he pulled his hand back and cut it on a piece of Chicago Bar. The incident occurred on 170(2018, but was not reported until 1/11/2018. The worker went to a doctor on his own.	No Dispatch			NEW BUILDING	121328027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
0/2018	Manhattan	118	FULTON STREET	0	1 A DOB inspector reported that a worker attempted to move an "A"-Frame cart that was loaded with about twenty flat stock metal sheets when the metal sheets fel onto his leg. The worker may have possibly suffered a broken leg. An EMT was on site. An ECB Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Methods for safe operations.		35300526R				Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	
1/2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager and a DOB inspector reported that a carpenter was standing on an "A" Frame ladder termove the door frame from an electrical closet on the S1 at floor when a piece of plywood that was behind the door frame came loose and hit fini in the shoulder, causing him to fall off of the ladder. The worker came look and the standard of the safety of				New Building	121333440	Worker Fell	CP V TS FULTON OWNER, LLC	CP V TS FULTON OWNER LLC
1/2018	Manhattan	151	MAIDEN LANE	0	1 A DOB inspector reported that a worker was using an "A"-Frame cart to move scaffolding elements when he wisted his wist while pulling the cart. The worker did not want to go in an ambulance and went to see a doctor on his own. There were no unsafe of hazardous conditions at the work area. No enforcement action was necessary.	No Action Necessary			New Building	121186769	Other Construction Related Incidents	151 MAIDEN LLC	PIZZAROTTI IBC LLC



ident Date	Borough	Address Numb	er Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	305	EAST 61 STREET	0	The Site Safety Manager reported that a worker tripped over a board that was on the floor and twisted his right	No Dispatch					Worker Fell	305 EAST 61ST STREET GROUP LLC	
					ankle. An ambulance was called to the site and took the worker to a hospital.								
)18	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that a pedestrian stepped on a piece of plywood under the upper sidewalk and slipped, injuring his right ankle. The pedestrian went to see a doctor on his own. An ECB Violation was issued.	ECB Violation	35300326M	011118BS05MA03			Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	
18	Queens	27-13	21 STREET	0	The Site Safety Manager reported that a carpenter was hitting a nail when the nail popped out and hit the worker in the face. The worker has no visible cut or injuries. An ambulance transported the worker to a hospital for a check up.	No Dispatch			NEW BUILDING	420993740	Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	DISANO DEMOLITION CO, INC
018	Manhattan	45	PARK PLACE	0	The Site Salety Manager reported that a worker was pumping concrete into a wheelbarrow when the concrete pump shifted and snagged his finger between the pump claims and the concrete cleaning basin, causing a large cut. The worker was taken to a hospial. A DOB inspector reported that according to the inspection of the logs, the injuryed worker did not lower by the was part of the operations. An Aggreened 2 ECD Violation, a DOB Violation, and a partial Slop Work Order were issued.		35263168X	011218CERMR01	NEW BUILDING	121185635-01-NB	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
018	Manhattan	590	EAST 83 STREET	0	The Site Safety Manager repoted that a worker was performing waterproofing work inside of a high concrete tank. When the worker was using a chemical sealant to waterproof the inside of the tank, he became overwhelmed by the fumes and passed out. The worker was taken to a hospital by an amulance. An ECB Violation, a DOB Violation, and a partial Stop Work Order were issued.	ECB Violation	35294740J	011518CERFC01	Alt 1 NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
2018	Manhattan	53	WEST 53 STREET	0	The Site Safety Manager reported that a worker pulled his groin while lifting a pipe. The worker went to a	No Dispatch			alt 1 NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LEND LEASE (US) CONSTRUCT
2018	Manhattan	130	EAST 82 STREET	0	MedRite. 1 The Site Safety Manager reported that a worker was cutting a piece of aluminum with a saw when the aluminum got caught in the saw and pierced his hand. The worker took a cab to a hospital.	No Dispatch			alt 1 NB	121325027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
018	Brooklyn	179	THROOP AVENUE	0	The Site Safety Manager reported that a worker was unloading a piece of pipe scaffold off of a truck when he lost control of the piece and the section fell onto his left leg. The worker was taken to a hospital by a friend.						Other Construction Related Incidents	NYC HHC	
2018	Manhattan	125	GREENWICH STREET	0	The Site Safety Manager reported that a piece of plywood fell onto a worker's hand during a stripping operation. There were two workers working one above the other, and the piece of plywood fell from above on the worker below. An ambulance was called. An a CIO Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Methods.	ECB Violation	35300553M				Other Construction Related Incidents	VS 125 LLC	
018	Manhattan	42	WEST 33 STREET	0	The Site Safety Manager reported that an iron worker was using a grinder to cut a piece of metal bar when the grinder kicked back and caused a cut to the worker's thumb. The grinder had all of its safety guards in place. The worker went to an urgent care facility for treatment.	No Dispatch			NEW BUILDING	121186849	Mechanical Construction Equipment	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
2018	Queens	22-44	JACKSON AVENUE	0	The Site Safety Manager reported that a worker was unpacking windows from a crate and was using a 2 X4 piece of wood as a lever to move the crate when the piece of wood snapped and hit him in the head, causing a scratch. An ambulance was called and the worker walked to the ambulance to go for a check up.	No Dispatch			NEW BUILDING	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
2018	Brooklyn	1601	KINGS HIGHWAY	0	2 A DOB inspector reported that a vehicle struck a manifi- with two workers in it that was parked in an occupied lane. The yockocks were not filled with water and a flagger was not present. The manifil wis not damaged, but one of the workers complained of leg pain, and the other worker was show up by the incident. Both of the workers were sent to a hospital for a check up. An ECB Volation and a partial Stop Work Order were issued.	ECB Violation	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
2018	Manhattan	200	AMSTERDAM AVENUE	0	The Site Safety Manager reported that a worker was unbooking the chain from an excavator that was lifting oxygen tranks when his glowes got stuck between the chain and the excavator's hock, prinching the worker's Imper. The worker was taken to a hospital by a construction of the control of the contro		3530559M 353055		NB	122887224	Mechanical Construction Equipment	AMSTERDAM AVENUE REDEVELOPMENT	Marc Depaul
/2018	Manhattan	650	5 AVENUE	0	The Site Safety Manager reported that a flagger was almost struck by a vehicle in the middle of the street and that he twisted his right ankle while moving out of the way. The flagger went to a hospital.	No Dispatch					Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	



	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Manhattan	445	WEST 35 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	CARE REALTY CORP.	
					moving a wooden plank while taking down a single								
					frame scaffold when he twisted his knee and complained of pain. The worker went to see a doctor on								
					his own.								
2018	Brooklyn	3003	WEST 21 STREET	0	1 The Site Safety Manager reported that a worker twisted	No Dispatch					Other Construction Related Incidents	CONCERN SURF VETS PLACE HOUSIN	
2010	Diodayii	5555	WEST ET STREET		her ankle while pushing a mini-dumpster. An ambulance was called and took the worker to a hospital.	Tro Disputori					Carci Conduction (Cated incidents	CONCENTION VETO I BIOC NOCON	
					was called and took the worker to a hospital.								
2018	Brooklyn	19	KENT AVENUE	0		ECB Violation	3505625p, 26r, 27z, 28k, 29m		CRANE NOTICE	871 17	Mechanical Construction Equipment	19 KENT ACQUISITION LLC	ALL ISLAN MASONRY & CONCRET
					setting up a mobile crane when his finger got pinched between the hook of the crane and a road barrier,								
					causing the finger to detach. A co-worker took him to a								
					hospital. Five ECB Violations and a partial Stop Work								
					Order were issued.								
/2018	Bronx	16	EAST 204 STREET	0	1 The Site Safety Manager reported that a worker slipped	No Dispatch					Worker Fell	HP VILLA GARDENS HDFC, INC.	
					and hurt his back at the job site. An ambulance was								
					called and took the worker to a hospital.								
2/2018	Manhattan	26	ANN STREET	0	1 The Site Safety Manager reported that a worker hurt his	No Dispatch					Worker Fell	143 FULTON STREET DEVELOPMENT	
22010	manatan	120	THE CONTROL		hand while taping and spackling on the ninteenth floor.	No Disputori					Worker Full	1401 OET ON OTHEET BEVEEOF MENT	
					The worker went to urgent care.								
2/2018	Queens	29-22	NORTHERN BOULEVARD	0	1 A DOB inspector reported that a worker was pushing an		35289063P				Material Fell	QSB NORTHERN LLC	
					"A"-Frame cart that was loaded with stone when the cart								
					overturned, causing stone to fall onto the worker's foot and possibly breaking the foot. An EMT was on site. An								
					ECB Violation and a partial Stop Work order were								
					ECB Violation and a partial Stop Work order were issued. The General Contractor is to provide a Means								
					and Methods and a Tool Box Talk.								
2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a worker cut his finger while cutting a piece of rebar. EMS was	No Dispatch			ALTERATION TYPE 1	321185953-01-AL	Worker Fell	THE SALVATION ARMY	SD BUILDERS AND CONSTRUCT
					cut his finger while cutting a piece of rebar. EMS was called. The worker was found conscious and was taken								
					to an area hospital.								
/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NYC HPD	
					doing form work with while he had his peligan hook								
					attached to himself. When the worker was climbing								
					down a ladder, the peligan hook fell and hit his right ear. The worker went to a City MD. An ambulance was not								
					called. This incident was the result of a worker error.								
3/2018	Manhattan	111	EAST 24 STREET	- 1	0 A DOB inspecor reported that an elevator foreman was	DOR Violation		012318BS0501BG	NR	121192798	Worker Fell	DEMETRIOS & FANIA SAMUEL, LLC	TRINITY BUILDERS INC
12010	manatar	ļ	ENOT 24 OTNEET		working on a platform for installing an elevator inside the			01201020000120	1.5	121102100	Worker Full	DEMETRIOS ATTAIN OF MISEE, EES	THAT I BOLDETTO INO
					elevator shaft at the sixth floor when the platform started								
					drifting upwards uncontrollably and would not stop. The								
					worker tried to jump to the machine room on the other platform at the ninth floor, but he fell backwards down								
					the shaft to the cellar floor, where he succumbed to his								
					injuries. The elevator foreman did not have a safety								
					harness on and was not tied to anything. There were no								
					safety lines found at the site. A DOB Violation and a full Stop Work Order were issued.								
					Stop Work Order were issued.								
3/2018	Queens	62-98	SAUNDERS STREET	- 1	The New York City Police Department reported that a	ECB Violation	35308671J. 35308670H	012318CERTQ01. 02			Worker Fell	NOT ON FILE	
3/2010	Queens	02-90	SAUNDENS STREET		worker was standing on a window sill of a sixth floor		333000713, 3330007011	0123180EKTQ01, 02			Workerren	NOT ON TIEE	
					apartment when he fell from the sixth floor to the ground								
					The worker was transported to North Shore University Hospital, but was found dead on arrival by the NYPD. A								
					Hospital, but was found dead on arrival by the NYPD. A DOB inspector inspected the site and reported that there								
					was work present that consisted of a gut renovation to								
					the bathroom, the installation of new electrical wiring								
					and box, and the installation of new sheetrock, without a								
					permit. Two ECB Violations, two DOB Violations, and a Stop Work Order were issued.								
					Stop Work Order were looked.								
10045		1-1-											
/2018	Staten Island	546	GULF AVENUE	0	The Site Safety Manager reported that a worker got concrete in his eyes during a concrete pour operation.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
/2018	Staten Island	546	GULF AVENUE	0	concrete in his eyes during a concrete pour operation.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
4/2018	Staten island	546	GULF AVENUE	0	The Site Safety Manager reported that a worker got concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
	Staten Island Manhattan	280	GULF AVENUE PARK AVENUE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an	No Dispatch ECB Violation	35312686Y	012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC BROADWAY 280 PARK FEE LLC	
				0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he		35312686Y	012918EE105FM1					
				0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The		35312686Y	012918EE105FM1					
				0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on		35312686Y	012918EE105FM1					
				0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The		35312686Y	012918EE105FM1					
				0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electricial work beino performed without a	ECB Violation	35312696Y	012918EE105FM1					
				0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation	ECB Violation	35312686Y	012918EE105FM1					
2018	Manhattan	280	PARK AVENUE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also as some performed without a permit.	ECB Violation	35312686Y	012918EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
/2018				0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also as some performed without a permit.	ECB Violation	35312686Y	012918EE105FM1					
2018	Manhattan	280	PARK AVENUE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electricial work being performed without a permit. A DOB Violation was also issued. 1 The Sile Safety Manager reports that a flagger was direction taffic when he was side-swieed by a vehicle.	ECB Violation	35312686Y	012918EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
/2018	Manhattan	280	PARK AVENUE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on so not motified until January 23, 2018. An ECR Violation was issued for electrical work being performed without a permit. A DOB Violation was discovered to the permit of the	ECB Violation	35312686Y	012918EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
/2018	Manhattan	280	PARK AVENUE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electricial work being performed without a permit. A DOB Violation was also issued. 1 The Sile Safety Manager reports that a flagger was direction taffic when he was side-swieed by a vehicle.	ECB Violation	35312686Y	012918EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
4/2018 4/2018 4/2018	Manhattan	280	PARK AVENUE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electricial work being performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle. The driver did not want to listen to the flagger. The flagger was day, but was taken to a hospital by an ambulance for a checkup.	ECB Violation	35312686Y	012918EE105FM1	ALTERATION TYPE 1	121333413-01-AL	Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	CNY CONSTRUCTION LLC
//2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This succident took place on most or contified until January 29, 29, 2918. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Sits Safety Manager reports that a flagger was directing traffic when he was also issued. The driver direct of wast of the control of the site of the direction of th	ECB Violation	35312686Y	012918EE105FM1	ALTERATION TYPE 1	121333413-01-AL	Other Construction Related Incidents Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	CNY CONSTRUCTION LLC
/2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electricial work being performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle. The driver did not want to listen to the flagger. The flagger was day, but was taken to a hospital by an ambulance for a checkup.	ECB Violation	35312686Y	012918EE105FM1	ALTERATION TYPE 1	121333413-01-AL	Other Construction Related Incidents Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	CNY CONSTRUCTION LLC
/2018	Manhattan Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This sneddent took place on most or contified until January 29, 29, 2918. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Sits Safety Manager reports that a flagger was directing traffic when he was also issued. 1 The Sits Safety Manager report that a flagger was directing traffic when he was also eviped by a vehicle. The driver direct of was that the superior was considered to the superior was observed to the superior was observed to the superior was observed to the superior was characteristic to the flagger. The flagger was okay, but was taken to a hospital by an ambulance for a checkup. 1 The Sits Safety Manager reported that a worker was cutting rebar when he slipped and cut his finger. The worker drove himself to a first med for precaution.	ECB Violation No Dispatch No Dispatch		012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	
/2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Site Safery Manager reports that a flagger was directing traffic when he was side-swiped by a whice. The driver did not want to listen to the flagger. The flagger was diversity to the state of the state	ECB Violation No Dispatch No Dispatch	35312686Y	012918EE105FM1		121333413-01-AL 122917503	Other Construction Related Incidents Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	CNY CONSTRUCTION LLC allba services
W2018	Manhattan Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE	0 0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 24 th, but the beganner of C Bulldings was usually a splice box when he was shocked took place on January 24, 25 th, but the beganner of C Bulldings was sissued for electrical work being performed without a permit. A DOB Violation was also issued by a welfold that the state of the split of of the spli	ECB Violation No Dispatch No Dispatch		012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	
3/2018 3/2018	Manhattan Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Site Safery Manager reports that a flagger was directing traffic when he was side-swiped by a whice. The driver did not want to listen to the flagger. The flagger was diversity to the state of the state	ECB Violation No Dispatch No Dispatch		012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	
/2018	Manhattan Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE	0 0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electricial work being performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle. The driver did not want to listen to the flagger. The flagger was day, but was taken to a hospital by an ambulance for a checkup. 1 The Site Safety Manager reported that a worker was cutting rebar when he slipped and cut his finger. The worker drove himself to a first med for precaution. 4 A DOB inspector reported that a worker was cutting rebar when he slipped and cut his finger. The flow of the precausion of the second floor when a rung on the ladder range, classing the worker to fall ten feet and land on his back. The worker was found conscious and was taken to the hospital by was found to the second floor when a rung on the ladder range, classing the worker to fall ten feet and land on his back. The worker was found conscious and was taken to the hospital by	ECB Violation No Dispatch No Dispatch		012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	
2018	Manhattan Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2015, but the Department Of Buildings was not notified until January 29, 2016. An ECB Violation was assued to electrical work being performed without a permit. A DB Violation was after that the performance of the desired with the performance of the desired without a permit. A DB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swyed by a vehicle. The driver did not want to listen to the flagger. The flagger was clearly the performance of the develop. Determine the list first flore to the worker drove thinself to a list met of prograduion. 1 A DOB inspector reported that a worker was cutting rebar when he slipped and cut his finger. The worker drove themself to a list met of for precaution. 1 A DOB inspector reported that a worker was cutting rebar when he slipped and cut his finger. The worker worker drove this part of the desired of the prograduion of the development of the prograduion. 1 A DOB inspector reported that a worker was climbing up and "A-"rame ladder from the first floor to the second for the prograduion of the prograduion of the prograduion. 2 Post prograduion of the prograduion of	ECB Violation No Dispatch No Dispatch ECB Violation		012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	
2018	Manhattan Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE	0 0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electricial work being performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle. The driver did not want to listen to the flagger. The flagger was day, but was taken to a hospital by an ambulance for a checkup. 1 The Site Safety Manager reported that a worker was cutting rebar when he slipped and cut his finger. The worker drove himself to a first med for precaution. 4 A DOB inspector reported that a worker was cutting rebar when he slipped and cut his finger. The flow of the precausion of the second floor when a rung on the ladder range, classing the worker to fall ten feet and land on his back. The worker was found conscious and was taken to the hospital by was found to the second floor when a rung on the ladder range, classing the worker to fall ten feet and land on his back. The worker was found conscious and was taken to the hospital by	ECB Violation No Dispatch No Dispatch ECB Violation		012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMINTCP	



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	44	UNION SQUARE	0	1 The Site Safety Manager reported that a worker at a						Other Construction Related Incidents	READING TAMMANY OWNER LLC	
					concrete truck had a miscommunication with the driver and the shoot came down and hit the worker on the hand. The worker suffered a minor injury and an								
					ambulance was called.								
2018	Manhattan	450	WEST 33 STREET	0	A DOB inspector reported that during a demolition operation on the first floor of the HVAC conduits and utilities lines, a construction worker was cleaning demolition debris on the first floor when a pipe section fell approximately four feet and hit the worker in the head. The pice section fell because another worker cut.	ECB Violation	35310356M		Alteration 2	140188767	Material Fell	450 PARTNERS LLC	Tishman Construction Corp
					leadur. He pipe secución reli obelación al obligation. The worker who was hit by the pipe section. The worker who was hit by the pipe section initially refused medicul attendion, but wasn't feeling well after a few hours and called EMS. The worker was taken to a hospital by ambulance. A Construction Superintendent was not required at the site. An ECB Violation and a full Stop Work Order were issued. The General Contractor must provide a Means and Methods for the demolition of the remaining HVAC conduits.								
2018	Manhattan	500	WEST 33 STREET	0	1 A DOB inspector reported that an electrician was in the	No Action Necessary			NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
					process of erecting a sharply while climbing an eight foot ladder when he missed a rung of the ladder and fell three feet. The worker was taken to Bellevet Hospital. A DOB inspector visited the site and reported that no enforcement action was deemed necessary.				NEW BOLES.NO	121100251 01110	Notice 1 cm	NOT SATURE	
9/2018	Brooklyn	404	11 STREET	0	1 A DOB inspector reported that workers were receiving a load of concrete masonry unit (CMU) brick on the third floor V-obits towads the rear of a new extension partially collapse due to excessive weight and because the C-Joists were not properly secured to the CMU wais. The collapse also caused the second and first floors to collapse into the cellar. One worker sustained minor injuries and was taken to Brooklyn Presbyterian Hospital. An Aggravated Level 2 ECB		35310459N		Alteration	321190858	Other Construction Related Incidents	404 11TH ST NY CORP	SUN SUN Contracting
					Violation and a full Stop Work Order were issued for a failure to saleguard. A aldewalk shed has been requested to be immediately installed at exposure four. ODB will remain on site until the sidewalk shed is installed. The site will be referring to DOB's Interior Demolition Engineering Unit for audit and approval of all temprary shoring.								
2018	Brooklyn	422	FULTON STREET	0	The Site Safety Manager reported that a worker fell	No Action Necessary					Worker Fell	NOT ON FILE	
					through the interior opening for a tower crane installation from the ninth floor the eighth floor. The worker was taken to a hospital, where he was eventually released with no injuries. The worker did attend a safety orientation meeting at the start of his shift. A DOB inspector visited the site and reported that there was proper signage and a proper guardrail system present at the perimeter of the slab opening, but that the worker disregarded all safety measures provided to prevent falling hazards. No enforcement action was necessary.								
/2018	Manhattan	209	EAST 19 STREET	0	The Site Safety Manager reported that a worker was using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.	No Dispatch			ALTERATION TYPE 1	121724946-01-AL	Worker Fell	227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
/2018	Manhattan	500	WEST 33 STREET	0	The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Manhattan	20	BROAD STREET	0	ambulance was called. 1 The Site Safety Manager reported that a worker was	ECB Violation	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
					pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.								
1/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a time floor column. One worker was positioned below the second worker, holding him in place while he was installing a claimp. While securing the claimp, the claimp, left and hit the below worker in the face. The worker staken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.	No Action Necessary					Material Fell	NYC HPD	
/2018	Manhattan	1283	YORK AVENUE	0	The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, lost his balance, and fell on his rear. The worker walked to a City MD for a check up.	No Dispatch					Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	
1/2018	Manhattan	209	EAST 19 STREET	0	The Site Safety Manager reported that a worker hurt his finger while unloading pipes from a delivery truck. The worker went to a City MD on his own.	No Dispatch					Other Construction Related Incidents	227 EAST 19TH STREET OWNER, LL	
/2018	Manhattan	435	EAST 13 STREET	0	The Construction Superintendent reported that a third party inspector missed the last step on his way down a permanent flight of stairs and hurt his foot. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	



cident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	532	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker slipped on ice meth pellets that were on the ground floor of the job site in an area where ice melt had been put down to melt ice. The worker hurt his wrist and his hip. The worker went to see the onsite medic before going to see an offsite medic on his own.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/2018	Manhattan	550	WEST 29 STREET	0	The Site Safety Manager reported that a worker was using a grinder when the blade caught his glove and caused a cut to his hand. An ambulance was called.	No Dispatch					Other Construction Related Incidents	550 WEST 29TH STREET LLC	
018	Manhattan	1865	BROADWAY	0	The Site Safety Manager reported that a worker cut his pinky finger while putting away his band-saw tool. The band-saw was unplugged. The worker went to a clinic. An ambulance was not called	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
)18	Manhattan	328	EAST 62 STREET	0	The Construction Superintendent reported that a worker was installing pour stops when he slipped into the side of rebar and injured his shoulder. The worker left the site				Alt 1 - NB	121189846	Other Construction Related Incidents	YYY 62ND STREET LLC	JOY CONSTRUCTION CORP
018	Manhattan	591	THIRD AVENUE	0	in a cab. 1 The Site Safety Manager reported that a painter was carrying down supplies when he lost hs balance on the fourth step and fell, hurting his leg. An ambulance was called and the ambulance took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	587-91 THIRD OWNER LLC	
018	Brooklyn	1	FLATBUSH	0	The Site Safety Manager reported that a worker was removing debris when a four inch pipe that was about three feet long fell on his foot. The worker went to a hospital.	No Dispatch					Other Construction Related Incidents		
2018	Bronx	869	EAST 147 STREET	0	The Site Safety Manager reported that a worker complained about lower back pain while pulling a stud during carpentry work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	HP MLK PLAZA HOUSING DEVELOPME	
2018	Brooklyn	1	FLATBUSH AVENUE	0	1 The Site Safety Manager reported that a worker was doing taping work while on an "A"-Frame ladder when he mis-stepped and fell two feet. The worker suffered a minor injury and an ambulance was called.	No Dispatch					Other Construction Related Incidents	ONE FLATBUSH AVENUE PROPERTY L	
2018	Brooklyn	37	BLUE SLIP	0	The Site Safety Manager reported that a worker got his thumb pinched between a window and a rack during a delivery. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT G LLC	
2018	Manhattan	10	RIVERSIDE BOULEVARD	0	The Site Safety Manager reported that a worker hurt his back while lifting a reel of wire into a box. An ambulance was called.	No Dispatch					Other Construction Related Incidents	RCB3 NOMINEE LLC	
2018	Manhattan	24	2 AVENUE	0	1 The Site Safety Manager reported that a worker was putting away his tools at the end of the day when he opened a sliding glass door came off of its track and hit the worker. The incident took place on 2/5/2018, but was not reported until 2/6/2018. An ambulance was not called, but the worker said that he was going to see a doctor to be checked out. An ECD Violation and a DOB Violation were issued. A partial Stop Work Order on the use and installation of all bactory sliding doors was issued. The General Contractor is to provide a Manufacturer's Specification on all door tracks and the reason for the door falling off its track.	ECB Violation	35299721R	020618BS03GD02			Material Fell	24 SECOND AVENUE OWNER LLC	
018	Manhattan	260	WEST 40 STREET	0	A DOB inspector reported that a worker was trying to reach for something on the platform of a baker scaffold when he moved the baker scaffold, causing it to strike the left shoulder of another worker. Both workers were on the floor and not using the scaffold. The injured worker was sent to a Mad-Rite Clinic for a check up. The injured worker did not suffer a major injury. An ECB Violation was issued.		35285826Y		NB	121187394	Material Fell	PORT 40TH PARKING CORP	ZDG LLC
2018	Staten Island	546	GULF AVENUE	0	The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con-Edison box. The worker went to Staten Island Hospital on his own for a check up.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Manhattan	91	LEONARD STREET	0	The Site Safety Manager reported that a worker tripped, fell, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital.	No Dispatch			NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
2018	Manhattan	91	LEONARD STREET		mechanical room and cut his pinky finger. The worker went ot a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	353-357 BROADWAY LLC	
018	Manhattan	2395	FREDERICK DOUGLAS BOULEVARD	0	1 A DOB inspector reported that a worker was hit in the head with a piece of timber that was dropped by another worker during a stripping operation. The worker who was hit by the piece of timber complained of a siff neck and was sent to a hospital. An ECB Violation was issued, as well as a partial Stop Work Order on all concrete work. A Means and Methods must be provided.	ECB Violation	35289390M				Other Construction Related Incidents	HP 2395 FDB HOUSING DEVELOPMEN	
2018	Manhattan	1283	YORK AVENUE	0	The Site Safety Manager reported that a worker was moving an "A"-Frame doily that was loaded with twenty sheets of 4 x 8 diamond plates when the doily tipped and hit her ankle. The injured worker went to an emergency room that was across the street from the site. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35299967R				Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	



ncident Date	Porquah	Address Number	Street	Estalities Initiales	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/6/2018	Brooklyn	Address Number 911	Street ERSKINE STREET	o O	IFOC Intal Description IThe Site Safety Manager reported that a worker was cutting the remainder of wood piles that were approximately four feet. While cutting one of the piles, the pile fell forward and hit him in the head. The worker went to a hospitable by ambulance. This incident coursed on 26/2018, but was not reported until 28/2018. An ECB Violation was issued for a failure to notify the Department Of Buildings of the incident, as well as a partial Stop Work Order for the cutting of all wood piles. A Means and Methods for safe cutting operations with a tool box talk will be provided.	ECB Violation	ECB Violation Numbers 35300647X,49J	DOB Violation Numbers 020818BS06HM01,02	Permit	restitt NO	Incident type Material Fell	OWNER'S Name FOUNTAIN SEAVIEW THREE HOUSING	consistor Name
/7/2018	Brooklyn	540	FULTON STREET	0	The Site Safety Manager reported that during a drilling operation for tie backs, a carpenter that was assisting the drill operator stepped not no equipment insert and the clamp closed down on his left foot. The worker was taken to a hospital by emergency personnel. Two ECB Violations, including an Aggravated Level 2 ECB Violations, and a transfer and a tra	ECB Violation	35309900Z 35309901K		NB	321185828	Mechanical Construction Equipment	540 FULTON ASSOCIATES	PAV-LAK CONTTRACTING INC
7/2018	Manhattan	460	PARK AVENUE SOUTH	0	The Site Safety Manager reported that a worker was opening a crate of window frames when a 5' X 5' tube pipe rolled out and onto his foot. The worker was seen walking around, but an ambulance was called.	No Dispatch					Other Construction Related Incidents	460 PARK AVENUE SOUTH ASSOCIAT	
7/2018	Queens	27-17	42 ROAD	0	The Site Safety Manager reported that a worker lacerated his hand with a utility knife during a stripping operation when the utility knife slipped. The worker went to a hospital on his own.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
/8/2018	Brooklyn	810	FULTON STREET	0	The Site Safety Manager reported that a worker was performing stripping work on the eleventh floor when he pulled down a piece of plywood and the aluminum leg of the formwork hit the worker in the face and split his lip. An ambulance was called. An ECB Vlotation was issued for a failure to provide safety measures. A DOB Violation was also issued. A Tool Box Talk will be issued before the start of stripping operations.		35300050K	020818BS02EP06			Material Fell	GREENPOINT-GOLDMAN CORP.	
2018	Manhattan	388	GREENWICH STREET	0	The Site Safety reported that a worker hurt his foot while using a chipping gun. The worker took a cab to urgent care.	No Dispatch			ALTERATION TYPE 1	121190503-01-AL	Other Construction Related Incidents	CITIGROUP TECHNOLOGY, INC.	TISHMAN CONSTRUCTION CORP
3/2018	Queens	34-11	BEACH CHANNEL DRIVE	0	The Site Safety Manager reported that a worker was dismantling a scafflod when the plank he was standing on broke and fell six feet. The worker went to a hospital by ambulance. An ECB Violation for a failure to safeguard all persons and property affected by construction operations was issued.	ECB Violation	35285811N		NB	421094283	Worker Fell	NOT ON FILE	Chateau GC LLC
/2018	Queens	160-08	JAMAICA AVENUE	0	The Site Safety Manger reported that a vehicle struck the flagman in the street. The Police Department responded to the incident. The worker was taken to Jamaica Hospital.	No Dispatch					Other Construction Related Incidents	160 JAMAICA, LLC	
2018	Manhattan	1865	BROADWAY	0		No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
9/2018	Brooklyn	500	GATES AVENUE	0	The Super reported that a mason was using a grinder for brick cutting when the grinder kicked back and the grinder's butt end (not the blade) hit the mason in the face. The mason suffered a bruise to his face and felt a little dizzy. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PCMH 500 GATES HOUSING DEVELOP	
/2018	Brooklyn	340	EVERGREEN AVENUE	0	The Fire Department reported that a worker was hit in the head with a piece of rebar. Four ECB Violations and four DOB Violations were issued. A partial Stop Work Order was also issued. A Means and Methods and a Tool Box Talk must be provided.	ECB Violation	35300117X,118H,120R,121Z	020918BS04DH01,02,04,05			Material Fell	BUSHWICK REALTY HOLDINGS LLC	
2/2018	Bronx	2568	PARK AVENUE	0	The Site Safety Manager reported that a worker cut his knee while walking by rebar. The worker was taken to an area medical facility by a co-worker.	No Dispatch				220152484	Other Construction Related Incidents	2568 BRONX PARK LLC	STEVEN ALESSIO
12/2018	Brocklyn	135	EMERSON PLACE	0	1 The Site Salety Manager reported that during a stripping operation, a worker fell down from the sixth floor and landed on top of the sidewalk shed. The worker was found unconscious, but breathing. The worker was found unconscious, but breathing. The worker was towned to the stripping form. The worker was taken to a hospital by ambulance. An ECB Violation and a full Stop Work forder were issued. Three additional EQB Violations/OATH Summonses and three partial Stop Work Orders were issued by the Concrete Enforcement Unit.	ECB Violation	35300065N				Worker Fell	PRATT INSTITUTE	
12/2018	Manhattan	11	WEST 53 STREET	0	The Site Safety Manager reported that a worker was working in a man lift when he moved his body and twisted his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	THE MUSEUM OF MODERN ART	
12/2018	Manhattan	200	EAST 95 STREET	0	1 The Site Safety Manager reported that a worker pinched his finger while moving a steel beam on an "A"-Frame. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents		



ncident Date		Address Number	r Street	Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/12/2018	Manhattan	461	WEST 34 STREET	0	The Site Safety Manager reported that a worker cut his left hand on metal studs. The worker was taken to an	No Dispatch			ALT 1	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	EDWARD M GRUNWALD
					area hospital and received several stitches.								
13/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker entered	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
					the site from the outside of the mall area by the dirt parking area side, fell in ice that was mixed with dirt, and								
					hurt his ankle. The worker went to urgent care.								
13/2018	Queens	80-08	135 STREET	0	2 The General Contractor reported that two workers were	ECB Violation	35309854r		ALT 1	420652378 AL	Mechanical Construction Equipment	BRIARWOOD MP LLC	PAV-LAK CONTRACTING INC
					injured while grouting when a pump hose got clogged with grout and blew into the worker's faces. The workers								
					with grout and blew into the worker's faces. The workers tried to un-clog the pump while it was in use. The two								
					workers were taken to a hospital for treatment. An ECB								
					Violation and a partial Stop Work Order were issued.								
13/2018	Queens	45-57	UNION STREET	0	1 A DOB inspector reported that a worker was using the	ECB Violation	35299630L				Worker Fell	DEPARTMENT OF EDUCATION	
					scaffold's stairs to bring rebars onto a floor when a rebar got caught on the stairs and pulled the same worker								
					down. The worker was experiencing aches in his body								
					and went to a clinic the next day. This incident took place on February 13, 2018, but was not reported until								
					Place on February 13, 2018, but was not reported until February 14, 2018. The building was a five story building								
					with no permanent stairs. An ECB Violation and a full	1							
					Stop Worker Order were issued for inadequate								
					ingress/egress, an adequate supported scaffold, and the	1							
					lack of internal stairs.								
5/2018	Brooklyn	1060	CLARKSON AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch			ALTERATION TYPE 2	202501247 04 514 07	Worker Fell	DEPARTMENT OF EDUCATION	ANSU CONSTRUCTION INC
13/2018	DIOUKIYN	1060	CLARRSON AVENUE	0	The Site Safety Manager reported that a worker cut his arm with a saw while cutting wood. The worker was	NO Dispatch			ALTERATION TYPE 2	30/258134/-01-EW-OT	WOIKEF FEII	DEPARTMENT OF EDUCATION	ANSU CONSTRUCTION INC
					taken to a hospital by ambulance.								
15/2018	Manhattan	101	WEST 57 STREET	0	1 A DOB inspector reported that contractors were	ECB Violation	35308906P	021518CERDY04			Material Fell	101 WEST 57TH STREET HOTEL INV	
					attempting to remove a tempered glass panel when the								
					panel shattered. A small piece of glass fell to the street level while the remainder of the shattered panel was on								
					the terrace. A woman was injured and taken to a								
					hospital by ambulance. The women's injury was minor								
					and not life threatening. An Aggravated Level 2 ECB Violation, a DOB Violation, and a partial Stop Work								
					Order were issued for a failure to safeguard all persons								
					and property during construction operations.								
15/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Worker Fell	38-46 WEST 33 STREET, LLC	
					climbing off of a scaffold when he slipped and fell approximately two feet, injuring his shoulder. An								
					ambulance was called.								
/15/2018	Queens	30-35	COLLEGE POINT BOULEVARD	0	1 A DOB inspector reported that a painter was on a	ECB Violation	35317705N				Other Construction Related Incidents	FEINSTEIN CP REALTY LLC	
					scissor lift painting the area next to a roll down door								
					sensor when he activated the door, which caused								
					another worker to get hit by the door. The worker had the wind knocked out of him and was sent to a hospital								
					An ECB Violation and a partial Stop Work Order were								
					issued for the failure to maintain safe operations. The								
					General Contractor at the site is to provide a Means and Methods.								
16/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a concrete	No Action Necessary					Other Construction Related Incidents	SMITELL SPONSOR LLC	
					worker was carrying a Doka form that was about 2 X 9 feet and 100 pounds when he slipped and fell. The								
					worker complained of back pain. A DOB inspector								
					responded to the incident and reported that no								
					enforcement action was necessary, as the injury occurred as the result of a worker error.								
16/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NEW BUILDING	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTRUCTION SERVICE
		200			lifting a piece of rebar when he claimed to have hurt his				boilbillo		The state of the s		
					back. The worker walked up to an ambulance and the								
					ambulance took him to a hospital.								
16/2018	Manhattan	20	HOWARD STREET	0	2 A DOB inspector reported that an inspector from Cole	ECR Violation	353089087	021618CERDY01			Material Fell	434 BROADWAY PROPERTY INVESTOR	CANV Architecture & Engineering DDC
10/2018	warnauan	38	HOWARD STREET	U	2 A DOB inspector reported that an inspector from Cole NY was performing an inspection of the building for	ECP VIOLATION	333009082	UZ1618CEKDYU1			Material Fell	434 BRUADWAY PROPERTY INVESTOR	CANT Architecture & Engineering, DPC.
					façade local law. While inspecting the building, the								
					inspector stepped out onto the fire escape on the								
					seventh floor, and a step of the fire escape became dislodged and fell to the ground, striking two								
					pedestrians. One of the pedestrians suffered a life								
					threatening injury, and the second pedestrian was in								
					serious condition. The inspector fell slightly through an opening, but not all the way down. EMS was called. An								
					ECB Violation, a DOB Violation, and an Immediate								
					Emergency Declaration were issued.								
6/2018	Queens	71-17	ROOSEVELT AVENUE	0	1 A DOB inspector reported that were four workers	ECB Violation			NEW BUILDING	420653000	Material Fell	ROOSEVELT PARC LLC	BRAVO BUILDERS LLC
					unloading bundles of rebar that were approximately forty	,			boilbillo				
					five feet from a flatbed truck when one of the workers								
					lost control of the bundle and the bundle fell on the leg of another worker. There was no equipment used during								
					the unloading. The injured worker suffered a broken								
					right leg and was taken to a hospital. An ECB Violation and a partial Stop Work Order were issued for a failure								
					and a partial Stop Work Order were issued for a failure								
					to maintain the safe operations and to stop all material handling, including deliveries. The General Contractor is								
					to provide a safe Means and Methods, including								
					equipment and Tool Box talks.								



cident Date		Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Manhattan	200	EAST 21 STREET	0	The Site Safety Manager reported that a worker dislocated his left shoulder when he lifted a bag of	No Dispatch			NEW BUILDING	121190479-01-NB	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC
					concrete onto it. The worker was taken to Mount Sinai Hospital by ambulance.								
1018	Brooklyn	805	WASHINGTON AVENUE	0	A DOB inspector reported that a worker was walking	ECB Violation	35317732Z, 35317733K AND 35317736K		NEW BUILDING	321478548	Mechanical Construction Equipment	805 WASHINGTON AVE LLC	HAPPY LIVING DEVELOPMENT
					close to a Bobcat while an I-Beam was on the forks attached to the Bobcat when the I-Beam moved and the worker's hand got caught between the I-Beam and the Bobcat track. The worker suffered a fractured hand and was taken to an area hospital. The worker operating the Bobcat was not trained by the employer, which created this situation that resulted in an rijury to another work. This incident occurred on 219/2018, but the Site Salety Manager was not informed of the incident until 2/20/2018. Four EGB Wichations and a partial stop Work order were issued.								
/2018	Brooklyn	211	SCHERMERHORN STREET	0	The Site Safety Manager reported that a worker rolled his ankle while moving material. The worker was taken to Brooklyn Hospital by EMS.	No Dispatch			FRANK HEALEY	321196200-01-NB	Other Construction Related Incidents	211 SCHERMERHORN DEVELOPMENT L	OESTREICHER CONSTRUCTION
/2018	Manhattan	115	DELANCY STREET	0	The Site Safety Manager reported that a worker cut his finger while using a grinder. The worker went to urgent	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Manhattan	425	PARK AVENUE	0	1 The Site Safety Manager reported that a worker fell from	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
2010			, Autoritation		the fourth step of an "A"-Frame ladder. The worker complained of back pain. An ambulance was called.	, no bispaidi					Carlot Contained included	1 G 42517111177VENGE, EEG	
1/2018	Brooklyn	5718	2 AVENUE	0	1 A DOB inspector reported that a worker was pulling on one of the clips of a outrigger scaffold in order to install it properly. The worker pulled the clip hard, which caused the worker to stilled down the planks and twest his ankle. The worker went to the emergency room across the street and then went home. The formwork and outriggers were all built as per design. No enforcement was action necessary, as it was determined that the injury occurred as the result of a worker error.				ALTERATION-1	321192702	Worker Fell	NYU HOSPITALS CENTER	HUNTER ROBERTS CONSTRUCTION
10040		217	hurat states		d To Co. Co. Co. Manual Co.	N. Brancos					M. J. F. B	OMETEL OPONOOD I O	
1/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager has reported that a worker wa climbing down an "A"-Frame ladder when he slipped and fell about four feet. An ambulance took the worker to a hospital. The worker suffered a possible fractured elbow.	s No Dispatch					Worker Fell	SMITELL SPONSOR LLC	
1/2018	Queens	131-11	FOWLER AVENUE	0	The Site Safety Manager reported that a worker twisted his right wrist while bending rebars. A co-worker took him to a clinic.	No Dispatch					Other Construction Related Incidents	131-05 HOLDING LLC	
1/2018	Queens	38-01	QUEENS BOULEVARD	0	1 The Site Safety Coordinator reported that a worker tripped on tape on a scaffold platform, which caused hir to fall and twist his knee. The worker was taken to urgent care. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard all persons and property.	ECB Violation	35285820P		NB	421387626	Worker Fell	CURBOUT QUEENS BLVD LLC	Sordoni Construction Comp
2/2018	Staten Island	35 a	BAY STREET	0	The Site Safety Manager reported that a rebar installer slipped on a rebar floor and twisted his ankle. An ambulance was on site.	No Dispatch					Other Construction Related Incidents		
2/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker was loading sheetrock onto an "A"-Frame when one of the boards slid and landed on his right foot. The worker was sent to urgent care.						Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
22/2018	Manhattan	122	LEXINGTON AVENUE	0	The Polico Department reported that two workers were making a delivery to the roof area of the structure when one of the workers led approximately eight to ten feet through an opening in the roof that was covered with a tarp. The worker fell to the third floor. The worker suffered injuries to his back and neck and was transported to Bellevue Hospital with head and neck injuries. A full Stop Work Corder had been issued to the building on 4/22/2015 and a Vacate Order was issued on 12/22/2017. Two EGW Violations, and two DOB Violations were issued for the unlawful continuation of work white on the notice of a Stop Work Order and for a failure to safeguard.		35308961K & 35308960Z	022218CERTQ01 & 022218CERTQ02			Worker Fell	122-24 LEXINGTON AVECP	
2/2018	Brooklyn	19	KENT AVENUE	0	1 The Site Safety Manager reported that a worker walked into a pile of plywood and then felt discomfort in his upper torso and chest. An ambulance was called and the worker was transported to a hospital.	No Dispatch			NEW BUILDING	320591944-01-NB	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
2/2018	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	NYC HPD	
					finger while handling rebar. The worker was seen by the								



ncident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/23/2018	Queens	83-09	35 AVENUE	0	1 A DOB inspector reported that workers at apartment number B42 were lowering a jeice of plywood that was approximately 2 X 5 from the fourth floor fire escape to the ground using a heavy thick rope in front of the building. According to the Project Manager at the site and a bystander, the plywood sipped off of the rope and fell from the third floor level, striking a young girl on the side of her head before! anding on the ground. Marks from the fallen wood can still be seen on the ground where it landed. The injured young girl was transferred to New York Presbyterian Hospital of Queens with injuries to the side of her head. These Aggravated Level 2 E CD following the sissed for a failure to safeguard 2 E CD Sollowing the sissed for a failure to safeguard 2 permit. 3 DOB Violetions, and a full Stop Work Order were also issued.		35309174N, 35308325L & 35309326N	022318CERKC03. 022318CERKC04 & 022318CERKC05	ALTERATION TYPE 2	421548999-01-EW-OT	Material Fell	83-09 35TH REALTY LLC	MNR GROUP INC
/26/2018	Marhattan	545	WEST 30 STREET	0	A DOB inspector reported that workers were using a lull to unload window panels off of a truck. While the lull was being taken into the building, one of the panels slid off of the lull and hit a worker's ankle. An ambulance took the worker to a hospital. An ECB Violation for a feature to maintain safe operations and a partial Slop Work Order were issued or all deliveries and material handling. The General Contractor is to provide a Means and Methods.	ECB Violation	35317717K				Other Construction Related incidents	15 HUDSON YARDS CONDOMINIUM	
/27/2018	Manhattan	685	FIRST AVENUE	0	The Site Safety Manage reported that a worker was working in a building when a couple of pieces of sheetrock fell over and onto his leg. An ambulance was called to the site.	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
/28/2018	Manhattan	1227	BROADWAY	0	1 A DOB inspector reported that a tower crane was engaged with loading a four foot piece of scaffolding material on top of a trailer within help ob site. After then load was lowered into place, a worker began unhooking material on top of a trailer within help ob site. After then load was lowered into place, a worker began unhooking help of the load of		35225172L 35225171J & 35225172L		CN	CN 913/16	Mechanical Construction Equipment	YJL BROADWAY HOTEL LLC	BMNY CONTRACTING CORP
/28/2018	Manhattan	2	PARK PLACE	0	The Site Safety Manager reported that a worker got dust in his eye. The worker went to a hospital for treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/1/2018	Brooklyn	391	HOOPER STREET	1	O DOE inspector reported that heavy gauge 2 x 10 calling joists were delivered and placed on top of the calling joists were delivered and placed on top of the top of the calling joists to the calling joists to the calling joists to the calling joists together, which lead to the joists collapsing and knocking the worker off of the scaffold to the ground. The joists landed on top of the worker as well. The worker was found dead on arrival. A DOB Violation and a full Stop Work Order were issued.	DOB Violation		030118BS01AS01			Other Construction Related Incidents	E8D MANAGEMENT GROUP LLC	
/2/2018	Queens	28-02	JACKSON AVENUE	0	1 A DOB inspector reported that a panel of plywood that was about 8 X fell from the parspect of a sidewalk shed and struck two pedestrians. One of the pedestrians suffered an injury in the shoulder area. The injured pedestrian was seen by the on-site medic, but denied pedestrian was seen by the on-site medic, but denied further medical attention and left the scene. An Aggravated Level 2 ECB Violation was issued for a faiture to safeguand public and property affected by construction operations. A second ECB Violation was considered to the sidewalk shed. A partial SION Work Order was also issued. The sidewalk shed company was sent to the side for repair work.	ECB Violation	35318105Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMPA
/2/2018	Manhattan	685	1 AVENUE	0	The Site Safety Manager reported that a worker was pushing a mini container when the gate on the bottom of a ramp swung and lacerated his right hand. The on-site medic put a band aid on the cut. An ambulance took the worker to a hospital.						Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
/2/2018	Manhattan	260	WEST 40 STREET	0	The Site Safety Manager reported that a worker was using a lade and cut his finger. The worker was patched up on-site, but then went to City M.D. where he received two to three stitches.	No Dispatch			NB - NEW BUILDING	121187394	Other Construction Related Incidents	PORT 40TH PARKING CORP	ZDG, LLC
/3/2018	Manhattan	150	EAST 23 STREET	0		No Dispatch			NB	121981748	Other Construction Related Incidents	154 EAST 23 LLC	W & L GROUP CONSTRUCTION
/3/2018	Manhattan	1912	1 AVENUE	0	The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the worker was transported to a hospital.	No Dispatch			NB	122879233	Worker Fell		PROCIDA CONSTRUCTION CORP



cident Date	Borough	Address Number	Street	Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	396	BROADWAY	0	The Site Safety Manager reported that a worker dropped a piece of plywood on his foot. The worker left the site in an ambulance.				A1 - ALTERATION TYPE 1	120786417	Other Construction Related Incidents	BRIDGETON 396 BROADWAY FEE LLC	ANTHONY T. RINALDI
018	Manhattan	425	WEST 18 STREET	0	The Site Safety Manager reported that a worker hurt his back while picking up a cement bag. An ambulance was called and the worker was transported to a hospital.	No Dispatch			NB	122736762	Other Construction Related Incidents	NOT ON FILE	ARTIMUS CONSTRUCTION INC
2018	Brooklyn	10	HURON STREET	0	1 The Site Safety Manager reported that there were two workers that were doing sheetrock work together when one of the workers lost his ging on a piece of sheetrock that landed on the other worker's finger, causing a cut. The second worker left the site and went to City M.D. to get stitches on his finger. This incident occurred on 35/2018, but was not reported to the Site Safety Manager or Construction Superintendent until 38/2018.	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
018	Queens	45-57	UNION STREET	0	A DOB inspector reported that a 16" X 8" size gate swung out and hit a pedestrian that was walking by. The pedestrian was a student that was approximately seven years old. The student was evaluated by a nurse.	ECB Violation	35317909P				Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
018	Manhattan	2255	BROADWAY	0	1 The Site Safety Manager reported that a worker was lifting a 2 X 3 X 10 wooden beam in the elevator pit when he hit himself in the face with the wooden beam. The worker went to urgent care and then went to a hospital. This incident occurred as a result of a worker error.	No Dispatch					Other Construction Related Incidents	2255 HOLDING LLC	
2018	Bronx	2395	FREDERICK DOUGLASS BLVD	0	1 The Ste Safety Manager reported that a pedestrain in a wheelchair fall over in a walleway due to a tripping hazard around a Con-Ed sewer cap. The pedestrain went to a hospital by ambulance. A DOB inspector responded to the incident, visited the site, and issued an ECB Violation. The tripping hazard was corrected as of the time that the inspector was at the site.		35300487N	030618BS10VP06			Other Construction Related Incidents		
2018	Brooklyn	416	KENT AVENUE	0	The Site Safety Manager reported that a worker slipped, fell, and hurt his arm. The worker was taken to a hospital for a check up.	No Dispatch				320622616	Other Construction Related Incidents	420 KENT AVENUE LLC	ZDG, LLC
2018	Manhattan	1681	3 AVENUE	0		No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a piece of plywood slid and hit a worker on the left knee while the worker was stocking plywood on the floor. The worker went to a clinic.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Queens	28-07	JACKSON AVENUE	0	I A DOB inspector reported that there were two electricians working on a scissor lift at the basement electricians working on a scissor lift at the basement between the control of the co	ECB Violation	35318121Y-FAIL TO SAFEGUARD	030818BS02KA01	NB	420656873	Material Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
2018	Staten Island	546	GULF AVENUE	0	The Site Safety Manager reported that a worker slid and hit his left knee as he was taking the stairs to his trailer. The worker was taken to a hospital for a check up.	No Dispatch					Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	
/2018	Manhattan	1059	3 AVENUE	0	1 The Site Safety Manager reported that a worker was carnying a few formwork clamps that weight a personated by 10-15 pounds and are about 18 feet long in length up the third floor steps when one of the clamps fell from his grip and hit the wrist of a mason that was working in the basement, possibly breaking the masor's wrist. An ambulance was called An EGB Violation and a partial Stop Work Order were issued for the unsafe handling of materials. A DDB Violation was also issued. A Means and Methods will be provided for the safe handling of form work materials.		35300269P	030918BS08MH01			Material Fell	63RD & 3RD NYC LLC	
/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker as carrying equipment when he slipped and fell. The worker in the back of his head and blacked out. The worker was sent to Mount Smail Hospital. A DOB inspector was sent to Mount Smail Hospital. A DOB inspector worker slid on what book like an Lee patch on the floor, even through there was ice melt spread throughout the are. An ECB Violation was issued for a failure to maintain safe operations.	ECB Violation	35286419N				Worker Fall	SMITELL SPONSOR LLC	
/2018	Manhattan	29	11 AVENUE	0	The Site Safety Manager reported that an iron worker was attempting to move a steel beam onto a dolly on his own when the beam slid and hit his left knee. 911 was called and the worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	NYS PARKS & RECREATION	
/2018	Manhattan	701	7 AVENUE	0	The Site Safety Manager reports that a worker pinched his finger while cutting a Formica board with a circular saw. The worker went to the emergency room on his	No Dispatch					Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	



cident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
11/2018	Manhattan	500	WEST 33 STREET	0	1 The Site Safety Manager reported that an ironworker	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					hurt his right index finger while prying a cross brace. The worker was transported to Bellevue Hospital by ambulance.								
2/2018	Manhattan	125	GREENWICH STREET	0	1 A DOB inspector reported that a worker was lifting up a four foot section of form work when the worker mishandled the form work, causing the form work to fall on his knee. An ambulance was called. It was determined that the incident happened as a result of a worker error and that no enforcement action was necessary.	No Action Necessary					Material Fell	VS 125 LLC	
/2018	Manhattan	125	GREENWICH STREET	0	The Site Safety Manager reported that a worker was handling a roll of felt paper when he slipped backwards and suffered a laceration to the left side of his forehead. The worker did not want an ambulance to be called and went to a City M.D. instead.	No Dispatch					Worker Fell	VS 125 LLC	
/2018	Manhattan	255	EAST HOUSTON STREET	0	The Site Safety Manager reported that a worker's finger got caught between two beams while he was pushing forwards beams on a truck. The worker was sent to Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	255 EAST HOUSTON OWNER LLC	
3/2018	Queens	150-13	80 AVENUE	1	O A DDB rispector reported that a worker was riding on the back of a fix lift during a placement of bundle windows in the storing garage. The bundle was 10 X 5 K 6 and bounced up and down due to its size and weight. The driver of the fortfilt heard a sound and then saw that the worker who was riding on the back was on the floor. The worker was found dead. There were no wincesses to the incident, and the incident is currently under police investigation. The driver of the fork lift was found to be not certified to operate a fork lift. The driver was in a traumatized state and went to a hospital. A DDB Violation for a failure to safeguard and a Stop Work Order were issued. ECB Violations are being prepared to be served.	DOB Violation		031318BS1201MC			Other Construction Related Incidents	88TH AVENUE OWNER LLC	
2018	Brooklyn	3617	13 AVENUE	0	A DOB inspector reported that a worker lacerated his foot while driving a walk-behind saw to a container in order to park if. The worker was sent to a hospital. A an ECB Violation was issued, as well as a partial Stop Work Order on the use of the walk-behind saw. Manufacturer specifications must be provided.	ECB Violation	35318355R				Other Construction Related Incidents	37TH STREET HOLDINGS LLC	
4/2018	Manhattan	220	CENTRAL PARK SOUTH	0	pinched his index finger while unloading a cart of steel. The worker went to a clinic to receive stitches for his finger.	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
5/2018	Brooklyn	225	4 AVENUE	0	1 A DOB inspector reported that workers were in the process of cleaning brick with an acid base solvent when some of the solvent fell into the eye of a female pedestrian. The pedestrian had her eye rinsed out and was treated on the site. The pedestrian did not go to the hospital. An Agravistate Level 2 EGB Violation for the hospital was present as many property affects the pedestrian did not go to the property of the property	ECB Violation	35309294H	031518CERDM01	NB	310086554	Material Fell	225 4TH AVENUE PROPERTY OWNER	TRM Construction
5/2018	Queens	21:30	44 DRIVE	0	1 The Site Safety Manager reported that a piece of phywood fell from the first floor to the cellar due to the wind. The phywood landed on the cellar floor where it then fiel onto a worker, burting the worker's shoulder. The first of the cellar floor was worker, burting the worker's shoulder. Department Of Bulldings was not rooffield until March 19, 2018, because the Construction Superintendent claimed that he called the office on 31/6/2018 after 4.00 PM and that no one answered the phone. An ECB Violation was issued for a failure to safeguard for not securing materials during a weather advisory. A DOB Violation and a partial Stoy Work Order for all florm work were also issued. A Means and Methods for the securing of materials during a weather advisory must be provided.		35318143P	031918BS02KA04			Material Fell	44TH DRIVE OWNER LLC	
16/2018	Manhattan	501	WEST 18 STREET	0	A DOB inspector reported that during excavation work, a worker was torching a hole in two steel I'f piles and was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which was been seen to see the second of the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hopsital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preparation of steel piles. The contractor is to provide a Means and Methods for the safe movement of steel around the construction site.	ECB Violation	35314141N		New Building	121191147	Excavation/Soil Work	18TH HIGHLINE ASSOCIATES, L.L.	Related Construction LLC



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
16/2018	Manhattan	220	CENTRAL PARK SOUTH	0	1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet floot. The worker went to Rossevelt Hospital. A DOB inspector responded to the incident and issued an ECB Violation for a failue to maintain unsafe equipment. A DOB Violation and a partial Stoy Work Order for fall work using equipment to transport loads as the second floor north of Tower Boulevard were also issued. The powered pallet jack was found to have no inspection logs. An orientation and a Means and Methods must be provided. The BEST Squad must be contacted for a reinspection.		ECB#35318284L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	G31618BS06MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
/16/2018	Brooklyn	416	KENT AVENUE	0	The Site Safety Manager reported that at a twenty-two story new building under construction, a worker that was on stills performing plastering work on the elightmenth floor fell backwards onto the floor. The worker hunt his pain, An ambulance was called and the worker was transported to Bellevue Hospital. The worker was transported to Bellevue Hospital. The worker was awake and alert.	·			NB	320622616	Worker Fell	420 KENT AVENUE LLC	ZDG, LLC
3/19/2018	Brooklyn	1277	EAST 14 STREET	0	1 A competent person at the construction site reported that a worker slipped on a supported scaffold and fell approximately six feet, along with a few planks. The worker's foreman stated that the worker drove to see a doctor on his own. A DOB inspector responded and visited the site and reported that the supported scaffold dwa not truly plaked, the planks were not tied down, and a guard rail system was missing from multiple locations. Two ECB Violations and a partial Stop Work Order for a supported scaffold were issued.		35285912M,35285913Y		NB	320597127	Worker Fell	1277 HOLDINGS LLC	Ray Builders Inc.
/19/2018	Manhattan	40	CLERMONT AVE	0	The Site Safety Manager reported that a carpenter was working on an "A"-Frame ladder when he missed the fifth step of the ladder and fell. An ambulance came and took the worker to a hospital.						Worker Fell		
/19/2018	Manhattan	590	EAST 83 STREET	0	The Site Safety Manager reported that a worker tripped and jammed his finger. An ambulance took the worker to a hospital	No Dispatch			NEW BUILDING	121190987-01-NB	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
20/2018	Brooklyn	10	MONTIETH STREET	0	The Site Super reported that a worker attempted to jump over a fence and fell. The worker was taken to a hospital by ambulance.				NEW BUILDING	320622750-01-NB	Worker Fell	BUSHWICK HOLDINGS I LLC	GALAXY DEVELOPERS LLC
20/2018	Manhattan	108	EAST 89 STREET	0	The Site Safety Manage reported that a worker hurt his shoulder while installing a pipe scaffold. The worker went to a City M.D. to get checked.	No Dispatch			ALTERATION TYPE 1	122988623-01-AL	Worker Fell		E.W. HOWELL CO, LLC
3/20/2018	Queens	43-12	HUNTER STREET	0	1 A DOB inspector reported that contractors were in the process of litting a section of steel classisson in order to set it on a drill ling when a worker had his hand pinched between the caisson and a steel hook. The worker was alert and awake and was taken to a nearty hospital by a tax. The extent of the ripury to the worker's hand was not known as of the time of inspection. An ECS Violation for a failure to safeguard and an ECB Violation for these may no log to native worker as well as a full Stop Work Order for the entire size. The contractor at the size was instructed to provide a Means and Methods for safe pile installation.		353143552 35314356k		NB	420659530	Mechanical Construction Equipment	49-12 HUNTER LLC	Judy y Lee
/21/2018	Bronx	2028	CRESTON AVENUE	0	1 The Site Safety Manager reported that at an eleven story new building under construction, a worker was handling concrete out of a mixer when cement splashed into the worker's right eye. The worker was alert and awake and was taken to Lincoln Hospital for treatment.	No Dispatch			NB	220392858	Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MINGMT
/21/2018	Manhattan	650	5 AVENUE	0	The Site Safety Manager reported that a worker was working with temporary electrical writing on the second floor when a 480-volt wire touched an I-Beam, which caused an ARC flash. The worker suffered an injury to his eyes and was taken to a hospital. A DOB inspector determined that there was no enforcement acton necessary.	No Action Necessary			Electrical	M00016968	Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
1/22/2018	Brooklyn	1835	STERLING PLACE	0	The Construction Superintendent reported that a worker slipped off of an "A"-Frame ladder while coming down from the ladder. The worker suffered a minor laceration to the head. The worker was found conscious and an ambulance was called.	No Dispatch					Worker Fell	NOT ON FILE	



	Borough	Address Number	r Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
23/2018	Manhattan	115	DELANCY STREET	0	1 The Site Safety Manager reported that a worker was cleaning around a On Estion wattl when he lifted an unmarked piece of plywood that was covering the vault, tripped into a shaft, and fell approximately eight to nine feet. The worker suffered a cut to his ankle. The worker was alter tand awake and was taken to Bellevue Hospital. An ECB Violation for a failure to safequard was issued, as well as a DOB Violation and a partial Spo Work Order for all exterior work at the ground floor at exposure there. Protections around the vaults at the ground level must be provided. An updated Means and Methods and Tool Box Talk must be provided.	ECB Violation	ECB#35317775Z -FAIL TO SAFEGUARD	032318BSO3GD01	NB	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
3/2018	Manhattan	40	10 AVENUE	0	The Site Safety Manager reported that an electrician was climbing up the rebar cage to reach the electricial conduit when he slipped, fell two feet, and landed on his right ankle. The electrician was sent to a clinic.	No Dispatch					Worker Fell	40-56 TENTH OWNER LLC	
4/2018	Manhattan	1865	BROADWAY	0	The Site Safety Manager reported that a worker was cutting metal studs when he cut the top of his hand with a chop saw. The worker went to the emergency room with another worker. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
25/2018	Brooklyn	19	INDIA STREET	0	The Site Safety Manager reported that a worker was moving windows when he tripped, fell three steps, and hit the back of his neck on a cinderblock. The worker was alert and responsive and was taken to Bellevue Hospital.	No Dispatch			NEW BUILDING	310234207-01-NB	Worker Fell	145 WEST STREET LLC	NOBLE CONSTRUCTION GR LLC
6/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	The Construction Superintendent reported that a worker was testing a refrigerant line when the line burst, causing discomfort to the worker's ears. A co-worker drove the injured worker to a hospital.	No Dispatch			Alt 1	320622894	Other Construction Related Incidents	ATLANTIC 2644, LLC	CAULDWELL WINGATE CO LLC
26/2018	Manhattan	250	SOUTH STREET	0	1 A DOB inspector reported that a worker was bringing a scaffold down when a gust of wind moved the platform out of the building. The worker stuck his hand out to prevent the impact against the building, but hurt his shoulder and back in the process. The worker was taken to a hospital where he was in stable condition. It was determined that no enforcement action was necessary, as the suspended scaffold was found to be in compliance with approed drawings, the current notification and installation letter from the engineer was onsite, and all logs were in order.		N/A		NB	121185528	Scaffold/Shed/Fence/Shoring/Installation	NOT ON FILE	Lend Lease (US) Construct
6/2018	Manhattan	420	EAST 54 STREET	0	1 The Site Safety Manager reported that the building owner's personal driver had his floot struck by a forklift. The injured person was taken to a hospital. A DOB inspector reported that only one flag person was used when moving the forklift and that the injured person walked into a controlled no access zone when he had his foot struck by the forklift. An ECB Wichaiton was issued for a failure to safeguard. A DOB Wichaiton and a partial Stop Work Crder were also issued. A Means and Methods and Tool Box Talks will be provided by the General Contractor at the site for safe delivery operations and for the proper amount of flaggers.	ECB Violation	35317780N	032618BSo6GD01			Other Construction Related Incidents	RIVER TOWER OWNER, LLC	
7/2018	Manhattan	432	EAST 14 STREET	0	The Construction Superintendent reported that a worker was pushing a mini container when she slipped and hit her knee. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	EAST 14TH STREET OWNERS LLC	
8/2018	Manhattan	441	9 AVENUE	0	The Site Safety Manager reported that a worker got his hand jammed between two stripping panels. A foreman took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
8/2018	Brooklyn	505	PACIFIC STREET	0	The Site Safety Manager reported that a worker slipped with a grinder and cut his face. An ambulance transported the worker to a hospital.	No Dispatch			NEW BUILDING	320909004-01-NB	Other Construction Related Incidents	PVII HSC ATLANTIC LLC	TRITON CONSTRUCTION CO.,
30/2018	Manhattan	265	WEST 114 STREET	0	1 The Site Safety Manager reported that there was a worker on the second floor scaffold deck carrying a plank. The worker leaned on the plank, which caused the plank to fall and hit a worker that was on the first floor scaffold deck in the arm. The injured worker went to a City M.D. for an X-ray, Ar EGS Violation was issued for the storage of excess materials on a scaffold.	ECB Violation	35286045H		Ait 1	121189668	Material Fell	TRINITY WEST HARLEM PHASE TWO	Mega Contracting Gp LLC
2/2018	Queens	22-06	31 STREET	0	A competent person at the site reported that a worker that was coming into the site slipped on snow and injured his knee. The worker went to see his doort for a check up. There was a snowstorm in progress as of the time of the incident.						Other Construction Related Incidents	DITMARS 31ST STREET ASSOCIATES	
2/2018	Staten Island	2655	RICHMOND AVENUE	0	A DOB inspector reported that there were workers that were moving a wooden ramp that was about 4 % 8 x 20. When the ramp was in a vertical position, one 2 X 4 fell onto the hand of one of the workers. The worker went to urgent care. An ECB Violation and a partial Stop Work Order (PSWO) were issued for all use of ramps. A Means and Methods and the design drawing must be provided.		35327352X				Other Construction Related incidents	MACY'S RETAIL HOLDINGS, INC.	



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/3/2018	Bronx	2681	MARION AVENUE	o 0	A DOB impector sported that a flagger was signaling for deliveries for traffic on the street when a cab driver larger was a signaling for deliveries for traffic on the street when a cab driver larger street. The flagger went of a heapital with a co-worker in an ambulance. The inspector determined that there was no enforcement action necessary, as the flagger was certified and a delivery Means and Methods was at the size.		ELB Violation Numbers	DUB Violation Numbers	Permit	Permit No	Other Construction Related Incidents	PCMH MARION AVENUE HOUSING DEV	Contractor Name
4/3/2018	Bronx	2760	BRIGGS AVENUE	0	The Site Safety Managar reported that a worker slipped on plywood that had snow on it. The worker claimed to have hun this wisk while trying to brace himself after slipping. The worker went to a doctor on his own. This incident occurred in the morning, but the worker walled until the afternoon to report the incident and go to a doctor. A DOS impector visited the site and reported that there were no witnesses to the worker slipping and that there was no sign of snow or any tripping hazards in the area that the worker was working. A cause of the slip could not be determined. Because of this, no enforcement action was deemed necessary.						Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
4/3/2018	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker slipped on a wet surface and fell on his hand. The worker went to a City M.D.	No Dispatch					Worker Fell	NYC HPD	
4/3/2018	Brooklyn	422	FULTON STREET	0	to a City M.D. The Site Safety Manager reported that a security guard tripped and fell. The security guard was taken to a hospital as a precaution.	No Dispatch			ALT 1	320908899	Other Construction Related Incidents	NOT ON FILE	TRANSPARENT CONSTRUCTION
4/4/2018	Brooklyn	5615	7 AVENUE			ECB Violation	35323275N	040418CERCM02	Alteration 1	320516152	Other Construction Related Incidents	SIU PING	GUO Z HUANG/NEWLAND CONSTRUCTION
4/4/2018	Manhattan	500	WEST 33 STREET	0	The Safety Director reported that a worker slipped and the ratiables while getting of 10 a scissor lift. An ambulance was called and transported the worker to a hospital. A Dol Sinspector visited the site and issued an ECB Violation and a partial Stop Work Order on all use of scissor lifts. The General Contractor is to provide training.	ECB Violation	35327428N				Other Construction Related Incidents	NOT ON FILE	
4/5/2018	Manhattan	4	WEST 37 STREET		The Sie Safety Manager reported that a plumber was bound dead on the fourth floor of a framed out empty room. There were no tools and no ladder found on the seene. A DOB inspector responded to the incident and visited the site, and reported that the worker suffered a possible heart attack and was revived with a faint pulse. No enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	4 WEST 37TH STREET LLC	
4/6/2018	Manhattan	125	GREENWICH STREET	0	The Site Safety Manager reported that a worker hit himself in the face while stripping forms. The worker was driven to a City M.D.	No Dispatch			NEW BUILDING	121183799-01-NB	Other Construction Related Incidents	VS 125 LLC	PLAZA CONSTRUCTION LLC
4/9/2018	Brooklyn	231	AINSLIE STREET		A DOB inspector reported that, according to a worker that was at the sike, the owner of the construction company at the site was on a pipe scaffold inspecting brick work that was done when he lost his balance and tried to grah a bike rack on the rear of the scaffold. The bike rack was not properly secured and gave way, causing the owner to fall eight leef from the pipe scaffold was transproted to an area hospital with serious injuries. There was some debris found on the sidewalk shad deck, and the pipe scaffold was not fully planked, did not have any railing, and did not have any fall sing. Two ECS Violations, was DOS Violations, and and Isos DW Ord (Violations, was DOS Violations, and and Isos DW Ord (PSWO) were assued for the failure to safeguard all persons and property, for the supported scaffold on top of the site of the failure to safeguard all persons and property, for the supported scaffold on top of the site of the failure to safeguard all persons and property, for the supported scaffold on the site of		35323245M & 35323246y	040918CERDF03 & 040918CERDF04			Worker Fell	ST OONO DE TEGGIANO C	
4/9/2018	Brooklyn	420	KENT AVENUE	0	The Site Safety Manager reported that a steamfitter cut his finger while putting coupling on a pipe. 911 was called and the worker was taken to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	420 KENT AVENUE LLC	
4/9/2018	Manhattan	11	WEST 53 STREET	0	The Construction Superintendent reported that a worker was on a scissor lift and was thying to pain access into a plenum. The worker's hand was on the handrail of the scissor lift and his hand got pinned between the handrail and the hanging door of the plenum. The worker's hand was cut and the worker went to a hospital for a checkup.				ALTERATION-1	121190193	Other Construction Related incidents	THE MUSEUM OF MODERN ART	TURNER CONSTRUCTION CO



	Borough	Address Number		r atalities injuries	s EOC Final Description		ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	15	WEST 26 STREET	0	1 A DOB inspector reported that a worker was using a hole saw that jammed. The Construction Superintendent unplugged the tool and straightened it out. When the hole saw was plugged back in, the saw swung around and pushed the Construction Superintendent down, causing into fall approximately eleven feet. The Construction Superintendent was taken to a hospital in serious condition. The Construction Superintendent is serious condition. The Construction Superintendent is violation, a DOB Violation, and a full Stop Work Order (FSWO) were issued for a failure to safeguard during (FSWO) were issued for a failure to safeguard during	DOB Violation	35323475H	040918CERND01	ALTERATION TYPE 2	123203069-01-EW-OT	Worker Fell	ST SAVA CATHEDRAL	G.P.J. O'DONOGHUE CONTRAC
					construction operations, as the Construction Superintendent fell in a location where there were no guardrails installed.								
018	Manhattan	25	PARK ROW	0	The Site Safety Manager reported that a hoist installer got the tip of his finger crushed while working on the hoist when the gate came down. The worker was taken to the emergency room.	No Dispatch					Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	
2018	Manhattan	420	EAST 54 STREET	0	1 A DDB inspector reported that there were three workers working on the thirty seventh floor dring flaterior demolition work and removing debris. There was an approximate 27 x 27 opening in the floor that was not properly covered, as a door from the demolition work was used to cover the hole and the hole was not properly marked or secured. One of the workers picked up the door, unaware of the hole underneath it, and fell through the opening to the thirty sixth floor. The worker was sent to a hospital for a checkup. Follow up information regarding the injured worker is not currently available. Two ECB Volostions were issued for the failure to maintain safety measures and for inadequate housekeeping. A full Stop Work Order was also issued. The GC is to provide a Means and Methods for the safe operation of the ipb, including the protection of empty shafts and floor openings.	ECB Violation	35317792K, 35317793M		ALTERATION 2	122939357	Worker Fell	RIVER TOWER OWNER, LLC	VECTOR BUILDING CORP
018	Queens	123-30	ROOSEVELT AVENUE	0	The Site Safety Manager reported that a worker tripped on a curb and twisted his ankle while carrying a panel. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NYC PARKS	
018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker stepped on a tie-wire that was used for rebar work and the tie- wire punctured his boot and foot. The worker went to see a doctor on his own.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Manhattan	150	5 AVENUE	0	The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taken to a hospital by an ambulance.	No Dispatch			ALTERATION TYPE 1	122700292-01-AL	Worker Fell	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that a worker was on a six foot ladder when he missed the second rung of the ladder while coming down from it and fell backwards and hit his head. The worker went to a hospital with his shop steward.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker was stripping form work when a dust particle got between his safety glasses and irritated his eye. The worker went to a nearby City M.D.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2/2018	Bronx	600	BERGEN AVENUE	0		ECB Violation	35314470y		NB	220151868	Mechanical Construction Equipment	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST.DEVELP.
/2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker was walking on the second floor when he stepped on a nail. The worker went to get a tetanus shot.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manger reported that a worker twisted his knee while climbing down from a machine. The worker was driven to the emergency room.	No Dispatch			NEW BUILDING	520135675-01-NB	Worker Fell	MACY'S RETAIL HOLDINGS, INC.	AURORA CONTRACTORS INC
3/2018	Bronx	2044	WESTCHESTER AVENUE	0	The Project Manager at the site reported that a masonry worker was laying cinderblocks when he fell off a supported scaffold that was approximately three feet in height. The worker landed on his back and appeared to be in stable condition, but refleave to talk to anyone unil an ambulance arrived. The worker was taken to Jacobi Medical Center. A DOB Inspector responded and visited the site and determined that no enforcement action was necessary, as the supported scaffold was found to be structurally sound with a guard rail system in place.		NA NA		NB	220152572	Worker Fell	HP WESTCHESTER MEWS HOUSING DE	Procida Construction Corp
13/2018	Manhattan	20	BROAD STREET	0	The Site Safety Manager reported that a worker was pushing a mini-container through a wall opening when he pinched his pinky finger. The worker left the site to see a doctor for treatment.	No Dispatch					Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.	
3/2018					The Site Safety Manager reported that a worker was				ALTERATION TYPE 1	121324343-01-AL		701 SEVENTH PROPERTY OWNER LLC	



ncident Date	Borough	Address Number	r Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
14/2018	Brooklyn	50	COURT STREET	O	3 DOB's Energency Response Team was informed that sidewalks they was in the process or being dismandled when a partial collapse occurred at the corner of Court Street and Jordamon Street. Approximately twenty linear feet of the sidewalk shed collapsed. Two pedestrians and one worker suffered non-life threatening injuries and were sent to Lutheran Hospital. The remaining unaffected parts of the sidewalk shed replaced the cross walk light at the site. An Aggravated Lavel 2 ECB Violation was issued for a failure to safeguard all persons and property affected by construction operations. A DOB Violation was asso		35323276P	041418CERCM01	Alt 3 - SH	321426774	Scaffold/Shed/Fence/Shoring/Installation		NEW FORCE CONSTRUCTION CO
17/2018	Manhattan	130	EAST 82 STREET	0	The Site Safety Manager reported that a worker accidentally ran a screw into his hand while screwing screws during duct work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	134 EAST 82 LLC	
7/2018	Brooklyn	856	WASHINGTON AVENUE	0	The Site Safety Manager reported that a worker was drilling a core hole in a deck slab when the drill kicked back and the base of the drill hit him on the side of his face. The worker was alert. The worker went to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
7/2018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker slipped while going down the stairs. There were no witnesses to the worker slipping, and the stairs were free of debris. An ambulance was called. The worker was okay, but walked to the ambulance when the ambulance at the arbulance at the site and went to a hospital.	No Dispatch					Other Construction Related Incidents	NYC DSBS	
17/2018	Brooklyn	1900	PARK PLACE	0	The Site Safety Manager reported that a worker strained his lower back while picking up a cement block. An ambulance was called.	No Dispatch					Other Construction Related Incidents	HABITAT FOR HUMANITY LATENT TH	
18/2018	Brooklyn	25	EAST 19 STREET	0	amousance was cause. I The Sites Safey Manager reported that a worker was passing an I-Beam down from a sidewalk shed when he tools his fotonig and fell about sixteen feet to the ground. The worker was wearing a harness that as not attached to anything. The worker was found awake and speaking and was taken to a hospital. An ECB Violation was issued for a failure to safeguard persons and property.	ECB Violation	35323790Н		Alt	340452520	Worker Fell	EBE HOLDING LLC	CS Bridge Corp
18/2018	Manhattan	220	CENTRAL PARK SOUTH	0	The Site Safety Manager reported that a worker cut his finger when another worker closed a door on his hand by accident. A co-worker took the injured worker to a hospital.	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
18/2018	Queens	71-17	ROOSEVELT AVENUE	0	The Site Safety Manager reported that a worker sprained his back while carrying steel form. The worker went to a hospital by ambulance for observation.	No Dispatch					Other Construction Related Incidents	ROOSEVELT PARC LLC	
18/2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manager reported that a worker hurt his shoulder when he picked up a bundle of threaded rods. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
19/2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker was conducting a survey and was wearing proper footwear when he stepped onto a nail that punctured his foot. The worker went to urgent care for a tetanus shot.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
19/2018	Manhattan	70	VESTRY STREET	0	The Site Safety Manager reported that a worker was installing 3' X 6" stone at the base of a building when his knee gave out, causing the worker to fall onto his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	BRIDGE LAND VESTRY LLC	
19/2018	Manhattan	112	WEST 25 STREET	0	The Site Safety Manager reported that a subcontractor was carrying a door from a truck when the door fell and leaned on the subcontractor's right knee. The worker did not suffer a visible injury, but was in pain. An ambulance transported the worker to a hospital for a check up.				NEW BUILDING	121187214	Material Fell	LAM GEN 25 LLC	FLINTLOCK CONSTR SVCS INC
19/2018	Brooklyn	422	FULTON STREET	0	performing demolition work on the roof of a building when he felt pain in his back while lifting a barrel. An	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
19/2018	Вголх	545	EAST 166 STREET	1	ambulance was called. O The New York City Police Department reported that a worker was hit by a hoist. A worker was on the eighth floor securing a piece of wingwall when he stepped uponto a bucket to look over the gate while trying to securing plywood. The hoist was on the floor above the worker and the hoist came down at the same time that the worker was learn gover the gate. The worker was struck in the hoist came down at the same time that struck in the dead and succumbed to his injuries. An Aggravated Level 2 ECB Violation was issued for the unsale or improper use of hoist equipment.	ECB Violation	38259262J	042018E2607B01			Mechanical Construction Equipment	545 E. 166TH STREET HDFC	
//20/2018	Manhattan	45	PARK PLACE	0	The Site Salety Manager reported that a carpenter foreman was securing a formwork panel for the shear wall and was repositioning his retractable device with both hooks in one anchor point when the insert gave way, causing the foreman to fall about ten feet backwards. The foreman was taken to a hospital.	ECB Violation	35326676H		NEW BUILDING	121185635	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST



cident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	560	WEST 33 STREET	0	1 The Site Sately Manager reported that a worker was 1 The Site Sately Manager reported that a worker was 1 the second rung of the ladder and fell about two feet. The worker rolled over onto a bucket and suffered an injury to his ribs. A DOB inspector responded and visite the site and reported that no enforcement action was necessary, as the necessary safety measures were provided at the site. It was determined that the incident	No Action Necessary	COS HOLLON HUMBER	SUST TORSECT NUMBER	NB	1211192618	Worker Fell	ERY NORTH TOWER RHC TENANT LLC	
/2018	Manhattan	400	WEST 61 STREET	0	occurred due to a worker's error. 1 The Site Safety Manager reported that at a thrity eight	No Action Necessary			121193181	NB	Worker Fell	RCB1 NOMINEE LLC	TISHMAN CONSTRUCTION CORP
					story new building under construction. a pulmber was placing a pie into hangers when the plumber fell off of a ladder. There were no winesses to the height of the fall, and the plumber claimed to have fallen approximately between five and seven feet. The plumber was found alert, awake, and complaining of pain in his hip. The plumber was taken to St. Luke's hospital by ambulance. A DOB inspector responded and visited the site and determined that there was no enforcement action necessary, as the fall occurred as the result of a worker's error.								
1018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker on the first floor bumped his knee on a reshore tripod. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Brooklyn	540	FULTON STREET	0	The Site Safety Manager reported that an iron worker pinched his finger while unloading steel rebar from a truck. The worker left to go to a clinic.	No Dispatch					Other Construction Related Incidents	540 FULTON ASSOCIATES	
2018	Manhattan	461	WEST 34 STREET	0	The Site Safety Manager reported that a worker was on the twenty eighth floor of a twenty nies story new building and was cutting shevetock and metal stud for electrical work when he suffered a cut to his hand. A reoprocal black jammed and two worker's hand got caught. The worker was found awake and allert and was taken to a nearby hospital.	No Dispatch			NB	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	ATRIA BUILDERS LLC
2018	Manhattan	225	BOWERY	0	1 It was reported that there were workers that were moving materials on the roof. When the workers moved a metal piece together, one of the workers fight hand got caught in the pinch point. The worker suffered a scrape to his right hand. An ambulance was called to the site. The worker received stitches at Mount Sinai Hospital.	No Dispatch				121862751	Worker Fell	VNAA BOWERY LLC	AEH-VSLV, LLC
2018	Manhattan	22	NORTH LOOP ROAD	0	The Site Safety Manager reported that a worker hit his left hand with a hammer. The worker went to urgent care	No Dispatch					Other Construction Related Incidents		
2018	Manhattan	2	PARK PLACE	0	The Site Safety Manager reported that at a fifty seven story building that was under construction, a worker was cutting metal with a grinder when he cut his left shin. The worker was conscious and alert and walked to New York Presbyterian Hospital.					121290085	Other Construction Related Incidents	NOT ON FILE	AHEARN-HOLTZMAN, INC
2018	Manhattan	1681	3 AVENUE	0	The Site Safety Manager reported that a worker was coming down the stairs on a scaffold when he slid down the stair riser. The worker went to a City M.D.	No Dispatch					Worker Fell	95TH AND THIRD LLC	
2018	Brooklyn	1	CLINTON STREET	0	The Site Safety Manager reported that during concrete operations, a laborer was removing concrete key when his finger got scratched between rebar. The worker was working alone and scratched his finger while reaching into formwork. The worker went to a City M.D. and returned to work in two days.	No Dispatch			NB	321197478	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker struck his left thumb with a hammer while hammering a nail. The worker took himself to a City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Brooklyn	109	2 AVENUE	0	The Construction Superintendent reported that a worker was shaking out steel at the street level when he pinched his finger between a two by four and a steel beam. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	THE SALVATION ARMY	
/2018	Manhattan	1059	3 AVENUE	0	1 The Site Safety Manager reported that a pedestrian went over a ramp in front of the site, slipped/tripped on dramaged mesh, and fell. The professition suffered an advantage mesh, and fell. The professition suffered an advantage of the site of the superior reported and visited the site and reported that the General Contractor at the site failed to maintain the pedestrian wallowsy that caused the incident. An Aggravated Level y ECB violation was issued for a failure to safeguard. A partial Stop Work Order was issued on all activities in the occupied lane next to the sidewalk shed. The General Contractor is to maintain the sidewalk to ensure that it is free of all tripping hazards.	ECB Violation	35318046N				Other Construction Related Incidents	6SRD & 3RD NYC LLC	
0/2018	Manhattan	130	WILLIAM STREET	0	The Site Safety Manager reported that a worker was attempting to help a carpenter when he accidentally walked into the swing radius of a hammer and got hit in the forehead by the hamer. The worker was taken to New York Presbytenian Hospital and was in stable condition. A DOB inspector responded and visited the sist and determined that no enforcement action was necessary, as the incident occurred as a result of a worker's error.	No Action Necessary			NB	121192903	Other Construction Related Incidents		GILBANE RESIDENTIAL CONST



cident Date	Borough	Address Number	Street	Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
//2018	Manhattan	425	PARK AVENUE	0	1 A DOB inspector reported that masons were finishing concrete pouring pads on the sixteenth floor when a worker that was working with the masons removed the floor protection and fell approximately thirteen feet from the sixteenth floor to the fitteenth floor. The worker suffered a cut to his ear and complained of head and neck pain. The worker was taken to Cornell University issued for there being no design drawings for floor openings present and for the failure to maintain safety operations. Two partial Stip Work Orders (FSWO) were issued on all work within ten feet of all floor coverings or all floors and for the floor coverings the stip of the floor openings being not properly secured. Two DOB Violations were also issued. A Means and Methods for the installation of floor coverings must be provided.		35326636N / 37P	043018BS05GD01/02			Worker Fell	T-C 425 PARK AVENUE, LLC	
1/2018	Manhattan	540	WEST 53 STREET	0	The Site Safety Manager reported that a worker suffered a cut finger. An ambulance was called.	No Dispatch			NEW BUILDING	121191968-01-NB	Other Construction Related Incidents	CLINTON HOUSING DEVELOPMENT	MEGA CONTRACTING GP LLC
/2018	Manhattan	390	MADISON AVENUE	0	a total ringer. In all indicates was selected that a worker on the first floor stepped up on a few concrete masonry unit blocks when he fell approximately three feet off of the blocks and landed on a metal plate. EMS was called and transported the worker to a hospital.	No Dispatch					Worker Fell	COMPTROLLER OF NY STATE	
2018	Manhattan	222	EAST 41 STREET	0	The Site Safety Manager reported that a worker was installing metal trim when a cut piece fell down and lacerated his wrist. The worker was sent to a hospital.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Brooklyn	1277	EAST 14 STREET	0	The Construction Superintendent reported that a plumber was cutting a metal stud to get to a pipe when he cut his arm on the stud. An ambulance was called.	No Dispatch					Other Construction Related Incidents	1277 HOLDINGS LLC	
2018	Brooklyn	63	FLUSHING AVENUE	0	The Site Salety Manager reported that a worker was waiking back from a coffee truck when he tryped, fell, and hit his head. The worker was found conscious and alert. An ambulance was called. A DOB inspector responded to the incident and visited the site and found no evidence of debris or tripping hazards, as well as no violating conditions. No enforcement action was necessary.	No Action Necessary			NB	321190563	Other Construction Related Incidents	NYC DSBS	GILBANE BUILDING COMPANY
018	Manhattan	10	VANDERBILT AVENUE	0	The Site Safety Manager reported that a latherer was coming down from a rebar cage when he missed his last step, fell backwards, and hurt har ankle. The worker the worker should be supported to the worker suffered a broken ankle. A DOB inspector responded and visited the site and reported that the worker misstepped during a rebar operation, and that the operation was proceeding according to the site plan. No enforcement action was deemed necessary.						Worker Fell	ONE VANDERBILT OWNER LLC	
018	Manhattan	320	EAST 43 STREET	0	1 The Site Safety Manager reported that a worker was cleaning near the dumpster in the basement C-Level area when he hit his lower leg on a dumpster. The worker was cut, but the bleeding was stopped. The worker does not know how he hurt himself. An ambulance was called	No Dispatch					Other Construction Related Incidents	FORD FOUNDATION	
2018	Brooklyn	10	HURON STREET	0	The Site Safety Manager reported that a worker cut the skin of his finger on a table saw. The worker went to a hospital with a co-worker.	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
018	Staten Island	546	GULF AVENUE	0	The Site Safety Manager reported that a worker got a spark in his eye under his safety glasses during a grinding operation. The worker went to a hospital on his	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
018	Queens	36-18	MAIN STREET	0	The Site Safety Manager reported that a worker was coming down off of a ladder when he lost his balance and grabbed onto a metal stud, causing a cut to two of his fingers. The worker went to urgent care.	No Dispatch					Worker Fell	134-22 35TH AVE., LLC	
2018	Manhattan	40	10 AVENUE	0	The Site Safety Manager reported that a worker sliped on rebar and hurt his wrist. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	40-56 TENTH OWNER LLC	
018	Manhattan	308	WEST 133 STREET	0	1 The Site Safety Managor reported that a worker was causiling a window when he left from a basier scaffold and burn his left leg. The worker was taken to a hospital A DOB inspector responded and visited the site and reported that the worker was not tied off when he fell. Two ECB Violations were issued for a failure to safeguard and for a failure to provide a four hour user training card. A partial Stop Vork Order was issued on baker scaffolds until a Means and Methods is provided.	ECB Violation	35323933X, 35323934H		NB	122620333	Worker Fell	308 WEST 133RD STREET LLC	Happy Living Development



ncident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/2018	Brooklyn	810	FULTON STREET	0	2 The Site Safety Manager reported that two workers were ringing in install a pipe on top of a baker scaffold when both of the workers leaned towards the same side of the scaffolding, which caused the baker scaffold for subject. The two workers fell approximately four feet and landed on the floor. An ambulance was called. A DOB inspector responded and visited the site. Two ECB Violations were issued: one violation for there being no personnel on site with proper documentation, which would be four hour user cards, and a second ECB Violation for a failure to safeguard all persons and property affected by construction operation. A partial Stop Work Order has been issued on baker scaffolds until a Means and Methods is provided.		35323694H,35323695J		NB	320597083	Worker Fell	GREENPOINT-GOLDMAN CORP.	Bradway Construction
1/2018	Brooklyn	63	FLUSHING AVENUE	0	The Site Safety Manager reported that a worker was unloading a pallet of glass that was approximately 2 X 8 when the pallet of glass the down of the Manager of the Manage		35318496K	050418BS02JJ01			Material Fell	NYC DSBS	
/2018	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker slipped on rebar and cut his right thumb. The worker walked to the ER.	No Dispatch					Other Construction Related Incidents	NYC HPD	
7/2018	Bronx	600	BERGEN AVENUE	0	I'he Site Safety Manager reported that a welder was performing Support OF Excavation (SOE) work when he performing Support OF Excavation (SOE) work when he when he in jure dis back. A co-worker took the worker to a City M.D., where a physician recommended medication for pain and rest for three days. A DOB inspector responded to the incident and visited the site and reported that there were no unsafe conditions found and that all of the workers at the site had ten hour OSHA carefs. No enforcement action was deemed necessary.				FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountoo Construction & development
//2018	Brooklyn	2085	ROCKAWAY PARKWAY	0	The Construction Superintendent reported that a worker from the sidewalk shed company fell four feet while descencing from a baker scaffold. An ambulance took the worker to a hospital.	No Dispatch			ALTERATION TYPE 3	340451308-01-EQ-SH	Worker Fell	NYC HOUSING AUTHORITY	SKYWORX CONTRACTING INC
7/2018	Brooklyn	314	BEDFORD AVENUE	0		ECB Violation	35327578Z				Worker Fell	814 PARK LLC	
7/2018	Queens	24-02	49 AVENUE	0	1 The Site Safety Manager reported that a worker at the louth floor level was struck by duct work that was approximately her feet high while on a ladder that was approximately eight feet high. The duct work had came loose, swang down, and stouck the worker, which close, swang down, and stouck the worker which will be seen to see the structure of the structure o		35326893Y	050718BS02DH01	ALT1	421518566	Worker Fell	LIG 73 OWNER, LLC	UNITY CONSTRUCTION GROUP
W2018	Manhattan	250	BRADHURST AVENUE	0	The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a façade connection. The worker went to a hospital by ambulance to receive stitches on his finger.	No Dispatch					Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
/2018	Brooklyn	535	4 AVENUE	0	The Site Safety Manager reported that a hoist mechanic lacerated his finger while cutting a piece of plastic away from a hoist. A co-worker took him to a hospital.	No Dispatch					Other Construction Related Incidents	XYZ PROPERTIES INC	
/2018	Brooklyn	11	HOYT STREET	0	The Site Safety Manager reported that a worker was working on a rebar wall when he was struck in the neck by dislodged shoring. A DOB inspector responded and visited the site and reported that reshores were installed contrary to the approved plan. An ECB Violation and a partial Stop Work order (PSWO) on all concrete work were issued.	ECB Violation	35331176X				Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	
9/2018	Manhattan	115	DELANCEY STREET	0	The Site Safety Manager reported that at a twenty six, story new building under construction, a worker was coming back on site when he stepped on loose concrete masony and turned his ankle. The worker was found alert and awake. The on-site medic assued ice for ordiste treatment and the worker went to a neathly urgent care corner to receive further treatment.	No Dispatch			NB	121191646	Other Construction Related Incidents		T.G. NICKEL & ASSOCIATES



ident Date	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager reported that a worker jammed his finger while drilling into concrete. The worker walked to the emergency room.	No Dispatch			NEW BUILDING	121333440-01-NB	Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	RNC INDUSTRIES LLC
018	Manhattan	560	WEST 33 STREET	0		No Dispatch					Other Construction Related Incidents	ERY NORTH TOWER RHC TENANT LLC	
0/2018	Queens	54-17	101 STREET	0	2 New York Chy Emergency Management reported that low ownters that were working on wires on the builtheat low ownters that were working on wires on the builtheat were able to make it down from the builtheat and were ransported to a hospital. A DOB inspector responded to the incident and visited the site and issued two ECB Violations for the equipment ground not being provided and for the exposed wives at the builthead area not being properly terminated, secure, and protected around the HVAZ air handler unit. A partial Slop Work Order (PSWO) was also issued for electrical work.	ECB Violation	35313362Z 35313363K				Other Construction Related Incidents	HANAC CORONA HOUSING DEV. FUND	
2018	Manhattan	80	EAST10 STREET	0	The Site Safety Coordinator reported that a worker was moving paties of concrete block around when some of the concrete block fell off and struck the worker's right leg. An ambulance was called and the worker went to a hospital for treatment. A DOB inspector responded and visited the site and reported that the worker pulled the stationary part of the patiet jack while pulling the concrete block onto hinself. It was determined that this modelen coursed as the result of a worker's error, and that no enforcement action was necessary.	No Action Necessary			NB	121193476	Other Construction Related Incidents		CCNY CONSTRUCTION INC
2018	Manhattan	7	WEST 57 STREET	0	The Site Safety Manager reported that a worker felt discomfort in his shoulder during stripping operations. The worker took a cab to a clinic on his own.	No Dispatch					Other Construction Related Incidents	7 WEST 57TH STREET REALTY COMP	
)/2018	Manhattan	515	WEST 36 STREET	0	The Site Safety Manager reported that a worker was pushing a cart when he tripped on planks that were covering a hole. The worker suffered a cut to his right hand and went to a hospital. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for the improper covering of holes.	ECB Violation	35331118J				Other Construction Related Incidents	FIRST ST MARKS LLC	
/2018	Manhattan	424	EAST 34 STREET	0	The Site Safety Manager reported that a tapper tried to move an "A"-Frame with masonite on it out of his way by himself when he tipped the "A"-Frame and was hit in the right shin by both the "A"-Frame and the masonite. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NYU HOSPITALS CENTER	
W2018	Brooklyn	8	NEVINS STREET	0	The Site Safety Manager repoted that a worker was stripping form work on the eighteenth floor when a post feel florward and hit him in the back. The worker experienced back pain and an ambulance was called. A DOB inspector responded and visited the site and reported that another worker had leaned a stripping post against a wall instead of stacking the post and the post slid from an upright position and hit the injured worker. An ECB Vlotation was issued for a failure to institutefollow safety measures for stripping operations. A DOB Violation was also issued.	ECB Violation	35326856P	051018BS02JJ01			Material Fell	NEVINS STREET OWNER LLC	
0/2018	Bronx	1410	STORY AVENUE	0	1 A DOB inspector reported that a worker was sitting on too of a beam setting joists on the second floor of a new building. He was setting joists and the situation of the production of the season of the production of the product		35327286R 35327285P	051018BS09VP01,02			Worker Fell	BR-2012 REALTY LLC	



ident Date	Borough	Address Numb		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker cut his right thumb while installing duct work. The worker went	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
					to urgent care. An ambulance was not called.								
18	Manhattan	553	WEST 30 STREET	0	The Site Safety Manager reported that a worker was using a grinder and suffered a cut to his right leg when	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
					the grinder kicked back. The worker was taken to a								
18	Manhattan	425	PARK AVENUE	0	hospital by an ambulance. 1 The Site Safety Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
					finger while using a band saw and suffered a minor gash to his finger. An ambulance was called.								
8	Manhattan	357	EAST 57 STREET	0	1 A DOB inspector reported that façade work was	ECB Violation	35245543J	051118CERJM01	ALTERATION TYPE 2	123179951-01-EW-OT	Material Fell	357 EAST 57 STREET CONDOMINIUM	EDRAS GROUP CORP
					underway at exposure floor on the sixteenth floor when a section of brick weneer disologed and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor rijany, but erfuster anderical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued.								
18	Manhattan	305	WEST END AVENUE	0	1 The Construction Superintendent reported that an	ECB Violation	35331190Y				Material Fell	305 WEST END PROPERTY, LLC	
					electrician was working on the emergency lighting of the seventh floor permanent stairs when he was hit in the head from a tape measure that fell from above. The electrician was taken to a hospital. A DOB inspector responded and visited the site and sissued an ECB Violation for the failure to maintain safe operations and a partial Stop Work Order (PSWO) for all work next to openings. The General Contractor is to provide a Means and Methods and a Toolbox Talk.								
18	Brooklyn	76	NORTH 6 TH STREET	0	The Construction Superintendent reported that a worker was cleaning a paint gun when his finger was injured by the pressure from the nozzle. The worker went home to see his doctor due to pain in his finger.	No Dispatch					Other Construction Related Incidents		
18	Manhattan	42	WEST 33 STREET	0	The Site Safety Manager reported that a worker twisted	No Dispatch			NEW BUILDING	121186849-01-NB	Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
					his knee on Saturday, May 12, 2018. This incident took place on May 12, 2018, but was reported on Monday, May 14, 2018. The worker walked himself to a hospital.								
018	Manhattan	500	WEST 25 STREET	0	1 The Site Safety Manager reported that workers wer removing material from the grade level at the leading edge when two pieces of caisson pilings that were approximately two feet long were cut in half. The pieces of caisson pilings fell approximately fifteen feet and struck a worker that was in the excavation pit in the leg. The worker went to a hospital. The status of the worker injuries is unknown. A DOB inspector responded and visited the site and issued four ECB Violations for the absocance of the boards at the guardrails, the presence of inadequate vertical netting, the presence of an inadequate agardrail that was not constructed to code, partial Stop Work Order (PSWO) and four DOB Violations were also issued. The contractor is to provide a Means and Methods and a Toolbox Talk for the safe continuation of work.	ECB Violation	35331326M/26V/Z7X/28H	051218BS04PK01/02/03/04			Other Construction Related Incidents	500 W25TH OWNER LLC	
В	Brooklyn	211	72 STREET	0	The New York City Fire Department reported that a	No Dispatch			A2 - ALTERATION TYPE 2	302579662	Worker Fell	DEPARTMENT OF EDUCATION	KG CONSTRUCTION SERVICES
					worker was walking on a scaffold on the second level when he tripped and hurt his knee. The worker was taken to an area hospital.								
018	Brooklyn	7	WHIPPLE STREET	0	1 The Construction Superintendent reported that workers were installing O-decking on the second floor when a worker fell from the second floor onto the first floor deck. The worker was found conscious and was transported to Bellevue Hospital. Additional information regarding the injuries was not available. The Construction Superintendent was not on site as of the time that the incident occurred. An DOB inspector responded and consideration of the construction of		35308771R	051418CNEDG01	Alt 1 / NB	321285275	Worker Fell	WHIPPLE PROPERTIES LLC	SUNSHINE CONSTRUSA INC
2018	Manhattan	150	FIFTH AVENUE	0	1 A DOB inspector reported that there were workers	ECB Violation	35331133H-FAIL TO SAFEGUARD.		ALT1	122700292	Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
					moving steel beams with an electric host through a shaftway for an alteration on a volved story building. The workers moved the beams by pipe rollers on the ground to be staked. One of the workers was adjusting the stack when he was struck by two other workers that were putting steel in place. The struck worker pot his right hand crushed between two beams and was taken to Beth Israel Hopstile for treatment. An CEB Variation for a failure to safepuard was issued. A partial Stop Work Order (PSWO) was issued on all work in shrhway hoisting materials. A Means and Methods and a Toolbox Talk must be provided.								



	Borough	Address Number	r Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers		Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was on	No Dispatch			ALT1	121324343	Worker Fell	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
					the roof setback setting roof pavers when he stepped in								
					a hole with the roof pavers that he was working on and								
					hit his right shin. The worker was conscious and alert								
					and walked to a City M.D. to be checked out.								
018	Manhattan	627	GREENWICH STREET	0	1 The Site Safety Manager reported that a plumber	No Dispatch					Worker Fell	627 GREENWICH OWNER LLC	
					slipped off of the fourth step of a ladder that he was working on and suffered a sprained ankle. An								
					ambulance was called.								
018		500	WEST 33 STREET			FORMULE	larananay.				Other Construction Related Incidents	NOT ON FILE	
018	Manhattan	500	WEST 33 STREET	0	1 A DOB inspector reported that materials that were stored in the staging area were blown away due to wind.	ECB Violation	35326800X				Other Construction Related Incidents	NOT ON FILE	
					Among the stored materials was a piece of styrofoam								
					that was approximately 8' X 3' X 3' that struck a security								
					guard in the back. The security guard complained of								
					pain and was taken to a hospital in a conscious state								
					with an unknown injury. An ECB Violation was issued,								
					as well as a partial Stop Work Order (PSWO) for all work in the staging area due to a failure to secure stored								
					material. The General Contractor is to provide a Means								
					and Methods for a safe storage procedure.								
					and methods for a sale storage procedure.								
018	Manhattan	20	BROAD STREET	0	1 The Site Safety Manager reported that a worker tripped	No Action Necessary					Worker Fell	NY STOCK EXCHANGE BLDG. CO.	
					on debris and fell on his back. An ambulance was								
					called. A DOB inspector responded and visited the site								
					and reported that no enforcement action was necessary, as the incident occurred as the result of a worker error.								
					The worker was okay and was reported to have returned								
					to work the following day.								
018	Manhattan	100	EAST 104 STREET	0	2 The New York City Police Department reported that	ECB Violation	35309489H	051518CNEGS02	NEW BUILDING	121192887-01-NB	Material Fell	TERRACE ON THE PARK LLC	GLENWOOD CONSTRUCTION
-		1.22			debris was falling from the building. A DOB inspector								
					responded and visited the site and reported that at the								
					fifteenth floor setback, sections of isolation and plywood								
					became separated due to high winds and fell to the								
					street level along Park Avenue, striking two individuals. One of the individuals that was struck was taken to a								
					local hospital. An Aggravated Level 2 ECB Violation was								
					issued for a failure to safeguard. A DOB Violation and a								
					full Stop Work Order (FSWO) were also issued.								
018	Manhattan	1	WALL STREET	0	The Site Safety Manaer reported that a worker was	ECB Violation	35327019M				Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
					setting up needle beams when a portion of screw jack								
					fell onto the worker when he bent down. The struck								
					worker complained of neck pain and left the site to visit								
					his own doctor. A DOB inspector responded to the								
					incident and visited the site and issued an ECB								
					Violation for a failure to maintain safe operations and a partial Stop Work Order (PSWO) on the use of all								
					needle beams. A Means and Methods and a Toolbox								
					Talk must be provided. An additional ECB Violation will								
					be issued for the installation of a pipe scaffold that was								
					done contrary to the design plans.								
2018	Brooklyn	626	SHEEPSHEAD BAY ROAD	0	1 The Project Manager reported that a painter was on a	No Dispatch					Other Construction Related Incidents	NEPTUNE SOUTH COMMERCIAL LLC	
					ladder on the third floor when he misused the ladder and								
					slipped off. The worker fell approximately six fee and								
					hurt his shoulder. An ambulance was called.								
14.0	Decables	110	KENT AVENUE		2 A DOB inspector reported that approximately 50'-0"	ECB Violation	35322610R	051518CERSM05	NEW BUILDING	320622616-01-NB	Material Fell	420 KENT AVENUE LLC	ZDG, LLC
018	Brooklyn	416	KENT AVENUE	0	2 A DOB inspector reported that approximately 50'-0" linear feet of sidewalk shed deck and parapet deck	ECB Violation	35322610R	051518CERSM05	NEW BUILDING	320622616-01-NB	material Fell	420 KENT AVENUE LLC	ZDG, LLC
					enclosure had blown off of a sidewalk shed and onto the								
					street, injuring two pedestrians. The two pedestrians								
					were taken to a hospital. Their condition was unknown								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECG Violation was issued for a								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safequard the public and property. A DOB								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. A Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also sized. A partial Stop Work Order								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued on all crans and exterior								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. A Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also sized. A partial Stop Work Order								
					were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the sale to remove the debris from the steet. An strated the sale to remove the debris from the steet. An fault to the sale sale to the								
110		4047	WARE STREET		were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued on all crast and exterior operations, except for work to make safe the installation of a sidewalk shed.	ECD Violation	362779001	05161985721001			Mandal Fall	DECAMAND AND HOME STEFFT USA	
118	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a rallure to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued on all crast and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was oflumbing us a metal stud wall when the stud wall	ECB Violation	3532729QJ	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
018	Втопх	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shad responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a altiture to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued on all crare and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall fell, hit as generator, and then bounced off the generator.	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
018	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWU) was issued on all crast and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall left, hit a generator, and then bounced off the generator and landed on the worker's lex. An ambulance was	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
018	Вголх	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shad responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a altiture to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued on all crare and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall fell, hit agenerator, and then bounced off the generator and landed on the worker's leg. An ambulance was called. A DOB impepetor responded to the incident and	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
018	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the sale to remove the debies from the steet. An instead the sale to remove the debies from the steet. An fault or safeguard the public and property, A DOB Violation was also insued. A parial Stop Work Order (PSWO) was issued on all crane and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall and though the worker was plumbing up a metal stud wall when the stud wall and landed on the worker's lag. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that sately measures were	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
018	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWV) was sused on all crase and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall fell his agenerator, and then bounced off the generator and landed on the worker's leg. An ambulance was called. A DOB impector responded to the incident and visited the site and reported that safely measures were not in place for a bearing wall installation. An ECB	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
018	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggarwated Level 2 ECED Violation was issued for a sidewalk shed respectively. We have the sidewalk shed to the company of the sidewalk shed to the sidewalk shed shed to the sidewalk shed shed to the sidewalk shed shed to the sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall fell, hit a generator, and then bounced off the generator and landed on the worker's leg. An ambulance was called. A DOB impector responded to the incident and color in place for a bearing wall installation. An ECB Violation was a DOB Violation was a DOB Violation and a DOB Violation and a DOB Violation was well as a	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
018	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWU) was issued on all crain and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall held it as generatio, and control to the stud wall held it as generatio, and control to the control to t	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
018	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shad responded and visited the sito to remove the debris from the steet. An Aggravated Level 2 ECD Violation was issued for a failure to safeguant the public and property. A DOB experience of the property of	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
18	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWU) was issued on all crain and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall held it as generatio, and control to the stud wall held it as generatio, and control to the control to t	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
8	Bronx	1017	HOME STREET	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shad responded and visited the sito to remove the debris from the steet. An Aggravated Level 2 ECD Violation was issued for a failure to safeguant the public and property. A DOB experience of the property of	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
18	Bronx Manhattan	1017	HOME STREET UNION SQUARE EAST	0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shad responded and visited the sito to remove the debris from the steet. An Aggravated Level 2 ECD Violation was issued for a failure to safeguant the public and property. A DOB experience of the property of		35327290J	051518BS03VP01			Material Fell Other Construction Related Incidents	DREAMYARD 1017 HOME STREET HOU	
		1017		0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shad responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a affautre to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order Toperation, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall left, hit agenerator, and then bounced off the generator and landed on the worker's leg. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that safety measures were not in place for a bearing wall installation. A ECB Violation and a DOB Violation were issued, as well as a partial Stop Work Order (FSW) on all bearing wall installations. A Means and Methods and safety measures for bearing wall installations. A Means and Methods and safety measures for bearing wall installations must be provided. 1 A competent person at the site reported that a worker was removing a vertical shoring post when his finger got was removing a vertical shoring post when his finger got was removing a vertical shoring post when his finger got was removing a vertical shoring post when his finger got the provided the site of the provided was removing a vertical shoring post when his finger got the provided the site of the provided was removing a vertical shoring post when his finger got the provided the site of the provided was removing a vertical shoring post when his finger got the provided the provided the site of	No Dispatch	35327290J	051518BS03VP01					
		1017		0	were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the sale to remove the debris from the steet. An Annual training the steet of the sidewalk shed responded and visited the sale to remove the debris from the steet. An Industry to safeguard the public and property, A DOB Violation was also insued. A partial Stop Work Order (PSWO) was issued on all crane and exterior operations, except for work to make safe the installation of a sidewalk shed. 1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall held that a generation, and the study wall she that a generation, and the safe the side of the study was called the safe that the safe tha	No Dispatch	35327290J	051518BS03VP01					



Incident Date	Description	Address Number	Ptenat	Fatalities Injurie	EOC Final December	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Insident Time	Owner's Name	Contractor Name
5/16/2018	sorougn Manhattan	76	Street 11 AVENUE	Pataintes Injurie	1 The Sire Safety Manager reported that a foreman was hanging an eight inch steel pipe when he lost control of the pipe. The foreman was then knocked off of a ladder by the pipe. An ambulance was called A DOB inspector responsed and visited the site and reported that the archor from which the pipe was to be hung from failed. An ECB Violenton was issued for a failure to maintain safe operations.	ECB Violation	35331136N	DUB Violation Numbers	Permit	Permit No	Incident Type Other Construction Related Incidents	Owner's Name 78 ELEVENTH AVENUE PROPERTY OW	Contractor Name
5/16/2018	Queens	45-07	COURT SQUARE	0	The Site Safety Coordinator reported that a worker was using a four inch grinder when the grinder kicked back and cut the worker's left arm. The handle and grinder guard were in place. The worker was conscious and awake and went to Mount Sinai Hospital for treatment.	No Dispatch			NB	420902410	Mechanical Construction Equipment	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
5/17/2018	Queens	2100	49 AVENUE	0	The Construction Superintendent reported that an electrician was re-adjusting a ladder when he fell approximately five feet off of the ladder. The worker complainted of back pain and was taken to Elmhurst Hospital. The worker was alert and awake.	No Dispatch			ALT1	420656686	Worker Fell	2100 49TH AVENUE OWNER, LLC	ARCHSTONE BUILDERS LLC
5/17/2018	Queens	101	PENNSYLVANIA AVE	0	The Construction Superintendent reported that while working on a seven story new buiding, a project manager picked up a sheet metal that cut his finger. The project manager went to urgent care.	No Dispatch			NB	320622894	Other Construction Related Incidents		CAULDWELL WINGATE CO LLC
5/17/2018	Manhattan	112	EAST 11 STREET	0	The Site Safety Manager reported that a worker was coming down a gang ladder when he slipped on the third step of the ladder and felt three feet. The worker complained of back pain. An ambulance was called. A DOB inspector responded and visited the site and found no unsafe conditions present as of the time of inspection. No enforcement action was necessary.	No Action Necessary					Worker Fell	UD-DEV ASSOCIATES LLC	
5/17/2018	Brooklyn	138	WILLOUGHBY STREET	0	2 A DOB inspector reported that a signalman had landed a banded load on the top deck with a tower crane. The rigging was released after the load was landed, and the load shittled and statistical endough service that was carrying pieces of rebar. The worker trapped, felt, and hunt his ankle. The worker was taken to a hospital for X-banding after releasing the rigging and want to a City M.D. for treatment. There were no witnesses to the worker falling. No enforcement action was necessary, as it was determined that the signalman suffered a cut due to a worker error.				CN	773/17	Worker Fell	NYC HPD	Trident General Contracting, GC lend lease
5/17/2018	Bronx	1903	WEST FARMS ROAD	0	The Site Safety Manager reported that a worker was performing insulation work behind a stud wall when she pushed a stack of sheetrock that was leaning against a wall, which caused the boards to fall forward and hit her in the leg. An ambulance was called.	No Dispatch					Material Fell	SAMARITAN-COMPASS V HOUSING DE	
5/18/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	The Site Safety Manager reported that a worker cut his finger on a piece of sheet metal. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	ATLANTIC 2644, LLC	
5/18/2018	Brooklyn	422	FULTON STREET	0	3	No Action Necessary			CN	80/17	Mechanical Construction Equipment	NOT ON FILE	FJM- Ferro Inc
5/18/2018	Brooklyn	578	COZINE AVENUE	0	A DOB inspector reported that a worker was performing asbestos abatement work on the roof when he fell approximately twenty feet through the roof. The worker was taken to Brookdale Hospital. The abatement work was being performed as per the posted notice. I'wo Aggravated Level 2 ECB Wolations for a failure to safeguard were issued to the abatement company and building owner. A partial Stop Work Order (PSWO) was issued for all work at the roof level. The contractor at the site is to provide a Means and Methods for the safe removal of material from the roof level.		35322901R 35322902Z	051818CERRJ03 051818CERRJ04	Abatement		Worker Fell	NYBC REALTY LLC	GSC Services Corp



Incident Date 5/18/2018	Borough Brooklyn	Address Number 6	Street METROTECH		EOC Final Description 1 A New York City Police Officer reported that a plumber was working on a pipe on the fifth floor when the pipe burst and hit the plumber in the cheat and chin. An ambulance was called. A DOB inspector responded to the incident and visited the site and determined that their owns no enforcement action recessary, as the job and the plumber of the control of		ECB Violation Numbers	DOB Violation Numbers	Permit PLUMBING	Permit No 321562288	Incident Type Mechanical Construction Equipment	Owner's Name NEW YORK UNIVERSITY	Contractor Name VITO M. GIACHETTI
5/18/2018	Manhattan	130	WILLIAM STREET	0	The Site Safety Manager reported that a ten feet long piece of rebar that was standing vertically and was to be installed fell on a worker that was standing on the ground, hitting him in the side of his hard hat. The worker went to a City M.D. A DOB inspector responded and visited the site and issued an ECB Violation for a failure to maintain safe operations, as well as a partial Stop Work Order (PSWD) for all concrete operations. The General Contractor at the site is to provide a Means and Methods and a Tool Box Tall.		35331400N				Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	
5/21/2018	Bronx	2865	CRESTON AVENUE	0	The Site Safety Manager reported that a worker was putting up forms on a column when he fell about six to seven feet and injured his foct. The worker was sent to a hospital. A DOB inspector responded and visited the site and found that a hook that was holding form up was damaged, which may have possibly caused the worker to fall. An ECB Violation for the failure to maintain safety operations was issued, as well as a partial Stop Work Order (PSWO) for all concrete work. Additional ECB Violations were abo issued for infractions that were not related to the incident.		35327296K, 35327297M, 98, 99X,353184OOR, 01Z				Worker Fell	10 MINERVA PLACE HOUSING DEVEL	
5/21/2018	Bronx	4215	PARK AVENUE	0	The Site Safety Manager reported that a worker fell from the top of a hoist that was stopped on the first floor. The worker suffered minor injuries and was transported to a	No Dispatch			NEW BUILDING	220157700-01-NB	Worker Fell	TREMONT RENAISSANCE HOUSING DE	JOY CONSTRUCTION CORP
5/21/2018	Manhattan	247	WEST 87 STREET	0	hospital by ambulance. 2 The New York City Police Department reported that two workers were in the process of installing a supported scaffold when they sipped and fell from three frames of pipe scalfold. The workers suffered scrapes and burney to their hands and legs and were taken to St. Luke's Hospital. A DOB inspector responded to the incident and visited the site and issued the Avo Aggravated Level 2 ECB Violations. The first violation was issued for the removal or alteration of the supported scaffold by the General Contractor before the inspector's arrival, which is the removal or alteration of the supported scaffold by the General Contractor before the inspector's arrival, which is the removal or alteration of the supported scaffold by the General Contractor before the inspector's arrival, which is the removal or alteration of the support of the second violation was issued for a failure to promptly notify the Department Of Buildings of the incident, as the incident was reported by the NYPD.	ECB Violation	35324011Y - 35324012X		N/A		Worker Fell	KSB BROADWAY ASSOCIATES	Jerrick Associates Inc
5/21/2018	Queens	30-02	39 AVENUE	0	cutting a metal stud when he cut his hand. An	No Dispatch					Other Construction Related Incidents	30-02 ASSOCIATES LLC	
5/23/2018	Staten Island	149	PROVIDENCE STREET	0	ambulance was called. I The New York City Office Of Emergency Management reported that a worker fell from the structure. EMS transported the worker to a hospital. A DOB inspector responded to the incident and visited the sale two ECB Voliations for the failure to adequate and for the failure to incidence of the incident. A Jul Slop York Order (FSWO) was also issued:	DOB Violation	35322904M/05Y	052318CERRJ01/02	ALT 1	520323212	Worker Fell	PERRI, ALFONSO	A. FONTANA & SONS LLC
5/23/2018	Manhattan	76	11 AVENUE	0	1 The Site Safety Manager reported that a worker was building the walk-out for a tower crane and was standing on the crane is the back beam when he slipped off of the beam and fell. The worker was wearing fall protection equipment. The worker dien of suffer an injury, but was taken to a hospital for precautionary observation. A DISE imspector responded to the incident and visited the site and reported that no enforcement action was necessary.						Worker Fell	76 ELEVENTH AVENUE PROPERTY OW	SBF Construction
5/23/2018	Manhattan	26	1 AVENUE	0	1 A New York City Police Officer reported that a worker fell approximately five stories or fifty feet from an unguarded section of pipe scaffield. The worker was in critical condition and was taken to Bellevue Hospital. A DOB inspector responded to the incident and visited the site and reported that it could not be determined what caused the worker to fall, as the people that the inspector interviewed claimed to have not seen or know about the incident. Four EOS Violations were issued for the faiture to safeguard, for the presence of a supported cardifold that was not built according to code and was missing guardraits, missing toe boards, and was not tally decked, for the absence of plans, drawings, and logs on site, and for the failure to provide a four hour supported scaffold what exact your negrees. A partial Stop Work Order (PSWO) was also issued.	,	35324057J, 35324058L, 35324059N, 35324060K		Alt	140761995	Worker Fell	DROBENKO NICHOLAS	Lime-Light Construction Co



ncident Date	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
24/2018	Brooklyn	2837	WEST 8 STREET	0	1 The Project Manager at the site reported that during the installation of concrete panel around a bulkhead, a panel cracked, fell, and caused a minor cut to a worker's hands. The worker went to a clinic and then came back to the site on the following day. A DOB inspector responded to the incident and visited the site and it he responded to the incident and visited the site and it he responded to the incident and visited the site and it he reported that a Means and Methods was in place at the reported that a Means and Methods. The suction cup equipment was found to see in working condition. The inspector observed that the concrete panel was effective. No enforcement action was deemed necessary.						Material Fell	AISD CORP.	
24/2018	Brooklyn	41	BLUE SLIP	0	The Site Safety Manager reported that the driver of a concrete truck was washing out his truck when he hopped off of a ladder and turned his ankle. EMS was called and the worker was sent to a nearby hospital.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT F LLC	
5/24/2018	Brooklyn	420	EAST 21 STREET	0	1 The New York City-Fire Department requested that an inspection please be performed due to a retaining wall mispection please be performed due to a retaining wall state of the proposed of the performed of the		35322725R, 35423726Z	052418CNESC04, 05, 052418CNE01SC			Other Construction Related Incidents	HOSSAIN, GOLAM	
/24/2018	Brooklyn	84	CARLTON AVENUE	0	A competent person at the site reported that a worker was installing roof protection when the worker tripped on a piece of plywood and fell. The worker was sent to a hospital for a check up.						Other Construction Related Incidents	NYC HOUSING AUTHORITY	
/24/2018	Manhattan	233	WEST 125 STREET	0	The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taken to a hospital by EMS.				NEW BUILDING	121187447-01-NB	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
/25/2018	Manhattan	24	2 AVENUE	0	The Site Safety Manager reported that a worker cut his arm with a sheetrock knife while cutting sheetrock. The worker went to a nearby urgent care facility to receive medical attention.						Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	
/25/2018	Queens	28-07	JAGKSON AVENUE	0	1 A DOB inspector reported that there was a six man tear that was dismantling support columns when one of the columns was released before one of the workers had a hold of the column. The column struck this worker to the ground. The worker was wearing his Personal Protection: Capulpment (PFP) and was found alter and responsive. The worker did not suffer a serious rijuty, but was taken Documentation was provided to show that the worker attended a pre-job meeting and that the worker was up to date with adily pre-task hazards afsety meetings that are designed to avoid such incidents. The inspector determined that no enforcement action was necessary and that the incident occurred as the result of a worker error.				ALT 1 NB	420656873	Material Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV



cident Date	Borough	Address Numb	er Street	Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
dent Date 5/2018	Borough Manhattan	Address Numb 217	er Street WEST 57 STREET	Fatalities Injuriu	DE CF inal Description A DOB Professional Engineer (PE) reported that at a sixty-seven story new building that was under construction, a security guard was walking from the front to the near on the first floor of the building when an approximate 16 x SF, 2.300 pound glass curtain wall panel with a supporting steel "A"-Frame toget and pinned the security guard underneath it. Several workers littled the "A"-Frame and removed the pinned security guard. The security guard was taken to Mount Sinal Hospital, where he was later pronounced dead. A DOB inspector that was also at the site reported that the glass panel fiel because it was succlearlially hit by another worker that was sitying to lift a piece of HVAC metal duct that was in close proximity. A contributing factor to the Frame that was supporting the panel was facing towards the walking area instead of towards the contribution. How the walk has also in the second to the second provides of the second provides and the second provides of the second provides and the second p	ECB Violation	ECB Violation Numbers 35322614Y	DOB Violation Numbers 052618CERSM01	Permit ALT 1 NB	Permit No 121328205	Incident Type Material Fell	Owner's Name SMITELL SPONSOR LLC	Contractor Name LEND LEASE (US) CONSTRUCT
					inspection at the site at the start of the work day that morning, However, he did not fill out his safety log. A full Stop Work Order (FSWO) was issued, as well as an Aggravated Level 2 ECB Violation for a failure to safe								
26/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	2 The New Yok City Fire Department requested that a structural stability inspection please be performed because a construction fence had partially colleged. A DOB inspector responded to the incident and visited the site and reported that there was approximately IOD feet site and reported that there was approximately IOD feet please the partial stability of the properties of the properties and a four foot chain link fence that had allean over onto a pedestrian walkway and injured to the pedestrians. The two pedestrians were not transported by EMS to receive off-site medical assistance. The barriers were found to have inadequate water levels. Two ECB Violations were issued for a failure to safeguard and for a defective job site fence. Two DOB Violations were sued to safeguard and for a defective job site fence. Two DOB Violations were also issued.		35323583P, 35323584R	052518CERFC02 , 03	ALT 1 NB	320622894	Material Fell	SPRINGER, JEAN E	CAULDWELL WINGATE CO LLC
9/2018	Bronx	220	EAST 178 STREET	0	The Site Safety Coordinator reported that while working on a twelve story New Building that was at the Support of Excavation (SQE) stage, a hose from the fire hydant that was across the sidewal was being used when a female pedestrain tripped and fell over the hose. The pedestrain was found alert and awake and was taken to a nearby hospital by ambulance. A DOB inspector responded to the incident and visited the site and reported that the pedestrain sidewalk was clear of any obstructions as of the time of inspection. Two ECB Violations for the presence of tripping hazards. A full Stop Work Order (FSWO) was issued for the entire site.	ECB Violation	35332113P 35332114R		New Building	220546620	Excavation/Soil Work	GRAND APTS HOUSING DEVELOPMENT	M. Melnick & Company Inc
9/2018	Manhattan	15	BRIDGE PARK DRIVE	0	The Site Safety Manager reported that a worker was unloading an air handler when he lacerated his middle finger on a sharp edge of the air handler. The worker went to a local clinic.	No Dispatch					Other Construction Related Incidents		
9/2018	Menhattan	151	MAIDEN LANE	0	went to a local clinic. I The Site Safety Manager reported that workers were moving a refingiration unit when it toppled over onto not the workers. The injured vorter was taken to a losspisal. A DOS inspector responded to the incident and hospital. A DOS inspector responded to the incident allower of the incident and the post of the incident and failure to maintain safe operations, as well as a partial Slop Work Order (PSWO) on material handling on the ground level at the exposure. The General Contractor is to provide a Means and Methods.		35336652H				Other Construction Related Incidents	151 MAIDEN LLC	
9/2018	Queens	45-57	UNION STREET	0	1 The Sate Safety Manager reported that a worker was on baker scaffold at the second floor when the worker fell from the scaffold. The worker was found conscious, but complainted of pain in his shoulder and leg. The worker seponded to the his chief was the safe and issued one ECB Violation for a scaffold platform that was not fully plainted and for the presence of planks that were not sed down. A partial Stop Work Order (PSWO) for the use of a supported scaffold was also issued.		35323972Z - 35323973K		NB	402898959	Worker Fell	DEPARTMENT OF EDUCATION	Leon D. Demattels Construction
9/2018	Queens	45-57	UNION STREET	0	The Site Safety Manager reported that an electrician tripped while walking and suffered an injury to his rubs. The worker went to urgent care.	No Dispatch					Worker Fell	DEPARTMENT OF EDUCATION	
80/2018	Brooklyn	2550	3 AVENUE	0	The Site Safety Coordinator reported that a worker's foot came into contact with a piece of pipe that was in a pile of garbage that was to be picked up. The worker suffered a foot laceration and was sent to a hospital.	No Dispatch					Other Construction Related Incidents		





Incident Date	Borough	Address Number	Street	Fatalities	Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/31/2018	Brooklyn	107	COLUMBIA HEIGHTS	0		The Site Safety Coordinator reported that four workers were carrying heavy mechanical equipment down the stairs when equipment fell on one of the workers. The worker was sent to a hospital for a check up A DOB inspector responded to the incident and visited the site and issued an ECE Vollation for the faulte to maintain safe operations and a partial Stop Work Order (PSWO) on the handling of heavy material. The General Contractor is to provide a Means and Methods.	ECB Violation	35326963N				Other Construction Related Incidents	CLIPPER 107 CH LLC	
5/31/2018	Manhattan	360	EAST 89 STREET	0		A DOB respector reported that a worker was sorting and moving glass window peales when one of the panels when one of the panels whited and hit the worker in the leg. The worker was taken to a hospital by ambulance for evaluation, An ECG Volation and a partial Step Work Order (PSWO) was sissed for the failure to martisin safety measures, as the worker was injured due to improper material a handling. The General Contractor is to provide a Means and Methods for safe material handling in order to prevent future incidents.		35318415J		NEW BUILDING	121186242	Material Fell	1711 LLC	RYDER CONSTRUCTION INC
	Queens	51-35	REEDER STREET	0		The Construction Superintendent reported that a worker strained his back while lifting a crate onto a dolly. An ambulance was called and the worker was transported to a hospital.	, , , , ,			NEW BUILDING	420812446-01-NB	Worker Fell	85-15 QUEENS BLVD. REALTY, LLC	STRUCTURAL LAND MANAGEMEN
5/31/2018 Grand Total	Queens	546	GULF AVENUE	0		The Site Safety Manager reported that a worker cut his finger while using a box cutter. The worker went to a clinic.	No Dispatch					Other Construction Related Incidents		