

ncident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2/2018	Manhattan	13	EAST 7 STREET	0	1 The New York City Police Department reported that an exterminator fail into a skit of order pexcavation in the basement. A DOB inspector reported that the worker suffered minor injuries and was taken to Believue Hospital and that there was unpermitted execuation word being performed in the basement. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard an work without a pemit. A full Stop Work Order was issued.	ECB Violation	35309613X		No Permit	No Permit	Worker Feil	TRIAD CAPITAL, LLC	No Permit
3/2018	Manhattan	269	WEST 87 STREET	0	1 The Site Safety Manager reported that a worker was cleaning a platform from a multipoint scaffold when he slipped and fell five feet onto the ground, hitting his right elbow. An ambulance was on site. Four ECB Violations and a partial Stop Work Order were issued.		35285606Y, 35285607X, 35285608H, 35285609J				Worker Fell	RIVERVIEW OPERATING CO., LLC	Leeding Builders Group LLC
3/2018	Manhattan	430	EAST 58 STREET	0	1 The Site Safety Manager reported that a worker got his hand stuck between a steel plate and a frame and got two of his fingers crushed. The worker was sent to Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	SUTTON 58 HOLDING COMPANY LLC	
4/2018	Manhattan	1681	3 AVENUE	0		No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
6/2018	Manhattan	301	FREEDOM PLACE SOUTH	0	1 The Site Safety Coordinator reported that a worker was unloading glass from a crate when a piece of glass fell and injured his leg. The worker was taken to a hospital. The extent of the worker's injuries was not known.	No Dispatch			NEW BUILDING	121192501-01-NB	Worker Fell	301 FREEDOM PLACE SOUTH, LLC	SCIAME CONSTRUCTION LLC
8/2018	Queens	22-44	JACKSON AVENUE	D	1 The Site Safety Manager reported that a worker on the twenty fourth floor slipped on a patch of loc and host his impactor regioned to the incident and reported that diamond plates on the cusistie of a host had water and i.e on them, which caused the worker to slip. An ECB Violation and a DOB Violation were issued.	ECB Violation	35301051R	010818BS02DH03			Worker Fell	G & M REALTY, LP.	
9/2018	Manhattan	40	10 AVENUE	0	¹ The Site Safety Manager reported that a worker slipped on a second floor concrete deck, landed on his back, and hurt his shoulder. The worker slipped because of snow. The worker walked to a City MD. A DDB inspector visited the site and confirmed that the deck was covered with snow, which caused the worker to fall. An ECB Violation, a DDB Violation, and a partial Stop Work Order were issued.	r	35301164N	010918BS02VP01			Worker Fell	40-56 TENTH OWNER LLC	
/2018	Manhattan	400	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was handing down a screwpick to another worker when the screwpick signed out of his hands and hit the other worker. The worker suffered a minor injury and went to a heaped by Eclivates for a check up. A DOB inspector heaped by Eclivates for a check up. A DOB inspector stop Work Order.		35301055Y	010918BS04DH03			Material Fell	BOP NE LLC	
0/2018	Staten Island	55	RICHMOND TERRACE	0	¹ The Site Safety Manager reported that a worker slipped on ice. An ambulance was called, A DOB inspector reported that the worker slipped on ice that was located in an area that was closed off and where there was no work in progress. No enforcement action necessary.	No Action Necessary					Worker Fell	ST. GEORGE OUTLET DEV LLC	
0/2018	Queens	27-17	42 ROAD	0	1 The Side Safety Manager reported that a worker was installing sheet rock when he cut his left hand on a meta duct. The worker went to urgent care with another worker.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
10/2018	Manhattan	130	EAST 82 STREET	0	1 The Site Safety Coordinator reported that an electrician was pulling cables in a box when he pulled his hand back and cut it on a piece of Chicago Bar. The incident occurred on 1/10/2018, but was not reported until 1/11/2018. The worker went to a doctor on his own.	No Dispatch			NEW BUILDING	121328027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
10/2018	Manhattan	118	FULTON STREET	0	1 A DOB inspector reported that a worker attempted to move an "A-Frame cart that was loaded with about twenty flat stock metal sheets when the metal sheets fell onto his leg. The worker may have possibly suffered a broken leg. Are IAT was on site. An ECB Violation and partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Method for safe operations.	a	35300526R				Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	
11/2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager and a DOB inspector reported that a cargenter was standing on an 'X Frame ladder to remove the door frame from an electrical closed on the S1st floor when a piece of plywood that was behind the consignem that of the sector of the sector of the origination multi off the ladder. The worker complaned of back pain and was transported to a hospital by ambulance. A DOB inspector reported that there were no unsafe or hazardous conditions at the working area. No enforcement action was necessary.	No Action Necessary			New Building	121333440	Worker Fell	CP V TS FULTON OWNER, LLC	CP V TS FULTON OWNER LLC
/11/2018	Manhattan	151	MAIDEN LANE	0	1 A DOB inspector reported that a worker was using an "A Frame cart to move scaffolding elements when he twisted his wist while pulling the cart. The worker did no want to go in an ambulance and went to see a doctor on his own. There were no unsale of hazardous conditions at the work area. No enforcement action was necessary.	it .			New Building	121186769	Other Construction Related Incidents	151 MAIDEN LLC	PIZZAROTTI IBC LLC



	Borough	Address Number	r Street	Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
11/2018	Manhattan	305	EAST 61 STREET	0	1 The Site Safety Manager reported that a worker tripped over a board that was on the floor and twisted his right ankle. An ambulance was called to the site and took the				- crine		Worker Fell	305 EAST 61ST STREET GROUP LLC	
/2018	Manhattan	42	WEST 33 STREET	0	worker to a hospital. 1 The Site Safety Manager reported that a pedestrian	ECB Violation	35300326M	011118BS05MA03			Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	
					stepped on a piece of plywood under the upper sidewalk and slipped, injuring his right ankle. The pedestrian went to see a doctor on his own. An ECB Violation was issued.								
/2018	Queens	27-13	21 STREET	0	1 The Site Safety Manager reported that a carpenter was hitting a nail when the nail popped out and hit the worker in the face. The worker has no visible cut or injuries. An ambulance transported the worker to a hospital for a check up.	No Dispatch			NEW BUILDING	420993740	Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	DISANO DEMOLITION CO, INC
2/2018	Manhattan	45	PARK PLACE	0	1 The Site Safety Manager reported that a worker was pumping correctie into a wheatmore when the concrete pump shifted and snagged his finger between the pump clamp and the concrete cleaning basin, causing a large cut. The worker was taken to a hospital. A DOB imspector reported that according to the inspection of the logs, the injured worker did not attend the concrete pe- pump meeting and did not know with he was part of the operations. An Aggravated 2 ECB Violation, a DOB Violation, and a partial Stop Work Order were issued.		35263168X	011218CERMR01	NEW BUILDING	121185635-01-NB	Worker Feil	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
/2018	Manhattan	590	EAST 83 STREET	0	¹ The Site Safety Manager repoted that a worker was performing waterproofing work inside of a high concrete tank. When the worker was using a chemical sealant to waterproof the inside of the tank, he became overwhelmed by the fumes and passed out. The worker was taken to a hospital by an amulance. An ECB Violation, a DOB Violation, and a partial Stop Work Order were issued.	ECB Violation	35294740J	011518CERFC01	Ait 1 NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
5/2018	Manhattan	53	WEST 53 STREET	0	 The Site Safety Manager reported that a worker pulled his groin while lifting a pipe. The worker went to a MedRite. 	No Dispatch			alt 1 NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LEND LEASE (US) CONSTRUCT
5/2018	Manhattan	130	EAST 82 STREET	0		No Dispatch			alt 1 NB	121325027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
/2018	Brooklyn	179	THROOP AVENUE	0	The Site Safety Manager reported that a worker was unloading a piece of pipe scaffold off of a truck when he lost control of the piece and the section fell onto his left leg. The worker was taken to a hospital by a friend.	No Dispatch					Other Construction Related Incidents	NYC HHC	
7/2018	Manhattan	125	GREENWICH STREET	0	¹ The Site Safety Manager reported that a piece of plywood fell onto a worker's hand during a stripping operation. There were two workers working one above the other, and the piece of plywood fell from above onto the worker below. An ambulance was catled. An ECB Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Methods.	ECB Violation	35300553M				Other Construction Related Incidents	VS 125 LLC	
/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that an iron worker was using a grinder to cut a piece of metal bar when the grinder kicked back and caused a cut to the worker's thumb. The grinder had all of its safety guards in place. The worker went to an urgent care facility for treatment.	No Dispatch			NEW BUILDING	121186849	Mechanical Construction Equipment	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
7/2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker was unpacking windows from a crate and was using a 2 X 4 piece of wood as a lever to move the crate when the piece of wood snapped and hit him in the head, causing a scratch. An ambulance was called and the worker walked to the ambulance to go for a check up.	No Dispatch			NEW BUILDING	420651912	Other Construction Related Incidents	G & M REALTY, LP.	G & M REALTY L.P
3/2018	Brooklyn	1601	KINGS HIGHWAY	0	2 A DOB inspector reported that a vehicle struck a matifi with two urders in it that was parked in an occupied lane. The yodocks were not filled with water and a flagger was on present. The manift was not damaged, but one of the workers complained of leg pain, and the other worker was shook up by the incident. Both of the workers were sent to a hospital for a check up. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35300560К				Other Construction Related Incidents	KINGSWAY REALTY LLC	
8/2018	Manhattan	200	AMSTERDAM AVENUE	0	The Site Safety Manager reported that a worker was unhooking the chain from an excavator that was liting oxygen tanks when his gloves of stuck between the chain and the excavator's hook, pinching the worker's finger. The worker was taken to a hoghtal by a co- worker. Two EGS violations and a full Stop Work Order were issued. The contractor at the site was directed by a DOB inspector to provide a Means and Methods to perform liting operations.		3530559M 353055		NB	122887224	Mechanical Construction Equipment	AMSTERDAM AVENUE REDEVELOPMENT	Marc Depaul
18/2018	Manhattan	650	5 AVENUE	0	1 The Site Safety Manager reported that a flagger was almost struck by a vehicle in the middle of the street and that he twisted his right ankle while moving out of the way. The flagger went to a hospital.	No Dispatch					Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
9/2018	Manhattan	445	WEST 35 STREET	0	1 The Site Safety Manager reported that a worker was moving a wooden plank while taking down a single frame						Other Construction Related Incidents	CARE REALTY CORP.	
					scaffold when he twisted his knee and complained of pain. The worker went to see a doctor on his own								



9/2018	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Brooklyn	3003	WEST 21 STREET	0	1 The Site Safety Manager reported that a worker twisted	No Dispatch					Other Construction Related Incidents	CONCERN SURF VETS PLACE HOUSIN	
					her ankle while pushing a mini-dumpster. An ambulance was called and took the worker to a hospital.								
					was called and took the worker to a hospital.								
018	Brooklyn	19	KENT AVENUE	0	1 The Site Safety Manager reported that a worker was	ECB Violation	3505625p, 26r, 27z, 28k, 29m		CRANE NOTICE	871 17	Mechanical Construction Equipment	19 KENT ACQUISITION LLC	ALL ISLAN MASONRY & CONCRE
					setting up a mobile crane when his finger got pinched								
					between the hook of the crane and a road barrier, causing the finger to detach. A co-worker took him to a								
					hospital. Five ECB Violations and a partial Stop Work								
					Order were issued.								
2018	Bronx	16	EAST 204 STREET	0	1 The Site Safety Manager reported that a worker slipped	No Dispatch					Worker Fell	HP VILLA GARDENS HDFC, INC.	
					and hurt his back at the job site. An ambulance was								
					called and took the worker to a hospital.								
2018	Manhattan	26	ANN STREET	0	1 The Site Safety Manager reported that a worker hurt his	No Dispatch					Worker Fell	143 FULTON STREET DEVELOPMENT	
2010		20	ANN OTHEET	Ŭ	hand while taping and spackling on the ninteenth floor.	no Dispaton					Provident da		
					The worker went to urgent care.								
2018	Queens	29-22	NORTHERN BOULEVARD	0	1 A DOB inspector reported that a worker was pushing an	ECB Violation	35289063P				Material Fell	QSB NORTHERN LLC	
					"A"-Frame cart that was loaded with stone when the cart overturned, causing stone to fall onto the worker's foot								
					and possibly breaking the foot. An EMT was on site. An								
					ECB Violation and a partial Stop Work order were								
					issued. The General Contractor is to provide a Means and Methods and a Tool Box Talk.								
					and metrious and a roor box raik.								
/2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a worker	No Discotch			ALTERATION TYPE 1	224485052.04.41	Worker Fell	THE SALVATION ARMY	SD BUILDERS AND CONSTRUCT
2010	BIOURIYII	109	2 AVENUE	0	cut his finger while cutting a piece of rebar. EMS was	NO Dispatch			ALTERATION TIPE I	321103953-01-AL	WOIKEI FEII	THE SALVATION ARM T	SD BUILDERS AND CONSTRUCT
					called. The worker was found conscious and was taken								
					to an area hospital.								
/2018	Brooklyn	138	WILLOUGHBY STREET	0		No Dispatch					Other Construction Related Incidents	NYC HPD	
					doing form work with while he had his peligan hook attached to himself. When the worker was climbing down								
					a ladder, the peligan hook fell and hit his right ear. The								
					worker went to a City MD. An ambulance was not called.								
					This incident was the result of a worker error.								
/2018	Manhattan	111	EAST 24 STREET	1	0 A DOB inspecor reported that an elevator foreman was working on a platform for installing an elevator inside the	DOB Violation		012318BS0501BG	NB	121192798	Worker Fell	DEMETRIOS & FANIA SAMUEL, LLC	TRINITY BUILDERS INC
					elevator shaft at the sixth floor when the platform started								
					drifting upwards uncontrollably and would not stop. The								
					worker tried to jump to the machine room on the other platform at the ninth floor, but he fell backwards down								
					the shaft to the cellar floor, where he succumbed to his								
					injuries. The elevator foreman did not have a safety								
					harness on and was not tied to anything. There were no								
					safety lines found at the site. A DOB Violation and a full Stop Work Order were issued.								
					Stop work Order were issued.								
/2018	Queens	62-98	SAUNDERS STREET	1	0 The New York City Police Department reported that a	ECD Vieletien	35308671J, 35308670H	012318CERTQ01, 02			Worker Fell	NOT ON FILE	
2010	Queens	02-90	SAUNDERS STREET	1	worker was standing on a window sill of a sixth floor	ECB VIOlation	353066713, 35306670H	012310CER1Q01, 02			WORKEI FEIL	NOT ON FILE	
					apartment when he fell from the sixth floor to the ground.								
					The worker was transported to North Shore University								
					Hospital, but was found dead on arrival by the NYPD. A DOB inspector inspected the site and reported that there								
					was work present that consisted of a gut renovation to								
					the bathroom, the installation of new electrical wiring and								
					box, and the installation of new sheetrock, without a permit. Two ECB Violations, two DOB Violations, and a								
					Stop Work Order were issued.								
	Staten Island												
/2018		546	GULE AVENUE	0	1 The Site Safety Manager reported that a worker got	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
/2018		546	GULF AVENUE	0	concrete in his eyes during a concrete pour operation.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
/2018		546	GULF AVENUE	0	The Site Safety Manager reported that a worker got concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
		546		0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work.								
	Manhattan	280	GULF AVENUE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an	ECB Violation	35312686Y	012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC BROADWAY 280 PARK FEE LLC	
	Manhattan	546		0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was	ECB Violation	35312686Y	012918EE105FM1					
	Manhattan	280		0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January	ECB Violation	36312686Y	012918EE105FM1					
	Manhattan	280		0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker want to a hospital. This incident took place on January 24. 2018, but the Department of Buildings was not	ECB Violation	35312686Y	012018EE105FM1					
	Manhattan	280		0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 28. 2018. An CGB Volation was	ECB Violation	35312686Y	012018EE 105FM1					
	Manhattan	280		0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 28. 2018. An CGB Volation was	ECB Violation	35312686Y	012818EE105FM1					
	Manhattan	546 280		0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker want to a hospital. This incident took place on January 24. 2018, but the Department of Buildings was not	ECB Violation	35312686Y	012818EE 106FM1					
/2018		280	PARK AVENUE	0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Objartment Of Suldings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued.	ECB Violation	35312686Y	012018EE 106FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
/2018	Manhattan Manhattan	280		0 0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two on his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Site Sarlety Manager reports that a flagger was directing tarfied when he was also issued.	ECB Violation	35312686Y	012018EE105FM1					
/2018		280	PARK AVENUE	0 0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two of his lingers burned. The worker went to a hospital. This incident took place on January 24, 2016, but the Department Of Buildings was not notified until January 28, 2016. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was aside sized. 1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle.	ECB Violation	35312686Y	012018EE 106FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
/2018		280	PARK AVENUE	0 0 0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two on his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 28, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager raports that a flagger was directing traffic when he was also issued. The driver did not want to listen to the flagger. The flagger was down, but was taken to a hospital by an	ECB Violation	35312686Y	012818EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
/2018 /2018	Manhattan	280	PARK AVENUE		 concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrication was working on a live splice box when he was electrication was working on a live splice box when he was electrication was working on a live splice box when he was electrication was working on a live splice box when he was electrication was working on a live splice box when he was electrication was working on a live splice box when he was splice to a hospital. This incident took place no hancey work to a hospital. This incident took place no hancey hospital was also be a performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle. The driver diro want to listen to he flagger. The flagger was okay, but was taken to a hospital by an ambulane for a checkup. 	ECB Violation	35312686Y	012018EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
/2018 /2018		280	PARK AVENUE	0 0 0 0	concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2016, but the Objactment Of Bullidings was not 24, 2016, but the Objactment Of Bullidings was not permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flegger was flated on ware to listen to the flagger. The flagger was okay, but was taken to a hospital by a mubulance for otherwise of the start of the flagger than 1 The Site Safety Manager reported that a worker was outing rebar when he siteside and on the Innore. The	ECB Violation	35312686Y	012918EE105FM1	ALTERATION TYPE 1	121333413-01-AL	Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	CNY CONSTRUCTION LLC
2018 2018	Manhattan	280	PARK AVENUE		concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and go the on bin fingers brunnst. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was side-awiped by a whick. The driver dird or want to listen to the flagger. The flagger was okay, but was taken to a hospital by an ambulane for a checkup.	ECB Violation	35312686Y	012018EE105FM1	ALTERATION TYPE 1	121333413-01-AL	Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	CNY CONSTRUCTION LLC
/2018 /2018 /2018	Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE		concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingest burned. The worker went to a hospital. This incident took place on January 24, 2016, but the Objactment Of Bulkings was not 54, 2016, but the Objactment Of Bulkings was not permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flegger was flate of the origin the flat was taken to a hospital by a whice an other was taken to a hospital by an ambulance for ot enckrup. 1 The Site Safety Manager reported that a worker was cutting retain when he sitegot and on this finger. The worker drove himself to a first med for precaution.	ECB Violation		012518EE105FM1	ALTERATION TYPE 1		Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC	CNY CONSTRUCTION LLC
/2018 /2018 /2018	Manhattan	280	PARK AVENUE		concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Site Saifety Manager reports that a flagger was directing traffic when he was also issued. The driver did not want to listen to the flagger. The flagger was chub, but was laken to ha hospital by an ambulance for a checkup. 1 The Site Saifety Manager proported that a worker was outing rebar when he sipped and cut his finger. The worker drove himself to a first med for precaution. 1 A DOB inspector reported that a worker was clinibing up	ECB Violation	35312686Y	012818EE105FM1	ALTERATION TYPE 1	121333413-01-AL 122917503	Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	CNY CONSTRUCTION LLC allba services
//2018 //2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE		concrete in his eyes during a concrete pour operation. The worker work to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, Ant De Opartment Of Buildings was not notified until January 28, 2018. An ECB Violation was permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing tartific when he was side-swiped by a whice. Thegine soft was also issued. 1 The Site Safety Manager reports that a flagger was directing tartific when he was side a whole and hambdance for a checkup. 1 The Site Safety Manager reported that a worker was cutting naker when he slighted and cut his finger. The worker drove himself to a first med for precaution. 1 A DOB inspector reported that a worker was and 'A-'Frame lidedr from he first floor to the second and 'A-'Frame lidedr from he first floor to the second	ECB Violation		012018EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC	
4/2018 4/2018 4/2018 5/2018 5/2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE		concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was also issued. The driver did not want to listen to the flagger. The flagger was dwo, but was taken to a hospital by an ambulance for a checkup. 1 The Site Safety Manager perported that a worker was cutting rebar when he slipped and cut his finger. The worker drove himself to a first med for precaution. 1 A DOB inspector reported that a worker was cutting neador when he start first floor to the second 1 Ar DOB inspector reported that a worker was similarity and an building on the ladder starts mapped, aussing the	ECB Violation		012818EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC	
//2018 //2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE		concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. The construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2016, but the Operatment Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a ipermit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffie when he was slate-wyiced by a whick. The driver did not want to listen to the flagger. The flagger was dow, but was taken to ha hospital by an ambulance for a checkup. 1 The Site Safety Manager reported that a worker was concident when he was also be the flagger. The worker drove himsell to a first med for precaution. 1 A DOB inspector reported that a worker was an Xi-firsten indder from the first floop to as second worker for fall ten feet and land on his back. The worker worker drove himsell dated have high the hospital by an an Xi-firsten indder from the first floop to be second worker for fall ten feet and land on his back in the hospital by	ECB Violation		012018EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC	
4/2018 4/2018 5/2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE		concrete in his eyes during a concrete pour operation. The worker work to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingest burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Neulidings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a issued for electrical work being performed without a fidencing traffic when he was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was also issued. The driver did not want to listen to the flagger. The flagger was due, but was laken to ha hospital by an ambulance for a checkup. 1 The Site Safety Manager proported that a worker was cutting rebar when he singhed and cut his finger. The worker drove harmed to a flast med for precaution. 1 A DOB inspector reported that a worker was cutting rebar when he singhed and cut he is flager. The flagger was clientified to the state of the second worker drove here neaded in tom he first floor to the second worker to risk in the related and too his back. The worker was found concisious and was taken to the hospital by Worker was found concisious and was taken to the hospital by Worker Marker Laker Laker Laker Kern was floor and a full Stop Work.	ECB Violation		012818EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC	
/2018 /2018 /2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE		concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. The construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a permit. A DOB Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffie when he was also issued. 1 The Site Safety Manager reported that a worker was directing traffied Manager perported that a worker was anythene to be hospital by an ambulance for a checkup. 1 A DOB inspector reported that a worker was over the when he was also in the flagger. The flagger was down, but was taken to he hospital by an ambulance to a checkup. 1 A DOB inspector reported that a worker was concised prove himself to a first med for precaution. 1 A DOB inspector reported that a worker was floor when a rung on the ladder stanged, causing the worker drove himself to a first med for precaution. 1 A DOB inspector reported that a worker was into floor when an up on the ladder stan to the hospital by EMT personnel. An ECB Violation and a full Stop Work Cher were issued. The site will be solved.	ECB Violation		012018EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC	
2018 2018 2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE		concrete in his eyes during a concrete pour operation. The worker work to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingest burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Neulidings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a issued for electrical work being performed without a fidencing traffic when he was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was also issued. The driver did not want to listen to the flagger. The flagger was due, but was laken to ha hospital by an ambulance for a checkup. 1 The Site Safety Manager proported that a worker was cutting rebar when he singhed and cut his finger. The worker drove harmed to a flast med for precaution. 1 A DOB inspector reported that a worker was cutting rebar when he singhed and cut he is flager. The flagger was clientified to the state of the second worker drove here neaded in tom he first floor to the second worker to risk in the related and too his back. The worker was found concisious and was taken to the hospital by Worker was found concisious and was taken to the hospital by Worker Marker Laker Laker Laker Kern was floor and a full Stop Work.	ECB Violation		012918EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC	
2018 2018 2018 2018	Manhattan Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE West 188 Street		concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a jermin. A DOB Violation was also issued. 1 The Site Saifety Manager reports that a flagger was directing traffic when he was also issued. 1 The Site Saifety Manager reports that a flagger was directing traffic when he was also issued. The driver did not want to listen to the flagger. The flagger was due, but was taken to ha hospital by an ambulance for a checkup. 1 The Site Saifety Manager reported that a worker was cutting rebar when he slipped and cut his finger. The worker drove himself to a first med for precaution. 1 A DOB inspector reported that a worker was cutting retain the darken to the hospital by ENV -Frame ladder from the first floor to the second floor when a rug on the ladder scaped, cussing the worker to fall ten feet and land on his back. The worker Worker drove to fall ten feet and land on a full Stop Work Order were issued. The site will received a full audit due to site conditions.	ECB Violation		012818EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell Worker Fell	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMNTOP NOT ON FILE	
2018 2018 2018	Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE		concrete in his eyes during a concrete pour operation. The worker work to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got woo f his fingest burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Oparatment OF Buildings was not notified until January 29, 2018. An ECB Violation was spent and 200 work of the fingest burned. The worker went to a hospital. This incident took place on January 24, 2018, but he Oparatment OF Buildings was not notified until January 29, 2018. An ECB Violation was spent and Do Violation was also issued. 1 The Site Safety Manager reports that a flagger was directing traffic when he was safe swined by a whelle. The driver did not want to itsen to the flagger. The flagger was only but was laken to the hospital by an and "A-Frame Manager protect that a worker was curiting rebar when he sloped and cut his finger. The worker drove haded from the finger. The worker worker to fail the nets and land on the back. The worker worker to fail the net and mild not not back. The worker worker to fail the net and mild not not back. The worker worker to fail the net and mild not may fails by Work Order were issued. The site will received a full audit due to a site conditions.	ECB Violation		012818EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell	BROADWAY 280 PARK FEE LLC	
0018	Manhattan Manhattan Manhattan	280	PARK AVENUE WEST 125 STREET PARK PLACE West 188 Street		concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work. 1 The Construction Superintendent reported that an electrician was working on a live spice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department of Buildings was not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a jermin. A DOB Violation was also issued. 1 The Site Saifety Manager reports that a flagger was directing traffic when he was also issued. 1 The Site Saifety Manager reports that a flagger was directing traffic when he was also issued. The driver did not want to listen to the flagger. The flagger was due, but was taken to ha hospital by an ambulance for a checkup. 1 The Site Saifety Manager proported that a worker was cutting rebar when he slipped and cut his finger. The worker drove himself to a first med for precaution. 1 A DOB inspector reported that a worker was cutting retaining on the ladder snapped, causing the worker to fall ten feet and land on his back. The worker Worker drove to fall ten feet and land on his back. The worker Worker droves insued. The site will received a full audit due to site conditions.	ECB Violation		012818EE105FM1			Other Construction Related Incidents Other Construction Related Incidents Worker Fell Worker Fell	BROADWAY 280 PARK FEE LLC HARLEM URBAN DVLPMNTOP NOT ON FILE	



cident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	450	WEST 33 STREET	0	1 A DOB respector reported that during a demolition operation on the first floor of the HVAC conduits and utilities lines, a construction worker was cleaning demolition detries on the first floor of the section fiel approximately four feet and hit the worker in the head. The pipe section fle Because another worker cut a strap pipe that was holding the pipe section. The worker who was hit by the pipe section. The worker who was hit by the pipe section midbly refused medical branching. Construction Superimiter for two reads the called EMS. The worker was taken to a hospital by ambudance. A Construction Superimendent was not required at the site. An ECB Violation and a full Stop Work Order were issued. The General Contractor must	ECB Violation	35310356M		Alteration 2	140188767	Material Fell	450 PARTNERS LLC	Tishman Construction Corp
27/2018	No. Long.	500			provide a Means and Methods for the demolition of the remaining HVAC conduits.					101100051 01 ND	Modes 7 H		
//2018	Manhattan	500	WEST 33 STREET	U	1 A DOB inspector reported that an electrician was in the process of erecting a shartly while climbing an eight foot ladder when he missed a rung of the ladder and fell three feet. The worker was taken to Bellevue Hospital. A DOB inspector visited the site and reported that no enforcement action was deemed necessary.	No Action Necessary			NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
9/2018	Brooklyn	404	11 STREET	0	1 A DOB inspector reported that workers were receiving a load of concrete measnory unit (CNU) brick on the third floor when the third floor C-Joists towads the rear of a new extension partially collapsed us to excessive weight and because the C-Joists were not properly secured to the CMU wais. The collapse also caused the second and first floors to collapse into the cellar. One worker sustained minor injuines and was taken to Brocklyn Presbyterian Hospital. An Aggravated Level 2 ECB Violation and a ful Stop Work Order were issued for a failure to safleguard. A sidewalk shed has been requested to be immediately installed at exposure four. DOB will remain on site unit the sidewalk shed is installed. The set will be referring to DOB's Interior Demolition Engineering Unit for audit and approval of all temprary shoring.		25310456N		Alteration	321190858	Other Construction Related Incidents	404 11TH ST NY CORP	SUN SUN Contracting
9/2018	Brooklyn	422	FULTON STREET	0	1 The Site Safety Manager reported that a worker fell through the interior opening for a tower crane installation from the ninh loos to the eighth floor. The worker was taken to a hospital, where he was eventually released with no injuries. The worker did tande a safety orientation meeting at the start of his shift. A DOB inspector visited the site and reported that there was proper signage and a proper guardrail system present at the perimeter of the slab opening, but that the worker disregarded all safety measures provided to prevent falling hazards. No enforcement action was necessary.	No Action Necessary					Worker Fell	NOT ON FILE	
/2018	Manhattan	209	EAST 19 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.	No Dispatch			ALTERATION TYPE 1	121724946-01-AL	Worker Fell	227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
/2018	Manhattan	500	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
0/2018	Manhattan	20	BROAD STREET	0	1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
1/2018	Brooklyn	138	WILLOUGHBY STREET	0	A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor colume, the worker was positioned below the installing a clamp. While securing the clamp, the clamp fiel and it the bolow worker in the face. The worker was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overright for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.	No Action Necessary					Material Fell	NYC HPD	
1/2018	Manhattan	1283	YORK AVENUE	0	 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, lost his balance, and fell on his rear. The worker walked to a City MD for a check up. 						Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	
1/2018	Manhattan	209	EAST 19 STREET	0	1 The Site Safety Manager reported that a worker hurt his finger while unloading pipes from a delivery truck. The worker went to a City MD on his own.	No Dispatch					Other Construction Related Incidents	227 EAST 19TH STREET OWNER, LL	
1/2018	Manhattan	435	EAST 13 STREET	0	1 The Construction Superintendent reported that a third party inspector missed the last step on his way down a permanent flight of stairs and hurt his foot. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
1/2018	Manhattan	532	WEST 33 STREET	0	In The Site Safety Manager reported that a worker slipped on ice melt pellets that were on the ground floor of the job site in an area where ice melt had been put down to melt ice. The worker hurt his wrist and his hip. The worker went to see the onsite medic before going to see an offsite medic on his own.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					an onsite medic on his own.		Page 4 of 33						



cident Date		Address Number	Street	Fatalities In	juries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	550	WEST 29 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	550 WEST 29TH STREET LLC	
					using a grinder when the blade caught his glove and caused a cut to his hand. An ambulance was called.								
18	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that a worker cut hi	s No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
					pinky finger while putting away his band-saw tool. The band-saw was unplugged. The worker went to a clinic An ambulance was not called								
018	Manhattan	328	EAST 62 STREET	0	1 The Construction Superintendent reported that a work	er No Dispatch			Alt 1 - NB	121189846	Other Construction Related Incidents	YYY 62ND STREET LLC	JOY CONSTRUCTION CORP
010		320			was installing pour stops when he slipped into the sid rebar and injured his shoulder. The worker left the site a cab.	e of			ALT-NO	121103040	Curer Construction related incidents		SOT CONSTRUCTION CORP
2018	Manhattan	591	THIRD AVENUE	0	1 The Site Safety Manager reported that a painter was	No Dispatch					Other Construction Related Incidents	587-91 THIRD OWNER LLC	
					carrying down supplies when he lost hs balance on th fourth step and fell, hurting his leg. An ambulance was called and the ambulance took the worker to a hospit	e s II.							
2018	Brooklyn	1	FLATBUSH	0	 The Site Safety Manager reported that a worker was removing debris when a four inch pipe that was about three feet long fell on his foot. The worker went to a hospital. 	No Dispatch					Other Construction Related Incidents		
/2018	Bronx	869	EAST 147 STREET	0	1 The Site Safety Manager reported that a worker	No Dispatch					Other Construction Related Incidents	HP MLK PLAZA HOUSING DEVELOPME	
					complained about lower back pain while pulling a stud during carpentry work. The worker went to urgent care An ambulance was not called.								
2018	Brooklyn	1	FLATBUSH AVENUE	0	1 The Site Safety Manager reported that a worker was doing taping work while on an'A'-Frame ladder when mis-stepped and fell two feet. The worker suffered a minor injury and an ambulance was called.	No Dispatch he					Other Construction Related Incidents	ONE FLATBUSH AVENUE PROPERTY L	
2018	Brooklyn	37	BLUE SLIP	0	1 The Site Safety Manager reported that a worker got hi thumb pinched between a window and a rack during a delivery. The worker went to urgent care on his own.	s No Dispatch					Other Construction Related Incidents	BOP GREENPOINT G LLC	
/2018	Manhattan	10	RIVERSIDE BOULEVARD	0	 The Site Safety Manager reported that a worker hurt h back while lifting a reel of wire into a box. An ambulan was called. 						Other Construction Related Incidents	RCB3 NOMINEE LLC	
5/2018	Manhattan	24	2 AVENUE	0	1 The Site Skiety Manager reported that a worker was purpling away his tools at the end of the day when he opened a sliding glass door on the eighth floor. The glass door came of di fist tack and hit the worker. Th incident took place on 2/5/2018, alwas not reported until 2/6/2018. An ambulance was not called, but the worker said that he was going to see a doctor to be checked out. An EGS Wolston and a DGB Violation restallation of all blockmy sliting doors was issued. Th General Contractor is to provide a Manufacturer's Specification on all door tracks and the reason for the door failing of tils track.	d e	35299721R	020618B503GD02			Material Fell	24 SECOND AVENUE OWNER LLC	
2018	Manhattan	260	WEST 40 STREET	0	A DOB inspector reported that a worker was trying to reach for something on the platform of a baker scaffol when he moved the baker scaffol, causing it to stifke the left shoulder of another worker. Both workers were on the floor and using the scaffold. The injured worker was and to stuffer a major injury. An ECB Violation was issued.	d ,	35285826Y		NB	121187394	Material Fell	PORT 40TH PARKING CORP	ZDG LLC
2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con-Edia box. The worker went to Staten Island Hospital on his	ion					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Manhattan	91	LEONARD STREET	0	own for a check up. 1 The Site Safety Manager reported that a worker trippe fell, and cut his hand. EMS was called. The worker wa conscious and was taken to an area hospital.	d, No Dispatch Is			NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
2018	Manhattan	91	LEONARD STREET	0	1 A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker went of a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	353-357 BROADWAY LLC	
2018	Manhattan	2395	FREDERICK DOUGLAS BOULEVARD	0	Here'r & a roopina or y anichanice. I A DGB impedior reported that a worker was hit in the head with a piece of imber that was dropped by anoth hit by the piece of imber or population of a staff neck at was sent to a hospital. An ECB Violation was issued, well as a partial Stop Work Order on all concrete work Means and Methods must be provided.	ier /as d as	35289390M				Other Construction Related Incidents	HP 2395 FDB HOUSING DEVELOPMEN	
2018	Manhattan	1283	YORK AVENUE	0	1 The Site Safety Manager reported that a worker was moving an 'A'-Frame dolly that was loaded with twent sheets of 4 X 8 diamond plates when the dolly topped hit her ankle. The injured worker went to an emergenor room that was across the street from the site. An ECE Violation and a partial Stop Work Order were issued.	y and v	35299967R				Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	
/2018	Brooklyn	911	ERSKINE STREET	0	1 The Site Safety Manager reported that a worker was cutting the remainder of wood piles that were approximately four feet. While cutting one of the piles the pile fel forward and hit him in the head. The work were to a hospital by ambulance. This incident occurs on 2/6/2018, but was not reported until 2/8/2018, An ECBV foldion was issued for a failure to notify the Department OF Buildings of the incident, as well as a partial Stop Work Order for the cutting of all wood pile A Means and Methods for safe cutting operations with fool box tak will be provided.	er ed	35300547X.49J	020618BS06HM01,02			Material Fell	FOUNTAIN SEAVIEW THREE HOUSING	



ncident Date	Borough	Address Numbe		Fatalities Injuri		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/7/2018	Brooklyn	540	FULTON STREET	0	1 The Size Safety Manager reported that during a drilling operation for the backs, a capement that was assisting the drill operator stepped onto an equipment insert and the clamp closed down on his left for the vorker was taken to a hospital by remergency personnel. Two ECB Violation, nucluding an Aggravated Level 2 ECB Violation, were issued, as well as a full Stop Work Order. The contractor has been directed to provide the manufacturer's specifications for the drilling equipment, as well as the required training for the personnel operation the equipment.	ECB Violation	35309900Z 35309901K		NB	321185828	Mechanical Construction Equipment	540 FULTON ASSOCIATES	PAV-LAK CONTTRACTING INC
/2018	Manhattan	460	PARK AVENUE SOUTH	0	1 The Site Safety Manager reported that a worker was opening a crate of window frames when a 5' X 5' tube pipe rolled out and onto his foot. The worker was seen walking around, but an ambulance was called.	No Dispatch					Other Construction Related Incidents	460 PARK AVENUE SOUTH ASSOCIAT	
2018	Queens	27-17	42 ROAD	0	1 The Site Safety Manager reported that a worker lacerated his hand with a utility knife during a stripping operation when the utility knife slipped. The worker went to a hospital on his own.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
/2018	Brooklyn	810	FULTON STREET	0	1 The Site Safety Manager reported that a worker was performing stripping work on the eleventh floor when he pulled down a piece of plywood and the aluminum leg of the formwork hit the worker in the face and split his lip. An ambulance was called. An ECB Violation was issued for a failure to provide safety measures. A DOB Violation was also issued. A Tord BoX Talk will be issued before the start of stripping operations.		35300050K	020818BS02EP06			Material Fell	GREENPOINT-GOLDMAN CORP.	
2018	Manhattan	388	GREENWICH STREET	0	 The Site Safety reported that a worker hurt his foot while using a chipping gun. The worker took a cab to urgent care 	No Dispatch			ALTERATION TYPE 1	121190503-01-AL	Other Construction Related Incidents	CITIGROUP TECHNOLOGY, INC.	TISHMAN CONSTRUCTION CORP
/2018	Queens	34-11	BEACH CHANNEL DRIVE	0	care. 1 The Site Safety Manager reported that a worker was dismantling a scaffold when the plank he was standing on broke and fills in text. The worker went to a hospital by ambulance. An ECB Violation for a failure to safeguard all persons and property affected by construction operations was issued.	ECB Violation	35285811N		NE	421094283	Worker Fell	NOT ON FILE	Chateau GC LLC
2018	Queens	160-08	JAMAICA AVENUE	0	1 The Site Safety Manger reported that a vehicle struck the flagman in the street. The Police Department responded to the incident. The worker wss taken to Jamaica Hospital.	No Dispatch					Other Construction Related Incidents	160 JAMAICA, LLC	
2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that an electrician was pulling his cart from the hoist when the handle on the cart became loose and the worker fell backwards to the floor, hurting his back. An ambulance was called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
2018	Brooklyn	500	GATES AVENUE	0	1 The Super reported that a mason was using a grinder for brick cutting when the grinder kicked back and the grinder's butt end (not the blade) hit the mason in the face. The mason suffered a bruise to his face and felt a little dizzy. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PCMH 500 GATES HOUSING DEVELOP	
2018	Brooklyn	340	EVERGREEN AVENUE	0	The Fire Department reported that a worker was hit in the head with a piece of rebar. Four ECB Violations and four DOB Violations were issued. A partial Stop Work Order was also issued. A Means and Methods and a Tool Box Talk must be provided.	ECB Violation	35300117X,118H,120R,121Z	020918BS04DH01,02,04,05			Material Fell	BUSHWICK REALTY HOLDINGS LLC	
2/2018	Bronx	2568	PARK AVENUE	0	1 The Site Safety Manager reported that a worker cut his knee while walking by rebar. The worker was taken to an area medical facility by a co-worker.	No Dispatch				220152484	Other Construction Related Incidents	2568 BRONX PARK LLC	STEVEN ALESSIO
12/2018	Brooklyn	135	EMERSON PLACE	0	1 The Site Safety Manager reported that during a stripping operation, a worker fell down from the sish floor and landed on top of the sidewalk sheet. The worker was found unconscious, but breathing. The worker was stored unconsciences to the stripping form. The worker was staken to a hospital by ambulance. An ECB Violation and a full Stop Work Order were issued. Three additional ECB Violations/OATH Summonses and three partial Stop Work Orders were issued by the Concrete Enforcement Unit.		35300065N				Worker Fell	PRATT INSTITUTE	
12/2018	Manhattan	11	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker was working in a man lift when he moved his body and twisted his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	THE MUSEUM OF MODERN ART	
2/2018	Manhattan	200	EAST 95 STREET	0	1 The Site Safety Manager reported that a worker pinched his finger while moving a steel beam on an "A"-Frame. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents		
2/2018	Manhattan	461	WEST 34 STREET	0	The worker went to urgent care. 1 The Site Safety Manager reported that a worker cut his left hand on metal studs. The worker was taken to an area hospital and received several stitches.	No Dispatch			ALT 1	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	EDWARD M GRUNWALD
3/2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manager reported that a worker entered the site from the outside of the mall area by the dirt parking area side, fell in ice that was mixed with dirt, and hurt his ankle. The worker went to urgent care.						Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	



ncident Date	Borough	Address Number	Street	Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/13/2018	Queens	80-08	135 STREET	0	2 The General Contractor reported that two workers were injured while growing when a pump hose got clogged with grout and blew into the worker's faces. The worker inde to un-clog the pump while twas in use. The two workers were taken to a hospital for treatment. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35309854r		ALT 1	420652378 AL	Mechanical Construction Equipment	BRIARWOOD MP LLC	PAV-LAK CONTRACTING INC
/13/2018	Queens	45-57	UNION STREET	0	¹ A DDB inspector reported that a worker was using the califield's asin to bring obtains with a flow when a rebar out aught on the stains and pulled the same worker down. The worker was experiencing aches in his body and went to a clinic the next day. This incident took piec on February 13, 2018, but was not reported until February 14, 2018. The building was a five story building with no permanent stairs. An EGB Volation and a full Stop Worker Order were issued for inadequate impress/ejress, an adequate supported scaffold, and the lack of internal stairs.	9	35299630L				Worker Fell	DEPARTMENT OF EDUCATION	
/15/2018	Brooklyn	1060	CLARKSON AVENUE	0	 The Site Safety Manager reported that a worker cut his arm with a saw while cutting wood. The worker was taken to a hospital by ambulance. 	No Dispatch			ALTERATION TYPE 2	302581347-01-EW-OT	Worker Fell	DEPARTMENT OF EDUCATION	ANSU CONSTRUCTION INC
2/15/2018	Manhattan	101	WEST 57 STREET	0		9	35308906P	021518CERDY04			Material Fell	101 WEST 57TH STREET HOTEL INV	
2/15/2018	Manhattan	42	WEST 33 STREET	0	 The Site Safety Manager reported that a worker was climbing off of a scaffold when he slipped and fell approximately two feet, injuring his shoulder. An ambulance was called. 	No Dispatch					Worker Fell	38-46 WEST 33 STREET, LLC	
2/15/2018	Queens	30-35	COLLEGE POINT BOULEVARD	0	A DOB inspector reported that a painter was on a scisso lift paining the area next to a roll down door sensor whe he activated the door, which caused another worker to get hit by the door. The worker had the wind knocked ou of him and was sent to a hospital. An ECB Violation and a partial Stop Work Order were issued for the failure to maintain sing experisions. The General Contractor at the site is to provide a Means and Methods.	t	35317705N				Other Construction Related Incidents	FEINSTEIN OP REALTY LLC	
2/16/2018	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a concrete worke was carrying a Doka form that was about 2 X 9 feet and 100 pounds when he slipped and fell. The worker complained of back pain. A DOB inspector responded to the incident and reported that no enforcement action was necessary, as the injury occurred as the result of a worker error.						Other Construction Related Incidents	SMITELL SPONSOR LLC	
2/16/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was lifting a piece of rebar when he claimed to have hurt his back. The worker walked up to an ambulance and the ambulance took him to a hospital.	No Dispatch			NEW BUILDING	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTRUCTION SERVICES L
//16/2018	Manhattan	38	HOWARD STREET	0	2 A DOB inspector reported that an inspector from Cole NY was performing an inspection of the building for façade local law. While inspecting the building, the inspector stepped out onto the fire escape became dislodged and fell to the ground, striking two pedestrians One of the pedestrians suffered all lie threatening injury, and the second pedestrian suffered all lie threatening injury, and the second pedestrian suffered all lie threatening injury, and the second pedestrian suffered all lie threatening injury. Advom. EMS was called. An ECB Violation, an DOB Violation, and an Immediate Emergency Declaration were issued.		35308908Z	021618CERDY01			Material Fell	434 BROADWAY PROPERTY INVESTOR	CANY Architecture & Engineering, DPC.
//16/2018	Queens	71-17	ROOSEVELT AVENUE	0	1 A DOB inspector reported that were four workers unloading bundles of rebar that were approximately forty five feet from a listlated truck when one of the workers lost control of the bundle and the bundle fiel on the leg or the unloading. The higher dworker suffered a broken right leg and was taken to a hospital. An ECB Volation and a partial Stop Work Coder were issued for a failure to maintain the safe operations and to stop all material handling, including deliveries. The General Contractor is to provide a safe Means and Methods, including equipment and Tool Box talks.	f			NEW BUILDING	420653000	Material Fell	ROOSEVELT PARC LLC	BRAVO BUILDERS LLC
2/19/2018	Manhattan	200	EAST 21 STREET	0	1 The Site Safety Manager reported that a worker dislocated his left shoulder when he lifted a bag of concrete onto it. The worker was taken to Mount Sinai Hospital by ambulance.	No Dispatch			NEW BUILDING	121190479-01-NB	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC



ncident Date	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
19/2018	Brooklyn	805	WASHINGTON AVENUE	0	1 A DOB inspector reported that a worker was walking close to a Bkotok while an Leasem was on the forks attached to the Bobcat when the Leasem moved and the worker's hand got caught between the Leasem and the Bobcat track. The worker suffered a fractured hand and was taken to an area hospital. The worker generiting the Bobcat was not trained by the employer, which created this situation and insignition and the Site Safety Manager was on Informed of the incident wolf. Zi202018, Four ECB Violations and a partial stop Work order were issued.	ECB Violation	35317732Z, 35317733K AND 35317736K		NEW BUILDING	321478548	Mechanical Construction Equipment	805 WASHINGTON AVE LLC	HAPPY LIVING DEVELOPMENT
19/2018	Brooklyn	211	SCHERMERHORN STREET	0	1 The Site Safety Manager reported that a worker rolled his ankle while moving material. The worker was taken to Brooklyn Hospital by EMS.				FRANK HEALEY	321196200-01-NB	Other Construction Related Incidents	211 SCHERMERHORN DEVELOPMENT L	OESTREICHER CONSTRUCTION
20/2018	Manhattan	115	DELANCY STREET	0	 The Site Safety Manager reported that a worker cut his finger while using a grinder. The worker went to urgent care. 	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
20/2018	Manhattan	425	PARK AVENUE	0	1 The Site Safety Manager reported that a worker fell from the fourth step of an "A"-Frame ladder. The worker complained of back pain. An ambulance was called.	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
/21/2018	Brooklyn	5718	2 AVENUE	0	A DOB inspector reported that a worker was pulling on one of the clips of a outrigger scaffold in order to install it properly. The worker pulled the clip hard, which caused the worker to slide down the plank and twist his arise streat and then work home. The formwork and outriggers were all built as per design. No enforcement was action necessary, as it was determined that the injury occurred as the result of a worker error.				ALTERATION-1	321192702	Worker Fell	NYU HOSPITALS CENTER	HUNTER ROBERTS CONSTRUCTION
21/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager has reported that a worker was climbing down an 'A'-Frame ladder when he slipped and fell about four feet. An ambulance took the worker to a hospital. The worker suffered a possible fractured elbow.						Worker Fell	SMITELL SPONSOR LLC	
/21/2018	Queens	131-11	FOWLER AVENUE	0	 The Site Safety Manager reported that a worker twisted his right wrist while bending rebars. A co-worker took him to a clinic. 	No Dispatch					Other Construction Related Incidents	131-05 HOLDING LLC	
21/2018	Queens	38-01	QUEENS BOULEVARD	0	1 The Site Safety Coordinator reported that a worker tripped on tape on a scaffold platform, which caused him to fail and twish his here. The worker was taken to urgent care. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard all persons and property.		35285820P		NB	421387626	Worker Fell	CURBCUT QUEENS BLVD LLC	Sordoni Construction Comp
22/2018	Staten Island	35 a	BAY STREET	0	1 The Site Safety Manager reported that a rebar installer slipped on a rebar floor and twisted his ankle. An ambulance was on site.	No Dispatch					Other Construction Related Incidents		
22/2018	Staten Island	2655	RICHMOND AVENUE	0		No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
/22/2018	Manhatlan	122	LEXINGTON AVENUE	0	The Police Department reported that two workers were making a delivery to the rod rate at the structure when one of the workers fell approximately eight to ten feet through an opening in the rod that was covered with a tap. The worker fell to the third floor. The worker suffered injuries to his back and neck and was transported to Bellevue Hospital with head and neck injuries. A full Stop Work Order thad been issued to the building on 4222015 and a Vacate Order was issued on 12222017. Two ECB Violations, and two DOB Violations were issued for the unlawful continuation of work while on the notice of a Stop Work Order and for a failure to safeguard.		35308861K & 35308860Z	022218CERTQ01 & 022218CERTQ02			Worker Fell	122-24 LEXINGTON AVECP	
22/2018	Brooklyn	19	KENT AVENUE	0	1 The Site Safety Manager reported that a worker walked into a pile of plywood and then felt discomfort in his upper torso and chest. An ambulance was called and the worker was transported to a hospital.				NEW BUILDING	320591944-01-NB	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
22/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker cut his finger while handling rebar. The worker was seen by the on-site medic and was sent to City M.D./urgent care.	No Dispatch					Other Construction Related Incidents	NYC HPD	
/23/2018	Queens	83-09	35 AVENUE	0	1 A DOB inspector reported that workers at apartment number B42 were lowering a piece of plywood that was approximately 2 X 5 from the louth floor free escape to the ground using a heavy thick rope in front of the building. According to the Projece Manager at the site and a bystander, the plywood slipped off of the rope and fell from the third floor level, string a young girl on the side of her head before landing on the ground. Marks from the failer word can site be seen on the ground where it landed. The injured young girl was transferred to New York Prospherein Hoppland I Queers with injuries to the side of her head. Three Aggrowated Level 2 ECB hore words and the plans, and for working without a kot not conforming to plans, and for working without a permit. 3 DOB Volations, and a full Stop Work Order were also issued.		35309174N, 35308325L & 35308326N	022318CERKC03, 022318CERKC04 & 022318CERKC05	ALTERATION TYPE 2	421548999-01-EW-OT	Material Fell	83-09 35TH REALTY LLC	MNR GROUP INC



cident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/2018	Manhattan	545	WEST 30 STREET	1 A DOB inspector reported that workers were using a 1 to unload window panels of a truck. While the full being taken into the building, one of the panels sid of the full and his worker's ank. An artbulance took it worker to a hospital. An ECB Violation for a failure to maintain aste operations and a partial Stop Work Ord were issued or all deliveries and material handing. Th General Contractor is to provide a Means and Method participation.	ull ECB Violation vas f of ee er	35317717K				Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
7/2018	Manhattan	685	FIRST AVENUE	0 1 The Site Safety Manage reported that a worker was working in a building when a couple of pieces of sheetrock fell over and onto his leg. An ambulance wa called to the site.						Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
28/2018	Manhattan	1227	BROADWAY	0 1 A DOB inspector reported that a tower crane was angaged with loading a four too piece of scattoding material on top of a trafer within the job site. After the load was lowered into pace, a worker began unbooki the rigging gear so that the crane could proceed within next lift. The gear was detached from the load and the crane hotisted up to clear the trailer and the loaded scatfolding when, ubeknowns to the worker, the rigging gear snagped the corner of the load that had just land which caused the load to flow or the side of the traile and bring the worker down, injuring him in the process The worker was found bleefact to be non-iffe threatening. Three ECB Violations and a partial Stop Work. Order were issued.	he ed, rr s. as	35225172L 35225171J & 35225172L		CN	CN 913/16	Mechanical Construction Equipment	YJL BROADWAY HOTEL LLC	BMNY CONTRACTING CORP
28/2018	Manhattan	2	PARK PLACE	0 1 The Site Safety Manager reported that a worker got d in his eye. The worker went to a hospital for treatment	ust No Dispatch					Other Construction Related Incidents	NOT ON FILE	
1/2018	Brooklyn	391	HOOPER STREET	A DOB inspector reported that heavy gauge 2 x 10 ceiling joists were delivered and placed on top of the Concrete Network Unit (CMA) and the set of the left he ceiling points together, which lead to the joist collapsing and knocking the worker off of the scaffold to the ground. joist landed on top of the worker as well. The worker was found dead on arrival. A DOB Violation and a full Stop Work Order were issued.	th ing The		030118BS01AS01			Other Construction Related Incidents	E&D MANAGEMENT GROUP LLC	
//2018	Queens	28-02	JACKSON AVENUE	I A DOB inspector reported that a panel of plywood this was about \$X\$ if elift rom the parapert of a sidewalk at and struck two pedestrians. One of the pedestrians suffered an injury in the shoulder area. The injured pedestrian injury in the shoulder area. The injured pedestrian is used for a failure to the sidewalk at the scene. An Aggravated Level 2 ECB Violation was issued for a failure to the sidewalk of the sidewalk back back marks the A particle Stop Work was also issued for a failure to maintain an inspection log; the sidewalk shed A particle Stop Work Orea was loss issued. The sidewalk shed company was sent to the s for repair work.	for p	35318105Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMPA
2018	Manhattan	685	1 AVENUE	0 1 The Site Safety Manager reported that a worker was pushing a mini container when the gate on the bottom a ramp swung and lacerated his right hand. The on-si medic put a band aid on the cut. An ambulance took t worker to a hospital.	te					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
2018	Manhattan	260	WEST 40 STREET	0 1 The Site Safety Manager reported that a worker was using a lade and cut his finger. The worker was patch up on-site, but then went to City M.D. where he receiv two to three stitches.	ed			NB - NEW BUILDING	121187394	Other Construction Related Incidents	PORT 40TH PARKING CORP	ZDG, LLC
2018	Manhattan	150	EAST 23 STREET	0 1 The Site Safery Manager reported that workers were carrying steel plates when one of the plates slipped a pinched one of the worker's left middle finger. The worker was transported to a hospital by ambulance.	nd			NB	121981748	Other Construction Related Incidents	154 EAST 23 LLC	W & L GROUP CONSTRUCTION
/2018	Manhattan	1912	1 AVENUE	0 1 The Site Safety Manager reported that a worker trippe and fell while carrying framing. EMS was called and th worker was transported to a hospital.	nd No Dispatch			NB	122879233	Worker Fell		PROCIDA CONSTRUCTION CORP
2018	Manhattan	396	BROADWAY	0 1 The Site Safety Manager reported that a worker dropp a piece of plywood on his foot. The worker left the site an ambulance.	ed No Dispatch			A1 - ALTERATION TYPE 1	120786417	Other Construction Related Incidents	BRIDGETON 396 BROADWAY FEE LLC	ANTHONY T. RINALDI
2018	Manhattan	425	WEST 18 STREET	1 The Site Safety Manager reported that a worker hurt h back while picking up a cement bag. An ambulance w called and the worker was transported to a hospital.	nis No Dispatch as			NB	122736762	Other Construction Related Incidents	NOT ON FILE	ARTIMUS CONSTRUCTION INC
/2018	Brooklyn	10	HURON STREET	The Site Safety Manager reported that there were two worknes that were doing sheetrock work together when one of the workers lost his gip on a piece of sheetroc that landed on the other worker's finger, causing a cu- ltude to the software of the software of the software that software which finger. This incident output with 35/2016, but was not reported to the Site Safety Manager or Construction Superintendent until 3/8/201	n k to					Other Construction Related Incidents	10 HURON FS CONDO LLC	



ncident Date	Borough	Address Numbe	r Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/2018	Queens	45-57	UNION STREET	0	1 A DOB inspector reported that a 16' X 8' size gate swung	ECB Violation	35317909P				Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
					out and hit a pedestrian that was walking by. The								
					pedestrian was a student that was approximately seven years old. The student was evaluated by a nurse.								
					years old. The student was evaluated by a hurse.								
018	Manhattan	2255	BROADWAY	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	2255 HOLDING LLC	
010	Maimatan	2235	BROADWAT		lifting a 2 X 3 X 10 wooden beam in the elevator pit when	1 Dispatch					Other Construction Related incidents		
					he hit himself in the face with the wooden beam. The								
					worker went to urgent care and then went to a hospital.								
					This incident occurred as a result of a worker error.								
2018	Bronx	2395	FREDERICK DOUGLASS BLVD	0	1 The Site Safety Manager reported that a pedestrian in a wheelchair fell over in a walkway due to a tripping hazard	ECB Violation	35300487N	030618BS10VP06			Other Construction Related Incidents		
					around a Con-Ed sewer cap. The pedestrian went to a	1							
					hospital by ambulance. A DOB inspector responded to								
					the incident, visited the site, and issued an ECB								
					Violation. The tripping hazard was corrected as of the time that the inspector was at the site.								
					une dat de inspector was at de site.								
2018	Brooklyn	416	KENT AVENUE	0	1 The Site Safety Manager reported that a worker slipped,	No Discotch				320622616	Other Construction Related Incidents	420 KENT AVENUE LLC	ZDG, LLC
010	Brooklyn	410	RENTAVENDE		fell, and hurt his arm. The worker was taken to a hospital					320022010	Other Construction Related incluents	420 KENT AVENDE EEG	200, 200
					for a check up.								
2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that an electrician was	s No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
					running a wire when he tripped on a piece of plywood								
					and skinned his right shin. The electrician went to a City M.D. for assistance.								
2018	Queens	147-40	ARCHER AVENUE	0		No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2010	ddoorio	141 40	intonent viende	Ŭ	plywood slid and hit a worker on the left knee while the	no biopatori							
					worker was stocking plywood on the floor. The worker								
					went to a clinic.								
2018	Queens	28-07	JACKSON AVENUE	0	1 A DOB inspector reported that there were two	ECB Violation	35318121Y-FAIL TO SAFEGUARD	030818BS02KA01	NB	420656873	Material Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
					electricians working on a scissor lift at the basement level when a temporary light fixture was accidentally								
					bumped and dislodged, causing it to fall approximately								
					five feet and strike a worker that was passing by on the								
					head and back. The electricians were working without a								
					controlled access zone below. The worker was found alert, but complained of head pain and went to urgent								
					care. An ECB Violation for a failure to safeguard was								
					issued, as well as a partial Stop Work Order for the								
					installation of electrical lighting work. A Means and								
					Methods must be provided.								
2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker slid and	No Dispatch					Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	
					hit his left knee as he was taking the stairs to his trailer. The worker was taken to a hospital for a check up.								
					I ne worker was taken to a nospital for a check up.								
2018	Manhattan	1059	3 AVENUE	0	1 The Site Safety Manager reported that a worker was	ECB Violation	35300269P	030918BS08MH01			Material Fell	63RD & 3RD NYC LLC	
					carrying a few formwork clamps that weight approximately 10-15 pounds and are about 18 feet long								
					approximately 10-15 pounds and are about 18 feet long								
					in length up the third floor steps when one of the clamps fell from his grip and hit the wrist of a mason that was								
					working in the basement, possibly breaking the mason's								
					wrist. An ambulance was called. An ECB Violation and a	1							
					partial Stop Work Order were issued for the unsafe								
					handling of materials. A DOB Violation was also issued. A Means and Methods will be provided for the safe								
					handling of form work materials.								
2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker as	ECB Violation	35286419N				Worker Fell	SMITELL SPONSOR LLC	
					carrying equipment when he slipped and fell. The worker	r							
					hit the back of his head and blacked out. The worker was	S							
					sent to Mount Sinai Hospital. A DOB inspector								
					responded and visited the site and reported that the worker slid on what look like an ice patch on the floor,								
					even through there was ice melt spread throughout the								
					are. An ECB Violation was issued for a failure to								
					maintain safe operations.								
2018	Manhattan	29	11 AVENUE	0	1 The Site Safety Manager reported that an iron worker was attempting to move a steel beam onto a dolly on his	No Dispatch					Other Construction Related Incidents	NYS PARKS & RECREATION	
					was attempting to move a steel beam onto a dolly on his own when the beam slid and hit his left knee. 911 was								
					called and the worker was taken to a hospital.								
2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reports that a worker pinched	No Dispatch					Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	
					his finger while cutting a Formica board with a circular								
					saw. The worker went to the emergency room on his								
/2018	Manhattan	500	WEST 33 STREET	0	1 The Site Safety Manager reported that an ironworker hur	t No Dispatch				-	Other Construction Related Incidents	NOT ON FILE	
,2010		300	ALOI 35 STILET	0	his right index finger while prying a cross brace. The	Cito Dispatch					Galer Construction Related incidents	NOT ON THE	
					worker was transported to Bellevue Hospital by								
					ambulance.								
/2018	Manhattan	125	GREENWICH STREET	0	1 A DOB inspector reported that a worker was lifting up a	No Action Necessary					Material Fell	VS 125 LLC	
					four foot section of form work when the worker								
					mishandled the form work, causing the form work to fall on his knee. An ambulance was called, it was								
					determined that the incident happened as a result of a								
					worker error and that no enforcement action was								
					necessary.								
2018	Manhattan	125	GREENWICH STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Worker Fell	VS 125 LLC	
					handling a roll of felt paper when he slipped backwards								
					and suffered a laceration to the left side of his forehead. The worker did not want an ambulance to be called and								
					went to a City M.D. instead.								
					,								



ncident Date	Borough	Address Number	Street	Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/12/2018	Manhattan	255	EAST HOUSTON STREET	0	1 The Site Safety Manager reported that a worker's finger						Other Construction Related Incidents	255 EAST HOUSTON OWNER LLC	
					got caught between two beams while he was pushing forwards beams on a truck. The worker was sent to								
/2018	Queens	150-13	89 AVENUE		Bellevue Hospital. 0 A DOB inspector reported that a worker was riding on the	DOB Vieleties		031318BS1201MC			Other Construction Related Incidents	88TH AVENUE OWNER LLC	
2016	Queens	150-13	89 AVENUE		back of a fork lift during a placement of bundle windows	BOB VIOLATION		031318B31201MC			Other Construction Related incidents	BOTH AVENUE OWNER LLC	
					in the storing garage. The bundle was 10' X 5' X 6' and								
					bounced up and down due to its size and weight. The								
					driver of the forklift heard a sound and then saw that the								
					worker who was riding on the back was on the floor. The								
					worker was found dead. There were no witnesses to the incident, and the incident is currently under police								
					investigation. The driver of the fork lift was found to be								
					not certified to operate a fork lift. The driver was in a								
					traumatized state and went to a hospital A DOB								
					Violation for a failure to safeguard and a Stop Work								
					Order were issued. ECB Violations are being prepared to	2							
					be served.								
2018	Brooklyn	3617	13 AVENUE		1 A DOB inspector reported that a worker lacerated his	ECB Vieleties	35318355R				Other Construction Related Incidents	37TH STREET HOLDINGS LLC	
2016	Brookiyn	3017	13 AVENUE	0	foot while driving a walk-behind saw to a container in	ECB VIOLATION	30316355K				Other Construction Related incidents	37TH STREET HOLDINGS LLC	
					order to park it. The worker was sent to a hospital. A an								
					ECB Violation was issued, as well as a partial Stop Work	c							
					Order on the use of the walk-behind saw. Manufacturer specifications must be provided.								
/2018	Manhattan	220	CENTRAL PARK SOUTH	0	1 The Site Safety Manager reported that an iron worker pinched his index finger while unloading a cart of steel.	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
					The worker went to a clinic to receive stitches for his								
2018	Brooklyn	225	4 AVENUE	0	finger. 1 A DOB inspector reported that workers were in the	ECB Violation	35309294H	031518CERDM01	NB	310086554	Material Fell	225 4TH AVENUE PROPERTY OWNER	TRM Construction
2010	Diodityn	110	4 AT ENDE		process of cleaning brick with an acid base solvent when		0000520411	do to to to be to bill of		010000004			
					some of the solvent fell into the eve of a female								
					pedestrian. The pedestrian had her eye rinsed out and was treated on the site. The pedestrian did not go to the								
					was treated on the site. The pedestrian did not go to the hospital. An Aggravated Level 2 ECB Violation for the								
					failure to safeguard all persons and property affected by								
					construction operations was issued, as well as a DOB								
					Violation and a partial Stop Work Order for façade work.								
					It was recommended that the BEST Squad perform a								
					follow up inspection for compliance and safety measures.								
2018	Queens	21-30	44 DRIVE	0	1 The Site Safety Manager reported that a piece of plywood fell from the first floor to the cellar due to the	ECB Violation	35318143P	031918BS02KA04			Material Fell	44TH DRIVE OWNER LLC	
					plywood fell from the first floor to the cellar due to the wind. The plywood landed on the cellar floor where it								
					then fell onto a worker, hurting the worker's shoulder.								
					This incident occurred on March 16, 2018, but the								
					Department Of Buildings was not notified until March 19,								
					2018, because the Construction Superintendent claimed								
					that he called the office on 3/16/2018 after 4:00 PM and that no one answered the phone. An ECB Violation was								
					issued for a failure to safeguard for not securing								
					materials during a weather advisory. A DOB Violation								
					and a partial Stop Work Order for all form work were also								
					issued. A Means and Methods for the securing of								
					materials during a weather advisory must be provided.								
2018	Manhattan	501	WEST 18 STREET	0	1 A DOB inspector reported that during excavation work, a	ECB Violation	35314141N		New Building	121191147	Excavation/Soil Work	18TH HIGHLINE ASSOCIATES, L.L.	Related Construction LLC
					worker was torching a hole in two steel "H" piles and was	5							
					laying side by side in order to sling and rig the pile when								
					the excavator that was being used moved, which caused								
					the worker's leg to become pinched between two piles.								
					The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was								
					okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was								
					issued for a failure to safeguard. A partial Stop Work								
					Order was issued to stop all movement and preperation								
					of steel piles. The contractor is to provide a Means and Methods for the safe movement of steel around the								
					Methods for the safe movement of steel around the construction site.								
/2018	Manhattan	220	CENTRAL PARK SOUTH	0	1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move	ECB Violation	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
					bags of cement down a ramp when the powered pallet								
					lack moved on its own and ran over the worker's left foot								
					The worker went to Roosevelt Hospital. A DOB inspector	r							
					responded to the incident and issued an ECB Violation for a failue to maintain unsafe equipment. A DOB								
					tor a failue to maintain unsafe equipment. A DOB Violation and a partial Stop Work Order for all work using								
					equipment to transport loads as the second floor north	,							
					of Tower Boulevard were also issued. The powered								
					pallet jack was found to have no inspection logs. An orientation and a Means and Methods must be provided.								
					orientation and a Means and Methods must be provided. The BEST Squad must be contacted for a re-inspection.								
					SECT OQUID MUST DO COMACIÓN A TE-ITSPECIÓN.								
2018	Brooklyn	416	KENT AVENUE	0	 The Site Safety Manager reported that at a twenty-two story new building under construction, a worker that was 	No Dispatch			NB	320622616	Worker Fell	420 KENT AVENUE LLC	ZDG, LLC
					story new building under construction, a worker that was on stilts performing plastering work on the eightteenth								
					floor fell backwards onto the floor. The worker hurt his								
					back, suffered a twisted knee, and complained of head								
					pain. An ambulance was called and the worker was								
					transported to Bellevue Hospital. The worker was awake and alert.								
							Page 11 of 33						



ident Date	Borough	Address Number					ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Brookiyn	1277	EAST 14 STREET		A competent person at the construction site reported that a worker slipped on a supported scatteriol and fell approximately six Ket, along with a few planks. The worker's foreman stated mat the worker drove to see a doctor on his own. A DOB inspector responded and visited the site and provind that the supported scatterior with not high probability of the planks, were not approximate that the site of the planks, were not apped to the support of the site of the planks, were not unlike locations. Two ECB Violations and a partial Stop Work Order for a supported scatfold were issued.		35285912M,35285913Y		NB	320597127	Worker Fell	1277 HOLDINGS LLC	Ray Builders Inc.
2018	Manhattan	40	CLERMONT AVE		The Site Safety Manager reported that a carpenter was working on an "A"-Frame ladder when he missed the fifth step of the ladder and fell. An ambulance came and took the worker to a hospital.						Worker Fell		
2018	Manhattan	590	EAST 83 STREET		The Site Safety Manager reported that a worker tripped and jammed his finger. An ambulance took the worker to a hospital.	No Dispatch			NEW BUILDING	121190987-01-NB	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
2018	Brooklyn	10	MONTIETH STREET	0 1	The Site Super reported that a worker attempted to jump over a fence and fell. The worker was taken to a hospital by ambulance.	No Dispatch			NEW BUILDING	320622750-01-NB	Worker Fell	BUSHWICK HOLDINGS I LLC	GALAXY DEVELOPERS LLC
2018	Manhattan	108	EAST 89 STREET	0 1	The Site Safety Manage reported that a worker hurt his shoulder while installing a pipe scaffold. The worker went to a City M.D. to get checked.	No Dispatch			ALTERATION TYPE 1	122988623-01-AL	Worker Fell		E.W. HOWELL CO, LLC
0/2018	Queens	43-12	HUNTER STREET	0 1	A DOB inspector reported that contractors were in the process of liting a section of steel casisson in order to set it on a diff regional source that the shard prinched between the caisson and a steel hook. The worker was aliest and awake and was taken to a nearly hospital by a taka. The extent of the injury to the worker's hand was not howm as of the time of inspection. An ECG Wolation for a failure to saleguard and an ECB Wolation for there being no logs on site were issued, as well as a full Stope Work Order for the entire site. The contractor at the site was instructed to provide a Means and Methods for sale ple installation.		35314355z 35314356k		NB	420659530	Mechanical Construction Equipment	43-12 HUNTER LLC	Judy y Lee
018	Bronx	2028	CRESTON AVENUE		The Site Safety Manager reported that at an eleven story new building under construction, a worker was handling concrete out of a mixer when cement splashed into the worker's right eye. The worker was alert and awake and was taken to Lincoln Hospital for treatment.	No Dispatch			NB	220392858	Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MNGMT
2018	Manhattan	650	5 AVENUE		The Site Safety Manager reported that a worker was working with temporary electrical wirting on the second floor when a 480-oth wirte touched an I-Beam, which caused an ARC flash. The worker suffered an injury to its eyes and was taken to a hospital. A DOB inspector determined that there was no enforcement acton necessary.	No Action Necessary			Electrical	M00016968	Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
018	Brooklyn	1835	STERLING PLACE		The Construction Superintendent reported that a worker slipped off of an "A-Frame ladder while coming down from the ladder. The worker suffered a minor laceration to the head. The worker was found conscious and an ambulance was called.	No Dispatch					Worker Fell	NOT ON FILE	
/2018	Manhattan	115	DELANCY STREET		The Site Safety Manager reported that a worker was cleaning around a Cort Edison vault when he lifed an unmarked piece of phywood hat was covinnig the vault, hipped inn a shaft, and fell approximately eight to nine was alert and awakes and was taken to Belinus Hegglin. An ECB Violation for a failure to safeguard was issued, as well as a 100 violation and a partial Step Work Order for all exterior work at the ground floor at exopoure times. Protections around the vaults at the ground level must be provided. An updated Means and Methods and Tool Box Taik must be provided.		ECB#35317775Z -FAIL TO SAFEGUARD	032318BSO3GD01	NB	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
8/2018	Manhattan	40	10 AVENUE		The Site Safety Manager reported that an electrician was climbing up the rebar cage to reach the electrical conduit when he slipped, fell two feet, and landed on his right ankle. The electrician was sent to a clinic.	No Dispatch					Worker Fell	40-56 TENTH OWNER LLC	
/2018	Manhattan	1865	BROADWAY		The Site Safety Manager reported that a worker was cutting metal studs when he cut the top of his hand with a chop saw. The worker went to the emergency room with another worker. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
2018	Brooklyn	19	INDIA STREET		The Site Safety Manager reported that a worker was moving windows when he tripped, fell three steps, and hit the back of his neck on a cinderblock. The worker was alert and responsive and was taken to Bellevue Hospital.	No Dispatch			NEW BUILDING	310234207-01-NB	Worker Fell	145 WEST STREET LLC	NOBLE CONSTRUCTION GR LLC
2018	Brooklyn	101	PENNSYLVANIA AVENUE	0 1	The Construction Superintendent reported that a worker was testing a refrigerant line when the line burst, causing discomfort to the worker's ears. A co-worker drove the injured worker to a hospital.	No Dispatch			Alt 1	320622894	Other Construction Related Incidents	ATLANTIC 2644, LLC	CAULDWELL WINGATE CO LLC



cident Date	Borough	Address Numbe	er Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/2018	Manhattan	250	SOUTH STREET		1 A DOB inspector reported that a worker was bringing a scaffold down when a gust of wind moved the platform out of the building. The worker stuck his hand out to prevent the impact against the building, but hurt his shoulder and back in the process. The worker was taken	No Action Necessary			NB	121185528	Scaffold/Shed/Fence/Shoring/Installation		Lend Lease (US) Construct
					to a hospital where he was in stable condition. It was determined that no enforcement action was necessary, as the suspended scaffold was found to be in compliance with approed drawings, the current notification and installation tetter from the engineer was onsite, and all logs were in order.								
5/2018	Manhattan	420	EAST 54 STREET	0	1 The Site Safety Manager reported that the building owner's personal driver had his foot struck by a forkfit. The injurce person was taken to a hospital. A DOB inspector reported that only one flag person was used when moving the forkfit and net the injurce person walked into a control on access zone when he had his foot struck by the forkfit. An ECB Violation was issued for a failure to safeguard. A DOB Violation and a partial Stop Work Order were also issued. A Means and Methods and Tool Box Talks will be provided by the General Contractor at the site for safe delivery operations and for the proper amount of flaggers.	ECB Violation	35317760N	032618BSo6GD01			Other Construction Related Incidents	RIVER TOWER OWNER, LLC	
/2018	Manhattan	432	EAST 14 STREET	0	1 The Construction Superintendent reported that a worker was pushing a mini container when she slipped and hit her knee. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	EAST 14TH STREET OWNERS LLC	
3/2018	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that a worker got his hand jammed between two stripping panels. A foreman took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
8/2018	Brooklyn	505	PACIFIC STREET	0	 The Site Safety Manager reported that a worker slipped with a grinder and cut his face. An ambulance transported the worker to a hospital. 	No Dispatch			NEW BUILDING	320909004-01-NB	Other Construction Related Incidents	PVII HSC ATLANTIC LLC	TRITON CONSTRUCTION CO.,
0/2018	Manhattan	265	WEST 114 STREET	0		ECB Violation	35286045H		Alt 1	121189668	Material Fell	TRINITY WEST HARLEM PHASE TWO	Mega Contracting Gp LLC
D18	Queens	22-06	31 STREET	0	1 A competent person at the site reported that a worker that was coming into the site slipped on snow and injurce his knee. The worker went to see his doctor for a check up. There was a snowstorm in progress as of the time of the incident.	(·					Other Construction Related Incidents	DITMARS 31ST STREET ASSOCIATES	
018	Staten Island	2655	RICHMOND AVENUE	0	1 A DOB inspector reported that there were workers that were moving a wooden ramp that was about 4 X 8 X 20. When the ramp was in a vertical position, one 2 X 4 fell onto the hand of one of the workers. The worker want to urgent care. An EC8 Violation and a partial Stop Work Order (PSWO) were issued for all use of ramps. A Means and Methods and the design drawing must be provided.		36327362X				Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
2018	Bronx	2681	MARION AVENUE	0	1 A DOB inspector reported that a flagger was signaling for deliveries for traffic on the street when a cab driver tride to manever around a corner and ran over the flagger's foot. The flagger went to a hospital with a co-worker in a mbulance. The inspector determined that there was no enforcement action necessary, as the flagger was certified and a delivery Means and Methods was at the site.						Other Construction Related Incidents	PCMH MARION AVENUE HOUSING DEV	
2018	Bronx	2760	BRIGGS AVENUE	0	1 The Site Safety Manager reported that a worker slipped on plywood that had snow on it. The worker claimed to have burth is wisk while trying to brace himself after slipping. The worker went to a doctor on his own. This incident occurred in the morning, but the worker wated doctor. A DOB inspector valued the site and reported the there were no withestase to the worker slipping and that there were now withestase to the worker slipping and that there were now write worker wated resident to the slip could not be determined. Because of this, no enforcement action was deemed necessary.	t					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker slipped on a wet surface and fell on his hand. The worker went to a City M.D.	,					Worker Fell	NYC HPD	
3/2018	Brooklyn	422	FULTON STREET	0	 The Site Safety Manager reported that a security guard tripped and fell. The security guard was taken to a hospital as a precaution. 	No Dispatch			ALT 1	320908899	Other Construction Related Incidents	NOT ON FILE	TRANSPARENT CONSTRUCTION



ncident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/4/2018	Brooklyn	5615	7 AVENUE	0	2 The NYPD requested that an inspection please be performed because a construction fence field at the site. DOB inspector responded and visited the site and reported that the job site fence at exposure one had collapsed onto the public sidewalk. There were two injuries reported, a mother and a doughter. The mother and daughter were both taken to an area hospital. All fencing and devise at the site has been removed and made safe against the wind. An Aggravated Level 2 EC Violation was issued for a failure to safeguard. A DOB Violation and a full Stop Work Order were also issued. This incident was reported under incident Number 25737. Incident Number 25737 was deleted by accident and incident Number 25473 was created in its place.	в	35323275N	040418CERCM02	Alteration 1	320516152	Other Construction Related Incidents	SIU PING	GUO Z HUANG/NEWLAND CONSTRUCTION
1/4/2018	Manhattan	500	WEST 33 STREET	0	1 The Safety Director reported that a worker slipped and hit her tailbone while againing off of a scissor lift. An ambulance was called and transported the worker to a hospital. A DOB inspector visited the site and issued an ECB Violation and a partial Stop Work Order on all use of scissor lifts. The General Contractor is to provide training.		35327428N				Other Construction Related Incidents	NOT ON FILE	
1/5/2018	Manhattan	4	WEST 37 STREET	0	1 The Site Safety Manager reported that a plumber was found dead on the fourth floor of a framed out empty room. There were no tools and no ladder found on the scene. A DOB Inspector responded to the incident and visited the site, and reported that the worker suffered a possible heart attack and was revived with a faint pulse No enforcement action was necessary.						Other Construction Related Incidents	4 WEST 37TH STREET LLC	
1/6/2018	Manhattan	125	GREENWICH STREET	0	1 The Site Safety Manager reported that a worker hit himself in the face while stripping forms. The worker wa driven to a City M.D.				NEW BUILDING	121183799-01-NB	Other Construction Related Incidents	VS 125 LLC	PLAZA CONSTRUCTION LLC
J/9/2018	Brooklyn	231	AINSLIE STREET	0	1 A DOB inspector reported that, according to a worker that was at the site, the owner of the construction company at the site was on a pipe scaffold inspecting brick work that was done when led the lost his balance and fired to grab a bike rack on the rear of the scaffold. The bike rack was not properly secured and gave way, causing the owner to fall eight teet from the pipe scaffold that was on to of the sidewalk hand deck. The owner that was not poor the scaffold. The sidewalk shed deck, and the pipe scaffold was not tably planked, did n have any mailing, and dd not have a life ine. Two EOB Violations, two DOB Violations, wor to ball ybalawed, did n have any naling, and dd not have a life ine. Two Croft (FSWQ) were issued for the failure to safeguard all persons and properly, for the supported scaffold on top of the shed not being maintained as per code, nor work without permit being performed, and for brick exterior work that exceeded the area that does not require a permit.	d st	35323246y	040918CERDF03 & 040918CERDF04			Worker Fell	ST OONO DE TEGGIANO C	
1/9/2018	Brooklyn	420	KENT AVENUE	0	1 The Site Safety Manager reported that a steamfitter cut his finger while putting coupling on a pipe. 911 was called and the worker was taken to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	420 KENT AVENUE LLC	
1/9/2018	Manhattan	11	WEST 53 STREET	0	¹ The Construction Support renderin reported that a worker has on a action of like and was trying to gain access in into person. The worker's hand was on the handrail of the accissor if and his hand og point and between the handrai and the hanging door of the plenum. The worker's hand was cut and the worker went to a hospital for a checkup	1			ALTERATION-1	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	TURNER CONSTRUCTION CO
1/9/2018	Manhattan	15	WEST 25 STREET	0	A DDB inspector reported that a worker was using a hol saw that jammed. The Construction Superinteredent hole saw evaluation of the construction Superinteredent hole saw evaluation of the saw evaluation and and pushed the Construction Superintendent down, causing him to fail approximately eliven flet. The Construction Superintendent was taken to a hospital in serious condition. The Construction Superintendent is now stable, but suffered a brain ripury. An ECB Violaton a DOB Violation, and a full Stop Work Order (FSWO) were issued for a failure to safeguard during construction operations, as the Construction Superintendent fell in a location where there were no guardfails installed.	ı, n	35323475H	040918CERND01	ALTERATION TYPE 2	123203069-01-EW-OT	Worker Fell	ST SAVA CATHEDRAL	G.P.J. O'DONOGHUE CONTRAC
1/9/2018	Manhattan	25	PARK ROW	0	1 The Site Safety Manager reported that a hoist installer got the tip of his finger crushed while working on the						Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	
					hoist when the gate came down. The worker was taken to the emergency room.								



cident Date	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Manhattan	420	EAST 54 STREET	0	I A DOB inspector reported that there were three workers working on the thirty seventh floor doing interior demolition work and removing debris. There was an approximate 27 X27 comparing in the floor that was not properly covered, as a door from the demolition work was used to cover the hole and the hole was not proper- duced to the hole and the hole was not proper- door, unaware of the hole undemeath it, and fell through the opening to the hirty said floor. The worker was sent	,	35317792K, 35317793M		ALTERATION 2	122939357	Worker Fell	RIVER TOWER OWNER, LLC	VECTOR BUILDING CORP
					to a hospital for a checkup. Follow up information regarding the injured vorker is not currently available. Two ECB Violations were issued for the failure to maintain safety measures and for inadequate housekeeping. A full Stop Work Order was also issued. The GC is to provide a Marea and Methods for the safe operation of the job, including the protection of empty shafts and floor openings.								
2018	Queens	123-30	ROOSEVELT AVENUE	0	 The Site Safety Manager reported that a worker tripped on a curb and twisted his ankle while carrying a panel. An ambulance was called. 	No Dispatch					Other Construction Related Incidents	NYC PARKS	
2018	Queens	147-40	ARCHER AVENUE	0	 The Site Safety Manager reported that a worker stepped on a tie-wire that was used for rebar work and the tie- wire punctured his boot and foot. The worker went to see a doctor on his own. 	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/2018	Manhattan	150	5 AVENUE	0	 The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taken to a hospital by an ambulance. 	No Dispatch			ALTERATION TYPE 1	122700292-01-AL	Worker Fell	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
/2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that a worker was on a six foot ladder when he missed the second rung of the ladder while coming down from it and fell backwards and hit his head. The worker went to a hospital with his shop steward.						Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker was stripping form work when a dust particle got between his safety glasses and irritated his eye. The worker went to a nearby City M.D.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/2018	Bronx	600	BERGEN ÄVENUE	0	1 The Site Safety Manager reported that a worker was pumping grout to ite backs when the hose clogged. When the worker opened up the hose clamps to clean the hose, the worker got grout in his eyes. The worker did not realize that pressure had built up when he removed the hose clamps. The worker was taken to a Crty M.D. and was then transferred to an emergency room at Lincoln Hospital.	ECB Violation	35314470y		NB	220151868	Mechanical Construction Equipment	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST.DEVELP.
2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker was walking on the second floor when he stepped on a nail. The worker went to get a tetanus shot.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manger reported that a worker twisted his knee while climbing down from a machine. The worker was driven to the emergency room.	No Dispatch			NEW BUILDING	520135675-01-NB	Worker Fell	MACY'S RETAIL HOLDINGS, INC.	AURORA CONTRACTORS INC
/2018	Bronx	2044	WESTCHESTER AVENUE	0	The Project Manager at the site reported that a masory worker was loging contexticates, when he fiel of a magnetic sector of the site of the site of the site of the height. The worker landed on this back and appeared to be in stable containo, but refused to talk to anyone until an ambulance arrived. The worker was taken to Jacobi Medical Center. A DOB Inspector responded and visited the site and determined that no enforcement action was necessary, as the supported scaffold was found to be structurally sound with a guard rail system in place.		NA		NB	220152572	Worker Feil	HP WESTCHESTER MEWS HOUSING DE	Procida Construction Corp
2018	Manhattan	20	BROAD STREET	0	1 The Site Safety Manager reported that a worker was pushing a mini-container through a wall opening when he pinched his pinky finger. The worker left the site to see a doctor for treatment.	No Dispatch					Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.	
2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was cutting boxes with a box cutter when he cut his left thumb. The worker walked to urgent care.	No Dispatch			ALTERATION TYPE 1	121324343-01-AL	Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	CNY CONSTRUCTION LLC
/2018	Brooklyn	50	COURT STREET	0	DOB's Emergency Response Team was informed that a sidewaik shell was in the process of being dismantied when a partial collapse occurred at the corner of Court Street and Joatemon Street, Approximately twenty linea feet of the sidewaik thed collapsed. Two pedestrians and one worker suffered non-tile threatening injuries and were sent to Lutheran Hospital. The remaining unaffected parts of the sidewaik shed were removed. The Department Of Transportation replaced the cross waik light at the site. An Aggravated Level 2 ECB Violation was issued for a failure to asfeguard all persons and properly affected by construction operations. A DOB Violation was also issued.	r	35323276P	041418CERCM01	Alt 3 - SH	321426774	Scaffold/Shed/Fence/Shoring/Installation	50 COURT STREET ASSOCIATES	NEW FORCE CONSTRUCTION CO
/2018	Manhattan	130	EAST 82 STREET	0	1 The Site Safety Manager reported that a worker accidentally ran a screw into his hand while screwing screws during duct work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	134 EAST 82 LLC	
/2018	Brooklyn	856	WASHINGTON AVENUE	0	1 The Site Safety Manager reported that a worker was drilling a core hole in a deck slab when the drill kicked back and the base of the drill hit him on the side of his	No Dispatch					Other Construction Related Incidents	856 WASHINGTON OWNER LLC	



ncident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/17/2018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker slipped while going down the stairs. There were no witnesses to	No Dispatch					Other Construction Related Incidents	NYC DSBS	
					the worker slipping, and the stairs were free of debris. An								
					ambulance was called. The worker was okay, but walked	1							
					to the ambulance when the ambulance arrived at the site and went to a hospital.								
17/2018	Brooklyn	1900	PARK PLACE	0	1 The Site Safety Manager reported that a worker strained	No Dispatch					Other Construction Related Incidents	HABITAT FOR HUMANITY LATENT TH	
					his lower back while picking up a cement block. An ambulance was called.								
18/2018	Brooklyn	25	EAST 19 STREET	0	1 The Site Safety Manager reported that a worker was	ECB Violation	35323790H		Alt	340452520	Worker Fell	EBE HOLDING LLC	CS Bridge Corp
10/2010	brooklyn	20	ENOT TO OTTLEET	Ŭ	passing an I-Beam down from a sidewalk shed when he	LOD VIOLUION	0002070011		7	040402020			Co Bridge Corp
					lost his footing and fell about sixteen feet to the ground. The worker was wearing a harness that as not attached								
					to anything. The worker was found awake and speaking								
					and was taken to a hospital. An ECB Violation was								
					issued for a failure to safeguard persons and property.								
18/2018	Manhattan	220	CENTRAL PARK SOUTH	0	1 The Site Safety Manager reported that a worker cut his						Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
					finger when another worker closed a door on his hand by accident. A co-worker took the injured worker to a								
					hospital.								
18/2018	Queens	71-17	ROOSEVELT AVENUE	0	1 The Site Safety Manager reported that a worker sprained his back while carrying steel form. The worker went to a	No Dispatch					Other Construction Related Incidents	ROOSEVELT PARC LLC	
					his back while carrying steel form. The worker went to a hospital by ambulance for observation.								
18/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker hurt his	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
					shoulder when he picked up a bundle of threaded rods. The worker went to urgent care on his own.								
					-								
19/2018	Queens	147-40	ARCHER AVENUE	0		No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
					conducting a survey and was wearing proper footwear when he stepped onto a nail that punctured his foot. The								
					worker went to urgent care for a tetanus shot.								
19/2018	Manhattan	70	VESTRY STREET	0	1 The Site Safety Manager reserved that a works	No Dispatch					Other Construction Related Incidents	BRIDGE LAND VESTRY LLC	
10/2018	ware ditter	10	VLOIRTOIREET	0	1 The Site Safety Manager reported that a worker was installing 3' X 6" stone at the base of a building when his	IND DISPAICH					Strier Construction Related incidents	DIVIDUE LAIND VESTRY LLC	
					knee gave out, causing the worker to fall onto his knee.								
					An ambulance was called.								
19/2018	Manhattan	112	WEST 25 STREET	0	1 The Site Safety Manager reported that a subcontractor	No Dispatch			NEW BUILDING	121187214	Material Fell	LAM GEN 25 LLC	FLINTLOCK CONSTR SVCS INC
					was carrying a door from a truck when the door fell and								
					leaned on the subcontractor's right knee. The worker did not suffer a visible injury, but was in pain. An ambulance								
					transported the worker to a hospital for a check up.								
/19/2018	Brooklyn	422	FULTON STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
10/2010	broadyn	722	i del dit ditteel	Ŭ	performing demolition work on the roof of a building	No Dispatori						NOT ON THEE	
					when he felt pain in his back while lifting a barrel. An ambulance was called								
/19/2018	Bronx	545	EAST 166 STREET	1	0 The New York City Police Department reported that a	ECB Violation	38259262J	042018E2607B01			Mechanical Construction Equipment	545 E. 166TH STREET HDFC	
					worker was hit by a hoist. A worker was on the eighth								
					floor securing a piece of wingwall when he stepped up onto a bucket to look over the gate while trying to								
					securing plywood. The hoist was on the floor above the								
					worker and the hoist came down at the same time that the worker was leaning over the gate. The worker was								
					struck in the head and succumbed to his injuries. An								
					Aggravated Level 2 ECB Violation was issued for the unsafe or improper use of hoist equipment.								
20/2018	Manhattan	45	PARK PLACE	0	1 The Site Safety Manager reported that a carpenter	ECB Violation	35326676H		NEW BUILDING	121185635	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
					foreman was securing a formwork panel for the shear								
					wall and was repositioning his retractable device with both hooks in one anchor point when the insert gave								
					way, causing the foreman to fall about ten feet								
					backwards. The foreman was taken to a hospital.								
20/2018	Manhattan	500	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was	No Action Moconess			NB	1211192618	Worker Fell	ERY NORTH TOWER RHC TENANT LLC	Roger & Sons Constrate Inc.
20/2010	The state of the s	500	NEO. 33 OTREET	0	climbing up a baker's scaffold when he lost his grip on	No Action Necessary				1211182010		ERT RORTH TOWER RIG TENANT ELC	Nogor & Sona Concrete Inc
					the second rung of the ladder and fell about two feet. The worker rolled over onto a bucket and suffered an								
					injury to his ribs. A DOB inspector responded and visited								
					the site and reported that no enforcement action was necessary, as the necessary safety measures were								
					provided at the site. It was deternined that the incident								
					occurred due to a worker's error.								
23/2018	Manhattan	400	WEST 61 STREET	0	1 The Site Safety Manager reported that at a thrity eight story new building under construction, a plumber was	No Action Necessary			121193181	NB	Worker Fell	RCB1 NOMINEE LLC	TISHMAN CONSTRUCTION CORP
					placing a pipe into hangers when the plumber fell off of a								
					ladder. There were no witnesses to the height of the fall, and the plumber claimed to have fallen approximately								
					between five and seven feet. The plumber was found								
					alert, awake, and complaining of pain in his hip. The								
					plumber was taken to St. Luke's Hospital by ambulance. A DOB inspector responded and visited the site and								
					determined that there was no enforcement action								
					necessary, as the fall occurred as the result of a worker's error.								
	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker on the	No Dispatch				-	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
23/2019	autoria	147-40	ANOTEN AVENUE	0	first floor bumped his knee on a reshore tripod. The worker went to a City M.D.	no piapaich					Surer Consulucion Related Incluents	Samora noosing Dev. Fund CO	
23/2018													
23/2018	-	-			worker went to a City M.D.								
23/2018 24/2018	Brooklyn	540	FULTON STREET	0	 worker went to a City M.D. The Site Safety Manager reported that an iron worker pinched his finger while unloading steel rebar from a 	No Dispatch					Other Construction Related Incidents	540 FULTON ASSOCIATES	



	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	461	WEST 34 STREET	0	1 The Site Safety Manager reported that a worker was on the twenty eighth floor of a twenty nine story new building	No Dispatch			NB	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	ATRIA BUILDERS LLC
					and was cutting sheetrock and metal stud for electrical work when he suffered a cut to his hand. A reciprocal blade jammed and the worker's hand got caught. The worker was found awake and alert and was taken to a nearby hospital.								
018	Manhattan	225	BOWERY	0	It was reported that there were workers that were moving materials on the roof. When the workers moved a metal piece together, one of the worker's right hand got caught	No Dispatch				121862751	Worker Fell	VNAA BOWERY LLC	AEH-VSLV, LLC
					in the pinch point. The worker suffered a scrape to his right hand. An ambulance was called to the site. The worker received stitches at Mount Sinai Hospital.								
2018	Manhattan	22	NORTH LOOP ROAD	0	1 The Site Safety Manager reported that a worker hit his left hand with a hammer. The worker went to urgent care.						Other Construction Related Incidents		
2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that at a fifty seven story building that was under construction, a worker was cutting metal with a grinder when he cut this fielt shin. The worker was conscious and alert and walked to New York Presbyterian Hospital.					121290085	Other Construction Related Incidents	NOT ON FILE	AHEARN-HOLTZMAN, INC
2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that a worker was coming down the stairs on a scalfold when he slid down the stair riser. The worker went to a City M.D.	No Dispatch					Worker Fell	95TH AND THIRD LLC	
/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that during concrete operations, a laborer was removing concrete key when his finger got scratched between rebar. The worker was working alone and scratched his finger while reaching into formwork. The worker want to a City M.D. and returned to work in two days.	No Dispatch			NB	321197478	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker struck his left thumb with a hammer while hammering a nail. The worker took himself to a City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a worker was shaking out steel at the street level when he pinched his finger between a two by four and a steel beam. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	THE SALVATION ARMY	
2018	Manhattan	1059	3 AVENUE	0	The Site Safety Manager reported that a pedestrian verto over a marp in front of the site, siteped/tripped on damaged mesh, and fell. The pedestrian suffered an injury to her left ellow and was taken to a hospital. A DOB inspector reponded and visited the site and reported that the General Contractor at the site failed to maintain the pedestrian walkway that caused the incident. An Aggravitatel Level 2 EOB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued on all activities in the occupied lane next to the sidewalk head. The General Contractor is to maintain the sidewalk nearus that its free of all tripping hazards.	ECB Violation	35318046N				Other Construction Related Incidents	63RD & 3RD NYCLLC	
2018	Manhattan	130	WILLIAM STREET	0	1 The Say Safety Manager reported that a worker was thermpring to be a garpenner when the accidentally walling to be any profile of a hommer and got hit he forehead by the harar. The worker was taken to New York Presbyteran Hospital and was no stable condition. A DOE inspector responded and visited the site and determined that no enforcement action was necessary, as the incident occurred as a result of a worker's error.	No Action Necessary			NB	121192903	Other Construction Related Incidents		GILBANE RESIDENTIAL CONST
/2018	Manhattan	425	PARK AVENUE	0	1 A DOB inspector reported that masons were finishing concrete pouring pads on the sixeeenth floor when a worker that was working with the masons removed the masons removed the masons removed the masons removed the subtract dots the sear and complianced of head and neck pain. The worker was taken to Cornel University Hospital for observation. Two ECE Violations were issued on these being no design drawings for floor openings present and for the failure to maintain safety operations. Two partial Stop Work Orders (PSWO) were issued on all work within the fleet of all floor coverings on all floors and for the floor coverings being not properly socured. Two DOE Violations were also issued. A Neans and Methods for the installation of floor coverings must be provided.		35326636N / 37P	043018BS05GD01/02			Worker Fell	T-C 425 PARK AVENUE, LLC	
2018	Manhattan	540	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker suffered a cut finger. An ambulance was called.	No Dispatch			NEW BUILDING	121191968-01-NB	Other Construction Related Incidents	CLINTON HOUSING DEVELOPMENT	MEGA CONTRACTING GP LLC
2018	Manhattan	390	MADISON AVENUE	0	a Coll inger. An antibulance was cared. 1 The Site Safery Manager reported that a worker on the first floor stepped up on a few concrete masonry unit blocks when he fell approximately three feet off of the blocks and landed on a metal plate. EMS was called and transported the worker to a hospital.						Worker Fell	COMPTROLLER OF NY STATE	
2018	Manhattan	222	EAST 41 STREET	0	1 The Site Safety Manager reported that a worker was installing metal trim when a cut piece fell down and lacerated his wrist. The worker was sent to a hospital.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	



	Borough	Address Number		Fatalities Injuri	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Brooklyn	1277	EAST 14 STREET	0	1 The Construction Superintendent reported that a plumber was cutting a metal stud to get to a pipe when	No Dispatch					Other Construction Related Incidents	1277 HOLDINGS LLC	
					he cut his arm on the stud. An ambulance was called.								
18	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker was	No Action Necessary			NB	321190563	Other Construction Related Incidents	NYC DSBS	GILBANE BUILDING COMPANY
					walking back from a coffee truck when he trpped, fell, and hit his head. The worker was found conscious and								
					alert. An ambulance was called. A DOB inspector								
					responded to the incident and visited the site and found no evidence of debris or tripping hazards, as well as no								
					violating conditions. No enforcement action was								
					necessary.								
018	Manhattan	10	VANDERBILT AVENUE	0	1 The Site Safety Manager reported that a latherer was coming down from a rebar cage when he missed his last	at					Worker Fell	ONE VANDERBILT OWNER LLC	
					step, fell backwards, and hurt his ankle. The worker we	nt							
					to a hospital by ambulance. It was reported that the worker suffered a broken ankle. A DOB inspector								
					responded and visited the site and reported that the worker misstepped during a rebar operation, and that the	•							
					operation was proceeding according to the site plan. No enforcement action was deemed necessary.	Ē.							
					enforcement action was deemed necessary.								
018	Manhattan	320	EAST 43 STREET	0	1 The Site Safety Manager reported that a worker was cleaning near the dumpster in the basement C-Level	No Dispatch					Other Construction Related Incidents	FORD FOUNDATION	
					area when he hit his lower leg on a dumpster. The								
					worker was cut, but the bleeding was stopped. The worker does not know how he hurt himself. An								
					ambulance was called.								
018	Brooklyn	10	HURON STREET	0	1 The Site Safety Manager reported that a worker cut the skin of his finger on a table saw. The worker went to a	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
	0				hospital with a co-worker.						010		
2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker got a spark in his eye under his safety glasses during a	NO Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
					grinding operation. The worker went to a hospital on his own.								
2018	Queens	36-18	MAIN STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Worker Fell	134-22 35TH AVE., LLC	
					coming down off of a ladder when he lost his balance and grabbed onto a metal stud, causing a cut to two of								
					his fingers. The worker went to urgent care.								
2018	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that a worker sliped	No Dispatch					Other Construction Related Incidents	40-56 TENTH OWNER LLC	
					on rebar and hurt his wrist. The worker went to a City M.D.								
018	Manhattan	308	WEST 133 STREET	0	1 The Site Safety Manager reported that a worker was caulking a window when he fell from a baker scaffold ar	ECB Violation	35323933X, 35323934H		NB	122620333	Worker Fell	308 WEST 133RD STREET LLC	Happy Living Development
					hurt his left leg. The worker was taken to a hospital. A	a							
					DOB inspector responded and visited the site and reported that the worker was not tied off when he fell.								
					Two ECB Violations were issued for a failure to								
					safeguard and for a failure to provide a four hour user training card. A partial Stop Work Order was issued on								
					baker scaffolds until a Means and Methods is provided.								
2018	Brooklyn	810	FULTON STREET	0	2 The Site Safety Manager reported that two workers were	e ECB Violation	35323694H,35323695J		NB	320597083	Worker Fell	GREENPOINT-GOLDMAN CORP.	Bradway Construction
					trying to install a pipe on top of a baker scaffold when both of the workers leaned towards the same side of the								
					scaffolding, which caused the baker scaffold to collapse	e							
					The two workers fell approximately four feet and landed on the floor. An ambulance was called. A DOB inspecto	e l							
					responded and visited the site. Two ECB Violations wer issued: one violation for there being no personnel on sit	e							
					with proper documentation, which would be four hour	e							
					user cards, and a second ECB Violation for a failure to safeguard all persons and property affected by								
					construction operation. A partial Stop Work Order has								
					been issued on baker scaffolds until a Means and Methods is provided.								
	De a la companya de la compa	~	FUIDUND NOT			EOD MOUNT	0504040016	050 (100000110)			Marca All Fall	10/0 0000	
018	Brooklyn	63	FLUSHING AVENUE	U	1 The Site Safety Manager reported that a worker was unloading a pallet of glass that was approximately 2' X 8	3'	35318496K	050418BS02JJ01			Material Fell	NYC DSBS	
					when the pallet of glass tiped over onto him and pinned him against the wall of the truck. The worker went to a								
					hospital by ambulance. A DOB inspector responded and	± t							
					visited the site and issued an Aggravated Level 2 ECB Violation for a failure to safeguard, as there was no								
					Means and Methods for delivery operations available fo	r							
					the previous delivery operations that happened at the site. A partial Stop Work Order was issued on all								
					deliveries. A Means and Methods for safe delivery operations and Tool Box Talks must be provided.								
018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker slipped	No Dispatch					Other Construction Related Incidents	NYC HPD	
				Ű	on rebar and cut his right thumb. The worker walked to the ER.								
018	Bronx	600	BERGEN AVENUE	0	1 The Site Safety Manager reported that a welder was	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & developmen
					performing Support Of Excavation (SOE) work when he picked up a steel plate that was 12' X 12' and 3/8 thick								
					when he injured his back. A co-worker took the worker t a City M.D., where a physician recommended medication	0							
					for pain and rest for three days. A DOB inspector								
					responded to the incident and visited the site and								
					reported that there were no unsate conditions found and								
					reported that there were no unsafe conditions found and that all of the workers at the site had ten hour OSHA	1							
					reported that there were no unsate conditions found am that all of the workers at the site had ten hour OSHA cards. No enforcement action was deemed necessary.	1							



cident Date		Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Brooklyn	2085	ROCKAWAY PARKWAY	0	1 The Construction Superintendent reported that a worker from the sidewalk shed company fell four feet while descencing from a baker scaffold. An ambulance took	No Dispatch			ALTERATION TYPE 3	340451308-01-EQ-SH	Worker Fell	NYC HOUSING AUTHORITY	SKYWORX CONTRACTING INC
018	Brooklyn	814	BEDFORD AVENUE	0	the worker to a hospital. 1 The Nev York City Energency Management Department and the New York City Firsi Department reported that a worker was ströpping concrete form work for the first floor deck when the worker fell approximately fitteen fest into the cellar and fanded on capped refax. The worker was taken to a hospital and was accompanied by another worker. The injured worker did not suffer any life- threatening injuries. An ECB Violation for the failure to maintain aslee operations was issued. A full Stop Work		35327578Z				Worker Fell	814 PARK LLC	
/2018	Queens	24-02	49 AVENUE	0	Order (FSWO) was also issued. Additional safety violations will be issued. 1 The Site Safety Manager reported that a worker at the fourth floor level was struck by duct work that was approximately grint feet high while on a ladder that was approximately grint feet high. The duct work had can are deproximately grint feet high. The duct work had can be him to fail off of the ladder. The worker safetered a hotes him to fail off of the ladder. The worker safetered a hotes leg and was taken to a nearby hospital. A DOB inspector responded and visited the site and issued an ECB Violation for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued.	l.	35326803Y	050718B502DH01	ALTI	421518566	Worker Fell	LIC 73 OWNER, LLC	UNITY CONSTRUCTION GROUP
2018	Manhattan	250	BRADHURST AVENUE	0	1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a façade connection. The worker went to a hospital by ambulance to receive stitches on his finger.						Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
2018	Brooklyn	535	4 AVENUE	0	 The Site Safety Manager reported that a hoist mechanic lacerated his finger while cutting a piece of plastic away from a hoist. A co-worker took him to a hospital. 	No Dispatch					Other Construction Related Incidents	XYZ PROPERTIES INC	
2018	Brooklyn	11	HOYT STREET	0	1 The Site Safety Manager reported that a worker was working on a rebar wall when he was struck in the neck by dialodged shoring. A DOB inspector responded and visited the site and reported that reshores were installed contrary to the approved plan. An ECB Violation and a partial Stop Work order (PSWO) on all concrete work were issued.	ECB Violation	35331175X				Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	
2018	Manhattan	115	DELANCEY STREET	0	1 The Site Safety Manager reported that at a twenty site toory nore building under contraction, a worker was coming back on site when he stapped on loose concrete masnory and turned his ankle. The worker was found alert and awake. The on-site medic issued ice for on-site reatment and the worker went to a nearby urgent care center to receive further treatment.				NB	121191646	Other Construction Related Incidents		T.G. NICKEL & ASSOCIATES
2018	Manhattan	118	FULTON STREET	0	 The Site Safety Manager reported that a worker jammed his finger while drilling into concrete. The worker walked to the emergency room. 	No Dispatch			NEW BUILDING	121333440-01-NB	Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	RNC INDUSTRIES LLC
018	Manhattan	560	WEST 33 STREET	0	1 The Site Safety Manager reported that an electrician was walking down stairs when he hurt his ankle on permanent stairs. An ambulance was called.	No Dispatch					Other Construction Related Incidents	ERY NORTH TOWER RHC TENANT LLC	
0/2018	Queens	54-17	101 STREET	0 0	2 New York City Emergency Management reported that two workners that were working on wires on the builkhead when they experienced electric bocks. The workners were able to make it down from the builkhead and were transported to a hospital. A DOB inspector responded to the incident and visited the site and issued two ECB Violations for the equipment ground not being provided and for the exposed wires at the builkhead area not being properly terminated, secure, and protected around the HVAC air handler unit. A partial Stop Work Order (PSWO) was also issued for electrical work.		35313352Z 35313353K				Other Construction Related Incidents	HANAC CORONA HOUSING DEV. FUND	
3/2018	Manhattan	80	EAST10 STREET	0	1 The Site Safety Coordinator reported that a worker was moving pallets of concrete block around when some of the concrete block fail off and struck the worker's right leg. An ambulance was called and the worker went to a hospital for traitmerr. A DOB inspector responded and visited the site and reported that the worker pulled the stationary part of the pallet jack with pulling the concrete block onto himself. It was determined that this incident occurred as the result of a worker's error, and that no enforcement action was necessary.	No Action Necessary			NB	121193476	Other Construction Related Incidents		CONY CONSTRUCTION INC
0/2018	Manhattan	7	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker felt discomfort in his shoulder during stripping operations. The worker took a cab to a clinic on his own.	No Dispatch					Other Construction Related Incidents	7 WEST 57TH STREET REALTY COMP	
0/2018	Manhattan	515	WEST 36 STREET	0	1 The Site Safety Manager reported that a worker was pushing a cart when he tripped on planks that were covering a hole. The worker suffered a cut to his right hand and were to a hospital. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for the improper covering of holes.	ECB Violation	35331118J				Other Construction Related Incidents	FIRST ST MARKS LLC	



ncident Date	Berevel	Address Number	Stread	Estalities Iniuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/10/2018	Manhattan	424	EAST 34 STREET		1 The Site Safety Manager reported that a tapper tried to		ECB Violation Numbers	DOB Violation Numbers	Fernin	Permit No	Other Construction Related Incidents	NYU HOSPITALS CENTER	Contractor Name
/10/2018	Marinattan	424	EAST 34 STREET	0	move an "A"-Frame with masonite on it out of his way by	NO Dispatch					Other Construction Related incidents	NTO HOSPITALS CENTER	
					himself when he tipped the "A"-Frame and was hit in the								
					right shin by both the "A"-Frame and the masonite. An								
					ambulance was called.								
/10/2018	Brooklyn	8	NEVINS STREET	0	1 The Site Safety Manager repoted that a worker was	ECB Violation	35326856P	051018BS02JJ01			Material Fell	NEVINS STREET OWNER LLC	
					stripping form work on the eighteenth floor when a post								
					fell forward and hit him in the back. The worker experienced back pain and an ambulance was called. A								
					DOB inspector responded and visited the site and								
					reported that another worker had leaned a stripping post								
					against a wall instead of stacking the post and the post								
					slid from an upright position and hit the injured worker.								
					An ECB Violation was isued for a failure to								
					institute/follow safety measures for stripping operations. A DOB Violation was also issued.								
					A DOB VIOLATION Was also issued.								
/10/2018	Bronx	1410	STORY AVENUE	0	1 A DOB inspector reported that a worker was sitting on	ECB Violation	35327286R 35327285P	051018BS09VP01,02			Worker Fell	BR-2012 REALTY LLC	
					top of a beam setting joists on the second floor of a new								
					building. He was setting joists and had just landed a joist	t							
					when the signal man signalled to the crane operator to hoist up with steel chokers (no load) on the hook. While								
					hoisting up, one of the chokers snagged the joist and								
					picked it up. The worker who had landed the joist tried to								
					get out of the way from the joist, but lost his balance and	1							
					fell two stories to the ground. The worker was not tied off	f.							
					Other workers at the site reported that the injured worker	r							
					was bleeding from the mouth and was experiencing severe pain in his legs, but was conscious. The worker								
					severe pain in his legs, but was conscious. The worker was taken to Lincoln Hospital by ambulance. The Hoist								
					Machine Operator (H.M.O.) at the site stated that he was								
					standing next to the crane operator's cab as of the time								
					of the incident and was given the okay to hoist up via								
					radio. The lift director's logs were filled out and were on								
					site. However, the lift director was not on site as of the								
					time of inspection, because he had gone to the hospital								
					with the injured worker. Two ECB Violations for a failure to safeguard were issued to the General Contractor and								
					the crane operator. A full Stop Work Order (FSWO) was								
					issued or there being no Construction Superintendent on								
					site as of the time of inspection, as well as a partial Stop								
					Work Order (PSWO) for the unsafe placement of steel								
					members/roof joists. A designated Construction								
					Superintendent on a PW2 application form and a Means								
					and Methods for the safe operations of steel placement								
					must be provided.								
/11/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch				1	Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
					right thumb while installing duct work. The worker went to	D							
					urgent care. An ambulance was not called.								
/11/2018	Manhattan	553	WEST 30 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
					using a grinder and suffered a cut to his right leg when								
					the grinder kicked back. The worker was taken to a hospital by an ambulance.								
/11/2018	Manhattan	425	PARK AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
					finger while using a band saw and suffered a minor gash to his finger. An ambulance was called.	1							
					to mo miger. An amoulance was called.								
/11/2018	Manhattan	357	EAST 57 STREET	0	1 A DOR inspector reported that feed a work way	ECB Violation	35245543J	051118CERJM01			Material Fall	357 EAST 57 STREET CONDOMINIUM	EDRAS CROUP CORP.
/11/2018	Mannattan	357	EADI 5/ SIREEI		1 A DOB inspector reported that façade work was	ECB Violation	30240043J						EDRAS GROUP CORP
				-				SOTTIOO ET GINOT	ALTERATION TYPE 2	123179951-01-EW-OT		357 ERGT 37 STREET CONDOMINION	
					underway at exposure floor on the sixteenth floor when a section of brick veneer dislodged and fell onto the	1			ALTERATION TYPE 2	123179951-01-EW-OT		337 EAST 37 STREET CONDOMINION	
					section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a				ALTERATION TYPE 2	123179951-01-EW-OT		357 ERGT 57 STREET CONDOMINION	
					section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company				ALTERATION TYPE 2	123179951-01-EW-OT		SO EROTO STREET CORDONING	
					section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the				ALTERATION TYPE 2	123179951-01-EW-OT			
					section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General				ALTERATION TYPE 2	123179951-01-EW-OT		SO ENDIOR STREET CONDOMINION	
					section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB				ALTERATION TYPE 2	123179951-01-EW-OT			
					section of brick veneer dislodged and fell onto the sidewalk sheal. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was insued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order				ALTERATION TYPE 2	123179951-01-EW-OT			
					section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB				ALTERATION TYPE 2	123179951-01-EW-OI			
					section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to terpair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued.	a			ALTERATION TYPE 2	123179951-01-EW-OI			
/11/2018	Manhattan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shad was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failore to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued.	ECB Violation	363311907		ALTERATION TYPE 2	123179951-01-EW-OI	Material Fell	305 WEST END PROPERTY, LLC	
/11/2018	Manhattan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. 1 The Construction Superintendent reported that an electrician was working on the emergency lighting of the	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9961-01-EW-OI			
/11/2018	Manhatlan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the stef for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. The Construction Superintendent reported that an electrican was working on the emergency lighting of the evenemt floor permanent staris when he was hit in the	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI			
/11/2018	Manhattan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to tepair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. 1 The Construction Superintendent reported that an electrician was working on the emergency lighting of the seventh floor permanent stairs when he was hit in the nead from a type measure that fell from above. The	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI			
/11/2018	Manhattan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. The Construction Superintendent reported that an electrician was working on the emergency lighting of the seventh floor permanent statisr when he was hit in the head from a tape measure that fell from above. The electrician vas taken to a hopsital. A DOB inspector	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI			
/11/2018	Manhattan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor highry, but refused medical attention. Th company that enercid the sidewalk shad was onsite to repair the Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. The safe for the state for a electrican was working on the emergency lighting of the electrican was taken to a hospital. A DOB inspector responded and wisted the site and insued an ECB	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI			
/11/2018	Manhatan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. 1 The Construction Superintendent reported that an electrician was working on the emergency lighting of the seventh floor permanent statisr when he was hit in the head from a tape measure that fell from above. The electrician vas taken to a hopstal. A DOB inspector responded and visited the site and issued an ECB Violation of the failure to maintains safe operations and a	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9961-01-EW-OI			
/11/2018	Manhattan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order electrician was working on the energency lighting of the head from a tape measure that full from above. The electrician was taken to a hogolit. A DOB impector responded and visited the site and issued an ECB Violation of the failure to maintain safe operations and a partial Stop Work Order (PSWO) for all work next to operanors. The General Contrators is to provide a Means	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI			
/11/2018	Manhatan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor nijury, but refused medical attention. Th company that erected the sidewalk shad was onsite to repair the control of the side for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order (FSWO) was also issued. If the side for a begin the electrician was working on the emergency lighting of the electrician was taken to a hospital. A DOB inspector responded and wisted the side di susued an ECB Violation for the failure to maintain safe operations and a partial Stop Work Order (FSWO) for all work next to	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI			
/11/2018	Manhattan	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order electrician was working on the energency lighting of the head from a tape measure that full from above. The electrician was taken to a hogolit. A DOB impector responded and visited the site and issued an ECB Violation of the failure to maintain safe operations and a partial Stop Work Order (PSWO) for all work next to operanors. The General Contrators is to provide a Means	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9961-01-EW-OI			
		305		0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shad was onsite to repair the shad. An ECB Violation was issued to the General Contractor at the she for a failure to safeguard. A DOB Violation was also issued. I The Construction Superintendent reported that an electrician was working on the emergency lighting of the seventh floor permanent stars' when he was hit in the head from a tape measure that fell from above. The electrician was taken to a hospital. A DOB inspector responded and visited the site and issued an ECB Violation for the lative to maintain safe operations and a partial Stop Work Order (FSWQ) for all work next to openings. The General Contractor is to provide a Means and Methods and a Toobox Talk.	ECB Violation	363311907		ALTERATION TYPE 2	1231/9951-01-EW-OI	Material Fell		
/11/2018 /11/2018	Manhattan Brooklyn	305	WEST END AVENUE	0	section of brick veneer dislodged and fell onto the sidewalk shed. A pedestrian at the street level suffered a minor njury, but refused medical attention. Th company that erected the sidewalk shed was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order electrician was working on the energency lighting of the head from a tape measure that full from above. The electrician was taken to a hogolit. A DOB impector responded and visited the site and issued an ECB Violation of the failure to maintain safe operations and a partial Stop Work Order (PSWO) for all work next to operanors. The General Contrators is to provide a Means	ECB Violation	36331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI			
		305		0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor nijury, but refused medical attention. Th company that erected the sidewalk shad was onsite to repair the Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) for the failure to maintain safe operations and a full Nor Corder (FSWO) for all work next to openings. The General Contractor is to provide a Means and Methods and Toobox Talk.	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI	Material Fell		
		305		0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shad was onsite to repair the shad. An ECB Violation was issued to the General Contractor at the ste for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order (FSWO) was also issued. The step of the step of the step of the seventh floor permanent stars' when he was hit in the head from a tape measure that fell from above. The electrician was working on the emergency lighting of the electrician was taken to a hospital. A DOB inspector responded and visited the site and issued an ECB Violation for the failure to maintains afe operations and a parial Stop Work Order (FSWO) for all work next to openings. The General Contractor is to provide a Means and Methods and a Toobux Taik.	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI	Material Fell		
		305		0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor nijury, but refused medical attention. Th company that erected the sidewalk shad was onsite to repair the Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) for the failure to maintain safe operations and a full Nor Corder (FSWO) for all work next to openings. The General Contractor is to provide a Means and Methods and Toobox Talk.	ECB Violation	35331190Y		ALTERATION TYPE 2	1231/9951-01-EW-OI	Material Fell		
		76		0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shad was onsite to repair the shed. An ECB Violation was issued to the General Contractor at the she for a failore to saleguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order (FSWO) was also issued. The stop of the step of the s	ECB Violation	35331190Y		ALTERATION TYPE 2		Material Fell		CAULDWELL WINGATE CO LLC
/11/2018	Brooklyn	76 42	NORTH 6 TH STREET	0 0	eection of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor nijury, but relused medical attention. Th company that erected the sidewalk shad was onsite to repair the contractor at the site for a failure to safeguard. A DOB Vicetaion was also issued. A full Stop Work Order (FSWO) for all work next to pentings. The General Contractor is to provide a Means and Methods and a Toobox Taik. 1 The Construction Superintendent reported that a worker was cleaning a paint gun when his finger was injured by he pressure from the nozze. The worker went home to be fis Satery Manager reported that a worker twisted his hee on Saturday. No 12.018. This incident took	ECB Violation	35331190Y				Material Fell Other Construction Related Incidents	305 WEST END PROPERTY, LLC	
/11/2018	Brooklyn	76 42	NORTH 6 TH STREET	0 0	section of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor injury, but refused medical attention. Th company that erected the sidewalk shad was onsite to repair the shad. An ECB Violation was issued to the General Contractor at the she for a failure to saleguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order (FSWO) was also issued. A full Stop Work Order (FSWO) was also issued. The stop of the step of the s	ECB Violation	35331190Y				Material Fell Other Construction Related Incidents	305 WEST END PROPERTY, LLC	
/11/2018	Brooklyn	305 76 42	NORTH 6 TH STREET	0 0	eection of brick veneer dislodged and fell onto the sidewalk shad. A pedestrian at the street level suffered a minor nijury, but relused medical attention. Th company that erected the sidewalk shad was onsite to repair the contractor at the site for a failure to safeguard. A DOB Vicetaion was also issued. A full Stop Work Order (FSWO) for all work next to pentings. The General Contractor is to provide a Means and Methods and a Toobox Taik. 1 The Construction Superintendent reported that a worker was cleaning a paint gun when his finger was injured by he pressure from the nozze. The worker went home to be fis Satery Manager reported that a worker twisted his hee on Saturday. No 12.018. This incident took	ECB Violation	35331190Y				Material Fell Other Construction Related Incidents	305 WEST END PROPERTY, LLC	



cident Date	Borough	Address Number		Fatalities Injuri	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2018	Manhattan	500	WEST 25 STREET	0	1 The Site Safety Menager reported that workers were removing material from the grade level at the leading edge when two pieces of caisson pilings that were approximately two feet long were out in half. The pieces of caisson pilings fell approximately fitteen feet and struck a worker that was in the excavation pil in the leg. The worker went to a hospital. The status of the worker injuries is unknown. A DOB negotor responded and visited the site and issued four ECB Violations for the abscence of the boards at the guardralis, the presence of inadequate vertical neiting, the presence of a nadequate vertical neiting, the presence of a partial Sito Work Crider (FSW) and four DOB Violations were also issued. The contractor is to provide a Meens and Methods and a Toolbox Talk for the safe continuation of work.		35331325M/26Y/27X/28H	051218BS04PK01/02/03/04			Other Construction Related Incidents	500 W25TH OWNER LLC	
14/2018	Brooklyn	211	72 STREET	0	1 The New York City Fire Department reported that a worker was walking on a scaffold on the second level when he tripped and hurt his knee. The worker was taken to an area hospital.	No Dispatch			A2 - ALTERATION TYPE 2	302579662	Worker Fell	DEPARTMENT OF EDUCATION	KG CONSTRUCTION SERVICES
14/2018	Brooklyn	7	WHIPPLE STREET	0	1 The Construction Superintendent reported that workers were installing C-decking on the second floor when a worker fell from the second floor onto the first floor deck. The worker was found consolution and was transported to Bellevue Hoopial. Additional information regarding the inguines was not available. The Construction indigent coursed. An DOB inspector responded and visited the size and issued an ECR Violation to the General Contractor for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) was also issued.		35308771R	051418CNEDG01	Air 1 / NB	321286275	Worker Fell	WHIPPLE PROPERTIES LLC	SUNSHINE CONSTRUISA INC
14/2018	Manhattan	150	FIFTH AVENUE	0	A DOB inspector reported that there were workers moving steel beams with an electric hoist through a shaftway for an alteration on a twelve story building. The workers moved the beams by pape rollers on the ground to be stacked. One of the workers was adjusting the putting steel in place. The struck worker got his right- hand curbeh between two beams and was taken to Beth haral Hospital for treatment. An ECD Violation for, failure to adjugund was issued on all work in shtway hoistin materials. A Means and Nethods and a Toolbox Talk must be provided.	e	35331133H-FAIL TO SAFEGUARD.		ALT1	122700292	Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
5/2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was on the roof setback setting roof pavers when he stepped in a hole with the roof pavers that he was working on and hit his rights hin. The worker was conscious and alert and walked to a City M.D. to be checked out.	No Dispatch			ALT1	121324343	Worker Fell	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
5/2018	Manhattan	627	GREENWICH STREET	0	1 The Site Safety Manager reported that a plumber slipper off of the fourth step of a ladder that he was working on and suffered a sprained ankle. An ambulance was called	d No Dispatch					Worker Fell	627 GREENWICH OWNER LLC	
15/2018	Manhattan	500	WEST 33 STREET	0	called. (A DOB inspector reported that materials that were storer in the staging area were blown away due to wind. Armon, the stored materials was a piece of styrofoam that was approximately 8' X 3' X 3' that struck a security guard in the back. The security guard complained of pain and was taken to a hospital in a conscious state with an unknown injury. An ECE Volation was suesued, as well as a partial Stop Work Order (PSWO) for all work in the staging area due to a failure to secure stored material. The General Contractor is to provide a Means and Methods for a safe storage procedure.	9 5 1	35326800X				Other Construction Related Incidents	NOT ON FILE	
5/2018	Manhattan	20	BROAD STREET	0	1 The Site Safety Manager reported that a worker tripped on debris and fell on his back. An ambulance was called A DOB inspector responded and visited the site and reported that no enforcement action was necessary, as the incident occurred as the result of a worker error. The worker was okay and was reported to have returned to work the following day.	L					Worker Fell	NY STOCK EXCHANGE BLDG. CO.	
15/2018	Manhatlan	100	EAST 104 STREET	0	2 The New York City Police Department reported that debris was failing from the building. A DOB respector low the second second second second second second effect of the settlex second second second second second became separated due to high winds and fell to the street level along Park Areney, striking two individuals. One of the individuals that was struck was taken to a local hospital. An Agginvated Level 2 ECB Violation was issued for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued.	5	35309489H	051518CNEG802	NEW BUILDING	121192887-01-NB	Material Fell	TERRACE ON THE PARK LLC	GLENWOOD CONSTRUCTION



Incident Date	Borough	Address Numbe	er Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/15/2018	Manhattan	1	WALL STREET	0	1 The Site Safety Manaer reported that a worker was setting up needle beams when a portion of screw jack fell onto the worker when he bend down. The struck worker complianed of neck pain and left the site to wisit his own doctor. A DOB inspector responded to the incident and visited the site and insued an ECE Violation for a failure to maintain safe operations and a partial Stop Work forder (PSWO) on the use of all needle beams. A Means and Methods and a Toolbox Talk much be provided. An additional ECE Violation will be issued for the installation of a pipe scathold that was done contrary to the design plans.	ECB Violation	35327019M				Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
5/15/2018	Brooklyn	626	SHEEPSHEAD BAY ROAD	0	1 The Project Manager reported that a painter was on a ladder on the third floor when he misused the ladder and slipped off. The worker fell approximately six fee and hun his shoulder. An ambulance was called.						Other Construction Related Incidents	NEPTUNE SOUTH COMMERCIAL LLC	
5/15/2018	Brooklyn	416	KENT ÄVENUE	0	2 A DOB respector reported that approximately 50-0° linear feet of allowarks thed dock and parapet deck enclosure had blown off of a sidewark had each and onto the streter, injuring two pedestrians. The two pedestrians were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewark shad responded and visited the side to rannow the debits from the size. An Aggravated Level 2 CED Violation was issued for a Violation was also issued, a partial Stop Work Order (PSWQ) was issued on all crane and axterior operations except for work to make safe the installation of a sidewalk shed.		35322610R	051518CERSM05	NEW BUILDING	320622616-01-NB	Material Fell	420 KENT AVENUE LLC	2D6, LLC
5/15/2018	Bronx	1017	HOME STREET	0	1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall left, hit a generator, and then bounced of the generator and landed on the worker's leg. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that safety measures were not in place for a bearing wall installation. An EGB Violation and a DOB Violation were issued, as well as a partial Stop Work Order (FSWO) on all bearing wall installations. A Means and Methods and safety measures for bearing wall installations must be provided		35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
5/16/2018	Manhattan	44	UNION SQUARE EAST	0	1 A competent person at the site reported that a worker was removing a vertical shoring post when his finger got caught between the safety pin and the plate. The worker suffered a swollen finger and went to a hospital on his own						Other Construction Related Incidents	READING TAMMANY OWNER LLC	
5/16/2018	Manhattan	76	11 AVENUE	0	1 The Site Safety Manager reported that a foreman was hanging an eight inch steel pipe when he lost control of the pipe. The foreman was then knocked off of a ladder by the pipe. An ambulance was called. A DDB inspector responed and visited the site and reported that the anchor from which the pipe was to be hung from failed. An ECB Violation was issued for a failure to maintain safe operations.		35331136N				Other Construction Related Incidents	76 ELEVENTH AVENUE PROPERTY OW	
5/16/2018	Queens	45-07	COURT SQUARE	0	1 The Site Safety Coordinator reported that a worker was using a four inch grinder when the grinder kicked back and cut the worker's left arm. The handle and grinder guard were in place. The worker was conscious and awake and went to Mount Sinai Hospital for treatment.	No Dispatch			NB	420902410	Mechanical Construction Equipment	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
5/17/2018	Queens	2100	49 AVENUE	0	1 The Construction Superintendent reported that an electrician was re-adjusting a ladder when he fell approximately five feet off of the ladder. The worker complainted of back pain and was taken to Elmhurst Hospital. The worker was alert and awake.	No Dispatch			ALT1	420656686	Worker Fell	2100 49TH AVENUE OWNER, LLC	ARCHSTONE BUILDERS LLC
5/17/2018	Queens	101	PENNSYLVANIA AVE	0	1 The Construction Superintendent reported that while working on a seven story new building, a project manage picked up a sheet metal that cut his finger. The project manager went to urgent care.	No Dispatch r			NB	320622894	Other Construction Related Incidents		CAULDWELL WINGATE CO LLC
	Manhattan	112	EAST 11 STREET	0	1 The Site Safety Manager reported that a worker was coming down a gang ladder when he slipped on the thirs step of the ladder and fell three feet. The worker complained of back pain. An ambulance was called. A DOB inspector responded and visited the site and found no unsafe conditions present as of the time of inspection No enforcement action was necessary.	s.					Worker Fell	UD-DEV ASSOCIATES LLC	
5/17/2018	Brooklyn	138	WILLOUGHBY STREET	0	2 A DOB inspector reported that a signalman had landed jab abandel dado no the top deck with a tower crane. The rigging was released after the load was landed, and the load shifted andheu worker that was carrying piaces of rebart. The worker traped, fell, and that this anales. The worker transition is a signalman suffered a cut to his finger from the banding after releasing the rigging and went to a City M.D. for treatment. There were no witnesses to the worker transition. Was determined that the signalman suffered a cut due to a worker error.				CN	773/17	Worker Fell	NYC HPD	Trident General Contracting, GC lend lease



No. N	cident Date	Borough	Address Number	Street	Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
Main </td <td></td> <td></td> <td>1903</td> <td>WEST FARMS ROAD</td> <td>0</td> <td>1 The Site Safety Manager reported that a worker was performing insulation work behind a stud wall when she pushed a stack of sheetrock that was leaning against a wall, which caused the boards to fall forward and hit her</td> <td>No Dispatch</td> <td></td> <td></td> <td></td> <td></td> <td>Material Fell</td> <td>SAMARITAN-COMPASS V HOUSING DE</td> <td></td>			1903	WEST FARMS ROAD	0	1 The Site Safety Manager reported that a worker was performing insulation work behind a stud wall when she pushed a stack of sheetrock that was leaning against a wall, which caused the boards to fall forward and hit her	No Dispatch					Material Fell	SAMARITAN-COMPASS V HOUSING DE	
MA <	/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	ATLANTIC 2644, LLC	
VI VI <th< td=""><td>/2019</td><td>Prosklan</td><td>422</td><td></td><td>0</td><td>urgent care.</td><td>No Action Nonoscone</td><td></td><td></td><td>CN</td><td>90/17</td><td>Mechanical Construction Equipment</td><td></td><td>E IM. Forro los</td></th<>	/2019	Prosklan	422		0	urgent care.	No Action Nonoscone			CN	90/17	Mechanical Construction Equipment		E IM. Forro los
Instrument Instrument <td></td> <td></td> <td></td> <td></td> <td></td> <td>routine it of a steel I-Beam from a trailer bed in the signal man gave the crane operator the signal to come op with the load. The caren has little of the load approximately two feet off of the bed of the trailer when approximately two feet off of the bed of the trailer when had point the load of the trailer when beam from swering. When the into mowfork did this, he had pot his leg inbetween the moving load and a stationary beam on the flatbed truck. When he did this, the worker created a pinch point, and the moving load struck the worker's leg and caused a cut. The worker was taken to a hospital with non-file threatening injuries. The DOB inspection, as all of the workers at the site had the sines were load taxed and as douated. the lift director lines were load taxed and as douated. the lift director</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>						routine it of a steel I-Beam from a trailer bed in the signal man gave the crane operator the signal to come op with the load. The caren has little of the load approximately two feet off of the bed of the trailer when approximately two feet off of the bed of the trailer when had point the load of the trailer when beam from swering. When the into mowfork did this, he had pot his leg inbetween the moving load and a stationary beam on the flatbed truck. When he did this, the worker created a pinch point, and the moving load struck the worker's leg and caused a cut. The worker was taken to a hospital with non-file threatening injuries. The DOB inspection, as all of the workers at the site had the sines were load taxed and as douated. the lift director lines were load taxed and as douated. the lift director								
Note No Note Note <	2018	Brooklyn	578	COZINE AVENUE	0	1 A DOB inspector repored that a worker was performing	ECB Violation	35322901R 35322902Z	051818CERRJ03 051818CERRJ04	Abatement		Worker Fell	NYBC REALTY LLC	GSC Services Corp
 In the second of the second of						asbesics abatement work on the rool when he fell approximately wenty feet through the rool. The worker was baken to Brookdale Hospital. The abatement work was being performed as per the posted notico. Two Aggravated Level 2 EGB Violations for a failure to safeguard were issued to the abatement company and building owner. A partial Stop Work Order (PSWO) was issued to rail work at the roof level. The contractor at the site is to provide a Maens and Mathods for the safe venoval of material from the roof level.								
Image: Section of the sectin of the section of the section		Brooklyn	6		0	was working on a pipe on the fifth floor when the pipe burst and hit the jumber in the chest and chin. An ambulance was called. A DOB inspector responded to the incident and visied the site and determined that there was no enforcement action necessary, as the job had on-site active Department Of Buildings permits and approved technical plans.				PLUMBING	321562288			VITO M. GIACHETTI
12118 Dem 242 9 APERALE 0 1 The Schedinger sproced of	V2018	Manhattan	130	WILLIAM STREET	0	piece of rebar that was standing vertically and was to be installed fell on a worker that was standing on the ground, hitting him in the side of his hard hart. The worker went to a City MD. A. DOB inspector responded and visited the site and issued an ECB Violation for a failure to maintain aside operations, as well as a partial Stop Work Order (PSWO) for all concrete operations. The General Contractor at the site is to provide a Means and		35331400N				Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	
Image:	1/2018	Bronx	2865	CRESTON AVENUE	0	putting up forms on a column when he field about six to servering feat and injuride his foot. The worker was sent to a hospital. A DOB inspector responded and visited the site and found that a hook that was holding form up was damaged, which may have possibly caused the worker to fail. An ECB Violation for the failure to maintain safety operations was issued, as well as a partial Stop Work Order (PSWO) for all concrete work. Additional ECB Violations were also issued for infractions that were not		35327296K, 35327297M, 98, 99X,353184OOR, 01Z				Worker Fell	10 MINERVA PLACE HOUSING DEVEL	
Image: Contract in the second seco	21/2018	Bronx	4215	PARK AVENUE	0	the top of a hoist that was stopped on the first floor. The	No Dispatch			NEW BUILDING	220157700-01-NB	Worker Fell	TREMONT RENAISSANCE HOUSING DE	JOY CONSTRUCTION CORP
1/2018 Queens 0-02 3-VENUE 0 1 The Site Satety Manager reported that a workers was No Dispatch 1/2018 Queens 0-02 3-VENUE 0 1 The Site Satety Manager reported that a workers was No Dispatch						hospital by ambulance.								
cutting a metal stud when he cut his hand. An	1/2018	Manhattan	247	WEST 87 STREET	0	workers were in the process of installing a supported scaffold when they sipped and fell from three frames of pipe scaffold. The workers suffered scrapes and burgs to their hands and legs and were taken to St. Lick's Hospital. A DDB inspector responded to the incident and violated the site and issued work objective to the removal or alteration of the supported scaffold by the General or alteration of the supported scaffold by the General has in set of the supported scaffold by the General removal of equijament, structural material, or evidence has in site of an incident. The second violation was issued for a failure to promptly notify the Department Of Buildings of the incident, at the incident tax serporde by		35324011Y - 35524012X		N/A		Worker Feil	KSB BROADWAY ASSOCIATES	Jerrick Associates Inc
outing a metal stud when he out his hand. An	1/2018	Queens	30-02	39 AVENUE	0		No Dispatch					Other Construction Related Incidents	30-02 ASSOCIATES LLC	
ambulance was called. Page 73 of 33						cutting a metal stud when he cut his hand. An ambulance was called.								



Incident Date	Recourds	Address Numbe	r Stroot	Estalition Injurior	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/23/2018	Staten Island	149	PROVIDENCE STREET	0	1 Other Version Capital Control of Emergency Management (Control Control Control Control Control Control Control Management) (Control Control Control Control Control Management) (Control Control Control Control Control Management) (Control Control Control Control Control Control Management) (Control Control		35322904M05Y	052318CERRJ01/02	ALT 1	520323212	Worker Fell	PERRI, ALFONSO	A FONTANA & SONS LLC
5/23/2018	Manhattan	76	11 AVENUE	0	1 The Site Safety Manager reported that a worker was building the waik-out for a tower crane and was standing on the carea's the back beam when he slipped off of the sequence of the standing of the standing of the sequence. The worker did not safety and party put was backen to a hooginal for precauciancy observation. A DOB inspector responded to the incident and visited the site and reported that no enforcement action was necessary.						Worker Fell	76 ELEVENTH AVENUE PROPERTY OW	SBF Construction
5/23/2018	Manhattan	26	1 AVENUE	0	1 A New York City Police Officer reported that a worker fell approximately five stories or firty feet from a nuguarded section of pies cartifield. The worker was in critical condition and was taken to Belliowue Hospital. A DOB imperior responde core in environment and visited the state section of the section of the section of the section of the piece of the section of the section of the section of the individual of the program of a support action of the individual of the program of a support acatfold that was not built according to code and was missing quardrafis, missing ue boards, and was not thuly decked, for the absence of plans, drawings, and logs on site, and to the failure to provide a four hour supported scatfold uder card upon request. A partial Stop Work Order (PSWO) was also issued.		35324057J, 35324058L, 35324059N, 35324060K		Alt	140761995	Worker Fell	DROBENKO NICHOLAS	Lime-Light Construction Co
5/24/2018	Brooklyn	2837	WEST & STREET	0	1 The Project Manager at the site reported that during the installation of concrete panel around a buildhead, a panel cracked, Bill, and caused a minor cut b a worker's hands. The worker went to a clinic and then came back to the site on the following dip A. DoB inspector insported that a Means and Methods was in place at the site, and that the workers were following the Means and Methods. The suction cup equipment was found to be in working condition. The inspector observed that the concrete panel may have broken because the concrete panel was effective. No enforcement action was deemed necessary.						Material Fell	AISD CORP.	
24/2018	Brooklyn	41	BLUE SLIP	0	1 The Site Safety Manager reported that the driver of a concrete truck was washing out his truck when he hopped off of a ladder and turned his ankle. EMS was called and the worker was sent to a nearby hospital.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT F LLC	
5/24/2018	Brooklyn	420	EAST 21 STREET	0	¹ The New York City File Department requested that and inspection please bit performed with the a relativing well collapse. A DOB inspector responded and valued the tait and reported that the building owner was performing work on the relativing well that was separating 420 and 412 East 21 Street when a section of the retaining well that was approximately twenty feet wide collapsed into the right side yord at exposure for Units that was approximately that was approximately twenty feet wide collapsed into the right side yord at exposure for units that and further collapse eliminated a safe path of agress from the first escale about the size and and garage and driveway. During search operations, an 'EDNY friefighter suffered a minor injury and was transported to a local hospital. Two Aggravated Level 2 CeS Violations which a permit A fuel Stop Work Order (FSWO) and a partial Vacate Order were also issued at 420 East 21 Street for a failure to safeguard and for work 243 East 21 Street A DOB Violations and a thi Xaate Collapse East 21 Street).		35322725R, 35423726Z	052418CNESC04, 05, 052418CNE01SC			Other Construction Related Incidents	HOSSAIN, GOLAM	
/24/2018	Brooklyn	84	CARLTON AVENUE	0	1 A competent person at the site reported that a worker was installing roof protection when the worker tripped on a piece of plywood and fell. The worker was sent to a hospital for a check up.	No Dispatch				_	Other Construction Related Incidents	NYC HOUSING AUTHORITY	
24/2018	Manhattan	233	WEST 125 STREET	0	 The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taken to a hospital by EMS. 				NEW BUILDING	121187447-01-NB	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
5/25/2018	Manhattan	24	2 AVENUE	0	1 The Site Safety Manager reported that a worker cut his arm with a sheetrock knife while cutting sheetrock. The worker went to a nearby urgent care facility to receive medical attention.	No Dispatch					Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	



ncident Date		Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/25/2018	Queens	28-07	JACKSON AVENUE	0	1 A DOB inspector reported that there was as it man team that was diamating support columns when one of the columns was released before one of the workers had a hold of the column. The column stuck this worker to the graupment (PPE) and was footned abler and responsive. The house of the columns are supported by the solution of the columns are column abler and responsive. The house of the columns are precisely, it was taken bocumentation was provided to show that the worker attended a pre-job meeting and that the worker was up to bocumentation was provided to show that the worker attended a pre-job meeting and that the worker was up to determined that no enforcement action was necessary and that the incident occurred as the result of a worker error.	D			ALT 1 NB	420656873	Material Fell	LIC SITE B-1 OWNER, LL.C.	NEW LINE STRUCTURES & DEV
5/26/2018	Manhattan	217	WEST 57 STREET	1	O A DOB Professional Engineer (PE) reported that at a sixty-seven story new building that was under construction, a security guard was waiking from the front lo the rear on the first floor of the building when an approximate 16 × 5 : 2.300 portug datas curtain wall parent with a supporting stell "A "Frame toppled and phrane the "security guard materia." How the security guard materia his several working guard. The security guard was taken the Mount Sina parent he was later pronunced dead. A DOB inspect that was also at the site reported that the glass panel fel baccuse it was acidentally hit by another worker that was supporting bit a piece of HVAC metal duct that was also a support that was incombuly durated to the walking area instead of towards the concrete wall. Ne additional panels or "A'-Frame topic "take" is a difficult of the walking area instead of towards the concrete wall. Ne Additional panels or "A'-Frame serve found to have been stored in an unsafe position. The on dury Site Safety Manager strated that the pareline of the walk agar reader was law sufficient of the walk and a subjection at the site at the start of the work day that morning. However, he did not fluor that a site is a start of the work day that Stop Work Order (ESWO) was issued, as well as an Agarovated Lowel 2 CEO Violation for a failure to safeguard. A DOB Violation was also issued.		36322614Y	052618CERSM01	ALT 1 NB	121328205	Material Fell	SMITELL SPONSOR LLC	LEND LEASE (US) CONSTRUCT
/26/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	2 The New Yok City Fire Department requested that a structural stability inspection please be performed because a construction frence had partially collapsed. A DOB inspector responded to the incident and visited the site and reported that there was approximately 100 feet of construction fence that was made of water-filled jersey barriers and a four loot chain fills frace that had failen over one a petientian or way and ing not have the site of the site of the site of the site of the petientian of the site of the site of the site of the petientian of the site of the site of the site of the barriers were found to have inadequate water levels. Two EGB Violations were issued for a failure to safeguard and for a detective job site fence. Two DOB Violations were also issued.		35323583P, 35323584R	052518CERFC02 . 03	ALT 1 NB	320622894	Material Fell	SPRINGER, JEAN E	CAULDWELL WINGATE CO LLC
5/29/2018	Bronx	220	EAST 178 STREET	0	1 The Site Safety Coordinator reported that while working on a twelve story New Building that was at the Support o Excavation (SQS) stage, a hose from the fire hydant that was across the sidewal was being used when a female pedestrian tripped and III over the hose. The pedestrian was found alert and awake and was taken to a nearby hospital by ambulance. A DOB inspector responded to the incident and visited the site and reported that the pedestrian sitewark was cale or any obstructions as of the time of inspection. Two ECB Violations for the presence of poor housekeeping and for the presence of tripping hazards. A full Stop Work Order (FSWO) was issued for the entire site.	ıf t	36332113P 36332114R		New Building	220546620	Excavation/Soil Work	GRAND APTS HOUSING DEVELOPMENT	M. Melnick & Company Inc
5/29/2018	Manhattan	15	BRIDGE PARK DRIVE	0	1 The Site Safety Manager reported that a worker was unloading an air handler when he lacerated his middle finger on a sharp edge of the air handler. The worker went to a local clinic.	No Dispatch					Other Construction Related Incidents		
5/29/2018	Manhattan	151	MAIDEN LANE	0	Went to a local cuinc. 1 The Site Safety Manager reported that workers were moving a refrigiration unit when it toppled over onto one of the workers. The injured worker was taken to a hospital. A DOB inspector responded to the incident and visited the site and fissued an EGE Violation for the failure to maintain safe operations, as well as a partial Stop Work / Over (PSWO) on material handling on the ground level at the exposure. The General Contractor is to provide a Means and Methods.	I.	35335652H				Other Construction Related Incidents	151 MAIDEN LLC	



ncident Date	Borough	Address Number	Street	Fatalities Injuri	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
29/2018	Queens	45-57	UNION STREET	0	The Site Safety Manager reported that a worker was on baker scafford at the second floor when the worker fell from the scaffold. The worker was found conscious, but compaining of pain in his shoulder and leg. The worker walked to a nearby hospital. A DOB inspector responde to the incident and visited the site and issued none ECB Violation for a scaffold patform that was not fully planker, and for the presence of planks that were not led down. A partial Stop Work Order (PSWO) for the use of a supported scaffold was also issued.	ECB Violation	35323972Z - 35323973K		NB	402898959	Worker Fell	DEPARTMENT OF EDUCATION	Leen D. Demattels Construction
29/2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that an electrician tripped while walking and suffered an injury to his rlbs. The worker went to urgent care.	No Dispatch					Worker Fell	DEPARTMENT OF EDUCATION	
30/2018	Brooklyn	2550	3 AVENUE	0	 The Site Safety Coordinator reported that a worker's foot came into contact with a piece of pipe that was in a pile of garbage that was to be picked up. The worker suffered a foot laceration and was sent to a hospital. 						Other Construction Related Incidents		
/31/2018	Brooklyn	107	COLUMBIA HEIGHTS	0	1 The Sile Safety Coordinator reported that four workers were carring havey mechanical equijement down the statis when equipment fail on one of the workers. The worker was sent to a hospital for a check up. A DDB inspector responded to the incident and visited the sile and issued an ECS Violation for the failure to maintain safe operations and a partial Stop Work (Order (FSWO) on the handling of heavy material. The General Contractor is to provide a Means and Methods.	ECB Violation	35326863N				Other Construction Related Incidents	CLIPPER 107 CH LLC	
/31/2018	Manhattan	360	EAST 89 STREET	0	1 A DOB inspector reported that a worker was sorting and moving glass window panels when one of the panels shifted and he the worker in the lag. The worker was taken to a hospital by ambulance for evaluation. An EGO Violation and a panella SQD whoch Order (PSWO) was issued for the failure to maintain safety measures, as the worker was injured due to impore material handing. The General Contractor is to provide a Means and Methods for safe material handling in order to prevent future incidents.		35318415J		NEW BUILDING	121186242	Material Fell	1711 LLC	RYDER CONSTRUCTION INC
31/2018	Queens	51-35	REEDER STREET	0	 The Construction Superintendent reported that a worker strained his back while lifting a crate onto a dolly. An ambulance was called and the worker was transported to a hospital. 				NEW BUILDING	420812446-01-NB	Worker Fell	85-15 QUEENS BLVD. REALTY, LLC	STRUCTURAL LAND MANAGEMEN
/31/2018	Queens	546	GULF AVENUE	0	 The Site Safety Manager reported that a worker cut his finger while using a box cutter. The worker went to a clinic. 	No Dispatch					Other Construction Related Incidents	_	
/1/2018	Manhattan	701	7 AVENUE	0	¹ The Site Safety Manager reported that two workers were loading glass panels that were approximately 5 X 3 onto a cart when the glass came into contact with a metal pan of the cart, which caused the glass to break into pieces. One of the workers suffered a minor laceration to his left hand. The injured worker went to a City M.D.	t					Other Construction Related Incidents	20 TSQ GROUNDCO LLC	
/1/2018	Manhattan	49	CHAMBERS STREET	0	¹ The Site Safety Manager reported that a worker was trying to move a doly that was carrying a machine motor for an exterior elevator up the ramp of the loading dock when he lost his balance and the machine motor tipped over, causing the worker to fail face down. The worker suffered outs and builses to the face and was taken to a hospital for treatment. A ROB inspector responded to the incident and visited the site and issued an ECB Violation and a partial Sito Wiok Order (SWO) to stop all deliveries and material handling. The General Contractor at the site is to provide a Means and Methods for safe operation.		35335925Y		ALTERATION 1	121186821	Material Feil	49-51 CHAMBERS LLC	NY DEVELOPERS & MANAGEMEN
/1/2018	Brooklyn	18	SPENCER STREET	0	1 The Site Safety Manager reported that a worker was working on a twelve story new building and suffered a cu to his arm while carrying 2 X 4's and share yedge metal track material. The worker went to a nearby doctor for treatment and received a few stitches.	No Dispatch t					Other Construction Related Incidents	LL 18 SPENCER HOLDINGS LLC	
/4/2018	Manhattan	10	VANDERBUILT AVE	0	1 The Site Safety Manager reported that an iron worker was climbing down the stairs when he slipped and fell about three feet. The worker complained of a sprained back. An ambulance was called.	No Dispatch					Worker Fell		
6/4/2018	Manhattan	108	LEONARD STREET	0	The Site Safety Manager reported that a steamfitter was working on a scissor iff and was installing sprinkler system anchors between pipes that were installed by other plumbers. One of the anchors failed and a pipe fail and landed one one of the steamfitter's hands, taking a tip of his hand off. A DOB inspector responded to the incident and visited the site and issued a DOB Violation and a partial Stop Work Order (PSWO) on all overhead installations. The General Contactor is to provide a Means and Methods and a Tool Box Taik.		35327073N				Material Fell	CIVIC CENTER COMMUNITY GROUP B	



cident Date	Borough	Address Number	er Street	Fatalities Injuri	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was stripping concrete form work on the first floor when he slipped and fell approximately four feet from the platform. The worker was found conscious and without a visible injury, but was taken to a hospital for a check up. A DOB inspector responded to the incident and visited the site		35327077K, 78M, 79Y		NEW BUILDING	121187447	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
					and reported that the worker was not using any type of fail arrest system, that the working area was not illuminated with lights, and that there was water on the floor that created a slipping hazard. Three ECB Violations and a full Stop Work Order (FSWO) were issued. The General Contrator at the site is to provide a Means and Methods for the safe operation of the job.								
2018	Brooklyn	4813	9 AVENUE	0	1 The Construction Superintendent reported that a worker was unloading a metal track when the track slid and cut his thumb. The worker went to urgent care for treatment.	No Dispatch					Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
2018	Manhattan	241	WEST 62 STREET	0	1 The Project Manager at the site reported that a worker was carrying a 2 X 4 when he accidentally dropped the 2 X 4 onto the foot of another worker. The injured worker was sent to a hospital for a check up and returned to the site afterwards.						Other Construction Related Incidents	NYC HOUSING AUTHORITY	
2018	Manhattan	500	WEST 33 STREET	0	 The Site Safety Manager reported that an electrician was moving his equipment when he hurt his back. An ambulance was called. 	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker twisted his left ankle while installing rebar. The worker went to a clinic and then returned to the site.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
2018	Manhattan	1059	3 AVENUE	0	The Site Safety Manager reported that during the construction of a thirty story new building, a worker waited into the corner of a steel Feam and hurt his right foot. The worker continued to work, but the Site that the worker was still in pain. The worker was taken to Cornell Hospital for treatment.	No Dispatch					Other Construction Related Incidents	63RD & 3RD NYC LLC	
2018	Manhattan	110	UNIVERSITY PLACE	0	 The Site Safety Manager reported that a plumber was installing a pipe when a piece of debris fell into his eyes. The plumber went to a doctor. 	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Manhattan	455	5 AVENUE	0	 A Project Manager at the site reported that during the installation of floor opening protection, a worker lost control of a plank that hit him in the nose. The worker walked to a clinic. 	No Dispatch					Other Construction Related Incidents	NEW YORK PUBLIC LIBRARY	
2018	Staten Island	35 a	BAY STREET	0	 The Site Safety Manager reported that a worker hurt his arm while removing formwork. The injured worker walked to urgent care. 	No Dispatch			NEW BUILDING	520138379-01-NB	Other Construction Related Incidents		HOLLISTER CONSTRUCTION SE
D18	Manhattan	209	EAST 19 STREET	0	1 The Site Safety Manager reported that an elevator mechanic hurt his lift leg on roll wire that was nudged by a forklift. The worker worked most of the rest of the day before he walked to urgent care on his own.	No Dispatch			NB	121958480	Other Construction Related Incidents	VISUAL ARTS HOLDING CORP	GRAMERCY SQUARE LLC
2018	Manhatian	15	EAST 30 STREET	0	The Site Safety Manager reported that a worker fell down from the first floor supporting deck to the ground and suffered a very bad head injury. The worker was found conscious and was taken to a hospital by ambulance. The worker was reported to be in stable condition. A DOB inspector responded to the incident and veited the safe and reported that the worker was waiking along the re-shores and may have possibly fainted or tripped and in th in lead on one of the re-shores. No enforcement action was deemed necessary, as the inspector did not closerve any lacatious conditions during the time of inspection.	No Action Necessary					Worker Fell	MADISON 30 31 OWNER LLC	
018	Manhattan	122	EAST 23 STREET	0	A DOB inspector reported that an electrical worker at the cellar level was on a twelve foot ladder installing start to seven the St. The worker was not washing a harmosis and was taken to a nearby hospital. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (FSWO) was also issued for all work at cellar levels that requires ladders. A keens and Methods and a Tool Box Taik must be provided.		3532074P		NB	121 190157	Worker Fell	NOT ON FILE	CM AND ASSOCIATES CONSTRU
2018	Manhattan	111	LEROY STREET	0	injured his middle finger while using a pallet-jack. The	No Dispatch					Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
2018	Brooklyn	4813	9 AVENUE	0	worker was sent to urgent care. 1 The Construction Superintendent reported that a worker was carrying a few metal studs when he came into contact with a pipe scaffold tieback and twisted his knee. The worker was taken to urgent care.	No Dispatch					Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
2018	Brooklyn	123	LINDEN BOULEVARD	0	 The Site Safety Manager reported that a worker hurt his arm while moving formwork. The worker was transported to a hospital by another worker. 	No Dispatch			NEW BUILDING	321228603-01-NB	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS LLC



ncident Date	Borough	Address Numbe		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/8/2018	Manhattan	60	GREENE STREET	0	1 A DOB inspector reported that a worker on the first floor was leaving the bathroom when he walked toward a temporary aluminum stair system that he hought was in place and secured. The stairway collapsed and the worker fell to the basement slab below. The worker suffered possible injuries to the neck and head and was able to stand on his own power. The worker received treatment in the enreggency room of a nearly hospital, and eventually returned to the site to pick up his tools. ECB Violations were issued for a failure to safeguard, for there being no plans on site for orgoing construction work, and for there being no plans awailable for a temporary staircase. A full Stop Work Order (FSWO) was also issued.		35314346r 35314347z		AL.	123172217	Worker Feil	NOT ON FILE	SHAWNMUT WOODWORKING & SUP
/8/2018	Manhattan	767	5 AVENUE	0	 The Site Safety Manager reported that a worker was doing waterproofing work in a tree pit on the plaza area. When the worker was walking away, he walked into a metal object that was on the wall. The worker went to a clinic for a check up on his own and will be reporting back to work. 	No Dispatch			ALTERATION 1	122970721	Other Construction Related Incidents		TURNER CONSTRUCTION COMPA
5/9/2018	Brooklyn	242	EAST 45 STREET	0	2 A DOB inspector reported that two workers were working on the eave and gutters of the roof while on pump jacks when the workers fell approximately twenty feet. One of the workers sustained injuries to his wrist, while the other worker sustained a head injury and was in critical condition. Both workers were transported to Kings Courtly Hospital by arbuilance. An ECB Violation, a DOB Violation, and a full Stop Work Order (FSWO) were issued for work being performed without a permit.		35322879R	060918CERMR05			Worker Fell	PRINCE, LINCOLN	
5/9/2018	Manhattan	200	EAST 59 STREET	0	2 A DOB inspector reported that there were two electricians that were working in the utility room on the fourteent floor with their foreman onsite. The workers were working on a panel board when they de-energized the upper half of the panel board. However, the lower half of the board remained live and was not insulated. Both workers were leakenouted and suffered burns, and both workers were leakenouted on suffered burns, and both workers were leakenouted on suffered burns, and both workers were leakenouted on suffered burns, and both workers were leakenouted and suffered burns, and both workers were leakenouted and suffered burns, and both workers were leakenouted and suffered burns, and both workers were leakenouted burns, and both workers were leake		35335966K, 35335967M		NEW BUILDING	121192912	Other Construction Related Incidents	MIPA 59THIRD OWNER LLC	GILBANE RESIDENTIAL CONST
/11/2018	Manhattan	45	BROAD STREET	0	1 A DOB inspector reported that a worker was holding a pin that was to be used to set the auger on a drill rig when another worker hit his finger with a harmer. The struck worker was taken to a nearby hospital and was later released with a bruised finger. An EGB Violation was issued for a failure to safeguard. A pathal Stop Work Order (PSVV) was issued on all use of the auger. The C in the state insaliation of an auger.		35332161J		NB	121190772	Excavation/Soll Work	MADISON 45 BROAD DEVELOPMENT L	pizzarotti LLC
/11/2018	Manhattan	138	EAST 38 STREET	0	1 The Site Safety Manager reported that an iron worker was cutting a tie wire with a utility knife when the knife slipped out of his hand and cut his forearm. The worker was transported to a hospital by ambulance for treatment.	No Dispatch			NB	121186028	Other Construction Related Incidents	TATHAM HOUSE,	TISHMAN CONSTRUCTION CORP
/11/2018	Brooklyn	41	BLUE SLIP	0	process of climbing down an eight foot ladder when he missed a thread at three feet high and fell to the floor. The worker complained of shoulder pain and was taken to a hospital for evaluation. The inspector found no defects to the ladder or the area where the work was being performed. No enforcement action was deemed necessary.	No Action Necessary			Alt 1	320597449-01-NB	Worker Fell	BOP GREENPOINT F LLC	T.G. NICKEL & ASSOCIATES
/11/2018	Bronx	988	EAST 180 STREET	0	1 The Site Safety Manager reported that a worker was cutting water proofing with a sheetrock knife when he accidentally cut his thumb. The worker was taken to urgent care for treatment.	No Dispatch			NB	220152233	Other Construction Related Incidents	988 EAST 180 STREET HOUSING DE	MONADNOCK CONSTRUCTION IN
/12/2018	Manhattan	300	LAFAVETTE \$TREET	0	1 The Construction Superintender reported that there were for underest that we many consider that were more and the oddly signed and caused the crate of glass on a dolly when the dolly signed and caused the crate of glass. It is a struct worker fell to the floor and suffered a back injury An ambulance was called. A Doll'singector responded to the incident and visited the site and reported has the design drawing for the makeshift dolly and that a design drawing for the makeshift dolly work of the (PSWQ) for material handling. A design drawing with load capacity for the makeshift dolly must be provided.		35335881L				Other Construction Related Incidents	LVC 298, LLC	



ncident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Queens	28-30	JACKSON AVENUE	0		ECB Violation			NEW BUILDING	420652886	Other Construction Related Incidents	LIC DEVELOPMENT OWNER, L.P.	HUDSON MERIDIAN CONSTRUCT
/13/2018	Manhattan	15	EAST 57 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder to cut steel when he lost control of the grinder, which caused a small laceration to his foreman. The worker went to a local hospital.	No Dispatch					Other Construction Related Incidents	15 EAST 57TH ST.ASSOC.	
13/2018	Manhattan	701	7 AVENUE	0	 The Site Safety Manager reported that a carpenter was cutting sheetrock with a utility knife when he accidentally cut his forearm. The worker's foreman took him to a City M.D. for treatment. The worker is expected to return to work. 	No Dispatch			ALTERATION 1	121324343	Other Construction Related Incidents	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
5/13/2018	Queens	42-20	27 STREET	0	1 The Site Safety Manager reported that a worker was lifting up the pipe frames of a supported scaffold with a pulley when the worker burned his hands on the rope and dropped the pipe frames of a supported scaffold. The worker was taken to a nearby hospital by a foreman for treatment. A DOB inspector responded to the incident and visited the site and reported that the details of how Volcisions were issued for the failure to perform a supported scaffold installation in a safe mamer and for the failure to provide a supported scaffold encor card. A partial Stop Work Order (PSWQ) for the installation of supported scaffolds was also issued.		35324220R - 35324230Y		SF.	Q0004061341-SF	Material Fell	CRESCENT & 27 LLC	Classic Consulting Group
13/2018	Staten Island	2589	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a water pipe was damaged by a worker on the second floor, which caused a flood on the first floor. One of the store workers at the address slipped and fell. An ambulance was called. A DOB inspector responded to the incident and visited the site and determined that there was no enforcement action necessary, as the work that was being performed was approved under a DOB issued permit.	No Action Necessary			SPRINKLER	540138929	Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	PATRICK BOWE
14/2018	Manhattan	532	WEST 33 STREET	0	 The Site Safety Manager reported that a roof worker complained of pain in the left side of his chest while lifting waterproofing materials. The worker was alert and awake and was taken to Bellevue Hospital by ambulance for treatment. 				NB	121191183	Other Construction Related Incidents	NOT ON FILE	TISHMAN CONSTRUCTION CORP
/14/2018	Brooklyn	210	CLASSON AVENUE	0	1 A DOB inspector reported that during a stripping operation that was taking place between the elevator shaft and north stainvell on the fifth floor, an 'ULMA' formowch beam that was approximately sixteen feet long struck a worker in the head while the worker was attempting to remove the beam. The worker was transported to a hospital, where it was reported that he had suffered a concusion. The worker was select and stable in the hospital. An ECB Violation was issued for a failure to maintian safe operations. A partial Sicp Work Order (FSWQ) was also issued on all concrete work. The General Contractor is to provide a Means and Methods for safe operations.		35336020Y				Other Construction Related Incidents	PRATT INSTITUTE	
14/2018	Brooklyn	1	CLINTON STREET	0	 The Site Safety Manager reported that a worker was walking down from the second floor when he missed his step and fell down. The worker hurt his knee and went to a City M.D. 						Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
14/2018	Bronx	600	BERGEN AVENUE	0	1 The Site Safety Manager reported that a worker was carrying a piece of lumber that was $4 \times 10 \times 7$ when the worker slipped, which caused the lumber to fall onto another worker's hand. The injured worker went to a City M D						Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	
14/2018	Bronx	600	BERGEN AVENUE	0	 The Site Safety Manager reported that a worker hit his foot while unloading a beam. The worker's foreman took him to a first med 	No Dispatch			NEW BUILDING	220151868-01-NB	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
/14/2018	Bronx	1812	VYSE AVENUE	0	I ADDB inspector reported that a worker was taking the delivery of a Concrete Masonov Juni (CMU) block that was being delivered by a lull when his fingerigo separated. The worker's foreman took him to a hospital for treatment. An ECB Violation was issued for the allow to maintain isately measures. A partial Stop Work Order (PSWO) was also all material handling, including deliveries. A second partial Stop Work Order (PSWO) was also all care all sate of a handling, including deliveries. A second partial Stop Work Order (PSWO) was also all care of a scholds in which the horizontal netting was not at the required height. The General netting was not at the required height. The General and worker's orientation before the first stop work order will be rescinded.		35318423J		NEW BUILDING	220152851	Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	HLS BUILDERS CORP



Incident Date	Borough	Address Number	Street	Fatalities Injur	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/18/2018	Brooklyn	15	WASHINGTON AVENUE	0	1 The Site Safety Manager reported that during the final pressure setting impection of a standpipe, the repulsion let the air out of the standpipe, which caused another worker to his avail. He worker compariand of a back ache and an ambulance was called. A DOB impector responded to the incident and wilked the site, and reported that no enforcement action was deemed necessary, as the incident occurred as the result of a worker error.						Other Construction Related Incidents	NYC DSBS	
6/18/2018	Manhattan	110	UNIVERSITY PLACE	0	1 The Site Safety Manager reported that an electrician was using a sheet rock knife to try to cut a conduit when he sliced his left index finger. The worker was escorted to the emergency room at Beth Israel Hospital with another cc-worker to receive treatment.						Other Construction Related Incidents	NOT ON FILE	
6/19/2018	Brooklyn	276	KENT AVENUE	0	A DOB inspector reported that a worker was forming a third floor deck when a retractable laryard device for a safety hanness was left on loose physicol. The deck was not fully planted and had gaps in 1. The worker stepped As a result of this, the retractable laryard device fell to the second floor and this another worker in the back. The worker was in a conscious state laryard device fell to a hospital with no visible injuries. An ECB Violation was susued for the faultre to adeguad persons and propery and for working on two levels simulaneously without a controlled access zone in place. A partial Stop Work Order (FSWO) was also issued to stop al forming operations. The Ganeral Contractor is to provide a Means and Methods and a worker orientation for safe operation.		35327169H		NEW BUILDING.	320916407	Material Foll	DOMINO A LLC	260 KENT CONSTRUCTION LLC
6/19/2018	Brooklyn	306	NORTH HENRY STREET	0	A DOB inspector reported that a contractor had overloaded joist ginders that expanded nighty eight feet with eight bundles of comgated steel decking that were treatly feet. The deckers was placed in a concentrated not properly installed, as the yeare only temporarily installed with one 34 ⁺ both that eventually sheared of and collapsed. This collapse caused the worker to fail forty feet to the ground. EMS was called and the worker was found atert and responsive when EMS arrived. The worker suffered a broken shoulder and possible back injuries and was taken to a nearby hospital. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard, as well as a full Stop Work Order (FSWO).		36336227L		EW-OT	340499080	Worker Fell	300 NORTH HENRY LLC	R, KING WINDOW CORP
6/19/2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that a worker was removing a kitchen cabinet when he was hit in the head by the cabinet when it became loose. The worker suffered a cut to his face. The worker went to a City M.D to receive treatment and will return to work.				NEW BUILDING	121191913	Material Fell	95TH AND THIRD LLC	GILBANE RESIDENTIAL CONST
6/19/2018	Queens	36-18	MAIN STREET	0	 The Site Safety Manager reported that an elevator company worker was putting down counter weights when his finger got pinched between the weights. The worker went to a City M.D. 	No Dispatch					Other Construction Related Incidents	134-22 35TH AVE., LLC	
6/19/2018	Queens	37-09	COLLEGE POINT BOULEVARD	0	A DOB impedior reported that a worker was installing guardrails on the parimeter of the job site when he was saked to help install-C-decking at the second floor. When the worker went to get a torch to help tim the deck, the worker went to get a torch to help tim the deck, the worker went to get a torch to help tim the deck the the worker went to get a torch to help tim and field apprime toely lifeting, hevee, jurch the The worker was found conscious and was taken to Flushing Hospital by ambulance. An EGP Volation was issued to a failure to stafeguard, as well as patrial Stop Work Order (PSWO) on building two on all statel exection and deck kipyud. A set specific Means and Methods for the provided. A set specific Means and Methods for the provided. A set specific Means and Methods for the provided.		ECB#35327475X		NB	420653607	Worker Fell	NOT ON FILE	TOP 8 CONSTRUCTION CORP
6/20/2018	Manhattan	328	EAST 62 STREET	0	1 A DOB inspector reporter that hare were workers that were getting trady to cut out and remove a rater sector that was connected to the Support Of Excertain (SOE) water and prototing through the foundation walls. The Construction Superintendent at the site stated that the section needed to be removed for the completion of a waterprofing installation. During the process of preparing jackhammers to chip out the concrete around the raker pit, a worker slipped and fell approximately four leaf into the raker pit, and/ong on the back. The worker got out of the raker pit and valided to a hospital with a co- to be okky. An ECD Violation was issued because there were quard rails missing. An additional ECD Violation was issued for the failure to provide a Means and Methods for the removal of S.O.E. sections. A partial S.O.E. sections.		35332281Y-35332282X		NB	121189846	Woker Fell	YYY 62ND STREET LLC	Joy Construction corp



ncident Date	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
20/2018	Manhattan	300	LAFAYETTE STREET	0	1 A DOB inspector reported that there were electricians moving spools down a flight of sairs when they lost control of one of the spools, which hit one of the workers in the lag. The worker was taken to a hospital by ambulance. An ECB Violation was issued for a failure to maintain safe operations. A partial Stop Work Order (PSWO) was also issued for all heavy material handling. A Means and Methods must be provided.	ECB Violation	35331146R				Other Construction Related Incidents	LVC 298, LLC	
20/2018	Manhattan	25	SUTTON PLACE SOUTH	0	1 A DOB inspector reported that a worker was attempting to lower a chipping gun from a root to a setback to another worker when he accidentally dropped the chipping gun approximately twenty feet, hitting the other worker on his hard hat. The struck worker was admitted into Correll Medical Center, where he received sitches. This incident occurred on June 19, 2018, but was not reported until une 20, 2018. Twe DCE Violations were issued: an Aggravated Level 2 violation for the failure to model and second violation for the failure to immediately notify the Department Of issued. A partial Stop Viol Arobit was issued for the lowering of any tools or equipment from a root to a setback without a DOB approved Means and Methods.		36322737Y 36333276Y	062018CNESC01 062018CNEGS01	ALTERATION TYPE 2	122907426-01-EW-OT	Other Construction Related Incidents	CANNON POINT NORTH INC	DNA CONTRACTING LLC
0/2018	Manhattan	1558	3 AVENUE	0	The Site Safety Manager reported that a garbage truck was passing by when it hit a barrier that hit a worker. The worker complained of back pain and walked to urgent care	No Dispatch					Other Construction Related Incidents	180 EAST 88TH STREET REALTY LL	
20/2018	Manhattan	1227	BROADWAY	0	1 The Site Safety Manager reported that a worker was cleaning and moving materials when he moved a job site box that was next to two hollow steel doors. The two follow steel doors fell and hit the worker's shoulders, causing him to fall. An ambulance took the worker to a hospital for a check up.	No Dispatch					Other Construction Related Incidents	YJL BROADWAY HOTEL LLC	
21/2018	Brooklyn	583	LORIMER STREET	0	1 A DOB inspector reported that a worker injured his finger while using a drill during steel erection/modification work because the drill was used contrary to the manufacturer's specifications. The injured worker was sent to a hospital, where he received sitiches. This incident occurred on June 21, 2018, but was not reporter until June 22, 2018. Four ECB Violations were issued. These violations include a violation for a failure to maintain asted operations, a violation for the use d a drill contrary to the manufacture's specifications, and a violation for the failure to notify the Department Of Buildings of the incident in a timely manner.		35331149M, 1450L,1451N, 1452P				Other Construction Related Incidents	583 LORIMER LLC	
1/2018	Brooklyn	77	CLARKSON AVENUE	0	1 A DOB inspector reported that a worker was working on a platform dock when he fell approximately six Ket to the lower level. The worker was found conscious and alert and was taken to a nearby hospital. An Aggravated Leve 2 ECB Violation was issued for the failure to asfeguard. A DOB Violation was issued for the failure to asfeguard. A DOB Violation was issued for the work being conducted at the fifth floor.		35309269X	062118CNERWS01	Alt - 1NB	321197771	Worker Fell	CLARKSON BU LLC	DAWNY CONSTRUCTION LTD
21/2018	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that an iron worker was working inside an elevator shaft on a man basket when an object fall from above and struck and cut the worker's arm. An ambulance transported the worker to a hospital for transment. A DOB inspector responded to the incident and visited the site and reported that design drawings for working platforms were provided, a certification for the usage of a scaffold was provided, an gravings for working platforms were provided. The inspection. However, an ECB Violation was issued for inspection. However, an ECB Violation was issued for the failure to notify the DOB Scaffold Safety Team for the presence of a suspended scaffold on the site. A partial Site Vition (Vor (PSWO)) also sub for all work in an elevational that. A Means and Methods for all safe operations in a shaft must be provided.	9	36331147Z	062118BS04SA01			Material Fell	CBP 441 NINTH AVENUE OWNER, LL	
/21/2018	Manhattan	45	BROAD STREET	D	1 A DOB inspector reported that contractors were transporting material with an excavator when the knuckte of the machine stuck the Concrete Masonry Unit (CMU) wall of the adjacent property (55 Broad Street, Broad Street, Street, Street, Street, Street, discloged a small section of concrete block that struck a customer that was eating funch inside of the restaurant. The customer suffered an injury to his left leg and was transported to New York Prebyterian Hospital by an ambulance. There were no structural concerns found. However, the restaurant has been closed. The damaged building's engineer will provide a Means and Methods fo repairs. An Aggravated Level 2 ECB Violation was issued for a failute to safeguard. A full Stop Work Order (FSWO) was issued for the entire site.	r	363322B3h		FO	121190772	Material Fell	MADISON 45 BROAD DEVELOPMENT L	Pizzarott LLC



aldent D-f	Barauch	Address Number	Phone	Fetel///	EQC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Truce	Owner's Name	Contractor Name
cident Date 22/2018	Borough Manhattan	Address Number	Street EAST 30 STREET	Fatalities Injurie	s EOC Final Description 1 The Site Safety Manager reported that a worker dropped		ECB violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type Material Fell	Owner's Name MADISON 30 31 OWNER LLC	Contractor Name
2010	Walliatan	15	EKST 50 STREET		a coupling on his foot during a rebar installation. The worker suffered a swelled foot and went to urgent care	NO Dispatch					Material Feil	INADISON 30 ST OWNER EEG	
					with a co-worker.								
018	Manhattan	315	EAST 46 STREET	0	1 The Site Safety Manager reported that a worker bent	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
					down to plug in an extension cord and hit his head on a stored piece of rebar. The worker went to urgent care.								
018	Manhattan	100	CHURCH STREET		1 A DOB inspector reported that at a nineteen story	ECB Violation	35327483X, 84H, 85J, 86L				Material Fell	100 CHURCH FEE OWNER LLC	R&S CONST. CONTRACT. INC
/10	Wannattan	100	CHURCH STREET	0	building that was having alteration work performed on it,		3332/463A, 64H, 65J, 66L				Material Pell	100 CHORCH FEE OWNER LLC	Ras CONST. CONTRACT. INC
					there were workers installing and welding sewer pipes or	n							
					the eigth floor utility shaft using a "Jewel Clamp" that keeps the pipes in position. The "Jewel Clamp" slipped								
					out of the hands of one of the workers and fell through								
					the shaft. The clamp bounced on the third floor and								
					landed in the cellar, where it hit another worker on his hand. The injured worker suffered cuts and bruises on								
					his arm, but did not suffer a broken bone. The injured								
					worker was taken to a hospital, where he received stitches. Four ECB Violations were issued: one an								
					Aggravated Level 2 violation for a failure to maintain								
					safety measures, a second violation for working on two								
					levels simultaneously without protection or a Controlled Access Zone (CAZ) in place, a third violation for working								
					without a permit, and a fourth violation for the absence of	ŧ							
					guardrails at open shafts. A full Stop Work Order								
					(FSWO) was issued as well. The General Contractor at the site is to obtain a permit and provide a Means and								
					Methods and a workers' orientation for safe operation at								
					the site before the Stop Work Order will be rescinded.								
2018	Queens	5	COURT SQUARE	0	1 The Site Safety Coordinator reported that a construction	No Dispatch			NB - NEW BUILDING	420902410	Worker Fell	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
					worker tripped and sustained a minor knee injury. EMS was called and the worker was transported to a local								
					hospital.								
2018	Manhattan	505	WEST 43 STREET	0	1 The Site Safety Manager reported that a worker was standing on an "A"-Frame ladder while performing a	ECB Violation	35300588M		NEW BUILDING	121187456	Worker Fell	NOT ON FILE	NEW LINE STRUCTURES & DEV
					grinding operation on the fourteenth floor of a concrete								
					wall surface when the ladder slipped, causing the worker	r							
					to fall. The worker was found unconscious. An ambulance was called and the worker was transported to								
					a hospital in a conscious state. A DOB inspector								
					responded to the incident and visited the site and issued	I I							
					an ECB Violation for the failure to maintain safety measures. A partial Stop Work Order was issued on all								
					grinding operations. The General Contractor at the site is	5							
					to provide a Means and Methods for safe operation.								
/2018	Manhattan	149	EAST 125 STREET	0	2 A DOB inspector reported that a Jekko crane machine on the fourth floor was in the process of placing a curtain				NEW BUILDING	121192388	Mechanical Construction Equipment	NOT ON FILE	ZDG, LLC
					wall panel on the third floor when the machine fell from								
					the fourth floor and two connectors also fell from the third floor. One worker fell from the third floor to the street and	d .							
					suffered a critical injury, and a second worker that was	1							
					on the third floor was struck by crane components and								
					suffered a non-life threatening back injury. Both injured workers were taken to a hospital. The inspector reported								
					that the injured workers were not tied off and that the								
					operation was not permitted, as there were no valid								
					permits, plans, or rigging certifications present. The crane operator did not have any certifications. The								
					inspector reported that the incident may have occurred								
					because the crane was overloaded, and that a Means								
					and Methods for hoisting and rigging, for overloading, and for safeguarding was not provided. DOB's BEST								
					and for safeguarding was not provided. DOB's BEST Squad issued a full Stop Work Order (FSWO) due to the								
					existence of multiple safety issues. DOB's Cranes and Derricks Unit also issued a Stop Work Order on all								
					hosting operations. Eight totals ECB Violations were								
					issued, as there were separate violations issued to both								
					the General Contractor and the crane user at the site for an unsafe operation, for the failure to safeguard, for the								
					absence of a valid HMO License or certifications, and for	r							
					not being in possession of 16 or 32 hour rigging certifications.								
					ceruncauoris.								
018	Brooklyn	420	ALBEE SQUARE	0	1 The Site Safety Manager reported that the Construction Superintendent was moving material on a pallet jack by	No Dispatch					Other Construction Related Incidents	JEMB ALBEE SQUARE LLC	
					himself when he hit a divet. The Construction								
					Superintendent tried to stop the piece of material that was being moved from falling, but the material fell on his								
					ankle. An ambulance was called.								
		1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
2018	Brooklyn		-LING OT OTTALL I	0	picking up a garbage bag when he backed into stacked						Construction Related Inductits	L. DIS REFICEO CONTENTS	
018	Brooklyn												
018	Brooklyn				rebars and suffered a scratch to his right calf. The worke	r							
		2028	CRESTON AVENUE	0	rebars and suffered a scratch to his right calf. The worke walked to a City M.D.						Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	
018	Brooklyn Bronx	2028	CRESTON AVENUE	0	rebars and suffered a scratch to his right calf. The worke						Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	



	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was fueling a generator when fuel was spilled on his arm. Th worker walked to a City M.D. as a precaution.				NEW BUILDING	321197478-01-NB	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
26/2018	Manhattan	1	BEEKMAN STREET	0	1 The Site Safety Manager reported that the diamond plate in a hoit car was not secured and that the diamond plate fell over and hit he ankle of a worker that was in the hoist. An ambulance was called. A DOB inspector responded to the incident and visited the site and issue an ECB Violation for the failure to institute safety measures for the diamond plate in the hoist. A DOB Violation was also issued. As of the time of inspector, th diamond plate was made secure.	4	38342761Z	062618BS01KR01			Other Construction Related Incidents	ONE BEEKMAN OWNER, LLC	
7/2018	Manhattan	1	WEST END AVENUE	0	1 A DOB inspector reported that workers were in the process of dimensiting a fourteen loch high addweak shed when one of the workers fell back between the junice beams. The worker was experiencing minor back pain and was taken to a local hospital by ambulance. Ar- ICCB Violaton was issued to the sidewark shed compan for the failure to safeguard all persons and property.	1	35324259H		Shed	M00023179	Worker Fell	NOT ON FILE	Colgate Enterprises Corp
3/2018	Manhattan	400	WEST 61 STREET	0	1 The Site Safety Manager reported that a worker was carrying material down a flight of stairs when he missed the last step. The worker suffered a shoulder injury and was taken to a hospital by ambulance.						Worker Fell	RCB1 NOMINEE LLC	
8/2018	Manhattan	61	9 AVENUE	0	1 The Site Safety Manager reported that a worker was doing sheet metal work with a screw gun when he accidentally drilled a screw into his right hand. The worker was transported to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	G.D.C.L. HOLDINGS LLC	
9/2018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker was going on a break when he opened a box and the lid of the box fell on his hand, causing a laceration to his middle finger. The worker went to a hospital for a check up.						Other Construction Related Incidents	NYC DSBS	
9/2018	Brooklyn	856	WASHINGTON AVENUE	0	1 The Sile Safety Managor reported that a section of sidewalk caved due to a min strom that occurred on June 28, 2018. A pedestrian stepped into the caved in socion of sidewalk and that ther ankle, knee, and shoulder. An ambulance was called and the pedestrian was taken to a hospital by ambulance. A DOB inspector responded to the incident and visited the site and reported that there were cracks along the section of sidewalk that caved in during the rain storm, which may have contributed to the cave in The area was being back filled while the inspector was on site. An ECB Violation was issued for a failue to maintain the sidewall		35335889J	062918BS08PK01			Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
9/2018	Manhattan	111	LEROY STREET	0	 The Site Safety Manager reported that a window installe was taking suction cups off of a window when he pulled his back. An ambulance was called. 	r No Dispatch					Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
29/2018	Queens	33-02	30 AVENUE	0	1 A DOB inspector reported that a worker was using a concrete trowell machine when he came upon a floor opening. The worker was using the machine close to the exterior well when he has the well, which cased the worker and the machine fell approximately twelve feet into the basement. The New York City Fire Department removed the worker and EMS took the injured worker to a hospital. Two ECB Violations were issued, including one Aggravated Level 2 violation for a failure to safeguard and a second violation for the failure to post project information panel. Two DOB Violations and a ful Stop Work Order (FSWO) were also issued.	9 8	35334832K & 35334833M	062918CERRJ01 & 062818CERRJ02	ALTERATION TYPE 1	420474347-01-AL	Worker Fell	ANDREW G GEORGIOU TRUST FUND B	CENTRAL BUILDERS DEVELOPM