

			r Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
cident Date 2/2018	Manhattan	13	EAST 7 STREET	0	1 The New York City Police Department reported that an exterminator fail into a six for deep excavation in the basement. A DOB inspector reported that the worker suffered minor inguines and was taken to Bellevue Hospital and that there was unpermitted executation work being performed in the basement. An Aggravated Level 2 EGB Violation was issued for a failure to safeguard and work without a permit. A full Stop Work Order was issued.	ECB Violation	35309613X		No Permit	No Permit	Worker Feil	TRIAD CAPITAL, LLC	No Permit
3/2018	Manhattan	269		0	¹ The Site Safety Manager reported that a worker was cleaning a platform from a multipoint scaffold when he slipped and fell five feet out the ground, hitting his right elbow. An ambulance was on site. Four ECB Violations and a partial Stop Work Order were issued.	ECB Violation	35285606Y, 35285607X, 35285608H, 35285609J				Worker Fell	RIVERVIEW OPERATING CO., LLC	Leeding Builders Group LLC
/2018	Manhattan	430	EAST 58 STREET	0	1 The Site Safety Manager reported that a worker got his hand stuck between a steel plate and a frame and got two of his fingers crushed. The worker was sent to Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	SUTTON 58 HOLDING COMPANY LLC	
/2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that a worker was loading garbage into a truck when he slipped on snow and hurt his arm. The worker walked to urgent care.	No Dispatch				_	Other Construction Related Incidents	95TH AND THIRD LLC	
/2018	Manhattan	301	FREEDOM PLACE SOUTH	0	1 The Site Safety Coordinator reported that a worker was unloading glass from a crate when a piece of glass fell and injured his leg. The worker was taken to a hospital. The extent of the worker's injuries was not known.	No Dispatch			NEW BUILDING	121192501-01-NB	Worker Fell	301 FREEDOM PLACE SOUTH, LLC	SCIAME CONSTRUCTION LLC
/2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Managor reported that a worker on the twenty touth flow slipped on a patch of ice and hun his shoulder. An ambulance was called to the site. A DOB inspector responded to the incident and reported that diamond plates on the outside of a hoist had water and ice on them, which caused the worker to site. An ECB Violation and a DOB Violation were issued.	ECB Violation	35301051R	010818BS02DH03			Worker Fell	G & M REALTY, LP.	
2018	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that a worker slipped on a second floor concrete deck, landed on his back, and hurt his shoulder. The worker slipped because of snow. The worker walked to a City MD. A DDB inspector visited the site and confirmed that the deck was covered with snow, which caused the worker to fall. An ECB Violation, a DDB Violation, and a partial Stop Work Order were issued.		35301164N	010918BS02VP01			Worker Fell	40-56 TENTH OWNER LLC	
2018	Manhattan	400	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was handing down a screw-pick to another worker when becrew-pick signed out on its hands and hit the other screw-pick signed out on its hands and hit the other another state of the state of the state of the state hospital by ambulance for a check up. A DOB inspector issued an ECB Violation, a DOB Violaton, and a partial Stop Work Order.		35301055Y	010918BS04DH03			Material Fell	BOP NE LLC	
/2018	Staten Island	55	RICHMOND TERRACE	0	1 The Site Safety Manager reported that a worker slipped on ice. An ambulance was called. A DOB inspector reported that the worker slipped on ice that was located in an area that was closed off and where there was no work in progress. No enforcement action necessary.	No Action Necessary					Worker Fell	ST. GEORGE OUTLET DEV LLC	
/2018	Queens	27-17	42 ROAD	0	1 The Side Safety Manager reported that a worker was installing sheet rock when he cut his left hand on a metal duct. The worker went to urgent care with another worker.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
2018	Manhattan	130	EAST 82 STREET	0	worker. 1 The Site Safety Coordinator reported that an electrician was pulling cables in a box when he pulled his hand back and cut it on a piece of Chicago Bar. The incident occurred on 1/10/2018, but was not reported until 1/11/2018. The worker went to a doctor on his own.	No Dispatch			NEW BUILDING	121328027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
/2018	Manhattan	118	FULTON STREET	0	1 A DOB inspector reported that a worker attempted to move an 'A'-Frame cart that was loaded with about toweny flat stock metal aheets when the metal sheets fell onto his leg. The worker may have possibly suffered a broken leg. An EMT was on site. An EOB Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Methods for safe operations.		35300526R				Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	
2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager and a DOB inspector reported that a carpenter was standing on an 'A' Frame Iadder to remove the door frame from an electrical closet on the 51st floor when a piece of plywood that was behind the door frame canne lose and hit him in the shoulder, causing him to fail of id the ladder. The worker hospital by ambudance. A DOB inspector reported that there were no unsafe or hazardous conditions at the working area. No enforcement action was necessary.	No Action Necessary			New Building	121333440	Worker Fell	CP V TS FULTON OWNER, LLC	CP V TS FULTON OWNER LLC
/2018	Manhattan	151	MAIDEN LANE	0	1 A DOB inspector reported that a worker was using an "A" Frame cart to move scatfolding elements when he twisted his wrist while pulling the cart. The worker did not want to go in an ambulance and went to see a doctor on his own. There were no unsafe of hazardous conditions.				New Building	121186769	Other Construction Related Incidents	151 MAIDEN LLC	PIZZAROTTI IBC LLC



a worker tripped No Dispatch wisted his right site and took the	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
visted his right site and took the					Worker Fell	305 EAST 61ST STREET GROUP LLC	
a pedestrian ECB Violation	35300326M	011118BS05MA03		_	Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	
e upper sidewalk					Julia		
e pedestrian went plation was							
a carpenter was No Dispatch			NEW BUILDING	420993740	Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	DISANO DEMOLITION CO, INC
and hit the worker							
hospital for a							
worker was ECB Violation	35263168X	011218CERMR01	NEW BUILDING	121185635-01-NB	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
stween the pump							
causing a large							
he concrete pre-							
was part of the							
r were issued.							
worker was ECB Violation	35294740J	011518CERFC01	Alt 1 NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
mical sealant to							
came							
a. An ECB							
I Stop Work							
a worker pulled No Dispatch			alt 1 NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LEND LEASE (US) CONSTRUCT
r went to a			un THD	121021224			
a worker was No Dispatch			alt 1 NB	121325027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
when the							
iced his hand.							
worker was No Dispatch					Other Construction Related Incidents	NYC HHC	
fell onto his left							
by a friend.							
FCD Viel-	2520055214				Other Construction Deleted loc 11-11-	NC 425 11 C	
a stripping	35300553M				Other Construction Related incidents	VS 125 LLC	
king one above							
rom above onto alled An ECB							
were issued.							
provide a Means							
an iron worker No Dispatch			NEW BUILDING	121186849	Mechanical Construction Equipment	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
etal bar when the							
the worker's quards in place.							
ity for treatment.							
a worker was No Dispatch as using a 2 X 4			NEW BUILDING	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
as using a 2 X 4 rate when the							
he head, causing							
he head, causing d the worker eck up.							
he head, causing d the worker eck up. e struck a manlift ECB Violation	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
e head, causing d the worker eck up. e struck a manlift ECB Violation a no occupied	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
e head, causing d the worker eck up. e struck a manlift ECB Violation a na occupied vater and a is not damaged,	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
e head, causing d the worker eck up. estruck a manlifit a sn cccupied vater and a s not damaged, g pain, and the	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
e head, causing d the worker eck up. a struck a manilit an an occupied water and a s not damaged, g pain, and the ent. Both of the eck up. An ECB	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
the head, causing d the worker ext up. e struck a manifit an occupied vater and a s not damaged, g pain, and the en. Both of the	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
e head, causing d the worker eck up. a struck a manilit an an occupied water and a s not damaged, g pain, and the ent. Both of the eck up. An ECB	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
a vorker was ECB Violation	35300560K 35300560K 3530559M 353055		NB	122887224	Other Construction Related Incidents	KINGSWAY REALTY LLC	Marc Depaul
he head, causing d he worker exk up. s struck a manift an occupied water and a is not damaged, g pain, and the enk Buh of the exk up. An ECB ware is and the exk up. An ECB ware is a contract of the ext of the structure is a contract of the a worker was ECB Violation			NB	122887224			Marc Depaul
he head, causing d the worker exk up. a munift sort cut, are munift exter and a sort cut, are munift and coupled water and a sort cut, and the exk up. An ECB water sort cut, and exk up. An ECB water sort cut, and exk up. An ECB by Collection the worker was the worker was			NB	122887224			Marc Depaul
he head, causing different of the worker was to be worker's table and the worker's table and t			NB	122887224			Marc Depaul
he head, causing different of the worker each up. ECB Violation an anoccupied water and a nor damaged in an decupied in a service is such as a worker ware is such as a worker ware is such as a worker water is and the each up. An ECB worker ware is such as a worker water is the water if the water if it by a co-s soo Work Order is a such as a worker water is a w			NB	122887224			Marc Depaul
he head, causing different of the worker - take up an another of the worker's take - struck a manifit sort damaged is not damaged in the sort damaged is the sort damaged is			NB	122857224			Marc Depaul
he head, causing dress with the worker was an occupied on the worker was an occupied sort damage and a sort damage of the sort			NB	122887224			Marc Depaul
he head, causing drive worker exk up. 2 struck a manift struck aran and star occupied water and a snot damaged. g pain, and the enk. Both of the exk up. An ECB ware issues that was fifting that was fifting to between the g the worker's Mathods to			NB	122887224			Marc Depaul
he head, causing different of the worker was not demonstrated by a worker was here was here was here was here was directed by a Methods by a Dispatch of the stream of the section of the stream of the was filling by consistent of the stream of the was here was directed by a Methods by a Dispatch of the stream			NB	122887224	Mechanical Construction Equipment	AMSTERDAM AVENUE REDEVELOPMENT	Marc Depaul
he head, causing drive worker exk up. 2 struck a manift struck aran and star occupied water and a snot damaged. g pain, and the enk. Both of the exk up. An ECB ware issues that was fifting that was fifting to between the g the worker's Mathods to			NB	122887224	Mechanical Construction Equipment	AMSTERDAM AVENUE REDEVELOPMENT	Marc Depaul
uh avisti ihestr aferciel ar ave affill agkfrar aeog	ut or injunies. An hospial for a worker was handle character of the hospial for a larger of the hospial ho	ut or injuries. An honeha concrete tween the purpose a worker was he occurrent pre- was part of the toron, a DOB r werder work he concrete pre- tween be purpose to a DOB r worker work mical selant to came loud. The Worker No Dispatch No Dispatch No Dispatch a worker was a stropping a stropping	ut or injuries An hospial for a worker was hospial for a worker was he nume concrete twee hospial of a large A. A DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for a large A. B DOB for twee hospial for twee hospi	ut or injunis An hospial for a worker was how how hospial for a store rwas his his his hospial for a store rwas his his his his his his his his his hi	ut or inspire An Image: Constraint of a constra constraint of a constra constraint of a constraint of a constrai	ud er bighelf for an enskelfer for enskelfer	d or gunder a a andra men de la contraction Related Incidenci E andra men de la contraction Related Incidentes a serier and a la contraction Related Incidentes a serier a a contraction Related Incidentes a serier de la contraction Related Incidentes a



cident Date	Borough	Address Numbe	r Street	Fatalities Injuri		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	445	WEST 35 STREET	0	1 The Site Safety Manager reported that a worker was moving a wooden plank while taking down a single fram scaffold when he twisted his knee and complained of pain. The worker went to see a doctor on his own.	No Dispatch					Other Construction Related Incidents	CARE REALTY CORP.	
2018	Brooklyn	3003	WEST 21 STREET	0	1 The Site Safety Manager reported that a worker twisted her ankle while pushing a mini-dumpster. An ambulance was called and took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	CONCERN SURF VETS PLACE HOUSIN	
2018	Brooklyn	19	KENT AVENUE	0	The Site Safety Manager reported that a worker was setting up a mobile crane when his finger got pinched between the hock of the crane and a road barrier, causing the finger to detach. A co-worker took him to a hospital. Five ECB Violations and a partial Stop Work Order were issued.	ECB Violation	3505625p, 26r, 27z, 28k, 29m		CRANE NOTICE	871 17	Mechanical Construction Equipment	19 KENT ACQUISITION LLC	ALL ISLAN MASONRY & CONCRETI
2018	Bronx	16	EAST 204 STREET	0	1 The Site Safety Manager reported that a worker slipped and hurt his back at the job site. An ambulance was called and took the worker to a hospital.	No Dispatch					Worker Fell	HP VILLA GARDENS HDFC, INC.	
/2018	Manhattan	26	ANN STREET	0	1 The Site Safety Manager reported that a worker hurt his hand while taping and spackling on the ninteenth floor. The worker went to urgent care.	No Dispatch					Worker Fell	143 FULTON STREET DEVELOPMENT	
2/2018	Queens	29-22	NORTHERN BOULEVARD	0	1 A DOB inspector reported that a worker was pushing an "At-Frame curit that was loaded with shore when the cart overturned, causing stone to fall onto the worker's foot and possibly breaking the foot. An EMT was on site. An ECB Violation and a partial Stop Work order were issued. The General Contractor is to provide a Means and Methods and a Tool Box Talk.	ECB Violation	35229063P				Material Fell	QSB NORTHERN LLC	
/2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a worker cut his finger while cutting a piece of rebar. EMS was called. The worker was found conscious and was taken falled.	No Dispatch			ALTERATION TYPE 1	321185953-01-AL	Worker Fell	THE SALVATION ARMY	SD BUILDERS AND CONSTRUCT
/2018	Brooklyn	138	WILLOUGHBY STREET	0	to an area hospital. 1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NYC HPD	
3/2016	Brookyn	130	WILLOUGHDI SIKEEI	0	This site Safety Manager reputed that a worker was doing form work with while he had his peligian hook attached to himself. When the worker was climbing down a ladder, the peligan hook faill and hit his right ear. The worker went to a City MD. An ambulance was not called. This incident was the result of a worker error.								
3/2018	Manhattan	111	EAST 24 STREET	1	O A DOB inspector reported that an elevator foreman was working on a platform for installing an elevator inside the elevator shaft at the sish floor when the platform starked drifting upwards uncontrollably and would not stop. The worker tried to jump to the machine room on the other platform at the innih floor, where he succumbed to his harms to me callest floor, where he succumbed to his harms so may alwas not the dot anything. There were no safety lines found at the site. A DOB Violation and a full Stop Work Order were issued.			012318BS0501BG	NB	121192798	Worker Fell	DEMETRIOS & FANIA SAMUEL, LLC	TRINITY BUILDERS INC
2018	Queens	62-98	SAUNDERS STREET	1	O The New York City Police Department reported that a worker was standing on a window all of a sixth floor method of the sixth of the sixth floor method. The worker was transported to North Shore University Hospital, but was found doad on arrival by the NYED. A DOB inspector inspected the sixth and reported that there was work present that consisted of a gut renovation to the bathroom, the installation of new electrical wiring and box, and the installation of new sheetrock, without a permit. Twe ECB Violations, word DOB Violations, and a Stop Work Order were issued.		35308671J, 35308670H	012318CERTQ01, 02			Worker Fell	NOT ON FILE	
/2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker got concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
4/2018	Manhattan	280	PARK AVENUE	0	1 The Construction Superintendent reported that an electrician was working on a live splice box when he was shocked and got two of his fingers burned. The worker went to a hospital. This incident took place on January 4, 2018, but the Department Of Buildings was not notified until January 23, 2018. An EGB Volation was issued for electrical work being performed without a permit. A DOB Violation was also issued.	ECB Violation	35312686Y	012018EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
4/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle. The driver did not want to listen to the flagger. The flagger was okay, but was taken to a hospital by an ambulance for a checkup.	No Dispatch					Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	
5/2018	Manhattan	2	PARK PLACE	0		No Dispatch			ALTERATION TYPE 1	121333413-01-AL	Worker Fell	NOT ON FILE	CNY CONSTRUCTION LLC
6/2018	Manhattan	102	West 188 Street	0	1 A DOB inspector reported that a worker was climbing up an "A"-Frame ladder from the first floor to the second floor when a rung on the ladder snapped, causing the worker to fail ten feet and land on his back. The worker was found conscious and was taken to the hospital by EMT personnel. An EOB Violation and a full Stop Work. Order were issued. The site will received a full audit due to site conditions.	ECB Violation	35310351n		ALT	122917503	Worker Fell		allba services



26/2018	Borough	Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	44	UNION SQUARE	0	1 The Site Safety Manager reported that a worker at a	No Dispatch					Other Construction Related Incidents	READING TAMMANY OWNER LLC	
					concrete truck had a miscommunication with the driver and the shoot came down and hit the worker on the								
					hand. The worker suffered a minor injury and an								
					ambulance was called.								
018	Manhattan	450	WEST 33 STREET	0	1 A DOB inspector reported that during a demolition	ECB Violation	35310356M		Alteration 2	140188767	Material Fell	450 PARTNERS LLC	Tishman Construction Corp
					operation on the first floor of the HVAC conduits and								
					utilities lines, a construction worker was cleaning								
					demolition debris on the first floor when a pipe section fell approximately four feet and hit the worker in the								
					tell approximately four feet and hit the worker in the head. The pipe section fell because another worker cut a								
					strap pipe that was holding the pipe section. The worker								
					who was hit by the pipe section initially refused medical								
					attention, but wasn't feeling well after a few hours and								
					called EMS. The worker was taken to a hospital by								
					ambulance. A Construction Superintendent was not								
					required at the site. An ECB Violation and a full Stop								
					Work Order were issued. The General Contractor must								
					provide a Means and Methods for the demolition of the remaining HVAC conduits.								
					remaining rivide conduits.								
2018	Manhattan	500	WEST 33 STREET	0	1 A DOB inspector reported that an electrician was in the	No Action Necessary			NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
					process of erecting a shanty while climbing an eight foot ladder when he missed a rung of the ladder and fell three								
					feet. The worker was taken to Bellevue Hospital. A DOB								
					inspector visited the site and reported that no								
					enforcement action was deemed necessary.								
2018	Brooklyn	404	11 STREET	0	1 A DOB inspector reported that workers were receiving a	ECB Violation	35310458N		Alteration	321190858	Other Construction Related Incidents	404 11TH ST NY CORP	SUN SUN Contracting
					load of concrete masonry unit (CMU) brick on the third floor when the third floor C-Joists towads the rear of a								
					floor when the third floor C-Joists towads the rear of a new extension partially collapse due to excessive weight								
					and because the C-Joists were not properly secured to								
					the CMU wals. The collapse also caused the second and								
					first floors to collapse into the cellar. One worker								
					sustained minor injuries and was taken to Brooklyn								
					Presbyterian Hospital. An Aggravated Level 2 ECB								
					Violation and a full Stop Work Order were issued for a failure to safeguard. A sidewalk shed has been								
					requested to be immediately installed at exposure four.								
					DOB will remain on site until the sidewalk shed is								
					installed. The site will be referring to DOB's Interior								
					Demolition Engineering Unit for audit and approval of all								
					temprary shoring.								
2018	Brooklyn	422	FULTON STREET	0	1 The Site Safety Manager reported that a worker fell through the interior opening for a tower crane installation	No Action Necessary					Worker Fell	NOT ON FILE	
					from the ninth floor to the eighth floor. The worker was								
					taken to a hospital, where he was eventually released								
					with no injuries. The worker did attend a safety								
					orientation meeting at the start of his shift. A DOB								
					inspector visited the site and reported that there was								
					proper signage and a proper guardrail system present at the perimeter of the slab opening, but that the worker								
					disregarded all safety measures provided to prevent								
					disregarded all safety measures provided to prevent falling hazards. No enforcement action was necessary.								
						No Dispatch				121724946-01-AL	Worker Fell		
/2018	Manhattan	209	EAST 19 STREET	0	1 The Site Safety Manager reported that a worker was	no biopaton			ALTERATION TYPE 1			227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
/2018	Manhattan	209	EAST 19 STREET	0	using a grinder to cut an angle when the grinder jumped	ino Disputan			ALTERATION TYPE 1			227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
/2018	Manhattan	209	EAST 19 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on	no Dispatori			ALTERATION TYPE 1			227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
2018	Manhattan	209		0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.				ALTERATION TYPE 1			227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
	Manhattan Manhattan	209	EAST 19 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.				ALTERATION TYPE 1		Other Construction Related Incidents	227 EAST 19TH STREET OWNER, LL NOT ON FILE	GRAMERCY SQUARE LLC
				0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An				ALTERATION TYPE 1		Other Construction Related Incidents		GRAMERCY SQUARE LLC
2018				0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the cut bor the machine room and hurt his arm. An ambulance was called. 1 The Site Safety Manager reported that a worker was	No Dispatch	35299847M		ALTERATION TYPE T		Other Construction Related Incidents		GRAMERCY SQUARE LLC
/2018	Manhattan		WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An ambulance was called. 1 The Site Safety Manager reported that a worker was pushing a debits cat when one of the wheels of the cart	No Dispatch	35299847M		ALTERATION TYPE T			NOT ON FILE	GRAMERCY SQUARE LLC
/2018	Manhattan		WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Sike Safety Manager reported that a worker tripped on the cut bor the machine com and hurt his arm. An ambulance was called. 1 The Sike Safety Manager reported that a worker was pushing a debris car twhen one of the where is of the cart broke off and cloned the worker foot. The worker worker	No Dispatch	35299847M		AL IERA ION I YPE 1			NOT ON FILE	GRAMERCY SQUARE LLC
2018	Manhattan		WEST 33 STREET	0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An ambulance was called. 1 The Site Safety Manager reported that a worker was pushing a debits cat when one of the wheels of the cart broke off and clipped the worker's foot. The worker wan to the wenterperv yrom. An ECE Volation and a partial	No Dispatch	35299847M		AL EKATION TYPE 1			NOT ON FILE	GRAMERCY SQUARE LLC
2018	Manhattan		WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Sike Safety Manager reported that a worker tripped on the cut bor the machine com and hurt his arm. An ambulance was called. 1 The Sike Safety Manager reported that a worker was pushing a debris car twhen one of the where is of the cart broke off and cloned the worker foot. The worker worker	No Dispatch	35299847M		AL LEKATION TYPE 1			NOT ON FILE	GRAMERCY SQUARE LLC
2018	Manhattan		WEST 33 STREET	0 0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the cut bo the machine room and hurt his arm. An ambulance was called. 1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker 50c. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued. 1 A DOB inspector reported that a team of two workers	No Dispatch	35299847M		AL LEKA ION I YPE 1			NOT ON FILE	GRAMERCY SQUARE LLC
2018 2018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET	0 0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the cut hor the machine round and hurt his arm. An ambulance was called. 1 The Site Safety Manager reported that a worker was pushing a debits can when one of the wheels of the cant broke off and clipped the worker's foot. The worker went to the emergency room. An ECS Volation and a partial Stop Work Order were issued. 1 A DOB inspector reported that a team of two workers was installing form work at the second foor for a third	No Dispatch ECB Violation	35299847M		AL LEKATION TYPE 1		Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
2018 2018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET	0 0 0	 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut bor the machine room and hur this arm. An ambulance was called. The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the workers foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued. A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the 	No Dispatch ECB Violation	35299847M		AL LEKA ION I YPE 1		Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET	0 0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut wes a minor cut. The worker waiked to Berh Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the cut bothe machine reported that a worker tripped in the cut bothe machine reported that a worker was pushing a debris cart when one of the wheels of the curt borke off and clipped the worker Stoc. The worker went borke off and clipped the worker Stoc. The worker went borke off and clipped the worker score stoc. The worker went borker was positioned that a team of ne workers was installing for work at the scored for for a third floor column. One worker was positioned below the second worker, hosting him in place while he was	No Dispatch ECB Violation	35299847M		AL EKATION TYPE 1		Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET	0 0 0	 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut bor the machine recomm and hurt his arm. An ambulance was called. The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the workers foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued. A DOB inspector reported that a tasam of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a climp. Whis security the clamp. the clamp 	No Dispatch ECB Violation	35299847M		AL LEKATION TYPE 1		Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET	0 0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the cut for the machine recomm and hurt his arm. An ambulance was called. 1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the workers foot. The worker was torker off and clipped the workers foot. The worker was installing a clipped the workers foot. The worker was hown. An ECB Violation and a partial Stop Work. Order were issued. 1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a thrid floor column. One worker was positioned below the second worker, holding him in place while he was installing a cling. White second floor for a land installing a cling. White second the clipped he worker is the floar observed.	No Dispatch ECB Violation No Action Necessary	35299847M		AL EKATION TYPE 1		Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET	· · · · · · · · · · · · · · · · · · ·	 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut bo the machine com and hurt his arm. An ambulance was called to the cut bo the machine com and hurt his arm. An ambulance was called the cut of the wheels of the cart broke off and clipped the worker is four. The worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker is four. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued. A DOB inspector reported that a team of two workers was installing form work at the second for for a third foor column. One worker was positioned below the foor column. One worker was positioned below the sumstalling a cliency. Whis securing the climp, the mestalling a cliency, brink securing the climp, the mestalling a climp. Whis securing the climp, the sum of the bodie worker in the face. The worker was taken to a hospital, where it was reported that the worker was taken to a hospital, where it was reported worker worker 	No Dispatch ECB Violation No Action Necessary	35299847M		AL LEKATION TYPE 1		Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
2018 2018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET	0 0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the cut for the machine com and hurt his arm. An ambulance was called. 1 The Site Safety Manager reported that a worker was pushing a debris car twhen one of the wheels of the cart broke off and clipped the workers foot. The worker was torke off and clipped the workers foot. The worker was to the emergency room. An ECB Violation and a partial Stop Work. Order were issued. 1 A DOB inspector reported that a team of two workers. Mage the second the second floor for a third floor column, One worker was positioned below the second worker, holding him in place while he was installing a clamp. While second floor for a hird installing a clamp. While second the clamp fell and hit the below worker in the face. The worker suffered a scratch, but not a concusion. The worker was suffered a scratch, but not a concusion.	No Dispatch ECB Violation No Action Necessary	35299847M		AL EKATION TYPE 1		Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
/2018 /2018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET	0 0 0	 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut bo the machine com and hurt his arm. An ambulance was called to the cut bo the machine com and hurt his arm. An ambulance was called the cut of the wheels of the cart broke off and clipped the worker is four. The worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker is four. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued. A DOB inspector reported that a team of two workers was installing form work at the second for for a third foor column. One worker was positioned below the foor column. One worker was positioned below the sumstalling a cliency. Whis securing the climp, the mestalling a cliency, brink securing the climp, the mestalling a climp. Whis securing the climp, the sum of the bodie worker in the face. The worker was taken to a hospital, where it was reported that the worker was taken to a hospital, where it was reported worker worker 	No Dispatch ECB Violation No Action Necessary	35299847M		AL EKATION TYPE 1		Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
/2018 /2018 /2018	Manhattan Manhattan Brooklyn	20	WEST 33 STREET BROAD STREET WILLOUGHBY STREET	0 0 0	using a grinder to cut an angle when the grinder jumped and cut his right tig above the knee. The cut we a minor cut. The worker waiked to Berh Israel Hospital on his own. 1 The Site Safety Manager reported that a worker tripped on the cut bothe machine recomma nd hurth is arm. An ambudance was called to the cut bothe machine recomma nd hurth is arm. An ambudance was called to the cut bother and the second to the wheels of the curt borke off and clipped the workers tool. The worker was pushing a debris cart when one of the wheels of the curt borke off and clipped the workers tool. The worker was to borker off and clipped the workers tool. The worker was borker off and grine work with second from for a third floor culumn. One worker was positioned below the second worker, holding him in grine while he was installing a clamp. While securing the clamp, the clamp fiell and hit the bolow worker in the face. The worker was half overright for observation. No enforcement action was deemend necessary, as this injury occurred due to a worker error.	No Dispatch ECB Violation No Action Necessary	35299847M				Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
2018	Manhatian Manhatian	500	WEST 33 STREET BROAD STREET		 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut bott the machine com and hurt his arm. An ambulance was called. The Site Safety Manager reported that a worker was pushing a debris car twhen one of the wheels of the cart broke off and clipped the worker soft. So the worker was functional to the cut bott of care to the when one of the wheels of the cart broke off and clipped the worker's foot. The worker was thork off and clipped the worker's foot. The worker was thork off and clipped the worker's foot. The worker was installing cloren work at the second floor for a third floor column. One worker was positioned below the second worker, holding thim in place while he was installing a clipped worker in the face. The worker was had ownerghold in or clausaro. The worker was had ownerghold in or clawaro, the ordina concussion. The worker was had ownerghold in ordina variant, but not a concussion. The worker was had ownerghold hor classvarian. New enforcement action worker are the class the in the class the owner and the classifier a state in the above worker in the face. The worker was worker are the soften deal to classify the ordina variant. 1 The Site Safety Manager reported that a worker was of the Site Safety Manager reported that the a worker was of the Site Safety Manager reported that the avorker was on the soften accurated the soften accurated the soften soften accurated the soften soften accurated the soften accura	No Dispatch ECB Violation No Action Necessary	35299847M				Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	GRAMERCY SQUARE LLC
2018 2018 2018	Manhattan Manhattan Brooklyn	20	WEST 33 STREET BROAD STREET WILLOUGHBY STREET		 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut bot the machine room and hurt his arm. An ambulance was called. The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart brock off and clipped the workers foot. The worker was force off and clipped the workers foot. The worker was torke off and clipped the workers foot. The worker was installing clipped the workers foot. The worker was installing form work at the second floor for a third foor column. One worker was positioned below the second worker, holding him in place while he was installing a clipped the worker septiend the taworker suffered a scratch, but not a concussion. The worker was held overnight for observation. Ne enforcement action was deemed necessary, as this linjury occurred due to a worker struct. The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, lost his balance. and left on his rear. The worker was and such worker was not a ladder when he tripped on the fourth step. In the site of the second floor beavior. 	No Dispatch ECB Violation No Action Necessary No Dispatch	35299847M				Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	
2018 2018 2018 2018 2018	Manhattan Manhattan Brooklyn Manhattan	20 138 1283	WEST 33 STREET BROAD STREET WILLOUGHBY STREET YORK AVENUE		 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker waiked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut both meanine room and hurt his arm. An ambulance was called to the more than the source of the when one of the wheels of the cut horker of the disped the worker source of the wheels of the cut horker was to hold clipped the workers four. The New Yes and the source of the wheels of the cut horker were to the weeks of the cut horker were to the weeks of the cut horker were to the weeks of the cut horker were to hold inspector propried that a tatam of hork were than the meagency room. An ECB Violation and a partial Stop Wick Order were issue? A DOB inspector reported that a tatam of hork were than the interface of the were second from the net body worker in the face. The worker was heat overright for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error. The Site Safety Manager reported that a worker was heat overright for observation. No enforcement action and a partial sufficient action. The worker was heat overright for observation. No enforcement action and a cotter error. The Site Safety Manager reported that a worker was heat overright for observation. No enforcement action a worker error. The Site Safety Manager reported that a worker was heat over error. 	No Dispatch ECB Violation No Action Necessary No Dispatch	35299847M				Material Fell Material Fell Other Construction Related Incidents	NOT ON FILE NY STOCK EXCHANGE BLDG. CO. NYC HPD THE NEW YORK AND PRESBYTERIAN	GRAMERCY SQUARE LLC
018	Manhattan Manhattan Brooklyn	20	WEST 33 STREET BROAD STREET WILLOUGHBY STREET		 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cuth for the machine com and hurt his arm. An ambulance was called. The Site Safety Manager reported that a worker was pushing a debris car twhen one of the wheels of the cart broke off and clipped the worker soft software to be address of the software software software to be wheels of the cart broke off and clipped the worker's foot. The worker was thork off and clipped the worker's foot. The worker was installing clipped the worker's foot. The worker was installing form work at the second floor for a thrift foor column. One worker was positioned below the second worker, holding thim in place while he was installing a clipped the worker software sufficient a succert and hit the below worker in the face. The worker was had owninght or observation. No enforcement action worker and hit or bearinght or bearing the clipped the worker sufficient a state. No had the owner as the single worker and the worker sufficient a scatch, but not a concussion. The worker was bad owninght or observation. No enforcement action worker and the cleansary, as this highly occurred due to a worker remover and the worker sufficient a light on hierarchice worker was on a ladder when he tripped on the fourth step, tost his balance, and fell on his rear. The worker was on a ladder when he tripped on the fourth step, tost his balance. and fell on his rear. The worker was on a ladder when he tripped on the fourth step, tost his balance. and fell on his rear. The worker was on a ladder when he tripped on the fourth step, tost his balance. and fell on his rear. The worker was on a ladder when he tripped on the fourth step, tost his balance. and they Manager reported that a worker hurth his of the scatch on the rear. The soft is they balance. and they Manager reported that a worker hurth	No Dispatch ECB Violation No Action Necessary No Dispatch	35299847M				Material Fell	NOT ON FILE NY STOCK EXCHANGE BLDG. CO.	
2018 2018 2018	Manhattan Manhattan Brooklyn Manhattan	20 138 1283	WEST 33 STREET BROAD STREET WILLOUGHBY STREET YORK AVENUE		 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker waiked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut both meanine room and hurt his arm. An ambulance was called to the more than the source of the when one of the wheels of the cut horker of the disped the worker source of the wheels of the cut horker was to hold clipped the workers four. The New Yes and the source of the wheels of the cut horker were to the weeks of the cut horker were to the weeks of the cut horker were to the weeks of the cut horker were to hold inspector propried that a tatam of hork were than the meagency room. An ECB Violation and a partial Stop Wick Order were issue? A DOB inspector reported that a tatam of hork were than the interface of the were second from the net body worker in the face. The worker was heat overright for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error. The Site Safety Manager reported that a worker was heat overright for observation. No enforcement action and a partial sufficient action. The worker was heat overright for observation. No enforcement action and a cotter error. The Site Safety Manager reported that a worker was heat overright for observation. No enforcement action a worker error. The Site Safety Manager reported that a worker was heat over error. 	No Dispatch ECB Violation No Action Necessary No Dispatch	35299847M				Material Fell Material Fell Other Construction Related Incidents	NOT ON FILE NY STOCK EXCHANGE BLDG. CO. NYC HPD THE NEW YORK AND PRESBYTERIAN	
2018 2018 2018 2018 2018	Manhattan Manhattan Brooklyn Manhattan Manhattan Manhattan	20 20 138 1283 209	WEST 33 STREET BROAD STREET WILLOUGHBY STREET YORK AVENUE EAST 19 STREET		 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker valked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut both the machine com and hurt his arm. An ambulance was called. The Site Safety Manager reported that a worker twas pushing a debris cart when one of the wheels of the cart broke off and clipped the worker Stort. The worker went to be mergency room. An ECB Volation and a partial Storp Web Core were issued. A DoB inspector reported that a tarm of the wheels of the cart has mergency room. An ECB Volation and a partial Storp Web Core were issued. A DoB inspector reported that a tarm of the worker was installing a clamp. White securities the securities of the tark mergency room. An ECB Volation and a partial Storp Web Core were issued. A DoB inspector reported that a tarm of the worker was installing a clamp. White securiting the clamp, the clamp. How worker was hold overright for observation. No enforcement action was deemed necessary, as this injury occurred due to a city MD for a check up. The Site Safety Manager reported that a worker was na ladder when he tripped on the clurth step, tas his injury occurred due to a City MD for a check up. The Site Safety Manager reported that a worker hut his finger while unadeding part reported that a worker was the due to a City MD on his own. 	No Dispatch ECB Violation No Action Necessary No Dispatch	35299847M				Material Fell Material Fell Other Construction Related Incidents Other Construction Related Incidents	NOT ON FILE NY STOCK EXCHANGE BLDG. CO. NYC HPD THE NEW YORK AND PRESBYTERIAN 227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
2018 2018 2018	Manhattan Manhattan Brooklyn Manhattan	20 138 1283	WEST 33 STREET BROAD STREET WILLOUGHBY STREET YORK AVENUE		 using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own. The Site Safety Manager reported that a worker tripped on the cut bott the machine com and hurt his arm. An ambulance was called. The Site Safety Manager reported that a worker was pushing a debries cart when one of the wheels of the cart broke off and object the worker west broke off and object the worker set of the worker was torker west to the emergency room. An ECB Violation and a partial Stop Work Order were issued. A DOB inspector reported that a team of two workers was insaling form work at the second factor for a third focor column, c. I worker went by the body work of the factor. The worker was taken to a hospital, where it was reported that the worker was held overright for observation. Ne enforcement due to a worker error. The Site Safety Manager reported that a worker was held overright for observation. Ne enforcement action a ladder when the torker the outh the factor. The worker was held overright for observation. Ne enforcement action a ladder when the tripped on the factor the worker was held overlight for observation. Ne enforcement action a ladder when the tripped on the factor that a worker was held overlight for expervation. Ne enforcement action a ladder when the tripped on the factor that a worker was held not a the second to worker was taken to a big balance, and tell on hir rear. The worker wasked to a City MD for a check up. The Site Safety Manager reported that a worker wasked to a City MD for a check up. 	No Dispatch ECB Violation No Action Necessary No Dispatch	35299847M				Material Fell Material Fell Other Construction Related Incidents	NOT ON FILE NY STOCK EXCHANGE BLDG. CO. NYC HPD THE NEW YORK AND PRESBYTERIAN	GRAMERCY SQUARE LLC



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	532	WEST 33 STREET	0	The Site Safety Manager reported that a worker slipped on ice melt pellets that were on the ground floor of the job site in an area where ice melt had been put down to melt ice. The worker hurt his wrist and his hip. The						Other Construction Related Incidents	NOT ON FILE	
					worker went to see the onsite medic before going to see an offsite medic on his own.								
2018	Manhattan	550	WEST 29 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder when the blade caught his glove and caused a cut to his hand. An ambulance was called.	No Dispatch					Other Construction Related Incidents	550 WEST 29TH STREET LLC	
018	Manhattan	1865	BROADWAY	0	The Site Safety Manager reported that a worker cut his pinky finger while putting away his band-saw tool. The band-saw was unplugged. The worker went to a clinic. An ambulance was not called	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
)18	Manhattan	328	EAST 62 STREET	0	The Construction Superintendent reported that a worker was installing pour stops when he slipped into the side of rebar and injured his shoulder. The worker left the site in a cab.				Alt 1 - NB	121189846	Other Construction Related Incidents	YYY 62ND STREET LLC	JOY CONSTRUCTION CORP
018	Manhattan	591	THIRD AVENUE	0	The Site Safety Manager reported that a painter was carrying down supplies when he lost hs balance on the fourth step and fell, hurting his leg. An ambulance was called and the ambulance took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	587-91 THIRD OWNER LLC	
018	Brooklyn	1	FLATBUSH	0	The Site Safety Manager reported that a worker was removing debris when a four inch pipe that was about three feet long fell on his foot. The worker went to a hospital.	No Dispatch					Other Construction Related Incidents		
2018	Bronx	869	EAST 147 STREET	0	The Site Safety Manager reported that a worker complained about lower back pain while pulling a stud during carpentry work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	HP MLK PLAZA HOUSING DEVELOPME	
2018	Brooklyn	1	FLATBUSH AVENUE	0	The Site Safety Manager reported that a worker was doing taping work while on an 'A'-Frame ladder when he mis-stepped and fell two feet. The worker suffered a minor injury and an ambulance was called.	No Dispatch					Other Construction Related Incidents	ONE FLATBUSH AVENUE PROPERTY L	
2018	Brooklyn	37	BLUE SLIP	0	The Site Safety Manager reported that a worker got his thumb pinched between a window and a rack during a delivery. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT G LLC	
2018	Manhattan	10	RIVERSIDE BOULEVARD	0	The Site Safety Manager reported that a worker hurt his back while lifting a reel of wire into a box. An ambulance was called.	No Dispatch					Other Construction Related Incidents	RCB3 NOMINEE LLC	
2018	Manhattan	24	2 AVENUE	0	The Site Safety Manager reported that a worker was putting away his tools at the end of the day when he opened a sliding glass door on the eighth floor. The glass door came off of its track and hit the worker. The incident took place on 25/2018, but was not reported until 24/2018. An ambulance was not called, but the worker said that he was going to see a doctor to be checked out. An CEG Violation and a DOB Violation were issued. A partial Stop Work Order on the use and tratslatilistic of all balcony silling doors was issued. The General Contractor is to provide a Manufacturer's Specification on all door tracks and the reason for the door failing off its track.	ECB Violation	35299721R	020618BS03GD02			Material Fell	24 SECOND AVENUE OWNER LLC	
018	Manhattan	260	WEST 40 STREET	0	A DOB inspector reported that a worker was trying to reach for something on the platform of a baker scalfold when he moved the baker scalfold, causing it to strike the left shoulder of another worker. Both workers were on the floor and not using the scalfold. The injured worker was sent to a Med-Rite Clinic for a check up. The injured worker did not suffer a major injury. An ECB Violation was issued.		35285826Y		NB	121187394	Material Fell	PORT 40TH PARKING CORP	ZDGLLC
2018	Staten Island	546	GULF AVENUE	0	The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con-Edison box. The worker went to Staten Island Hospital on his own for a check up.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
018	Manhattan	91	LEONARD STREET	0	The Site Safety Manager reported that a worker tripped, fell, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital.	No Dispatch			NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
2018	Manhattan	91	LEONARD STREET	0	A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker went ot a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	353-357 BROADWAY LLC	
018	Manhattan	2395	FREDERICK DOUGLAS BOULEVARD	0	1.A DOB inspector reported that a worker wash hit in the head with a pice of Imber that was dropped by another worker during a strepping operation. The worker who was hit by the pice of Imber complianced of a stiff neck and was sent to a hospital. An EGB Violation was issued, as well as a partial Stog Work Order on all concrete work. A Means and Methods must be provided.		35289390M				Other Construction Related Incidents	HP 2395 FDB HOUSING DEVELOPMEN	
2018	Manhattan	1283	YORK AVENUE	0	The Site Safety Manager reported that a worker was moving an "A"-Frame dolly that was loaded with twenty behets of 4 X 8 diamond plates when the dolly tipped and hit her ankle. The injured worker went to an emergency room that was across the street from the site. An ECB Violation and a partial Stop Work Order were issued.		35299967R				Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	



cident Date	Borough	Address Numbe		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/2018	Brooklyn	911	ERSKINE STREET	0		ECB Violation	35300547X,49J	020818BIS05HM01.02			Material Fell	FOUNTAIN SEAVIEW THREE HOUSING	
7/2018	Brooklyn	540	FULTON STREET	0	1 The Site Safety Manager reported that during a drilling operation for the backs, a cargeneter that was assisting the drill operators beped onto an equipment inset and the clamp closed down on his left foot. The worker was taken to a hospital by emergency personnel. Two ECB Violations, mer sisued, as well as a full Stop Work Order. The constractor has been directed to provide the manufacture's specifications for the drilling equipment, as personnel operation of the personnel operation the equipment.	3	35309900Z 35309901K		NB	321185828	Mechanical Construction Equipment	540 FULTON ASSOCIATES	PAV-LAK CONTTRACTING INC
2018	Manhattan	460	PARK AVENUE SOUTH	0	1 The Site Safety Manager reported that a worker was opening a crate of window frames when a 5' X 5' tube pipe rolled out and onto his foot. The worker was seen walking around, but an ambulance was called.	No Dispatch					Other Construction Related Incidents	460 PARK AVENUE SOUTH ASSOCIAT	
/2018	Queens	27-17	42 ROAD	0	 The Site Safety Manager reported that a worker lacerated his hand with a utility knife during a stripping operation when the utility knife slipped. The worker went to a hospital on his own. 	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
8/2018	Brooklyn	810	FULTON STREET	0	1 The Site Safety Manager reported that a worker was performing stripping work on the eleventh floor when he pulled down a piece of plywood and the aluminum leg of the formwork hit the worker in the face and split his lip. An ambulance was called. An ECS Violation was have a bar stripping safety measures. A DOB Violation was also issued. A Toro Box Taik will be issued before the start of stripping operations.		35300050K	020818BS02EP06			Material Fell	GREENPOINT-GOLDMAN CORP.	
2018	Manhattan	388	GREENWICH STREET	0	1 The Site Safety reported that a worker hurt his foot while using a chipping gun. The worker took a cab to urgent care.	No Dispatch			ALTERATION TYPE 1	121190503-01-AL	Other Construction Related Incidents	CITIGROUP TECHNOLOGY, INC.	TISHMAN CONSTRUCTION CORP
W2018	Queens	34-11	BEACH CHANNEL DRIVE	0	1 The Site Safety Manager reported that a worker was dismariting a scaffold when the plank he was standing on broke and fell six feet. The worker went to a hospital by ambulance. An ECG Violation for a failure to safeguard all persons and property affected by construction operations was issued.	ECB Violation	35285811N		NB	421094283	Worker Fell	NOT ON FILE	Chateau GC LLC
9/2018	Queens	160-08	JAMAICA AVENUE	0	1 The Site Safety Manger reported that a vehicle struck the flagman in the street. The Police Department responded to the incident. The worker wss taken to Jamaica Hospital.	No Dispatch					Other Construction Related Incidents	160 JAMAICA, LLC	
/2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that an electrician was pulling his cart from the hoist when the handle on the cart became loose and the worker fell backwards to the floor, hurting his back. An ambulance was called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
/2018	Brooklyn	500	GATES AVENUE	0	1 The Super reported that a mason was using a grinder for brick cutting when the grinder kicked back and the grinder's butt end (not the blade) hit the mason in the face. The mason suffered a bruise to his face and felt a little dizzy. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PCMH 500 GATES HOUSING DEVELOP	
2018	Brooklyn	340	EVERGREEN AVENUE	0	1 The Fire Department reported that a worker was hit in the head with a piece of rebar. Four ECB Violations and four DOB Violations were issued. A partial Stop Work Order was also issued. A Means and Methods and a Tool Box Talk must be provided.	ECB Violation	35300117X,118H,120R,121Z	020918BS04DH01,02,04,05			Material Fell	BUSHWICK REALTY HOLDINGS LLC	
2/2018	Bronx	2568	PARK AVENUE	0	1 The Site Safety Manager reported that a worker cut his knee while walking by rebar. The worker was taken to an area medical facility by a co-worker.	No Dispatch				220152484	Other Construction Related Incidents	2568 BRONX PARK LLC	STEVEN ALESSIO
2/2018	Brooklyn	135	EMERSON PLACE	0	1 The Site Safety Manager reported that during a stripping operation, a worker fell down from the sixth floor and landed on top of the sidewalk sheed. The worker was found unconscious, but breathing. The worker was steven to a nospital by ambulance. An ECB Violation and a full Stop Work Order were issued. Three additional ECB Violations/OATH Summonses and three partial Stop Work Orders were issued by the Concrete Enforcement Unit.		35300065N				Worker Fell	PRATT INSTITUTE	
12/2018	Manhattan	11	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker was working in a man lift when he moved his body and twisted his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	THE MUSEUM OF MODERN ART	
12/2018	Manhattan	200	EAST 95 STREET	0	1 The Site Safety Manager reported that a worker pinched his finger while moving a steel beam on an "A"-Frame. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents		



ncident Date	Borough	Address Number	Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/12/2018	Manhattan	461	WEST 34 STREET	0	1 The Site Safety Manager reported that a worker cut his				ALT 1	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	EDWARD M GRUNWALD
					left hand on metal studs. The worker was taken to an area hospital and received several stitches.								
/2018	Staten Island	2655	RICHMOND AVENUE	0	 The Site Safety Manager reported that a worker entered the site from the outside of the mall area by the dirt 	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
					parking area side, fell in ice that was mixed with dirt, and	1							
					hurt his ankle. The worker went to urgent care.								
2018	Queens	80-08	135 STREET	0	2 The General Contractor reported that two workers were	ECB Violation	35309854r		ALT 1	420652378 AL	Mechanical Construction Equipment	BRIARWOOD MP LLC	PAV-LAK CONTRACTING INC
					injured while grouting when a pump hose got clogged with grout and blew into the worker's faces. The workers								
					tried to un-clog the pump while it was in use. The two								
					workers were taken to a hospital for treatment. An ECB								
					Violation and a partial Stop Work Order were issued.								
3/2018	Queens	45-57	UNION STREET	0	1 A DOB inspector reported that a worker was using the	ECB Violation	35299630L				Worker Fell	DEPARTMENT OF EDUCATION	
					scaffold's stairs to bring rebars onto a floor when a rebar got caught on the stairs and pulled the same worker								
					down. The worker was experiencing aches in his body								
					and went to a clinic the next day. This incident took place on February 13, 2018, but was not reported until	э							
					February 14, 2018. The building was a five story building								
					with no permanent stairs. An ECB Violation and a full Stop Worker Order were issued for inadequate								
					ingress/egress, an adequate supported scaffold, and the								
					lack of internal stairs.								
5/2018	Brooklyn	1060	CLARKSON AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch			ALTERATION TYPE 2	302581347-01-EW-OT	Worker Fell	DEPARTMENT OF EDUCATION	ANSU CONSTRUCTION INC
3/2010	DIODKIYI	1000	OLANGON AVENUE	0	arm with a saw while cutting wood. The worker was	No Dispatch			ALTERATION TYPE 2	302301347-01-EW-01	WORKE FUI	DEFACIMENT OF EDUCATION	
					taken to a hospital by ambulance.								
15/2018	Manhattan	101	WEST 57 STREET	0	1 A DOB inspector reported that contractors were attempting to remove a tempered glass panel when the	ECB Violation	35308906P	021518CERDY04			Material Fell	101 WEST 57TH STREET HOTEL INV	
					panel shattered. A small piece of glass fell to the street								
					level while the remainder of the shattered panel was on the terrace. A woman was injured and taken to a hospita								
					by ambulance. The women's injury was minor and not life	9							
					threatening. An Aggravated Level 2 ECB Violation, a DOB Violation, and a partial Stop Work Order were								
					issued for a failure to safeguard all persons and property								
					during construction operations.								
15/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was climbing off of a scaffold when he slipped and fell	No Dispatch					Worker Fell	38-46 WEST 33 STREET, LLC	
					approximately two feet, injuring his shoulder. An								
					ambulance was called.								
/15/2018	Queens	30-35	COLLEGE POINT BOULEVARD	0	1 A DOB inspector reported that a painter was on a scisso lift painting the area next to a roll down door sensor when	r ECB Violation	35317705N				Other Construction Related Incidents	FEINSTEIN CP REALTY LLC	
					he activated the door, which caused another worker to								
					get hit by the door. The worker had the wind knocked ou of him and was sent to a hospital. An ECB Violation and								
					a partial Stop Work Order were issued for the failure to								
					maintain safe operations. The General Contractor at the site is to provide a Means and Methods.								
16/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a concrete worke	r No Action Necessary					Other Construction Related Incidents	SMITELL SPONSOR LLC	
					was carrying a Doka form that was about 2 X 9 feet and								
					100 pounds when he slipped and fell. The worker complained of back pain. A DOB inspector responded to								
					the incident and reported that no enforcement action was necessary, as the injury occurred as the result of a	5							
					necessary, as the injury occurred as the result of a worker error.								
16/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NEW BUILDING	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTRUCTION SERVICES LL
					lifting a piece of rebar when he claimed to have hurt his back. The worker walked up to an ambulance and the								
					ambulance took him to a hospital.								
16/2018	Manhattan	38	HOWARD STREET	0	2 A DOB inspector reported that an inspector from Cole NY was performing an inspection of the building for	ECB Violation	35308908Z	021618CERDY01			Material Fell	434 BROADWAY PROPERTY INVESTOR	CANY Architecture & Engineering, DPC.
					facade local law. While inspecting the building, the								
					inspector stepped out onto the fire escape on the seventh floor, and a step of the fire escape became								
					dislodged and fell to the ground, striking two pedestrians								
					One of the pedestrians suffered a life threatening injury,								
					and the second pedestrian was in serious condition. The inspector fell slightly through an opening, but not all the								
					way down. EMS was called. An ECB Violation, a DOB								
					Violation, and an Immediate Emergency Declaration were issued.								
16/2018	Queens	71-17	ROOSEVELT AVENUE	0		ECB Violation			NEW BUILDING	420653000	Material Fell	ROOSEVELT PARC LLC	BRAVO BUILDERS LLC
					unloading bundles of rebar that were approximately forty five feet from a flatbed truck when one of the workers								
					lost control of the bundle and the bundle fell on the leg o	f							
					another worker. There was no equipment used during the unloading. The injured worker suffered a broken right								
					the unloading. The injured worker suffered a broken right leg and was taken to a hospital. An ECB Violation and a	t							
					partial Stop Work Order were issued for a failure to								
					maintain the safe operations and to stop all material								
					handling, including deliveries. The General Contractor is to provide a safe Means and Methods, including								
					equipment and Tool Box talks.								



dent Date		Address Numbe		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	200	EAST 21 STREET	0	1 The Site Safety Manager reported that a worker dislocated his left shoulder when he lifted a bag of	No Dispatch			NEW BUILDING	121190479-01-NB	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC
					concrete onto it. The worker was taken to Mount Sinai Hospital by ambulance.								
018	Brooklyn	805	WASHINGTON AVENUE	0	1 A DOB inspector reported that a worker was waiking close to a Blockar while an Heam was on the forks attached to the Bobcat when the Heam moved and the worker's hand got caught between the Heam and the Bobcat track. The worker suffered a fractured hand and was taken to an area hospital. The worker operating the was taken to an area hospital. The worker operating the this situation that resulted in an injury to another work. This incident occurred on 21/92/018, but the State Safety Manager was not informed of the incident until 2/202018. Four ECB Violations and a partial stop Work order were issued.		35317732Z, 36317733K AND 36317736K		NEW BUILDING	321478548	Mechanical Construction Equipment	805 WASHINGTON AVE LLC	HAPPY LIVING DEVELOPMENT
2018	Brooklyn	211	SCHERMERHORN STREET	0	1 The Site Safety Manager reported that a worker rolled his ankle while moving material. The worker was taken to				FRANK HEALEY	321196200-01-NB	Other Construction Related Incidents	211 SCHERMERHORN DEVELOPMENT L	OESTREICHER CONSTRUCTION
2018	Manhattan	115	DELANCY STREET	0	Brooklyn Hospital by EMS. 1 The Site Safety Manager reported that a worker cut his finger while using a grinder. The worker went to urgent	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Manhattan	425	PARK AVENUE	0	care. 1 The Site Safety Manager reported that a worker fell from the fourth step of an "A"-Frame ladder. The worker complained of back pain. An ambulance was called.	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
2018	Brooklyn	5718	2 AVENUE	0	1 A DOB inspector reported that a worker was pulling on one of the clips of a outrigger scaffold in noter to install property. The worker pulled the clip hard, which caused the worker to slide down the plank and twist his ankle. The worker worker to the emergency room access the work all built as per design. No enforcement was action necessary, as it was determined that the injury occurred as the result of a worker error.	s			ALTERATION-1	321192702	Worker Fell	NYU HOSPITALS CENTER	HUNTER ROBERTS CONSTRUCTION
D18	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager has reported that a worker was climbing down an "A"-Frame ladder when he slipped an fell about four feet. An ambulance took the worker to a hospital. The worker suffered a possible fractured elbow						Worker Fell	SMITELL SPONSOR LLC	
2018	Queens	131-11	FOWLER AVENUE	0	1 The Site Safety Manager reported that a worker twisted his right wrist while bending rebars. A co-worker took his to a clinic.						Other Construction Related Incidents	131-05 HOLDING LLC	
2018	Queens	38-01	QUEENS BOULEVARD	0	The Site Safety Coordinator reported that a worker tripped on tape on a scaffold platform, which caused him to fail and twick his knee. The worker was taken to urger care. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard all persons and property.	1	35285820P		NB	421387626	Worker Fell	CURBCUT QUEENS BLVD LLC	Sordoni Construction Comp
2018	Staten Island	35 a	BAY STREET	0	The Site Safety Manager reported that a rebar installer slipped on a rebar floor and twisted his ankle. An ambulance was on site.	No Dispatch					Other Construction Related Incidents		
2018	Staten Island	2655	RICHMOND AVENUE	0	ambulance was on site. 1 The Site Safety Manager reported that a worker was loading sheetrock onto an "A"-Frame when one of the boards slid and landed on his right foot. The worker was sent to urgent care.					_	Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
//2018	Manhattan	122	LEXINGTON AVENUE	0	1 The Police Department reported that two workers were making a delivery to the roof area of the siturcure when one of the workers fiel approximative sight to be fact and the workers fiel approximative sight to be fact that the siturcure of the the siturcure when suffered injuries to bis back and neck and was transported to Bellevue Hospital with head and neck injuries. A full Stop Work Order had been issued to the building on 4222015 and a Vacate Order was issued of 1222/2017. Two ECS Violations, and two DOB Violations were issued for the unlawful continuation of work while on the notice of a Stop Work Order and for a failure to safeguard.	n	35308861K & 35308860Z	022218CERTQ01 & 022218CERTQ02			Worker Fell	122-24 LEXINGTON AVEOP	
/2018	Brooklyn	19	KENT AVENUE	0	1 The Site Safety Manager reported that a worker walked into a pile of plywood and then felt discomfort in his upper torso and chest. An ambulance was called and th worker was transported to a hospital.	- · ·			NEW BUILDING	320591944-01-NB	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
/2018	Brooklyn	138	WILLOUGHBY STREET	0	 The Site Safety Manager reported that a worker cut his finger while handling rebar. The worker was seen by the on-site medic and was sent to City M.D./urgent care. 						Other Construction Related Incidents	NYC HPD	



/23/2018	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Queens	83-09	35 AVENUE	0	1 A DOB inspector reported that workers at apartment number BA2-were lowering a piece of piywood that was approximately 2 X 5 from the fourth floor fire escape to the ground using a heavy thick tope in front of the building. According to the Project Manager at the site and a bystander, the piywood siteped off of the rope and fell from the third floor lovel, striking a young grif on the side of her head before landing on the ground. Marks from the fallen wood can still be seen on the ground where it landed. The injured young grif was transferred to New York Presbyteian Hospital of Queens with injuries to the side of her head. Three Approved Level 2 ECB Violations were issued for a failure to safeguard, for work not conforming to plans, and for working without a permit. 3 DOB Violations, and a full Stop Work Order were also issued.		35309174N, 35309325L & 35309326N	022319CERKC03, 022319CERKC04 & 022319CERKC04 & 022319CERKC05	ALTERATION TYPE 2	421548999-01-EW-OT	Material Fell	83-09 35TH REALTY LLC	MNR GROUP INC
3/2018	Manhattan	545	WEST 30 STREET	0	1 A DOB inspector reported that workers were using a lull to unload window panels off of a truck. While the lull was being taken into the building, one of the panels sid of of worker to a hospital. An ECB Violation for a failure to maintain safe operations and a partial Stop Work Order were issued or all deliveries and material handling. The General Contractor is to provide a Means and Methods.		35317717K				Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
7/2018	Manhattan	685	FIRST AVENUE	0	1 The Site Safety Manage reported that a worker was working in a building when a couple of pieces of sheetrock fell over and onto his leg. An ambulance was called to the site.	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
28/2018	Manhattan	1227	BROADWAY	0		ECB Violation	35225172L 35225171J & 35225172L		CN	CN 913/16	Mechanical Construction Equipment	YJL BROADWAY HOTEL LLC	EMNY CONTRACTING CORP
/2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that a worker got dust in his eye. The worker went to a hospital for treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Brooklyn	391	HOOPER STREET	1	a DOB inspector reported that heavy gauge 2 X 10 caling joists were delivered and placed on top of the Concreter Macony Unit (CMU) exterior walls of the suffic points together, which leads to the joists collapsing and knocking the worker of of the scaffed to the ground. The joists landed on top of the worker as well. The worker was found dead on arrival. A DOB Violation and a full Stop Work Order were issued.			030118BS01AS01			Other Construction Related Incidents	E&D MANAGEMENT GROUP LLC	
2018	Queens	28-02	JACKSON AVENUE	0	A DOB inspector reported that a panel of plywood that was about 8" X" fillers the parapet of a sidewalk shed and struck two pedestrians. Core of the pedestrians suffered an injury in the shoulder area. The injured pedestrian was seen by the on-site medic, but denied further medical attributes and attributes and the scenes. An Aggrevance of the site of the scenes. An additional structure of the scenes and instruction balegoried cited and property affective by failure to sitegoried. A second ECB Violation was able bissued or a failure to maintain an inspection log for the sidewalk shed. A partial Stop Work Order was also issued. The sidewalk shed company was sent to the site for repair work.	ECB Violation	35318105Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMPA
2018	Manhattan	685	1 AVENUE	0	1 The Site Safety Manager reported that a worker was pushing a mini container when the gate on the bottom of a ramp swung and lacerated his right hand. The on-site medic put a band aid on the cut. An ambulance took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
018	Manhattan	260	WEST 40 STREET	0	1 The Site Safety Manager reported that a worker was using a lade and cut his finger. The worker was patched up on-site, but then went to City M.D. where he received two to three stitches.				NB - NEW BUILDING	121187394	Other Construction Related Incidents	PORT 40TH PARKING CORP	ZDG, LLC
2018	Manhattan	150	EAST 23 STREET	0	two to three stitches. 1 The Site Safety Manager reported that workers were carrying steel plates when one of the plates slipped and pinched one of the worker's left middle finger. The worker was transported to a hospital by ambulance.	No Dispatch			NB	121981748	Other Construction Related Incidents	154 EAST 23 LLC	W & L GROUP CONSTRUCTION
2018	Manhattan	1912	1 AVENUE	0	 The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the worker was transported to a hospital. 				NB	122879233	Worker Fell		PROCIDA CONSTRUCTION CORP



	Borough	Address Number	Street Fa	atalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	425	WEST 18 STREET	0 1 The Site Safety Manager reported that a worker hu	rt his No Dispatch			NB	122736762	Other Construction Related Incidents	NOT ON FILE	ARTIMUS CONSTRUCTION INC
				back while picking up a cement bag. An ambulanc	was							
				called and the worker was transported to a hospita								
8	Brooklyn	10	HURON STREET	0 1 The Site Safety Manager reported that there were	wo No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
				workers that were doing sheetrock work together w	hen							
				one of the workers lost his grip on a piece of sheet	ock							
				that landed on the other worker's finger, causing a	cut.							
				The second worker left the site and went to City M. get stitches on his finger. This incident occurred or	D. to							
				3/5/2018, but was not reported to the Site Safety								
				Manager or Construction Superintendent until 3/8/	018.							
2018	Queens	45-57	UNION STREET	0 1 A DOB inspector reported that a 16' X 8' size gate	wung ECB Violation	35317909P				Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
				out and hit a pedestrian that was walking by. The								
				pedestrian was a student that was approximately s years old. The student was evaluated by a nurse.	even							
				years old. The student was evaluated by a nurse.								
2018		2255	BROADWAY							Other Construction Related Incidents	2255 HOLDING LLC	
2018	Manhattan	2255	BROADWAY	0 1 The Site Safety Manager reported that a worker wa lifting a 2 X 3 X 10 wooden beam in the elevator pi	s No Dispatch					Other Construction Related Incidents	2255 HOLDING LLC	
				he hit himself in the face with the wooden beam. T	when h							
				worker went to urgent care and then went to a hos	ital.							
				This incident occurred as a result of a worker error								
018	Bronx	2395	FREDERICK DOUGLASS BLVD	0 1 The Site Safety Manager reported that a pedestria	in a ECB Violation	35300487N	030618BS10VP06			Other Construction Related Incidents		
				wheelchair fell over in a walkway due to a tripping	azard							
				around a Con-Ed sewer cap. The pedestrian went								
				hospital by ambulance. A DOB inspector responde the incident, visited the site, and issued an ECB	1 10							
				Violation. The tripping hazard was corrected as of	he							
				time that the inspector was at the site.								
018	Brooklyn	416	KENT AVENUE	0 1 The Site Safety Manager reported that a worker sli	ned No Dispatch				320622616	Other Construction Related Incidents	420 KENT AVENUE LLC	ZDG, LLC
		-10		fell, and hurt his arm. The worker was taken to a h	spital				OLOOLLO TO	Construction reduced inducints		
				for a check up.								
018	Manhattan	1681	3 AVENUE	0 1 The Site Safety Manager reported that an electricia	n was No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
				running a wire when he tripped on a piece of plywo	bd							
				and skinned his right shin. The electrician went to a M D for assistance	City							
018	Queens	147-40	ARCHER AVENUE	0 1 The Site Safety Manager reported that a piece of	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
				plywood slid and hit a worker on the left knee while worker was stocking plywood on the floor. The wor	uie (er							
				worker was stocking plywood on the ridor. The work								
018	Queens	28-07	JACKSON AVENUE	0 1 A DOB inspector reported that there were two	ECB Violation	35318121Y-FAIL TO SAFEGUARD	030818BS02KA01	NB	420656873	Material Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
		200		electricians working on a scissor lift at the baseme	nt		5001050210101		120000010			Ente on coroned a DEV
				level when a temporary light fixture was accidental	y l							
				bumped and dislodged, causing it to fall approxima								
				five feet and strike a worker that was passing by or								
				head and back. The electricians were working with controlled access zone below. The worker was fou	outa							
				alert, but complained of head pain and went to urg	id int							
				alert, but complained of head pain and went to urg care. An ECB Violation for a failure to safeguard w	as							
				issued, as well as a partial Stop Work Order for the								
				installation of electrical lighting work. A Means and								
				Methods must be provided.								
2018	Staten Island	546	GULF AVENUE	0 1 The Site Safety Manager reported that a worker sli	and No Dispatch					Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	
.010	Statemalariu	346	GOEI AVENDE	hit his left knee as he was taking the stairs to his tr	ailer.					WORKELLER	STATEN ISEAND GEODAE EOGISTIC	
				The worker was taken to a hospital for a check up.								
018	Manhattan	1059	3 AVENUE	0 1 The Site Safety Manager reported that a worker wa	s ECB Violation	35300269P	030918BS08MH01			Material Fell	63RD & 3RD NYC LLC	
				carrying a few formwork clamps that weight								
				approximately 10-15 pounds and are about 18 feet	long							
				in length up the third floor steps when one of the cl fell from his grip and hit the wrist of a mason that w	amps							
				tell from his grip and hit the wrist of a mason that w working in the basement, possibly breaking the ma	do son's							
				working in the basement, possibly breaking the ma wrist. An ambulance was called. An ECB Violation	and a							
				partial Stop Work Order were issued for the unsafe								
				handling of materials. A DOB Violation was also is	ued.							
				A Means and Methods will be provided for the safe								
				handling of form work materials.								
2018	Manhattan	217	WEST 57 STREET	0 1 The Site Safety Manager reported that a worker as	ECB Violation	35286419N				Worker Fell	SMITELL SPONSOR LLC	
				carrying equipment when he slipped and fell. The	orker							
				hit the back of his head and blacked out. The work sent to Mount Sinai Hospital. A DOB inspector	er was							
				sent to Mount Sinai Hospital. A DOB inspector responded and visited the site and reported that th								
				worker slid on what look like an ice patch on the flo	or,							
				even through there was ice melt spread throughout	the							
				are. An ECB Violation was issued for a failure to								
				maintain safe operations.								
018	Manhattan	29	11 AVENUE	0 1 The Site Safety Manager reported that an iron wor	er No Dispatch					Other Construction Related Incidents	NYS PARKS & RECREATION	
				was attempting to move a steel beam onto a dolly	on his							
				own when the beam slid and hit his left knee. 911	/as							
				called and the worker was taken to a hospital.								
_												
018	Manhattan	701	7 AVENUE	0 1 The Site Safety Manager reports that a worker pin						Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	
				his finger while cutting a Formica board with a circ	lar							
				saw. The worker went to the emergency room on h	5							
			WEST 33 STREET		ar hunt Nie Diment					Other Construction Related Incidents	NOT ON FILE	
	March 1997											
018	Manhattan	500	WEST 33 STREET	0 1 The Site Safety Manager reported that an ironwork bis right index finger while point a cross brace. The	a nun no Dispatch						NOTONTILL	
2018	Manhattan	500	WEST 33 STREET	 I he site safety manager reported that an ironwork his right index finger while prying a cross brace. Th worker was transported to Bellevue Hospital by 	e						NOTONTILL	



ncident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	125	GREENWICH STREET	0	1 A DOB inspector reported that a worker was lifting up a four foot section of form work when the worker mishandled the form work, causing the form work to fall on his knees. An arbulance was called. It was determined that the incident happened as a result of a worker error and that no enforcement action was necessary.	No Action Necessary					Material Fell	VS 125 LLC	
/12/2018	Manhattan	125	GREENWICH STREET	0	1 The Site Safety Manager reported that a worker was handling a roll of felt paper when he slipped backwards and suffered a laceration to he left side of his forehead. The worker did not want an ambulance to be called and went to a City M.D. instead.						Worker Fell	VS 125 LLC	
/12/2018	Manhattan	255	EAST HOUSTON STREET	0	1 The Site Safety Manager reported that a worker's finger got caught between two beams while he was pushing forwards beams on a truck. The worker was sent to Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	255 EAST HOUSTON OWNER LLC	
/13/2018	Queens	150-13	89 AVENUE	1	0 A DOB inspector reported that a worker was riding on the back of a tork till during a placement of bundle windows in the said grade. The bundle sides and the said of the said said the sai			031319BS1201MC			Other Construction Related Incidents	88TH AVENUE OWNER LLC	
14/2018	Brooklyn	3617	13 AVENUE	0	1 A DOB inspector reported that a worker lacerated his foot while driving a walk-behind saw to a container in order to park it. The worker was sent to a hospital. A an ECB Violation was issued, as well as a partial Stop Wof Order on the use of the walk-behind saw. Manufacturer specifications must be provided.		35318355R				Other Construction Related Incidents	37TH STREET HOLDINGS LLC	
14/2018	Manhattan	220	CENTRAL PARK SOUTH	0	1 The Site Safety Manager reported that an iron worker pinched his index finger while unloading a cart of steel. The worker went to a clinic to receive stitches for his finger.	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
15/2018	Brooklyn	225	4 AVENUE	0	1 A DOB inspector reported that workers were in the process of cleaning price with an add base solvent whete some of the solvent lefi into the wey of a fernale pedestrian. The pedestrian had her eye innsed out and was treated on the site. The pedestrian did not go to the hospital. An Aggravated Level 2 ECB Violation for the linear to saleguard all persons and property affected by construction operations was issued, as well as a DOB Violation and a parial Site WOrk Order for fagade work. It was recommended that the BEST Squad perform a follow up inspection for compliance and safety measures.		35309294H	031518CERDM01	NB :	310086554	Material Fell	225 4TH AVENUE PROPERTY OWNER	TRM Construction
16/2018	Queens	21-30	44 DRIVE	0	¹ The Site Safety Manager reported that a piace of pyeaced fail from the first floor to the cellur face to the wind. The physicol landed on the cellur floor when it then fail onto a worker, hurling the worker's shoulder. This incident occurred on March 16, 2018, but the Department OF Buildings was not notified until March 19, 2016, because the Construction Superintendent claimed that he called the office on 31/52/018 after 4:00 PM and that he called the office on 31/52/018 after 4:00 PM and that he one answered the phone. An ECB Violation was issued for a failure to safeguard for not securing materials during a weather advisory. A DOB Violation and a partial Stop Work Order of all form work were alls issued. A Means and Methods for the securing of materials during a weather advisory must be provided.		35318143P	031918BS02KA04			Material Fell	44TH DRIVE OWNER LLC	
/16/2018	Manhattan	501	WEST 18 STREET	0	1 A DOB inspector reported that during excavation work, a worker was torching a hole in two steel "H" piles and was laying side by side in order to siling and rig the pile when the excavator that was being used moved, which cause the worker's lig to become pinched between two piles. The Sile Safety Manager stated that the worker was sent to a hospital as a precaution. An EGB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel piles. The ontractor is to provide a Means and Methods for the safe movement of steel around the construction site.	s f	35314141N		New Building	121191147	Excavation/Soil Work	18TH HIGHLINE ASSOCIATES, L.L.	Related Construction LLC



cident Date	Borough	Address Numbe	r Street	Fatalities Iniuri	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/2018	Manhattan	220	CENTRAL PARK SOUTH	0	To characteristic processing reported that a secker or the bacevise States Maxing's powered pallet jack to move bags of cameral down a many when the powered pallet jack moved on its own and ran over the worker's left foot. The worker went to Roosevelt Hospital. A DOB inspector responded to the incident and sissed an ECB Violation for a failue to maintain unsale equipment. A DOB Violation and a partial Stip Work Order for all work using equipment to transport loads as the second floor north of Towne Boolevard were also issued. The powered orientation and a Maans and Mathods must be provided. The BEST Squad must be contacted for a re-inspection.	ECB Violation	ECBI/SS18264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	OST618BSOSMA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 56TH STREET LLC	LEND LEASE CONSTRUCTION
/2018	Brooklyn	416	KENT AVENUE	0	The Site Safety Manager reported that at a twenty-two story new building under construction, a worker hat was on sitils performing plassing work on the eightheenth floor fell backwards onto the floor. The worker hut his back, suffered a twisted knee, and complained of head pain. An ambulance was called and the worker was transported to Bellevue Hospital. The worker was awake and alert.	No Dispatch			NB	320622616	Worker Fell	420 KENT AVENUE LLC	ZDG, LLC
9/2018	Brooklyn	1277	EAST 14 STREET	0	1 A competent person at the construction site reported that a worker slipped on a supported scaffold and fell approximately is ket est along with a few planks. The worker's foreman stated that the worker drove to see a doctor on his own. A DOB inspector responded and visited the site and reported that the supported scaffold did not conform to code specifications, as the scaffold was not fully plaked, the planks were not tied down, and a guard rail system was missing from multiple locations. Twe ECB Violations and a partial Stop Work.Order for a supported scaffold were issued.		35286912M,35285913Y		NB	320597127	Worker Fell	1277 HOLDINGS LLC	Ray Builders Inc.
/2018	Manhattan	40	CLERMONT AVE	0	1 The Site Safety Manager reported that a carpenter was working on an "A"-Frame ladder when he missed the fifth step of the ladder and fell. An ambulance came and took the worker to a hospital.						Worker Fell		
/2018	Manhattan	590	EAST 83 STREET	0	1 The Site Safety Manager reported that a worker tripped and jammed his finger. An ambulance took the worker to a hospital.	No Dispatch			NEW BUILDING	121190987-01-NB	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
2018	Brooklyn	10	MONTIETH STREET	0	1 The Site Super reported that a worker attempted to jump over a fence and fell. The worker was taken to a hospital by ambulance.	No Dispatch			NEW BUILDING	320622750-01-NB	Worker Fell	BUSHWICK HOLDINGS I LLC	GALAXY DEVELOPERS LLC
2018	Manhattan	108	EAST 89 STREET	0	1 The Site Safety Manage reported that a worker hurt his shoulder while installing a pipe scaffold. The worker went to a City M.D. to get checked.	No Dispatch			ALTERATION TYPE 1	122988623-01-AL	Worker Fell		E.W. HOWELL CO, LLC
1/2018	Queens	43-12	HUNTER STREET	0	A DOB inspector reported that contractors were in the process of lifting a section of stell casison in order to set it on a drill reg when a worker had his hand pinched between the calisson and a steller hok. The worker was alert and awake and was taken to a nearly hospital by a taxi. The extent of the injury of inspection. An EGS Violation for the a failure to satiguard and an EGS Violation for there a failure to satiguard and an EGS Violation for there was instructed to provide a Means and Methods for safe pile installation.		35314356z 35314356k		NB	420659530	Mechanical Construction Equipment	43-12 HUNTER LLC	Judy y Lee
/2018	Bronx	2028	CRESTON AVENUE	0	1 The Site Safety Manager reported that at an eleven story new building under construction, a worker was handling concrete out of a mixer when cement splashed into the worker's right yee. The worker was allert and awake and was taken to Lincoln Hospital for treatment.	No Dispatch			NB	220392858	Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MNGMT
/2018	Manhattan	650	5 AVENUE	0	The Site Safety Manager reported that a worker was working with temporary electrical wirting on the second floor when a 480-volt wire touched an I-Beam, which caused an ARC flash. The worker suffered an injury to his eyes and was taken to a hospital. A DOB inspector determined that there was no enforcement acton necessary.	No Action Necessary			Electrical	M00016968	Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
2/2018	Brooklyn	1835	STERLING PLACE	0	1 The Construction Superintendent reported that a worker sipped off of an "A-Frame ladder while coming down from the ladder. The worker suffered a minor lacenation to the head. The worker was found conscious and an ambulance was called.	No Dispatch					Worker Fell	NOT ON FILE	
23/2018	Manhattan	115	DELANCY STREET	0	1 The Bias Safety Manager reported that a worker was downing moving a Con Safetion wait when he lifed an ormanized piece of physoed that was covering the value, tripped rint a shaft, and fell aground waits waits the first. The worker suffered a cut to his ankie. The worker was alert and awake and was taken to Bellevue Hooptal. An ECB Violation for a failure to safeguard was issued, as well as a DOB Violation and a partial Skop Work Order for all exterior work at the ground floor at exposure three. Protections around the valual at the ground level must be provided. An updated Means and Methods and Tool Box Taik must be provided.		ECB#35317775Z -FAIL TO SAFEGUARD	032318BSO3GD01	NB	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES



ncident Date	Borough	Address Numbe	r Street	Fatalities Injuri		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
23/2018	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that an electrician wa climbing up the rebar cage to reach the electrical condu when he slipped, fell two feet, and landed on his right ankle. The electrician was sent to a clinic.	s No Dispatch					Worker Fell	40-56 TENTH OWNER LLC	
4/2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that a worker was cutting metal studs when he cut the top of his hand with a chop saw. The worker went to the emergency room with another worker. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
/2018	Brooklyn	19	INDIA STREET	0	1 The Site Safety Manager reported that a worker was moving windows when he tripped, fell three steps, and hit the back of his neck on a cinderblock. The worker was alert and responsive and was taken to Bellevue Hospital.	No Dispatch			NEW BUILDING	310234207-01-NB	Worker Fell	145 WEST STREET LLC	NOBLE CONSTRUCTION GR LLC
/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	 The Construction Superintendent reported that a worker was testing a refrigerant line when the line burst, causin, discomfort to the worker's ears. A co-worker drove the injured worker to a hospital. 	No Dispatch			Alt 1	320622894	Other Construction Related Incidents	ATLANTIC 2644, LLC	CAULDWELL WINGATE CO LLC
6/2018	Manhattan	250	SOUTH \$TREET	0	1 A DOB inspector reported that a worker was bringing a scaffold down when a guid dwind moved the platform out of the building. The worker stuck his hand out to prevent the impact against the building, but hut his shoulder and back in the process. The worker was taket to a hospital where he was in stable condition. It was determined that no enforcement action was necessary, as the suspended scaffold was found to be in Continuation and inspitation terms, the current continuation and inspitation terms on the engineer was onsite, and all logs were in order.		NA		NB	121185528	Scaffold/Shed/Fence/Shoring/Installation	NOT ON FILE	Lend Lease (US) Construct
26/2018	Manhattan	420	EAST 54 STREET	0	1 The Site Safety Manager reported that the building owner's personal driver had his foot struck by a forklit. The injured person was taken to a hospital. A DOB inspector reported that only one flag person was used when moving the forklit and that the injured person walked into a controlled no access zone when he that the or a failarly bardgenizer. A DOB Violation on as a Stop Work Order were also issued. A Means and Methods and Tool Box Take will be provided by the General Contractor at the site for safe delivery operations and for the proper amount of flaggers.	ECB Violation	35317780N	032618BSx6GD01			Other Construction Related Incidents	RIVER TOWER OWNER, LLC	
7/2018	Manhattan	432	EAST 14 STREET	0	1 The Construction Superintendent reported that a worker was pushing a mini container when she slipped and hit her knee. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	EAST 14TH STREET OWNERS LLC	
/2018	Manhattan	441	9 AVENUE	0	 The Site Safety Manager reported that a worker got his hand jammed between two stripping panels. A foreman took the worker to a hospital. 	No Dispatch					Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
3/2018	Brooklyn	505	PACIFIC STREET	0	1 The Site Safety Manager reported that a worker slipped with a grinder and cut his face. An ambulance transported the worker to a hospital.	No Dispatch			NEW BUILDING	320909004-01-NB	Other Construction Related Incidents	PVII HSC ATLANTIC LLC	TRITON CONSTRUCTION CO.,
0/2018	Manhattan	265	WEST 114 STREET	0	1 The Size Safety Managar reported that there was a worker on the second floor catalid deck carrying a plank. The worker learned on the plank, which caused the plank to fail and his a worker that was on the first floor scaffold deck in the arm. The injured worker went to a City MD. Jor an X-ray. An ECG Violation was issued for the storage of excess materials on a scaffold.	ECB Violation	35286045H		Ait 1	121189668	Material Fell	TRINITY WEST HARLEM PHASE TWO	Mega Contracting Gp LLC
2/2018	Queens	22-06	31 STREET	0	1 A competent person at the site reported that a worker that was coming into the site slipped on snow and injure his knee. The worker went to see his doctor for a check up. There was a snowstorm in progress as of the time or the incident.	d					Other Construction Related Incidents	DITMARS 31ST STREET ASSOCIATES	
2018	Staten Island	2655	RICHMOND AVENUE	0	A DOB inspector reported that there were workers that were moving a wooden ramp that was about 4' X B' X 20'. When the ramp was in a vertical position, one 2 X 4 fell onto the hand of one of the workers. The worker were to urgent care. An ECB Violation and a partial Slop Wor Order (PSWO) were issued for all use of ramps. A Means and Methods and the design drawing must be provided.	t	35327352X				Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
3/2018	Bronx	2681	MARION AVENUE	0	A DOB inspector reported that a flagger was signaling for deliveries for traffic on the street when a cab driver tride to manusever around a correr and ran over the flagger's foor. The flagger went to a hospital with a co-worker in a ambulance. The inspector determined that there was no enforcement action necessary, as the flagger was certified and a delivery Means and Methods was at the site.	n					Other Construction Related Incidents	PCMH MARION AVENUE HOUSING DEV	



ncident Date		Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/2018	Bronx	2760	BRIGGS AVENUE	0	1 The Site Safety Manager reported that a worker slipped on plywood that had now on it. The worker claimed to have hunt his wrist while trying to brace himself after slipping. The worker went to a dotor on his own. This incident accurred in the morning, but the worker waited until the aftermono to report the incident and go to a doctor. A DOB inspector visited the site and reported that there were no witnesses to the worker slipping and that there were novelra wisson work any tripping hazards in the area that the worker worker working, A cause of the slip could not be determined. Because of this, no enforcement action was deemed necessary.						Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
3/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker slipped						Worker Fell	NYC HPD	
3/2018	Brooklyn	422	FULTON STREET	0	on a wet surface and fell on his hand. The worker went to a City M.D. 1 The Site Safety Manager reported that a security guard				ALT 1	320908899	Other Construction Related Incidents	NOT ON FILE	TRANSPARENT CONSTRUCTION
					tripped and fell. The security guard was taken to a hospital as a precaution.								
/4/2018	Brooklyn	5615	7 AVENUE	0	2 The NYPD requested that an inspection please be performed because a construction fence fell at the site. A ODB inspector responded and visited the site and reported that the job site facera et avposure one had collapsed onto the public sidewalk. There were two injuries reported, a mother and a daughter. The mother and daughter were both taken to an area hospital. All fencing and debris at the site has been removed and made sale against the wind. An Aggravated Level 2 ECG Violation was issued for failure to safeguard. A DOB Violation and a full Sipp Work Order were also issued. This incident Number 25737 was deleted by acodent, and Incident Number 25473 was created in its place.		35323275N	040418CERCM02	Alteration 1	320516152	Other Construction Related Incidents	Siu Ping	GUO Z HUANG/NEWLAND CONSTRUCTIO
4/2018	Manhattan	500	WEST 33 STREET	0	1 The Safety Director reported that a worker slipped and hit her tailbone while getting off of a scissor lift. An ambulance was called and transported the worker to a hospital. A DOB inspector visited the site and issued an ECB Violation and a partial Stop Work Order on all use of scissor lifts. The General Contractor is to provide training.	ECB Violation	35327428N				Other Construction Related Incidents	NOT ON FILE	
5/2018	Manhattan	4	WEST 37 STREET	0	1 The Site Safety Manager reported that a plumber was found dead on the fourth floor of a framed out empty room. There wave no tools and no ladder found on the scene. A DOB inspector responded to the incident and visited the site, and reported that the worker suffered a possible heart stack and was revived with a faint pulse. No enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	4 WEST 37TH STREET LLC	
/6/2018	Manhattan	125	GREENWICH STREET	0	1 The Site Safety Manager reported that a worker hit himself in the face while stripping forms. The worker was driven to a City M.D.	No Dispatch			NEW BUILDING	121183799-01-NB	Other Construction Related Incidents	VS 125 LLC	PLAZA CONSTRUCTION LLC
/9/2018	Brooklyn	231	AINSLIE STREET	0	arriven to a Lity AU.: 1 A DOB inspector reported that, according to a worker that was at the site, the owner of the construction company at the lise was on a pipe scalified inspecting divided to grab a bite rack on the rear of the scalified. They bite rack was not properly secured and gave way, causing the owner to fail eight feet from the gipe scalified third to grab a bite rack on the rear of the scalified. The that was not point of the sidewalk shed dex. The owner was transported to an area hospital with serious inpures. There was scene debris found on the sidewalk shed deck, and the pipe scalified was not fully planked, aid not Crief (FSWO) were issued for the failure to saleguard Order (FSWO) were issued for the failure to saleguard to pip of the sidewalk mend, and a full Stop Work work without germit being performed, and for brick exterior work that exceeded the area that does not require a permit.		35323246M & 35323246y	040918CERDF03 & 040918CERDF04			Worker Fell	ST OONO DE TEGGIANO C	
/9/2018	Brooklyn	420	KENT AVENUE	0	1 The Site Safety Manager reported that a steamfitter cut his finger while putting coupling on a pipe. 911 was called and the worker was taken to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	420 KENT AVENUE LLC	
/9/2018	Manhattan	11	WEST 53 STREET	0	amountoe. 1 The Construction Superintendent reported that a worker was on a acissor lift and was trying to gain access into a plenum. The worker's hand was on the handrail of the acissor lift and his hand got pinned between the handrail and the hanging door of the plenum. The worker's hand was cut and the worker went to a hospital for a checkup.				ALTERATION-1	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	TURNER CONSTRUCTION CO



cident Date		Address Number		Fatalities Injuri		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	15	WEST 25 STREET	0	1 A DOB inspector reported that a worker was using a hole	DOB Violation	35323475H	040918CERND01	ALTERATION TYPE 2	123203069-01-EW-OT	Worker Fell	ST SAVA CATHEDRAL	G.P.J. O'DONOGHUE CONTRAC
					saw that jammed. The Construction Superintendent unplugged the tool and straightened it out. When the								
					unplugged the tool and straightened it out. When the hole saw was plugged back in the saw swung around								
					and pushed the Construction Superintendent down.								
					causing him to fall approximately eleven feet. The								
					Construction Superintendent was taken to a hospital in								
					serious condition. The Construction Superintendent is								
					now stable, but suffered a brain injury. An ECB Violation,								
					a DOB Violation, and a full Stop Work Order (FSWO)								
					were issued for a failure to safeguard during construction	i la							
					operations, as the Construction Superintendent fell in a								
					location where there were no guardrails installed.								
)18	Manhattan	25	PARK ROW	0	1 The Site Safety Manager reported that a hoist installer	No Dispatch					Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	
					got the tip of his finger crushed while working on the								
					hoist when the gate came down. The worker was taken								
					to the emergency room.								
18	Manhattan	420	EAST 54 STREET	0	1 A DOB inspector reported that there were three workers	ECB Violation	35317792K, 35317793M		ALTERATION 2	122939357	Worker Fell	RIVER TOWER OWNER, LLC	VECTOR BUILDING CORP
					working on the thirty seventh floor doing interior								
					demolition work and removing debris. There was an								
					approximate 27" X 27" opening in the floor that was not								
					properly covered, as a door from the demolition work was used to cover the hole and the hole was not properly								
					marked or secured. One of the workers picked up the	/							
					marked or secured. One of the workers picked up the door, unaware of the hole underneath it, and fell through								
					door, unaware of the hole underneath it, and tell through the opening to the thirty sixth floor. The worker was sent								
					to a hospital for a checkup. Follow up information								
					regarding the injured worker is not currently available.								
					Two ECB Violations were issued for the failure to								
					maintain safety measures and for inadequate								
					housekeeping. A full Stop Work Order was also issued.								
					The GC is to provide a Means and Methods for the safe								
					operation of the job, including the protection of empty								
					shafts and floor openings.								
18	Queens	123-30	ROOSEVELT AVENUE	0	1 The Site Safety Manager reported that a worker tripped	No Dispatch					Other Construction Related Incidents	NYC PARKS	
					on a curb and twisted his ankle while carrying a panel.								
					An ambulance was called.								
18	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker stepped	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
10	Queens	147-40	ARGHER AVENDE		on a tie-wire that was used for rebar work and the tie-	NO Dispatch					Other Construction Related Incidents	THE SAMSTA HOUSING DEV. FUND CO	
					wire punctured his boot and foot. The worker went to see								
					a doctor on his own.								
		150	5 AVENUE		1 The Site Safety Manager reported that a worker slipped				ALTERATION TYPE 1	122700292-01-AL	Worker Fell	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
2018	Manhattan	150	5 AVENUE	0	1 The Site Safety Manager reported that a worker slipped	No Dispatch			ALTERATION TYPE 1	122700292-01-AL	Worker Fell	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
					while coming down from a ladder. The worker was taken								
					to a hospital by an ambulance.								
2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that a worker was on	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
					a six foot ladder when he missed the second rung of the ladder while coming down from it and fell backwards and								
					hit his head. The worker went to a hospital with his shop								
					steward.								
2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
					stripping form work when a dust particle got between his								
					safety glasses and irritated his eye. The worker went to a	1							
					nearby City M.D.								
2018	Bronx	600	BERGEN AVENUE	0	1 The Site Safety Manager reported that a worker was	ECB Violation	35314470y		NB	220151868	Mechanical Construction Equipment	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST.DEVELP.
					pumping grout to tie backs when the hose clogged.								
					When the worker opened up the hose clamps to clean								
					the hose, the worker got grout in his eyes. The worker								
					did not realize that pressure had built up when he								
					removed the hose clamps. The worker was taken to a								
					City M.D. and was then transferred to an emergency								
					room at Lincoln Hospital.								
2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
					walking on the second floor when he stepped on a nail.								
					The worker went to get a tetanus shot.								
/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manger reported that a worker twisted	No Dispatch			NEW BUILDING	520135675-01-NB	Worker Fell	MACY'S RETAIL HOLDINGS, INC.	AURORA CONTRACTORS INC
					his knee while climbing down from a machine. The								
					worker was driven to the emergency room.								
2018	Bronx	2044	WESTCHESTER AVENUE	0	1 The Project Manager at the site reported that a masonry	No Action Necessary	NA		NB	220152572	Worker Fell	HP WESTCHESTER MEWS HOUSING DE	Procida Construction Corp
		2011		Ŭ	worker was laying cinderblocks when he fell off a				10				Construction only
					supported scaffold that was approximately three feet in								
					height. The worker landed on his back and appeared to								
					be in stable condition, but refused to talk to anyone until								
					an ambulance arrived. The worker was taken to Jacobi								
					Medical Center. A DOB Inspector responded and visited								
					the site and determined that no enforcement action was								
					necessary, as the supported scaffold was found to be								
					structurally sound with a guard rail system in place.								
		20	BROAD STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.	
018	Manhattan				pushing a mini-container through a wall opening when he	9							
018	Manhattan												
18	Manhattan				pinched his pinky finger. The worker left the site to see a								
018	Manhattan				doctor for treatment.								
	Manhattan	701	7 AVENUE	0	doctor for treatment.				ALTERATION TYPE 1	121324343-01-AL	Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	CNY CONSTRUCTION LLC
2018		701	7 AVENUE	0					ALTERATION TYPE 1	121324343-01-AL	Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	CNY CONSTRUCTION LLC



ncident Date	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
14/2018	Brooklyn	50	COURT STREET	0	3 DOB's Emergency Response Team was informed that a sidewalk shed was in the process of being dismanifed when a partial collapse occurred at the corner of Court Street and Joralemon Street. Approximately twenty linea feet of the sidewalk shed collapsed. Two pedestrians and one worker suffered non-life threatening injuries and were sent to Luthrean Aboptial. The remaining	ECB Violation	35323276P	041418CERCM01	Alt 3 - SH	321426774	Scaffold/Shed/Fence/Shoring/Installation		NEW FORCE CONSTRUCTION CO
					unaffected parts of the sidewalk shed were removed. The Department Of Transportation replaced the cross walk light at the site. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard all persons and property affected by construction operations. A DOB Violation was also issued.								
/2018	Manhattan	130	EAST 82 STREET	0	1 The Site Safety Manager reported that a worker accidentally ran a screw into his hand while screwing screws during duct work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	134 EAST 82 LLC	
2018	Brooklyn	856	WASHINGTON AVENUE	0	1 The Site Safety Manager reported that a worker was drilling a core hole in a deck slab when the drill kicked back and the base of the drill hit him on the side of his face. The worker was alert. The worker went to a hospita by ambulance.	No Dispatch					Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
/2018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker slipped while going down the stairs. There were no witnesses to the worker slipping, and the stairs were free of debris. Ar ambulance was called. The worker was okay, but walker to the ambulance when the ambulance arrived at the site and went to a hospital.	1					Other Construction Related Incidents	NYC DSBS	
7/2018	Brooklyn	1900	PARK PLACE	0	 The Site Safety Manager reported that a worker strained his lower back while picking up a cement block. An ambulance was called. 	No Dispatch					Other Construction Related Incidents	HABITAT FOR HUMANITY LATENT TH	
8/2018	Brooklyn	25	EAST 19 STREET	0	The Site Safety Manager reported that a worker was passing an I-Beam down from a sidewalk shed when he lost his footing and leil about sideen feet to the ground. The worker was wearing a harness that as not attached to anything. The worker was found awake and speaking and was taken to a hospital. An ECB Violation was issued for a failure to safeguard persons and property.	ECB Violation	35323790H		Alt	340452520	Worker Fell	EBE HOLDING LLC	CS Bridge Corp
8/2018	Manhattan	220	CENTRAL PARK SOUTH	0	 The Site Safety Manager reported that a worker cut his finger when another worker closed a door on his hand by accident. A co-worker took the injured worker to a hospital. 	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
3/2018	Queens	71-17	ROOSEVELT AVENUE	0	1 The Site Safety Manager reported that a worker sprainec his back while carrying steel form. The worker went to a hospital by ambulance for observation.	I No Dispatch					Other Construction Related Incidents	ROOSEVELT PARC LLC	
8/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker hurt his shoulder when he picked up a bundle of threaded rods. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
/2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker was conducting a survey and was wearing proper footwear when he stepped onto a nail that punctured his foot. The worker went to urgent care for a tetanus shot.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
9/2018	Manhattan	70	VESTRY STREET	0	1 The Site Safety Manager reported that a worker was installing 3' X 6" stone at the base of a building when his knee gave out, causing the worker to fall onto his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	BRIDGE LAND VESTRY LLC	
/2018	Manhattan	112	WEST 25 STREET	0	1 The Site Safety Manager reported that a subcontractor was carrying a door from a truck when the door fell and leaned on the subcontractor's right knee. The worker did not suffer a visible injury, but was in pain. An ambulance transported the worker to a hospital for a check up.				NEW BUILDING	121187214	Material Fell	LAM GEN 25 LLC	FLINTLOCK CONSTR SVCS INC
9/2018	Brooklyn	422	FULTON STREET	0	1 The Site Safety Manager reported that a worker was performing demolition work on the roof of a building when he felt pain in his back while lifting a barrel. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/2018	Bronx	545	EAST 166 STREET	1	ambulance was called. O The New York City Police Department reported that a worker was hit by a hoist. A worker was on the eighth floor securing a pixed winking within he stepped up onto a bucket to look over the gate while trying to securing pixed. The hoist came down at the same time that the worker was learning over the gate. The worker was struck in the head and succumbed to his injuries. An Aggraviate Level 2 ECB Violation was issued for the unsale or improper use of hoist equipment.	ECB Violation	38259262J	042018E2607B01			Mechanical Construction Equipment	545 E. 166TH STREET HDFC	
0/2018	Manhattan	45	PARK PLACE	0	1 The Site Safety Manager reported that a carpenter foreman was securing a formwork panel for the shear wall and was repositioning his retractable device with both hocks in one anchor point when the insert gave way, causing the foreman to fall about ten feet backwards. The foreman was taken to a hospital.	ECB Violation	35326676H		NEW BUILDING	121185635	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST



cident Date	Bereuch	Address Music	- Ctreat	Estalities Interior	EQC Final Description	DOB Action	ECD Violation Numbers	DOB Violation Numbers	Permit	Desmit No.	Incident True	Oursele Neme	Contractor Name
cident Date 20/2018	Borough Manhattan	Address Number 560	WEST 33 STREET	Fatalities Injuries	ECC Final Description 1 The Site Safety Manager reported that a worker was climbing up a baker's scatfold when he lost his grip on the second rung of the ladder and fell about two feet. The worker holde over onto a bucket and stiffered an injury to his rise. A DOB inspector responded and visited the site and reported that no enforcement action was	No Action Necessary	ECB Violation Numbers	DOB Violation Numbers	Permit NB	Permit No 1211192618	Incident Type Worker Fell	Owner's Name ERY NORTH TOWER RHC TENANT LLC	Contractor Name Roger & Sons Conctrete Inc
					necessary, as the necessary safety measures were provided at the site. It was detemined that the incident occurred due to a worker's error.								
2018	Manhaitan	400	WEST 61 STREET	0	1 The Site Safety Manager reported that at a thrify eight istory new building under construction, a plumber was placing a pipe into hangers when the plumber fell off of a ladder. There were no witnesses to the height of the fail, and the plumber claimed to have failen approximately alter, awake, and complaining of pluin in his iny. The plumber was taken to SL Luke's Hospital by ambulance. A DOB inspector responded and wisted the site and determined that there was no enforcement action necessary, as the fail occurred as the result of a worker's error.				121193181	NB	Worker Fell	RCB1 NOMINEE LLC	TISHMAN CONSTRUCTION CORP
2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker on the first floor bumped his knee on a reshore tripod. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Brooklyn	540	FULTON STREET	0	1 The Site Safety Manager reported that an iron worker pinched his finger while unloading steel rebar from a truck. The worker left to go to a clinic.	No Dispatch					Other Construction Related Incidents	540 FULTON ASSOCIATES	
6/2018	Manhattan	461	WEST 34 STREET	0	1 The Gills Solidy Managor reported that a worker was on the twenty rejubit floor of a twenty rines story new building and ware cutting sheetrook and metal tetut for electrical work when he suffered a cut to his hand. A negrocal blade jammed and the worker's hand got caught. The worker was found awake and alert and was taken to a nearby hospital.	No Dispatch			NB	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	ATRIA BUILDERS LLC
/2018	Manhattan	225	BOWERY	0	1 It was reported that there were workers that were moving materials on the root. When the workers moved a netal pice together, one of the worker's right hand yot caught in the pinch point. The worker suffered a scrape to his right hand. An ambulance was called to the site. The worker received stitches at Mount Sinai Hospital.					121862751	Worker Fell	VNAA BOWERY LLC	AEH-VSLV, LLC
/2018	Manhattan	22	NORTH LOOP ROAD	0	1 The Site Safety Manager reported that a worker hit his left hand with a hammer. The worker went to urgent care	No Dispatch					Other Construction Related Incidents		
/2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that at a fifty seven story building that was under construction, a worker was cutting metal with a grinder when he cut his left shin. Th worker was conscious and alert and walked to New York Presbyterian Hospital.					121290085	Other Construction Related Incidents	NOT ON FILE	AHEARN-HOLTZMAN, INC
/2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that a worker was coming down the stairs on a scaffold when he slid down the stair riser. The worker went to a City M.D.	No Dispatch					Worker Fell	95TH AND THIRD LLC	
/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that during concrete operations, a laborer was removing concrete key when his finger got scatched between refar. The worker was working alone and scratched his finger while reaching into formwork. The worker went to a City M.D. and returned to work in two days.	No Dispatch			NB	321197478	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
/2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker struck his left thumb with a hammer while hammering a nail. The worker took himself to a City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a worker was shaking out steel at the street level when he pinchee his finger between a two by four and a steel beam. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	THE SALVATION ARMY	
//2018	Manhatan	1059	3 AVENUE	0	1 The Site Safety Manager reported that a pocketrian were over a ramp in front of the site, singeditipped on damaged mesh, and fell. The pedestrian suffered an injury to het let below and was taken to a hospital. A DOB imspector reported and visited the site and reported that the General Cortractor at the site failed to maintain the pedestrian walkway that caused the incident. An Apgravetal Cavel 2 CEO Violation was issued for a failure to safeguard. A partial Slop Work Order was issued on all activities in the occupied lane next to the sidewalk to ensure that it is free of all tripping hazards.	ECB Violation	35318046N				Other Construction Related Incidents	63RD & 3RD NYC LLC	
0/2018	Manhattan	130	WILLIAM STREET	0	1 The Site Safety Manager reported that a worker was tattempting to help a carpenter when he accidentally walked into the wwing radius of a hammer and got hit in the forehead by the hammer. The worker was taken to New York Presubjerian Hospital and was in stable condition. A DOB inspector responded and visited the site and determined that no enforcement action was necessary, as the incident occurred as a result of a worker's error.	No Action Necessary			NB	121192903	Other Construction Related Incidents		GILBANE RESIDENTIAL CONST



ident Date	Borough	Address Number	Street	Fatalities Iniuri	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Goroga Manhattan	425	PARK AVENUE	0	I A DOB inspector reported that masons were finishing concrete pouring pads on the sixteem floor when a worker that was working with the masons removed the floor protection and fell approximately bitmeen feet from the sixteemth floor to the fitteenth floor. The worker suffered a out to his ear and comparised to have any hexpair. The worker was taken to Cornel University hexpair floor exercision. The SEO Violations were openings present and to the failure to maintain safety openings present and to the failure to maintain safety openings.	ECB Violation	35326636N / 37P	043078BS05GD01/02			Worker Fell	T-C 425 PARK AVENUE, LLC	
					issued on all work within ten feet of all floor coverings on all floors and for the floor coverings being not properly secured. Two DOB Violations were also issued. A Means and Methods for the installation of floor coverings must be provided.								
18	Manhattan	540	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker suffered	No Dispatch			NEW BUILDING	121191968-01-NB	Other Construction Related Incidents	CLINTON HOUSING DEVELOPMENT	MEGA CONTRACTING GP LLC
118	Manhattan	390	MADISON AVENUE		a cut finger. An ambulance was called. 1 The Site Safety Manager reported that a worker on the	No Dispatah					Worker Fell	COMPTROLLER OF NY STATE	
10	Wallhattall	390	MADISON AVENUE	0	first floor stately wanager reported that a worker on the first floor stepped up on a few concrete mesonry unit blocks when he fell approximately three feet off of the blocks and landed on a metal plate. EMS was called and transported the worker to a hospital.						wurker Peil	COMPTROLLER OF NT STATE	
118	Manhattan	222	EAST 41 STREET	0	1 The Site Safety Manager reported that a worker was installing metal trim when a cut piece fell down and lacerated his wrist. The worker was sent to a hospital.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
018	Brooklyn	1277	EAST 14 STREET	0	1 The Construction Superintendent reported that a plumber was cutting a metal stud to get to a pipe when he cut his arm on the stud. An ambulance was called.	No Dispatch					Other Construction Related Incidents	1277 HOLDINGS LLC	
2018	Manhatlan	10	VANDERBILT AVENUE	0	1 The Site Safety Manager reported that a latherer was coming down from a rebar cage when he missed his last step, fell backwards, and hurth har ankle. The worker went to a hospital by ambulance. It was reported that the worker suffered a broken ankle. A DOB inspector responded and visited the site and reported that the operation was proceeding according to the site plan. No enforcement action was deemed necessary.						Worker Fell	ONE VANDERBILT OWNER LLC	
8	Manhattan	320	EAST 43 STREET	0	1 The Site Safety Manager reported that a worker was cleaning near the dumpster in the basement C-Level area when he hit his lower lego na dumpster. The worker was cut, but the bleeding was stopped. The worker does not know how he hurt himself. An ambulance was called.	No Dispatch					Other Construction Related Incidents	FORD FOUNDATION	
)18	Brooklyn	10	HURON STREET	0	 The Site Safety Manager reported that a worker cut the skin of his finger on a table saw. The worker went to a hospital with a co-worker. 	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
18	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker got a spark in his eye under his safety glasses during a grinding operation. The worker went to a hospital on his own.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
18	Queens	36-18	MAIN STREET	0	1 The Site Safety Manager reported that a worker was coming down off of a ladder when he lost his balance and grabbed onto a metal stud, causing a cut to two of his fingers. The worker went to urgent care.	No Dispatch					Worker Fell	134-22 35TH AVE., LLC	
18	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that a worker sliped on rebar and hurt his wrist. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	40-56 TENTH OWNER LLC	
18	Manhattan	308	WEST 133 STREET	0	The Site Safety Manager reported that a worker was calking a window when he felt from a baker scafficd and hurt his left leg. The worker was taken to a hospital. A DOB inspector responded and visited the site and reported that the worker was not tied of twhen he felt. Two ECB Violations were issued for a failure to safeguard and for a failure to provide a four hour user training card. A partial Sitey Work Order was issued on baker scaffolds until a Means and Methods is provided.	ECB Violation	35323933X, 35323934H		NB	122620333	Worker Fell	308 WEST 133RD STREET LLC	Happy Living Development
18	Brooklyn	810	FULTON STREET	0	2 The Sine Safety Manager reported that two workers were trying to install a pipe on top of a baker scaffold when both of the workers leaned towards the same side of the scaffolding, which caused the baker scaffold to collapse. The two workers fell approximately four feet and landed on the floor. An ambulance was called. A DOB inspector responded and visitation for three baing no personnel on site issued: one visitation for three baing no personnel on site user cards, and a second ECB Violation twere safeguard all persons and property affected by construction operation. A partial Stop Work Order has been issued on baker scaffolds until a Means and Methods is provided.		36323604H,36323605J		NB	320597083	Worker Fell	GREENPOINT-GOLDMAN CORP.	Bradway Construction



cident Date	Borough	Address Number	Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/2018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker was unloading a pallet of glass that was approximately 2' X 8' when the pallet of glass tiped over onto him and primed him against the wall of the truck. The worker went to a hospital by ambulance. A Dob Inspector responded and visited the site and issued an Aggravated Level 2 ECB Violation for a failure to aslexuard, as there was no	ECB Violation	35318496K	050418BS02JJ01			Material Fell	NYC DSBS	
					Means and Methods for delivery operations available for the previous delivery operations that happened at the site. A partial Stop Work Order was issued on all deliverens. A Means and Methods for safe delivery operations and Tool Box Talks must be provided.								
/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker slipped on rebar and cut his right thumb. The worker walked to the FR	No Dispatch					Other Construction Related Incidents	NYC HPD	
/2018	Bronx	600	BERGEN AVENUE	0	1 The Site Safety Manager reported that a welder was performing Support OE scawation (SOE) work when he picked up a step late that was 12 X 12 and 38 thick when he injured his back. A co-worker took the worker to a City M.D., where a physician economenide medication for pain and rest for three days. A DOE inspector responded to the incident and wisited the site and reported that there were no unsafe conditions found and hat all of the workers at the site had ten hour OSHA cads. No enforcement action was deemed necessary.	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountoo Constroution & development
2018	Brooklyn	2085	ROCKAWAY PARKWAY	0	1 The Construction Superintendent reported that a worker from the sidewalk shed company fell four feet while descencing from a baker scaffold. An ambulance took the worker to a hospital.	No Dispatch			ALTERATION TYPE 3	340451308-01-EQ-SH	Worker Fell	NYC HOUSING AUTHORITY	SKYWORX CONTRACTING INC
2018	Brooklyn	814	BEDFORD AVENUE	0	1 The New York City Emergency Management Department and the New York City Ten Department reported that and the New York City Ten Department reported that and the New York City Ten Department reported that dock when the worker for algorotransky fifteen feet into the cellar and landed on capped rebar. The worker was lawn to a hospital and was accompanied by another worker. The injured worker did not suffer any life- threatening injuries. An ECB Volucian for the failure to maintain safe operations was issued. A full Stop Work Order (FSWQ) was also issued. Additional safety volations will be issued.	ECB Violation	36327578Z				Worker Fell	814 PARK LLC	
2018	Queens	24-02	49 AVENUE	0	1 The Site Safety Manager reported that a worker at the foorth floor level was struck by duct work that was approximately time the high white the non-level that was approximately time the high white the software losses, same down, and struck the worker white o taude him to fail of the laider. The worker suffered a broken leg and was taken to a nearby hospital. A DOB inspector responded and visited the site and tissued an ECB Volation for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued.		35326093Y	050718BS02DH01	ALT1	421518566	Worker Fell	LIC 73 OWNER, LLC	UNITY CONSTRUCTION GROUP
2018	Manhattan	250	BRADHURST AVENUE	0	1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a façade connection. The worker went to a hospital by ambulance to receive stitches on his finger.	No Dispatch					Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
2018	Brooklyn	535	4 AVENUE	0	1 The Site Safety Manager reported that a hoist mechanic lacerated his finger while cutting a piece of plastic away from a hoist. A co-worker took him to a hospital.	No Dispatch					Other Construction Related Incidents	XYZ PROPERTIES INC	
2018	Brooklyn	11	HOYT STREET	0	1 The Site Safety Manager reported that a worker was working on a rebar wall when he was struck in the neck by disodged shoring. A DOB inspector responded and vited the site and reported that reshores were installed contrary to the approved plan. An ECB Violation and a partial Stop Work order (PSWO) on all concrete work were issued.	ECB Violation	35331175X				Other Construction Related Incidents	11 HOYT PROPERTY OWNER, LP.	
2018	Manhattan	115	DELANCEY STREET	0	1 The Site Safety Manager reported that at a twenty us story one building under construction, a worker was coming back on site when he stapped on hose concrete masony and turned his andle. The worker was found alert and awake. The on-site medic issued ice for on-site (reatment and the worker werk to a nearby urgent care center to receive further treatment.	No Dispatch			NB	121191646	Other Construction Related Incidents		T.G. NICKEL & ASSOCIATES
2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager reported that a worker jammed his finger while drilling into concrete. The worker walked to the emergency room.				NEW BUILDING	121333440-01-NB	Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	RNC INDUSTRIES LLC
/2018	Manhattan	560	WEST 33 STREET	0	1 The Site Safety Manager reported that an electrician was walking down stairs when he hurt his ankle on permanent stairs. An ambulance was called.	No Dispatch					Other Construction Related Incidents	ERY NORTH TOWER RHC TENANT LLC	



ident Date	Borough	Address Number			DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Oueens	54-17	101 STREET 0	2 New York City Emergency Management reported that two workers that were working on wires on the builthead when they experienced electric schock. The workers were able to make it down from the builthead and were transported to a hospital. A DOB imspector responded to the incident and visited the site and issued two EGB Violations for the exposed wires at the builthead area not being properly terminated, secure, and protected around the HVAC air handler unit. A partial Stop Work Order (PSWO) was also issued for electrical work.	ECB Violation	З5313352Z 35313353K				Other Construction Related Incidents	HANAC CORONA HOUSING DEV. FUND	
0/2018	Manhattan	80	EAST10 STREET 0	1 The Site Safety Coordinator reported that a worker was moving paliets of concrete block around when some of the concrete block field and astack the worker's right nospital for treatment. A DOB inspector responded and visited the site and record that the worker culled the	No Action Necessary			NB	121193476	Other Construction Related Incidents		CCNY CONSTRUCTION INC
018	Manhattan	7	WEST 57 STREET 0		No Dispatch					Other Construction Related Incidents	7 WEST 57TH STREET REALTY COMP	
				discomfort in his shoulder during stripping operations. The worker took a cab to a clinic on his own.								
)/2018	Manhattan	515	WEST 36 STREET 0	1 The Site Safety Manager reported that a worker was pushing a cart when he tripped on planks that were covering a hole. The worker suffered a cut to his right hand and went to a hospital. A DOB inspector responde to the incident and visited the site and issued an ECB Volation for the improper covering of holes.	ECB Violation	35331118J				Other Construction Related Incidents	FIRST ST MARKS LLC	
2018	Manhattan	424	EAST 34 STREET 0	1 The Site Safety Manager reported that a tapper tried to move an "A"-Frame with masonite on it out of his way by himself when he tipped the "A"-Frame and was hit in the right shin by both the "A"-Frame and the masonite. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NYU HOSPITALS CENTER	
2018	Brooklyn	8	NEVINS STREET 0	1 The Site Safety Manager repoted that a worker was stripping form work on the eighteenth floor when a post fell forward and hit him in the back. The worker experienced back pain and an ambulance was called. A DOB inspector responded and visited the site and reported that another worker had leand a stripping post against a wall instead of stacking the post and the post and the post and worker. An ECB Violation post of or a time will worker. Institute/follow safety measures for stripping operations. A DOB Violation was also issued.	ECB Violation	35326856P	05101888/02.J01			Material Fell	NEVINS STREET OWNER LLC	
2018	Bronx	1410	STORY AVENUE 0	A DOB inspector reported that a worker was sitting on top of a beam setting joists on the second floor of a new when the signal runs signal data beam second floor of a new when the signal runs signal data beam second floor of a hoist up with steel chokers (no load) on the book. While hoisting up, one of the chokers snagged the joist and picked it up. The worker who had landed the joist tried of get out of the way from the joist, built ost his balance and fell two stories to the ground. The worker was not tied of Other workers at the sile reported that the injured worker was bleeding from the mouth and was experiencing severe pain in his legs, but was conscious. The worker was bleeding from the mouth and was experiencing severe pain in his legs, but was conscious. The worker when how the severe the severe the severe the severe the size of the severe the severe the severe the severe the balance operator (H MG) at the site stated at the time of the incident and was given the lokar to host up via radio. The lift director loys severe filed out and were on site. However, the lift director was not on site as of the time of inspection, because he had gone to the hospital with the nigured worker. Two ECB Violations for a failure to safeguard were issues to the General Contractor and the crane operator. A full Stop Work Order (FSWO) was set as a file time of inspection, as well as a pairtial Stop Work Order (FSWO) for the unsafe placement of steel member/viol joist. A designated Construction Superintendent on a PW2 application form and a Means and Methods for the aslee operations of steel placement must be provided.		35327286R 35327285P	051018BS08VP01.02			Worker Fell	BR-2012 REALTY LLC	
2018	Staten Island	2655	RICHMOND AVENUE 0	1 The Site Safety Manager reported that a worker cut his right thumb while installing duct work. The worker went to urgent care. An ambulange was not called.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
2018	Manhattan	553	WEST 30 STREET 0	urgent care. An ambulance was not called. 1 The Site Safety Manager reported that a worker was using a grinder and suffered a cut to his right leg when the grinder kicked back. The worker was taken to a hosoital by an ambulance.	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	425	PARK AVENUE	0	1 The Site Safety Manager reported that a worker cut his finger while using a band saw and suffered a minor gash	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
/11/2018	Manhattan	357	EAST 57 STREET		to his finger. An ambulance was called.	ECB Violation	35245543J	051118CERJM01	ALTERATION TYPE 2	123179951-01-EW-OT		357 EAST 57 STREET CONDOMINIUM	EDRAS GROUP CORP
11/2018	Manhatlan	357	EASI 57 SIREEI	U	1 A DOB inspector reported that flagade work was underway at exposure floor on the sixteenth floor when a section of brick veneer dislogided and fell onto the sixtewait shoet. A pedestrian at the street level suffrerd amore injury, but refused medical attention. Th company that encided the sidewalk shed was onsiste to repair the shed. An EOS Violation was issued to the General Contractor at the site for a failure to safeguard. A DOB Violation was also issued. A full Stop Work Order (FSWO) was also issued.		352455433	05118CERJM01	ALTERATION TYPE 2	123179951-01-EW-OI	Matenal Fell	357 EAST 57 STREET CONDOMINIUM	EURAS GROUP CORP
11/2018	Manhatlan	305	WEST END AVENUE	0	1 The Construction Superintendent reported that an electrician was working on the emergency lighting of the seventh floor permanent stairs when he was hit in the head from a tape measure that fell from above. The electrician was taken to a hospital. A DOB inspector responded and visited the site and issued an ECB Violation for the failure to maintain safe operations and a partial Stop Work Order (PSWQ) for all work next to operings. The General Contractor is to provide a Means and Methods and a Toolbox Taik.		35331190Y				Matarial Fell	305 WEST END PROPERTY, LLC	
1/2018	Brooklyn	76	NORTH 6 TH STREET	0	1 The Construction Superintendent reported that a worker was cleaning a paint gun when his finger was injured by the pressure from the nozzle. The worker went home to see his doctor due to pain in his finger.	No Dispatch					Other Construction Related Incidents		
2/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker twisted his knee on Saturday, May 12, 2018. This incident took place on May 12, 2018, but was reported on Monday, May 14, 2018. The worker walked himself to a hospital.	No Dispatch			NEW BUILDING	121186849-01-NB	Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
/12/2018	Manhatlan	500	WEST 25 STREET	0	The Site Safety Manager reported that workers were removing material from the grade level at the leading edge when the pieces of calisson pillings that were approximately two feet tong were cuin halt. The pieces of calisson pillings felt approximately fifteen feet and struck a worker that was in the eactwardion pill in the leg. The worker went to a hospital. The status of the worker's righters is unknown. A DGB inspector responded and visited the site and issued four ECB Violations for the abscence of the bands at the guardhalt, the presence of an addreguate writical nations, the presence of an addreguate writical nation, the presence of an and the presence of inadequate housekeeping. A partial Stop Work Order (PSWO) and four DDB Violations were also issued. The contractor is to provide a Means and Methods and a Toolbox Talk for the sale continuation of work.	ECB Violation	35331325M/26Y/27X/28H	051218BS04PK01/02/03/04			Other Construction Related Incidents	500 W25TH OWNER LLC	
4/2018	Brooklyn	211	72 STREET	0	1 The New York City Fire Department reported that a worker was walking on a scaffold on the second level when he tripped and hurt his knee. The worker was taken to an area hospital.	No Dispatch			A2 - ALTERATION TYPE 2	302579662	Worker Fell	DEPARTMENT OF EDUCATION	KG CONSTRUCTION SERVICES
'14/2018	Brooklyn	7	WHIPPLE STREET	0	1 The Construction Superintendent reported that workers were installing O-decking on the second floor when a worker fell from the second floor onto the first floor deck. The worker was found conscious and was transported to Bellevue Hospital. Additional information regarding the injuries was not available. The Construction Superintendent was not on site as of the time that the Incident occurred. An DOB impector responded and Visited the site and insued an ECB Violation to the General Contractor for a failure to safeguird. ADOB General Contractor for a failure to safeguird. ADOB issued.	ECB Violation	35308771R	051418CNEDG01	Ait 1 / NB	321285275	Worker Fell	WHIPPLE PROPERTIES LLC	SUNSHINE CONSTR USA INC
4/2018	Manhattan	150	FIFTH AVENUE	0	1 A DOB inspector reported that there were workers moving steel beams with an electric hoist through a shaftway for an alteration on a twelve story building. The workers moved the beams by pipe rollers on the ground to be stacked. One of the workers was adjusting the stack when he was struck by two other workers that were putning steel in place. The struck worker got his right hand crushed between two beams and was taken to failure to stagend was issued. A partial 30% Work. Order (PSWQ) was issued on all work in athtway hoisting materials. A Means and Methods and a Toolbox Talk must be provided.	6	35331133H-FAIL TO SAFEGUARD.		ALT1	122700292	Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
5/2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was on the roof setback setting roof pavers when he stepped in a hole with the roof pavers that he was working on and hit his right shin. The worker was conscious and alert and walked to a City M.D. to be checked out.	No Dispatch			ALT1	121324343	Worker Fell	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
15/2018	Manhattan	627	GREENWICH STREET	0	1 The Site Safety Manager reported that a plumber slipped off of the fourth step of a ladder that he was working on and suffered a sprained ankle. An ambulance was called	No Dispatch					Worker Fell	627 GREENWICH OWNER LLC	



cident Date		Address Number	Street			DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	500	WEST 33 STREET		1 A DOB inspector reported that materials that were stored in the staging area were blow away due to wind. Among the stored materials was a piece of styroloam that was approximately by X3 X3 that that twick a security guard in the back. The security guard complained of pain and was taken to a hospital in a conscious state with an unknown injury. An ECB Violation was issued, as well as a partial due to a failure to secure stored material. The General Contractor is to provide a Means and Methods for a safe storage procedure.	ECB Violation	35326800X				Other Construction Related Incidents	NOT ON FILE	
/2018	Manhattan	20	BROAD STREET	0	The Site Safety Manager reported that a worker tripped on definis and fall on his back. An ambulance was called a DOB inspector responded and wisked the site and reported that no enforcement action was necessary, are worker was calvery and was reported to have returned to work the following day.	No Action Necessary					Worker Fell	NY STOCK EXCHANGE BLDG. CO.	
5/2018	Manhattan	100	EAST 104 STREET	0	2 The New York City Police Department reported that (debrs was failing from the building, A DOB inspector responded and visited the site and reported that at the fifteenth hoor setback, sections of isolation and plywood became separated due to high winds and fell bot the site of the individual that was struck was taken to a local hospital. An aggraveted Level 2 ECB Violation was issued for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued.	ECB Violation	35309489H	051518CNEGS02	NEW BUILDING	121192887-01-NB	Material Foll	TERRACE ON THE PARK LLC	GLENWOOD CONSTRUCTION
5/2018	Manhattan	1	WALL STREET	0	1 The Site Safety Manaer reported that a worker was setting up needle beams when a portion of screw jack fiell onto the worker when he band down. The struck worker complained of neck pain and left he site to visit is own doctor. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for a failure to ministina sife operations and a partial Stop Work Order (/FSWO) on the use of all needle beams. A Means and Methods and a Toolbox Talk must be provided. An additional ECB Violation will be issued for the installation of a pipe scaffold that was done contrary to the design plans.	ECB Violation	35327019M				Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
2018	Brooklyn	626	SHEEPSHEAD BAY ROAD	0	1 The Project Manager reported that a painter was on a ladder on the third floor when he misused the ladder and slipped off. The worker fell approximately six fee and hurt his shoulder. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NEPTUNE SOUTH COMMERCIAL LLC	
5/2018	Brooklyn	416	KENT AVENUE	0	2 A DOB inspector reported that approximately 50'-0" linear feet of sidewalk shed deck and parapet deck enclosure had blown off of a sidewalk shed and onto the street, ripuring two pedestrians. The two pedestrians were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that ereaded the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued on all crane and exterior operations, except for work to make safe the installation of a sidewalk shed.	ECB Violation	35322610R	051518CERSM05	NEW BUILDING	320622616-01-NB	Material Fell	420 KENT AVENUE LLC	ZDG, LLC
5/2018	Bronx	1017	HOME STREET	0	1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall ell, hit a generator, and then bounced off the generator and landed on the worker's leg. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that safety measures were not in place for baering wall installation. An ECB Violation and a DOB Violation were issued, as well as a parial Stop Work Order (FSWO) on all bearing wall installations. A Means and Methods and safety measures for bearing wall installations must be provided.	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
6/2018	Manhattan	44	UNION SQUARE EAST	0	1 A competent person at the site reported that a worker was removing a vertical shoring post when his finger go caught between the safety pin and the plate. The worker suffered a swollen finger and went to a hospital on his own.	No Dispatch					Other Construction Related Incidents	READING TAMMANY OWNER LLC	
2018	Manhattan	76	11 AVENUE	0	The Site Safety Manager reported that a foreman was hanging an eight inch steel pipe when he lost control of he pipe. The foreman was then knocked off of a ladder by the pipe. An ambulance was called. A DOB inspector responde and visited the site and reported that the anchor from which the pipe was to be hung from failed. An ECB Violation was issued for a failure to maintain safe operations.	ECB Violation	35331136N				Other Construction Related Incidents	76 ELEVENTH AVENUE PROPERTY OW	
6/2018	Queens	45-07	COURT SQUARE	0	1 The Site Safety Coordinator reported that a worker was using a four inch grinder when the grinder kicked back and cut the worker's left arm. The handle and grinder guard were in place. The worker was conscious and awake and went to Mount Sinai Hospital for treatment.	No Dispatch			NB	420902410	Mechanical Construction Equipment	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S



cident Date	Borough	Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/2018	Queens	2100	49 AVENUE	0	1 The Construction Superintendent reported that an	No Dispatch			ALT1	420656686	Worker Fell	2100 49TH AVENUE OWNER, LLC	ARCHSTONE BUILDERS LLC
					electrician was re-adjusting a ladder when he fell								
					approximately five feet off of the ladder. The worker complainted of back pain and was taken to Elmhurst								
					Hospital. The worker was alert and awake.								
2018	Queens	101	PENNSYLVANIA AVE	0	1 The Construction Superintendent reported that while	No Dispatch			NB	320622894	Other Construction Related Incidents		CAULDWELL WINGATE CO LLC
					working on a seven story new building, a project manage	r							
					picked up a sheet metal that cut his finger. The project								
					manager went to urgent care.								
/2018	Manhattan	112	EAST 11 STREET	0	1 The Site Safety Manager reported that a worker was	No. Action Measurers					Worker Fell	UD-DEV ASSOCIATES LLC	
/2018	Marinattan	112	EAST IT STREET	0	coming down a gang ladder when he slipped on the third	NO ACION NECESSARY					WORKER Pell	OD-DEV ASSOCIATES LLC	
					step of the ladder and fell three feet. The worker								
					complained of back pain. An ambulance was called. A								
					DOB inspector responded and visited the site and found no unsafe conditions present as of the time of inspection								
					No enforcement action was necessary.								
					,,								
/2018	Brooklyn	138	WILLOUGHBY STREET	0	2 A DOB inspector reported that a signalman had landed a	No Action Necessary			CN	773/17	Worker Fell	NYC HPD	Trident General Contracting, GC lend les
					banded load on the top deck with a tower crane. The								-
					rigging was released after the load was landed, and the								
					load shiftled and startled another worker that was carrying pieces of rebar. The worker tripped, fell, and								
					hurt his ankle. The worker was taken to a hospital for X-								
					rays. The signalman suffered a cut to his finger from the								
					banding after releasing the rigging and went to a City								
					M.D. for treatment. There were no witnesses to the worker falling. No enforcement action was necessary, as								
					it was determined that the signalman suffered a cut due								
					to a worker error.								
7/2018	Bronx	1903	WEST FARMS ROAD	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Material Fell	SAMARITAN-COMPASS V HOUSING DE	
					performing insulation work behind a stud wall when she								
					pushed a stack of sheetrock that was leaning against a								
					wall, which caused the boards to fall forward and hit her in the leg. An ambulance was called.								
					in the leg. An ambulance was called.								
3/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	ATLANTIC 2644, LLC	
0/2010	biookiyii	101	PENNOTEVANIA AVENOE	0	finger on a piece of sheet metal. The worker went to	NO Dispatch					Cirlei Construction Related incidents	ATEANTIC 2000, EEC	
					urgent care.								
3/2018	Brooklyn	422	FULTON STREET	0	1 A DOB inspector reported that a crane was making a	No Action Necessary	1		CN	80/17	Mechanical Construction Equipment	NOT ON FILE	FJM- Ferro Inc
					routine lift of a steel I-Beam from a trailer bed in the								
					street to the roof. The beam was rigged up and the								
					signal man gave the crane operator the signal to come up with the load. The crane had lifted the load								
					approximately two feet off of the bed of the trailer when								
					an iron worker attemped to steady the load to keep the I-								
					Beam from swaying. When the iron worker did this, he								
					had put his leg inbetween the moving load and a stationary beam on the flatbed truck. When he did this.								
					the worker created a pinch point, and the moving load								
					struck the worker's leg and caused a cut. The worker								
					was taken to a hospital with non-life threatening injuries.								
					The DOB inspector found no violating conditions during his inspection, as all of the workers at the site had the								
					appropriate 16 or 32 hour rigging certification cards, the								
					slings were found tagged and adequate, the lift director								
					had logs, and the signal man had his card. No								
					enforcement action was necessary.								
3/2018	Brooklyn	578	COZINE AVENUE	0	1 A DOB inspector repored that a worker was performing	ECB Violation	35322901R 35322902Z	051818CERRJ03 051818CERRJ04	Abatement		Worker Fell	NYBC REALTY LLC	GSC Services Corp
				Ŭ	asbestos abatement work on the roof when he fell								P P
					approximately twenty feet through the roof. The worker								
					was taken to Brookdale Hospital. The abatement work								
					was being performed as per the posted notice. Two Aggravated Level 2 ECB Violations for a failure to								
					safeguard were issued to the abatement company and								
					building owner. A partial Stop Work Order (PSWO) was								
					issued for all work at the roof level. The contractor at the								
					site is to provide a Means and Methods for the safe removal of material from the roof level.								
					removal or material norm tile tool level.								
8/2018	Brooklyn	6	METROTECH	0	1 A New York City Police Officer reported that a plumber	No Action Nococces			PLUMBING	321562288	Mechanical Construction Equipment	NEW YORK UNIVERSITY	VITO M. GIACHETTI
	Brooklyn	0	METROTEON	0	was working on a pipe on the fifth floor when the pipe	no Action Necessary			LOWDING	321302200	mechanical construction Equipment	ALW TORK ONVERSIT	ITO M. GROTE ITI
					burst and hit the plumber in the chest and chin. An								
					ambulance was called. A DOB inspector responded to								
					the incident and visited the site and determined that there was no enforcement action necessary, as the job								
					there was no enforcement action necessary, as the job had on-site active Department Of Buildings permits and								
					approved technical plans.								
8/2018	Manhattan	130	WILLIAM STREET	0	1 The Site Safety Manager reported that a ten feet long	ECB Violation	35331400N				Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	
					piece of rebar that was standing vertically and was to be								
					installed fell on a worker that was standing on the ground, hitting him in the side of his hard hat. The worke								
					went to a City M D. A DOB inspector responded and								
					went to a City M.D. A DOB inspector responded and visited the site and issued an ECB Violation for a failure								
					to maintain safe operations, as well as a partial Stop								
					Work Order (PSWO) for all concrete operations. The								
					General Contractor at the site is to provide a Means and Methods and a Tool Box Talk.								
					metrious and a Tool Box Talk.								



cident Date	Borough	Address Number	Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
21/2018	Bronx	2865	CRESTON AVENUE	0	1 The Site Safety Managor reported that a worker was putting up forms on a column when he fell about six to seven feet and injured his foot. The worker was sent to a hospital. A DOB inspector responded and visited the site and found that a hock that was holding form up was damaged, which may have possibly caused the worker tr fall. An ECB Violation for the failure to maintain safety operations was issued, as well as a partial Stop Work Order (PSWO) for all concrete work. Additional ECB Violations were also issued for infractions that were not related to the incident.		35327296K, 35327297M, 98, 99X,353184OOR, 01Z				Worker Fell	10 MINERVA PLACE HOUSING DEVEL	
1/2018	Bronx	4215	PARK AVENUE	0	1 The Site Safety Manager reported that a worker fell from the top of a hoist that was stopped on the first floor. The worker suffered minor injuries and was transported to a hospital by ambulance.	No Dispatch			NEW BUILDING	220157700-01-NB	Worker Fell	TREMONT RENAISSANCE HOUSING DE	JOY CONSTRUCTION CORP
21/2018	Manhattan	247	WEST 87 STREET	0	nospiral by amount of City Police Department reported that two workers were in the process of installing a supported scaffold when they sibped and full from three frames of pipe scaffold. The workers suffered scapes and bungs to their hands and legs and were taken to St. Luke's when the stand and legs and were taken to St. Luke's visited the site and issued two Aggravated Level 2 (2CS Violations. The first violation was issued for the removal or alteration of the supported scaffold by the General Contractor before the inspector's anival, which is the removal of equipment, structural material, or evidence that is related to an incident. The second violation was issued for a failure to promptly notify the Department Of Buildings of the incident, as the incident was reported by the NYPD.		36324011Y - 35324012X		NA		Worker Fell	KSB BROADWAY ASSOCIATES	Jerrick Aesociates Inc
21/2018	Queens	30-02	39 AVENUE	0	1 The Site Safety Manager reported that a worker was cutting a metal stud when he cut his hand. An	No Dispatch					Other Construction Related Incidents	30-02 ASSOCIATES LLC	
23/2018	Staten Island	149	PROVIDENCE STREET	0	ambulance was called. 1 The New York City Office Of Emergency Management reported that a worker tell from the structure. EMS transported the worker to a hospital. A DOB inspector responded to the incident and visited the site two EGB Violations for the failure to adeguard and for the failure to notify the Department Of Buildings of the incident. A full Sitey Work Order (FSWO) was also issued.	DOB Violation	35322904M/05Y	052318CERRJO1/02	ALT 1	520323212	Worker Fell	PERRI, ALFONSO	A. FONTANA & SONS LLC
3/2018	Manhattan	76	11 AVENUE	0	1 The Site Safety Manager reported that a worker was building the walk-out for a tower crane and was standing on the crane's lie-back beam when he slipped tfd the beam and fell. The worker was wearing fall protection equipment. The worker dir on tsuffer an injury, but was taken to a hospital for precautionary observation. A DOG inspector responded to the inicident and visited the site and reported that no enforcement action was necessary.						Worker Fell	76 ELEVENTH AVENUE PROPERTY OW	SBF Construction
3/2018	Manhattan	26	1 AVENUE	0	1 A New York City Police Officer reported that a worker fell approximately five stories or fifty feel from an ungurated section of pix scaffield. The worker was in critical condition and was taken to Bellervue Hospital. A DOB inspector responded to the incident and visited the site and reported that it could not be determined what causes the worker to fail, as the poople that the inspector interviewed claimed to have not seen or hrow about the incident. Four EOB Violations were issued for the failure to safeguard, for the presence of a supported scaffold that was not built according to code and was missing guardraits, missing toe boards, and was not fully decked for the absence of plans, drawings, and logs on site, and for the failure to provide a four hour supported scaffold user card upon request. A partial Stop Work Order (PSWO) was also issued.	a	35324057J, 35324058L, 35324059N, 35324060K		Alt	140761995	Worker Fell	DROBENKO NICHOLAS	Lime-Light Construction Co
4/2018	Brooklyn	2837	WEST 8 STREET	0	1 The Project Manager at the site reported that during the installation of concrete panel around a bulkhead, a pane cracks, fiel, and an anior can be workers in the site of the site of the site of the site of the the site on the investige site. A OB inspector responded to the incident and visited the site and reported that a Means and Methods was in place at the site, and that the workers were following the Means and Methods. The suction cup equipment was found to be in working condition. The inspector observed that the concrete panel may have broken because the concrete panel may have broken because the concrete panel may affective. No enforcement action was deemed necessary.						Material Fell	AISD CORP.	
24/2018	Brooklyn	41	BLUE SLIP	0	1 The Site Safety Manager reported that the driver of a concrete truck was washing out his truck when he hopped off of a ladder and turned his ankle. EMS was called and the worker was sent to a nearby hospital.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT F LLC	



Incident Date	Borough	Address Number	Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/24/2018	Brooklyn	420	EAST 21 STREET	0	Took Nation 2000 That Description apportant in the provided that an account of the provided provided that the participant of the provided provided the provided provided provided the provided provide	ECB Violation	35322725R, 354237262	052419CNEBC04, 05, 052418CNE01SC			Other Construction Related Incidents	HOSSAIN, GOLAM	
5/24/2018	Brooklyn	84	CARLTON AVENUE	0	 A competent person at the site reported that a worker was installing roof protection when the worker tripped on a piece of plywood and fell. The worker was sent to a 						Other Construction Related Incidents	NYC HOUSING AUTHORITY	
5/24/2018	Manhattan	233	WEST 125 STREET	0	hospital for a check up. 1 The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taken	No Dispatch			NEW BUILDING	121187447-01-NB	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
5/25/2018	Manhattan	24	2 AVENUE	0	to a hospital by EMS. 1 The Site Safety Manager reported that a worker cut his arm with a sheetrock knife while cutting sheetrock. The worker went to a nearby urgent care facility to receive medical attention.	No Dispatch					Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	
5/25/2018	Queens	28-07	JACKSON AVENUE	0	Insocial settinuit? A DDB inspector reported that there was a six man team that was dismantling support columns when one of the columns was released before one of the workers had a hold of the column. The column struck this worker to the ground. The worker was setting in Personal Protection Equipment (PPE) and was found alert and responsive. The worker did not suffer a serious injury, but was taken to a hospital by ambulance as a precaution. Documentation was provided to show that the worker attended a pre-job meeting and that the worker was up to date with daily pre-task hazard safety meetings that are designed to avoid such incidents. The inspector and that the incident occurred as the result of a worker error.	5			ALT 1 NB	420656873	Material Fell	LIC SITE B-1 OWNER, LL.C.	NEW LINE STRUCTURES & DEV
5/26/2018	Manhattan	217	WEST 57 STREET	1	0 A DOB Professional Engineer (PE) reported that at a sixty-seven story new building that was under to be rear on the limit floor of the building when an approximate 16 X 8.2.300 pound glass currain wall panel with a supporting steel "A-Frame toppeder and pinned the security guard underneath it. Several worksers lifted the "A-Frame and removed the pinned security guard. The security guard was taken to Mount Sinai Hospital, where he was later pronounced dead. A DOB inspector that was also at the site reported that the glass panel fell become power that the under the security guard. The security guard was taken to Mount Sinai Hospital, where he was later ponend was facing towards that was include that the vertical side of the "A- Frame that was supporting the panel was facing towards the walking area instead of lowards the concrete wall. No additional panel is of "A-Frame and was facing towards the walking area instead of lowards the concrete wall. No Safety Main panel is a black of the base Safety Main panel size at the base portmode a daily safety safety of (FSWO) was its used, as well as an Aggravated Level 2 ECB Violation for a failure to safeguard. A DOB Violation was also issued.		35322614Y	052618CERSM01	ALT 1 NB	121328205	Material Fell	SMITELL SPONSOR LLC	LEND LEASE (US) CONSTRUCT
5/26/2018	Brooklyn	101	PENNSYLVANIÄ AVENUE	0	2 The New Yok City Fire Department requested that a structural stability inspection please be performed because a construction fince head partially collopsed. A DOB inspector responded to the incident and visited the site and reported that there was approximately 100 feet of construction fince that was made of water-filled jersy barries and a low foor chain this fince that had failen pedestrians. The two pedestrians were not transported by EMS to recoive of r-file medical assistance. The barriers were found to have inadequate water levels. Two ECB Violations were issued for a failure to safeguard and for a delective job site fence. Two DOB Violations were also issued.		35323583P, 35323584R	052518CERFC02 , 03	ALT 1 NB	320622894	Material Fell	SPRINGER, JEAN E	CAULDWELL WINGATE CO LLC



ncident Date	Borough	Address Numb		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/29/2018	Bronx	220	EAST 178 STREET	0	1 The Site Safety Coordinator reported that while working on a twive story New Building that was at the Support of Excavation (SOC) stage, a hose from the fire hydant that was across the sidewal was being used when a female pedestrian tripped and fell over the hose. The pedestrian was found alert and awake and was taken to a nearby hospital by ambulance. A DOB inspector responded to the incident and visited the site and reported that the pedestrian aidewalk was clear of any obstructions as of the time of inspector. Twe EOE Violations for the presence of poor housekeeping and for the presence of tripping hazards. A hall Sixp Work Order (FSWO) was issued for the entire site.		36332113P 36332114R		New Building	220546620	Excavation/Soil Work	GRAND APTS HOUSING DEVELOPMENT	M. Melhick & Company Inc
29/2018	Manhattan	15	BRIDGE PARK DRIVE	0	1 The Site Safety Manager reported that a worker was unloading an air handler when he lacerated his middle finger on a sharp edge of the air handler. The worker went to a local clinic.	No Dispatch					Other Construction Related Incidents		
29/2018	Manhattan	151	MAIDEN LANE	0	The Site Safety Manager reported that workers were moving a retrigization unit when it toppled over onto one of the worksrs. The injured worksr was taken to a moving the safety of the safety of the safety of the visited the site and issued an ECB Violation for the latiture to maintain safe oparation, set well as a partial Stop Work Order (PSWO) on material handling on the ground level at the exposure. The General Contractor is to provide a Means and Methods.	ECB Violation	35335652H				Other Construction Related Incidents	151 MAIDEN LLC	
29/2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that a worker was on baker scaffold at the second floor when the worker fell from the scaffold. The worker set sound concicus, but compainted of pain in his shoulder and leg. The worker to the scaffold in the shoulder and leg. The worker to the incident and visited that site and issued one ECB Violation for a scaffold plafform that was not fully planted and for the presence of plants that were not tied down. A partial Stop Work Order (PSWO) for the use of a supported scaffold was also issued.		35323972Z - 35323973K		NB	402898959	Worker Fell	DEPARTMENT OF EDUCATION	Leon D. Demattels Construction
29/2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that an electrician tripped while walking and suffered an injury to his rlbs. The worker went to urgent care.	No Dispatch					Worker Fell	DEPARTMENT OF EDUCATION	
0/2018	Brooklyn	2550	3 AVENUE	0	The Site Safety Coordinator reported that a worke's foot came into contact with a piece of pipe that was in a pile of garbage that was to be picked up. The worker suffered a foot laceration and was sent to a hospital.						Other Construction Related Incidents		
81/2018	Brooklyn	107	COLUMBIA HEIGHTS	0	1 The Site Safety Coordinator reported that four workers were carrying heavy mechanical equipment down the stairs when equipment field on one of the workers. The worker was sent to a hospital for a check up, A DOB inspector responded to the inicident and visited the site and issued an ECB Violation for the failure to maintain safe operations and a partial SIDV Work Order (PSWO) on the handling of heavy material. The General Contractor is to provide a Means and Methods.	ECB Violation	35326853N				Other Construction Related Incidents	CLIPPER 107 CH LLC	
1/2018	Manhattan	360	EAST 89 STREET	0	1 A DOB inspector reported that a worker was sorting and moving glass window panels when one of the panels shifted and hit the worker in the leg. The worker was taken to a hospital by ambulance for evaluation. An ECG Violation and a partial Stop Work Order (PSWO) was issued for the failure to maintain safety messures, as the worker was injured due to improve material handling. The General Contractor is to provide a Means and Methods for safe material handling in order to prevent future incidents.		35318415J		NEW BUILDING	121186242	Material Fell	1711 LLC	RYDER CONSTRUCTION INC
1/2018	Queens	51-35	REEDER STREET	0	1 The Construction Superintendent reported that a worker strained his back while lifting a crate onto a dolly. An ambulance was called and the worker was transported to a hospital.	No Dispatch			NEW BUILDING	420812446-01-NB	Worker Fell	85-15 QUEENS BLVD. REALTY, LLC	STRUCTURAL LAND MANAGEMEN
1/2018	Queens	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker cut his finger while using a box cutter. The worker went to a clinic.	No Dispatch					Other Construction Related Incidents		
2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that two workers were loading glass panels that were approximately 5 X 3 onto a cart when the glass care into contact with a metal part of the cart, which caused the glass to break into pieces. One of the workers suffered a minor laceration to his left hand. The injured worker went to a City M.D.						Other Construction Related Incidents	20 TSQ GROUNDCO LLC	
2018	Manhatlan	49	CHAMBERS STREET	0	1 The Site Salety Manager reported that a worker was trying to move a doily that was carrying a machine motor for an exterior elevator up the ramp of the loading dock when he lost his balance and the machine motor typed work; causing the worker to fail tace down. The worker suffered cuts and bruises to the face and was taken to a hospital for treatment. A DOB supector responded to the incident and visited the site and assued an ECB Violation and a partial Stop Work Order (FWVO) to stop all deliveries and material handling. The General Contractor at the site is to provide a Means and Methods for sale operation.		35335925Y		ALTERATION 1	121186821	Material Fell	49-51 CHAMBERS LLC	NY DEVELOPERS & MANAGEMEN



cident Date	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/2018	Brooklyn	18	SPENCER STREET	0	1 The Site Safety Manager reported that a worker was working on a twelve story new building and suffered a cu to his arm while carrying 2 X 4's and sharp edge metal track material. The worker went to a nearby doctor for treatment and received a few stitches.	No Dispatch					Other Construction Related Incidents	LL 18 SPENCER HOLDINGS LLC	
/2018	Manhattan	10	VANDERBUILT AVE	0	1 The Site Safety Manager reported that an iron worker was climbing down the stairs when he slipped and fell about three feet. The worker complained of a sprained back. An ambulance was called.	No Dispatch					Worker Fell		
/2018	Manhattan	108	LEONARD STREET	0	1 The Site Safety Managor reported that a staentifier was working on a science iff and was installing opinikal system anchors between pipes that were installed by other glumbers. One of the anchors failed and a pipe fail and landed on one of the steamtitter's hands, taking at of his hand of LA DOB inspector responded to the incident and visited the site and issued a DOB Violation and a partial Site Work Order (PSWQ) on all overhead installations. The General Contractor is to provide a Means and Methods and a Tool Box Talk.		35327073N				Material Fell	CIVIC CENTER COMMUNITY GROUP B	
4/2018	Marihattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was stropping concrete form work on the first floor when he sipped and fiell approximately four feet from the platform The worker was found conscious and without a visible injury, but was taken to a hospital for a check w.p. A DOE inspector responded to the incident and visited the site and reported that the worker was not using any type of fall arrest system, that the working area was not illuminated with lights, and that here was water on the floor that created a slipping hazard. Three ECB Violations and a Juli SbQ Work Order (FSWO) were issued. The General Contractor at the site is to provide a Means and Methods for the safe operation of the job.		36327077K, 78M, 79Y		NEW BUILDING	121187447	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
2018	Brooklyn	4813	9 AVENUE	0	1 The Construction Superintendent reported that a worker was unloading a metal track when the track slid and cut his thumb. The worker went to urgent care for treatment.	No Dispatch					Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
/2018	Manhattan	241	WEST 62 STREET	o	1 The Project Manager at the site reported that a worker was carrying a 2 X 4 when he accidentally dropped the 2 X 4 onto the foot of another worker. The injured worker was sent to a hospital for a check up and returned to the site afterwards.						Other Construction Related Incidents	NYC HOUSING AUTHORITY	
/2018	Manhattan	500	WEST 33 STREET	0	1 The Site Safety Manager reported that an electrician was moving his equipment when he hurt his back. An ambulance was called.	s No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker twisted his left ankle while installing rebar. The worker went to a clinic and then returned to the site.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
/2018	Manhattan	1059	3 AVENUE	0	1 The Site Safety Manager reported that during the construction of a thirty story new building, a worker waiked into the corner of a steel -Beam and hurt his right foot. The worker continued to work, but the Site story and the steel of the steel of the steel of the steel and the worker were still in pain. The worker was taken to Cornell Hospital for treatment.	No Dispatch					Other Construction Related Incidents	63RD & 3RD NYC LLC	
/2018	Manhattan	110	UNIVERSITY PLACE	0	 The Site Safety Manager reported that a plumber was installing a pipe when a piece of debris fell into his eyes. The plumber went to a doctor. 	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/2018	Manhattan	455	5 AVENUE	0	1 A Project Manager at the site reported that during the installation of floor opening protection, a worker lost control of a plank that hit him in the nose. The worker walked to a clinic.	No Dispatch					Other Construction Related Incidents	NEW YORK PUBLIC LIBRARY	
/2018	Staten Island	35 a	BAY STREET	0	 The Site Safety Manager reported that a worker hurt his arm while removing formwork. The injured worker walker to urgent care. 	No Dispatch			NEW BUILDING	520138379-01-NB	Other Construction Related Incidents		HOLLISTER CONSTRUCTION SE
/2018	Manhattan	209	EAST 19 STREET	0		No Dispatch			NB	121958480	Other Construction Related Incidents	VISUAL ARTS HOLDING CORP	GRAMERCY SQUARE LLC
7/2018	Manhattan	15	EAST 30 STREET	0	1 The Site Safety Manager reported that a worker fell dow from the first floor supporting deck to the ground and suffered a very bad head injury. The worker was found conscious and was taken to a hospital by ambulance. The worker was exported to be in stable condition. A DOB inspector responded to the incident and visited the site and reported that the worker was waiking along the re-shores and may have possibly fainted or tripped and thit his head on one of the re-shores. No enforcement action was deemed necessary, as the inspector did not observe any hazardous conditions during the time of inspection.						Worker Fell	MADISON 30 31 OWNER LLC	



ncident Date		Address Number		Fatalities Injuries EOC Final Description			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/7/2018	Manhattan	122	EAST 23 STREET	0 1 Å DOB Inspector reporte cellar løvel was on a tveh electrical work on the ceil six to seven feet. The wor and was taken to a nearb was issued for a failure to Order (FSWO) was also i	ing when he fell approximately ker was not wearing a harness y hospital. An ECB Violation safeguard. A partial Stop Work ssued for all work at cellar s. A Means and Methods and	B Violation	3532074P		NB	121190157	Worker Fell	NOT ON FILE	CM AND ASSOCIATES CONSTRU
/7/2018	Manhattan	111	LEROY STREET	0 1 The Site Safety Coordinat injured his middle finger w worker was sent to urgent	hile using a pallet-jack. The	Dispatch					Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
7/2018	Brooklyn	4813	9 AVENUE	was carrying a few metal	d tieback and twisted his knee.	Dispatch					Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
7/2018	Brooklyn	123	LINDEN BOULEVARD	0 1 The Site Safety Manager arm while moving formwo to a hospital by another w	reported that a worker hurt his No rk. The worker was transported	Dispatch			NEW BUILDING	321228603-01-NB	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS LLC
5/8/2018	Manhattan	60	GREENE STREET	0 1 A DOB inspector reported was leaving the bathroom temporary aluminum stair place and secured. The s worker fell to the baseme suffered possible injunes teatment in the emergence EGB Violations were insu- there here no colars on s	the according to the first floor ECI when he waiked toward a system that he hough was in airway collapsed and the table bow. The worker received yourser. The worker received yourser the worker received yourser the worker received yourse and an adeguard, for the site to pick up his tools, a dro a failure to a safeguard, tor parts available for a Stop Work Order (FSWO)	B Violation	35314346r 35314347z		AL	123172217	Worker Fell	NOT ON FILE	SHAWNMUT WOODWORKING & SUP
/8/2018	Manhattan	767	5 AVENUE	doing waterproofing work When the worker was wal metal object that was on t	reported that a worker was No in a tree pit on the plaza area. king away, he walked into a he wall. The worker went to a s own and will be reporting	Dispatch			ALTERATION 1	122970721	Other Construction Related Incidents		TURNER CONSTRUCTION COMPA
9/2018	Brooklyn	242	EAST 45 STREET	on the eave and gutters o when the workers fell app the workers sustained inju- worker sustained a head i condition. Both workers w County Hospital by ambul	ere transported to Kings ance. An ECB Violation, a Stop Work Order (FSWO) were	B Violation	35322879R	060918CERMR05			Worker Fell	PRINCE, LINCOLN	
/9/2018	Manhattan	200	EAST 50 STREET	fourteenth floor with their were working on a panel the upper half of the pane half of the board remaines Both workers were leater both workers were leater both workers were leater both workers were later both workers were later Conter (FSWO) was also in Order (FSWO) was also in	that there were two ECG king in the utility room on the forman onsite. The workers board when they de-energized I board. However, the lower J live and was not insulated. cuted and suffered burns, and a hospital. Two Aggravated es issued: one othe General L'Excittad Subcontractor, for a ssued. Two other ECB infractions not related to the	B Violation	35335966K, 35335967M		NEW BUILDING	121192912	Other Construction Related Incidents	MIPA 59/THIRD OWNER LLC	GILBANE RESIDENTIAL CONST
/11/2018	Manhattan	45	BROAD STREET	pin that was to be used to when another worker hit h struck worker was taken to later released with a bruis was issued for a failure to Order (PSWO) was issue	that a worker was holding a ECI set the auger on a drill rig is finger with a hammer. The o a nearby hospital and was ed finger. An ECB Violation safeguard. A partial Stop Work d on all use of the auger. The rowide a Means and Methods an auger.	B Violation	36332161J		NB	121190772	Excavation/Soil Work	MADISON 45 BROAD DEVELOPMENT L	pizzarotti LLC
6/11/2018	Manhattan	138	EAST 38 STREET	was cutting a tie wire with	reported that an iron worker No a utility knife when the knife d cut his forearm. The worker ital by ambulance for	Dispatch			NB	121186028	Other Construction Related Incidents	TATHAM HOUSE,	TISHMAN CONSTRUCTION CORP
6/11/2018	Brocklyn	41	BLUE SLIP	0 1 A DOB inspector reported process of climbing down missed a thread at three f floor. The worker complair taken to a hospital for eve defects to the ladder or th	an eight foot ladder when he	Action Necessary			Alt 1	320597449-01-NB	Worker Fell	BOP GREENPOINT F LLC	T.G. NICKEL & ASSOCIATES
/11/2018	Bronx	988	EAST 180 STREET	cutting water proofing with	a sheetrock knife when he The worker was taken to	Dispatch			NB	220152233	Other Construction Related Incidents	988 EAST 180 STREET HOUSING DE	MONADNOCK CONSTRUCTION IN



cident Date	Borough	Address Number	Street	Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
12/2018	Manhattan	300	LAFAYETTE STREET	0	The Construction Superintendent reported that there were four workers that were monig a crite of glass on a doly when the doly topped and caused the crate of glass to side and hit one of the workers in the chest. The struck worker fell to the floor and suffered a back injury. An ambulance was called. A Dol Inspector responded to the incident and visited the site and reported that the glass was being moved on a makeshift dolly wan to available. An ECB Violation was issued A Tot the failure to maintain safe operations, as well as a partial Stop Work Order (PSWO) for material handing A design d awing with load capacity for the makeshift dolly wust be provided.		35335891L				Other Construction Related Incidents	LVC 298, LLC	
12/2018	Queens	28-30	JACKSON AVENUE	0	1 A DOB inspector reported that an electrician was working on a PVC punction box in the floor with glue. The box had live electrical wires, and the wires got touched as the electrician tired to push them down into the box, which created a spark that set the glue on fire. The electrician suffered a second degree burn and was taken to a hospital, where he was reported to be in stable condition. An Aggravated Level 2 ECB Violation was issued for the failure to maintain safety measures while working on live electrical wires. A partial 50p Work Order (PSWO) was also issued to stop all electrical work.				NEW BUILDING	420652886	Other Construction Related Incidents	LIC DEVELOPMENT OWNER, L.P.	HUDSON MERIDIAN CONSTRUCT
3/2018	Manhattan	15	EAST 57 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder to cut steel when he lost control of the grinder, which caused a small laceration to his foreman. The worker went to a local hospital.	No Dispatch					Other Construction Related Incidents	15 EAST 57TH ST.ASSOC.	
3/2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a carpenter was cutting sheetrock with a utility knife when he accidentally cut his forearm. The worker's foreman took him to a City M.D. for treatment. The worker is expected to return to work	No Dispatch			ALTERATION 1	121324343	Other Construction Related Incidents	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
13/2018	Queens	42.20	27 STREET	0	The Site Safety Managor reported that a worker was lifting up the performs of a supported scafed with a pulley when the worker burned his hands on the rope and dropped the pipe frames of a supported scafed. The worker was taken to a nearby hospital by a foreman for treatment. A DOB inspector responded to the incident and visited the site and reported that the details of how the incident Courder were not known. Two ECB Violatons were issued for the failure to perform a supported scaffold installition in a safe manner and for thermal Site Work Over (PSWO) for the installation of aupported scaffolds was also issued.		35324229R - 35324230Y		SF	Q0004061341-SF	Material Feil	CRESCENT & 27 LLC	Classic Consulting Group
3/2018	Staten Island	2589	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a water pipe was damaged by a worker on the second floor, which caused a flood on the first floor. Nee of the store workers at the address slipped and fell. An ambulance was called. A DOB inspector responded to the incident and visited the site and determined that there was no enforcement action necessary, as the work that was being performed was approved under a DOB issued permit.	No Action Necessary			SPRINKLER	540138929	Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	PATRICK BOWE
4/2018	Manhattan	532	WEST 33 STREET	0	1 The Site Safety Manager reported that a roof worker complained of pain in the left side of his chest while lifting waterproofing materials. The worker was alert and awake and was taken to Bellevue Hospital by ambulance for treatment.	No Dispatch			NB	121191183	Other Construction Related Incidents	NOT ON FILE	TISHMAN CONSTRUCTION CORP
4/2018	Brooklyn	210	CLASSON AVENUE	0	A DOB inspector reported that during a stripping operation that was taking place between the elevator shaft and north stainvell on the fifth floor, an 'ULMA' formwork beam that was approximately sixteen feet long struck a worker in the head while the worker was attempting to remove the beam. The worker was transported to a hospital, where it was reported that he had suffered a concusion. The worker was set and failure to maintain safe operations. A partial Stop Work Order (PSWU) was also issued on all concrete work. The General Contractor is to provide a Means and Methods for safe operations.	ECB Violation	35336020Y				Other Construction Related Incidents	PRATT INSTITUTE	
4/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was walking down from the second floor when he missed his step and fell down. The worker hurt his knee and went to a City MD.						Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
4/2018	Bronx	600	BERGEN AVENUE	0	1 The Site Safety Manager reported that a worker was carrying a piece of lumber that was 4 X 10 X 7 when the worker sitpped, which caused the lumber to fall onto another worker's hand. The injured worker went to a City M.D.						Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	
14/2018	Bronx	600	BERGEN AVENUE	0	1 The Site Safety Manager reported that a worker hit his foot while unloading a beam. The worker's foreman took him to a first med	No Dispatch			NEW BUILDING	220151868-01-NB	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP



ncident Date	Borough	Address Number	Street Fatali	ties Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
rcident Date	Borough Bronx	Address Number 1812	Street Fatali	Injuries EOC Final Description 0 1 A DOB inspector reported that a worker was taking the delivery of a Concrete Masonry Unit (CMU) block that was being delivered by a lull when his finger opt caugi- between patiets and one of his fingerips separated. Th worker's forman took him to a hospital for treatment. ECB Violation was issued for the failure to maintain safety measures. A partial Stop Work Order (FSWO) was issued on all material handling, including deliverie A second partial Stop Work Order (FSWO) was issued for the use of scaffolds in which the horizontal netting was not at the required height. The General Contraction is to provide a Means and Methods and a worker's orientation before the first too work order with the orient of the second partice Stop work of the second partice	ECB Violation t te e An S.	EGB Violation Numbers 35316423J	20B Violation Numbers	Permit NEW BUILDING	Permit No 220152851	Incident Type Other Construction Related Incidents	Owner's Name VIA VYSE PARTNERSHIP HOUSING D	Contractor Name HLS BUILDERS CORP
/18/2018	Brooklyn	15	WASHINGTON AVENUE	be rescinded. 1 The Site Safety Manager reported that during the final pressure testing inspection of a standpipe, the regulate the air out of the standpipe, which caused another worker to hit a wall. He worker complianed of a back ache and an ambulance was called. A DOB inspector responded to the incident and visited the site, and reported that no enforcement action was deemed necessary, as the incident occurred as the result of a worker error.	No Action Necessary					Other Construction Related Incidents	NYC DSBS	
/18/2018	Manhattan	110	UNIVERSITY PLACE	0 1 The Site Safety Manager reported that an electrician w using a sheet cock krile to ty to ut a conduit when he sloed his left index finger. The worker was escorted to the emergency room at Beth Israel Hospital with anoth co-worker to receive treatment.						Other Construction Related Incidents	NOT ON FILE	
/19/2018	Brooklyn	276	KENT AVENUE	A DOB inspector reported that a worker was forming a finited floor deck when a retractable lanyard device for a safety harmess was lift on loose physicol. The deck was on the loose physicol and the safety of the safety of the on the loose physicol causing the loose physicol to sit As a result of this, the retractable lanyard device felt to the second floor and hit another worker in the back. Th worker was in a conscious state and was transported to a hospital with no visible injuries. An ECB Violation was issued for the failure to safeguard persons and proper- y and for working on two levels simultaneously without a controlled access zone in place. A partial Stop Whot Order (FSWO) was also issued to stop all forming operations. The General Contractor is to provide a Means and Methods and a worker orientation for safe operation.	ns Id p. e o s	35327169H		NEW BUILDING.	320916407	Material Fol	DOMINO A LLC	260 KENT CONSTRUCTION LLC
19/2018	Brooklyn	306	NORTH HENRY STREET	0 1 A DOB inspector reported that a contractor had overloaded pist girders that expanded right girls fee with eight bundles of corrugated steel decking that we herently feet. The decking was placed in a concentrated area on the pist girders. However, the pist girders we not properly installed, as they were only temporarily installed steel. The decking was used to be a steel of the form of the pist girders was an explored by the pist girders was not properly installed. So they were only temporarily installed steel of the document of the the order of the forty feet to the ground. EMS was called and the work was found alert and responsive when EMS arrived. The worker suffered a broken shoulder and possible back rightines and was taken to a nearby hospital. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard, as well as a full Stop Work Order (FSWO).	e e r	35336227L		EW-OT	340499060	Worker Fell	300 NORTH HENRY LLC	R, KING WINDOW CORP
/19/2018	Manhattan	1681	3 AVENUE	0 1 The Site Safety Manager reported that a worker was removing a kitchen cabinet when he was hit in the hea by the cabinet when in becarne loose. The worker suffered a cut to his face. The worker went to a City M. to receive treatment and will return to work.	d D.			NEW BUILDING	121191913	Material Fell	95TH AND THIRD LLC	GILBANE RESIDENTIAL CONST
/19/2018	Queens	36-18	MAIN STREET	0 1 The Site Safety Manager reported that an elevator company worker was putting down counter weights wh his finger got pinched between the weights. The worke went to a City M.D.	en					Other Construction Related Incidents	134-22 35TH AVE., LLC	
/19/2018	Queens	37-09	COLLEGE POINT BOULEVARD	0 1 A DOB inspector reported that a worker was installing quardrails on the perimeter of the job site when he was asked to help install Q-decking at the second floor. When the worker went to get a torch to help tim the deck, the worker stepped on a loose sheet of decking and fel approximately filteen to hever the the two- suffered injuries to this ankles, knees, and head. The suffered injuries to this ankles, knees, and head. The Hospital by ambulance. An EGD Workleon was itsued a failure to safeguard, as well as a partial Stop Work Order (FSWQ) on building two on all setel eraction and deck layout. A site specific Means and Methods for the prevention of further decking accidents must be provided. A Tool Box Talk and an adequare ite off procedure for controlled deck zones must also be provided.	r g or	ECB#35327475X		NB	420653607	Worker Fell	NOT ON FILE	TOP 8 CONSTRUCTION CORP



ncident Date	Borough	Address Numbe	r Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/20/2018	Manhattan	328	EAST 62 STREET	0	A DOB inspector reported that there were workers that were geiting ready to cot out and remove a raker section that was connected to the Support Of Excussion (SOE) waler and portuniting through the foundation valls. The Construction Superintendent at the site stated that the section needed to be removed for the completion of a waterproofing installation. During the process of preparing jacktammers to chip out the concrete around the raker pit, a worker slipped and fell approximately four feel into the raker pit, landing on the back. The worker got out of the raker pit and walked to a hospital with a converter. The worker received treatment and was reported to be dwy. An EGB Violation was issued because there were guard rails missing. An additional EGB Violation was issued for the failure to provide a Means and Methods for the removal of S.O.E. sections. A partial Stop Viork. Order (PSWO) was issued on the removal of S.O.E. sections.	ECB Violation	35332281Y-35332282X		NB	121189846	Worker Fell	YYY 62ND STREET LLC	Joy Construction corp
6/20/2018	Manhattan	300	LAFAYETTE STREET	0	1 A DOB inspector reported that there were electricians moving spools down a flight of stairs when they lost control of one of the spools, which hit one of the workers ambulance. An ECS Visitions was itseed for a failure to maintain safe operations. A partial Stop Work Order (PSWQ) was also issued for all heavy material handling. A Means and Methods must be provided.	ECB Violation	35331146R				Other Construction Related Incidents	LVC 298, LLC	
5/20/2018	Manhatlan	25	SUTTON PLACE SOUTH	0	1 A DOB inspector reported that a worker was attempting to lower a chipping gun from a root to a setback to chipping gun approximately twenty first, hitting the other worker on his hard hat. The struck worker was admited into Correll Medical Center, where he received stitches. This incident occurred on June 19, 2016, but was not reported until wave 20, 2018. Twe EOB violations were lissued; an Aggravated Level 2 violation for the failure to indify all persons and property and a second violation for the failure to immediately rootly the Department O issued. A partial Stopy Woh Order was issued for the lowering of any tools or equipment from a root to a seeback without a DOB approved Means and Methods.	ECB Violation	35322737Y 35333276Y	062018CNESC01 062018CNEGS01	ALTERATION TYPE 2	122907426-01-EW-OT	Other Construction Related Incidents	CANNON POINT NORTH INC	DNA CONTRACTING LLC
6/20/2018	Manhattan	1558	3 AVENUE	0	1 The Site Safety Manager reported that a garbage truck was passing by when it hit a barrier that hit a worker. The worker complained of back pain and walked to urgent	No Dispatch					Other Construction Related Incidents	180 EAST 88TH STREET REALTY LL	
5/20/2018	Manhattan	1227	BROADWAY	0	care. 1 The Site Safety Manager reported that a worker was cleaning and moving materials when he moved a job site box that was next to two hollow sele doors. The two follow steel doors fell and hit the worker's shoulders, causing him to fall. An ambulance took the worker to a hospital for a check up.						Other Construction Related Incidents	YJL BROADWAY HOTEL LLC	
5/21/2018	Brooklyn	583	LORIMER STREET	0	1 A DOB inspector reported that a worker injured his finger while using a drill during steel erection/modification work because the drill was used contrary to the manufacturer's specifications. The injured worker was sent to a hospital, where he received stitches. This incident occurred on June 21, 2018, but was not reported unil June 22, 2018. Four EGS Violations were issued. These violations include a violation for a failure to maintain aside operations, a violation for the non-site modification of steel, a violation for the on-site modification of steel, a violation for the on-site modification of steel, a violation for the on-site modification of steel, a violation for the set of a drill contrary to the manufacturer's specifications, and a violation for the failure to notify the Department Of Buildings of the modent in a timely manner.	ECB Violation	36331149M, 1450L,1451N, 1452P				Other Construction Related Incidents	583 LORIMER LLC	
6/21/2018	Brooklyn	77	CLARKSON AVENUE	0	1 A DOB inspector reported that a worker was working on a platiom deck when he fell approximately six feet to the lower level. The worker was found conscious and alert and was taken to a nearly hospital. An Aggravated Level 2 ECB Violation was issued of the failure to safeguard. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued or all of the work being conducted at the fifth floor.		35309269X	062118CNERWS01	Alt - 1NB	321197771	Worker Fell	CLARKSON BU LLC	DAWNY CONSTRUCTION LTD
5/21/2018	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that an iron worker was working inside an elevator shaft on a man basket when an object fall from above and struck and cut the worker's arm. An ambulance transported the worker to a hospital for transment. A DOB inspector responded to the incident and visited the site and reported that design drawings for working platforms were provided, a certification for the usage of a scaffold was provided, and lighting was being put in place during the time of inspection. However, an ECB Violation was issued for the failure to notify the DOB Scaffold Safety Team for the presence of a suspended scaffold on theirs. A partial Stop Wiok Chore (FSWO) was issued for all work in an elevator shaft. A Means and Methods for all safe operations in a shaft must be provided.		35331147Z	062118BS04SA01			Matorial Fell	CBP 441 NINTH AVENUE OWNER, LL	
							Page 31 of 52						



					DOB Action		DOB Violation Numbers		Permit No			
incident Date 5/21/2018	Borougn Manhattan	Address Number 45	Street BROAD STREET	Fatalities Injuries EOC Final Description 0 1 A DOB inspectre reported that contractors were transporting material with an excavator when the kin of the machine struck the Concrete Masony Unit. Of the machine is truck the Concrete Masony Unit. Of the machine is truck the Concrete Masony Unit. Of the machine is the struck the Concrete Masony Unit. Customer that was eating funch inside of the result. The financial contract disloged a small section of concrete block that structure customer suffered an injury to his left is and with an excerning the machine to the Work To Protection Hospital by an ambulance. There were no structural concorners four publicity is regimer will provide a Masma and Muthor repairs. An Aggrevated Level 2 ECB Volation was issued for failure to safeguard. A Uli Stop Work O (FSWO) was issued for the entire site.	ECB Violation MU) ck a ant. as i. gged Is for	ECR Violation Numbers 35332283n	UUB Violation Numbers	Permit FO	121190772	Incident Type Material Feil	Owner's Name MADISON 45 BROAD DEVELOPMENT L	Contractor Name Przzaroti LLC
5/22/2018	Manhattan	15	EAST 30 STREET	The Site Safety Manager reported that a worker drop a coupling on his foot during a rebar installation. Th worker suffered a swelled foot and went to urgent ca with a co-worker.						Material Fell	MADISON 30 31 OWNER LLC	
6/22/2018	Manhattan	315	EAST 46 STREET	1 The Site Safety Manager reported that a worker ben down to plug in an extension cord and hit his head o stored piece of rebar. The worker went to urgent car	na					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
6/23/2018	Manhattan	100	CHURCH STREET	0 1 A DOB inspector reported that at a instense story building that was having alteration work performed there were workers installing and walding sever pp the eight floor utility shatt using a "Jewel Clamp" this out of the hands of one of the workers and fell through the staff. The clamp bounced on the third floor and landed in the cellsr, where it han other worker on to hand. The injured worker aufferted cuts and bruises has arm, bud for to suffer a bound how. The injure entry of the staff. The clamp bounced on the third floor and landed in the cellsr, where it has not how. The injure entry of the staff. The clamp bounced on the third floor and landed in the vell voidation for a failure to maintain safety measures, a second violation for working on levels simultaneously without protection or a Comto Access Zone (CA2) in place, a third violation for the without a permit and fourth violation for the staff (FSWO) was used as well. The General Contractor the state is to obtain a permit and provide a Means a Methods and a voinser orientation for sale openation the state before the Stop Work Order will be rescinde the state before the Stop Work Order will be rescinde	n R, s on ed ph on d d wo o be o f d d n a t	35327483X, 84H, 85J, 86L				Material Fell	100 CHURCH FEE OWNER LLC	R&S CONST. CONTRACT. INC
6/23/2018	Queens	5	COURT SQUARE	1 The Site Safety Coordinator reported that a constructive worker tripped and sustained a minor knee injury. El was called and the worker was transported to a local hospital.	//S			NB - NEW BUILDING	420902410	Worker Fell	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
6/25/2018	Manhattan	505	WEST 43 STREET	0 The Site Safety Manager reported that a worker wat latanding on an "X-F arean ladder while performing a value surface when the ladder support, causing the we to fail. The worker was found unconscious. An ambulance was called and the worker was transpor- a hospital in a conscious state. A DOB inspector responded to the individent and visited the site and is an ECB Violation for the failure to maintain safety measures. A partial Sibp Work fordor was its used to provide a Means and Methods for safe operation.	rte rrker ed to sued all	35300588M		NEW BUILDING	121187456	Worker Fell	NOT ON FILE	NEW LINE STRUCTURES & DEV
5/25/2018	Manhattan	149	EAST 125 STREET	0 2 A DOB inspector reported that a Jekko crane machino the on the fourth floor was in the process of placing a considered of the fourth floor was in the process of placing a considered of the floor. The worker fail floor was struck by crane components a suffered a micro floor was struck by crane components a suffered a micro barrier to the stress suffered a micro barrier to barrier to the stress suffered a micro barrier to barrier to the stress suffered a micro barrier to barrier to barrier to barrier to the stress suffered a micro barrier to barr	ntain m and as d ed ed b b b b b b b b b b b b b b b b			NEW BUILDING	121102388	Mechanical Construction Equipment	NOT ON FILE	ZDG, LLC



cident Date	Borough	Address Number	Street	Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Brooklyn	420	ALBEE SQUARE	0	1 The Site Safety Manager reported that the Construction Superintendent was moving material on a pallet jack by himself when he hit a divet. The Construction Superintendent tried to stop the piece of material that was being moved from falling, but the material fell on his ankle. An ambulance was called.						Other Construction Related Incidents	JEMB ALBEE SQUARE LLC	
25/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was picking up a garbage bag when he backed into stacked rebars and suffered a scratch to his right calf. The worke walked to a City M.D.						Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
25/2018	Bronx	2028	CRESTON AVENUE	0	1 The Site Safety Manager reported that a worker pulled his back while using a pallet jack. The worker complained of a back ache. An ambulance was called.	No Dispatch					Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	
6/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was fueling a generator when fuel was spilled on his arm. The worker walked to a City M.D. as a precaution.	No Dispatch			NEW BUILDING	321197478-01-NB	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
26/2018	Manhattan	1	BEEKMAN STREET	0	1 The Site Safety Manager reported that the diamond plate im a brott car wan not accurate and that the diamond plate foil over and hit the enkled of a worker that was in the host. An ambulance ware called. A DOB impector responded to the incident and visited the site and issued an ECB Violation for the failure to institute safety measures for the diamond plate in the host. A DOB Violation was also issued. As of the time of inspector, the diamond plate was made secure.		353427512	062618BS01KR01			Other Construction Related Incidents	ONE BEEKMAN OWNER, LLC	
//2018	Manhattan	1	WEST END AVENUE	0	1 A DDB inspector reported that workers were in the process of diamanting a fourteen toot high idewalk shad when one of the workers elit back between the junic beams. The worker was experiencing minor back pain and was taken to a local hospital by ambudance. An per state of the state of the state of the state of the process of the state of the state of the state of the process of the state of the state of the state of the process of the state of the state of the state of the process of the state of the state of the state of the process of the state of the state of the state of the process of the state of the state of the state of the process of the state of	ECB Violation	35324259H		Shed	M00023179	Worker Fell	NOT ON FILE	Colgate Enterprises Corp
/2018	Manhattan	400	WEST 61 STREET	0	1 The Site Safety Manager reported that a worker was carrying material down a flight of stairs when he missed the last step. The worker suffered a shoulder injury and was taken to a hospital by ambulance.	No Dispatch					Worker Fell	RCB1 NOMINEE LLC	
/2018	Manhattan	61	9 AVENUE	0	1 The Site Safety Manager reported that a worker was doing sheet metal work with a screw gun when he accidentally drilled a screw into his right hand. The worker was transported to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	G.D.C.L. HOLDINGS LLC	
/2018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker was going on a break when he opened a box and the lid of the box fell on his hand, causing a laceration to his middle finger. The worker went to a hospital for a check up.	No Dispatch					Other Construction Related Incidents	NYC DSBS	
19/2018	Brooklyn	856	WASHINGTON AVENUE	0	¹ The Site Safety Manager reported that a section of sidewalk cived due to a rain storm that occurred on June 28, 2018. A pedestrian stepped into the caved in section of sidewalk and hurt her ankle, knee, and shoulder. An antokunce was called and the pedestrian was taken to a heaptal by ambulance. A DOB inspector responded to the indent and whiled the site and reported that there were cracks along the section of sidewalk that caved in during the rain storm, which may have contributed to the cave in. The area was being back filled while the inspector was on site. An ECB Volation was issued for a failue to maintain the sidewalk	ECB Violation	35335899J	062918BS08PK01			Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
9/2018	Manhattan	111	LEROY STREET	0	1 The Site Safety Manager reported that a window installer was taking suction cups off of a window when he pulled his back. An ambulance was called.						Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
9/2018	Queens	33-02	30 AVENUE	0	1 A DOB inspector reported that a worker was using a concrete trowell machine when he came upon a floor opening. The worker was using the machine close to the exterior wall when he hat the wall, which caused the worker and the machine fell agroups of the basement. The New York City Fire Department removed the worker and the Most Not the injured worker to a hospital. Two ECB Violations were issued, including one Aggravated Level 2 violations for a failure to safeguard and a second violation for the failure to safeguard and a second violation for the failure to post a project information penel. Two DOB Violations and a full Stop Work Order (FSWO) were also issued.		35334832K & 35334833M	062918CERRJ01 & 062818CERRJ02	ALTERATION TYPE 1	420474347-01-AL	Worker Fell	ANDREW G GEORGIOU TRUST FUND B	CENTRAL BUILDERS DEVELOPM



cident Date	Borough	Address Numbe	r Street	Fatalities Injuri	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2018	Bronx	1520	STORY AVENUE	0 1	A DOB inspector reported that a worker was on too of a concrete mixer and was atterning to remove a piece of concrete. The worker was pushing the piece of concrete with his right foot when he got his foot caught in the shreader of the concrete mixer. One of the worker's toes was severed. The General Contractor at the site contacted NYC Fire Department EMT personnel, who transported the worker to Jacoby Hospital. An Aggravated Level 2 ECB Violation was issued to the General Contractor for a failure to safeguard. A partial Stop Work Order (PSWQ) on all concrete and cement operations was also issued. The contractors at the site must provide a Means and Methods for concrete and cement operations.		35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
/2018	Bronx	1880	BOSTON ROAD	0 1	The Site Safety Manager reported that a roofer hit the edge of the coping while doing roof work and cut his hand. An ambulance was called.	No Dispatch					Other Construction Related Incidents	1880 BOSTON ROAD LLC	
2/2018	Bronx	764	EAST 152 STREET	0 1	A DOB inspector reported that at the fifth floor, a worker wars moving a hose when he became entangled in the hose and fell approximately live feet from a pipe scatilor to the deck or the fifth floor. The worker was taken to a hospital for treatment. Two Aggravated Level 2 EGB Violations were issued, one violation for a failure to safeguard, and a second violation for the failure to notify the Department Of Buildings of the incident. Two DOB Violations and a full Stop Work. Order (FSWO) were also issued.		35322847P & 35322848R	070218CER.JM02 & 070218CER.JM01	NEW BUILDING	220562905-01-NB	Worker Fell	764 EAST 152ND STREET LLC	UA BUILDERS CORP
//2018	Brocklyn	350	HENRY STREET	0 1	A DOB inspector reported that a worker was cleaning around a sharinary when he life da piece of phywood away from the sharlway and fell approximately filteen feet through an opening. The phywood was not secure and the opening was not marked. The worker suffered a possible fractured arm and fractured vertebrae. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (PSWQ) was issued on demolition work around sharlways.		3334214MEAU TO SAFEGUARD HOLES NOT SECURE: WORKER CLEANING UP THE SITE FELL THRU TO THE FLOOR		ALT1	320625294	Worker Fell	FPG CH 350 HENRY, LLC	ICS BUILDERS, INC
2018	Manhattan	301	PARK AVENUE	0 1	The Site Safety Manager reported that a worker cut the middle finger of his right hand while pushing a mini container. The worker was taken to a clinic to get stitches.	No Dispatch			ALT-11	122978625	Other Construction Related Incidents	THOR 30 PARK AVENUE LLC	TISHMAN CONSTRUCTION CORP
2/2018	Manhattan	49	CHAMBERS STREET	0 1	The Site Safety Manager reported that a HVAC worker cut his right arm during a duct installation. A DOB inspector happened to be at the site as of the time of the incident and reported that the injury occurred as the result of a worker's error. The worker walked to a hospital. No enforcement action was necessary.						Other Construction Related Incidents	49-51 CHAMBERS LLC	
/2018	Manhattan	815	5 AVENUE	0 1	The Site Safety Manager reported that there were workers that overloaded an "A"-Frame cart, which caused a few 2 X 4 X 4" stones to slide off the cart. One of the stones fell onto a worker's foot. An ambulance wa called.	No Dispatch					Other Construction Related Incidents	EIGHT HUNDRED AND FIFTEEN FIFT	
/2018	Brooklyn	1	CLINTON STREET	0 1	The Site Safety Manager reported that a worker lost his footing and hurt his leg while pushing garbage in a thirty yard dumpster. An ambulance was called.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
/2018	Manhattan	1	WALL STREET	0 1	The Site Safety Manager reported that a worker came to the end of his shift when he complained that he strained his testicles while pushing a min-dumpster. An ambulance was called.						Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
3/2018	Manhattan	150	5 AVENUE	0 1	A DOB inspector reported that a plumber was running a new line above an existing bolier when he came into contact with a live electrical wire. The plumber's partner pulled him of the wire. Both the worker and his partner were shaken up and were taken to a hospital by ambulance for a check up. An ECB Violation was issued for the presence of unapproved unsate whiring in the seminated wares were also choud in the basement bolar room. A partial Stop Work Order was issued on work on a confined space by the cellar bolier. A DOB Violation was also issued.		35343112R	070318EE105EFF01			Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	
5/2018	Manhattan	25	PARK ROW	0 1	The Site Safety Manager reported that a worker had pulled off some plywood during a stripping operation when he was hit in the eye by an II. The worker went to a City M.D. A DOB inspector responded to the incident and visited the site and reported that the worker was not wearing his safety goggles/PFC (Personal Protection Equipment). An EOB Violation was issued for a failure to maintain safe operations.		35343005L				Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	



ident Date	Borough	Address Number	Street	Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
ident Date (2018	Borough Manhattan	Address Number 392	Street ASSER LEVY PLACE	Fatalities Injurie 0 1	ECC: Final Description The New York City Police Department reported that an on site worker called 911 and reported that he fill from supported scaffold and sustained injurises. A DOB inspector responded to the incident and visited the site and reported that the worker was found laying on the ground roof level. The worker told the NYPD, the FDNY, and the responding paramedics that he fell from the second level of the installed pips scaffold. The worker suffered a horken right arm and was antified by the FDNY and transported to Bellevue Hospital by ambulance. The DOB inspector also reported that the contractor at the site was doing facade pointing work that did not require a permit, and that the contractor was in scaffold permits. Three ECB Violations wave issued con violation for the presence of a scaffold that was not enclosed, one Aggravated Level 2 violation for a failure to safeguard and a second Aggravated Level 2 violation for stress and a second Aggravated Level 2 violation	ECB Violation	ECB Violation Numbers 35324344M, 35324345Y,35324346X	DOB Violation Numbers	Permit	Permit No	Incident Type Worker Fell	Owner's Name PARKS AND RECREATION (GENERAL)	Contractor Name BQE Industries Inc
2018	Manhattan	701	7 AVENUE	0 1	for the absence of a complete guard rail system. A partial Stop Work Order (PSWO) was also issued on the use of supported scaffolds. The Site Safety Manager reported that an electrician cut his arm on a metal stud. The electrician went to urgent care.	No Dispatch					Other Construction Related Incidents		
2018	Queens	147-40	ARCHER AVENUE	0 1	The Site Safety Manager reported that a worker twisted his ankle while coming down the stairs. The worker went to a City M.D. This incident occurred on July 5, 2018, but the Site Safety Manager was not notified of the incident until July 6, 2018.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Manhattan	25	PARK ROW	0 1	The Site Safety Manager reported that a worker on the sixth floor was standing on stilts to install track when he walked into a pipe hanger and fell off of the stilts and to the ground. The worker complained of left arm pain. EMS was called and the worker was taken to a nearby hospital.	No Dispatch			NB	121190610	Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	URBAN ATELIER GROUP LLC
2018	Manhattan	425	PARK AVENUE	0 1	A DOB inspector reported that a worker stepped on a piece of unsecured plywood on the second floor and fell approximately twenty hwo feet to the first floor. The worker was taken to a hospital, and its reported to have suffered a dislocated hip. Four ECB Violations were issued: one violation for the presence of two or openings that were not securely covered and markad, a second violation for the presence of very poor housekeeping throughout the building, for the absence of perimter protecting at various places and vertical netting, and for a failure to safeguard persons and property. A full Stop Work. Order (FSWO) was also issued.	ECB Violation	35342980M,81Y,82X,83H		NEW BUILDING	121333921	Worker Feil	T-G 425 PARK AVENUE, LLC	TISHMAN CONSTRUCTION CORP
018	Manhattan	215	PEARL STREET	0 1	A DOB inspector reported that a worker was using a baker scaffold on the twenty fifth floor to perform tapping work. The scaffold was not properly rected, the wheels of the scaffold ware not properly placed, and there were housekeeping issues present in the work area. As a result, the worker fell approximately six feet off of the scaffold. The worker was found conscious and was take to a hospital for a checkup. An ECB Violation was sused to the presence of poor housekeeping under the scaffold. A partial Stop Work Order (PSWO) was issued for all work on baker scaffolds. The General Contractor to provide a Means and Methods for safe operation.	n	35331468J		121017559	NEW BUILDING	Worker Fell	LAM PEARL STREET HOTEL LLC	ANTHONY T. RINALDI LLC
018	Manhattan	1227	BROADWAY	0 1	A DOB inspector reported that a worker was installing rebar inside of column cages on the sixteenth floor. The worker was installing an eighteen fool long, and the sixteenth of the sixteenth of the sixteenth of the sixteenth of the rebar and was the sixteenth of the sixteenth lost control of the rebar and was there how the worker suffered a dislocated shoulder and was taken to hospital. Three ECB Violations were issued, including a violation for the failure to provide a DOB-approved design drawing for climbing form work. A partial Stop Work Order (PSWO) was also issued.	a	35345150R, 51Z, 52K		NEW BUILDING	121191986	Material Fell	YJL BROADWAY HOTEL LLC	FUNTLOCK CONSTR SERV LLC
2018	Bronx	603	JACKSON AVENUE	0 1	The Site Safety Manager reported that a worker fell form a baker scaffold. The worker was experiencing back pair and was taken to a hospital.	No Dispatch			NEW BUILDING	220151840-01-NB	Worker Fell	HP JACKSON AVENUE HOUSING DEVE	GALAXY GENERAL CONTRACTIN
2018	Manhattan	111	LEROY STREET	0 1	The Site Safety Manager reported that an electrical worker was on the roof and using a band saw when he cut his middle finger one inch deep. The worker was alee and conscious and was taken to a nearby hospital for treatment.	No Dispatch			NB	122622992	Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	PMG CONSTRUCTION GROUP LL



Incident Date		Address Number	Street	Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/9/2018	Manhattan	315	EAST 46 STREET	0 1	A DOB inspector reported that a signal man was gying signals to a crane operator that was operating a mobile crane that had a load on its hook. While giving signals, the signal man got his give caught inbetween the crane's main hoist cable and the sheave of a load block. The signal man suffered a severed left pinkly finger and was taken to Bellevue Hospital. The inspector reported that the crane operator was in possession of a sixteen hour rigging card and had all required certifications, paper work, and logs on site. The other members of the work crew were also in possession of sixteen hour rigging cards. No enforcement action was deemed necessary, as it was determined that the incident occured as the result of a worker error.				CN	382/18	Mechanical Construction Equipment	GOVERNMENT OF THE UNITED ARAB	Urban foundation engineering lic
7/9/2018	Queens	36-18	MAIN STREET	0 1	The Site Safety Manager reported that a roofer got some waterproofing material in his eyes while he was spraying. The roofer walked to an urgent care center.	No Dispatch					Other Construction Related Incidents	134-22 35TH AVE., LLC	
/10/2018	Brooklyn	1520	FULTON STREET	0 1	The Site Safety Manager reported that a plumber that was working in the basement slipped on water that was on the floor and hurt his knee. The worker went with another worker by car to see a doctor.	No Dispatch					Other Construction Related Incidents	HELLO FULTON LLC	
7/10/2018	Brooklyn	170	BUFFALO AVENUE	0 1	The Site Safety Manager reported that a worker fell from an "A"-Frame ladder and hurt his ankle. The worker went to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	BUFFALO AVE. REALTY ASSOCIATES	
7/10/2018	Manhattan	19	EAST 70 STREET	0 1	The Site Safety Manager reported that a worker was carrying a pail of sweeping compound on his shoulder when he lost control of the pail and the pail fell on his right leg. The worker was sent to a hospital.	No Dispatch					Other Construction Related Incidents	NY 70TH STREET LLC, A NY LLC,	
7/10/2018	Manhattan	218	EAST 16 STREET	0 1	The Site Safety Manager reported that a worker was cuting off a tie-wire from an extension cord when he ut his hand with a cuting krille. The worker had his protective gloves on, but the krille went through the top of the glove. Detween the thumb and index finger. An ambulance was called.	No Dispatch					Other Construction Related Incidents	SOCIETY OF FRIENDS	
7/12/2018	Manhattan	524	RIVERSIDE DRIVE	1 0	A DOB inspector reported that a piece of the suspended scaffold system became dislodged at the rool level, fail herelve storks, and struck a workder in the head. The worker was taken to the nearest hospital in critical obligation, the sissued for a failent hesitypites. A DO obligation the issues of or a failent hesitypites. A DO Stop Work Order (FSWO) were issued.	DOB Violation		071218CER01KC	ALTERATION TYPE 2	122912027-01-EW-OT	Scaffold/Shed/Fence/Shoring/Installation	INTERNATIONAL HOUSE	PRATT CONSTRUCTION & REST
/13/2018	Brooklyn	138	WILLOUGHBY STREET	0 1	A DOB inspector reported that there were workers using chainfails to move on the ground the collar d a crane in order to position it into a better working position as part of a crane jumping operation. While the collar was being moved, one of the worker's lags was pinned between the collar and a piece of the building. The worker was taken to Mattodist Hoopial by antibuations. The crane was not being used as of the time of the incident. The inspector reported that incident was caused by the use of Mattodist and a more accurate by the use of Rigger. An ECB Violation was issued for a failure to safeguard. A DOB Violation was also issued.		35322622Y	07131BCERSM01	NEW BUILDING	321197085-01-NB	Other Construction Related Incidents	NYC HPD	LEND LEASE (US) CONSTRUCT
/13/2018	Manhattan	20	WEST 40 STREET	0 1	The New York City Fire Department requested that an inspection please be performed because a construction worker suffered a head injury after coming into contact with a grinder. The worker was in stable condition and suffered a broken nose. The worker was transported to a hospital by EMS and received batterfly attiches on his forthwead. The worker was reasonable to the objatal incident and visited the site and reported that the grinder was used contrary to the manufacture's specifications. An ECB Violation was issued for the failure to maintain safe operations. A partial Stop Work Chorder (FSWO) was issued on the use of all grinders. A Means and Methods and a Tool Box Talk must be provided.		35326871N				Other Construction Related Incidents	NOT ON FILE	
7/16/2018	Queens	24-16	QUEENS PLAZA SOUTH	0 1	The Site Safety Manager reported that a worker on the top of a deck at the twenty third floor was cut on his arm						Other Construction Related Incidents	24-16 QUEENS PLAZA PROPERTY OW	
/16/2018	Manhattan	9	ORCHARD STREET	0 1	by a circular saw. The worker was taken to a hospital by ambulance. The Site Safety Manager reported that a worker hurt his						Other Construction Related Incidents	NINE ORCHARD PARTNERS, LLC	
7/16/2018	Manhattan	50	AMSTERDAM AVENUE	0 1	back while placing a chipping gun on the floor. An ambulance was called. The Project Manager at the site reported that a female worker tripped on a temporary electrical conduit that was laying on the roof of the building. The worker suffered builded knew and a swollen wrist and was taken to a hospital by ambulance. A DOB inspector responded to the incident and visited the site and issued two ECB Violations: one violation for the presence of an unsupported auminum pipe, and a second violation for unsupported auminum pipe, and a second violation for disconsect of 200 amps that ran between the basement and the rootbors sub panel. Two DOB Violations were	ECB Violation	35343201Z, 35343202K.	71818EE107RID01, 71818EE107RID02			Worker Fell	NYC HOUSING AUTHORITY	



ncident Date	Borough	Address Number	Street	Fatalities Injuri	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/16/2018		36	GROVE STREET	1 0	A DOB inspector reported that a worker was performing an electrical installation on an energized circuit in the bathroom. The worker suffered an 120 volt electrical shock. The worker was taken to Lenox Hill Health Plex, where he was pronounced dead. The inspector reported that the worker liaide to de-energize the circuit before performing the electrical installation. Three ECB Violations were issued: one violation for the presence of unapproved and unsafe wrining that had not been terminated, unsupported boxes, unsecured splice boxes, the failure to provide a GFCI, and the failure to provide a lang guard for temporary lights, one violation for the failure to post an electrical permit, and one violation for the used an electrical porm a storage.		35315697N, 35315698P & 35343200R	74648EE102RID01,74618EE102RID02 & 71618EE102RID03			Other Construction Related Incidents	LUKE, TIMOTHY	
//16/2018	Brooklyn	25	COLUMBIA HEIGHTS	0 1	The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was driven to a hospital.	No Dispatch					Other Construction Related Incidents	25-30 COLUMBIA HEIGHTS BROOKLY	
7/17/2018	Manhattan	125	GREENWICH STREET	0 1	The Site Safety Manager reported that a worker was performing a window installation when he flipped over a piece of tube steel and oth is index finger caught between the tube steel and the floor. The tip of the worker's index finger was crushed. The worker went to a hospital by taxi.						Other Construction Related Incidents	VS 125 LLC	
/17/2018	Queens	28-07	JACKSON AVENUE	0 1	The Site Safety Manager reported that a truck driver cut his finger while loading garbage. 911 was called.	No Dispatch					Other Construction Related Incidents	LIC SITE B-1 OWNER, L.L.C.	
7/18/2018	Brooklyn	422	FULTON STREET	0 1	The Sale Safety Managar reported that a worker slipped and fail line of 3 × 3 × 2 depicted and a particular inspection in the cellar. The worker suffered a log input and an ambulance was called A DOB inspector responded to the incident and visited the site and confirmed the Site Safety Manager's report. The inspector determined that the incident occurred as the result of a human error and that no enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	NOT ON FILE	
7/18/2018	Manhattan	214	WEST 29 STREET	0 1	A competent person at the site reported that a worker slipped off an "A"-Frame ladder. The worker went to a hospital for a check up.	No Dispatch					Other Construction Related Incidents	WALSAM TWENTY-NINE CO	
7/18/2018	Manhattan	24	2 AVENUE	0 1	The Site Safety Manger reported that a worker stepped on a nail. The worker walked to medic care for a check up.	No Dispatch					Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	
7/18/2018	Queens	147-40	ARCHER AVENUE	0 1	The Site Safety Manager reported that a worker was walking down a flight of stairs when he lost his balance on the bottom step and hurt his right foot. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
7/19/2018	Brooklyn	420	UNION STREET	0 1	The Construction Superintendent reported that an electrician that was working on a School Construction Authority (SCA) project cut his right thumb. The electrician went to an out patient clinic.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
7/19/2018	Manhattan	140	ESSEX STREET	0 1	The Construction Superintendent reported that during a serial region of the series of the series of the series of the worker in the back. The worker was awake and conscour- and was able to walk, but paramedics put the worker on a stretecher and took him to a hospital. The foreman at the site ails own to the hospital to check on the worker. The Construction Superintendent reported that the worker had selfered micro threads, with no broken bones, and was released from the hospital. A DOB inspector responded to the incident and visited the site and reported that the Construction Superintendent license had expired. An ECB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued.		35336263z		FO	121187642	Material Fell	SITE 8 DSA HOUSING DEVELOPMENT	Essex Site θ Builders LLC
7/19/2018	Manhattan	625	WEST 125 STREET	0 1	The Site Safety Manager reported that a worker was installing a light fixture when he tripped over the light fixture and hurt his knee. The worker went to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	THE TRUSTEES OF COLUMBIA UNIVE	
7/20/2018	Manhattan	30	EAST 31 STREET	0 1	Up anti-usance. The Site Safety Manager reported that a pedestrian was entering her building when she was hit in the head by a piece of debris that fill from a construction site. The pedestrian did not safet any visible inplices, but an ambulance was called. A DOB inspector responded to the incident and visited the site and and issued an ECB Violation for a failure to safeguard. A partial Sitop Work. Order (PSWO) on all concrete work operations was also issued. A Netwar and Methods for safe operations must be provided.		35342859K				Other Construction Related Incidents	31ST STREET ZEF LLC	



cident Date	Borough	Address Number	r Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
21/2018	Brooklyn	3514	SURF AVENUE	0 1	A DOB inspector reported that a worker was stripping plywood with two workers coming from behind him. The worker that was performing the stripping did not notify the other workers that he opened a hole, and the worker that was performing the stripping operation fell two		35342860H/61J/62/	072118BS13EP01/02/03			Worker Fell	RED APPLE SURF REALTY III LLC	
					that was performing the simpping operation reli two stories through the hole. The worker was found conscious and was taken to an area hospital. The inspector observed that the protocol for a pre-task								
					meeting for stripping operation was not followed up, and that there were house keeping issues present at the top								
					floor that were recorded by the Site Safety Manager. Three ECB Violations were issued: one violation for the failure to maintain or institute safety measures for								
					construction operations, one violation for the failure to revise the pre-shift task meeting, and one violation for the failure to provide a Professional Engineering letter or design drawing for protection at large slab openings.								
					Three DOB Violations were also issued. A partial Stop Work Order (PSWO) was issued on concrete and stripping operations. A Means and Methods for the safe continuation of work must be provided.								
3/2018	Manhattan	545	WEST 30 STREET	0 1	The Site Safety Manager reported that a worker was in	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
2010		010			the hoist with equipment when he got his foot caught under the equipment. The worker went to urgent care.	no biopaton							
23/2018	Manhattan	401	WEST 31 STREET	0 1	performed under the stetel level for the removal of existing Amrika tracks and the installation of new steel for the relocation of an existing sub-station. An iron worker was installing steel decking when he fell approximately ten feet through a gap and suffered a firactured arm. The worker was build used in stable condition firactured start. The worker was taken to a hospital. An ECB by EMS. The worker was taken to a hospital. An ECB violation was issued for a failure to safequard. A DOB	ECB Violation	36245391J	072318CNEDB01	A2 - ALTERATION TYPE 2	123091705	Worker Fell	BOP WEST 31ST STREET LLC	JOHN CIVETTA & SONS INC
/2018	Manhattan	217	WEST 57 STREET		Violation was also issued. A partial Stop Work Order (PSWO) was issued for all steel work bering performed for the relocation of a sub-station.	1. 5						SMITELL SPONSOR LLC	
92018	Mannattan	217	WEST 57 STREET	0 1	The Site Safety Manager reported that there were workers that were backing up a trailer on the job site with flaggers when a bicyclist went around the flagger, slipped on wet pavement, and hurt his arm. The pavement was wet because of rain. The bicyclist did not hit the trailer. An ambulance was called.	No Dispatch					Other Construction Related Incidents	SMITELL SPONSOR LLC	
3/2018	Manhattan	152	EAST 87 STREET	0 1	A worker fell back and scrapped his arm against a trash chute. The worker went to a hospital for treatment. The worker received two stitches and returned to work.	No Dispatch					Other Construction Related Incidents	ALLAN GARAGE,	
3/2018	Manhattan	150	EAST 38 STREET	0 5	A DOB inspector reported that contractors were performing interior demolition work on the fourth floor when the wood and plaster celling collapsed and injured five workers. Two of the workers were in serious condition and vere taken to Belliever Hospital. No structural damage was observed. An Aggravated Level ECB Violation was issued for a failure to safeguard A full Stop Work Order (FSWO) was also issued.	ECB Violation	35343417H		Alt 1	123254263	Other Construction Related Incidents	SUN, ANGELA	zzz carpentry Inc
4/2018	Manhatan	19	EAST 70 STREET	0 1	A DOB inspector reported that during the hosting of page scaffold frames from the fifth host down to the interior of a staris shaft, one of the frames got loose and hit the Construction Superintendent in the head on the second floor, knocking him unconscious. The worker was taken to Presbyterian Hospital in stable condition. Two ECB Violations were issued: one violation for a failure to safeguaria all periors affected by construction operations, and one violation for work being periformed work order was issued for material hoist work and for supported scaffold work.	ECB Violation	353244222 - 35324423K		Alt 1	121944227	Material Fell	NY 70TH STREET LLC, A NY LLC.	Sweeney & Conroy Inc
25/2018	Manhattan	315	EAST 46 STREET	0 1	The Site Safety Manager reported that a worker performing form work when he got his finger pinched during an installation and suffered a cut to his finger. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
5/2018	Queens	43-12	HUNTER STREET	0 1	The Site Safety Manager reported that a worker in the basement cut his right eye while moving rebar. The worker went to a City M.D. with a co-worker.	No Dispatch					Other Construction Related Incidents	43-12 HUNTER LLC	
/2018	Staten Island	546	GULF AVENUE	0 1	The Site Safety Manager reported that a worker was experiencing back pain. The worker left the site to go to a hospital on his own.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
6/2018	Staten Island	546	GULF AVENUE	0 1	The Site Safety Manager reported that a steel worker was using a chain when the chain slipped out of his hand and pinched his left finger. The worker went to urgent	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	



ncident Date	Borough	Address Numb	er Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	250	SOUTH STREET	0 1	The Site Safety Manager reported that an iron worker		35331357R	072618BS03JJ01	- crime		Material Fell	NOT ON FILE	
					was on a man lift and working on a small piece of steel								
					clip that was approximately 2" X 4" when he lost control								
					of the clip and fell approximately 30' inside the job site. A DOB inspector responded to the incident and visited the								
					site and reported that the worker suffered a minor injury								
					to his shoulder from the steel clip when the clip fell. The								
					worker did not report the injury, and left the site without								
					letting anyone know. An ambulance was not called. The worker later reported that he went to see a doctor. An								
					ECB Violation was issued for the failure to institute safety								
					measures. A DOB Violation and a partial Stop Work								
					Order (PSWO) were also issued.								
2018	Manhattan	215	PEARL STREET	0 1	The Site Safety Manager reported that a worker was standing on a ladder that was behind a closed door when	ECB Violation	35342769R	072618BS01KR02			Worker Fell	LAM PEARL STREET HOTEL LLC	
					another worker opened the door and knocked the worker								
					off of the ladder. The worker hit his head, and an								
					ambulance was called. A DOB inspector responded to the incident and visited the site and issued an ECB								
					Violation for a failure to institute safety measures. A DOB								
					Violation was also issued. A partial Stop Work Order								
					(PSWO) was issued on all door closure installations. A								
					Means and Methods and a safe Controlled Access Zone area for ladder work during an installation must be								
					provided.								
2018	Manhattan	438	WEST 54 STREET	0 1	A DOB inspector reported that a worker was on a truck and receiving planks while dismantling a sidewalk shed	ECB Violation	35324486H - 35324487J		NB	122822605	Worker Fell	15024 EMMUT PROPERTIES LLC	Best Point Mgmt Corp
					when he lost his footing and fell off of the truck and onto								
					a pedestrian. The pedestrian received aid from the								
					onsite Sidewalk Shed company, Tri Borough Scaffolding.								
					The pedestrian requested medical treatment. The FDNY responded to the request and visited the site, and								
					responded to the request and visited the site, and examined both the worker that fell from the truck and the								
					pedestrian. The worker was determined to be okay and								
					returned to work, while the pedestrian as taken to a								
					hospital. Two ECB Violations were issued: one violation for a failure to safeguard pedestrians and property, and								
					one violation for a failure to provide a sidewalk shed as								
					required. A full Stop Work Order (FSWO) was also								
					issued.								
018	Bronx	1812	VYSE AVENUE	0 1	The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	
2010	BIOIX	1012	VISE AVENUE	0	moving pipes when his right middle finger got caught	NO Dispatch					Other Construction Related incidents	VIA VISE PARTNERSHIP HOUSING D	
					between pipes. The worker went to the emergency room								
					with his supervisor. An ambulance was not called.								
/2018	Bronx	4511	3 AVENUE	0 1	The Site Safety Manager reported that a plumber was	No Dispatch					Other Construction Related Incidents	STB HOUSING DEVELOPMENT FUND C	
					tightening a sprinkler pipe when he hit a stud and cut his								
					finger. The worker walked to urgent care across the street from the job site.								
/2018	Manhattan	110	UNIVERSITY PLACE	0 1	The Site Safety Manager reported that a worker was on	No Dispatch					Worker Fell	NOT ON FILE	
2010	ind indicate	110	on tenor tenor		a ladder when he mis-stepped, fell off of the ladder, and	no bioputori					Wond P di	NOT ON THE	
					pulled his back at. The worker went to urgent care.								
/2018	Manhattan	122	EAST 23 STREET	0 1	The Site Safety Manager reported that a cleaning person	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					was cleaning the apartments when she went down to the								
					cellar, where there was construction work being performed. The cleaning person stepped walked off of								
					the elevator and hit her foot on a man-lift that was left in								
					the basement. The man-lift was in the basement								
					because it was being used in construction work that was								
					being perofrmed. The cleaning person went to urgent care on her own.								
2018	Manhattan	233	WEST 125 STREET	0 1	SThe Site Safety Manager reported that at a twenty six story new building that was under construction, a worker	No Dispatch			NB	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
					was cutting rebar with a chop saw when a fragment of								
					the rebar hit him in the face. The worker did not appear								
					to suffer any cuts. The worker went to see a private doctor								
2018	Brooklyn	269	4 AVENUE	0 1	The Site Safety Manager reported that at the foundation	No Dispatch			NB	320596805	Other Construction Related Incidents	FIRST BUILDING ENTERPRISES LLC	NEW EMPIRE BUILDER CORP
	,	200			level of a twelve story new building, a worker was loading					52000000	Conditioner results incluents		
					in plywood material when he pinched his left pinky finger								
					between plywood. The worker was found alert and conscious and was taken to Lutheran Hospital for								
					conscious and was taken to Lutheran Hospital for treatment.								
018	Manhattan	26	ANN STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	143 FULTON STREET DEVELOPMENT	
					using a utility knife when he accidentally cut himself by								
					mistake. The worker went to a City M.D.								
18	Manhattan	77	WEST 55 STREET	0	1 A DOB inspector reported that there were workers that	ECB Violation	35324558H, 35324553Z		Alt	M00050141	Worker Fell	GALLERY HOUSE CONDOMINIUM	Phonex Sutton Str Inc
					were in the process of installing a sidewalk shed on top of a baker scaffold when one of the workers lost his								
					footing and fell. During the fall, the workers lost his								
					hat and bumped his forehead on a mud sill. The worker								
					was found conscious and was taken to a local hospital.								
					Two ECB Violations were issued to the General								
					Contractor at the site: one violation for a failure to safeguard all persons and property affected by								
					construction operations, as the supported scaffold did								
					not feature any guardrails, and a second violation for a								
					failure to provide a four hour supported scaffold user certificate. A partial Stop Work Order (PSWO) was also								
					issued.								
_	1						Page 39 of	52					



	Borough				ies EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/2018	Queens	110	UNIVERSITY PLACE	0	1 A DOB inspector inported that there were workers that were moving an 'A-Frame older that was overloaded with sheet metal when the 'A-Frame oldipased and fell onto the legat and fest of one of the workers. The worker was taken to Bellevue Hospital by ambulance for treatment. You EGB Violations were issued: one violation for the presence of unsafe working conditions and equipment, and a second violation for the absence of manufactuer specifications for the 'A-Frame. A patie Stop Work Order (PSWQ) mass issued on all use of 'A- Frame ladders. A Tool Box Talk and a sequence for the handing of materials must be provided.	ECB Violation	35345140N,41P		NB	121187241	Other Construction Related Incidents		CNY CONSTRUCTION LLC
2/2018	Brooklyn	3021	WEST 25 STREET	0	1 A DOB inspector reported that during the alteration of an existing building, a worker was using an excavator to organize piping, while there was another worker that was standing behind the excavator. The excavator backed up without notice, and the worker that was standing behind the excavator was struck in the head by the bucket of the excavator. The worker was found alert and conscious and was taken to a nearby hospital. An ECB Violation was issue for the presence of usafe conditions and equipment. A partial Stop Work Order (PSWO) was issued on handling material and plumbing operations.	5	ECB#353161125M- UNSAFE CONDITIONS AND EQUIPMENT	080218BS13KR01	NB	321447243	Excavation/Soil Work	NYC HOUSING AUTHORITY	AWL INDUSTRIES INC
/2018	Manhattan	1	WALL STREET	0	1 The Site Safety Manager reported that a worker hit his left eye while removing form work. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
/3/2018	Manhattan	621	GREENWICH STREET	0	1 The Project Manager at the site reported that a worker was on a scaffold when he slipped and fell while trying to move away from the rain. The worker hurt his shoulder and was taken to a hospital by EMS.						Worker Fell	PMG LEROY STREET DEVELOPMENT L	
/3/2018	Manhattan	441	9 AVENUE	D	¹ The Site Safety Manager and a DOB inspector reported that a worker was working on a deck when he unbroked his fail areas system, los the balance, and lei at the care, and the urgent care center called an ambulance to transport the worker to a hospital. The Site Safety Manager was not informed of the incident until the end of the day on August 3, 2018, and did not report the incident immediately to the Department Of Buildings because he wanted to have all of the fasts of the incident before reporting it. Five ECB Violations were issued, inciding one violation for the unseles storage of acetylene and oxygen tasks, one violation for poor unacguped reak-one violation for the presence of unacquerd reak-one violations of the presence of unacquerd reak-one violation of	é t	35345468R/692/70X/71H/72J	080418BS04GD03/04/05/06/07			Worker Fell	CBP 441 NINTH AVENUE OWNER, LL	
/2018	Manhattan	110	CHARLTON STREET	0	1 The Site Safety Manager reported that two workers were carrying rebar on the first floor when one of the workers lost his balance and hurt his shoulder. The injured worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	
3/2018	Manhattan	10	VANDERBILT AVENUE	0	1 The Site Safety Manager reported that a worker was coming down the stairs when he tripped and fell. The worker suffered a laceration to his back. EMS took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	ONE VANDERBILT OWNER LLC	
3/2018	Brooklyn	2442	OCEAN AVENUE	0	1 The Site Safety Manager reported that a worker was looking for a shovel when he slipped on form work in the cellar. The worker did not notify the Site Safety Manager of the incident until three hours after the incident occurred. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	2442 OCEAN AVENUE, LLC	
3/2018	Brooklyn	10	NEVINS STREET	0	 The Site Safety Manager reported that a worker was handling duct work when he cut his hand on sheet metal The worker was found conscious and alert and was taken to Brooklyn Hospital for treatment. The worker required several stitches. 	No Dispatch			NB	320915578	Other Construction Related Incidents	NEVINS STREET OWNER LLC	DANYA CEBUS CONSTRUCTION
/3/2018	Bronx	316	EAST 165 STREET	O		t	35344814X, 35344815H, 35344816J, 35344817L		NB	220619150	Worker Fell	CG EDUCATIONAL HOLDING CORP.	Hellister Construction Se



ident Date	Borough	Address Number	Street Fataliti	lities Injuries			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that at an Alteration 1 job at a fifty eight story building, on the twenty-ninth floor, a worker mis-stepped while stepping outo a landing and twisted his ankle. The worker was found conscious and alert and was taken to New York Prebyterian Hospital for				ALT 1	121333413	Worker Fell	NOT ON FILE	CNY CONSTRUCTION LLC
					treatment.								
118	Aanhattan	445	WEST 35 STREET	0	1 The Site Safety Manager reported that a worker was ripping plywood with a tablesaw when he cut his hand by accident. The worker was taken to a hospital. A DOB inspector responded to the incident and visited the site and reported that the worker was using a cordess circular saw as per the manufacturer's specifications. Because of this, it was determined that the incident occurred as the result of a worker's error, and that no enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	CARE REALTY CORP.	
)18	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
		40.01		Ū	moving metal angles around the site when he cut his arm on one of the metal angles. The worker went to an emergency room on his own.	no popular							
)18	Aanhattan	60	WEST 120 STREET	0	1 A DOB inspector reported that approximately twenty four feet of parapet fell onto a public street. A pedestrian suffered an unconfirmed injury. The pedestrian was treated at the scene and released. An ECB Violation was issued for a failure to safeguard. A DOB Violation was also issued.	ECB Violation	35323035Y	080719CERSM01	A2 - ALTERATION TYPE 2	121230382	Scaffold/Shed/Fence/Shoring/Installation	LENOX LLC	D&L DESIGN & BUILD LLC
018	Manhattan	130	WILLIAM STREET	0	1 The Site Safety Manager reported that a worker fell and hurt his chin while picking up rebar. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	
2018	Aanhattan	108	EAST 89 STREET	0	1 A DOB inspector reported that a worker was on the world's floor inside of particina values. He attempted to move some sheetrock that was beind a stack of sheetrock that was leaning against the wall in order to install insulating material when a stack of sheetrock fell on his andle. The worker did not appear to have any visible injury, but complained of pain. The worker's foreman look him to a hospital for a check up. No enforcement action was deemed necessary, as it was determined that this incident occurred as the result of worker foreman.					122988623	Material Fell	DALTON SCHOOLS INC	E.W. HOWELL CO, LLC
8	3rooklyn	277	SOUTH 5 STREET	0	1 The Site Safety Manager reported that a worker was stripping form work in the basement when a piece of plywood hit him in the shoulder. The worker went to a hospital by ambulance for a check up. The Site Safety Manager also reported that the worker will be returning to work.	No Dispatch					Other Construction Related Incidents	HAVEMEYER OWNER LLC	
018	Srooklyn	2401	AVENUE Y	0	1 The Project Manager at the site reported that a worker opened a roof tack han del algorizontawish thitteen and a half leet through an opening. The worker suffered a fractured pelvis and elbow. A Dold inspector responded to the incident and visited the site and reported that no quartifiait were provided around the opening at the roof, which caused the worker to fall. An EGS Violation was issued for the failure to safeguard all persons and/or property affected by construction operations. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35350727M	08061188515L106			Worker Fell	PARKS AND RECREATION (GENERAL)	
118	Brooklyn	555	4 AVENUE	0	 The Site Safety Coordinator reported that a worker was moving rebar when he hit himself in the mouth and chipped his tooth. The worker went to a medical office on his own. 	No Dispatch					Other Construction Related Incidents	PARTNERS VI//541-555 FOURTH OW	
2018	Staten Island	546	GULF AVENUE	0	1.1						Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Manhattan	787	11 AVENUE	0	1 The Site Safety Manager reported that an electrician was cutting a pipe with a bend saw when he cut his finger tip. The worker went home to see his doctor. A co-worker	No Dispatch			ALTERATION-1	121190399	Other Construction Related Incidents	GEORGETOWN ELEVENTH AVENUE OWN	CAULDWELL WINGATE CO LLC
2018	Brooklyn	2527	CHURCH AVENUE	0	went with him. 1 The Construction Superintendent reported that a worker fell on the first floor. The worker was taken to a hospital by ambulance. A DOB inspector responded to the	ECB Violation	35332476Y				Other Construction Related Incidents	2527-2529 CHURCH GROUP LLC	



cident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Brookijn	211	MCGUINESS BOULEVARD	0	A DOB inspector reported that at the construction of a now nine story residential building, there was a pipe scalfold that was in the process of being removed. While the worknew rever taking down the sideand end horacket from the sixth floor level of the scalfold with a rope pulley, the bracket hit one of the scalfold by his hard that. The struck hordre worknew that was standing on the fourth floor of the scalfold by his hard responsive and was taken to a local hospital for a check up. Two ECG Violations were issued: one Agravated Level 2 ECB Violation for a failure to safeguard, and one violation for the installistion of needles beams that was contrary to the approved plan issued to the scalfold was also issued.	ECB Violation	35351651X - 35351652H		Ait 3	340442550	Scaffold/Shed/Fence/Shoring/Installation		Rock Group of NY Corp
9/2018	Bronx	300	HUTCHINSON RIVER PARKWAY	0	1 The Construction Superintendent reported that an electrician at the site was on an "A"-Frame ladder when he missed a step, fell, and hurt his foot. The electrician was taken to a hospital by ambulance.	No Dispatch				_	Other Construction Related Incidents	PARKS AND RECREATION (GENERAL)	
9/2018	Bronx	2028	WEST CRESTON AVE	0	1 The Site Safety Managor reported that a worker was using a wire acound a pipe when he lost his grip and the wire sid, hitting him on the side of the head. The Site Safety Managor reported that are worker was using a wire around a pipe when he lost his grip and the wire sid, causing the pipe to hit him on the side of the head. An ambulance was called.	No Dispatch					Other Construction Related Incidents		
9/2018	Bronx	1812	VYSE AVENUE	0	1 The Site Safety Manager reported that a worker was moving a cast iron pipe when he twisted his ankle. The worker went to urgent care for treatment.	No Dispatch					Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	
10/2018	Manhattan	115	DELANCY STREET	0	1 The Site Safety Manager reported that a painter had finished his work using a spray gun and went to clean them had a spray gun and went to clean the when had and spray and the spray of the spray of the water went into the worker's sys. The worker was taken to a hospital by ambulance in order to have his eyes cleaned.				NEW BUILDING	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
10/2018	Manhattan	1485	PARK AVENUE	0	¹ The Site Safety Manager reported that a worker was stripping concrete form work. The worker was led off, but his retractuable cable did not release, lerking him backwards and causing him to full. The worker sufficed DOB inspectro responded to the incident and visited the site and issued an ECB Violation for inadequate safety measures. A DOB Violation was also issued. A partial Stop Work Order (PSWQ) was issued for all form work and stripping partitions, and to check workers: Personal Protection Equipment (PPE), must be provided.	ECB Violation	35315942H	061019BS11BG04			Worker Fell	LEX GARDENS II TP4 HOUSING DEV	
10/2018	Manhattan	553	WEST 30 STREET	0	1 A DOB inspector reported that there was an electrician that was drawing wires on the fifty-seventh floor when he stepped on phywod that was used to cover a floor opening for mechanical duct work. The phywod that was used for the floor covering was not in proper condition that the capacity to carry the worker's lead and when he worker stepped on 1t, the phywod split into two parts and his leg want through the opening. The worker's lead was cut by ar eather that was protunding from the floor. The worker was transported to a hospital by ambulance. An ECB Violation was issued for the failure to maintain safery measures. A partial Slop Work Order (PSWO) was issued for all work on the fifty-seventh floor and in proxmity of floor openings and shafts.		35350712X		NEW BUILDING	121184208	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
0/2018	Queens	29-22	NORTHERN BOULEVARD	0	A DOB inspector reported that there were workers that were moving a diesel fuel container on a doil when they lost balance on the aldewalk, causing the diesel fuel to splanh a pedestrian that was standing on the sidewalk. The cogo of the barrie was blocked and do not cheed on the sidewalk. The sidewalk was shown and do not cheed pedestrian was transported to a hospital by EMS. The workers that were moving the disea fuel container did not have a Certificate Of Friness from the Fire Department. The job dd not have a Fire Department permit for the storage and use of dises fuel at the site. Three ECB Violations were issued: one violation for the failure to safeguard persons and property, one violation for the handing of Harmable liquid attuid without an FDNY Certificate Of Firness, and one violation for the storage and use of flammable liquid attuid at FDNY permit. A partial Stop Work Order (PSWO) was also issued.	ECB Violation	35350687N, 35350688P, 35350689R		NEW BUILDING	420650398	Other Construction Related Incidents	QSB NORTHERN LLC	LEEDING BUILDERS GROUP LL
13/2018	Queens	28-07	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker was installing an exterior panel when he cut his finger on a metal clip. The worker went to a clinic.	No Dispatch					Other Construction Related Incidents	LIC SITE B-1 OWNER, L.L.C.	



	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	817	BROADWAY	0	1 The Site Safety Manager reported that a worker in the basement was removing some debris when he was stuck in the hand by a hypodermic needle. The worker went to						Other Construction Related Incidents	817 BROADWAY OWNER LLC	
					a hospital.								
:018	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that a worker field rid an extension ladder on the servementh floor and hurt his head and arm. An ambulance was called and took the worker to a hospital. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for a failure to institute safety measures. A DOB Violation was also issued.		35332478H	0813188S04DH02			Worker Fell	CBP 441 NINTH AVENUE OWNER, LL	
2018	Brooklyn	814	BEDFORD AVENUE	0	1 A DOB inspector reported that at a new building that was under construction, a worker was working in the basement when his heinert was struck by a falling metal post. The worker was taken to a hospital by ambulance, and was released from the hospital without injury. An ECB Violation was issued for a failure to safeguard the public and property during construction operations. A DOB Violation was also issued. A full Stop Work Order (FSWO) was issued to the job site.	ECB Violation	35323079X	081318CNELC01	NEW BUILDING	321362565-01-NB	Other Construction Related Incidents	814 PARK LLC	PARKVIEW BUILDERS LLC
018	Brooklyn	10	HURON STREET	0	1 The Site Safety Manager reported that a worker was walking down the stairs when he tripped on the last step and bumped his head. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
4/2018	Manhattan	249	WEST 14 STREET	0	1 The Site Safety Manager reported that a pedestrian in a wheelchair was going over a ramp in the walkway and lifped backwards in the wheelchair. An ambulance was called. A DOB inspector responded to the incident and visited the site and issued an ECE Violation for the presence of a ramp that was inadequate for wheelchair accessibility. A DOB Violation was also issued. A partial Stop Work Order (FSWO) was issued for the use of a hydrant hose covered by a ramp on a pedestrian walkway.		35345323X	081418BS04VP04			Other Construction Related Incidents	261 WEST 14 STREET, LLC	
018	Brooklyn	308	NORTH 7 STREET	0	1 The New York CIIP Fire Department requested that an impection please be performed wide to a worker falling from a scatfloid. A DOB inspector responded and visited the site and reported that the General Contractor was in the process of dismantling a supported scatfold. While a truck as being loaded, the parapet panel from the sidewalk shed collapsed, causing the worker to fail. The worker was concisious and was able to move his arms. Thospital. Two ECS Violations was issued to me violation for a failure to aveloations and was able to move his arms overstocked, which caused the parapet panel to collapse, and ne violation was issued to the Construction Superintendent for the failure to perform duries, as the Construction Superintendent allowed the work area to become overstocked with maternials. A partial Stop Work Coder (FSWO) was issued on facade work and the removal of a supported scaffold.		35351611L - 35351612N		NB	320597074	Worker Fell	N7 OWNER LLC	Britt Realty LLC
2018	Manhattan	110	CHARLTON STREET	0	1 The Site Safety Manager reported that a worker stepped on a nail. The worker went to urgent care.	No Dispatch			NEW BUILDING	121191263-01-NB	Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	PLAZA CONSTRUCTION LLC
5/2018	Manhattan	1558	3 AVENUE	0	1 The Site Safety Manager reported that a worker on the twenty-aighth floor was getting ready for his work day when a reshort fell from its position and hit him in the shoulder. The worker went to a City MD. A DOB impector was on site as of the time of the incident and reported that there was formwork learning against the reachores, which caused the reshorts that struck the large of the structure of the structure of the instance of the structure of the structure the large of the structure of the structure of the structure of issued. A partial Stop Work Order (PSWO) was also issued.	ECB Violation	35332462N	081518BS08AD01			Material Fell	180 EAST 88TH STREET REALTY LL	
5/2018	Mənhattən	233	WEST 125 STREET	0	1 A DOB inspector reported that a worker was cutting metal straps to remove dill rods of a bundle during a crane footing installation when the metal straps snapped and a dill rod section rolled down and hit the worker foot. The worker's foreman called EMS and the worker was taken to a hospital for treatment. The worker did net suffer any broken bones. The worker was later released from the hospital. An EGD shop how the worker work also issued The General Contractor was directed to provide a Means and Methods for the loading and unloading of drilling and construction material.		35316082L		NB	121187447	Material Feil	HARLEM URBAN DVLPMNTCP	Flintlock construction lle



cident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/2018	Manhattan	555	WEST 22 STREET	1 A DOB inspector reported that a female predestina we sprayed in the face by hydrautic oi while waiting for th bus. The pedestrian was taken to an area hospital by ambulance. A hydraulic oil the had nytured in the aug while cutting for a secant pile wall in the northeast coro of the site on the West 23C Hostion was issued for the failure to safeguard pedestrians. A DOB Violation was also issued. A partial Step Viol. Order (F2NO) was also issued. A partial Step Viol. Order (F2NO) was also issued. A partial Step Viol. Order (F2NO) was also issued. A partial Step Viol. Order (F2NO) was also issued. A partial Step Viol. Order (F2NO) was also issued. A partial Step Viol. Order (F2NO) was also issued. Step Viol. A partial Step Viol. Order (F2NO) was also issued. Step Viol. A partial Step Viol. Order (F2NO) was also issued. Step Viol. A partial Step Viol. Order (F2NO) was also issued. Step Viol. Net Viol. Viol. Net Viol. Viol. Net Viol. Net Viol. Vi	er ier	36343891L	081518CERMR01	NEW BUILDING	121204366-01-FO	Other Construction Related Incidents	22ND AND 11TH ASSOCIATES, LL	RELATED CONTRUCTION LLC
5/2018	Queens	22-44	JACKSON AVENUE	0 1 The Site Safety Manager reported that a worker was o stills doing taping work when he either tripped or lost h balance and fell, hurting his wrist and ribs. An ambulance was called.	n No Dispatch is					Other Construction Related Incidents	G & M REALTY, L.P.	
5/2018	Queens	22-44	JACKSON AVENUE	0 The Size Safety Manager reported that while working a forty behaviory new building, a worker get his four the size of the size of the size of the size of the size was being formed at the second floor. The worker was taken to Einhurst Hospital by ambulance for treatmen The worker was alert and conscious as of the time that the ambulance arrived.				NB	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
6/2018	Brooklyn	1056	MANHATTAN AVENUE	1 A DOB inspector reported that during a support of execution operation, a welder was injured by a 12" X 12" boulder that fell from the support of exacavation walter. The welder was approximately four feet from the ground when he was thin in the shoulder by the boulder The welder was found consistent of university of the performed on the worker, but on internal injuries were found. An Aggregated Laws 2 EB work of the CFSWO was able issued for a support of excertaints (FSWO) was able issued for a support of excertaints in for review.	e ore ed	35336324N		NE	321211960	Material Fell	MANHATTAN EAGLE LLC	Empire management and const
6/2018	Manhattan	130	WILLIAM ST	0 1 The Site Safety Manager reported that two workers we hanging HVAC duct work when one of the workers los his balance and the duct work hit him in the head. The worker suffered a cut to his forehead. An ambulance w called						Other Construction Related Incidents		
6/2018	Manhattan	30	HUDSON YARD	0 1 The Site Safety Manager reported that a worker was moving a man lift when he ran over his own foot. The worker felt slight pain and went to see a medic.	No Dispatch				_	Other Construction Related Incidents		
/2018	Manhattan	25	PARK ROW	0 1 The Site Safety Manager reported that a concrete bug had stalled and rolled over the machine operator's foo while the operator was exiting the machine. The opera was transported to a local hospital.				NEW BUILDING	121190610-01-NB	Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	URBAN ATELIER GROUP LLC
7/2018	Brooklyn	11	HOYT STREET	0 1 The Site Safety Manager reported that a worker was using a circular saw when the saw kicked back and cu the worker's finger. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	
18/2018	Manhattan	315	PARK AVENUE SOUTH	1 Å DOB inspector reported that there were working on the ninth floor scaffolding at the exter working on the ninth floor scaffolding at the exter when a brick came off and hit a pedestrian hat was or the roadway at exposure two. The pedestrian was in stable condition, but may have possibly suffered two broken toes. The pedestrian was taken to a hospital. To pies scaffold was found to note fully adequately enclosed at the ends, with holes in some locations. Debris was not removed at the end of the shift as of the time of any enclosed at the ends, with holes in some locations. Debris was not removed at the end of the shift as of the safe of approximate level 2 violation for a failure to safeguard, me violation for a failure to safeguard, me violation for a failure to the stepping haltway, and office spaces. Three DOS Violations were also issued. A full filep Work Order (FSWO) was also issued. A fault she was and Methods for the safe continuatio of work must be provided.	or e d	35350784P / B9Y / 90L	081818BS05BG05/06/07			Other Construction Related Incidents	COLUMBIA REIT - 315 PARK AVENU	
20/2018	Manhattan	217	WEST 57 STREET	0 1 The Site Safety Manager reported that a worker was o twelve foot high 'A-Frame ladder on the twelfth floor performing dut work when he fell from the ladder and his head on a ramp. It is not known from what height the worker fail. The worker was conscious and afer ar was taken to Cornell Medical Center for treatment.	hit			NB	121328205	Worker Fell	SMITELL SPONSOR LLC	LENDLEASE(US)CONSTRUCTION



ncident Date		Address Number			EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/20/2018	Manhattan	540	WEST 53 STREET	0	1 A DOB inspector reported that a worker was doing exterior work at the second floor level at exposure one when he fell through the gap between the top deck of the sidewalk shed and the face of the building, landing on the ground floor. The worker possibly suffered a broken wrist and was taken to a hospital. The sidewalk shed deck was not tight to the structure, as there was a gap that was covered by a tary. Two ECB Violations were issued: one Aggravated Level 2 violation for a failure to asfeguard the public and property. due to the failure to	ECB Violation	35344820M - 35344821Y		NB	121191968	Worker Fell	CLINTON HOUSING DEVELOPMENT	Mega Contracting GP LLC
					sareguard us public an poperty, use in the matter to close the gap between the top deck of the sideralit she and the face of the building, and one violation for the performance of work that does not conform to the approved plans, as the scatfloid was not vertically and horizontally bed into the structure at every second frame Two partial Stop Work Orders (PSWO) were issued: one PSWO for exterior work from the sidewalk shed level, and a second PSWO for the use of a supported scatfold								
21/2018	Bronx	600	BERGEN AVENUE	0	1 A DOB inspector reported that a worker was stripping formwork at the foundation level when he was hit in the head by a piece of metal that lell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin Hospital, where he was treated for concusion. Two ECB Volations were issued: one Aggravated Level 2 volation for a failure to safeguard, and one violation for work that was not conforming to the approved pian, as the contractor was using phywod as formwork. A full Stop Work Order (FSWO) was issued for all astropping operations and for the rerection of concrete formwork. The contractor has been directed to bring Methods for the erection and removal of concrete form work must be provided.	a	35319497R		FO	220151869	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constroution & development
21/2018	Brooklyn	277	SOUTH 5 STREET	0	1 The Site Safety Manager reported that a woman tripped under the sidewalk shed at the job site. An ambulance was called. A DOB inspector was on site and issued an EOB Violation for a failure to safeguard, as there was a tripping hazard present between a fence and a tree. The woman tripped because there was no clear 5 waikway. DOB Violation was also issued.		35342748J	062118BS01KA01			Other Construction Related Incidents	HAVEMEYER OWNER LLC	
21/2018	Manhattan	115	DELANCEY STREET	0	1 A DOB inspector reported that a worker was working close to a temporary light that wasn't properly installed when he came too close and got shocked by live wire. The worker did not suffer any visual injuries, but was transported to a hospital. An ECE Violation was issued for a failure to maintain safe operations. A partial Stop Work Order (VPOV) was issued on work within ten feet of temporary lights. A Means and Methods must be provided.	ECB Violation	35316164P				Other Construction Related Incidents	NOT ON FILE	
1/2018	Manhattan	215	PEARL STREET	0	1 The Site Safety Manager reported that a worker was performing tile work when he cut his finger on a piece of tile. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	LAM PEARL STREET HOTEL LLC	
21/2018	Manhattan	316	WEST 88 STREET	0		No Dispatch					Other Construction Related Incidents	316 WEST 88TH ST, LLC	
21/2018	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that two workers were lifting a power trowel when one of the workers lost his grip, causing the power trowel to fall on his hand. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
22/2018	Manhattan	100	FRANKLIN STREET	0	The Site Safety Manager reported that a worker was using a drill to cut a hole in the wall when he slipped and cut his hand. The worker left the site and went to a City M D	No Dispatch					Other Construction Related Incidents	DDG 100 FRANKLIN LLC	
22/2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that a worker claimed to have tripped and fell during a plumbing inspection on the thirty second floor. The worker claimed to have faller around 11:00 AM, but did not report the incident until 2:00 PM. The worker went to urgent care.						Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
22/2018	Manhattan	315	EAST 46 STREET	0	 The Site Safety Manager reported that an electrician accidentally cut his left palm with a razor knife while cutting tubing. The worker went to see an off-site medic. 	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
22/2018	Manhattan	668	BROADWAY	0	1 The Site Safety Manager reported that a pedestrian tripped on an MTA steel plate that was on a pedestrian walkway. The godestrian suffered an injury to their left knee. A DOB inspector responded to the incident and visited the site and reported that the pedestrian walkway had a tripping hazard near the grating, which caused the pedestrian to the. The area was being repaired as of the time of inspector. An ECB Violation for a failure to safeguard was issued. A DOB Violation was also issued	ECB Violation	35345025H	082218BS02KA01			Other Construction Related Incidents	NOT ON FILE	
/23/2018	Brooklyn	243	4 AVENUE	0	1 The Site Safety Manager reported that a worker claimed that a piece of plywood fell on his right hand and bruised his knuckle. The worker went to urgent care for treatment.	No Dispatch					Other Construction Related Incidents	243 DEVELOPMENT LLC	



ident Date		Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/2018	Manhattan	180	BROOME STREET	0	1 The Site Safety Manager reported that a worker was performing stripping work on the second floor when his forearm was punctured by a piece of a nail. The worker was taken to Bellevue Hospital.	No Dispatch			NB - NEW BUILDING	121191110	Other Construction Related Incidents	SITE 4 DSA OWNER LLC	T.G. NICKEL & ASSOCIATES
2018	Brooklyn	535	4 AVENUE	0	1 The Site Safety Coordinator reported that a plumber wa using a cord drill on the second floor when he hit a piece of steel. The machine twisted and out the plumber's righ forearm. The worker was transported to a hospital by ambulance.	1			NB - NEW BUILDING	320626612	Other Construction Related Incidents	XYZ PROPERTIES INC	DYNATEC CONTRACTING INC
2018	Brooklyn	535	4 AVENUE	0	1 The Site Safety Manager reported that a worker was moving a ladder when he slipped on a piece of BX cable and fell. The worker sulfered an injury to his back. An ambulance was called.						Other Construction Related Incidents	XYZ PROPERTIES INC	
2018	Brooklyn	840	FULTON STREET	0	1 The New York City Fire Department reported that a worker fell down the stairs while carrying material. The worker was experiencing back pains and was transported to a hospital by EMS.	No Dispatch			NEW BUILDING	320596565-01-NB	Worker Fell	840 FULTON, LLC	TITAN REALTY & CONSTRUCTI
2018	Manhattan	110	CHARLTON STREET	0	1 The Site Safety Manager reported that a worker was moving a ladder when he knocked over a reshore that him him in his calve. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	
2018	Manhattan	264	WEST STREET	0	1 The Site Safety Manager reported that a worker was using a gas saw to cut a granite curb stone when the stone kicked back and lacerated his shoulder. EMS was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/2018	Manhatian	301	EAST 117 STREET	0	The Sile Safety Manager reported that a worker was changing position on a robar. The worker was harmass, and removed his harmess to be able to move to a different location. The worker misstepped, lef approximately six feet, and suffered injuries to his right man and leg. The worker was solurial aert and awake and was taken to Harlem Hospital for treatment. A DOB imspector responded to the inicident and visited the site and reported that there was no enforcement action necessary, as the incident occurred as the result of a worker's error.				NB	121190460	Worker Fell	AMP HOLDINGS LLC	TRANS COUNTY CORP
/2018	Brooklyn	170	BUFFALO AVENUE	O	1 A DOB inspector reported that an elevator worker claimed that he was struck by public harf fail from the eighth floor while he was was working on top of an elevator car at the sevent fillow. The worker was transported to a hospital, where he received one stich- and was released. The inspector observed an enclosed elevator core with block and core board from the cellar t the machine room with no performations at the machine room and no active work at other cars. No dehis or other materials were found at the top of the car and elevator pit. The inspector also found permits for timeproary work for the elevators that were current. No enforcement action was deemed necessary.	o r			A1 - ALTERATION TYPE 1	321482418	Material Fell	BUFFALO AVE. REALTY ASSOCIATES	CFSC MAINTENANCE, LLC
2018	Brooklyn	30	COLUMBIAHEIGHTS	0	1 The Site Safety manager reported that a worker was coming down from the bulkhead to the roof on a ladder while holding some objects. The worker missed a step and fell on his knee on the third rung of the ladder. The worker went home to see a doctor. It was not known what the worker was holding as he was coming down th ladder.				ALTERATION -1	321194346	Worker Fell		ARCHSTONE BUILDERS LLC
//2018	Manhattan	425	PARK AVENUE	D	A DOB inspector reported that during a stripping operation on the wall on the cellar floor, a panel of formwork that was approximately 4 X 3 poped out and his a worker. There was no Controllevel Access Zontan overhead operation was in prograss, which created a hazardous condition. Two ECB Violations were issued, one violation for the failure to maintain safety measures and one violation for a work platform that was improped rected. Two partial SAD Work Orders (FSWO) were issued: One for stripping operations, and one for the rection of work platform. The General Contractor is to provide a Means and Methods for the safe operation of the job.	,	35353478K, 79M		NEW BUILDING	121333921	Material Fell	T-C 425 PARK AVENUE, LLC	TISHMAN CONSTRUCTION CORP
/2018	Manhattan	553	WEST 30 STREET	0	1 The Site Safety Manager reported that an electrician tripped on a piece of plywood that was being used to cover a hole on the floor. The electrician injured his low back. An ambulance took the electrician to the hospital for a check up.				NEW BUILDING	121184208	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
2018	Bronx	2760	BRIGGS AVENUE	0	1 The Site Safety Manager reported that a worker had got his finger pinched between a scissor lift cage and a stee beam during the removal of fire retardant material. An ambulance was called.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	



ncident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
y/30/2018	Queens	81-10	135 STREET	0	1 A DOB inspector reported that while the double dock platform of an williple-fixed scattering that may not nop of a sidewaik shed was being assembled, the scaffold platforms folded and hit one of the workser secting the platform in his knees. The worker was taken to Jamaica Hospital, where it was reported that the worker did not suffer any broken bones. The worker was released from the hospital. The worker was necleased from Volations were issued: one violation for the failure to notify the Department Of Buildings of the installation of a supported scaffold, one violation for an installation that was contrary to the approved plan, one violation for failure to safeguard, and one violation for the subsence of guard rails and secure prime. Two partial Stop Work Orders (FSWO) were issued: one PSWO for the use of a supponded scaffold, and one PSWO for the use of a supponded scaffold.		36351752P, 36351753R,363351754Z, 36351755K		Air 1	429652387	Scatfold/Shed/Fence/ShoringInstallation	BRIARWOOD MP LLC	Pav-Lak Contracting Inc
3/31/2018	Brocklyn	2007	SURF AVENUE	0	1 A DOB inspector reported that while workers were assembling and securing a baker scaffold to a steel column, the baker scaffold was pushed by strong wind and struck a worker in the head. The worker was taken down from the building by the Work Ork (Tie) frie Department's semegancy team and transported to Cney Baker were found to have been in possession of a valid training card. An ECB Violation was issued for a failure to safeguard persons and propeny. A panital Stop Work Order (PSWO) was issued for the use of a baker scaffold. A Means and Methods must be provided.	ECB Violation	35351756M		Alt 2	340190046	Scaffold/Shed/Fence/Shoring/Installation	NYC HOUSING AUTHORITY	Forte Construction Corp
/31/2018	Manhattan	100	VARICK STREET	0	 The Site Safety Manager reported that a worker was unloading a shower glass panel when the glass broke and cut the worker's hand and knee. The worker went to urgent care. 	No Dispatch					Other Construction Related Incidents	BROOME PROPERTY OWNER JV LLC	
/31/2018	Manhattan	215	PEARL STREET	0		No Dispatch					Other Construction Related Incidents	LAM PEARL STREET HOTEL LLC	
/1/2018	Manhattan	540	MADISON AVENUE		O A DOB inspector reported that an electrician was working on a twenty-second floor and hooking up an air conditioning pump when the worker was electrocuted. The worker sourced to be injuries. Two ECB Violations were issued: one violation for after-hours wark being performed without an after-hours warkince, and one violation issued for a failure to safeguard. A full Stop Work Order (FSWO) and two DOB Violations were also issued. The Department Of Buildings' Electrical Unit performed a follow up inspection and reported that the electrician had failed to de-energize the electrical electrical while the work was in progress, and that there was an active permit for work between the twenty second and Wrenty fourth hors. The Electrical Unit din of issue a violation, because the incident was determined to have been caused by a wriker's error.	ECB Violation	35322957X, 35322958H	090118CERND01, 090118CERND02		M00048913	Other Construction Related Incidents	540 MADISON VENTURES LLC	
/4/2018	Manhattan	242	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker was stripping cauking from the windows on the cellar floor with a box cuting krife when the krife sipped and caused a cut to the worker's left arm. An ambulance transported the worker to a hospital for treatment	No Dispatch			NEW BUILDING	121185966	Other Construction Related Incidents	ROSELAND DEVELOPMENT ASSOCIATE	PAVARINI MCGOVERN LLC
4/2018	Queens	21-26	45 ROAD	0	1 The Site Safety Manager reported that a worker claimed to have fallen approximately six feet from a ladder. The worker suffered a shoulder injury. No one saw the worker fall. An ambulance was called.	No Dispatch					Other Construction Related Incidents	SALM PROPERTIES LLC	
5/2018	Manhattan	111	MURRAY STREET	0	1 The Site Safety Manager reported that a worker slipped while going down the stairs on the thirty-third floor. A DOB inspector responded to the incident and visited the site and determined that no enforcement action was necessary.	No Action Necessary					Worker Fell	NOT ON FILE	
/5/2018	Manhattan	301	EAST 81 STREET	0	The Siss alry Manager reported that a worker tripped and fell on rebar. The worker suffered an injury to his pinky finger and went to a hospital on his own. A DOB inspector visited the sits and determined at no enforcement action was necessary, as the incident was caused by a worker's enror. The inspector issued two caused by a worker's enror. The inspector issued two invisitent one worker's enror. The inspector issued two invisitent one worker's enror. The inspector issued to worker to envisite the state of the state of the state invisitent one work to be inspector worker worker of the presence of horizontal network flat was not in code compliance. A partial Stop Work Order (PSWO) was also issued, but not in relation to the incident.				NEW BUILDING.	122143377	Worker Fell	1562/1564 SECOND REALTY LLC	CM AND ASSOCIATES CONSTRU
/5/2018	Manhattan	514	WEST 24 STREET	0	The Site Safety Manager reported that an electrician was working on a pull box when he cut his finger by the edge of the box. The electrician panicked and called an ambulance	No Dispatch			NEW BUILDING	121186858	Other Construction Related Incidents	514 WEST 24TH OWNER LLC	JDS CONSTRUCTION GROUP*
/7/2018	Manhattan	138	EAST 50 STREET	0	1 The Site Safety Manager reported that a worker sat on a	No Dispatch			NEW BUILDING	121186028	Other Construction Related Incidents	50 LEX DEVELOPMENT LLC	TISHMAN CONSTRUCTION CORP



ncident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
12/2018	Brooklyn	714	39 STREET	Torking and the set of the s	DOB Violation se.		091218EX0704RV	Alteration	321481703	Excavation/Soil Work		Ground to sky city builders
/12/2018	Manhattan	113	WEST 24 STREET	0 1 The Site Safety Manager reported that a worker scratched his shin on rebar. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	LG CHELSEA LLC	
/12/2018	Manhattan	425	WEST 18 STREET	0 1 The Site Safety Manager reported that a worker was drilling in concrete when the tool jammed, spun atorunc and struct the worker above the eye. The worker went home for the day to see his doctor. The incident occur on September 12, 2018, but was not reported until September 13, 2018.	1,			NEW BUILDING	122736762	Other Construction Related Incidents	NOT ON FILE	ARTIMUS CONSTRUCTION INC
/13/2018	Brooklyn	198 A	KENT STREET	1 The Construction Superintendent reported that a work was performing carving work on a stucco when he was cut under his shin by a trowet. The worker was taken to hospital by ambulance for treatment.				NEW BUILDING.	320908201	Other Construction Related Incidents	KENT BUILDING DEVELOPMENT LLC	BROOKLYN B COMPANY GROUP
/14/2018	Manhattan	53	WEST 53 STREET	0 1 The Site Safety Manager reported that an iron worker pinched his finger by the choker while rigging a piece of metal. The on site medic treated the worker and sent th to urgent care.	of			NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/14/2018	Manhattan	228	EAST 20 STREET	In origin case. I The Construction Superintendent reported that a work field onto the fourth floor working platform from a height between the fitth and staff. Inco. The worker authened a broken albow and was taken to a hospital. The more than the staff of	5	35333294H	091418CNEGS01.	NEW BUILDING	121958480-01-NB	Worker Fell	NOT ON FILE	GRAMERCY SQUARE LLC
/14/2018	Manhattan	221	WEST 17 STREET	0 1 The Site Safety Manager reported that a worker was cutting a piece of sheet metal when he got a piece of metal in his eye. An anti-union was called to take the worker to a hospital for a check up.				ALTERATION-1	121186965	Other Construction Related Incidents	221 W. 17TH STREET, LLC	OTL ENTERPRISES LLC
/14/2018	Manhattan	1465	PARK AVENUE	I A DOB inspector reported that four workers were dragging a scaffolding frame that had planks on it whe one of the planks fell off off the scaffold and hit one off workers in the head. The worker was wearing his Personal Protection Equipment (PPE) and was in stab condition, but fell drazy. EMS was called and the work, was transported to a hospital. An EGB Violation was issued for the presence of un-secured equipment on a scaffold. A partial Stop Work. Order (SWO) was also issued.	he le ar	35351819K		NB	121191432	Scaffold/Shed/Fence/ShoringInstallation	LEX GARDENS II TP4 HOUSING DEV	Congress Builders LLC
/14/2018	Manhattan	138	EAST 50 STREET	1 The Site Safety Manager reported that a worker was walking towards a starway when he turned his head hit the threaded rod of a beach pulley system that was being used for a curtain wall installation. The worker suffered a curt to his head and was taken to a hospital ambulance for treatment.	nd			NEW BUILDING	121186028	Other Construction Related Incidents	50 LEX DEVELOPMENT LLC	TISHMAN CONSTRUCTION CORP
/14/2018	Manhattan	105	WEST 28 STREET	0 1 A DOB impector reportset that there were workers learning a concrete pump after concrete was pound onto the stairs on the first floor when pressure billing and a hose knocked one of the workers down. The worker was found conscious and was taken to a hospip by arributione. Three ECB Violations were issued: one violation for the failure to maintain safety measures, as safety orientation was not concluded before the concor- ding an adequate concrete washout box, and a third violatio for the failure to comply with the maindacture's specification, as an inspection of the concrete pump winch performed before it was used. Two partial Stop WC Orders (PWO) were issued on all concrete pump and pumping.	tal 5 a 5 a 19 5 9 9 1 1	355858581, 402, 41K		NEW BUILDING	121184529	Mechanical Construction Equipment	LSG 105 WEST 28TH LLC	FUNTLOCK CONSTR SERV LLC



cident Date		Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/2018	Brocklyn	422	FULTON STREET	0 1 A DOB inspector reported that a ductivork in the cellar factor for a the basement. The worker was conditioning unit and ella backwa consistentiations, but suffered a comparante conscious, but suffered a comparante and was taken to a hospit worker was not using a safety hincident, and there was no fail p ECR Violations were issued: on Contractor, and one to the Sub maintain safety measures. A paranter of the safety of the safety of the safety operation of Box Talks.	tanding on top of the air trik approximably seven The worker was found und fracture to his left I by ambulance. The mess at the time of the otecicion in place. Two to the General Contractor, for a failure to ail Stop Work Order Luct and air conditioning to provide a Maens and	35353393L, 94N		ALTERATION-1	320908899	Worker Feil	NOT ON FILE	TRANSPARENT CONSTRUCTION
4/2018	Brooklyn	138	WILLOUGHBY STREET	0 1 The Site Safety Manager report walking on a stripping floor when the worker's eye. The on-site m eye and sent him to a City M.D. worker returned to work.	dic cleaned the worker's			NEW BUILDING	321197085	Other Construction Related Incidents	NYC HPD	LEND LEASE (US) CONSTRUCT
14/2018	Bronx	988	EAST 180 STREET	0 1 A DOB inspector reported that is cart that was loaded with thirtee was overloaded and urbalances worker was styring to more it. Th injury to his left leg and was tak Violation was issued for the rurs A partial Jopy Work Corder (PSV General Contractor is to provide for sale material handlings with	, and toppled while the worker suffered an n to a hospital. An ECB de handling of materials. O) was also issued. The a Means and Methods	35350602P		NEW BUILDING	220152233	Material Fell	988 EAST 180 STREET HOUSING DE	MONADNOCK CONSTRUCTION IN
/2018	Manhattan	527	WEST 27 STREET	0 1 The Site Safety Manager report in his eye. The worker went to a	d that a worker got dust No Dispatch first med.			NEW BUILDING		Other Construction Related Incidents	WC 28 REALTY LLC	PIZZAROTTI LLC
/2018	Staten Island	546	GULF AVENUE	0 1 The Site Safety Manager report dismantling a baker scaffold wh pinched his foot. The worker wa	n a plank fell and			NEW BUILDING	520601968	Material Fell	STATEN ISLAND GLOBAL LOGISTIC	MATRIX CONSTRUCTION SERVI
7/2018	Staten Island	546	GULF AVENUE	0 11 A DOB inspector reported that a temporary barricades that were then tripped on non of the bolts ambulance was called to take the The inspector did not observe a in the are, and determined that a result of a worker's error. How was itsued for the removing of before the inspection was perfor	volted to the floor, and und hit his head. An worker to a hospital. In Additional to a hospital the incident occurred as aver, an ECB Violation the bolts from the area	35350841M		NEW BUILDING	520301968	Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	MATRIX CONSTRUCTION SERVI
/2018	Queens	22-18	JACKSON AVENUE	0 1 The Site Safety Manager report finger while cutting a pipe. The v care by taxi.	d that a plumber cut his No Dispatch rorker went to urgent			NEW BUILDING	420655838	Other Construction Related Incidents	22-12 JACKSON OWNER LLC	BRITT REALTY LLC
17/2018	Queens	195-06	111 AVENUE		4 in order to create an ar. The foundation wall b in the process of the property owner. The eee ECB Violations were to safeguard, one d without a DOB-issued presence of inadequate Order (FSWO) was					Material Fell	ADAM A PERRY	
17/2018	Manhattan	138	EAST 50 STREET	0 1 The Site Safety Manager report forearm while using a box cuttin to urgent care and will return to	d that a worker cut his knife. The worker went vork.					Other Construction Related Incidents	50 LEX DEVELOPMENT LLC	TISHMAN CONSTRUCTION CORP
7/2018	Brooklyn	266	KENT AVENUE	0 2 A DOB inspector reported that is operation pressure had ball up operation pressure had ball up workers. One of the two workers of the worker end of the sector worker remained on sets. Issued one violation for the fail measures during pumping operation of the sector worker to the manufacturer's s Stop Work Order (PSWO) was a stop of the Vorker of the Vorker (PSWO) was a sector violation of the sector of the Vorker of the Vorke	inside of a hose, knock down two went to a hospital; the wo ECB Violations were et to maintain safety titons, as the pump was caused the incident, and a concrete pump ecifications. A partial	35316269L, 70Z		NEW BUILDING	320916407	Mechanical Construction Equipment	260 KENT LLC	260 KENT CONSTRUCTION LLC



ncident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
17/2018	Brooklyn	123	MELROSE STREET	0 2 2.4 COB impector reported that workers were using a pallet jack to move a component of a bolicy unit inside the bolier room on the root. The component was approximately 4.4 X 2 and 7 high. Balance was lost, an inter component of the bolier unit failed one onto two workers. One worker suffered a shoulder imury, and the second worker suffered a broken lag. Two ECB Violations were issued on violation for a failure to safeguard persons and propent affected by construction operation for the hazardous conditions of the jack of the partial Stop Work Order (PSWO) was also issued.	ECB Violation f	353162267H, 68J		NEW BUILDING	320717140	Material Fell	EVERGREENS GARDENS I LLC	BROOKLYN GC, LLC
18/2018	Bronx	2028	CRESTON AVENUE	1 A DOB inspector reported that while in the processing of diamanting an actinic personal hold; the worker went on top of a holds can that was all grade level to close the latch of the hatch door. The worker fell from the holds at suffred an input yo bia section. The worker had his safety harmess on, but was not tied off. Four ECB Violations were issued, two violations (one to the General Centrator), one to the holds to grade the holds of the protection y statem, the violation for the tensoring of an original solution (one to the denormal control of the protection) and evolution to the service grade grade and an affective fail protection system, one violation for the protection grade and one violation for the presence of an affective grade and a part off the leading edge was also issued.	nd e	35360606M, 07Y, 08X, 09H.		NEW BUILDING	220392868	Worker Fell	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MNGMT
18/2018	Manhattan	545	WEST 30 STREET	1 A DOB inspector reported that a worker was moving pipes from a rack when the pipes rolled over and hit the worker in his eye. The worker was trasted by the on-sit medic before being sent to urgent care. The incident occurred on September 19, 2018. Liv tans not reported until September 19, 2018. This incident, as well as incident Number 2574. Said Incident Number 26744, all these incidents, an ECB Violation was insued for the unsafe handing or materials. A partial Soly Work Order (PSWO) was issued on all material handling, including deliveries. The General Contractor is to provide a Mara and Methods, with a Tool Box Talk, for safe material handling and the safe operation of the job.	5 5 6	35366613R		ALTERATION-1	121192397	Matorial Fell	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
8/2018	Manhattan	590	EAST 83 STREET	0 1 The Site Safety Manager reported that a worker was working on an "X-Frame ladder when he missed a step and field from the ladder. The worker auflered an injury t his leg. The worker walked down and his foreman took him to upgent care for a check up.				NEW BUILDING	121190987	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
18/2018	Staten Island	546	GULF AVENUE	0 1 The Site Safety Manager reported that an electrician we installing an electric sign when he received a shock. Th electrician went with a co-worker to urgent care for a check up.	as No Dispatch e			NEW BUILDING	520301968	Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	MATRIX CONSTRUCTION SERVI
19/2018	Manhattan	550	WEST 34 STREET	The Site Safety Manager reported that a worker was walking through an area where concrete was pound th previous day when he timped on a pice of form work. The worker did not fall, but he hit his head on form work The worker walked to the on-site medic, and the on-site medic sent the worker to a hospital for evaluation.	e 			NEW BUILDING	121184841	Other Construction Related Incidents	ONE HUDSON YARDS OWNER LLC	GILBANE BUILDING COMPANY
19/2018	Manhattan	545	WEST 30 STREET	The Site Safety Manager, and a DOB inspector, report that a worker was out his finger while cutting sheet tock. The worker went to urgent care. This incident, as well a locident Number 26742 and Incident Number 26743, all occurred during the same job. In response to all three or these incidents, an ECB Violation was issued for the unsafe handing of meterials. A partial Soly Work Order (PSWO) was issued on all material handling, including deliveries. The General Contractor is to provide a Maar and Methods, with a Tool Box Taik, for safe material handling and the safe operation of the job.	s l f			ALTERATION-1	121192397	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
19/2018	Manhattan	545	WEST 30 STREET	ADDB inspector reported that a worker's left index fing gct pinched while loading materials. The worker was treated by the on-site medic, and the medic then sent it worker to urgent care. This incident, as well as incident Number 25/42 and incident Number 25/44. all occurs during the same job. In response to all three of these handling of materials. A partial Stop Work Order (PSW) was issued on all material handling, including deliveres The General Contractor is o provide a Neans and Methods, with a Tool Box Talk, for safe material handling and the safe operation of the job.	ne d D)			ALTERATION-1	121192397	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC



ncident Date		Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
19/2018	Manhattan	525	WEST 122 STREET	0	1 A DOB inspector reported that a worker was holding, by hand, at VA section of prelabinized form work fiel place when the section of prelabinized form work fiel onto the worker. The worker suffered a laceration to his head and was examined by an on-site medical facility. The worker was then escorted to a local urgent care center. An ECB Violation was issued for a failure to safeguard. A partial Skp Work Order (PSWO) was issued for the area where the incident occurred. A DOB Violation was also issued.		35355256Y	091918CERJMO1	NEW BUILDING	121191628-01-NB	Other Construction Related Incidents	WEST 122ND STREET PROPERTY INV	Pinnacle Contracing
19/2018	Manhattan	110	UNIVERSITY PLACE	0	1 The Site Safety Manager reported that a worker suffered a cut to his right finger while picking up a bundle of metal. The worker walked to an urgent care center for treatment.	I No Dispatch			NEW BUILDING	121187241	Other Construction Related Incidents	NOT ON FILE	CNY CONSTRUCTION LLC
20/2018	Brooklyn	3514	SURF AVENUE	0	1 The Site Safety Manager reported that a delivery truck was entering the site when it ran over the foot of the flagman. The flagman suffered a minor injury. An ambulance was called.	No Dispatch					Other Construction Related Incidents	RED APPLE SURF REALTY III LLC	
/20/2018	Manhatlan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was doing form work on the sixth four of each when the worker slipped and fell about three feet into a beam pocket. The worker hit his back. An ambulance was called. A DOB inspector responded to the incident and visited the site and issued an ECS Violation for a failure to maintain safety measures. A partial Stop Work Order (PSWO) an a DOB Violation were also issued. The General Contractor is to provide a Means and Methods for the covering of beam pockets during form work operations.	3	353506111 failure to provide safety measures	092018ce10vp01			Worker Fell	HARLEM URBAN DVLPMNTCP	
21/2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that workers were loading windows on an 'A'-Frame at the loading dock when a window sild and a worker got his hand caught between windows. The worker suffered a cut to his hand and went to a hospital for treatment.				NB	121190219	Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	LEND LEASE (US) CONSTRUCT
21/2018	Manhattan	161	MAIDEN LANE	0	1 A DOB inspector reported that during a material deliven at the thirty-ninth floor, a pallet of cernent on a floor jack was accidentally lowered onto another worker's hand. The injured worker's finger was swollen, and the injured worker went to a hospital with another worker to have x- rays performed on his finger. The inspector reported that he incident occurred due to a miscommunication between a worker that was installing 27 x4 cribing and worker that was installing 27 x4 cribing and but worker that was installing 27 x4 cribing and between a worker that was installing 27 x4 cribing and worker that was installing 27 x4 cribing and thirty-inith floor and no hazardous conditions were observed. No enforcement action was deemed necessary.	t			NEW BUILDING	121185680-01-NB	Other Construction Related Incidents	FPG MAIDEN LANE, LLC	PIZZAROTTI LLC
21/2018	Manhattan	115	DELANCEY STREET	0	1 The Site Safety Manager reported that a worker in the sub-cellar tripped and suffered a cut to his left arm. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
21/2018	Manhattan	100	EAST END AVENUE	0	¹ A DOB inspector reported that during a stain installator at the trinh toor level, a state inprovader that was approximately 0.5° X 0.5° X2 fell from the ternh floor an struck a worker that was on the sixth floor set back. The struck worker complained of back pain and was taken to a hospital by ambulance. A controlled access zone was not provided to prevent work from being performed at this stath floor set back and the ternh floor perimeter at the same time. An ECB Violation was issued for a failure to maintain safety measures at the job site. A partial Stop Work Order (PSWO) and a DOB Violation were also issued.	d e	35350614m	092118ce08vp01			Other Construction Related Incidents	THE CHAPIN SCHOOL LTD	
/24/2018	Manhattan	147	EAST 86 STREET	0	1 The Site Safety Manager reported that a brick layer dropped a concrete masonry unit (CMU) on his hand. The tip of the brick layer's hand was severed. The brick layer was transported to a local hospital by the job foreman.				NEW BUILDING	122668648-01-NB	Other Construction Related Incidents	NOT ON FILE	GILBANE RESIDENTIAL CONST



cident Date	Borough	Address Number	r Street	Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
ident Date	Brough Bronx	Address Number 2365	r Street HOFFMAN STREET	Fatalities Injurie	EOC Final Description 1 A DOB inspector reported that a worker was standing on loose dir while collecting delate when the pile of dir metric, which the collecting delate worker was standing on the standing of the standing of the standing of the standing of the metric of the standing worker worker with the standing of the standing of the standing of the standing of the standing of the standing of the standing of the violation for the presence of the standing of the work standing of violation for the presence of the standing of the work standing of the standing of the standing of the standing of the work standing of the violation for the presence of the standing of the work standing of the work standing of the standing of the work standing the pice.		ECB Violation Numbers 35316196N, 99P, 35353130J, 31L, 32N, 33P, 34R & 35	DOB Violation Numbers	Permit DEMOLITION	Permit No 220582029	Incident Type Worker Fell	Owner's Name HOFFMAN PROPERTIES NY LLC	Contractor Name KING DEMOLITION SERVICES
26/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	1 The Construction Superintendent reported that a worker field of d a six foot 1-5-frame ladder. The worker suffered pain to his hack and anke, and wave taken to a hospital by amultance. A DOB imspector response to the incident and reported that the incident occurred as the result of a worker's error. No enforcement action was necessary.				NB	320622894	Worker Fell	ATLANTIC 2844, LLC	Cauldwell Wingste co. llc.
/2018	Manhattan	12	EAST 48 STREET	0	1 The Site Safety Manager reported that a worker was passing a piece of plywood to another worker when the plywood silpeed out of his hand and struck the worker on the nose. A co-worker took the struck worker to a clinic. The worker received treatment and then returned to work. The incident occurred on Thursday, September 27, 2018, but was not reported until Friday, September 28, 2018.				NEW BUILDING	121190816	Material Fell	1248 ASSOCIATES LLC	ANTHONY T. RINALDI LLC
2018	Manhattan	25	PARK ROW	0	1 The Site Safety Manager reported that a worker dislocated his shoulder while lifting a bundle of insulation. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	
2018	Queens	148-10	ARCHER AVENUE	0	The Site Safety Manager reported that a worker hurt his finger while loading shores onto racks. The worker was driven to a first med.	No Dispatch			NEW BUILDING	420654517-01-NB	Other Construction Related Incidents	BRP JAMSTA TWO TC OWNER LLC	CNY CONSTRUCTION LLC
/2018	Manhattan	108	LEONARD STREET	0					ALTERATION-1	121185831	Other Construction Related Incidents	CIVIC CENTER COMMUNITY GROUP B	NEW LINE STRUCTURES & DEV
3/2018	Manhattan	11	GREENE STREET	0	1 The Site Safety Manager reported that an iron worker was shaking out 0-Decking when he stepped back and fail from the filt floor 0-Deck to the fourth floor concrete floor. The worker was found bleeding from his head, but was conscious. An ambulance was on site. A DOB inspector resorded to the incident and visited the site and issued an EOB Violation or a faile to safeguard. A full Stop Work Order (FSWO) and a DOB Violation will be liasued, one violation for the presence of indequate puperty, one violation for the presence of adequate puterty in the violation for the presence of adequate puterty in the violation for the presence of use President Protection (PPE) while working on the fifth floor Q-Deck.		36366652J	092818CE02MA01			Worker Fell	335 CANAL STREET	
8/2018	Manhattan	685	1 AVENUE	0	1 The Site Safety Manager reported that a worker hurt his back while picking up materials. The worker was taken to a hospital by a co-worker. An ambulance was not called.						Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
/2018	Manhattan	500	WEST 33 STREET	0	The Site Safety Manager reported that a worker was carrying material when he slipped and suffered an arm injury. The worker was taken to a hospital.	No Dispatch			NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
0/2018	Manhattan	15	EAST 30 STREET	0	1 The Site Safety Manager reported that a worker was inserting a fastening pin when he hit his hand with a hammer. The worker was transported to a local hospital by a co-worker.	No Dispatch			NEW BUILDING	122128679	Other Construction Related Incidents	MADISON 30 31 OWNER LLC	RC STRUCTURES INC