

cident Date	Borough	Address Numbe	r Street	Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2018	Manhattan	13	EAST 7 STREET	0	1 The New York City Police Department reported that an exterminator fell into a six for deep excavation in the basement. A DOB inspector reported that the worker Hospital and that there was unpermitted excavation work being performed in the basement. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard and work without a permit. A full Stop Work Order was issued.	ECB Violation	35309613X		No Permit	No Permit	Worker Feil	TRIAD CAPITAL, LLC	No Permit
2018	Manhattan	269		0	1 The Site Safety Manager reported that a worker was cleaning a platform from a multipoint scaffold when he slipped and fell five feet onto the ground, hitting his right elbow. An ambulance was on site. Four ECB Violations and a partial Stop Work Order were issued.		35285606Y, 35285607X, 35285608H, 35285609J				Worker Fell	RIVERVIEW OPERATING CO., LLC	Leeding Builders Group LLC
3/2018	Manhattan	430	EAST 58 STREET	0	1 The Site Safety Manager reported that a worker got his hand stuck between a steel plate and a frame and got two of his fingers crushed. The worker was sent to Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	SUTTON 58 HOLDING COMPANY LLC	
/2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that a worker was loading garbage into a truck when he slipped on snow and hurt his arm. The worker walked to urgent care.	No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
/2018	Manhattan	301	FREEDOM PLACE SOUTH	0	<ol> <li>The Site Safety Coordinator reported that a worker was unloading glass from a crate when a piece of glass fell and injured his leg. The worker was taken to a hospital. The extent of the worker's injuries was not known.</li> </ol>	No Dispatch			NEW BUILDING	121192501-01-NB	Worker Fell	301 FREEDOM PLACE SOUTH, LLC	SCIAME CONSTRUCTION LLC
2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker on the wenny fourth topo slipped on a patch of ice and hun his shoulder. An ambulance was called to the site. A DOB impector responded to the incident and reported that diamond plates on the outside of a hoist had water and ice on them, which caused the worker to site. An ECB Violation and a DOB Violation were issued.	ECB Violation	35301051R	010818BS02DH03			Worker Fell	G & M REALTY, LP.	
2018	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that a worker slipped on a second floor concrete deck, landed on his back, and hurt his shoulder. The worker slipped because of snow. The worker walked to a City MD. A DDB inspector visited the site and confirmed that the deck was covered with snow, which caused the worker to fall. An ECB Violation, a DDB Violation, and a partial Stop Work Order were issued.	r	35301164N	010918BS02VP01			Worker Fell	40-56 TENTH OWNER LLC	
2018	Manhattan	400	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was handing down a screw-jack to another worker when the acrew-jack siteped out of his hands and hit the other worker. The worker suffered a minor injury and went to a hospital by analutance for a check up, A DOB inspector issued an EOB Violation, a DOB Violaton, and a pantial Step Viola Order.		35301055Y	010918BS04DH03			Material Fell	BOP NE LLC	
0/2018	Staten Island	55	RICHMOND TERRACE	0	1 The Site Safety Manager reported that a worker slipped on ice. An ambulance was called. A DOB inspector reported that the worker slipped on ice that was located in an area that was closed off and where there was no work in progress. No enforcement action necessary.	No Action Necessary					Worker Fell	ST. GEORGE OUTLET DEV LLC	
/2018	Queens	27-17	42 ROAD	0	1 The Side Safety Manager reported that a worker was installing sheet rock when he cut his left hand on a metal duct. The worker went to urgent care with another worker	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
0/2018	Manhattan	130	EAST 82 STREET	0	1 The Site Safety Coordinator reported that an electrician was pulling cables in a box when he pulled his hand back and cut it on a piece of Chicago Bar. The incident occurred on 1/10/2018, but was not reported until 1/11/2018. The worker went to a doctor on his own.	No Dispatch			NEW BUILDING	121328027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
0/2018	Manhattan	118	FULTON STREET	0	1 A DOB inspector reported that a worker attempted to move an 'A'-Frame cart that was loaded with about twenty flat stock metal sheets when the metal sheets fell onto his leg. The worker may have possibly suffered a broken leg. An ENT was on site. An EOS Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Methods for safe operations.		35300526R				Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	
1/2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager and a DOB inspector reported that a cargenter was standing on an "A" Frame ladder to remove the door frame form an electrical closed on the 51st floor when a piece of plywood that was behind the door frame cannel ioses and hit him in the shoulder, causing him to fail off of the ladder. The worker boxpilal by antiubance. A DOB inspector reported that there were no unsafe or hazardous conditions at the working area. No enforcement action was necessary.	No Action Necessary			New Building	121333440	Worker Fell	CP V TS FULTON OWNER, LLC	CP V TS FULTON OWNER LLC
1/2018	Manhattan	151	MAIDEN LANE	0	1 A DOB inspector reported that a worker was using an "A"-Frame cart to move scaffolding elements when he wristed his wrist while pulling the cart. The worker did not want to go in an ambulance and went to see a doctor on his own. There were no unsafe of hazardous conditions at the work area. No enforcement action was necessary.	No Action Necessary			New Building	121186769	Other Construction Related Incidents	151 MAIDEN LLC	PIZZAROTTI IBC LLC



cident Date	Borough	Address Number	r Street	Fatalities Injurior	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/2018	Manhattan	305	EAST 61 STREET	0	1 The Site Safety Manager reported that a worker tripped			DOD VIOLATION NUMBERS	Fernit	r erinic No	Worker Fell	305 EAST 61ST STREET GROUP LLC	
					over a board that was on the floor and twisted his right ankle. An ambulance was called to the site and took the								
2018	Manhattan	10	WEST 33 STREET		worker to a hospital. 1 The Site Safety Manager reported that a pedestrian	ECB Violation	35300326M	011118BS05MA03			Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	
010	Wannattan	42	WEST 33 STREET	0	stepped on a piece of plywood under the upper sidewalk		35300326W	UTTTIBBSUSINAUS			Other Construction Related incidents	38-46 WEST 33 STREET, ELG	
					and slipped, injuring his right ankle. The pedestrian went	:							
					to see a doctor on his own. An ECB Violation was issued								
018	Queens	27-13	21 STREET	0	1 The Site Safety Manager reported that a carpenter was	No Dispatch			NEW BUILDING	420993740	Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	DISANO DEMOLITION CO, INC
2010	Goons	27.10	21 Office 1		hitting a nail when the nail popped out and hit the worker				inclu bolebillo	420000140			biorito belioenton oo, ito
					in the face. The worker has no visible cut or injuries. An ambulance transported the worker to a hospital for a								
					check up.								
2018	Manhattan	45	PARK PLACE	0	1 The Site Safety Manager reported that a worker was	ECB Violation	35263168X	011218CERMR01	NEW BUILDING	121185635-01-NB	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
					pumping concrete into a wheelbarrow when the concrete pump shifted and snagged his finger between the pump	1							
					clamp and the concrete cleaning basin, causing a large								
					cut. The worker was taken to a hospital. A DOB inspector reported that according to the inspection of the								
					logs, the injured worker did not attend the concrete pre-								
					pump meeting and did not know why he was part of the operations. An Aggravated 2 ECB Violation, a DOB								
					Violation, and a partial Stop Work Order were issued.								
2018	Manhattan	590	EAST 83 STREET	0	1 The Site Safety Manager repoted that a worker was	ECB Violation	35294740J	011518CERFC01	Alt 1 NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
					performing waterproofing work inside of a high concrete tank. When the worker was using a chemical sealant to								
					waterproof the inside of the tank, he became								
					overwhelmed by the fumes and passed out. The worker was taken to a hospital by an amulance. An ECB								
					Violation, a DOB Violation, and a partial Stop Work								
					Order were issued.								
/2018	Manhattan	53	WEST 53 STREET	0	<ol> <li>The Site Safety Manager reported that a worker pulled his groin while lifting a pipe. The worker went to a</li> </ol>	No Dispatch			alt 1 NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LEND LEASE (US) CONSTRUCT
					MedRite.								
2018	Manhattan	130	EAST 82 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch			alt 1 NB	121325027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
					cutting a piece of aluminum with a saw when the aluminum got caught in the saw and pierced his hand.								
					The worker took a cab to a hospital.								
2018	Brooklyn	179	THROOP AVENUE	0	1 The Site Safety Manager reported that a worker was unloading a piece of pipe scaffold off of a truck when he	No Dispatch					Other Construction Related Incidents	NYC HHC	
					lost control of the piece and the section fell onto his left								
					leg. The worker was taken to a hospital by a friend.								
/2018	Manhattan	125	GREENWICH STREET	0	<ol> <li>The Site Safety Manager reported that a piece of plywood fell onto a worker's hand during a stripping</li> </ol>	ECB Violation	35300553M				Other Construction Related Incidents	VS 125 LLC	
					operation. There were two workers working one above								
					the other, and the piece of plywood fell from above onto the worker below. An ambulance was called, An ECB								
					Violation and a partial Stop Work Order were issued.								
					The General Contractor at the site is to provide a Means and Methods.								
					and wethous.								
/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that an iron worker	No Dispatch			NEW BUILDING	121186849	Mechanical Construction Equipment	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
		-			was using a grinder to cut a piece of metal bar when the								
					grinder kicked back and caused a cut to the worker's thumb. The grinder had all of its safety guards in place.								
					The worker went to an urgent care facility for treatment.								
2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NEW BUILDING	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
					unpacking windows from a crate and was using a 2 X 4 piece of wood as a lever to move the crate when the								
					piece of wood snapped and hit him in the head, causing								
					a scratch. An ambulance was called and the worker walked to the ambulance to go for a check up.								
					and a second and a second go for a check up.								
/2018	Brooklyn	1601	KINGS HIGHWAY	0	2 A DOB inspector reported that a vehicle struck a manlift	ECB Violation	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
					with two workers in it that was parked in an occupied								
					lane. The yodocks were not filled with water and a flagger was not present. The manlift was not damaged,								
					but one of the workers complained of leg pain, and the								
					other worker was shook up by the incident. Both of the workers were sent to a hospital for a check up. An ECB								
					Violation and a partial Stop Work Order were issued.								
2018	Manhattan	000	AMSTERDAM AVENUE			500 10 10	3530559M 353055		ND	122887224		AMSTERDAM AVENUE REDEVELOPMEN	
2018	wanhattan	200	AMSTERDAM AVENUE	0	1 The Site Safety Manager reported that a worker was unhooking the chain from an excavator that was lifting	ECB Violation	3530559M 353055		NB	122887224	Mechanical Construction Equipment	AMSTERDAM AVENUE REDEVELOPMEN	Marc Depaul
					oxygen tanks when his gloves got stuck between the								
					chain and the excavator's hook, pinching the worker's finger. The worker was taken to a hospital by a co-								
					worker. Two ECB Violations and a full Stop Work Order								
					were issued. The contractor at the site was directed by a	1							
					DOB inspector to provide a Means and Methods to perform lifting operations.								
018	Manhattan	650	5 AVENUE	0	1 The Site Safety Manager reported that a flagger was	No Dispatch					Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
					almost struck by a vehicle in the middle of the street and								
					that he twisted his right ankle while moving out of the way. The flagger went to a hospital.								



ident Date		Address Number	Street	Fatalities In	juries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	445	WEST 35 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	CARE REALTY CORP.	
					moving a wooden plank while taking down a single frame scaffold when he twisted his knee and complained of pain. The worker went to see a doctor his own.	on							
018	Brooklyn	3003	WEST 21 STREET	0	1 The Site Safety Manager reported that a worker twiste	d No Dispatch					Other Construction Related Incidents	CONCERN SURF VETS PLACE HOUSIN	
.010	DIOURIYI	3003	WESTZTSINEET		her ankle while pushing a mini-dumpster. An ambular was called and took the worker to a hospital.	ice							
018	Brooklyn	19	KENT AVENUE	0	1 The Site Safety Manager reported that a worker was	ECB Violation	3505625p, 26r, 27z, 28k, 29m		CRANE NOTICE	871 17	Mechanical Construction Equipment	19 KENT ACQUISITION LLC	ALL ISLAN MASONRY & CONCRETE
					setting up a mobile crane when his finger got pinched between the hook of the crane and a road barrier, causing the finger to detach. A co-worker took him to hospital. Five ECB Violations and a partial Stop Work Order were issued.	a							
018	Bronx	16	EAST 204 STREET	0	1 The Site Safety Manager reported that a worker slippe	ed No Dispatch					Worker Fell	HP VILLA GARDENS HDFC, INC.	
					and hurt his back at the job site. An ambulance was called and took the worker to a hospital.								
2018	Manhattan	26	ANN STREET	0	<ol> <li>The Site Safety Manager reported that a worker hurt hand while taping and spackling on the ninteenth floo The worker went to urgent care.</li> </ol>	nis No Dispatch r.					Worker Fell	143 FULTON STREET DEVELOPMENT	
2018	Queens	29-22	NORTHERN BOULEVARD	0	1 A DOB inspector reported that a worker was pushing "A"-Fame car that was backed with store when the c overturned, causing stone to fall onto the worker's foc and possibly breaking the Foc. An EMT was on site. J ECB Violation and a partial Stop Work order were issued. The General Contractor is to provide a Means and Methods and a Tool Box Taik.	art t An	35289063P				Material Fell	OSB NORTHERN LLC	
2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a work	er No Dispatch			ALTERATION TYPE 1	321185953-01-AL	Worker Fell	THE SALVATION ARMY	SD BUILDERS AND CONSTRUCT
					cut his finger while cutting a piece of rebar. EMS was called. The worker was found conscious and was take to an area hospital.	an							
2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NYC HPD	
					doing form work with while he had his peligan hook attached to himself. When the worker was climbing down a ladder, the peligan hook fell and hit his right en- The worker went to a City MD. An ambulance was no called. This incident was the result of a worker error.	É .							
/2018	Manhattan	111	EAST 24 STREET	1	0 A DOB inspector reported that an elevator foreman we working on a platform for installing an elevator inside elevator shaft at the sixth floor when the platform start, and thing upwards uncontrollably and would not stop. Th worker thied to jump to the machine room on the other platform at the minih floor. Use the fell backwards down injuries. The elevator foreman dd not have a safety harmess on and was not tell on anything. There were safety lines found at the site. A DOB Volation and a f Stop Work. Order were issued.	the ted is		0123188505018G	NB	121192798	Worker Fell	DEMETRIOS & FANIA SAMUEL, LLC	TRINITY BUILDERS INC
2018	Queens	62-98	SAUNDERS STREET	1	O The New York Chy Polica Department reported that a worker was standing on a window all of a sich floor. The worker was transported to North Showe University Hospital, but was found dead on arrival by the YVPD- DOB inspector inspected the site and reported that th was work present that consisted of a gut renovation to the bathroom, the installation of new destrictal wining and box, and the installation of new sheetrical wining and box, and the installation of new both the Sheetrock, withou permit. Two ECB Violations, two DOB Violations, and Stop Work. Order were issued.	nd. A ere o	35308671J, 35308670H	012318CERTQ01, 02			Worker Fell	NOT ON FILE	
2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker got concrete in his eyes during a concrete pour operation The worker went to a hospital and returned to work.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
/2018	Manhatlan	280	PARK AVENUE	0	1 The Construction Superintendent reported that an electrician was working on a live spite box when he was shocked and gott wor of his fingers burned. The worker went to a hospital. This incident took place on January 24, 2018, but the Department Of Buildings w not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed withou permit. A DOB Violation was also issued.	as	35312686Y	012918EE106FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
\$/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reports that a flagger was directing traffic when he was side-swiped by a vehicle	No Dispatch					Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	
					The driver did not want to listen to the flagger. The flagger was okay, but was taken to a hospital by an ambulance for a checkup.								
2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that a worker was cutting rebar when he slipped and cut his finger. The worker drove himself to a first med for precaution.	No Dispatch			ALTERATION TYPE 1	121333413-01-AL	Worker Fell	NOT ON FILE	CNY CONSTRUCTION LLC
/2018	Manhattan	102	West 188 Street	0	1 A DOB inspector reported that a worker was climbing	up ECB Violation	35310351n		ALT	122917503	Worker Fell		allba services
		102			In Code inspection reporties that are indicer was unitneed in an X-rapeautor reporties that the first floor to the second floor when a rung on the ladder snapped, causing the worker to fail ten feet and land on his back. The work was found conscious and was taken to the hospital by EMT personnel. An CEG Violation and a full Stop Wo Order were issued. The site will received a full audit d to site conditions.	ər / rk							



cident Date		Address Numbe	r Street	Fatalities Injuri	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	44	UNION SQUARE	0	1 The Site Safety Manager reported that a worker at a concrete truck had a miscommunication with the driver and the shoot came down and hit the worker on the hand. The worker suffered a minor injury and an	No Dispatch					Other Construction Related Incidents	READING TAMMANY OWNER LLC	
					ambulance was called.								
6/2018	Manhattan	450	WEST 33 STREET	0	A DOB inspector reported that during a demolition operation on the first floor of the HVAC conduits and utilities lines, a construction worker was cleaning demolition dehicin on the first floor when a pipe section fell approximately four fleet and hit the worker in the head. The pipe section influences another worker out a strap pipe that was holding the pipe section. The worker who was hit by the pipe section. The worker who was hit by the pipe section influences medical attention, but wasn't feeling well after a few mounter who wasn't feeling well after a few hours and called EMS. The worker was taken to a hospital by ambulance. A Construction Superintendent was not required at the site. An EDB Violation and a full Stop Work Order were issued. The General Contractor must provide a Means and Methods for the demolition o the remaining HVAC conduits.		35310356M		Alteration 2	140188767	Material Fell	450 PARTNERS LLC	Tishman Construction Corp
27/2018	Manhattan	500	WEST 33 STREET	0	1 A DOB inspector reported that an electrician was in the process of erecting a shanty while climbing an eight foot ladder when he missed a rung of the ladder and fell three feet. The worker was taken to Bellevue Hospital. A DOB inspector visited the site and reported that no enforcement action was deemed necessary.				NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
29/2018	Brooklyn	404	11 STREET	0	<sup>1</sup> A DOB inspector reported that workers were receiving a basd of operative manopy mult (GNU) brick on the third floor when the third floor d-bists towards the rear of a new extension partially collapsed the te accessive weigh and because the C-Joints were not properly secured to the CMU wark. The collapse alto caused the second and first floors to collapse into the cellar. One worker sustained minor inpires and ware staken to Brooklym Presbyterian Hospital. An Aggravated Level 2 ECB Violation and a full Stop Work. Order were issued for a failure to safeguard. A sidewalk shed has been requested to be immediately installed at exposure four. DOB will remain on site until the sidewalk shed is installed. The side will be referring to DOB's Interior Demolition Engineering Unit for audit and approval of all temprary shoring.		35310456N		Alteration	321190858	Other Construction Related Incidents	404 11TH ST NY CORP	SUN SUN Contracting
9/2018	Brooklyn	422	FULTON STREET	0	The Site Safety Manager reported that a worker fail through the interior oppning port to tweer crane installation from the ninh floor to the eighth floor. The worker was taken to a hooginal, where he was eventually released with no injuries. The worker did attend a safety orientation meeting at the start of his shift. A DOB inspector visited the site and reported that there was proper signage and a proper guardial system present at the perimeter of the slate opening, but that the worker darseguirded at slately measures provided to prevent failing hazards. No enforcement action was necessary.						Worker Fell	NOT ON FILE	
/2018	Manhattan	209	EAST 19 STREET	0	The Site Safety Manager reported that a worker was using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.	No Dispatch			ALTERATION TYPE 1	121724946-01-AL	Worker Fell	227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
0/2018	Manhattan	500	WEST 33 STREET	0	<ol> <li>The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An ambulance was called</li> </ol>	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
30/2018	Manhattan	20	BROAD STREET	0	The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
31/2018	Brooklyn	138	WILLOUGHBY STREET	0	<sup>1</sup> A Deciration of the second state of the vertices was installing. Dem works at the second flow for a find was installing. Dem works at the second flow for a find second works, holding him in place while he was installing a clamp. While securing the clamp, the clamp fell and hit the boliow worker in the face. The worker was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.	No Action Necessary					Material Fell	NYC HPD	
31/2018	Manhattan	1283	YORK AVENUE	0	1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, lost his balance, and fell on his rear. The worker walked to a City MD for a check up.						Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	
31/2018	Manhattan	209	EAST 19 STREET	0	<ol> <li>The Site Safety Manager reported that a worker hurt his finger while unloading pipes from a delivery truck. The worker went to a City MD on his own.</li> </ol>	No Dispatch					Other Construction Related Incidents	227 EAST 19TH STREET OWNER, LL	
31/2018	Manhattan	435	EAST 13 STREET	0	1 The Construction Superintendent reported that a third party inspector missed the last step on his way down a permanent flight of stairs and hurt his foot. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	



cident Date	Borough	Address Number	Street F	atalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	532	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker slipped on ice melt pellets that were on the ground floor of the job site in an are where ice melt had been put down to melt ice. The worker hurt his wrist and his hip. The worker went to see the onsite medic before going to see an offsite medic on his own.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2018	Manhattan	550	WEST 29 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder when the blade caught his glove and caused a cut to his hand. An ambulance was called.	No Dispatch					Other Construction Related Incidents	550 WEST 29TH STREET LLC	
)18	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that a worker cut his pinky finger while putting away his band-saw tool. The band-saw was unplugged. The worker went to a clinic. An ambulance was not called	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
018	Manhattan	328	EAST 62 STREET	0	<ol> <li>The Construction Superintendent reported that a worker was installing pour stops when he slipped into the side of rebar and injured his shoulder. The worker left the site in a cab.</li> </ol>				Alt 1 - NB	121189846	Other Construction Related Incidents	YYY 62ND STREET LLC	JOY CONSTRUCTION CORP
D18	Manhattan	591	THIRD AVENUE	0	1 The Site Safety Manager reported that a painter was carrying down supplies when he lost hs balance on the fourth step and fell, hurting his leg. An ambulance was called and the ambulance took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	587-91 THIRD OWNER LLC	
018	Brooklyn	1	FLATBUSH	0	<ol> <li>The Site Safety Manager reported that a worker was removing debris when a four inch pipe that was about three feet long fell on his foot. The worker went to a hospital.</li> </ol>	No Dispatch					Other Construction Related Incidents		
2018	Bronx	869	EAST 147 STREET	0	1 The Site Safety Manager reported that a worker complained about lower back pain while pulling a stud during carpentry work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	HP MLK PLAZA HOUSING DEVELOPME	
2018	Brooklyn	1	FLATBUSH AVENUE	0	1 The Site Safety Manager reported that a worker was doing taping work while on an "A"-Frame ladder when he mis-stepped and fell two feet. The worker suffered a minor injury and an ambulance was called.	No Dispatch					Other Construction Related Incidents	ONE FLATBUSH AVENUE PROPERTY L	
2018	Brooklyn	37	BLUE SLIP	0	<ol> <li>The Site Safety Manager reported that a worker got his thumb pinched between a window and a rack during a delivery. The worker went to urgent care on his own.</li> </ol>	No Dispatch				_	Other Construction Related Incidents	BOP GREENPOINT G LLC	
2018	Manhattan	10	RIVERSIDE BOULEVARD	0	The Site Safety Manager reported that a worker hurt his back while lifting a reel of wire into a box. An ambulance was called.	No Dispatch					Other Construction Related Incidents	RCB3 NOMINEE LLC	
2018	Manhattan	24	2 AVENUE	0	1 The Site Satiety Manager reported that a worker was putting away his tools at the end of the day when he opened a sliding glass door on the eighth floor. The glass door came off of its track and hit the worker. The incident took place on 2/5/2018, but was not reported until 2/6/2018. An ambulance was not called, but the worker said that he was going to see a doctor to be checked out. An arbulance was not called, but the more said that he was going to see a doctor to be checked out. An CEO Violation and a DOB Violation were issued. A partial Stop Work Order on the use and missilation of all balcony sliding doors was issued. The General Contractor is to provide a Manufacturer's Specification on all door tracks and the reason for the door failing off its track.	ECB Violation	35299721R	0206188503GD02			Material Fell	24 SECOND AVENUE OWNER LLC	
018	Manhattan	260	WEST 40 STREET	0	A DOB inspector reported that a worker was trying to reach for something on the platform of a baker scaffold when he moved the baker scaffold, causing it to strike the left shoulder of another worker. Both workers were on the floor and not using the scaffold. The injured worker was sent to a Med-Nite Clinic for a check up. The injured worker did not suffer a major injury. An ECB Violation was issued.		35285826Y		NB	121187394	Material Fell	PORT 40TH PARKING CORP	ZDG LLC
2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con- Edison box. The worker went to Staten Island Hospital on his own for a check up.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Manhattan	91	LEONARD STREET	0	1 The Site Safety Manager reported that a worker tripped, fell, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital.	No Dispatch			NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
2018	Manhattan	91	LEONARD STREET	0	1 A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker went ot a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	353-357 BROADWAY LLC	
018	Manhattan	2395	FREDERICK DOUGLAS BOULEVARD	0	1 A DOB inspector reported that a worker was hit in the head with a piece of timber that was dropped by another worker during a stripping operation. The worker who was hit by the piece of timber complianed of a stiff neck and was sent to a hospital. An ECB Violation was issued, as well as a partial Stop Vork Order on all concrete work. A Means and Methods must be provided.		35289390M				Other Construction Related Incidents	HP 2395 FDB HOUSING DEVELOPMEN	
2018	Manhattan	1283	YORK AVENUE	0	<sup>1</sup> The Site Safety Manager reported that a worker was moving an "A"-Frame doily that was loaded with twenty heates of 4 X8 diamond plates when the doily tipped and hit her ankle. The injured worker went to an emergency room that was across the street from the site. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35299967R				Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	



cident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/2018	Brookyn	911	ERSKINE STREET	0	EVC Prinz Description 1 The Site Safety Manager reported that a worker was approximately four text. While catting one of the piles, the pile fail forward and hit him in the head. The worker work to a hospital by ambulance. This incident occurred on 256/2018, but was not reported until 28/2018. An ECB Violation was issued for a failure to notify the Department Of Buildings of the incident, as well as a partial Stop Work. Order for the cutting operations with a too box talk will be provided.	ECB Violation	ELS VIOLATION NUMBERS	0284188505HM01.02			incoent ype Material Feil	FOUNTAIN SEAVIEW THREE HOUSING	
//2018	Brooklyn	540	FULTON STREET	0	1 The Site Safety Manager reported that during a drilling operation for the backs, a carpenter that was assisting the drill operator stepped onto an equipment insert and the clamp closed down on his left foot. The worker was taken to a hospital by emergency personnel. Two ECB Violation, were issued, as well as that Site North Anger Safety and Safe	ECB Violation	35309900Z 35309901K		NB	321185828	Mechanical Construction Equipment	540 FULTON ASSOCIATES	PAV-LAK CONTTRACTING INC
2018	Manhattan	460	PARK AVENUE SOUTH	0	1 The Site Safety Manager reported that a worker was opening a crate of window frames when a 5 X 5' tube pipe rolled out and onto his foot. The worker was seen walking around, but an ambulance was called.	No Dispatch					Other Construction Related Incidents	460 PARK AVENUE SOUTH ASSOCIAT	
2018	Queens	27-17	42 ROAD	0	1 The Site Safety Manager reported that a worker lacerated his hand with a utility knife during a stripping operation when the utility knife slipped. The worker went to a hospital on his own.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
V2018	Brooklyn	810	FULTON STREET	0	1 The Site Safety Manager reported that a worker was performing stripping work on the eleventh floor when he pulled down a piece of plywood and the aluminum leg of the formwork hit the worker in the face and split his lip. An ambulance was called. An ECD Violation was issued for a failure to provide safety measures. A DOB Violation was also issued. A Tool Box Talk will be issued before the start of stripping operations.		35300050К	020818BS02EP06			Material Fell	GREENPOINT-GOLDMAN CORP.	
018	Manhattan	388	GREENWICH STREET	0	<ol> <li>The Site Safety reported that a worker hurt his foot while using a chipping gun. The worker took a cab to urgent care.</li> </ol>	No Dispatch			ALTERATION TYPE 1	121190503-01-AL	Other Construction Related Incidents	CITIGROUP TECHNOLOGY, INC.	TISHMAN CONSTRUCTION CORP
2018	Queens	34-11	BEACH CHANNEL DRIVE	0	1 The Site Safety Manager reported that a worker was dismantling a scaffold when the plank he was standing on broke and fell six feet. The worker went to a hospital by ambulance. An ECB Violation for a failure to safeguard all persons and property affected by construction operations was issued.	ECB Violation	35285811N		NB	421094283	Worker Fell	NOT ON FILE	Chateau GC LLC
2018	Queens	160-08	JAMAICA AVENUE	0	1 The Site Safety Manger reported that a vehicle struck the flagman in the street. The Police Department responded to the incident. The worker was taken to Jamaica Hospital.	No Dispatch					Other Construction Related Incidents	160 JAMAICA, LLC	
2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that an electrician was pulling his cart from the hoist when the handle on the cart became loose and the worker fell backwards to the floor, hurting his back. An ambulance was called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
2018	Brooklyn	500	GATES AVENUE	0	1 The Super reported that a mason was using a grinder for brick cutting when the grinder kicked back and the grinder's butt end (not the blade) hit the mason in the face. The mason suffered a bruise to his face and felt a little dizzy. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PCMH 500 GATES HOUSING DEVELOP	
2018	Brooklyn	340	EVERGREEN AVENUE	0	1 The Fire Department reported that a worker was hit in the head with a piece of rebar. Four ECB Violations and four DOB Violations were issued. A partial Stop Work Order was also issued. A Means and Methods and a Tool Box Talk must be provided.	ECB Violation	35300117X,118H,120R,121Z	020918BS04DH01,02,04,05			Material Fell	BUSHWICK REALTY HOLDINGS LLC	
/2018	Bronx	2568	PARK AVENUE	0	1 The Site Safety Manager reported that a worker cut his knee while walking by rebar. The worker was taken to an area medical facility by a co-worker.	No Dispatch				220152484	Other Construction Related Incidents	2568 BRONX PARK LLC	STEVEN ALESSIO
2/2018	Brooklyn	135	EMERSON PLACE	0	1 The Site Safety Manager reported that during a stripping operation, a worker fell down from the sixth floor and landed on top of the sidewalk sheet. The worker was found unconscious, but breathing. The worker was taken to a hospital by ambulance. An ECB Violation and a full Stop Work Order were issued. Three additional ECB Violations/0ATH Summonses and three partial Stop Work Orders were issued by the Concrete Enforcement Unit.	ECB Violation	35300065N				Worker Fell	PRATT INSTITUTE	
2/2018	Manhattan	11	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker was working in a man lift when he moved his body and twisted his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	THE MUSEUM OF MODERN ART	
12/2018	Manhattan	200	EAST 95 STREET	0	1 The Site Safety Manager reported that a worker pinched his finger while moving a steel beam on an "A"-Frame. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents		



ncident Date	Borough	Address Numbe	r Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/12/2018	Manhattan	461	WEST 34 STREET	0	1 The Site Safety Manager reported that a worker cut his left hand on metal studs. The worker was taken to an	No Dispatch			ALT 1	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	EDWARD M GRUNWALD
					area hospital and received several stitches.								
3/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker entered the site from the outside of the mall area by the dirt parking area side, fell in ice that was mixed with dirt, and hurt his ankle. The worker went to urgent care.						Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
3/2018	Queens	80-08	135 STREET	0	2 The General Contractor reported that two workers were injured while grouting when a pump hose god clogged with grout and beiw into the worker's faces. The workers tried to un-clog the pump while if was in use. The two workers were taken to a hospital for treatment. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35309854r		ALT 1	420652378 AL	Mechanical Construction Equipment	BRIARWOOD MP LLC	PAV-LAK CONTRACTING INC
13/2018	Queens	45-57	UNION STREET	0	1 A DOB inspector reported that a worker was using the solifield's stains to bring rebars onto a floor when a rebar got caught on the stains and pulled the same worker down. The worker was experiencing aches in his body and went to a clinic the set day. This incident took place on February 13, 2018, but was not reported until February 14, 2018. The building was a five soroy building with no permanent stains. An ECB Violation and a full imgressiongress, an adequate supported scaffold, and the lack of internal stains.		35299630L				Worker Fell	DEPARTMENT OF EDUCATION	
15/2018	Brooklyn	1060	CLARKSON AVENUE	0	1 The Site Safety Manager reported that a worker cut his arm with a saw while cutting wood. The worker was	No Dispatch			ALTERATION TYPE 2	302581347-01-EW-OT	Worker Fell	DEPARTMENT OF EDUCATION	ANSU CONSTRUCTION INC
/15/2018	Manhattan	101	WEST 57 STREET	0	taken to a hospital by ambulance. 1 A DOB inspector reported that contractors were attempting to remove a tempered glass panel when the panel shattered. A small piece of glass fell to the street level while the remainder of the shattered panel was on the terrace. A woman was injured and taken to a hospital by ambulance. The women's injury was mixor and not like threatening. An Agazwated Level 2 ECB Violation, a DOB Violation, and a partial Stop Work and property during construction operations.	ECB Violation	35306906P	021518CERDY04			Material Fell	101 WEST 57TH STREET HOTEL INV	
15/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was climbing off of a scaffold when he slipped and fell approximately two feet, injuring his shoulder. An ambulance was called.	No Dispatch					Worker Fell	38-46 WEST 33 STREET, LLC	
15/2018	Queens	30-35	COLLEGE POINT BOULEVARD	0	1A DOB inspector reported that a painter was on a scissor illt painting the area next to a roll down door sensor when he activated the door, which caused another worker to get hit by the door. The worker had the wink Incode do ut of him and was sent to a hospital. An ECB Violation and a partial Stop Work Order were issued for the failure to maintain safe operations. The General Contractor at the site is to provide a Means and Methods.	ECB Violation	35317705N				Other Construction Related Incidents	FEINSTEIN CP REALTY LLC	
16/2018	Manhattan	217	WEST 57 STREET	0	1 The Sete Safety Manager reported that a concrete worker was carring a Doka form that was about 2 X 9 leat and 100 pounds when he slipped and fell. The worker complianded of back pain A DOB inspector responded to the incident and reported that no enforcement action was necessary, as the injury occurred as the result of a worker error.	No Action Necessary					Other Construction Related Incidents	SMITELL SPONSOR LLC	
16/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was lifting a piece of rebar when he claimed to have hurt his back. The worker walked up to an ambulance and the ambulance took him to a hospital.	No Dispatch			NEW BUILDING	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTRUCTION SERVICES LI
(16/2018	Manhattan	38	HOWARD STREET	0	2 A DOB inspector reported that an inspector from Cole NY was performing an inspection of the building for façade local aww. While inspecting the building, the inspector stepped out onto the fire escape became disidoged and fell to the ground, striking two pedestrians. One of the pedestrian suffered a life threatening injury, and the second pedestrian was in epicous condition. The inspector (all slightly through an opening, but not all the way down. ENS was called. An ECB4 Violation, a DOB Violation, and an immediate Emergency Declaration were issued.	ECB Violation	35308908Z	021618CERDY01			Material Fell	434 BROADWAY PROPERTY INVESTOR	CANY Architecture & Engineering, DPC.
/16/2018	Queens	71-17	ROOSEVELT AVENUE	0	1 A DOB inspector reported that were four workers unloading bundles of rebar that were approximately forty five feet from a flabed truck when one of the workers load control of the bundle and the bundle tell on the leg of another worker. There was no equipment used dump then the granty. The tell was no equipment used dump that the granty. The tell was no equipment used dump that the granty. The tell was no equipment used dump that the granty. The tell was no equipment used dump that the granty. The tell was no equipment to the CDV loadian and a partial Star Work Order ware issued for a failure to maintain the safe operations and to stop all material handling, including deliveries. The General Constructor is to provide a safe Means and Methods, including equipment and Tool Box talks.				NEW BUILDING	420653000	Material Fell	ROOSEVELT PARC LLC	BRAVO BUILDERS LLC



ident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Manhattan	200	EAST 21 STREET	0	1 The Site Safety Manager reported that a worker	No Dispatch			NEW BUILDING	121190479-01-NB	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC
					dislocated his left shoulder when he lifted a bag of concrete onto it. The worker was taken to Mount Sinai Hospital by ambulance.								
2018	Brooklyn	805	WASHINGTON AVENUE	0	1 A DOB inspector reported that a worker was walking	ECB Violation	35317732Z, 35317733K AND 35317736K		NEW BUILDING	321478548	Mechanical Construction Equipment	805 WASHINGTON AVE LLC	HAPPY LIVING DEVELOPMENT
					close to a Bobcat while an Hesam was on the forts attached to the bobcat when the Heam moved and the worker's hand got caught between the i-Beam moved and the bobcat track. The worker suffered at factured hand and was taken to an area hospital. The worker operating the Bobcat was not trained by the employer, which created this situation that resulted in an injury to another work. This incident courden of 21/82/82, but the Site Sately Manager was not informed of the incident until coder were issued.								
/2018	Brooklyn	211	SCHERMERHORN STREET	0	1 The Site Safety Manager reported that a worker rolled his ankle while moving material. The worker was taken to Brooklyn Hospital by EMS.	No Dispatch			FRANK HEALEY	321196200-01-NB	Other Construction Related Incidents	211 SCHERMERHORN DEVELOPMENT L	OESTREICHER CONSTRUCTION
/2018	Manhattan	115	DELANCY STREET	0	<ol> <li>The Site Safety Manager reported that a worker cut his finger while using a grinder. The worker went to urgent</li> </ol>	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					care.								
0/2018	Manhattan	425	PARK AVENUE	0	1 The Site Safety Manager reported that a worker fell from the fourth step of an "A"-Frame ladder. The worker complained of back pain. An ambulance was called.	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
1/2018	Brooklyn	5718	2 AVENUE	0	A DOB inspector reported that a worker was pulling on one of the clips of a outrigger scattolio in order to install in property. The worker pulled the clip hard, which caused the worker to slide down the plank and twist his ankle. The worker went to the emergency com across the strete and then went home. The formwork and outriggers were all built as per design. No enforcement was action necessary, as it was determined that the injury occurred as the result of a worker error.				ALTERATION-1	321192702	Worker Fell	NYU HOSPITALS CENTER	HUNTER ROBERTS CONSTRUCTION
2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager has reported that a worker was climbing down an 'A'-Frame ladder when he slipped and fell about four feet. An ambulance took the worker to a hospital. The worker suffered a possible fractured elbow.	No Dispatch					Worker Fell	SMITELL SPONSOR LLC	
/2018	Queens	131-11	FOWLER AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker twisted his right wrist while bending rebars. A co-worker took him to a clinic.</li> </ol>	No Dispatch					Other Construction Related Incidents	131-05 HOLDING LLC	
1/2018	Queens	38-01	QUEENS BOULEVARD	0	1 The Site Safety Coordinator reported that a worker tripped on tape on a scalfold platform, which caused him to fall and thrist his knee. The worker was taken to urgent care. An ECB Violation was issued to the General Contractor at the site for a failure to safeguard all persons and property.	ECB Violation	35285820P		NB	421387626	Worker Fell	CURBCUT QUEENS BLVD LLC	Sordoni Construction Comp
2/2018	Staten Island	35 a	BAY STREET	0	The Site Safety Manager reported that a rebar installer slipped on a rebar floor and twisted his ankle. An ambulance was on site.	No Dispatch					Other Construction Related Incidents		
2/2018	Staten Island	2655	RICHMOND AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker was loading sheetrock onto an "A"-Frame when one of the boards slid and landed on his right foot. The worker was sent to urgent care.</li> </ol>						Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
2/2018	Manhattan	122	LEXINGTON AVENUE	0	1 The Police Department reported that two workers were making a delway to the roof area of the structure when one of the workers fell approximately eight to ten feet through an opening in the roof that was covered with a tarp. The worker fell to the third floor. The worker suffered injuries to his back and neck injuries. A full Serv Work Order has been issued to the building on 422/2015 and 3 vacate Order was issued by Valations were issued for the unider continuation of work while on the notice of a Stop Work Order and for a failure to safeguard.		35308861K & 35308860Z	022218CERTQ01 & 022218CERTQ02			Worker Fell	122-24 LEXINGTON AVECP	
2/2018	Brooklyn	19	KENT AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker walked into a pile of plywood and then felt discomfort in his upper torso and chest. An ambulance was called and the worker was transported to a hospital.</li> </ol>	No Dispatch			NEW BUILDING	320591944-01-NB	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
2/2018	Brooklyn	138	WILLOUGHBY STREET	0	<ol> <li>The Site Safety Manager reported that a worker cut his finger while handling rebar. The worker was seen by the on-site medic and was sent to City M.D./urgent care.</li> </ol>	No Dispatch					Other Construction Related Incidents	NYC HPD	



cident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit		Incident Type	Owner's Name	Contractor Name
23/2018	Queens	83-09	35 AVENUE	0	1 A DDB inspector reported that workers at apartment number B42 were lowering a pice of phywood that was approximately Z X 5 from the fourth floor fire escape to the ground using a heavy thick ruope in front of the building. According to the Project Manager at the site and a bystander, the phywood siteped off of the rope and fall from the third floor level, striking a young gif or the site of the head before landing on the ground. Marks from the fallen wood can still be seen on the ground to b New Yoof Prosbyterion Hospital of Oueners with inguries to the side of her head. Three Aggravated Level 2 EGB Violations were issued for a failure to adequark, for wrk not conforming to plans, and for working without a permit. 3 DOB Violations,and a full Stop Work Order were also issued.		35309174N, 35309326N	022319CERKC03, 022319CERKC04 & 022319CERKC04 &	ALTERATION TYPE 2	421548999-01-EW-OT	Material Fell	83-09 35TH REALTY LLC	MNR GROUP INC
26/2018	Manhattan	545	WEST 30 STREET	0	1 A DOB inspector reported that workers were using a luli to unload window panels off of a truck. While the luli was being taken into the building, one of the panels slid off of the luli and hit a worker's ankle. An ambuince book the worker to a hospital. An ECB Violation for a book the worker to a hospital. An ECB Violation for a book the worker of a hospital. An ECB Violation for Work Order were issued or all deliveries and material handling. The General Contractor is to provide a Means and Methods.	ECB Violation	35317717K				Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
27/2018	Manhattan	685	FIRST AVENUE	0	1 The Site Safety Manage reported that a worker was working in a building when a couple of pieces of sheetrock fell over and onto his leg. An ambulance was called to the site.	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
128/2018	Manhattan	1227	BROADWAY	0		ECB Violation	35225172L 35225171J & 35225172L		CN	CN 913/16	Mechanical Construction Equipment	YJL BROADWAY HOTEL LLC	BMNY CONTRACTING CORP
28/2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that a worker got dust in his eye. The worker went to a hospital for treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
'1/2018	Brooklyn	391	HOOPER STREET	1	0 A DOB inspector reported that heavy gauge 2 X 10 ceiling joists were delivered and placed on top of the billing joists were delivered and placed on top of the billing of the second second second second second billing of the second second second second second and knocking the worker off of the secand(s) to the ground. The joists landed on top of the worker as well. The worker was found second on second second second and a full Stop Work Order were issued.	DOB Violation		030118B501AS01			Other Construction Related Incidents	E&D MANAGEMENT GROUP LLC	
2/2018	Queens	28-02	JACKSON AVENUE	0	1 A DOB inspector reported that a panel of plywood that was about 8' X 4' fell from the parapet of a sidewalk shed and struct two pedestrians. One of the pedestrians suffered an injury in the shoulder area. The injured pedestrian was seen by the on-site medic, but denied further medical attention and left the scene. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard public and property affected by construction operations. A second ECB Violation was also issued for a failure to maintain an inspection log for the sidewalk shed. A partial Story Work Order was also issued. The sidewalk shed company was sent to the site for repair work.	ECB Violation	35318105Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMPA
2/2018	Manhattan	685	1 AVENUE	0	1 The Site Safety Manager reported that a worker was pushing a min container when the gate on the bottom of a ramp swung and lacerated his right hand. The on-site medic put a band aid on the cut. An ambulance took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
2/2018	Manhattan	260	WEST 40 STREET	0	<ol> <li>The Site Safety Manager reported that a worker was using a lade and cut his finger. The worker was patched up on-site, but then went to City M.D. where he received two to three sittches.</li> </ol>	No Dispatch			NB - NEW BUILDING	121187394	Other Construction Related Incidents	PORT 40TH PARKING CORP	ZDG, LLC
3/2018	Manhattan	150	EAST 23 STREET	0	1 The Site Safety Manager reported that workers were carrying steel plates when one of the plates slipped and pinched one of the worker's left middle finger. The worker was transported to a hospital by ambulance.	No Dispatch			NB	121981748	Other Construction Related Incidents	154 EAST 23 LLC	W & L GROUP CONSTRUCTION
3/2018	Manhattan	1912	1 AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the worker was transported to a hospital.</li> </ol>	No Dispatch			NB	122879233	Worker Fell		PROCIDA CONSTRUCTION CORP



cident Date	Borough	Address Number	Street F	atalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	396	BROADWAY	0	<ol> <li>The Site Safety Manager reported that a worker dropped a piece of plywood on his foot. The worker left the site in an ambulance.</li> </ol>	No Dispatch			A1 - ALTERATION TYPE 1	120786417	Other Construction Related Incidents	BRIDGETON 396 BROADWAY FEE LLC	ANTHONY T. RINALDI
018	Manhattan	425	WEST 18 STREET	0	The Site Safety Manager reported that a worker hurt his back while picking up a cement bag. An ambulance was called and the worker was transported to a hospital.	No Dispatch			NB	122736762	Other Construction Related Incidents	NOT ON FILE	ARTIMUS CONSTRUCTION INC
2018	Brooklyn	10	HURON STREET	0	1 The Site Safety Manager reported that there were two workers that were doing sheetrock work together when one of the workers loat his ging on a piece of sheetrock that landed on the other worker's finger, causing a cut. The second worker left the sits and went to City M.D. to get stitches on his finger. This incident occurred on 35/2018, but was not reported to the Site Safety Manager or Construction Superintendent until 3/8/2018.	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
018	Queens	45-57	UNION STREET	0	1 A DOB inspector reported that a 16' X 8' size gate swung out and hit a pedestrian that was walking by. The pedestrian was a student that was approximately seven years old. The student was evaluated by a nurse.	ECB Violation	35317909P				Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
2018	Manhattan	2255	BROADWAY	0	1 The Site Safety Manager reported that a worker was Ifiting a 2 X 3 X 10 wooden beam in the elevator pit when he hit himself in the face with the wooden beam. The worker want to urgent care and then went to a hospital. This incident occurred as a result of a worker error.	No Dispatch					Other Construction Related Incidents	2255 HOLDING LLC	
2018	Bronx	2395	FREDERICK DOUGLASS BLVD	0	1 The Site Safety Manager reported that a pedestrian in a wheelchair lidow in a walkney due to a tripping hazard around a Con-Ed sever cap. The pedestrian went to a hospital by ambulance. A DOB inspector responded to the incident, visited the site, and issued an ECB Violation. The tripping hazard was corrected as of the time that the inspector was at the site.		35300487N	030618BS10VP06			Other Construction Related Incidents		
2018	Brooklyn	416	KENT AVENUE	0	1 The Site Safety Manager reported that a worker slipped, fell, and hurt his arm. The worker was taken to a hospital for a check up.	No Dispatch				320622616	Other Construction Related Incidents	420 KENT AVENUE LLC	ZDG, LLC
2018	Manhattan	1681	3 AVENUE	0		No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
2018	Queens	147-40	ARCHER AVENUE	0		No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
/2018	Queens	28-07	JACKSON AVENUE	0		ECB Violation	35318121Y-FAIL TO SAFEGUARD	030818BS02KA01	NB	420656873	Material Fell	LIC SITE B-1 OWNER, LL.C.	NEW LINE STRUCTURES & DEV
2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker slid and hit his left knee as he was taking the stairs to his trailer. The worker was taken to a hospital for a check up.	No Dispatch					Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	
2018	Manhattan	1059	3 AVENUE	0	The Site Safety Manager reported that a worker was carrying a few formwork clamps that weight approximately 10-15 pounds and are about 18 feet long in length up the third floor steps when one of the clamps ell from his grian dhi the write of a mason that was working in the basement, possibly breaking the masor's wrist. An ambufance was called. An EGB Violation and a partial Stop Work Order were issued for the unsafe handling of materials. A DGB Violation was also issued. A Means and Methods will be provided for the safe handling of form work materials.		35300269P	030918ES08MH01			Material Fell	63RD & 3RD NYC LLC	
/2018	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a worker as carrying equipment when he slipped and full. The worker in the back of his head and blacked out. The worker is the back of his head and blacked out. The worker responded and visited the site and reported that the worker sild on what look like an ice patch on the floor, even through there was ice melt spread throughout the are. An ECB Violation was issued for a failure to maintain safe operations.	ECB Violation	35296419N				Worker Fell	SMITELL SPONSOR LLC	
/2018	Manhattan	29	11 AVENUE	0	The Site Safety Manager reported that an iron worker was attempting to move a steel beam onto a dolly on his own when the beam slid and hit his left knee. 911 was called and the worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	NYS PARKS & RECREATION	
2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reports that a worker pinched his finger while cutting a Formica board with a circular saw. The worker went to the emergency room on his own	No Dispatch					Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	



ncident Date		Address Number		Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
11/2018	Manhattan	500	WEST 33 STREET	0	hurt his right index finger while prying a cross brace. The worker was transported to Bellevue Hospital by	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
12/2018	Manhattan	125	GREENWICH STREET	0	ambulance. 1 A DOB inspector reported that a worker was lifting up a four foot section of form work when the worker mishandled the form work, causing the form work to fall on his knee. An ambulance was called. It was determined that the incident happened as a result of a worker error and that no enforcement action was	No Action Necessary					Material Fell	VS 125 LLC	
12/2018	Manhattan	125	GREENWICH STREET	0	necessary. 1 The Site Safety Manager reported that a worker was handling a roll of felt paper when he slipped backwards and suffered a laceration to the left side of his forehead The worker did not want an ambulance to be called and went to a City M.D. instead.						Worker Fell	VS 125 LLC	
12/2018	Manhattan	255	EAST HOUSTON STREET	0	1 The Site Safety Manager reported that a worker's finger got caught between two beams while he was pushing forwards beams on a truck. The worker was sent to Bellevue Hospital.	No Dispatch			_		Other Construction Related Incidents	255 EAST HOUSTON OWNER LLC	
/13/2018	Queens	150-13	89 AVENUE	1	0 A DOB inspector reported that a worker was riding on the back of a fork iff outing a placement of bundle windows in the soring garage. The bundle was 10 x 5 weight. The driver of the forkill heard a sound and then saw that the worker who was refaing on the back was on the floor. The worker was found dead. There were no witnesses to the incident, and the incident is currently under police investigation. The driver of the fork iff was found to be not certified to operate a fork iff. The driver was in a traumatized state and went to a hospital. A DOB Violation for a failure to seleguard and a Stop Work Order were issued. ECB Violations are being prepared to be served.			031318BS1201MC			Other Construction Related Incidents	86TH AVENUE OWNER LLC	
/14/2018	Brooklyn	3617	13 AVENUE	0	1 Å DOB inspector reported that a worker lacerated his foot while driving a walk-behind saw to a container in order to park i. The worker was sent to a hospital. A an EGB Violation was issued, as well as a partial Stop Work Order on the use of the walk-behind saw. Manufacturer specifications must be provided.		35318355R				Other Construction Related Incidents	37TH STREET HOLDINGS LLC	
/14/2018	Manhattan	220	CENTRAL PARK SOUTH	0	<ol> <li>The Site Safety Manager reported that an iron worker pinched his index finger while unloading a cart of steel. The worker went to a clinic to receive stitches for his finger.</li> </ol>	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
/15/2018	Brooklyn	225	4 AVENUE	0	1 A DOB inspector reported that workers were in the process of clearing brick with an acid base solvent when some of the solvent fell into the eye of a female pedestrian. The pedestrian fails the eye rinade out and was treated on the site. The pedestrian fails of the other halter to safegurate the eye of the 2CB violation for the failure to safegurate the eyes of the solvent as a DOB construction operations was issued, as well as a DOB construction operations was issued, as well as a DOB to the eyestime of the the the EST Squad perform a follow up inspection for compliance and safety measures.	,	35309224H	031518CERDM01	NB	310086554	Material Fell	225 4TH AVENUE PROPERTY OWNER	TRM Construction
/16/2018	Queens	21-30	44 DRIVE	0	The Site Safety Manager reported that a piece of plywood fell from the first floor to the cellar due to the wind. The plywood fanded on the cellar floor where it then fell onto a worker, huring the worker's shoulder. This incident occurred on March 16, 2016, but the 2018, because the March 16, 2016, but the 2018, because the Gonstruction Superintendent calime that he callest the office on 2192018 after 4-00 PM and that he callest the office on 2192018 after 4-00 PM and that he callest the office on 2192018 after 4-00 PM and that he callest the office on 2192018 after 4-00 PM and that no one answered the phone. An EGB Violation was issued for a failure to antiguard for not securing materials during a weather advisory. DOB Violation and a partial Stoy Work Corte or all form work were also issued. A Means and Methods for the securing of materials during a weather advisory must be provided.	di l	35318143P	031918BS02KA04			Material Fell	44TH DRIVE OWNER LLC	
/16/2018	Mənhattan	501	WEST 18 STREET	0	1 Å DOB inspector reported that during excavation work, worker was torching a hole in two steel TH piles and was laying side by side in order to sling and righte pile when the excavator that was being used moved, witch caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An DEC8 Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of site piles. The contractor is to provide a Means and Methods for the safe movement of steel around the construction site.		35314141N		New Building	121191147	Excavation/Soil Work	18TH HIGHLINE ASSOCIATES, L.L.	Related Construction LLC



ncident Date	Borough	Address Number	er Street	Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
16/2018	Manhattan	220	CENTRAL PARK SOUTH	0	1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack moved on its own and ran over the worker's left foot. The worker went to Roosevelt Hospital. A DOB inspector responded to the incident and issued an ECB Violation for a failue to maintain unsafe equipment. A DOB Violation and a partial Stop Work Order for all work using equipment to transport loads as the second floor north of Tower Boulevard were also issued. The powered pallet jack was found to have no inspection logs. An orientation and a Marka and Methods must be provided. The BEST Squad must be contacted for a re- inspection.		ECB#S5318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
6/2018	Brooklyn	416	KENT AVENUE	0	1 The Site Safety Manager reported that at a twenty-two story new building under construction, a worker that was on sitts performing plastering work on the eightmenth floor fell backwards onto the floor. The worker hun this back, suffered a wisted schea, and complianed of head pain. An ambulance was called and the worker was transported to Bellevue Hospital. The worker was awake and alert.				NB	320622616	Worker Fell	420 KENT AVENUE LLC	ZDG, LLC
19/2018	Brocklyn	1277	EAST 14 STREET	0	1 A competent person at the construction site reported that a worker slipped on a supported scatfold and fell approximately is freet, along with a few planks. The worker's foreman stated that the worker drove to see a doctor on his own. A DOB inspector responded and visited the site and reported that the supported scatfold did not conform to code specifications, as the scatfold was not fully plaked, the planks were not tied down, and a quard rait system was missing from multiple locations. Two ECB Violations and a partial Stop Work Order for a supported scatfold were issued.		35285912M, 35285913Y		NB	320597127	Worker Fell	1277 HOLDINGS LLC	Ray Builders Inc.
/2018	Manhattan	40	CLERMONT AVE	0	1 The Site Safety Manager reported that a carpenter was working on an "A"-Frame ladder when he missed the fifth step of the ladder and fell. An ambulance came and took the worker to a hospital.						Worker Fell		
9/2018	Manhattan	590	EAST 83 STREET	0	<ol> <li>The Site Safety Manager reported that a worker tripped and jammed his finger. An ambulance took the worker to a hospital.</li> </ol>	No Dispatch			NEW BUILDING	121190987-01-NB	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
0/2018	Brooklyn	10	MONTIETH STREET	0	<ol> <li>The Site Super reported that a worker attempted to jump over a fence and fell. The worker was taken to a hospital by ambulance.</li> </ol>				NEW BUILDING	320622750-01-NB	Worker Fell	BUSHWICK HOLDINGS I LLC	GALAXY DEVELOPERS LLC
/2018	Manhattan	108	EAST 89 STREET	0	<ol> <li>The Site Safety Manage reported that a worker hurt his shoulder while installing a pipe scaffold. The worker went to a City M.D. to get checked.</li> </ol>	No Dispatch			ALTERATION TYPE 1	122988623-01-AL	Worker Fell		E.W. HOWELL CO, LLC
0/2018	Queens	43-12	HUNTER STREET	0	I A DOB inspector reported that contractors were in the process of lifting a section of steel casisson in order to set i on a drill reg when a worker had his hand pinched between the casisson and a steel hook. The worker was alert and awake and was taken to a nearby hospital by a taxi. The extent of the injury to the worker's hand was not known as of the time of inspection. An ECB Violation for a failure to steelguard and and ECB Violation for there being no logs on site were issued, as well as a full Stop Work Coder for the entire site. The contractor at the site was instructed to provide a Means and Methods for sale pile installation.		35314355z 35314356k		NB	420659530	Mechanical Construction Equipment	43-12 HUNTER LLC	Judy y Lee
1/2018	Bronx	2028	CRESTON AVENUE	0	1 The Site Safety Manager reported that at an eleven story new building under construction, a worker was handling concrete out of a mixer when cement splashed into the worker's right eye. The worker was allert and awake and was taken to Lincoln Hospital for treatment.	No Dispatch			NB	220392858	Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MNGMT
/2018	Manhattan	650	5 AVENUE	0	1 The Site Safety Manager reported that a worker was working with temporary electrical wirting on the second floor when a 480-volt wire touched an I-Beam, which caused an ARC flash. The worker suffered an injury to his eyes and was taken to a hospital. A DOB inspector determined that there was no enforcement acton necessary.	No Action Necessary			Electrical	M00016968	Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
22/2018	Brooklyn	1835	STERLING PLACE	0	<sup>1</sup> The Construction Superintendent reported that a worker slipped off of an "A-Frame ladder while coming down from the ladder. The worker suffered a minor lacenation to the head. The worker was found conscious and an ambulance was called.	No Dispatch					Worker Fell	NOT ON FILE	



cident Date	Borough	Address Number	Street	Fatalities Injuri	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/2018	Marhattan	115	DELANCY STREET	0	1 TThe Site Safety Manager reported that a worker was cleaning around a Con Edison valt when he lifted an unmarked piece of phywood that was covering the valut, tripped into a shaft, and fell approximately eight to nine feet. The worker suffered a cut to his ankie. The worker was alert and awake and was taken to Bellevue Hospital. An ECB Violation for a failure to safeguard was issued, as well as a DOB Violation and a partial Slop Work Order for all exterior work at the ground floor at exposure three. Protections anround the valuts at the	ECB Violation	ECB#35317775Z -FAIL TO SAFEGUARD	0323188503GD01	NB	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
3/2018	Manhattan	40	10 AVENUE		ground level must be provided. An updated Means and Methods and Tool Box Talk must be provided.	No Dispatch					Worker Fell	40-56 TENTH OWNER LLC	
2010	ind a later i	40	IN AVENUE		was climbing up the relar cage to reach the electrical conduit when he slipped, fell two feet, and landed on his right ankle. The electrician was sent to a clinic.						WORKET EI	NO TENTI OWNER LEG	
4/2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that a worker was cutting metal studs when he cut the top of his hand with a chop saw. The worker went to the emergency room with another worker. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
5/2018	Brooklyn	19	INDIA STREET	0	1 The Site Safety Manager reported that a worker was moving windows when he tripped, fell three steps, and hit the back of his neck on a cinderblock. The worker was alert and responsive and was taken to Bellevue Hospital.	No Dispatch			NEW BUILDING	310234207-01-NB	Worker Fell	145 WEST STREET LLC	NOBLE CONSTRUCTION GR LLC
6/2018	Brookiyn	101	PENNSYLVANIA AVENUE	0	1 The Construction Superintendent reported that a worker was testing a refrigerant line when the line burst, causing discomfort to the worker's ears. A co-worker drove the injured worker to a hospital.	No Dispatch			Alt 1	320622894	Other Construction Related Incidents	ATLANTIC 2644, LLC	CAULDWELL WINGATE CO LLC
6/2018	Manhattan	250	SOUTH STREET	0	1 A DOB inspector reported that a worker was bringing a scattoid down when a guar down drowed the plaiform out of the building. The worker stuck his hand out to prevent the impact against the building, but hur his shoulder and back in the process. The worker was taken to a hospital where he was in stuble condition. It was determined that no enforcement action was mecessary, as the suspended scatticid was found to be in notification and installation letter from the engineer was onsite, and all logs were in order.		N/A		NE	121185528	Scaffold/Shed/Fence/Shoring/Installation	NOT ON FILE	Lend Lease (US) Construct
2018	Manhattan	420	EAST 54 STREET	0	1 The Site Safety Manager reported that the building owner's personal driver had his foot struck by a forkit. The injured person was take ho is hospital. A DB inspector reported that only one flag person was used when moving the forkit! and that the injured person walked into a controlled no access zone when he had his foot struck by the forkit. An CEU Violation was issued for a failure to safeguard. A DOB Violation and a partial Sibty Mork Oder were also issued. A Means and Methods and Tool Box Taks will be provided by the General Contractor at the safe to is safe delivery operations and for the proper amount of flaggers.	ECB Violation	35317780N	03261885c6GD01			Other Construction Related Incidents	RIVER TOWER OWNER, LLC	
/2018	Manhattan	432	EAST 14 STREET	0	1 The Construction Superintendent reported that a worker was pushing a mini container when she slipped and hit her knee. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	EAST 14TH STREET OWNERS LLC	
3/2018	Manhattan	441	9 AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker got his hand jammed between two stripping panels. A foreman took the worker to a hospital.</li> </ol>						Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
3/2018	Brooklyn	505	PACIFIC STREET	0	1 The Site Safety Manager reported that a worker slipped with a grinder and cut his face. An ambulance transported the worker to a hospital.				NEW BUILDING	320909004-01-NB	Other Construction Related Incidents	PVII HSC ATLANTIC LLC	TRITON CONSTRUCTION CO.,
0/2018	Manhattan	265	WEST 114 STREET	0	The Site Safety Manager reported that there was a worker on the second floor scatiolid deck carrying a plank. The worker leaned on the plank, which caused the plank to fail and hi a worker that was on the first floor scatfloid deck in the arm. The injured worker went to a City MJ for an X-ray. An EDS Violation was issued for the storage of excess materials on a scatfloid.	ECB Violation	35286045H		Ait 1	121189668	Material Fell	TRINITY WEST HARLEM PHASE TWO	Mega Contracting Gp LLC
2/2018	Queens	22-06	31 STREET	0	1 A competent person at the site reported that a worker that was coming into the site slipped on snow and injured his knee. The worker wont to see his doord for a check up. There was a snowstorm in progress as of the time of the incident.	No Dispatch					Other Construction Related Incidents	DITMARS 31ST STREET ASSOCIATES	
2/2018	Staten Island	2655	RICHMOND AVENUE	0	1 A DOB inspector reported that there were workers that were moving a wooden ramp that was about 4 x 8 x 20°. When the ramp was in a vertical position, one 2 x 4 fell onto the hand of one of the workers. The worker werk to urgent care. An ECB Violation and a partial Stop Work Croder (SVOI) were issued for all use of ramps. A Means and Methods and the design drawing must be provided.		35327352X				Other Construction Related Incidents	MAGY'S RETAIL HOLDINGS, INC.	



ncident Date	Borough	Address Number		Fatalities Injurie			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/2018	Bronx	2681	MARION AVENUE	0	1 A DOB inspector reported that a flagger was signaling						Other Construction Related Incidents	PCMH MARION AVENUE HOUSING DEV	
					for deliveries for traffic on the street when a cab driver tried to maneuver around a comer and ran over the flagger's foot. The flagger went to a hospital with a co- worker in an ambulance. The inspector determined that there was no enforcement action necessary, as the								
					flagger was certified and a delivery Means and Methods was at the site.								
/2018	Bronx	2760	BRIGGS AVENUE	0	1 The Site Safety Manager reported that a worker sipped on plywood that had snow on it. The worker claimed to have but his wrist while trying to brace himself after sipping. The worker went to a doctro on his own. This incident occurred in the morning, but the worker wated until the afternot or terport the incident and go to a doctor. A DOB inspector visited the site and reported that there was no sign of snow or any tripping hazards in the area that the worker. But the worker, a cause of the site could not be determined. Because of this, no enforcement action was deemed necessary.						Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker slipped on a wet surface and fell on his hand. The worker went	No Dispatch					Worker Fell	NYC HPD	
3/2018	Brooklyn	422	FULTON STREET	0	to a City M.D. 1 The Site Safety Manager reported that a security guard	No Dispatch			ALT 1	320908899	Other Construction Related Incidents	NOT ON FILE	TRANSPARENT CONSTRUCTION
4/2018	Brooklyn	5615	7 AVENUE		tripped and fell. The security guard was taken to a hospital as a precaution.	ECB Violation	35323275N	040418CERCM02	Alteration 1	320516152	Other Construction Related Incidents	SILLPING	GUO Z HUANG/NEWLAND CONSTRUCTION
~2010	Cickyi				2 The NYPD requested that an inspection please be performed because a construction fence fiel at the site. A DOB inspector responded and viaited the site and reported that the job site fence at exposure one had collapsed onto the public sidewalk. There were two injuries reported, a mother and a daughter. The mother and daughter were both taken to an area hospital. All fencing and debris at the site has been removed and made safe against the wind. An Aggravated Level 2 ECB violation and a full Stop Work Order were also issued. This inclent was reported under incident Number 29737. Incident Number 25473 was deleted by place.					2010/22			
4/2018	Manhattan	500	WEST 33 STREET	0	1 The Safety Director reported that a worker slipped and hit her tailbone while getting off of a actissor lift. An ambulance was called and transported the worker to a hospital. A DOB inspector visited the site and issued an ECB Violation and a partial Stop Work Order on all use of actissor lifts. The General Contractor is to provide training.	ECB Violation	35327428N				Other Construction Related Incidents	NOT ON FILE	
5/2018	Manhattan	4	WEST 37 STREET	0	1 The Site Safety Manager reported that a pulmeter was round easied on the fourth floor of a fammed out entryly room. There were no tools and no ladder found on the scene. A DOB impactor responded to the incident and visited the site, and reported that the worker suffered a possible heart attack and was envired with a faint pulse. No enforcement action was necessary.						Other Construction Related Incidents	4 WEST 37TH STREET LLC	
/6/2018	Manhattan	125	GREENWICH STREET	0	1 The Site Safety Manager reported that a worker hit himself in the face while stripping forms. The worker was driven to a City M.D.	No Dispatch			NEW BUILDING	121183799-01-NB	Other Construction Related Incidents	VS 125 LLC	PLAZA CONSTRUCTION LLC
/9/2018	Brooklyn	231	AINSLE STREET	0			35323245M & 35323246y	040918CERDF03 & 040918CERDF04			Worker Fell	ST CONO DE TEGGIANO C	
/9/2018	Brooklyn	420	KENT AVENUE	0	The Site Safety Manager reported that a steamfitter cut his finger while putting coupling on a pipe. 911 was called and the worker was taken to a hospital by	No Dispatch					Other Construction Related Incidents	420 KENT AVENUE LLC	
/9/2018	Manhattan	11	WEST 53 STREET	0	ambulance. 1 The Construction Superintendent reported that a worker	No Dispatch			ALTERATION-1	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	TURNER CONSTRUCTION CO
					was on a scissor lift and was trying to gain access into a plenum. The worker's hand was on the handrail of the scissor lift and his hand got pinned between the handrail and the hanging door of the plenum. The worker's hand was cut and the worker went to a hospital for a checkup.								



cident Date		Address Numb		Fatalities Injurie			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Manhattan	15	WEST 25 STREET	0	1 A DOB inspector reported that a worker was using a hole saw that jammed. The Construction Superintendent unplugged the tool and straightened it out. When the hole saw was plugged back in, the saw swung around and pushed the Construction Superintendent down, causing hin to fall approximately eleven feet. The Construction Superintendent was taken to a hospital in serious condition. The Construction Superintendent is now stable, but suffered a brain rigury. An ECB Violation, a DOB Violation, and a full Stop Work Order (FSWQ) were issued for a failure to safeguard during construction operations, as the Construction Superintendent fell in a location where there were no guardrafis installed.	DOB Violation	35323475H	040918CERND01	ALTERATION TYPE 2	123203069-01-EW-OT	Worker Feil	ST SAVA CATHEDRAL	G.P.J. ODONOGHUE CONTRAC
/2018	Manhattan	25	PARK ROW	0	1 The Site Safety Manager reported that a hoist installer got the tip of his finger crushed while working on the hoist when the gate came down. The worker was taken to the emergency room.	No Dispatch					Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	
9/2018	Manhattan	420	EAST 54 STREET	0	A DOB inspector reported that there ware three workers working on the third seventh forcing hatroir synchronic terms and the synchronic terms of the sproprimate 27 X 277 opening the floor that was not properly covered, as a door from the demolition work was used to cover the hole and the hole was not properly marked or secured. One of the workers picked up the door, unaware of the hole underneath is, and fell through the opening to the thirty sixth floor. The worker was send to a hospital for a checkup. Follow up information regarding the injured worker is not currently variable. Two EGS Violations were issued for the failure to maintain safety measures and for inadequate housekeeping. A full SND Work Order was also issued. The GC is to provide a Means and Methods for the safe operation of the job, including the protection of empty shafts and floor openings.	ECB Violation	35317792K, 35317793M		ALTERATION 2	122938357	Woker Fell	RIVER TOWER OWNER, LLC	VECTOR BUILDING CORP
2018	Queens	123-30	ROOSEVELT AVENUE	0	1 The Site Safety Manager reported that a worker tripped on a curb and twisted his ankle while carrying a panel. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NYC PARKS	
2018	Queens	147-40	ARCHER AVENUE	0	An announce was caned. The Site Safety Manager reported that a worker stepped on a tie-wire that was used for rebar work and the tie- wire punctured his boot and foot. The worker went to see a doctor on his own.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
0/2018	Manhattan	150	5 AVENUE	0	1 The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taken to a hospital by an ambulance.	No Dispatch			ALTERATION TYPE 1	122700292-01-AL	Worker Fell	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
1/2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that a worker was on a six foot ladder when he missed the second rung of the ladder while coming down from it and fell backwards and hit his head. The worker went to a hospital with his shop steward.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
1/2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker was stripping form work when a dust particle got between his safety glasses and irritated his eye. The worker went to a nearby City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2/2018	Bronx	600	BERGEN ÄVENUE	0	1 The Site Safety Manager reported that a worker was pumping group to the back when the hose cloged. When the worker opened up the hose clamps to clean the hose, the worker got grout in his eyes. The worker did not realize that pressure had built up when he removed the hose clamps. The worker was taken to a Chy M.D. and was then transferred to an emergency room at Lincoln Hospital.	ECB Violation	35314470y		NB	220151868	Mechanical Construction Equipment	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. DEVELP.
2/2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker was walking on the second floor when he stepped on a nail. The worker went to get a tetanus shot.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manger reported that a worker twisted his knee while climbing down from a machine. The worker was driven to the emergency room.	No Dispatch			NEW BUILDING	520135675-01-NB	Worker Fell	MACY'S RETAIL HOLDINGS, INC.	AURORA CONTRACTORS INC
3/2018	Bronx	2044	WESTCHESTER AVENUE	0	1 The Project Manager at the site reported that a masonry worker was laying cinderblocks when he fell off a supported scafford hat was approximately three feet in height. The worker landed on his back and appeared to be in stable condition, but reflexed to talk to anyone until an ambulance arrived. The worker was taken to Jacobi Medical Center. A DOB Inspector responded and visited the site and determined that no enforcement action was necessary, as the supported scafford was fund to be structurally sound with a guard rail system in place.		NA		NB	220152572	Worker Fell	HP WESTCHESTER MEWS HOUSING DE	Procida Construction Corp
13/2018	Manhattan	20	BROAD STREET	0	pushing a mini-container through a wall opening when he pinched his pinky finger. The worker left the site to see a doctor for treatment.	No Dispatch					Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.	
13/2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was cutting boxes with a box cutter when he cut his left thumb. The worker walked to urgent care.	No Dispatch			ALTERATION TYPE 1	121324343-01-AL	Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	CNY CONSTRUCTION LLC



ncident Date	Borough	Address Numbe	er Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
14/2018	Brooklyn	50	COURT STREET	3 DOB's Emergency Response Team was informed that isdewalk shed was in the process of being dismantled when a partial collapse occurred at the corner of Court Street and Johaniemon Street. Approximately twenty linear feet of the sidewalk shed collapsed. Two pedestrians and one worker suffered nor-file threatening injuries and were sent to Lutheran Hoppita The remaining unaffected parts of the sidewalk shed replaced the cross wak light at the site. An Approximate Lewel 2 ECE Voldenion was issued for a failure to isslequard all persons and property affected by construction operations. A DOB Violation was also issued.	a ECB Violation	35323276P	041418CERCM01	Ait 3 - SH	321426774	Scaffold/Shed/Fence/Shoring/Installation		NEW FORCE CONSTRUCTION CO
7/2018	Manhattan	130	EAST 82 STREET	0 1 The Site Safety Manager reported that a worker accidentally ran a screw into his hand while screwing screws during duct work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	134 EAST 82 LLC	
17/2018	Brooklyn	856	WASHINGTON AVENUE	0 1 The Site Safety Manager reported that a worker was drilling a core hole in a deck slab when the drill kicked back and the base of the drill hit him on the side of his face. The worker was alert. The worker went to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
/17/2018	Brooklyn	63	FLUSHING AVENUE	0 The Site Safety Manager reported that a worker slipper while going down the stairs. There were no witnesses is the worker slipping, and the stairs were free of debris. An ambulance was called. The worker was okay, but walked to the ambulance when the ambulance wark the ambulance when the ambulance when the ambulance wark slipping.	D					Other Construction Related Incidents	NYC DSBS	
17/2018	Brooklyn	1900	PARK PLACE	0 1 The Site Safety Manager reported that a worker straine his lower back while picking up a cement block. An ambulance was called	d No Dispatch					Other Construction Related Incidents	HABITAT FOR HUMANITY LATENT TH	
/18/2018	Brocklyn	25	EAST 19 STREET	anitoulation was called:     1 The Site Satery Manager reported that a worker was     passing an I-Beam down from a sidewalk shed when h     loats his footing and fell about siteme feet to the ground.     The worker was wearing a harness that as not attache     to anything. The worker was found awake and speakin     and was taken to a hospital. An ECB Violation was     issued for a failure to safeguard persons and property.	ə - 1	35323700H		Alt	340452520	Worker Fell	EBE HOLDING LLC	CS Bridge Corp
18/2018	Manhattan	220	CENTRAL PARK SOUTH	1 The Site Safety Manager reported that a worker cut his finger when another worker closed a door on his hand by accident. A co-worker took the injured worker to a hospital.	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
18/2018	Queens	71-17	ROOSEVELT AVENUE	0 1 The Site Safety Manager reported that a worker sprained his back while carrying steel form. The worke went to a hospital by ambulance for observation.	No Dispatch					Other Construction Related Incidents	ROOSEVELT PARC LLC	
18/2018	Staten Island	2655	RICHMOND AVENUE	0 1 The Site Safety Manager reported that a worker hurt hi shoulder when he picked up a bundle of threaded rods The worker went to urgent care on his own.	s No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
19/2018	Queens	147-40	ARCHER AVENUE	0 1 The Site Safety Manager reported that a worker was conducting a survey and was wearing proper footwaar when he stopped onto a nail that puncture his foot. Th worker went to urgent care for a tetanus shot.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
19/2018	Manhattan	70	VESTRY STREET	0 1 The Site Safety Manager reported that a worker was installing 3' X 6" stone at the base of a building when h knee gave out, causing the worker to fall onto his knee An ambulance was called.	is					Other Construction Related Incidents	BRIDGE LAND VESTRY LLC	
19/2018	Manhattan	112	WEST 25 STREET	0 1 The Site Safety Manager reported that a subcontractor was carrying a door from a truck when the door fell and leaned on the subcontractor's right knee. The worker not suffer a visible injury, but was in pain. An ambulan transported the worker to a hospital for a check up.	d			NEW BUILDING	121187214	Material Fell	LAM GEN 25 LLC	FLINTLOCK CONSTR SVCS INC
19/2018	Brooklyn	422	FULTON STREET	0 1 The Site Safety Manager reported that a worker was performing demolition work on the roof of a building when he felt pain in his back while lifting a barrel. An	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/19/2018	Bronx	545	EAST 166 STREET	ambulance was called.     The New York City Police Department reported that a     worker was hit by a hoist. A worker was on the eighth     floor securing a piece of wingwall when the stepped up     onna a backet to lock over the gate while trying to     securing plywood. The hoist was on the floor above th     worker and the hoist care down at the same time that     the worker was learning over the gate. The worker was     struck in the head and succurred to his injuries. An     Aggravated Level 2 ECB Violation was issued for the     unsale or improper use of hoist equipment.		38259262J	042018E2807B01			Mechanical Construction Equipment	545 E. 166TH STREET HDFC	
4/20/2018	Manhattan	45	PARK PLACE	1 The Site Safety Manager reported that a carpenter foreman was securing a formwork panel for the shear wall and was repositioning his retractable device with both hooks in one anchor point when the insert gave way, causing the foreman to fail about the feet backwards. The foreman was taken to a hospital.	ECB Violation	35326676H		NEW BUILDING	121185635	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST



cident Det	Borough	Address Non Lon	Streat	stalition Injurion EOC Final Description	DOB Action	ECP Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Ownor's Namo	Contractor Namo
icident Date 20/2018	Borough Manhatlan	Address Number 560	Street F WEST 33 STREET	Statilities         Injuries         EOC Final Description           0         1         Thes Site Sately Manager reported that a worker was climbing up a baker's scatfold when he lost his grip on the second rung of the ladder and fell about two feet. The worker roled over on the sucket and suffered an injury to his ribs. A DOB inspector responded and visit he site and reported that no encoment action was necessary, as the necessary safety measures were provided at the site. Hwas determined that the incident occurred due to a worker's error.	No Action Necessary	ECB Violation Numbers	DOB Violation Numbers	Permit NB	Permit No 1211192618	Incident Type Worker Fell	Owner's Name ERY NORTH TOWER RHC TENANT LLC	Contractor Name Roger & Sons Conctrete Inc
23/2018	Manhattan	400	WEST 61 STREET	The Site Safety Manager reported that at a thrity eight story new building under construction, a plumber was placing a pipe into hangers when the plumber fell off of a ladder. There were no witnesses to the height of the fall, and the plumber draimed to have fallen approximately between five and seven feet. The plumber was found aint, awake, and complaining of pain in his hip. The plumber was taken to SL tuke's Hospital by antivations. A DOB inspector responded and visited the site and determined that there was no enforcement action necessary, as the fall occurred as the result of a worker's error.				121193181	NB	Worker Fell	RCB1 NOMINEE LLC	TISHMAN CONSTRUCTION CORP
3/2018	Queens	147-40	ARCHER AVENUE	0 1 The Site Safety Manager reported that a worker on the first floor bumped his knee on a reshore tripod. The worker went to a City M D	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
24/2018	Brooklyn	540	FULTON STREET	0 1 The Site Safety Manager reported that an iron worker pinched his finger while unloading steel rebar from a truck. The worker left to go to a clinic.	No Dispatch					Other Construction Related Incidents	540 FULTON ASSOCIATES	
26/2018	Manhattan	461	WEST 34 STREET	O     The Size Safety Menninger reported that a worker was or the twenty eight floor of a wear inner larger was substrated and the set of the set of the set of the set of the electrical work when he suffered as out to his hand. A reciprocal blade jammed and the worker's hand got caught. The worker was found awake and alert and wa taken to a nearby hospital.				NB	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	ATRIA BUILDERS LLC
26/2018	Manhattan	225	BOWERY	0 1 It was reported that there were workers that were moving materials on the roof. When the workers move a metal piece together, one of the worker's roight hand got caught in the pinch point. The worker suffered a scrape to his right hand. An ambulance was called to the site. The worker received stitches at Mount Sinai Hospital.					121862751	Worker Fell	VNAA BOWERY LLC	AEH-VSLV, LLC
6/2018	Manhattan	22	NORTH LOOP ROAD	0 1 The Site Safety Manager reported that a worker hit his left hand with a hammer. The worker went to urgent ca	No Dispatch re.					Other Construction Related Incidents		
86/2018	Manhattan	2	PARK PLACE	0 1 The Sile Safety Manager reported that at a fifty seven story building that was under construction, a worker wa cutting metal with a grinder when he cut his left shin. The worker was conscius and alert and walked to Nex York Presbyterian Hospital.	s				121290085	Other Construction Related Incidents	NOT ON FILE	AHEARN-HOLTZMAN, INC
6/2018	Manhattan	1681	3 AVENUE	0 1 The Site Safety Manager reported that a worker was coming down the stairs on a scalfold when he slid dow the stair riser. The worker went to a City M.D.	No Dispatch n					Worker Fell	95TH AND THIRD LLC	
26/2018	Brocklyn	1	CLINTON STREET	0 1 The Site Safety Manager reported that during concrete operations, a laborer was removing concrete key when his finger got scatched between rebar. The worker was working alone and scratched his finger while reaching into formwork. The worker ware to a City M.D. and returned to work in two days.	s			NB	321197478	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
7/2018	Queens	147-40	ARCHER AVENUE	0 1 The Site Safety Manager reported that a worker struck his left thumb with a hammer while hammering a nail. The worker took himself to a City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
30/2018	Brooklyn	109	2 AVENUE	1 The Construction Superintendent reported that a worke was shaking out steel at the street level when he pinched his finger between a two by four and a steel beam. The worker went to urgent care.	r No Dispatch					Other Construction Related Incidents	THE SALVATION ARMY	
30/2018	Manhattan	1059	3 AVENUE	0 1 The Site Safety Manager reported that a pedestrian wert over a ramp in front of the site, piped/tipped on damaged meaks, and fell. The destination suffered an troop beneficial and visited the site and roop beneficial end visited the site and roop beneficial end visited the site and roop of the damaged meak of the General Contractor at the site failed the incident. An Apgravated Level 2 CEN Violation was issued for a failure to safeguard. A partial Stop Work Order was issued on all activities in the occupied lane next to the sidewalk shed. The General Contractor is the maintain the sidewalk shed. The General Contractor is to maintain the sidewalk to ensure that it is free of all tripping hazards.	)	35318046N				Other Construction Related Incidents	GSRD & 3RD NYC LLC	
'30/2018	Manhattan	130	WILLIAM STREET	0 1 The Site Safety Manager reported that a worker was attempting to help a carpenter when he accidentally walked into the swing radius of a harmner and got ht if the forshead by the harmer. The worker was taken to New York Presidentian Hospital and was in stabile condition. A DOB inspector responded and visited the encessary, as the incident occurred as a result of a worker's error.				NB	121192903	Other Construction Related Incidents		GILBANE RESIDENTIAL CONST



cident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
30/2018	Manhaitan	425	PARK AVENUE	0	1 A DOB inspector reported that masons were finishing concrete pouring packs on the sixteenth floor when a worker that was working with the masons removed the floor protection and fell apportuniately thirteen feet from the studenth floor. The Mitter and the state of the suffered a cut to his ear and comparised of head and neck pain. The worker was taken to Cornell University Hospital for observation. Twe CSE Violations were issued for there being no design drawings for floor openings present and for the failure to maintain safety operations. Two partial Stop Work Orders (PSWO) were issued on all work within fen feet of all floor coverings on all floors and for the floor coverings being not properly secured. Two DEB Violations were also issued. A Means and Methods for the installation of floor coverings must be provided.		35326636N / 37P	043018B505GD01/02			Worker Fell	T-C 426 PARK AVENUE, LLC	
1/2018	Manhattan	540	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker suffered	No Dispatch			NEW BUILDING	121191968-01-NB	Other Construction Related Incidents	CLINTON HOUSING DEVELOPMENT	MEGA CONTRACTING GP LLC
1/2018	Manhattan	390	MADISON AVENUE	0	a cut finger. An ambulance was called. 1 The Site Safety Manager reported that a worker on the first floor stepped up on a few concrete masorry unit blocks when he feil approximately three feet off of the blocks and landed on a metal plate. EMS was called and transported the worker to a hospital.	No Dispatch					Worker Fell	COMPTROLLER OF NY STATE	
/2018	Manhattan	222	EAST 41 STREET	0	<ol> <li>The Site Safety Manager reported that a worker was installing metal trim when a cut piece fell down and lacerated his wrist. The worker was sent to a hospital.</li> </ol>	No Dispatch				_	Other Construction Related Incidents	NOT ON FILE	
/2018	Brooklyn	1277	EAST 14 STREET	0	1 The Construction Superintendent reported that a plumber was cutting a metal stud to get to a pipe when he cut his arm on the stud. An ambulance was called.	No Dispatch					Other Construction Related Incidents	1277 HOLDINGS LLC	
2/2018	Mənhattən	10	VANDERBILT AVENUE	0	1 The Site Safety Manager reported that a latherer was coming down from a rebar cage when he missed his last step, fell backwards, and hurt his nike. The worker went to a hospital by ambulance. It was reported that the worker suffered a broken ankle. A DOB inspector responded and visited the site and reported that the worker missepped during a rebar operation, and that the operation was proceeding according to the site plan. No enforcement action was deemed necessary.						Worker Fell	ONE VANDERBILT OWNER LLC	
2018	Manhattan	320	EAST 43 STREET	0	1 The Site Safety Manager reported that a worker was cleaning near the dumpster in the basement C-Level area when he hit his lower leg on a dumpster. The worker was cut, but the bleeding was stopped. The worker does not know how he hurt himself. An ambulance was called.	No Dispatch					Other Construction Related Incidents	FORD FOUNDATION	
2018	Brooklyn	10	HURON STREET	0	1 The Site Safety Manager reported that a worker cut the skin of his finger on a table saw. The worker went to a hospital with a co-worker.	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker got a spark in his eye under his safety glasses during a grinding operation. The worker went to a hospital on his own	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Queens	36-18	MAIN STREET	0	1 The Site Safety Manager reported that a worker was coming down off of a ladder when he lost his balance and grabbed onto a metal stud, causing a cut to two of his fingers. The worker went to urgent care.	No Dispatch					Worker Fell	134-22 35TH AVE., LLC	
2018	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that a worker sliped on rebar and hurt his wrist. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	40-56 TENTH OWNER LLC	
/2018	Manhattan	308	WEST 133 STREET	0		ECB Violation	35323833X, 35323834H		NB	122620333	Worker Fell	308 WEST 133RD STREET LLC	Happy Living Development
1/2018	Brooklyn	810	FULTON STREET	0	2 The Site Safety Manager reported that two workers were trying to install a pipe on top of a baker scaffold when both of the workers leand to wards the same side of the scaffolding, which caused the baker scaffold to collapse. The two workers led approximately four feat and landed on the floor. An ambulance was called, A DOB import were issued cone violation for three being no personnel no site with proper documentation, which would be four hour user cards, and a second EC Violation for a failure to safeguard all persons and property affected by construction operation. A partial Site Work of the has been issued on baker scaffolds until a Means and Methods is provided.		35323694H,35323895J		NB	320597083	Worker Fell	GREENPOINT-GOLDMAN CORP.	Bradway Construction



	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/2018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker was		35318496K	050418BS02JJ01	- crime		Material Fell	NYC DSBS	
					unloading a pallet of glass that was approximately 2' X 8'								
					when the pallet of glass tiped over onto him and pinned him against the wall of the truck. The worker went to a								
					hospital by ambulance. A DOB inspector responded and								
					visited the site and issued an Aggravated Level 2 ECB								
					Violation for a failure to safeguard, as there was no Means and Methods for delivery operations available for								
					the previous delivery operations that happened at the								
					site. A partial Stop Work Order was issued on all								
					deliveries. A Means and Methods for safe delivery operations and Tool Box Talks must be provided.								
					operations and root box raiks must be provided.								
2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker slipped	No Dispatch					Other Construction Related Incidents	NYC HPD	
2010	biookiyii	150	WILLOUGHDT STREET	0	on rebar and cut his right thumb. The worker walked to	NO Dispatori					Citier Construction Related incidents	NICHED	
					the ER.								
2018	Bronx	600	BERGEN AVENUE	0	1 The Site Safety Manager reported that a welder was	No Action Necessary			FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & development
					performing Support Of Excavation (SOE) work when he picked up a steel plate that was 12' X 12' and 3/8 thick								
					when he injured his back. A co-worker took the worker								
					to a City M.D., where a physician recommended medication for pain and rest for three days. A DOB								
					inspector responded to the incident and visited the site								
					and reported that there were no unsafe conditions found								
					and that all of the workers at the site had ten hour OSHA cards. No enforcement action was deemed								
					necessary.								
018	Brooklyn	2085	ROCKAWAY PARKWAY	0	1 The Construction Superintendent reported that a worker	No Dispatch			ALTERATION TYPE 3	340451308-01-EQ-SH	Worker Fell	NYC HOUSING AUTHORITY	SKYWORX CONTRACTING INC
-					from the sidewalk shed company fell four feet while								
					descencing from a baker scaffold. An ambulance took the worker to a hospital.								
2018	Brooklyn	814	BEDFORD AVENUE	0		ECB Violation	35327578Z				Worker Fell	814 PARK LLC	
2018	BLOOKIYN	814	BEDFORD AVENUE	0	Department and the New York City Fire Department	EGB VIOLATION	3332/5/82				VVOIKEF FBII	OIN PARK LLC	
					reported that a worker was stripping concrete form work								
					for the first floor deck when the worker fell approximately fifteen feet into the cellar and landed on capped rebar.								
					The worker was taken to a hospital and was								
					accompanied by another worker. The injured worker did								
					not suffer any life-threatening injuries. An ECB Violation for the failure to maintain safe operations was issued. A								
					full Stop Work Order (FSWO) was also issued.								
					Additional safety violations will be issued.								
2018	Queens	24-02	49 AVENUE	0	1 The Site Safety Manager reported that a worker at the	ECB Violation	35326893Y	050718BS02DH01	ALT1	421518566	Worker Fell	LIC 73 OWNER, LLC	UNITY CONSTRUCTION GROUP
					fourth floor level was struck by duct work that was approximately ten feet high while on a ladder that was								
					approximately eight feet high. The duct work had came								
					loose, swung down, and struck the worker, which								
					caused him to fall off of the ladder. The worker suffered								
					a broken leg and was taken to a nearby hospital. A DOB inspector responded and visited the site and issued an								
					inspector responded and visited the site and issued an ECB Violation for a failure to safeguard. A DOB								
					inspector responded and visited the site and issued an ECB Violation for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also								
					inspector responded and visited the site and issued an ECB Violation for a failure to safeguard. A DOB								
018	Manhattan	250	BRADHURST AVENUE		inspector responded and visited the site and issued an ECB Violation for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued.	No Dispatch					Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
018	Manhattan	250	BRADHURST AVENUE	0	Inspector responded and visited the site and issued an ECB Violation for a failure to asligurand. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a fagade	No Dispatch					Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
2018	Manhatlan	250	BRADHURST AVENUE	0	Inspector responded and visited the site and issued an ECB Violation for a failure to saligurund. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a facade connection. The worker work to alsociate by ambulance	No Dispatch					Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
018	Manhattan	250	BRADHURST AVENUE	0	Inspector responded and visited the site and issued an ECB Violation for a failure to asligurand. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a fagade	No Dispatch					Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
	Manhattan Brooklyn	250	BRADHURST AVENUE	0	Inspector responded and visited the site and issued an ECB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a façade connection. The worker went to a hospital by ambulance to receive sitches on his finger. 1 The Site Safety Manager reported that a host mechanic						Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
				0	Inspector responded and visited the site and issued an ECB Violation on a failure to saligurard. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a fagade connection. The worker went to Anophata by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a host mechanic laverated his finger while cutting a piece of plastic away								
				0	Inspector responded and visited the site and issued an ECB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a façade connection. The worker went to a hospital by ambulance to receive sitches on his finger. 1 The Site Safety Manager reported that a host mechanic								
2018				0	Inspector responded and visited the site and issued an ECB Violation on a failure to saligurard. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a fagade connection. The worker went to Anophata by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a host mechanic laverated his finger while cutting a piece of plastic away	No Dispatch	35331175X						
2018	Brooktyn		4 AVENUE	0	Inspector responded and visited the site and issued an ECB Violation for a failure to saligurund. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a facade connection. The worker work to a hospital by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a host mechanic lacerated his finger while cutting a piece of plastic away from a hoist. A co-worker took him to a hospital. 1 The Site Safety Manager reported that a worker was working on a reabraival when he was struck in the neck	No Dispatch	35331175X				Other Construction Related Incidents	XYZ PROPERTIES INC	
018	Brooktyn		4 AVENUE	0	Inspector responded and visited the site and issued an ECB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a fagade connection. The worker went to a hospital by ambulance to receive stuthes on his finger. 1 The Site Safety Manager reported that a hoist mechanic lacerated his finger while cutting a piece of plastic away from a hoist. A co-worker tock him to a hospital. 1 The Site Safety Manager reported that a worker was working on a rebar wall when he was struck in the neck by disidoged schring. A DOB inspector responded and	No Dispatch	36331175X				Other Construction Related Incidents	XYZ PROPERTIES INC	
018	Brooktyn		4 AVENUE	0	Inspector responded and visited the site and issued an ECB Violation for a failure to saligurand. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Salety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a flapde connection. The worker went to a hospital by ambulance to receive stitches on his finger. 1 The Site Salety Manager reported that a hosit mechanic lacerated his finger while cuting a place of plastic away from a hoist. A co-worker took him to a hospital. 1 The Site Salety Manager reported that a worker was working on a rether wall whole weas struck in the neck by disodged shoring. A DOB inspector responded and viset the site and reported that rechores were installed	No Dispatch	35331175X				Other Construction Related Incidents	XYZ PROPERTIES INC	
018	Brooktyn		4 AVENUE	0 0 0	Inspector responded and visited the site and issued an ECB Violation for a failure to saligurand. A DOB Violation and a full Stop Work Order (FSWO) were also issued. If The Site Salety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a fapade connection. The worker went to a hospital by ambulance to receive stitches on his finger. If The Site Salety Manager reported that a holist mechanic lacentarch is finger while cuting a place of platics away from a hoist. A co-worker took him to a hospital. If The Site Salety Manager reported that a hovier weak working on a real-wared when he was struck in the neck by discloged shoring. A DOB inspector responded and visted the site and reported that reshores were installed contrary to the approved plan. An ECB Violation and a partial Stop Work order (FSWO) on all concrete work	No Dispatch	35331175X				Other Construction Related Incidents	XYZ PROPERTIES INC	
018	Brooktyn		4 AVENUE	0	Inspector responded and visited the site and issued an ECB Violation on a faluer to saleguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a fagade connection. The worker went to a hospital by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a hoist mechanic lacerated his finger while cutting a piece of plastic away from a hoist. A co-worker toch him to a hospital. 1 The Site Safety Manager reported that a worker was working on a rebar wall when he was struck in the neck by dislodged shoring. A DOB inspector responded and visited the site and reported that reshores were installed contrary to the approved plank. A CEB Violation and a	No Dispatch	35331175X				Other Construction Related Incidents	XYZ PROPERTIES INC	
018	Brooklyn Brooklyn	535	4 AVENUE HOYT STREET	0	Inspector responded and visited the site and issued an ECB Violation for a failure to saligurund. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Salety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a facade connection. The worker went to a hospital by ambulance to receive stitches on his finger. 1 The Site Salety Manager reported that a host mechanic lacerated his finger white cutting a pleice of plastic away from a hoist. A co-worker took him to a hospital. 1 The Site Salety Manager reported that a worker was working on a realivrual weak struck in the neck by disolged shoring. A DOB inspector responded and vised the site and reported that reshores were installed contrary to the approved plan. An ECB Violation and a partial Stop Work order (PSWO) on all concrete work were issued.	No Dispatch ECB Violation	35331175X				Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	
018	Brooktyn		4 AVENUE	0	Inspector responded and visited the site and issued an ECB Violation on a failure to saligurand. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a facade connection. The worker went to a hospital by ambulance to receive sathles on his finger. 1 The Site Safety Manager reported that a hoist mechanic lacerated his finger while cutting a piece of plastic away from a hoist. A co-worker took him to a hospital by dialodged shoring. A DOB inspector responde and visited the site and reported that a worker was working on a rebar wall when he was struck in the neck by dialodged shoring. A DOB inspector responde and visited the site and reported that reshores were installed contrary to the approved plan. A reCS Violation and a partial Stop Work order (PSWO) on all concritete work were issued.	No Dispatch ECB Violation	36331175X		NB	121191646	Other Construction Related Incidents	XYZ PROPERTIES INC	T.G. NICKEL & ASSOCIATES
018	Brooklyn Brooklyn	535	4 AVENUE HOYT STREET	0	Inspector responded and visited the site and issued an ECB Violation for a failure to saligurund. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Salety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a fazade connection. The worker went to a hospital by ambulance to receive stitches on his finger. 1 The Site Salety Manager reported that a host mechanic lacerated his finger white cutting a pleice of plastic away from a hoist. A co-worker took him to a hospital. 1 The Site Salety Manager reported that a worker was working on a realivrual when the worker works working on a end reported that reshores were installed contrary to the approved plan. An ECB Violation and a partial Stop Work order (PSWO) on all concrete work were issued.	No Dispatch ECB Violation	35331175X		NB	121191646	Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	T.G. NICKEL & ASSOCIATES
2018	Brooklyn Brooklyn	535	4 AVENUE HOYT STREET		Inspector responded and visited the site and issued an ECB Violation for a failure to saligurand. A DOB Violation and a full Stop Work Order (FSWO) were also issued. The Site Salety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a flapde connection. The worker went to a hospital by ambulance to receive stitches on his finger. The Site Salety Manager reported that a host mechanic lacerated his finger while cuting a place of plastic away from a hoist. A co-worker took him to a hospital. The Site Salety Manager reported that a worker was working on a rether wall whole weas struck in the neck by disdoged shoring. A DOB inspector responded and viset dhe site and reported that reshores were installed contrary to the approved plan. An ECB Violation and a partial Stop Work order (PSWO) on all concrete work were issued.	No Dispatch ECB Violation	35331175X		NB	121191646	Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	T.G. NICKEL & ASSOCIATES
2018 2018 2018	Brooklyn Brooklyn	535	4 AVENUE HOYT STREET	0 0 0	Inspector responded and visited the site and issued an ECB Violation for a failure to saligurari. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a fagade connection. The worker went to a hospital by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a hospital by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a hospital by moving on a reador with the table state and working on a reador was full to the table state by disdoged shoring. A DOB inspector responded and visited the site and reported that reshores were installed partial Stop Work order (PSWO) on all concrete work were issued. 1 The Site Safety Manager reported that a to kerty site source of the state of the state of the state of the neck by disdoged shoring. A DOB inspector responded and partial Stop Work order (PSWO) on all concrete work were issued. 1 The Site Safety Manager reported that a to kerty site source on site when he stepped on loose concrete masony and turned his ankle. The worker was found altert and awake. The on-site medic issued ice for on-	No Dispatch ECB Violation	36331175X		NB	121191646	Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	T.G. NICKEL & ASSOCIATES
018	Brooklyn Brooklyn	535	4 AVENUE HOYT STREET	0 0 0	Inspector responded and visited the site and issued an ECB Violation for a failure to saligurand. A DOB Violation and a full Stop Work Order (FSWO) were also issued. The Site Salety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a flapde connection. The worker went to a hospital by ambulance to receive stitches on his finger. The Site Salety Manager reported that a host mechanic lacerated his finger while cuting a place of plastic away from a hoist. A co-worker took him to a hospital. The Site Salety Manager reported that a worker was working on a rether wall whole weas struck in the neck by disdoged shoring. A DOB inspector responded and viset dhe site and reported that reshores were installed contrary to the approved plan. An ECB Violation and a partial Stop Work order (PSWO) on all concrete work were issued.	No Dispatch ECB Violation	35331175X		NB	121191646	Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	T.G. NICKEL & ASSOCIATES
2018 2018 2018	Brookiyn Brookiyn Manhattan	535	4 AVENUE HOYT STREET DELANCEY STREET		Inspector responded and visited the site and issued an ECB Violation for a failure to saligurad. A DOB Violation and a full Stop Work Order (FSWO) were also issued. The Site Salety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a fazade connection. The worker went to a hospital by ambulance to receive stitches on his finger. The Site Salety Manager reported that a host mechanic lacerated his finger while cuting a pleice of plastic away from a hoist. A co-worker took him to a hospital. The Site Salety Manager reported that a worker was working on a rebraval whon he was struck in the neck by disdoged shoring. A DOB inspector responded and visited the site and reported that a worker was working on a rebraval whon he was struck in the neck by disdoged shoring. A DOB inspector responded and visited the site and reported that a towerty was sconing back on site when he stepped on loose correte masory and tume his ankie. The worker was found alert and awake. The on-site medic issued loss	No Dispatch ECB Violation No Dispatch	36331175X		NB		Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	
2018	Brooklyn Brooklyn	535	4 AVENUE HOYT STREET		Inspector responded and visited the site and issued an ECB Violation for a failure to saligurar. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a fagade connection. The worker went to a hospital by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a host mechanic lacerated his finger while cuting a plece of platic away from a hoist. A co-worker took him to a hospital. 1 The Site Safety Manager reported that a worker was working on a reabir wall show the was struck in the neck by disologied shoring. A DOB inspector responded and point stop Work order (PSWO) on all concrete work were issued. 1 The Site Safety Manager reported that a twerty six coming back. The on-Site method construction, a worker was coming back. The on-Site method concortee masony and turned his ankle. The worker was found altert and awake. The owsfer was found alter tand awake. The owsfer was found alter and awake. The owsfer etament.	No Dispatch ECB Violation No Dispatch	35331175X		NB NEW BUILDING		Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	T.G. NICKEL & ASSOCIATES
2018 2018 2018	Brookiyn Brookiyn Manhattan	535	4 AVENUE HOYT STREET DELANCEY STREET		Inspector responded and visited the site and issued an ECB Violation for a failure to saligurad. A DOB Violation and a full Stop Work Order (FSWO) were also issued. The Site Salety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a fazade connection. The worker went to a hospital by ambulance to receive stitches on his finger. The Site Salety Manager reported that a host mechanic lacerated his finger while cuting a place of plastic away from a hoist. A co-worker took him to a hospital. The Site Salety Manager reported that a worker was working on a rebraval whon he was struck in the neck by disodged shoring. A DOB inspector responded and visited the site and reported that a worker was working on a rebraval whon he was struck in the neck by disodged shoring. A DOB inspector responded and visited the site and reported that a towerty was sconing back on site when he stepped on loose correte masory and tume his ankie. The worker was lound alert and awake. The on-site medic issued lose for on-site treatment and he worker work to a nearby urgent care center to receive further treatment. The Site Salety Manager reported that at a towerty six sconing back on site when he stepped on loose correte masory and tume his ankie. The worker was lound alert and awake. The on-site medic issued los for visite treatment of the worker worke to an anaity urgent care center to receive further treatment.	No Dispatch ECB Violation No Dispatch	35331175X		NB NEW BUILDING		Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	
2018 2018 2018	Brookiyn Brookiyn Manhattan	535	4 AVENUE HOYT STREET DELANCEY STREET		Inspector responded and visited the site and issued an ECB Violation on a falue to saligural. A DOB Violation and a full Stop Work Order (FSWO) were also issued. 1 The Site Safety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a fagade connection. The worker went to a hospital by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a hospital by ambulance to receive stitches on his finger. 1 The Site Safety Manager reported that a hospital by moving on a readward worker took him to a hospital. 1 The Site Safety Manager reported that a host mechanic working on readward worker tows move the neck by diadoged shoring. A DOB inspector responded and visited the sate and reported that reshores were installed coartial Stop Workprovert Joy Ko DOB on all concrete work were issued. 1 The Site Safety Manager reported that a newser was coming back. The on-site mechanic succession alter and awake. The on-site mechanged on loose econcrete masory and turned his ankle. The worker was found alter and awake. The on-site metament. 1 The Site Safety Manager reported that a newser was coming back. The on-site metament. 1 The Site Safety Manager reported that a newser was coming back. The on-site metament.	No Dispatch ECB Violation No Dispatch No Dispatch	35331175X		NB NEW BUILDING		Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES ING 11 HOYT PROPERTY OWNER, L.P. CP V TS FULTON OWNER, LLC	
018	Brooklyn Brooklyn Manhattan	535 11 115 115 118	4 AVENUE HOYT STREET DELANCEY STREET		Inspector responded and visited the site and issued an ECB Violation for a failure to saligurad. A DOB Violation and a full Stop Work Order (FSWO) were also issued. The Site Salety Manager reported that a worker cut his finger on a table saw while cuting zinc clips for a fazade connection. The worker went to a hospital by ambulance to receive stitches on his finger. The Site Salety Manager reported that a host mechanic lacerated his finger while cuting a place of plastic away from a hoist. A co-worker took him to a hospital. The Site Salety Manager reported that a worker was working on a rebraval whon he was struck in the neck by disodged shoring. A DOB inspector responded and visited the site and reported that a worker was working on a rebraval whon he was struck in the neck by disodged shoring. A DOB inspector responded and visited the site and reported that a towerty was sconing back on site when he stepped on loose correte masory and tume his ankie. The worker was lound alert and awake. The on-site medic issued lose for on-site treatment and he worker work to a nearby urgent care center to receive further treatment. The Site Salety Manager reported that at a towerty six sconing back on site when he stepped on loose correte masory and tume his ankie. The worker was lound alert and awake. The on-site medic issued los for visite treatment of the worker worke to an anaity urgent care center to receive further treatment.	No Dispatch ECB Violation No Dispatch No Dispatch	35331175X		NB NEW BUILDING		Other Construction Related Incidents Other Construction Related Incidents Other Construction Related Incidents	XYZ PROPERTIES INC	



ncident Date	Borough	Address Number	Street	Fatalities Injurie			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
10/2018	Queens	54-17	101 STREET	0	2 New York City Emergency Management reported that two workers that were working on wires on the bulkhaad when they experienced electric shocks. The workers were able to make it down from the bulkhaad and were imaniporties to a hooghalt. A Dob impector responded to the incident and visited the site and issued two ECS Violations for the exposend rule numl not being provided and for the exposed wires at the bulkhaad area not being properly terminated, secure, and protected around the HVAC air handler unit. A partial Stop Work Order (PSWO) was also issued tor electrical work.	ECB Violation	35313352Z 35313353K				Other Construction Related Incidents	HANAC CORONA HOUSING DEV. FUND	
10/2018	Manhattan	80	EAST10 STREET	0	1 The Site Safety Coordinator reported that a worker was moving pallets of concrete block around when some of the concrete block fell off and struck the workers right leg. An ambulance was called and the worker went to a hosphal for treatment. A DOB inspector responded and visited the site and reported that the worker pulled the stationary part of the pallet jack while pulling the concrete block onto Intraell. It was determined that this incident occurred as the result of a worker's error, and that no enforcement action was necessary.	No Action Necessary			NB	121193476	Other Construction Related Incidents		CONY CONSTRUCTION INC
10/2018	Manhattan	7	WEST 57 STREET	0	<ol> <li>The Site Safety Manager reported that a worker felt discomfort in his shoulder during stripping operations.</li> <li>The worker took a cab to a clinic on his own.</li> </ol>	No Dispatch					Other Construction Related Incidents	7 WEST 57TH STREET REALTY COMP	
/10/2018	Manhattan	515	WEST 36 STREET	0	1 The Site Safety Manager reported that a worker was pushing a cart when he tripped on planks that were covering a hole. The workers etitied a cut to his right hand and went to a hospital. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for the improper covering of holes.	ECB Violation	35331118J				Other Construction Related Incidents	FIRST ST MARKS LLC	
/10/2018	Manhattan	424	EAST 34 STREET	0	1 The Site Safety Manager reported that a tapper tried to move an 'A'-Frame with masonite on it out of his way by himself when he tipped the 'A'-Frame and was hit in the right shin by both the 'A'-Frame and the masonite. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NYU HOSPITALS CENTER	
10/2018	Brooklyn	8	NEVINS STREET	0	1 The Sile Safety Manager repoted that a worker was stripping form work on the eighteenth floor when a post fell forward and hit him in the back. The worker appendenced back present the back the work of the construction of the same stripping post reported that another worker had leaned a stripping post against a wall instead of stacking the post and he post slid from an upright postion and hit the injured worker. An EGB Volation was lawd for a failure to institute/follow safety measures for stripping operations. A DOB Violation was also issued.	ECB Violation	35326856P	051018BS/02JJ01			Material Fell	NEVINS STREET OWNER LLC	
10/2018	Bronx	1410	STORY AVENUE	0	A DOB inspector reported that a worker was sitting on top of a boars assitting joists and hear just landed a joist when the signal man signalized to the crane operator to hoist up with steel chokers (no load) on the hook. While hoisting up, one of the chokers assaged the joist and picked true. The worker who had landed the joist tief of get out of the way from the joist, but load is balance and fell two stories to the ground. The worker was not tied off. Other workers at the site reported that the injured worker was bleeding from the mouth and was experiencing severe pain in his law, but was to take the worker was taken to Lincoln Hospital by ambulance. The Host Machine Operator (HAO.) at the site stated that he was standing not to the crane operator's cab as some of the load on the link of the site and the hoist up vior and to the trane operator's cab as the load Machine Operator (HAO.) at the site stated that he was standing not to the crane operator's cab as the load the date. The lift director was not the General Contractor and the crane operator. A kull Sop Work Order (SVW) was issued to the General Contractor and the crane operator. A lull Sop Work Order (SVW) was issued to the trane operator. A lull Sop Work Order (SVW) was issued to the General Contractor and the crane operator. A lull Sop Organization Superintendent on site as of the time of inspecton, as well as a partial Sop Work Order (PSWV) for the unsale placement of site and Methods for the safe operations of steel placement must be provided.		35327286R 35327285P	051018BS09VP01,02			Worker Fell	BR-2012 REALTY LLC	
1/2018	Staten Island	2655	RICHMOND AVENUE	0	1 The Site Safety Manager reported that a worker cut his right thumb while installing duct work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
/11/2018	Manhattan	553	WEST 30 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder and suffered a cut to his right leg when the grinder kicked back. The worker was taken to a hospital by an ambulance.	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	



ncident Date	Borough	Address Number	Street	Fatalities Injurios	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
11/2018	Manhattan	425	PARK AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker cut his finger while using a band saw and suffered a minor gash to his finger. An ambulance was called.</li> </ol>	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
1/2018	Manhattan	357	EAST 57 STREET	0		ECB Violation	35245543J	051118CERJM01	ALTERATION TYPE 2	123179951-01-EW-OT	Material Fell	357 EAST 57 STREET CONDOMINIUM	EDRAS GROUP CORP
11/2018	Manhattan	305	WEST END AVENUE	0		ECB Violation	35331190Y				Material Fell	305 WEST END PROPERTY, LLC	
11/2018	Brookiyn	76	NORTH 6 TH STREET	0	The Construction Superintendent reported that a worker was cleaning a paint gun when his finger was injured by the pressure from the nozzle. The worker went home to see his doctor due to pain in his finger.	No Dispatch					Other Construction Related Incidents		
12/2018	Manhattan	42	WEST 33 STREET	0	<ol> <li>The Site Safety Manager reported that a worker twisted his knee on Saturday, May 12, 2018. This incident took place on May 12, 2018, but was reported on Monday, May 14, 2018. The worker walked himself to a hospital.</li> </ol>	No Dispatch			NEW BUILDING	121186849-01-NB	Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
/12/2018	Manhattan	500	WEST 25 STREET	0	1 The Site Safety Manager reported that workers were removing material from the grade level at the leading dege when two pleces of catason plings that were easily a strain the safety of the safety of the safety of catason plings fail approximately filteren foet and struck a worker that was in the eacurvation pit in the leg. The worker went to a hoopital. The status of the worker's injuries is unknown. A DOB inspector responded and visited the site and issued four ECB violations for the absectione of too boards at the guardrafts, the presence of nadequate vertical noting, the presence of an inadequate quardial that was not constructed to code, partial Stop Work Order (PSWQ) and four DOB Violations were also issued. The contractor is to provide a Means and Methods and a Toolbox Talk for the safe continuation of work.	ECB Violation	35331325M/26Y/27X/28H	051218BS04PK01/02/03/04			Other Construction Related Incidents	500 W25TH OWNER LLC	
14/2018	Brooklyn	211	72 STREET	0	<ol> <li>The New York City Fire Department reported that a worker was walking on a scaffold on the second level when he tripped and hurt his knee. The worker was taken to a narea hospital.</li> </ol>	No Dispatch			A2 - ALTERATION TYPE 2	302579662	Worker Fell	DEPARTMENT OF EDUCATION	KG CONSTRUCTION SERVICES
/14/2018	Brocklyn	7	WHIPPLE STREET	0	The Construction Superintendent reported that workers were installing Q-decking on the second floor when a worker elil from the second floor on the first floor deck. The worker was found conscious and was transported to Bellevue Hospital. Additional information regarding the injuries was not available. The Construction Superintendent was not on site as of the time that the incident occurred. An DOB inspector responded and visited the site and issued an ECE Violation to the General Contractor for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) was also issued.	ECB Violation	35308771R	051418CNEDG01	Ait 1 / NB	321285275	Worker Fell	WHIPPLE PROPERTIES LLC	SUNSHINE CONSTR USA INC
14/2018	Manhattan	150	FIFTH AVENUE	0	1 A DOB inspector reported that there were workers moving steel beams with an electric hoist through a shaftway for an alteration on a twelve story building. The workers moved the beams by pipe rollers on the ground to be stacked. One of the workers was adjusting the stack when he was struck by two other workers that were puting steel in place. The struck workers got his right hand crushed between two beams and was taken to Beth israel hospital for tradment. An ECB Violation for a failure to safeguard was issued. A partial Stop Work Order (PSWO) was issued on all work in shthway hoisting materials. A Means and Methods and a Toobox Talk must be provided.	ECB Violation	35331133H-FAIL TO SAFEGUARD.		ALT1	122700292	Other Construction Related Incidents	150 STH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
15/2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was on the roof setback setting roof pavers when he stepped in a hole with the roof pavers that he was working on and hit his right shin. The worker was conscious and alert and walked to a City M.D. to be checked out.	No Dispatch			ALT1	121324343	Worker Fell	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
15/2018	Manhattan	627	GREENWICH STREET	0	1 The Site Safety Manager reported that a plumber slipped off of the fourth step of a ladder that he was working on and suffered a sprained ankle. An ambulance was called.	No Dispatch					Worker Fell	627 GREENWICH OWNER LLC	



ncident Date		Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
15/2018	Manhattan	500	WEST 33 STREET	0	1 A DOB inspector reported that materials that were stored in the stanging area were blown away due to wind. Among the stored materials was a piece of styroloam that was approximately 8X 3X 3Y that struck a security guard in the back. The security guard complained of pain and was taken to a hospital in a conscious state with an unknown riguy. An ECB Violation was issued, as well as a paint Sloby Work Order (PSWO) for all work in the staging area due to a failure to secure stored material. The General Contractor is to provide a Means and Methods for a safe storage procedure.	ECB Violation	35328900X				Other Construction Related Incidents	NOT ON FILE	
5/2018	Manhattan	20	BROAD STREET	0	1 The Site Safety Manager reported that a worker tripped on debris and fell on his back. An ambulance was called. A DOB inspector responded and visited the site and reported that no enforcement action was necessary, as the incident occurred as the result of a worker error. The work the following day.						Worker Fell	NY STOCK EXCHANGE BLDG. CO.	
5/2018	Machattan	100	EAST 104 STREET	0	2 The New York City Police Department reported that debris was failing from the building. A DOB inspector responded and visited the site and reported that at the fifteemh floor sotback, sections of isolation and plymod tarteet level along Park Avenue, a kiting has individuals. One of the individuals that was struck was taken to a local hospital. An Apgravated Level 2 ECB Violation was issued for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued.	ECB Violation	35309489H	051518CNEGS02	NEW BUILDING	121192887-01-NB	Material Fell	TERRACE ON THE PARK LLC	GLENWOOD CONSTRUCTION
5/2018	Manhattan	1	WALL STREET	0	1 The Site Safety Manaer reported that a worker was setting up needle beams when a portion of screw jack left onto the worker when he beart down. The struck worker complianed of neck pain and left the site to visit his own doctor. A DOB rspector responded to the incident and visited the site and issued an ECB Violation for a failure to maintain safe operations and a partial Stop Work Order (PSWO) on the use of all needle beams. A Means and Methods and a Toolbox Tafk must be provided. An additional ECB Violation will be issued for the installation of a pipe scaffold that was done contrary to the design plans.	ECB Violation	35327019M				Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
5/2018	Brooklyn	626	SHEEPSHEAD BAY ROAD	0	1 The Project Manager reported that a painter was on a ladder on the third floor when he misused the ladder and slipped off. The worker fell approximately six fee and hurt his shoulder. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NEPTUNE SOUTH COMMERCIAL LLC	
5/2018	Brooklyn	416	KENT AVENUE	0	2 A DOB inspector reported that approximately 50°-0" linear feet of sidewalk shed deck and paraget deck enclosure had blown off of a sidewalk shed and onto the street, injuring two padestrians. The two padestrians were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to remove the debris from the steet. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard the public and property. A DOB Violation was also issued. A parail Stop Work Order (PSWO) was issued on all crane and exterior operations, except for work to make safe the installation of a sidewalk shed.	ECB Violation	35322610R	051518CERSM05	NEW BUILDING	320622616-01-NB	Material Fell	420 KENT AVENUE LLC	ZDG, LLC
5/2018	Bronx	1017	HOME STREET	0	1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall fell, hit a generator, and then bounced off the generator and landed on the worker's leg. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that safety measures were not in place for bearing wall installation. An ECB Violation and a DOB Violation were issued, as well as a partial Stop Work Order (PSWO) on all bearing wall installations. A Means and Methods and safety measures for bearing wall installations must be provided.	ECB Violation	35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
6/2018	Manhattan	44	UNION SQUARE EAST	0	<ol> <li>A competent person at the site reported that a worker was removing a vertical shoring post when his finger got caught between the safety pin and the plate. The worker suffered a swollen finger and went to a hospital on his own</li> </ol>						Other Construction Related Incidents	READING TAMMANY OWNER LLC	
6/2018	Manhattan	76	11 AVENUE	0	own. 1 The Site Safety Manager reported that a foreman was hanging an eight inch steel pipe when he lost control of he pipe. The foreman was then incocked off of a ladder by the pipe. An ambulance was called. A DOB inspector respond and wisited the site and reported that the anchor from which the pipe was to be hung from failed. An ECB Violation was issued for a failure to maintain safe operations.		35331136N				Other Construction Related Incidents	76 ELEVENTH AVENUE PROPERTY OW	
16/2018	Queens	45-07	COURT SQUARE	0	1 The Site Safety Coordinator reported that a worker was using a four inch grinder when the grinder kicked back and cut the worker's left arm. The handle and grinder guard were in place. The worker was conscious and awake and went to Mount Sinai Hospital for treatment.	No Dispatch			NB	420902410	Mechanical Construction Equipment	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S



ncident Date	Borough	Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/2018	Queens	2100	49 AVENUE	0	1 The Construction Superintendent reported that an	No Dispatch			ALT1	420656686	Worker Fell	2100 49TH AVENUE OWNER, LLC	ARCHSTONE BUILDERS LLC
					electrician was re-adjusting a ladder when he fell approximately five feet off of the ladder. The worker								
					complainted of back pain and was taken to Elmhurst Hospital, The worker was alert and awake.								
	2	101	PENNSYLVANIA AVE		1 The Construction Superintendent reported that while	No Dispatch			NB	320622894	Other Construction Related Incidents		CAULDWELL WINGATE CO LLC
/2018	Queens	101	PENNSYLVANIA AVE	U	working on a seven story new building, a project				NB	320622894	Other Construction Related Incidents		CAULDWELL WINGATE CO LLC
					manager picked up a sheet metal that cut his finger. The project manager went to urgent care.	9							
					project manager went to urgent care.								
2018	Manhattan	112	EAST 11 STREET	0	1 The Site Safety Manager reported that a worker was	No Action Necessary					Worker Fell	UD-DEV ASSOCIATES LLC	
					coming down a gang ladder when he slipped on the third step of the ladder and fell three feet. The worker								
					complained of back pain. An ambulance was called. A								
					DOB inspector responded and visited the site and found no unsafe conditions present as of the time of								
					inspection. No enforcement action was necessary.								
/2018	Brooklyn	138	WILLOUGHBY STREET	0	2 A DOB inspector reported that a signalman had landed	No Action Necessary			CN	773/17	Worker Fell	NYC HPD	Trident General Contracting, GC lend le
					a banded load on the top deck with a tower crane. The rigging was released after the load was landed, and the								
					load shiftled and startled another worker that was								
					carrying pieces of rebar. The worker tripped, fell, and hurt his ankle. The worker was taken to a hospital for X-								
					rays. The signalman suffered a cut to his finger from the								
					banding after releasing the rigging and went to a City								
					M.D. for treatment. There were no witnesses to the worker falling. No enforcement action was necessary, as	3							
					it was determined that the signalman suffered a cut due to a worker error.								
					to a worker error.								
/2018	Bronx	1903	WEST FARMS ROAD	0	1 The Site Safety Manager reported that a worker was performing insulation work behind a stud wall when she	No Dispatch					Material Fell	SAMARITAN-COMPASS V HOUSING DE	
					pushed a stack of sheetrock that was leaning against a								
					wall, which caused the boards to fall forward and hit her in the leg. An ambulance was called.								
					in the leg. An ambulance was called.								
3/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	1 The Site Safety Manager reported that a worker cut his finger on a piece of sheet metal. The worker went to	No Dispatch					Other Construction Related Incidents	ATLANTIC 2644, LLC	
					urgent care.								
/2018	Brooklyn	422	FULTON STREET	0	1 A DOB inspector reported that a crane was making a routine lift of a steel I-Beam from a trailer bed in the	No Action Necessary			CN	80/17	Mechanical Construction Equipment	NOT ON FILE	FJM- Ferro Inc
					street to the roof. The beam was rigged up and the								
					signal man gave the crane operator the signal to come up with the load. The crane had lifted the load								
					approximately two feet off of the bed of the trailer when								
					an iron worker attemped to steady the load to keep the l Beam from swaying. When the iron worker did this, he	-							
					had put his leg inbetween the moving load and a								
					stationary beam on the flatbed truck. When he did this, the worker created a pinch point, and the moving load								
					struck the worker's leg and caused a cut. The worker								
					was taken to a hospital with non-life threatening injuries. The DOB inspector found no violating conditions during								
					his inspection, as all of the workers at the site had the appropriate 16 or 32 hour rigging certification cards, the								
					slings were found tagged and adequate, the lift director								
					had logs, and the signal man had his card. No								
					enforcement action was necessary.								
2018	Brooklyn	578	COZINE AVENUE	0	1 A DOB inspector repored that a worker was performing	ECB Violation	35322901R 35322902Z	051818CERRJ03 051818CERRJ04	Abatement		Worker Fell	NYBC REALTY LLC	GSC Services Corp
					asbestos abatement work on the roof when he fell approximately twenty feet through the roof. The worker								
					was taken to Brookdale Hospital. The abatement work								
					was being performed as per the posted notice. Two Aggravated Level 2 ECB Violations for a failure to								
					safeguard were issued to the abatement company and								
					building owner. A partial Stop Work Order (PSWO) was issued for all work at the roof level. The contractor at the								
					site is to provide a Means and Methods for the safe removal of material from the roof level.								
					removal of material from the root level.								
/2018	Brooklyn	6	METROTECH	0	1 A New York City Police Officer reported that a plumber was working on a pipe on the fifth floor when the pipe	No Action Necessary			PLUMBING	321562288	Mechanical Construction Equipment	NEW YORK UNIVERSITY	VITO M. GIACHETTI
					burst and hit the plumber in the chest and chin. An								
					ambulance was called. A DOB inspector responded to the incident and visited the site and determined that								
					there was no enforcement action necessary, as the job								
					had on-site active Department Of Buildings permits and approved technical plans.								
10045	Markana					FORMULAT	0700110001				010		
/2018	Manhattan	130	WILLIAM STREET	0	<ol> <li>The Site Safety Manager reported that a ten feet long piece of rebar that was standing vertically and was to be</li> </ol>	ECB Violation	35331400N				Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	
					installed fell on a worker that was standing on the ground, hitting him in the side of his hard hat. The								
					worker went to a City M.D. A DOB inspector responded								
					and visited the site and issued an ECB Violation for a failure to maintain safe operations, as well as a partial								
					Stop Work Order (PSWO) for all concrete operations.								
					The General Contractor at the site is to provide a Means and Methods and a Tool Box Talk.	5							
					ano metrious anu a roor dox raik.								



cident Date	Borough	Address Number	Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
21/2018	Bronx	2865	CRESTON AVENUE	0	1 The Site Safety Managor reported that a worker was putting up forms on a column when he fell about six to seven feet and injured his foot. The worker was sent to a hospital. A DOB inspector responded and visited the site and found that a hook that was holding form up was duranged, which may have possibly caused the worker to fail. An ECB Violation for the failure to maintain astely offset (FSW) for all concrete awork. Additional ECB Violations were also issued for infractions that were not related to the incident.	ECB Violation	35327296K, 35327297M, 98, 99X,3531840OR, 01Z				Worker Fell	10 MINERVA PLACE HOUSING DEVEL	
1/2018	Bronx	4215	PARK AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker fell from the top of a hoist that was stopped on the first floor. The worker suffered minor injuries and was transported to a hospital by ambulance.</li> </ol>	No Dispatch			NEW BUILDING	220157700-01-NB	Worker Fell	TREMONT RENAISSANCE HOUSING DE	JOY CONSTRUCTION CORP
21/2018	Manhattan	247	WEST 87 STREET	0	2 The New York City Pelice Department reported that hwo workenersers in the process of Installing a supported of the New York Pelice Pelice Pelice Pelice pipe scaffold. The worken suffered scapes and burrys in their hands and logs and were taken to St. Lukes Hospital. A DOB inspector responded to the incident and visited the site and issued two Aggravated Level 2 CR2 Violations. The first violation was issued for the removal or alteration of the supported scaffold by the General Contractor before the inspector's arrival, which is the removal of equipment, structural material, or evidence that is related to an incident. The second violation was issued for a failure to promptly notify the Department OF Buildings of the incident, as the incident was reported by the NYPD.	ECB Violation	35324011Y - 35324012X		MA		Worker Fell	KSB BROADWAY ASSOCIATES	Jerrick Associates Inc
21/2018	Queens	30-02	39 AVENUE	0	1 The Site Safety Manager reported that a worker was cutting a metal stud when he cut his hand. An ambulance was called.	No Dispatch					Other Construction Related Incidents	30-02 ASSOCIATES LLC	
23/2018	Staten Island	149	PROVIDENCE STREET	0	antibilitative was called 1. The New York City Office Of Emergency Management reported that a worker full from the structure. EMS mespondet to the incident and willing the acity two ECB Violations for the failure to safeguard and for the failure to netly the Department OF Buildings of the incident. A full Stop Work Order (FSWO) was also issued.	DOB Violation	35322904M/06Y	052318CERRJ01/02	ALT 1	520323212	Worker Fell	PERRI, ALFONSO	A. FONTANA & SONS LLC
23/2018	Manhattan	76	11 AVENUE	0	1 The Site Safety Managor reported that a worker was builting the walk-out for a tower crains and was standing on the crane's lie-back beam when he slipped off of the beam and fell. The worker was warring fail protection equipment. The worker did not suffer an injury, but was taken to a hospital for preacutionary observation. A DOB inspector responded to the incident and visited the site and reported that no enforcement action was necessary.						Worker Fell	76 ELEVENTH AVENUE PROPERTY OW	SBF Construction
23/2018	Manhattan	26	1 AVENUE	0	1 A New York City Police Officer reported that a worker fell approximately five stories or fifty feet from an unguarded section of pipe scaffield. The worker was in critical condition and was taken to Bellevue Hospital. A DOB inspector responded to the incident and visited the site and reported that it could not be determined what caused the worker to fall, as the people that the inspector interviewed claimed to have not seen or know about the incident. Four EGS Visitations were issued for the failure to safeguard, for the presence of a suppoted scaffield that was not built according to code and was messing guardials, missing the boards, and was not have setting the failure to provide a four how supported set. and for the failure to provide a four how supported scaffield uter card upon request. A partial Stop Work Order (PSWO) was also issued.		35324057J, 35324058L, 35324059N, 35324060K		Ait	140761995	Worker Fell	DROBENKO NICHOLAS	Lime-Light Construction Co
24/2018	Brookiyn	2837	WEST & STREET	0	1 The Project Manager at the site reported that during the installation of concrete panel around a bulkhead, a panel cracked, fell, and ccaused a minor cut to a worker's hands. The worker went to a clinic and then came back to the site on the following day. A DOB inspector responded to the incident and visited the site and reported that Means and Methods was in place at the site, and that the workers were following the Means and Methods. The suction cap equipment was found to be in working condition. The inspector observed that the concrete panel may have broken because the concrete pater as a site. No enforcement action was deemed necessary.						Material Fell	AISD CORP.	
24/2018	Brooklyn	41	BLUE SLIP	0	1 The Site Safety Manager reported that the driver of a concrete truck was washing out his truck when he hopped of a ladder and turned his ankle. EMS was called and the worker was sent to a nearby hospital.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT F LLC	



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
Incident Date 5/24/2018	Brookyn Brookyn	Address Number 420	Street EAST 21 STREET	Fatalities Injuries	ECC Final Description 1 The New York Circy Fire Department requested that an inspection plasses be performed due to a retaining wall collapse. A DOB inspection responded and visited the site and reported that the building owner was performing work on the retaining wall hast was separating 420 and 142 East 21 Sterest Wene a section of the retaining wall that the section of the retaining wall that was expendited and that East 21 Sterest Wene as exclusion of the retaining wall that was expension of the retaining wall that was expension for the presence of the retaining wall that was expension four The potential of a further collapse eliminated a atle path of geness from the fire escape along Exposure Four to the streat and compromised the stability of 12 East 21 Streaf's garage and driveway. During search operations, an TPDNV firefighter suffered a mnoximation and wo DOB Violations were issued at 420 East 21 Street for afalure to safeguard and for work being performed without a permit. A full Stop Work Order (FSWQ) and a partial Vacate Order were also issued at 420 East 21 Street A DOB Violation and a full		ECB Violation Numbers 35322725R, 35423726Z	DOB Violation Numbers 052418CNESC04, 05, 052418CNE01SC	Permit	Permit No	Incident Type Other Construction Related Incidents	Owner's Name HOSSAIN, GOLAM	Contractor Name
5/24/2018	Brooklyn	84	CARLTON AVENUE	0	Vacate Order were issued the garage of 412 East 21 Street. (412 Garage East 21 Street).  1 A competent person at the sile reported that a worker was installing roof protection when the worker tripped on a piece of phywodra die (11: the worker was sent to a	No Dispatch					Other Construction Related Incidents	NYC HOUSING AUTHORITY	
5/24/2018	Manhattan	233	WEST 125 STREET	0	hospital for a check up. 1 The Site Safety Manager reported that a worker slipped	No Dispatch			NEW BUILDING	121187447-01-NB	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
5/25/2018	Manhattan	24	2 AVENUE	0	while coming down from a ladder. The worker was taken to a hospital by EMS. 1 The Site Safety Manager reported that a worker cut his arm with a sheetrock knife while cutting sheetrock. The worker went to a nearby urgent care facility to receive						Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	
5/25/2018	Queens	28-07	JACKSON ÄVENUE	0	medical attention. 1 A DOB inspector reported that there was a six man team 1 A DOB inspector reported that there was a six man team that was dismantling support columns when one of the columns was released before one of the workers had a hold of the column. The column struck this worker to the ground. The worker was found alert and responsive. The worker din of suffer a serious injury, but was taken to a hospital by ambulance as a precaution. Documentation was provided to show that the worker attended a pre-job meeting and that the worker attended a the centorement action was necessary and that the incident occurred as the result of a worker error.				ALT 1 NB	420656873	Meterial Fell	UC SITE B-1 OWNER, LL.C.	NEW LINE STRUCTURES & DEV
5/26/2018	Manhattan	217	WEST 57 STREET	1	O A DOB Professional Engineer (PE) reported that at a sixty-seven story new building that was under construction, a security guard was waiking from the front to the rear on the first floor of the building when an interport of the security guard was a security guard panel with a supporting steel "A-trame topped and pinned the security guard underneath it. Several workser lifted the "A-trame nar memower the pinned security guard. The security guard was taken to Mount Sinai Hospital, when he was later pronunced dead. A DOB inspector that was also at the site reported that the glass panel fell because it was acidentially in thy another worker that was sing to fit a piece of HVAC metal duct that was in close proximity. A contributing factor to the glass panels fall was that the vertical side of the "A- that was in close proximity. A contributing factor to the glass panels fall was that the vertical adde of the "A- bean stored in a unsafe position. The on duty Site Safety Manager stated that he performed a daily safety inspection at the site at the start of the work gy that morring. However, he did not fill out his safety log A thut safetguard. A DOB Violation the site due that the safetguard. A DOB Violation was also insued.		35322614Y	062618CERSM01	ALT 1 NB	121328205	Material Fell	SMITELL SPONSOR LLC	LEND LEASE (US) CONSTRUCT
5/26/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	2 The New Yok City Fire Department requested that a structural stability inspection please be performed because a construction fence hard partially collapsed. A DOB inspector responded to the incident and visited the site and reported that there was approximately 100 feet of construction fence that was made of water-filled jersey barriers and a four foot chain link fence that had latten over onto a pedestrian awkway and injured two pedestrians. The two pedestrians were not transported by ENIS for exervice off-site medical assistance. The barriers were found to have inadequate water levels. Two ECS Violations were issued for a failure to safeguard and for a detective job site fence. Two DOB Violations were also issued.		35323583P, 35323584R	062518CERFC02 , 03	ALT 1 NB	320622894	Material Fell	SPRINGER, JEAN E	CAULDWELL WINGATE CO LLC



ncident Date	borougn	Address Numbe	r Street	Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/29/2018	Bronx	220	EAST 178 STREET	0	The Silk Safety Coordinator reported that while working on a twelve story New Building that was at the Support of Excavation (SOE) stage, a hose from the fire hydrat that was across the sidewal was being used when a female pedestrian tripped and fell over the hose. The pedestrian was lound alter and anawke and was taken to a nearby hospital by ambulance. A DOB inspector responded to the individent and variated the site and reported that the pedestrian sidewalk was clear of any cottaructions at of the irms of inspection. Twe ECB Volations for the presence of poor housekeping and for the presence of tripping housed. A full Step Violk Order (FSWO) was issued for the entire site.	ECB Violation	35332113P 35332114R		New Building	220546620	Excavation/Soil Work	GRAND APTS HOUSING DEVELOPMENT	M. Melnick & Company Inc
29/2018	Manhattan	15	BRIDGE PARK DRIVE	0	1 The Site Safety Manager reported that a worker was unloading an air handler when he lacerated his middle finger on a sharp edge of the air handler. The worker went to a local clinic.	No Dispatch					Other Construction Related Incidents		
29/2018	Manhattan	151	MAIDEN LANE	0	With to a local call. The 1The Site Safety Manager reported that workers were moving a refrigination unit when it toppied over onto one of the workers. The injurde worker was taken to a new statement in the second second second second second visited the site and saved an ECB violation for the failure to maintain safe operations, as well as a partial Stop Work Order (PSWO) on material handling on the ground livel at the exposure. The General Contractor is to provide a Means and Methods.		35336652H				Other Construction Related Incidents	151 MAIDEN LLC	
29/2018	Queens	45-57	UNION STREET	0	<sup>1</sup> The Site Safety Manager reported that a worker was on baker scattidid at the second floor when the worker fell from the scattidid. The worker was found concious, but complainted of pain in his shoulder and leg. The worker mapponder to the incident and visited the site and issued one ECB Violation for a scattidid patient mixet was not fully planked and for the presence of planks that were not tied down. A partial Stop Work Order (PSWO) for the use of a supported scatfold was also issued.	ECB Violation	35323972Z - 35323973K		NB	402898959	Worker Feil	DEPARTMENT OF EDUCATION	Leon D. Dematteis Construction
9/2018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that an electrician tripped while walking and suffered an injury to his rlbs. The worker went to urgent care.	No Dispatch					Worker Fell	DEPARTMENT OF EDUCATION	
/2018	Brooklyn	2550	3 AVENUE	0	The Site Safety Coordinator reported that a worker's foot came into contact with a piece of pipe that was in a pile of garbage that was to be picked up. The worker suffered a foot laceration and was sent to a hospital.	No Dispatch					Other Construction Related Incidents		
1/2018	Brooklyn	107	COLUMBIA HEIGHTS	0	The Site Safety Coordinator reported that four workers were carrying heavy mechanical equipment down the sairai when equipment fail on one of the workars. The worker was sent to a heaptial for a check up, A DOS and issued are ECR Violation for the failure to maintain safe operations and a partial Stop Work Ordor (PSWO) on the handfing of heavy material. The General Contractor is to provide a Means and Methods.	ECB Violation	35326863N				Other Construction Related Incidents	CLIPPER 107 CH LLC	
1/2018	Manhattan	360	EAST 80 STREET	0	A DOB inspector reported that a worker was sorting and moving glass window panels when one of the panels shifted and hit the worker in the leg. The worker was taken to a hospital by ambulance for evaluation. An ECB Violation and a partial Stop Work Order (PSWO) was issued for the failure to maintain astlery measures, as the worker was injured due to improper material handling. The General Contractor is to provide a Means and Methods for safe material handling in order to prevent future incidents.		35318415J		NEW BUILDING	121186242	Material Fell	1711 LLC	RYDER CONSTRUCTION INC
1/2018	Queens	51-35	REEDER STREET	0	<ol> <li>The Construction Superintendent reported that a worker strained his back while lifting a crate onto a dolly. An ambulance was called and the worker was transported to a hospital.</li> </ol>	No Dispatch			NEW BUILDING	420812446-01-NB	Worker Fell	85-15 QUEENS BLVD. REALTY, LLC	STRUCTURAL LAND MANAGEMEN
/2018	Queens	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker cut his finger while using a box cutter. The worker went to a clinic	No Dispatch					Other Construction Related Incidents		
/2018	Manhattan	701	7 AVENUE	0	cainic. 1 The Site Safety Manager reported that two workers were loading glass panels that were approximately 5 X 3 onto a cart when the glass came into contact with a metal part of the cart, which caused the glass to break into pieces. One of the workers suffered a minor laceration to his left hand. The injured worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	20 TSQ GROUNDCO LLC	
1/2018	Manhattan	49	CHAMBERS STREET	0	The Site Safety Manager reported that a worker was trying to move a dolly that was carrying a machine motor for an exterior elevator up the ramp of the loading dock when he lost his balance and the machine motor tipped over, causing the worker to fall face down. The worker suffered cuts and bruises to the face and was taken to a hospital for treatment. A DOB imspector responded to the incident and visited the site and issued an ECB Violation and a partial Stop Work Order (PSWO) to stop all deliveries and material handling. The General Contractor at the site is to provide a Maens and	ECB Violation	353359257		ALTERATION 1	121186821	Material Fell	49-51 CHAMBERS LLC	NY DEVELOPERS & MANAGEMEN



ncident Date	Borough	Address Numb	er Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/1/2018	Brooklyn	18	SPENCER STREET	0	1 The Site Safety Manager reported that a worker was working on a twelve story new building and suffered a cut to his arm while carrying 2 X 4's and sharp edge	No Dispatch					Other Construction Related Incidents	LL 18 SPENCER HOLDINGS LLC	
					metal track material. The worker went to a nearby doctor for treatment and received a few stitches.								
1/2018	Manhattan	10	VANDERBUILT AVE	0	1 The Site Safety Manager reported that an iron worker was climbing down the stairs when he slipped and fell about three feet. The worker complained of a sprained back. An ambulance was called.	No Dispatch					Worker Fell		
1/2018	Manhattan	108	LEONARD STREET	0	1 The Site Safety Managor reported that a staentifier was working on a scisocilit and was installing spinkler system anchors between pipes that were installed by other glumbers. One of the anchors failed and a pipe fell and landed on one of the steamtitter's hands, taking a tip of his hand of I.A. DOB inspector responded to the incident and visited the site and issued a DOB Violation and a partial Sko Work Order (PSWQ) on all overhead installations. The General Contractor is to provide a Means and Methods and a Tool Box Taik.		35327073N				Material Fell	CIVIC CENTER COMMUNITY GROUP B	
/4/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was stripping concrete form work on the first floor when he platform. The worker was found conscious and without a valiable injury, to was taken to a hospital for a check up. A DOB respector responded to the incident and visited the site and reported that the worker was not using any type material area by a site of the site and reserve and the site and responded to the incident and visited the site and responded to the site was not floor that created a slipping hazard. Three ECB Violations and a full Stop Work Order (FSWO) were issued. The General Contrator at the site is to provide a Means and Methods for the safe operation of the job.		35327077K, 78M, 79Y		NEW BUILDING	121187447	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
5/2018	Brooklyn	4813	9 AVENUE	0	1 The Construction Superintendent reported that a worker was unloading a metal track when the track slid and cut his thumb. The worker went to urgent care for treatment.						Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
5/2018	Manhattan	241	WEST 62 STREET	0	<ol> <li>The Project Manager at the site reported that a worker was carrying a 2 X 4 when he accidentally dropped the 2 X 4 onto the foot of another worker. The injured worker was sent to a hospital for a check up and returned to the site afterwards.</li> </ol>	1					Other Construction Related Incidents	NYC HOUSING AUTHORITY	
5/2018	Manhattan	500	WEST 33 STREET	0	<ol> <li>The Site Safety Manager reported that an electrician was moving his equipment when he hurt his back. An ambulance was called.</li> </ol>	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker twisted his left ankle while installing rebar. The worker went to a clinic and then returned to the site.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
6/2018	Manhattan	1059	3 AVENUE	0	1 The Site Safety Manager reported that during the construction of a thirty story new building, a worker waiked into the corner of a steel Hearm and hurt his right foot. The worker continued to work, but the Site Safety Manager noticed that he was not doing well and that the worker was still in pain. The worker was taken to Cornel Hoppital for treatment.						Other Construction Related Incidents	63RD & 3RD NYC LLC	
6/2018	Manhattan	110	UNIVERSITY PLACE	0	<ol> <li>The Site Safety Manager reported that a plumber was installing a pipe when a piece of debris fell into his eyes.</li> <li>The plumber went to a doctor.</li> </ol>	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
3/2018	Manhattan	455	5 AVENUE	0	1 A Project Manager at the site reported that during the installation of floor opening protection, a worker lost control of a plank that hit him in the nose. The worker walked to a clinic.	No Dispatch					Other Construction Related Incidents	NEW YORK PUBLIC LIBRARY	
7/2018	Staten Island	35 a	BAY STREET	0	1 The Site Safety Manager reported that a worker hurt his arm while removing formwork. The injured worker walked to urgent care.	No Dispatch			NEW BUILDING	520138379-01-NB	Other Construction Related Incidents		HOLLISTER CONSTRUCTION SE
7/2018	Manhattan	209	EAST 19 STREET	0		No Dispatch			NB	121958480	Other Construction Related Incidents	VISUAL ARTS HOLDING CORP	GRAMERCY SQUARE LLC
7/2018	Manhattan	15	EAST 30 STREET	0	1 The Site Safety Manager reported that a worker fell down from the first floor supporting deck to the ground and suffred a very bach head injury. The worker was found conscious and was taken to a hospital by ambulance. The worker was reported to be in stable condition. A DOB inspector responded to the incident and visited the site and reported that the worker was walking along the re-shores and may have possibly fainted or thipped and hit his head on one of the re- shores. No enforcement action was deemed necessary, as the inspector did not observe any hazardous conditions during the time of inspection.						Worker Fell	MADISON 30 31 OWNER LLC	



Incident Date         Borou           7/72018         Manha           7/72018         Manha           7/72018         Brooki           7/72018         Brooki           7/72018         Brooki           7/72018         Brooki           7/72018         Brooki	hattan kiyn	122 111 4813 123 60	EAST 23 STREET LEROY STREET 9 AVENUE	0	<ul> <li>A DOB Inspector reported that an electrical worker at the cellar level was on a twelve local ladder installing electrical work on the celling when he fell approximately six to sever feet. The worker was not waaring a harness and was taken to a nearby hospital. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (/FSWO) was also issued for all work at celliar levels that requires ladders. A Means and Methods and a Tool Box Taik must be provided.</li> <li>The Site Safety Coordinator reported that a worker injured his middle finger while using a pallet-jack. The worker was sent to urgent care.</li> </ul>		3532074P		NB	121190157	Worker Fell	NOT ON FILE	CM AND ASSOCIATES CONSTRU
/2018 Brook! /2018 Brook!	kiya	4813		0	injured his middle finger while using a pallet-jack. The	No Dispatch							
/2018 Brookl	ktyn		9 AVENUE	0							Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
		123			1 The Construction Superintendent reported that a worker was carrying a few metal studs when he came into contact with a pipe scaffold tieback and twisted his knee. The worker was taken to urgent care.	No Dispatch					Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
/2018 Manha	hattan	60	LINDEN BOULEVARD	0	<ol> <li>The Site Safety Manager reported that a worker hurt his arm while moving formwork. The worker was transported to a hospital by another worker.</li> </ol>	No Dispatch			NEW BUILDING	321228603-01-NB	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS LLC
			GREENE STREET	0	1 A DOB inspector sported that a worker on the first floor torsis lowing the bachroom when the headback toward a tempoonry allumisum static system that he bought was in place and secured. The stainway collapsed and the worker fell to the backment static below. The worker suffered possible injuries to the neck and head and was able to stand on his own power. The worker received treatment in the emergency room of a nearly hospital, and eventually returned to the site to pick up his tools. ECB Violations were issued for a failure to safeguard, for there being no plans on site for ongoing construction work, and for there being no plans available for a temporary starcase. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35314346r 38314347z		AL	123172217	Worker Fell	NOT ON FILE	SHAWNMUT WOODWORKING & SUP
V2018 Manha	hattan	767	5 AVENUE	0	1 The Site Safety Manager reported that a worker was doing waterproofing work in a tree pit on the plaza area. When the worker was walking away, he walked into a metal object that was on the wall. The worker went to a clinic for a check up on his own and will be reporting back to work.	No Dispatch			ALTERATION 1	122970721	Other Construction Related Incidents		TURNER CONSTRUCTION COMPA
W2018 Brook!	klyn	242	EAST 45 STREET	0	2 A DOB inspector reported that two worksers were working on the eave and gatters of the roof while on pump jacks when the worksen stell approximately twenty feet. One of the worksen sustained in pluries to the initial, while the other worksen sustained a head injury and was in critical condition. Both workser were transported to Kings County Hospital by ambutance. An ECB Woldston, a DOB Violation, and a full Stop Work Order (FSWO) were issued for work being performed without a permit.	ECB Violation	35322879R	060918CERMR05			Worker Fell	PRINCE, LINCOLN	
N2018 Manha	hattan	200	EAST 59 STREET	0	2 A DOB inspector reported that there were two electricians that were working in the utility room on the fourteenth floor with their foreman consite. The workers were working on a panel beard when they de-energized the upper hard of the panel board. However, the lower Boh workers were electrocated and saffered burns, and both workers were taken to a hospital. Two Agarvated Level 2 ECB Violations were issued: one to the General Contractor, and one to the Electrical Subcontractor, for a failure to maintain safety measures. A partial Stop Work Order (FSWU) was also issued. Two other ECB Violations were issued for infractions not related to the incident.		35335066K, 35335067M		NEW BUILDING	121192912	Other Construction Related Incidents	MIPA 59/THIRD OWNER LLC	GILBANE RESIDENTIAL CONST
1/2018 Manha	hattan	45	BROAD STREET	0	1 A DOB inspector reported that a worker was holding a pin that was to be used to set the auger on a drill rig when another worker it his finger with a harmmer. The struck worker was taken to a nearby hospital and was inter released and a structure of the structure of the struck worker was taken to a nearby hospital and was more than the structure of the structure of the structure of the structure of the structure of the Work Order (PSWO) was issued on all use of the suger. The General Contractor is to provide a Maans and Methods for the safe installation of an auger.	ECB Violation	35332161J		NB	121190772	Excavation/Soil Work	MADISON 45 BROAD DEVELOPMENT L	pizzarotti LLC
11/2018 Manha	hattan	138	EAST 38 STREET	0	The Site Safety Manager reported that an iron worker was cutting a tie wire with a utility knife when the knife slipped out of his hand and cut his forearm. The worker was transported to a hospital by ambulance for treatment	No Dispatch			NB	121186028	Other Construction Related Incidents	TATHAM HOUSE,	TISHMAN CONSTRUCTION CORP
1/2018 Brook!	kiyn	41	BLUE SLIP	0		No Action Necessary			Air 1	320597449-01-NB	Worker Fell	BOP GREENPOINT F LLC	T.G. NICKEL & ASSOCIATES
11/2018 Bronx	x	988	EAST 180 STREET	0	<ol> <li>The Site Safety Manager reported that a worker was cutting water proofing with a sheetrock knife when he accidentally cut his thumb. The worker was taken to urgent care for treatment.</li> </ol>	No Dispatch			NB	220152233	Other Construction Related Incidents	988 EAST 180 STREET HOUSING DE	MONADNOCK CONSTRUCTION IN



cident Date	Borough	Address Numbe	r Street	Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
ident Date 2/2018	Borough Manhattan	Address Numbe	r Street	Fatalities Injuri	BEOC Final Description The Construction Superintendent reported that there were four workers that were moving a crate of glass on a dolly when the doly tipped and caused the crate of glass to slide and hit one of the workers in the chest. The struck worker left to the floor and suffered a back injury. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that the glass was being moved on a makeshift dolly was not available. An ECB Violation was issued for the failure to maintin safe operations, as well as a partial Stop Work Order (ESWO) for material handling. A design drawing with load capacity for the makeshift dolly must be provided.	ECB Violation	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type Other Construction Related Incidents	Owner's Name LVC 298, LLC	Contractor Name
12/2018	Queens	28-30	JACKSON AVENUE	0	1 A DOB inspector reported that an electrician was working on a PVC junction box in the floor with glue. The box had live electrician tires of the box, which created a spark that set the glue on fire. The electrician stress of a spark that set the glue on fire. The electrician suffered a second degree burn and was taken to a hospital, where he was reported to be in stable condition. An Aggravated Level 2 E CB Violation was issued for the failure to maintain safety measures while working on live electricial Uwes. A partial Stop Work Order (PSWO) was also issued to stop all electricial work.	ECB Violation			NEW BUILDING	420652886	Other Construction Related Incidents	LIC DEVELOPMENT OWNER, L.P.	HUDSON MERIDIAN CONSTRUCT
3/2018	Manhattan	15	EAST 57 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder to cut steel when he lost control of the grinder, which caused a small laceration to his foreman. The worker went to a local hospital.	No Dispatch					Other Construction Related Incidents	15 EAST 57TH ST.ASSOC.	
3/2018	Manhattan	701	7 AVENUE	0	The Site Safety Manager reported that a carpenter was cutting sheetrock with a utility knife when he accidentally cut his forearm. The worker's foreman took him to a City M.D. for treatment. The worker is expected to return to work.				ALTERATION 1	121324343	Other Construction Related Incidents	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
13/2018	Queens	42-20	27 STREET	0	1 The Site Safety Manager reported that a worker was lifting up the pipe frames of a supported scaffold with a pulley when the worker burned his hands on the rope and dropped the pipe frames of the supported scaffold. The worker was taken to a narely hospital by a foreman for treatment. A DOB inspector responded to the incident and visited the safe and reported that the details of how the incident accurred were not known. Two ECB Violations were issued for the failure to perform a supported scaffold installation in a safe manner and for the failure to provide a supported scaffold erector card. A partial Stop Work Order (PSWO) for the installation of supported scaffold svas also issued.	ECB Violation	35324229R - 35324230Y		SF	Q00040613-11-SF	Material Fell	CRESCENT & 27 LLC	Classic Consulting Group
13/2018	Staten Island	2589	RICHMOND AVENUE	0	The Site Safety Manager reported that a water pipe was damaged by a worker on the second floor, which caused a flood on the first floor. One of the store workers at the address slipped and full. An ambulance was called. A DOB inspector responded to the incident and visited the site and determined that there was no enforcement action necessary, as the work that was being performed was approved under a DOB issued permit.	No Action Necessary			SPRINKLER	540138929	Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	PATRICK BOWE
4/2018	Manhattan	532	WEST 33 STREET	0	1 The Site Safety Manager reported that a roof worker complained of pain in the left side of his chest while lifting waterproofing materials. The worker was alert and awake and was taken to Bellevue Hospital by ambulance for treatment.	No Dispatch			NB	121191183	Other Construction Related Incidents	NOT ON FILE	TISHMAN CONSTRUCTION CORP
4/2018	Brooklyn	210	CLASSON AVENUE	0	1 A DOB inspector reported that during a stripping operation that was taking place between the elevator shaft and onch staiwell on the tifth floor, an 'ULMA' formwork beam that was approximately sixteen feet long struck a worker in the head with the worker was attempting to remove the beam. The worker was attempting to a hospital, AhreE DV iolation was sisted for a stable in the hospital. AhreE DV iolation was sisted for a failure to maintain safe operations. A partial Stop Work Order (FSWU) was able issued on all concrete work. The General Contractor is to provide a Means and Methods for safe operations.		35336020Y				Other Construction Related Incidents	PRATT INSTITUTE	
4/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was walking down from the second floor when he missed his step and fell down. The worker hurt his knee and went to a City M.D.						Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
4/2018	Bronx	600	BERGEN AVENUE	0	1 The Site Safety Manager reported that a worker was carrying a piece of lumber that was 4 X 10 X 7 when the worker slipped, which caused the lumber to fall onto another worker's hand. The injured worker went to a City M.D.						Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	
14/2018	Bronx	600	BERGEN AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker hit his foot while unloading a beam. The worker's foreman took him to a first med.</li> </ol>	No Dispatch			NEW BUILDING	220151868-01-NB	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP



cident Date		Address Number	Street	Fatalities Injuries			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
14/2018	Bronx	1812	VYSE AVENUE	0	1 A DOB inspector reported that a worker was taking the delivery of a Concrete Masonry Init (CMU) block that was being delivered by a lul when his finger got caught between paletist and one of his fingertips separated. The worker's foreman took him to a hospital for treatment. An ECB Violation was issued for the failure to maintain safety measures. A partial Stop Work Order (PSWO) was issued on all material handling, including deliveries. A second partial Stop Work Order (PSWO) was also issued for the use of sadflocts in which the horizontal netting was not at the required height. The General Contraction is to provide a Mass and Methods and a worker's orientation before the first stop work-order will be rescinded.	ECB Violation	35316423J		NEW BUILDING	220152851	Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	HLS BUILDERS CORP
18/2018	Brooklyn	15	WASHINGTON AVENUE	0	<sup>1</sup> The Site Safety Managor reported that during the final pressure tosting linguisation of a stundiple, the regulator left the air out of the standpipe, which caused another worker to hit a wall. He worker complained of a back ache and an ambulance was called. A DOB inspector responded to the incident and visited the site, and reported that no enforcement action was deemed necessary, as the incident occurred as the result of a worker error.	No Action Necessary					Other Construction Related Incidents	NYC DSBS	
8/2018	Manhattan	110	UNIVERSITY PLACE	0	1 The Site Safety Manager reported that an electrician was using a sheet rock knille to try to cut a conduit when he sliced his leit index finger. The worker was escorted to the emergency room at Beth Israel Hospital with another co-worker to receive treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
19/2018	Brooklyn	276	KENT AVENUE	0	A DOB inspector reported that a worker was forming a third floor deck when a retractable lanyard device for a safety hamess was let on loose phywod. The deck was not fully planked and had gaps in t. The worker stepped on the loses phywod. Takating the loose phywod to sip. As a result of his, the retractable lanyard device fait on the social floor and hit another worker in the back. The in second toor and hit another worker in the back. The in the social floor and hit another worker in the back. The lane of the langer of the langer of the langer and for working on two levels simutaneously without a controlled access zone in place. A partial Stop Work Order (PSWQ) was also issued to stop all forming operations. The General Contractor is to provide a Means and Methods and a worker orientation for safe operation.		353271694		NEW BUILDING.	320916407	Material Fell	DOMINO A LLC	280 KENT CONSTRUCTION LLC
9/2018	Brooklyn	306	NORTH HENRY STREET	0	1 A DOB inspector reported that a contractor had overloaded pict prirets that expanded nighty leaf when sight bundles of corrugated steel desking that were thenry feet. The desking was placed in a concentrated area on the joist pirders. However, the joist girders were not properly installed, as they were only temporarily installed with one 34 <sup>th</sup> both that eventually sheared off and collapsed. This collapse caused the worker to fail form four the gradient caused the worker to fail worker suffered a blocken shoulder and possible back injuries and was taken to a nearby hospital. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard, as well as a full Stop Work Order (FSWO).	ECB Violation	35336227L		EW-OT	340499080	Worker Fell	300 NORTH HENRY LLC	R, KING WINDOW CORP
9/2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that a worker was removing a kitchen cabinet when he was hit in the head by the cabinet when it became loose. The worker suffered a cut to his face. The worker went to a City M.D. to receive treatment and will return to work.	No Dispatch			NEW BUILDING	121191913	Material Fell	95TH AND THIRD LLC	GILBANE RESIDENTIAL CONST
/2018	Queens	36-18	MAIN STREET	0	1 The Site Safety Manager reported that an elevator company worker was putting down counter weights when his finger got pinched between the weights. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	134-22 35TH AVE., LLC	
19/2018	Queens	37-09	COLLEGE POINT BOULEVARD	0	A DOB inspector reported that a worker was installing guardrais on the perimeter of the job site when he was asked to help sissall - deduing at the second floor. Which the worker serged in a torch heard of deduing and feel approximately fitteen of the service suffered injuries to his ankles, knees, and head. The worker was found conscious and was taken to Fluxhing Hospital by ambulance. An ECB Violation was issued for a failure to askegurad, as wells a partial Stop Work Order (PSWO) on building two on all steel erection and deck layout. A site specific Means and Methods for the provided. A Tor OB NoT Rial and a adequare ite off procedure for controlled deck zones must also be provided.		EC8#35327475X		NB	420653607	Worker Fell	NOT ON FILE	TOP 8 CONSTRUCTION CORP



cident Date		Address Number		Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0/2018	Manhattan	328	EAST 62 STREET	0 11 A DOB inspector reported that there were workers that were getting ready to cut out and remove a raker section that was connected to the Support Of Excavation (SOE) waler and protruding through the foundation walls. The Construction Superintendent at the site stated that the section needed to be removed for the completion of a waterprofing installation. During the process of preparing justice that and set the site of the tracker pit and walked to a hospital with a co-worker. The worker got and fell approximately four feel into the raker pit, landing on his back. The worker got out of the raker pit and walked to a hospital with a co-worker. The worker should be the site work and a state of a hospital with a co-work. The worker are bed the missing. An additional ECR Violation was issued for the failure to provide a Means and Methods for the removal of S.O.E. sections. A partial Stop Work Order (FSWO) was issued on the removal of S.O.E. sections.		35332281Y-35332282X		NB	121189846	Worker Feil	YYY 62ND STREET LLC	Joy Construction corp
0/2018	Manhattan	300	LAFAYETTE STREET	A DOB inspector reported that there were electricians covering spools down a flight of stars when they lost control of one of the spools, which hit one of the worker in the leg. The work was taken to a hospital by ambuilding. A nCEB Violation wai issued for a failure to maintain safe operations. A partial Stop Work Order (PSWO) was also issued for all heavy material handling A Means and Methods must be provided.		35331146R				Other Construction Related Incidents	LVC 298, LLC	
20/2018	Manhattan	25	SUTTON PLACE SOUTH	0 1 A DOB inspector reported that a worker was attempting to lower a chipping gun from a roof to a setback to another worker when he acidotentally dropped the chipping gun approximately twenty leat. Initing the other worker on his hard hat. The stuck worker was admitted the incident occurred on June 19, 2018, but was not reported until June 20, 2018. The DCB Violations were issued: an Aggravated Level 2 violation for the failure to notify all persons and property and a second violation for the failure to immediately notify the Department Of Buildings of an otools or equipment from a roof to a setback without a DOB approved Means and Methods.		35322737Y 35333276Y	062018CNESC01 062018CNEGS01	ALTERATION TYPE 2	122907426-01-EW-OT	Other Construction Related Incidents	CANNON POINT NORTH INC	DNA CONTRACTING LLC
0/2018	Manhattan	1558	3 AVENUE	0 1 The Site Safety Manager reported that a garbage truck was passing by when it hit a barrier that hit a worker. The worker complained of back pain and walked to	No Dispatch					Other Construction Related Incidents	180 EAST 88TH STREET REALTY LL	
20/2018	Manhattan	1227	BROADWAY	urgent care. 0 The Site Safety Manager reported that a worker was cleaning and moving materials when he moved a job site box that was next to two hollow steel doors. The two follow steel doors fell and hit the worker's shoulders, causing him to fail. An ambulance took the worker to a hospital for a check up.						Other Construction Related Incidents	YJL BROADWAY HOTEL LLC	
21/2018	Brooklyn	583	LORIMER STREET	0 1 A DOB inspector reported that a worker injured his finger while using a drill during steel erection/modification work because the drill was used contrary to the manufacturer's specifications. The injured worker was sent to a hospital, where he receives stitches. This incident occurred on June 21, 2018, but was not reported until June 2, 2018, Four ECB Violations were issued. These violations include a violation for the on-site modification of steel, a violation for the use of admic to maintain safe operations, and violation for the manufacturer's specifications, and a violation for the lailure to maintain the maintaine to notify the Department Of Buildings of the incident in a timely manner.		35331149M, 1450L,1451N, 1452P				Other Construction Related Incidents	583 LORIMER LLC	
21/2018	Brocklyn	77	CLARKSON AVENUE	0 1 A DOB inspector reported that a worker was working on a platform deck when he fell approximately six feet to the lower level. The worker was found conscious and alert and was taken to a nearby hospital. An Aggraved Level 2 ECB Voltation was issued for the failure to safeguard. A DOB Violation was also issued. A partial Stop Wink. Order (PSWQ) was issued to all of the work being conducted at the fifth floor.		35306269X	062118CNERWS01	Ait - 1NB	321197771	Worker Fell	CLARKSON BUILC	DAWNY CONSTRUCTION LTD



ncident Date	Borough	Address Number	Street	Fatalities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
21/2018	Manhattan	441	9 AVENUE	1 The Site Safety Manager reported that an iron worker was working inside an elevator shaft on a ma basket when an object fell from above and struck and cut the worker's arm. An anthulance transported the worker's are many struct the two shaft or a many structure to hospital for treatment. A DOB inspector responder to the hospital for treatment. A DOB inspector responder to the distribution of the usage of a scaffod was provided, and lighting was being put in place during the time of inspector. However, an ECB Violation was issued for the failure to notify the DOB Scaffold Safety Team for the paresence of a supended scaffold on the site. A partial Stop Work Creder (PSV) was issued for all was in an elevator shaft. A Means and Methods for all safe operations in a shaft must be provided.	an	35331147Z	062118BS04SA01			Material Fell	C8P 441 NINTH AVENUE OWNER, LL	
21/2018	Manhattan	45	BROAD STREET	A A DOB inspector reported that contractors were transporting material with an escavator when the knuckle of the machine struct. Net CONUM was an excavator the sagicaret property (S5 Broad Street, Manhatan), which is a Cosi restaurant. The impact dislogidad a small section of concrete block that struck a customer that was eating lunch hiside of the restaurant. The customer suffered an injury to his left in and was transported to lew York Prebytemia Hospital by an ambulance. There were no structural concerns found. However, the restaurant has been closed. The duranged buildings engineer will provide a Maana Vicelance situation to safety and York order (FSWO) was issued for the entire site Stop Work Order (FSWO) was issued for the entire site site of the entire site site site site of the entire site site site site site site site sit	g	35332283h		FO	121190772	Material Fell	MADISON 45 BROAD DEVELOPMENT L	Pizzaroti LLC
22/2018	Manhattan	15	EAST 30 STREET	0 1 The Site Safety Manager reported that a worker droppe	d No Dispatch					Material Fell	MADISON 30 31 OWNER LLC	
				a coupling on his foot during a rebar installation. The worker suffered a swelled foot and went to urgent care with a co-worker.								
/2018	Manhattan	315	EAST 46 STREET	0 1 The Site Safety Manager reported that a worker bent down to plug in an extension cord and hit his head on a stored piece of rebar. The worker went to urgent care.	1					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
3/2018	Manhatlan	100	CHURCH STREET	In A DOB inspector reported that at a initiaten story building that them ishing altamisticn work performed on i there were workers installing and welding sever pipes on the eight floor utility shat using a 'Jowel Clamp' the keeps the pipes in position. The 'Jewel Clamp' singled out of the hands of one of the workers and fell through the shaft. The clamp bounced on the third floor and landed in the cellar, where it it handher worker on his hand. The injured worker suffered cuts and bruises on his arm, build onto suffare barben bone. The injured with thes. Four EOB Volations were issued - one and Approved Level 2 volation for a failure to maintain safety measures, a second violation for working without a permit, and a (outh volation for the absence of guardinia at open shafts. A full Stop Work Order (FSWO) was issued as we'll. The Gameral Contractor a he site is to obtain a permit and provide a Means and he site before the Stop Work Order will be rescinded.	, a g t	35327483X, 84H, 85J, 86L				Material Fell	100 CHURCH FEE OWNER LLC	R&S CONST. CONTRACT. INC
3/2018	Queens	5	COURT SQUARE	0 1 The Site Safety Coordinator reported that a construction worker tripped and sustained a minor knee injury. EMS was called and the worker was transported to a local	n No Dispatch			NB - NEW BUILDING	420902410	Worker Fell	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
				hospital.								
25/2018	Manhattan	505	WEST 43 STREET	0 1 The Site Safety Manager reported that a worker was standing on an 'A-Frame ladder while performing a grinding operation on the fourteenth floor of a concrete wall surface when the ladder slipped, causing the worker to fail. The worker was found unconscious. An ambulance was called and the worker was transported to a hospital in a conscious state. A DOB inspector responded to the incident and visited the site and issue an ECB Violation for the failure to maintain safety measures. A partial Sitey OwnK Order was issued on all grinding operations. The General Contractor at the site is to provide a Means and Methods for safe operation.	id	35300588M		NEW BUILDING	121187456	Worker Fell	NOT ON FILE	NEW LINE STRUCTURES & DEV



cident Date	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	149	EAST 125 STREET	0	2 A DOB inspector reported that a Jekko crane machine				NEW BUILDING	121192388	Mechanical Construction Equipment	NOT ON FILE	ZDG, LLC
					on the fourth floor was in the process of placing a								
					curtain wall panel on the third floor when the machine								
					fell from the fourth floor and two connectors also fell from the third floor. One worker fell from the third floor to								
					the street and suffered a critical injury, and a second								
					worker that was on the third floor was struck by crane								
					components and suffered a non-life threatening back								
					injury. Both injured workers were taken to a hospital.								
					The inspector reported that the injured workers were not								
					tied off and that the operation was not permitted, as								
					there were no valid permits, plans, or rigging								
					certifications present. The crane operator did not have								
					any certifications. The inspector reported that the								
					incident may have occurred because the crane was overloaded, and that a Means and Methods for hoisting								
					and rigging, for overloading, and for safeguarding was								
					not provided. DOB's BEST Squad issued a full Stop								
					Work Order (FSWO) due to the existence of multiple								
					safety issues. DOB's Cranes and Derricks Unit also								
					issued a Stop Work Order on all hosting operations.								
					Eight totals ECB Violations were issued, as there were								
					separate violations issued to both the General								
					Contractor and the crane user at the site for an unsafe operation, for the failure to safeguard, for the absence of								
					a valid HMO License or certifications, and for not being								
					in possession of 16 or 32 hour rigging certifications.								
					in possession of to or oz nour rigging detailouistic.								
018	Brooklyn	420	ALBEE SQUARE	0	1 The Site Safety Manager reported that the Construction	No Dispatch					Other Construction Related Incidents	JEMB ALBEE SQUARE LLC	
					Superintendent was moving material on a pallet jack by								
					himself when he hit a divet. The Construction								
					Superintendent tried to stop the piece of material that was being moved from falling, but the material fell on his								
					was being moved from failing, but the material fell on his ankle. An ambulance was called								
					unite. All unbulance was caned.								
	Decility of the second s										01.0	CADMAN ASSOCIATES LLC	
2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was	NO Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
	blokyn				picking up a garbage bag when he backed into stacked rebars and suffered a scratch to his right calf. The								
					rebars and suffered a scratch to his right calf. The worker walked to a City M.D.								
010	Bassa	2000	ODESTON AVENUE	0		No Disect."					Other Construction Data that the		
2018	Bronx	2028	CRESTON AVENUE	0	1 The Site Safety Manager reported that a worker pulled his back while using a pallet jack. The worker	NU Dispatch					Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	
					his back while using a pallet jack. The worker complained of a back ache. An ambulance was called.								
					sentences of a back done. For ambalance was called.								
2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NEW BUILDING	321197478-01-NB	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
2016	BIOOKIYII	'	CLINTON STREET	0	fueling a generator when fuel was spilled on his arm.	NO Dispatch			NEW BOILDING	32119/4/0-01-IND	Other Construction Related incidents	CADMAN ASSOCIATES LLC	1.G. NICKEL & ASSOCIATES
					The worker walked to a City M.D. as a precaution.								
					The worker walked to a only m.D. do a production.								
2018	Manhattan	1	BEEKMAN STREET	0	1 The Site Safety Manager reported that the diamond	ECB Violation	35342751Z	062618BS01KR01			Other Construction Related Incidents	ONE BEEKMAN OWNER, LLC	
					plate in a hoist car was not secured and that the								
					diamond plate fell over and hit the ankle of a worker that								
					was in the hoist. An ambulance was called. A DOB								
					inspector responded to the incident and visited the site								
					and issued an ECB Violation for the failure to institute safety measures for the diamond plate in the hoist. A								
					DOB Violation was also issued. As of the time of								
					inspction, the diamond plate was made secure.								
2018	Manhattan	1	WEST END AVENUE	0	1 A DOB inspector reported that workers were in the	ECB Violation	35324259H		Shed	M00023179	Worker Fell	NOT ON FILE	Colgate Enterprises Corp
					process of dismantling a fourteen foot high sidewalk								
					shed when one of the workers fell back between the								
					junior beams. The worker was experiencing minor back pain and was taken to a local hospital by ambulance. An								
					ECB Violation was issued to the sidewalk shed								
					company for the failure to safeguard all persons and								
					property.								
2018	Manhattan	400	WEST 61 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch				_	Worker Fell	RCB1 NOMINEE LLC	
2010	maimauail	400	WEST DI SIRCEI	0	a line Site Safety Manager reported that a worker was carrying material down a flight of stairs when he missed	No Dispatch					WORKEL CHI	NOB I NOMINEE LLG	
					the last step. The worker suffered a shoulder injury and								
					was taken to a hospital by ambulance.								
2018	Manhattan	61	9 AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	G.D.C.L. HOLDINGS LLC	
				Ŭ	doing sheet metal work with a screw gun when he						Contraction includes includes its		
					accidentally drilled a screw into his right hand. The								
					worker was transported to a hospital by ambulance.								
2018	Brooklyn	63	FLUSHING AVENUE	0		No Dispatch					Other Construction Related Incidents	NYC DSBS	
					going on a break when he opened a box and the lid of								
					the box fell on his hand, causing a laceration to his								
					middle finger. The worker went to a hospital for a check								
					up.								
018	Brooklyn	856	WASHINGTON AVENUE	0		ECB Violation	35335899J	062918BS08PK01			Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
					sidewalk caved due to a rain storm that occurred on								
					June 28, 2018. A pedestrian stepped into the caved in								
					section of sidewalk and hurt her ankle, knee, and								
					shoulder. An ambulance was called and the pedestrian was taken to a hospital by ambulance. A DOB inspector								
					was taken to a hospital by ambulance. A DOB inspector responded to the incident and visited the site and								
					responded to the incident and visited the site and reported that there were cracks along the section of								
					sidewalk that caved in during the rain storm, which may								
					have contributed to the cave in. The area was being								
					back filled while the inspector was on site. An ECB								
					Violation was issued for a failue to maintain the sidewalk								



cident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Manhattan	111	LEROY STREET	0	1 The Site Safety Manager reported that a window	No Dispatch			, crime	l chille the	Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
					installer was taking suction cups off of a window when he pulled his back. An ambulance was called.								
2018	Queens	33-02	30 AVENUE	0	1 A DOB inspector reported that a worker was using a	ECB Violation	35334832K & 35334833M	062918CERRJ01 & 062818CERRJ02	ALTERATION TYPE 1	420474347-01-AL	Worker Fell	ANDREW G GEORGIOU TRUST FUND B	CENTRAL BUILDERS DEVELOPM
					concrete trowel machine when he came upon a floor								
					opening. The worker was using the machine close to the	3							
					exterior wall when he hit the wall, which caused the machine to kick back towards the opening. Both the								
					worker and the machine fell approximately twelve feet								
					into the basement. The New York City Fire Department								
					removed the worker and EMS took the injured worker to								
					a hospital. Two ECB Violations were issued, including								
					one Aggravated Level 2 violation for a failure to safeguard and a second violation for the failure to post a								
					safeguard and a second violation for the failure to post a project information panel. Two DOB Violations and a full								
					Stop Work Order (FSWO) were also issued.								
018	Bronx	1520	STORY AVENUE	0 1	A DOB inspector reported that a worker was on top of a	ECB Violation	35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
					concrete mixer and was attempting to remove a piece of								
					concrete. The worker was pushing the piece of concrete								
					with his right foot when he got his foot caught in the shredder of the concrete mixer. One of the worker's toes								
					was severed. The General Contractor at the site								
					contacted NYC Fire Department EMT personnel, who								
					transported the worker to Jacoby Hospital. An								
					Aggravated Level 2 ECB Violation was issued to the								
					General Contractor for a failure to safeguard. A partial								
					Stop Work Order (PSWO) on all concrete and cement operations was also issued. The contractors at the site								
					must provide a Means and Methods for concrete and								
					cement operations.								
018	Bronx	1880	BOSTON ROAD	0 1	The Site Safety Manager reported that a roofer hit the	No Dispatch					Other Construction Related Incidents	1880 BOSTON ROAD LLC	
					edge of the coping while doing roof work and cut his hand. An ambulance was called.								
018	Bronx	764	EAST 152 STREET	0 1	A DOB inspector reported that at the fifth floor, a worker was moving a hose when he became entangled in the	ECB Violation	35322847P & 35322848R	070218CERJM02 & 070218CERJM01	NEW BUILDING	220562905-01-NB	Worker Fell	764 EAST 152ND STREET LLC	UA BUILDERS CORP
					was moving a hose when he became entangled in the hose and fell approximately five feet from a pipe scaffold								
					to the deck on the fifth floor. The worker was taken to a	·							
					hospital for treatment. Two Aggravated Level 2 ECB								
					Violations were issued; one violation for a failure to								
					safeguard, and a second violation for the failure to notify	r III.							
					the Department Of Buildings of the incident. Two DOB Violations and a full Stop Work Order (FSWO) were also								
					issued.								
018	Brooklyn	350	HENRY STREET	0	A DOB inspector reported that a worker was cleaning	CCR Violation	25242544M FAIL TO SAFECUARD, HOLES NOT		AI T1	320625294	Worker Fell	FPG CH 350 HENRY, LLC	ICS BUILDERS, INC
.010	Biotkiyii	330	HENRY STREET	0	around a shaftway when he lifted a piece of plywood	LOD VIOLATION	35342614M-FAIL TO SAFEGUARD- HOLES NOT SECURE, WORKER CLEANING UP THE SITE FELL		ALTI	520025254	WORKETTEN	THO OTTOS THENRY, EEG	ICS DOLEDENS, INC
					away from the shaftway and fell approximately fifteen		THRU TO THE FLOOR						
					feet through an opening. The plywood was not secure								
					and the opening was not marked. The worker suffered a possible fractured arm and fractured vertebrae. An ECB								
					Violation was issued for a failure to safeguard. A partial								
					Stop Work Order (PSWO) was issued on demolition								
					work around shaftways.								
018	Manhattan	301	PARK AVENUE	0 1	The Site Safety Manager reported that a worker cut the	No Dispatch			ALT-11	122978625	Other Construction Related Incidents	THOR 30 PARK AVENUE LLC	TISHMAN CONSTRUCTION CORP
					middle finger of his right hand while pushing a mini								
					container. The worker was taken to a clinic to get stitches								
)18	Manhattan	40	CHAMBERS STREET	0 1	The Site Safety Manager reported that a HVAC worker	No Antion Management					Other Construction Related Incidents	49-51 CHAMBERS LLC	
110	Mannattan	49	CHAMBERS STREET	0	cut his right arm during a duct installation. A DOB	NO ACTOR NECESSARY					Other Construction Related incidents	49-51 CHAMBERS LLC	
					inspector happened to be at the site as of the time of the								
					incident and reported that the injury occurred as the								
					result of a worker's error. The worker walked to a hospital. No enforcement action was necessary.								
					noophal. No enforcement action was needssally.								
18	Manhattan	815	5 AVENUE	0 1	The Site Safety Manager reported that there were workers that overloaded an "A"-Frame cart, which	No Dispatch					Other Construction Related Incidents	EIGHT HUNDRED AND FIFTEEN FIFT	
					workers that overloaded an "A"-Frame cart, which caused a few 2 X 4 X 4" stones to slide off the cart. One								
					of the stones fell onto a worker's foot. An ambulance								
					was called.								
018	Brooklyn	1	CLINTON STREET	0 1	The Site Safety Manager reported that a worker lost his	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
					footing and hurt his leg while pushing garbage in a thirty								
					yard dumpster. An ambulance was called.								
018	Manhattan	1	WALL STREET	0 1	The Site Safety Manager reported that a worker came to	No Dispatch					Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
					the end of his shift when he complained that he strained								
					his testicles while pushing a mini-dumpster. An ambulance was called.								
)18	Manhattan	150	5 AVENUE	0 1	A DOB inspector reported that a plumber was running a	ECB Violation	35343112R	070318EE105EFF01			Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	
					new line above an existing boiler when he came into								
					contact with a live electrical wire. The plumber's partner pulled him off the wire. Both the worker and his partner								
					pulled him off the wire. Both the worker and his partner were shaken up and were taken to a hospital by								
					ambulance for a check up. An ECB Violation was issued	1							
					for the presence of unapproved unsafe wiring in the								
					basement. Defective wiring, exposed wires, and not-								
					terminated wires were also found in the basement boiler room. A partial Stop Work Order was issued on work on								
					room. A partial Stop Work Order was issued on work on a confined space by the cellar boiler. A DOB Violation								
					was also issued.								



	B		<b>2</b> 4444	Excellence for the	FOO FILLD	000 4-41-4		DOD 1/ L.C. Number	D	D	1	a made Name	2
Incident Date 7/5/2018	Borough Manhattan	Address Number 25	Street PARK ROW	Patalities Injur 0 1	EOC Final Description The Site Safety Manager reported that a worker had putled off some plywood during a stripping operation when he was hit in the eye by anal. The worker went to a Caty MD. A DOB inspector responded to the incident and visited the site and reported that the worker was not wearing his safety gogles/PFC (Personal Protection Equipment). An ECB Violation was issued for a failure to maintain safe operations.		ECB Violation Numbers 35343005L	DOB Violation Numbers	Permit	Permit No	Incident Type Other Construction Related Incidents	Owner's Name PARK ROW 23 OWNERS LLC	Contractor Name
7/5/2018	Manhaltan	392	ASSER LEVY PLACE	0 1	The New York City Polics Department reported that an on site works called 011 and sponted table to fill from a supported scalability of the sponted table to fill from a supported scalability of the sponted table to the fill from the ground root level. The worker was found haying on the second level well. The worker was found haying on the second level of the installed poly scalability. The vorker suffered a broken right arm and was ainfilled by the PDWY and themspreds to Bellewide Hospital U and ambulance. The DOS inspector also reported that the minute of the installed poly and that the orthorized of the size of the second level with the ambulance. The DOS inspector also reported that the had dird not engine a permit, and that the contractor was in possession of DOB-issued sidewalk thed and supported scalability permits. The ECS Violations were issued: one violation for the presence of a scalfold that was not enclosed, one Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a failure to safeguard, and a second Aggravated Level 2 violation for a safe to the safe aggravated Level 2 violation for a safe to		35324344M, 35324345Y,35324346X				Worker Fell	PARKS AND RECREATION (GENERAL)	BQE Industries Inc
7/5/2018	Manhattan	701	7 AVENUE	0 1	The Site Safety Manager reported that an electrician cut his arm on a metal stud. The electrician went to urgent	No Dispatch					Other Construction Related Incidents		
7/5/2018	Queens	147-40	ARCHER AVENUE	0 1	care. The Site Safety Manager reported that a worker twisted his ankle while coming down the stairs. The worker went to a City M.D. This incident occurred on July 5, 2018, but the Site Safety Manager was not notified of the incident until July 6, 2018.	No Dispatch t					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
7/6/2018	Manhattan	25	PARK ROW	0 1	The Site Safety Manager reported that a worker on the sixth floor was standing on stills to install track when he walked into a pipe hanger and fell off of the stills and to the ground. The worker complianed of lett arm pain. EMS was called and the worker was taken to a nearby hospital.	No Dispatch			NB	121190610	Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	URBAN ATELIER GROUP LLC
7/7/2018	Manhattan	425	PARK AVENUE	0 1	A DOB inspector reported that a worker stepped on a piece of unsecured phywod on the second floor and fell approximately twenty two feet to the first floor. The worker was taken to a hospital, and its reported to have suffered a discated hip. Four CES Violations were issued, one violation for the presence of floor openings that were not securely covered and marked, a second violation for the presence of very poor houskkeeping throughout the building. for the secne cal perimer phroughout the building. For the secne cal perimer p failum to sufficient persons adviced in project. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35342980M,81Y,82X,83H		NEW BUILDING	121333921	Worker Fell	T-G 425 PARK AVENUE, LLC	TISHMAN CONSTRUCTION CORP
7/7/2018	Manhattan	215	PEARL STREET	0 1	A DOB inspector reported that a worker was using a baker scalified on the twenty fifth floor to perform tapping work. The scalifold was not properly acted, the whethel of the scalifold were not properly placed, and there were housekeeping issues present in the work area. As a result, the worker fell approximately six fleet off of the scalifold. The worker were solved conscious and was taken to a hospital for a checkup. An EGB Violation was sissued for the presence of poor housekeeping under the scalifold. A partial Stop Work Order (PSWO) was issued for all work on baker scalifolds. The General Contractor is to provide a Means and Methods for safe operation.		3533140BJ		121017559	NEW BUILDING	Worker Feil	LAM PEARL STREET HOTEL LLC	ANTHONY T. RINALDI LLC
7/7/2018	Manhattan	1227	BROADWAY	0 1	A DOB inspector reported that a worker was installing rebar inside of column cages on the sixteenth floot. The worker was installing an eighteen foot long, approximately one hundred pound piece of rebar all by humself. When he listed the rebar about three lefet, he lost control of the rebar and was thrown to the floor. The about the rebar and was thrown to the floor. The about the rebar and was thrown to the floor. The about the rebar and was thrown to the floor. The about the rebar and was thrown to the floor. The about the rebar and was thrown to the floor. The about the rebar and was thrown to the floor. The about the rebar and was thrown to the floor. The about the rebar and was thrown to the floor. The about the rebar and was the rebar about the about the rebar and the about the rebar about the about the rebar about the about the about the about the about the rebar about the about the		35346150R, 51Z, 52K		NEW BUILDING	121191986	Material Fell	YJL BROADWAY HOTEL LLC	FLINTLOCK CONSTR SERV LLC
7/9/2018	Bronx	603	JACKSON AVENUE	0 1	The Site Safety Manager reported that a worker fell form a baker scaffold. The worker was experiencing back pain and was taken to a hospital.	No Dispatch			NEW BUILDING	220151840-01-NB	Worker Fell	HP JACKSON AVENUE HOUSING DEVE	GALAXY GENERAL CONTRACTIN



ncident Date		Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
9/2018	Manhattan	111	LEROY STREET	0 1	The Site Safety Manager reported that an electrical worker was on the roof and using a band saw when he	No Dispatch			NB	122622992	Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	PMG CONSTRUCTION GROUP LL
					cut his middle finger one inch deep. The worker was								
					alert and conscious and was taken to a nearby hospital								
					for treatment.								
2018	Manhattan	315	EAST 46 STREET	0 1	A DOB inspector reported that a signal man was giving	No Action Necessary			CN	392/18	Mechanical Construction Equipment	GOVERNMENT OF THE UNITED ARAB	Urban foundation engineering IIc
					signals to a crane operator that was operating a mobile								
					crane that had a a load on its hook. While giving signals, the signal man got his glove caught inbetween								
					the crane's main hoist cable and the sheave of a load								
					block. The signal man suffered a severed left pinky								
					finger and was taken to Bellevue Hospital. The inspecto	r							
					reported that the crane operator was in possession of a								
					sixteen hour rigging card and had all required certifications, paper work, and logs on site. The other								
					members of the work crew were also in possession of								
					sixteen hour rigging cards. No enforcement action was								
					deemed necessary, as it was determined that the incident occurred as the result of a worker error.								
					incident occurred as the result of a worker error.								
2018	Queens	36-18	MAIN STREET	0 1	The Site Safety Manager reported that a roofer got	No Dispatch					Other Construction Related Incidents	134-22 35TH AVE., LLC	
					some waterproofing material in his eyes while he was spraying. The roofer walked to an urgent care center.								
/2018	Brooklyn	1520	FULTON STREET	0 1	The Site Safety Manager reported that a plumber that	No Dispatch					Other Construction Related Incidents	HELLO FULTON LLC	
					was working in the basement slipped on water that was								
					on the floor and hurt his knee. The worker went with another worker by car to see a doctor.								
					another worker by car to see a doctor.								
/2018	Brooklyn	170	BUFFALO AVENUE	0 1	The Site Safety Manager reported that a worker fell from	No Dispatch					Other Construction Related Incidents	BUFFALO AVE. REALTY ASSOCIATES	-
2010	Stoonlyff	170	SOTTALO AVENUE	0	an "A"-Frame ladder and hurt his ankle. The worker	, ito Diapaton					Galar Construction Related incidents	SOLTALO AVE. NEALTT ASSOCIATES	
					went to a hospital by ambulance.								
/2018	Manhattan	19	EAST 70 STREET	0 1	The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NY 70TH STREET LLC, A NY LLC,	
					carrying a pail of sweeping compound on his shoulder when he lost control of the pail and the pail fell on his								
					right leg. The worker was sent to a hospital.								
					ngin log. The worker was sent to a hospital.								
2018	Manhattan	218	EAST 16 STREET	0 1	The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	SOCIETY OF FRIENDS	
					cutting off a tie-wire from an extension cord when he cut	t i i i i i i i i i i i i i i i i i i i							
					his hand with a cutting knife. The worker had his								
					protective gloves on, but the knife went through the top								
					of the glove, between the thumb and index finger. An ambulance was called.								
2/2018	Manhattan	524	RIVERSIDE DRIVE	1 0	A DOB inspector reported that a piece of the suspended	DOB Violation		071218CER01KC	ALTERATION TYPE 2	122912027-01-EW-OT	Scaffold/Shed/Fence/Shoring/Installation	INTERNATIONAL HOUSE	PRATT CONSTRUCTION & REST
2010		024			scaffold system became dislodged at the roof level, fell	BOD Holdion		of 12 hoden of the			ocurior of concerning installation	internationale noode	i iuni conoridoriona ileor
					twelve stories, and struck a workder in the head. The								
					worker was taken to the nearest hospital in critical condition, but later succumbed to his injuries. A DOB								
					Violation was issued for a failure to safeguard and a full								
					Stop Work Order (FSWO) were issued.								
/2018	Brooklyn	138	WILLOUGHBY STREET	0 1	A DOB inspector reported that there were workers using	ECB Violation	35322622Y	071318CERSM01	NEW BUILDING	321197085-01-NB	Other Construction Related Incidents	NYC HPD	LEND LEASE (US) CONSTRUCT
					chainfalls to move on the ground the collar of a crane in								
					order to position it into a better working position as part of a crane jumping operation. While the collar was being								
					moved, one of the worker's legs was pinned between	1							
					the collar and a piece of the building. The worker was								
					taken to Methodist Hospital by ambulance. The crane								
					was not being used as of the time of the incident. The inspector reported that incident was caused by the use								
					of inadequate means and methods in rigging by the								
					Master Rigger. An ECB Violation was issued for a failure	э							
					to safeguard. A DOB Violation was also issued.								
/2018	Manhattan	20	WEST 40 STREET	0 1	The New York City Fire Department requested that an	ECB Violation	35326871N				Other Construction Related Incidents	NOT ON FILE	
					inspection please be performed because a construction								
					worker suffered a head injury after coming into contact with a grinder. The worker was in stable condition and								
					suffered a broken nose. The worker was in stable condition and								
					a hospital by EMS and received butterfly stitches on his								
					forehead. The worker was released from the hospital								
					after treatment. A DOB inspector responed to the incident and visited the site and reported that the orinde	r							
					was used contrary to the manufactuer's specifications.								
					An ECB Violation was issued for the failure to maintain								
					safe operations. A partial Stop Work Order (PSWO) was issued on the use of all grinders. A Means and Methods	5							
					issued on the use of all grinders. A Means and Methods and a Tool Box Talk must be provided.								
					and a rear box run mus be promote.								
/2018	Queens	24-16	QUEENS PLAZA SOUTH	0 1	The Site Safety Manager reported that a week of the	No Dispatch					Other Construction Palated Insides 1	24-16 QUEENS PLAZA PROPERTY OW	
/2018	Queens	24-16	QUEENS PLAZA SOUTH	0 1	The Site Safety Manager reported that a worker on the top of a deck at the twenty third floor was cut on his arm	NO Dispatch					Other Construction Related Incidents	24-10 QUEENS PLAZA PROPERTY OW	
					by a circular saw. The worker was taken to a hospital by								
					ambulance.								
						No. Bringer					Other Construction Related Incidents	NINE ORCHARD PARTNERS, LLC	
2018	Manhattan	9	ORCHARD STREET	0 1	The Site Safety Manager reported that a worker hurt his	No Dispatch							
/2018	Manhattan	9	ORCHARD STREET	0 1	The Site Safety Manager reported that a worker hurt his back while placing a chipping gun on the floor. An ambulance was called.	No Dispatch					Other Construction Related incluents		



ncident Date	Borough	Address Number	r Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/16/2018	Borough Manhattan	50	AMSTERDAM AVENUE	o 1	EOC imal Description The Project Manager at the site reported that a female worker tripped on a temporary electrical conduit that was laying on the roof of the building. The worker suffered bruised knee and a swollen wrist and was taken to a hospital by amulance. A DOB inspector responded to the incident and visited the site and issued two EOB Violations: one violation for the presence of an unsupported aluminum pipe, and a second violation for the disconnect of 200 amps that ran between the basement and the roofby sub panel. Two DOB Violations were also issued.	ECB Violation	ECB Volation Numbers 353432017, 35343202K	DOB Violation Numbers 71618EE107RID01, 71618EE107RID02	-ennx	- dinit NG	Incident Type Worker Fell	Owner's Name	Constituti name
7/16/2018	Manhattan	36	GROVE STREET	1 0	A DOB inspector reported that a worker was performing an electrical installation on an energized circuit in the bathroom. The worker suffered at 120 volt electrical shock. The worker staten to Lenox Hill Health Piezy, where he was pronounced dead. The inspector reported that the worker failed to de-energize the circuit before performing the electrical installation. Three ECB Violations were issued: one violation for the presence of unapproved and unsafe wiring that had not been terminated, unsupported boxes, unsecured splice boxes, the failure to provide a CPC1, and the failure to provide a lamp guard for temporary lights, one violation for the failow to pot an electrical provide actione Violation for the use of an electrical room as storage.	ECB Violation	35315697N, 35315698P & 35343200R	71618EE102RID01, 71618EE102RID02 & 71618EE102RID03			Other Construction Related Incidents	LUKE, TIMOTHY	
7/16/2018	Brooklyn	25	COLUMBIA HEIGHTS	0 1	The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was driven to a hospital.	No Dispatch					Other Construction Related Incidents	25-30 COLUMBIA HEIGHTS BROOKLY	
7/17/2018	Manhattan	125	GREENWICH STREET	0 1	arriven to a nospital. The Site Setter Manager reported that a worker was performing a window installation when he flipped over a piece of tube steel and got his index finger caught between the tube steel and the floor. The tip of the worker's index finger was crushed. The worker went to a hospital by taxi.	No Dispatch					Other Construction Related Incidents	VS 125 LLC	
7/17/2018	Queens	28-07	JACKSON AVENUE	0 1	The Site Safety Manager reported that a truck driver cut his finger while loading garbage. 911 was called.	No Dispatch					Other Construction Related Incidents	LIC SITE B-1 OWNER, L.L.C.	
7/18/2018	Brooklyn	422	FULTON STREET	0 1	The Site Safety Manager reported that a worker slipped and fail into a $3 \times 3 \times 2$ deep hole during a refear inapection in the cellar. The worker suffered leg highly and an anti-utance was called. A DOB inspector responded to the incident and visited the site and confirmed the Site Safety Manager's report. The inapector determined that the incident occurred as the result of a human error and that no enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	NOT ON FILE	
7/18/2018	Manhattan	214	WEST 29 STREET	0 1	A competent person at the site reported that a worker slipped off an "A"-Frame ladder. The worker went to a hospital for a check up.	No Dispatch					Other Construction Related Incidents	WALSAM TWENTY-NINE CO	
7/18/2018	Manhattan	24	2 AVENUE	0 1	The Site Safety Manger reported that a worker stepped on a nail. The worker walked to medic care for a check up	No Dispatch					Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	
7/18/2018	Queens	147-40	ARCHER AVENUE	0 1	The Site Safety Manager reported that a worker was walking down a flight of stars when he lost his balance on the bottom step and hurt his right foot. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
7/19/2018	Brooklyn	420	UNION STREET	0 1		No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
7/19/2018	Manhattan	140	ESSEX STREET	0 1	The Construction Superintendent reported that during a diffing operation, a accitor of a diffi bit fell and thit a worker in the back. The worker was awake and conscious and was able to walk, but parametics put the worker on a stretecher and took him to a hospital. The foreman at the site also work to the hospital to check on the worker. The Construction Superintendent reported that the worker had suffered minor bruises, with no broken bones, and was released from the hospital A DOB singeotor responded to the incident and visited the site and reported that the Construction Superintenders (incres had segued. An EOB Vorkion was issued for a failure to safeguard. A Full Stop Work Order (FSWO) was also issued.	ECB Violation	35336263z		FO	121187642	Material Fell	SITE 8 DSA HOUSING DEVELOPMENT	Essex Site 8 Builders LLC
7/19/2018	Manhattan	625	WEST 125 STREET	0 1	The Site Safety Manager reported that a worker was installing a light fixture when he tripped over the light fixture and hurt his knee. The worker went to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	THE TRUSTEES OF COLUMBIA UNIVE	
7/20/2018	Manhattan	30	EAST 31 STREET	0 1	The Site Safety Manager reported that a pedestrian was entering her building when she was hit in the head by a piece of dehis that tell from a construction site. The pedestrian did not suffer any visible injuries, but an ambulance was called. A DOB inspector responded to the incident and visited the site and and issued an ECD Violation for a failure to safeguard. A partial Slop Work Order (PSWO) on all concrete work operations was also issued. A Mean and Methods for safe operations must be provided.	ECB Violation	35342859K				Other Construction Related Incidents	31ST STREET ZEF LLC	



	Borough	Address Numbe		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/2018	Brooklyn	3514	SURF AVENUE	0 1	A DOB inspector reported that a worker was stripping	ECB Violation	35342860H/61J/62/	072118BS13EP01/02/03			Worker Fell	RED APPLE SURF REALTY III LLC	
					plywood with two workers coming from behind him. The worker that was performing the stripping did not notify								
					the other workers that he opened a hole, and the worker								
					that was performing the stripping operation fell two								
					stories through the hole. The worker was found								
					conscious and was taken to an area hospital. The								
					inspector observed that the protocol for a pre-task								
					meeting for stripping operation was not followed up, and								
					that there were house keeping issues present at the top								
					floor that were recorded by the Site Safety Manager.								
					Three ECB Violations were issued: one violation for the								
					failure to maintain or institute safety measures for								
					construction operations, one violation for the failure to revise the pre-shift task meeting, and one violation for								
					the failure to provide a Professional Engineering letter or								
					design drawing for protection at large slab openings.								
					Three DOB Violations were also issued. A partial Stop								
					Work Order (PSWO) was issued on concrete and								
					stripping operations. A Means and Methods for the safe								
					continuation of work must be provided.								
2018	Manhattan	545	WEST 30 STREET	0 1	The Site Safety Manager reported that a worker was in the hoist with equipment when he got his foot caught	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
					under the equipment. The worker went to urgent care.								
)18	Manhattan	401	WEST 31 STREET	0 1	A DOB inspector reported that there was work being	ECB Violation	35245391J	072318CNEDB01	A2 - ALTERATION TYPE 2	123091705	Worker Fell	BOP WEST 31ST STREET LLC	JOHN CIVETTA & SONS INC
					performed under the street level for the removal of existing Amtrak tracks and the installation of new steel								
					for the relocation of an existing sub-station. An iron								
					worker was installing steel decking when he fell								
					approximately ten feet through a gap and suffered a								
					fractured arm. The worker was found in stable condition								
					and with his harness on, as the harness had to be cut								
					off by EMS. The worker was taken to a hospital. An ECB								
					Violation was issued for a failure to safeguard. A DOB								
					Violation was also issued. A partial Stop Work Order								
					(PSWO) was issued for all steel work bering performed								
					for the relocation of a sub-station.								
018	Manhattan	217	WEST 57 STREET	0 1	The Site Safety Manager reported that there were workers that were backing up a trailer on the job site	No Dispatch					Other Construction Related Incidents	SMITELL SPONSOR LLC	
					with flaggers when a bicyclist went around the flagger,								
					slipped on wet pavement, and hurt his arm. The								
					pavement was wet because of rain. The bicyclist did not								
					hit the trailer. An ambulance was called.								
018	Manhattan	152	EAST 87 STREET	0 1	A worker fell back and scrapped his arm against a trash	No Dispatch					Other Construction Related Incidents	ALLAN GARAGE,	
					chute. The worker went to a hospital for treatment. The								
					worker received two stitches and returned to work.								
018	Manhattan	150	EAST 38 STREET	0 5	A DOB inspector reported that contractors were	ECB Violation	35343417H		Alt 1	123254263	Other Construction Related Incidents	SUN, ANGELA	zzz carpentry Inc
010	Marinattan	130	EKST 30 STREET	0 5	performing interior demolition work on the fourth floor	LOD VIOLATION	3334341711		ALL	123234203	Other Construction Related Incidents	SON, ANGELA	222 calpentry inc
					when the wood and plaster ceiling collapsed and injured								
					five workers. Two of the workers were in serious								
					condition and were taken to Bellevue Hospital. No								
					structural damage was observed. An Aggravated Level								
					2 ECB Violation was issued for a failure to safeguard. A								
					full Stop Work Order (FSWO) was also issued.								
18	Manhattan	19	EAST 70 STREET	0 1	A DOB inspector reported that during the hoisting of	ECB Violation	35324422Z - 35324423K		Alt 1	121944227	Material Fell	NY 70TH STREET LLC, A NY LLC,	Sweeney & Conroy Inc
					pipe scaffold frames from the fifth floor down to the								
					interior of a stairs shaft, one of the frames got loose and								
					hit the Construction Superintendent in the head on the								
					second floor, knocking him unconscious. The worker								
					was taken to Presbyterian Hospital in stable condition.								
					Two ECB Violations were issued: one violation for a								
					failure to safeguard all persons affected by construction								
					operations, and one violation for work being performed								
					that did not conform to approved plans. A partial Stop								
					Work Order was issued for material hoist work and for supported scaffold work.								
					supported scanold work.								
18	Manhattan	315	EAST 46 STREET	0 1	The Site Safety Manager reported that a worker	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
					performing form work when he got his finger pinched								
					during an installation and suffered a cut to his finger. The worker went to urgent care.								
18	Queens	43-12	HUNTER STREET	0 1	The Site Safety Manager reported that a worker in the	No Dispatch					Other Construction Related Incidents	43-12 HUNTER LLC	
					basement cut his right eye while moving rebar. The worker went to a City M.D. with a co-worker.								
						N. Brand					010		
018	Staten Island	546	GULF AVENUE	0 1	The Site Safety Manager reported that a worker was experiencing back pain. The worker left the site to go to	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
					experiencing back pain. The worker left the site to go to a hospital on his own.								
	Staten Island	546	GULF AVENUE	0 1		No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
18		340	COLI AVENUE	0	was using a chain when the chain slipped out of his	no Dispaton					Galer Construction Related incluents	STATEM ISEAND SEODAE EOGISTIC	
18	otatorristand												
3	Clater Island				hand and pinched his left finger. The worker went to urgent care.								



ncident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	250	SOUTH STREET	0 1	The Site Safety Manager reported that an iron worker was on a main fill and working on a small pace of steel clip that was approximately 2" X 4" when he lost control of the clip and fell approximately 30 inside the job site. A DOB inspector responded to the incident and visited the site and reported that the worker suffered a minor injury to his shoulder from the steel clip when the clip fell. The worker do not report the injury, and left the site whoth Lefting anyone know. An ambulance was not called. The worker later reported that he works one a doctor. An ECB Violation was issued for the failure to institute safety measures. A DOB Violation and a partial Stop Work. Order (PSWO) were also issued.		35331367R	072618BS03JJ01			Material Fell	NOT ON FILE	
26/2018	Manhattan	215	PEARL STREET	0 1	The Site Safety Manager reported that a worker was standing on a ladder that was behind a closed door when another worker opened the door and knocked the worker off of the ladder. The worker thit his head, and ar ambulance was called. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for affaulter to institute safety measures. A DOB Violation was also issued. A partial Stop Work Order (FSWQ) was issued on all door closure installations. A Means and Methods and a safe Controlled Access Zine area for fadder work during an installation must be provided.		35342769R	072618BS01KR02			Worker Fell	LAM PEARL STREET HOTEL LLC	
/27/2018	Manhattan	438	WEST 54 STREET	0 1	A DOB inspector reported that a worker was on a truck and receiving blanks while dismantling a sidewalk shed when he to shis tooling and fell off to the truck and once a pedestrian. The pedestrian received aid from the onstes Sidewalk Shed company. The Storough Scatfloling. The pedestrian requested medical treatment. The FDN' responde to the request and visited the site, and examined both the worker that fell from the truck and the pedestrian. The worker was determined to be okay and returned to work, while the pedestrian as then to a hospital. The worker local verse issue: one violation for a failure to safeguard pedestrian as then to a hospital. Two CED Violations were issue: one violation for a failure to safeguard pedestrians and then to a hospital. Two CED Violations of reference of the site of the site of the truck the site of the order (rSWO) was also issued.		35324486H - 35324487J		NB	122822605	Worker Feil	15024 EMMUT PROPERTIES LLC	Best Point Mgmt Corp
30/2018	Bronx	1812	VYSE AVENUE	0 1	The Site Safety Manager reported that a worker was moving pipes when his right middle finger got caught between pipes. The worker went to the emergency room with his supervisor. An ambulance was not called.						Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	
30/2018	Bronx	4511	3 AVENUE	0 1	The Site Safety Manager reported that a plumber was tightening a sprinkler pipe when he hit a stud and cut hir finger. The worker walked to urgent care across the street from the job site.	No Dispatch					Other Construction Related Incidents	STB HOUSING DEVELOPMENT FUND C	
30/2018	Manhattan	110	UNIVERSITY PLACE	0 1	The Site Safety Manager reported that a worker was on a ladder when he mis-stepped, fell off of the ladder, and pulled his back at. The worker went to urgent care.	No Dispatch					Worker Fell	NOT ON FILE	
/30/2018	Manhattan	122	EAST 23 STREET	0 1	The Site Safety Manager reported that a cleaning person was cleaning the apartments when she worth down to the caller. When there was construction work down to the caller when there was construction when the she was an experiment of the she was of all the deviative and thit her foot on a maxifielt that was left in the basement. The maxifier was in the basement because it was being used in construction work that was being performed. The cleaning person went to urgent care on her own.						Other Construction Related Incidents	NOT ON FILE	
30/2018	Manhattan	233	WEST 125 STREET	0 1	SThe Site Safety Manager reported that at a twenty six story new building that was under construction, a worke was cutting rebar with a chop saw when a fragment of the rebar hit him in the face. The worker did not appear to suffer any cuts. The worker went to see a private doctor.	No Dispatch			NB	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
1/2018	Brooklyn	269	4 AVENUE	0 1	doctor. The Site Safety Manager reported that at the foundation level of a twelve story new building, a worker was loading in plywood material when he pinched his left pinky finger between plywood. The worker was found alert and conscious and was taken to Lutheran Hospital for treatment.				NB	320596805	Other Construction Related Incidents	FIRST BUILDING ENTERPRISES LLC	NEW EMPIRE BUILDER CORP
1/2018	Manhattan	26	ANN STREET	0	The Site Safety Manager reported that a worker was using a utility knife when he accidentally cut himself by mistake. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	143 FULTON STREET DEVELOPMENT	



cident Date		Address Number		lities Injuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	77	WEST 55 STREET	0 1 A DOB inspector reported that there were workers that were in the process of installing a sidewalk shed on top of a baker scaffold when one of the workers tost his footing and relIL. During the fail, the worker lost his hard hat and burnped his forehead on a mud sill. The worker was found conscious and was taken to a local hospital. Two ECB Violations were issued to the General safeguard all presons and yongethy affected by construction operations, and the supported scaffold did not feature any quartarilis, and a second violation for a failure to provide a four hour supported scaffold user centificate. A partial Stop Work. Order (PSWO) was also issued.		35324558H, 35324553Z		Ait .	M00050141	Worker Fell	GALLERY HOUSE CONDOMINIUM	Phonex Sutton Str Inc
2018	Queens	110	UNIVERSITY PLACE	1 A DOB inspector reported that there were workers that were moving an "A"-Frame ladder that was overloaded with sheet metal when the "A'-Frame collapsed and tell onto the legs and feet of one of the workers. The worker was taken to Belleview Hospital by arbuitance for treatment. Two ECB Violations were issued: one violation for the presence of unsale working conditions and equipment, and a second violation for the abaence partial Stop Work Order (PSWO) was issued on all use of "A'-Frame ladders. A Tool Box Talk and a sequence for the handling of materials must be provided.		35345140N,41P		NB	121187241	Other Construction Related Incidents		CNY CONSTRUCTION LLC
2018	Brooklyn	3021	WEST 25 STREET	1 A DOB inspector reported that during the alteration of a existing building, a worker was using an excavator to organize piping, while there was another worker that was standing behind the excavator. The excavator backed up whotor notice, and the worker that was standing behind the excavator. The worker was found dath the bucket of the excavator. The worker was found dath ECB Violation was itsue for the presence of unsafe conditions and exgument. A partial Sky Work (PSWO) was issued on handling material and plumbing operations.	r	ECB#353161125M-UNSAFE CONDITIONS AND EQUIPMENT	080218BS13KR01	NB	321447243	Excavation/Soil Work	NYC HOUSING AUTHORITY	AWL INDUSTRIES INC
2018	Manhattan	1	WALL STREET	0 1 The Site Safety Manager reported that a worker hit his left eye while removing form work. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
2018	Manhattan	621	GREENWICH STREET	organization of this own:         The Project Manager at the site reported that a worker         was on a scaffold when he slipped and fell while trying         to move away from the rain. The worker hurt his         shoulder and was taken to a hospital by EMS.	No Dispatch					Worker Fell	PMG LEROY STREET DEVELOPMENT L	
2018	Manhatlan	441	9 AVENUE	The Site Safety Manager and a DOB inspector reported bits an excitent wavered and a DOB inspector reported bits fail arrows and the safety of the safety of the safety and the urgent care conter called an ambulance to transport the worker to a hospital. The Site Safety Manager was not informed of the incident until the end of the day on August 3, 2018, and din or teport the incident immediately to the Department Of Buildings because he wanted to have all of the facts of the sisted including point bits and the safety of housekeeping, one violation for the presence of unaceured reshores at the leading edge, and one violation for a failure to noity bits of the presence of unaceured reshores at the leading edge, and one violation for a failure to noity the Department Of Buildings of the incident in a timely manner. Five DOB Violations were also issued.		35345468R/892/70X/71H/72J	080418BS04GD03/04/05/06/07			Worker Fell	CBP 441 NNTH AVENUE OWNER, LL	
2018	Manhattan	110	CHARLTON STREET	0 1 The Site Safety Manager reported that two workers wer carrying mear on the first floor when one of the workers lost his balance and hurt his shoulder. The injured worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	
018	Manhattan	10	VANDERBILT AVENUE	0 1 The Site Safety Manager reported that a worker was coming down the stairs when he tripped and fell. The worker sulfered a laceration to his back. EMS took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	ONE VANDERBILT OWNER LLC	
018	Brooklyn	2442	OCEAN AVENUE	Waters to a notation     (1) The Site Safety Manager reported that a worker was     locking for a showl when he slipped on form work in the     cellar. The worker did not notify the Site Safety Manage     of the incident until three hours after the incident     occurred. The worker went to upgert care on his own.						Other Construction Related Incidents	2442 OCEAN AVENUE, LLC	
018	Brooklyn	10	NEVINS STREET	0 1 The Site Safety Manager reported that a worker was handling duct work when he cut his hand on sheet metal. The worker was found conscious and alert and was taken to Brooklyn Hospital for treatment. The worker required several stitches.	No Dispatch			NB	320915578	Other Construction Related Incidents	NEVINS STREET OWNER LLC	DANYA CEBUS CONSTRUCTION



	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
3/2018	Bronx	316	EAST 165 STREET	0	2 A DOB inspector reported that a side bracket for a supported scalified collepsed at the third floor level with two workers that were laying bricks. The workers landed on the working level below, suffered minor injuries, and went to Broxx Care Health System Hospital. The collapse was caused by a loose champ for the side bracket. As of the time of inspection, the working level was put back together. Four CES Volations were issued: one Aggravated Level 2 violation for work being performed that was not in accordance with approved plans, one violation for the failure by one of the workers involved in the collapse to provide a supported calfold training card, and for the foreman that was supervising an expined supported scalfold training card, one violation for the failure to keep the equipment that was related to the construction incident untouched. A partial Stop Work Order (PSWO) for the use of supported scalfolds was also issued.		35344814X, 35344815H, 35344816J, 35344817L		NB	220619150	Worker Fell	CG EDUCATIONAL HOLDING CORP.	Hollister Construction Se
2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that at an Alteration 1	No Dispatch			ALT 1	121333413	Worker Fell	NOT ON FILE	CNY CONSTRUCTION LLC
					job at a fifty eight story building, on the twenty-ninth floor, a worker mis-stepped while stepping onto a landing and twisted his ankle. The worker was found conscious and alert and was taken to New York Prebyterian Hospital for treatment.								
3/2018	Manhatlan	445	WEST 35 STREET	0	1 The Site Safety Manager reported that a worker was ripping physicod with a tablesaw when he cut his hand by inpactor responded to the incident and visited the site and reported that the worker was using a cordisas circular awa aper the manufacturer's specifications. Because of this, it was determined that the incident occurred as the result of a worker's error, and that no enforcement action was necessary.	No Action Necessary					Other Construction Related Incidents	CARE REALTY CORP.	
018	Queens	45-57	UNION STREET	0	1 The Site Safety Manager reported that a worker was moving metal angles around the site when he cut his arm on one of the metal angles. The worker went to an emergency room on his own.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
2018	Manhattan	60	WEST 129 STREET	0	1 A DOB inspector reported that approximately twenty four feet of parapet fell onto a public street. A pedestrian suffered an unconfirmed injury. The pedestrian was treated at the scene and released. An ECB Violation was issued for a failure to safeguard. A DOB Violation was also issued.	ECB Violation	35323035Y	080718CERSM01	A2 - ALTERATION TYPE 2	121230382	Scalfold/Shed/Fence/Shoring/Installation	LENOX LLC	D&L DESIGN & BUILD LLC
2018	Manhattan	130	WILLIAM STREET	0	1 The Site Safety Manager reported that a worker fell and hurt his chin while picking up rebar. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	
/2018	Manhattan	108	EAST 89 STREET	0	A ADDB inspector reported that a worker was on the Iwelfin floor installing insulations inside of partition walls. He attempted to move some sheethock that was behind a stack of abeetrock that was learning against the wall in order to insall insulation material when a stack of sheetrock fell on his ankle. The worker din ot appear to have any visible injury, but compared not pain. The worker's foreman took him to a hospital for a check up. No enforcement action was deemed necessary, as it was determined that this incident occurred as the result of worker eror.					122988623	Material Feli	DALTON SCHOOLS INC	EW. HOWELL CO, LLC
2018	Brooklyn	277	SOUTH 5 STREET	0	1 The Site Safety Manager reported that a worker was stripping form work in the basement when a piece of plywood hit him in the shoulder. The worker want to a hospital by ambulance for a check up. The Slatety Manager also reported that the worker will be returning to work.	No Dispatch					Other Construction Related Incidents	HAVEMEYER OWNER LLC	
/2018	Brooklyn	2401	AVENUE Y	0	The Project Manager at the site reported that a worker opened a roof hatch and fell approximately thirteen and a half fest through an opening. The worker suffered a first-timed paivis and elibox. A DCB inspector responded guardrafia were provided around the opening at the root, which caused the worker to fail. An ECB Volation was issued for the failure to safeguard all persons and/or property affected by construction operations. A full Stop Work Order (FSWO) was also issued.		35350727M	060816BS15LJ06			Worker Fell	PARKS AND RECREATION (GENERAL)	
2018	Brooklyn	555	4 AVENUE	0	The Site Safety Coordinator reported that a worker was moving rebar when he hit himself in the mouth and chipped his tooth. The worker went to a medical office on his own.	No Dispatch					Other Construction Related Incidents	PARTNERS VI/541-555 FOURTH OW	



ncident Date		Address Number		Fatalities Injuries			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Staten Island	546	GULF AVENUE	0	1 A DOB inspector reported that a worker was in the process of pulling a rope inside of a pull box that was next to an electrical panel. There was a knife laying inside of the panel. While the worker was pulling the rope, the vibration caused the knife inside of the panel to all the pulling the panel. There was a knife inside of the panel to all the panel the panel. There was a knife inside of the panel of the panel to all the panel to all the panel. There was a knife to be panel to be panel. The panel the panel to be panel to be panel to be panel to be panel. The panel the panel of the panel of the panel to be panel. The panel to be panel to be panel to be panel to be panel. The panel to be panel to be panel to be panel to be panel. The panel to be	No Action Necessary					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Manhattan	787	11 AVENUE	0	1 The Site Safety Manager reported that an electrician was cutting a pipe with a bend saw when he cut his finger tip. The worker went home to see his doctor. A co- worker went with him.	No Dispatch			ALTERATION-1	121190399	Other Construction Related Incidents	GEORGETOWN ELEVENTH AVENUE OW	CAULDWELL WINGATE CO LLC
/2018	Brocklyn	2527	CHURCH AVENUE	0	The Construction Superintendent reported that a worker fell on the first floor. The worker was taken to a hospital by ambulance. A DOB inspector responded to the incident and visited the site and reported that no one at the site knew tworker's name, and that there was no report of the incident given. An ECB Violation and a full Step Viol. Order (FWO) were issued for a violation of the responsibility for safety under Building Code Chapter 30(1.1.1.		36332476Y				Other Construction Related Incidents	2627-2529 CHURCH GROUP LLC	
9/2018	Brooklyn	211	MCGUINESS BOULEVARD	o	1 A DOB inspector reported that at the construction of a new nine story residential building, there was a pipe scaffold that wais in the process of being removed. While the workers were taking down the sideand end bracket from the scaffold of the scaffold with a rope pulley, the bracket hit one of the scaffold with a rope pulley, the bracket hit one of the workers that was standing on the fourth floor of the scaffold with a rope pulley, the bracket hit one activation of the scaffold hat. The struck worker was found conscious and that. The struck worker was found conscious and the struck worker worker worker worker worker voltation for the installation of more deciles beams that were contrary to the approved plan issued to the scaffold was also issued.		35361651X - 35351652H		Ait 3	340442550	Scalfold/Shed/Fence/Shoring/Installation	MCGUINNESS DEVELOPMENT LLC	Rock Group of NY Corp
9/2018	Bronx	300	HUTCHINSON RIVER PARKWAY	0	1 The Construction Superintendent reported that an electrician at the site was on an "A"-Frame ladder when he missed a step, fell, and hurt his foot. The electrician was taken to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	PARKS AND RECREATION (GENERAL)	
9/2018	Bronx	2028	WEST CRESTON AVE	0	The Site Salety Manager reported that a worker was using a wire around a pipe when he lost his pip and the Salety Manager reported that a worker was using a wire around a pipe when he lost his grip and the wire sid, causing the pipe to hit him on the side of the head. An ambulance was called.						Other Construction Related Incidents		
2018	Bronx	1812	VYSE AVENUE	0	1 The Site Safety Manager reported that a worker was moving a cast iron pipe when he twisted his ankle. The worker went to urgent care for treatment.	No Dispatch					Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	
10/2018	Manhattan	115	DELANCY STREET	0	1 The Site Safety Manager reported that a painter had finished his work using a spray gun and went to clean disases when be disconnected the spray gun from the hose. Dirty water went into the worker's eye. The worker was taken to a booptial by ambulance in order to have his eyes cleaned.	No Dispatch			NEW BUILDING	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
10/2018	Marhattan	1465	PARK AVENUE	0	<sup>1</sup> The Site Safety Manager reported that a worker was sitipping concrete form work. The worker was tied off, but his retractable cable did not unless, jarking him and the site of the same site of the same site of the probability of the same site of the same site of the probability of the same site of the same site of the site and issued an ECB Violation for inadequate safety measures. A DOB Violation was also issued. A partial Stop Work Order (FSWO) was issued for all form work and stripping certains. A Means and Methods for safe stripping and form work operations, and to check workers Personal Protection Equipment (PPE), must be provided.		35319942H	081018BS11BG04			Worker Fell	LEX GARDENS II TP4 HOUSING DEV	



ncident Date		Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0/2018	Manhattan	553	WEST 30 STREET	0	1 A DOB inspector reported that there was an electrician that was drawing wires on the fifty-seventh floor when he istepped on plywood that was used to cover a floor opening for mechanical duct work. The plywood that was used for the floor covering was not in proper covering and the and a securice to the floor. The blyhand when the worker stepped on it, the plywood split in the worker's leg was cut by a rebar that was protruding from he floor. The worker was transported to a hospital by ambulance. An ECB Violation was issued for the failure (PSWQ) was issued for all work on the fifty-seventh floor and in proxmity of floor openings and shafts.		35350712X		NEW BUILDING	121184208	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
/10/2018	Queens	29-22	NORTHERN BOULEVARD	0	1 A DOB inspector reported that there were workers that were moving a diese fuel container on a doil when they lost balance on the sidewalk, causing the diesel fuel to splash a pedestrian that was standing on the sidewalk. The cap of the barrel was broken and was not dosed during its transfer out of the construction site. The pedestrian was transported to a hospital by EMS. The workers that were moving the diseal fuel container di not have a 0 efficience of times from the Fire Department. The job did not have a Fire Department permit for the storage and use of diseal fuel at the site. Three EOS Molators were issued: one violation for the off or the handing of flammable liquid without an FDMY Certificate Of Finess, and one violation for the storage and use of flammable liquid at we site without an FDMY permit. A partial Stop Work Order (PSWO) was also issued.	r I	35350687N, 35350688P, 35350689R		NEW BUILDING	420650398	Other Construction Related Incidents	OSB NORTHERN LLC	LEEDING BUILDERS GROUP LL
13/2018	Queens	28-07	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker was installing an exterior panel when he cut his finger on a	No Dispatch					Other Construction Related Incidents	LIC SITE B-1 OWNER, L.L.C.	
13/2018	Manhattan	817	BROADWAY	0	metal clip. The worker went to a clinic. 1 The Site Safety Manager reported that a worker in the basement was removing some debris when he was stuck in the hand by a hypodermic needle. The worker went to a hospital.	No Dispatch					Other Construction Related Incidents	817 BROADWAY OWNER LLC	
13/2018	Manhattan	441	9 AVENUE	0	1 The Site Safety Managar reported that a worker fell off of an extension ladder on the seventeenth floor and hurt his head and arm. An ambulance was called and took the worker to a hospital. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for a failure to institute cately measures. A DOB Violation was also issued.		35332478H	081318BS04DH02			Worker Fell	CBP 441 NINTH AVENUE OWNER, LL	
13/2018	Brocklyn	814	BEDFORD AVENUE	0	1 A DOB inspector reported that at a new building that was under construction, a worker was working in the basement when his heinet was struck by a failing metal post. The worker was taken to a hospital by ambulance, and was released from the hospital without injury. An EOB Violation was issued for a failure to safeguard the public and property during construction operations. A DOB Violation was also issued. A full Stop Work Order (FSWO) was issued to the job site.		35323079X	081318CNELC01	NEW BUILDING	321362565-01-NB	Other Construction Related Incidents	814 PARK LLC	PARKVIEW BUILDERS LLC
/14/2018	Brooklyn	10	HURON STREET	0	<ol> <li>The Site Safety Manager reported that a worker was walking down the stairs when he tripped on the last step and bumped his head. The worker went to a City M.D.</li> </ol>						Other Construction Related Incidents	10 HURON FS CONDO LLC	
/14/2018	Manhattan	249	WEST 14 STREET	0	1 The Site Safety Manager reported that a pedestrian in a wheelchair was going over a ramp in the walkway and lipped backwards in the wheelchair. An ambulance was called, A DOB inspector responded to the incident and visited the site and issued an ECB Violation for the presence of a ramp that was inadequate for wheelchair accessibility, A DOB Violation was also issued. A partial Stop Work: Order (PSWO) was issued for the use of a hydrant hose covered by a ramp on a pedestrian walkway.		35345323X	081418BS04VP04			Other Construction Related Incidents	261 WEST 14 STREET, LLC	



ncident Date	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
15/2018	Brooklyn	308	NORTH 7 STREET	0	1 The New York Citip Fire Department requested that an inspection please be performed use to a worker falling from a scaffold. A DOB inspector responded and visited the site and reported that the General Contractor was in the process of dismantling a supported scaffold. While index as being loaded, the parapet panel ifrom the sidewalk shed collapsed, causing the worker to fall. The worker was conscious and was as loade to move his arms. The worker suffered minor injuries and was taken to a hospital. The CED Violations was issued one violation hospital. The CED Violations was issued to rever his arms. Construction Superintendent for the failure to perform durise, as the Construction Supportient dent allowed the work rate to become overstocked with materials. A partial Slop Worch Order (FSWV) was issued on facade work and the removal of a supported scaffold.		35351611L - 35351612N		NB	320597074	Worker Feil	N7 OWNER LLC	Britt Really LLC
5/2018	Manhattan	110	CHARLTON STREET	0	The Site Safety Manager reported that a worker stepped on a nail. The worker went to urgent care.	No Dispatch			NEW BUILDING	121191263-01-NB	Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	PLAZA CONSTRUCTION LLC
/15/2018	Manhatan	1558	3 AVENUE	0	1 The Site Safety Manager reported that a worker on the weety-sight floor was getting ready for his work day shoulder. The worker went to a GVM bD. A DOB inspector was on site as of the time of the incident and reported that there was formwork learning against the reshores, which caused the reshore that struck the worker to fall. An ECB Violation was issued for a failure to institute safety measures. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was also issued.	ECB Violation	35332462N	081518BS08AD01			Material Fell	180 EAST 88TH STREET REALTY LL	
15/2018	Manhatlan	233	WEST 125 STREET	0	1 A DOB inspector reported that a worker was cutting metal straps to remove diff rock of a bundle during a crane footing installation when the metal straps anapper and the local section notified and an entities of the worker's way and the section of the section of the section of the section of the section of the section of the section of the section of the section of the section suffer any troken bones. The worker was later released from the hospital. An EGB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued. The General Contractor was directed to provide a Means and Methods for the loading and unloading of drilling and construction material.		35316082L		NB	121187447	Material Fell	HARLEM URBAN DVLPMNTCP	Flintlock construction IIc
5/2018	Manhattan	555	WEST 22 STREET	0	1 A DOB inspector reported that a female pedestrian was sprayed in the face by hydraulic oil while waiting for the bus. The pedestrian was taken to an area hospital by ambulance. A hydraulic oil line had nutruted in the auge contra of the site on the West 24d Street side, causing hydraulic oil to spray onto the sidewaik and street. An Aggravised Level 2 ECB Violation was issued for the failure to safeguard pedestrians. A DOB Violation was lise lossed. A partial Sbrg Work Order (FSWO) was lise lossed. A partial Sbrg Work Order (FSWO) was lise lossed. A partial Sbrg Work Order (FSWO) was lise lossed. A partial Sbrg Work Cerler (FSWO) was lise lossed. A partial Sbrg Work as a per the Site Safety Plan, in order to protect pedestrians.		35343881L	081518CERMR01	NEW BUILDING	121204366-01-FO	Other Construction Related Incidents	22ND AND 11TH ASSOCIATES, LL.	RELATED CONTRUCTION LLC
5/2018	Queens	22-44	JACKSON AVENUE	0	The Site Safety Manager reported that a worker was on stills doing taping work when he either tripped or lost his balance and fell, hurting his wrist and ribs. An ambulance was called	No Dispatch					Other Construction Related Incidents	G & M REALTY, L.P.	
5/2018	Queens	22-44	JACKSON AVENUE	0	amount of was called manager reported that while working on a forty-four story new building, a worker got his foot caught between formwork at the interior staticase that was being formed at the second floor. The worker was laten to Einhwist Hospital by ambulance for treatment. The worker was alert and conscious as of the time that the ambulance arrived.	No Dispatch			NB	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
6/2018	Brooklyn	1056	MANHATTAN AVENUE	0	1 A DOB respector reported that during a support of executation copression, a wider was injured by a 12° X 12° bouldar that fell from the support of exacavation waller. The welder was approximately lour feet from the ground when he was hit in the shoulder by the boulder. The welder was found conscious and was taken to a hospital for treatment. A CAT scan and a sonogram were performed on the worker, but no internal injuries were found. An Aggravated Level 2 ECB Violation was issued for the failur to safeguard. A full Stop Work Order (FSWO) was also issued on support of excavation work and welding operations. The contract has been directed to bring the construction documents in for review.	ECB Violation	36336324N		NB	321211960	Material Fell	MANHATTAN EAGLE LLC	Empire management and const
16/2018	Manhattan	130	WILLIAM ST	0	1 The Site Safety Manager reported that two workers were hanging HVAC duct work when one of the workers lost his balance and the duct work hit him in the head. The worker suffered a cut to his forehead. An ambulance was called.	No Dispatch					Other Construction Related Incidents		



/16/2018	Borough	Address Number	Street	Fatalities I	njuries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	30	HUDSON YARD	0	1 The Site Safety Manager reported that a worker was moving a man lift when he ran over his own foot. The	No Dispatch					Other Construction Related Incidents		
					worker felt slight pain and went to see a medic.								
018	Manhattan	25	PARK ROW		1 The Site Safety Manager reported that a concrete bug	mu Na Dispatah			NEW BUILDING	121190610-01-NB	Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	URBAN ATELIER GROUP LLC
010	mainatan	25	PARTIE	0	had stalled and rolled over the machine operator's for	t listagateri			NEW BOILDING	121130010-01-140	Other Construction Related Incluents	PARTICIDUE 23 OWNERS LEG	UNDAN AT LEIEN GROOF LEG
					while the operator was exiting the machine. The operator was transported to a local hospital.								
					operator was transported to a local hospital.								
2018	Brooklyn	11	HOYT STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	
					using a circular saw when the saw kicked back and cu the worker's finger. The worker went to urgent care.	1							
2018	Manhattan	315	PARK AVENUE SOUTH	0	1 A DOB inspector reported that there were workers that	ECB Violation	35350784P / 89Y / 90L	081818BS05BG05/06/07			Other Construction Related Incidents	COLUMBIA REIT - 315 PARK AVENU	
					were working on the ninth floor scaffolding at the exte when a brick came off and hit a pedestrian that was o	1							
					the roadway at exposure two. The pedestrian was in stable condition, but may have possibly suffered two								
					broken toes. The pedestrian was taken to a hospital.								
					The pipe scaffold was found to not be fully adequately enclosed at the ends, with holes in some locations.								
					Debris was not removed at the end of the shift as of the	ie							
					time of inspection. Three ECB Violations were issued one Aggravated Level 2 violation for a failure to								
					safeguard, one violation for the absence of an approv	ed							
					Site Safety Plan at the site, and one violation for the absence of an Occupant Protection Plan for the freigh								
					hallway, and office spaces. Three DOB Violations wer	e							
					also issued. A full Stop Work Order (FSWO) was also issued. A Means and Methods for the safe continuation								
					issued. A Means and Methods for the safe continuation of work must be provided.	'							
2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker was o twelve foot high "A"-Frame ladder on the twelfth floor	n No Dispatch			NB	121328205	Worker Fell	SMITELL SPONSOR LLC	LENDLEASE(US)CONSTRUCTION
					performing duct work when he fell from the ladder and								
					hit his head on a ramp. It is not known from what heig did the worker fall. The worker was conscious and ale	it rt							
					and was taken to Cornell Medical Center for treatmen	L I							
018	Manhattan	540	WEST 53 STREET	0	<ol> <li>A DOB inspector reported that a worker was doing exterior work at the second floor level at exposure one</li> </ol>	ECB Violation	35344820M - 35344821Y		NB	121191968	Worker Fell	CLINTON HOUSING DEVELOPMENT	Mega Contracting GP LLC
					when he fell through the gap between the top deck of the sidewalk shed and the face of the building, landing								
					the sidewalk shed and the face of the building, landing on the ground floor. The worker possibly suffered a	i							
					broken wrist and was taken to a hospital. The sidewal								
					shed deck was not tight to the structure, as there was gap that was covered by a tarp. Two ECB Violations	а							
					were issued: one Aggravated Level 2 violation for a								
					failure to safeguard the public and property, due to the failure to close the gap between the top deck of the	l i i i i i i i i i i i i i i i i i i i							
					sidewalk shed and the face of the building, and one								
					violation for the performance of work that does not conform to the approved plans, as the scaffold was no								
					conform to the approved plans, as the scaffold was no vertically and horizontally tied into the structure at eve	t ov							
					second frame. Two partial Stop Work Orders (PSWO)	y							
					were issued: one PSWO for exterior work from the sidewalk shed level, and a second PSWO for the use	of							
					a supported scaffold.								
	Bronx												
2018		600	BERGEN AVENUE	0	A DOB inspector reported that a worker was stripping	ECB Violation	35319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrcution & development
2018		600	BERGEN AVENUE	0	formwork at the foundation level when he was hit in th	e	35319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrcution & development
2018		600	BERGEN AVENUE	0	formwork at the foundation level when he was hit in the head by a piece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and	e	35319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrcution & development
2018		600	BERGEN AVENUE	0	formwork at the foundation level when he was hit in h head by a piece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoln Hospital, where he was treated f	e	36319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrcution & development
2018		600	BERGEN AVENUE	0	formwork at the foundation level when he was hit in th head by a piece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoln Hospital, where he was treated f a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a failure to safeguard	e pr	35319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrcution & development
2018		600	BERGEN AVENUE	0	formwork at the foundation level when he was hit in the head by a piece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoln Hospital, where he was treated f a concusion. Two ECB Volations were issued: one Aggravated Level 2 violations for a failure to safeguard and one violation for work that was not conforming to	e or	36319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrcution & development
2018		600	BERGEN AVENUE	0	formovick at the foundation level when he was hit in it head by a plece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin Hospital, when he was teated of a concussion. Twe EGB Voltations were issued: one Aggravated Level 2 volation for a failure to safeguard and one volation for work that was not conforming to the approved plan, as the contractor was using plywo as formovick. A full Sog Work Order (FSWO) was	e or , d	35319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrution & development
018		600	BERGEN ÄVENUE	0	formork at the foundation level when he was hit in it head by a piece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin Hospital, where he was treated fi a concussion. Two ECB Violations were issued: one Aggravated Level 2 Violation for a failure to safeguard and one violation for work that was not conforming to the approved plan, as the contractor was using plwon as formwork. A full Stop Work Order (FSWO) was issued for all stropping operations and for the erection	e or od	35319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Construction & developmen
018		600	BERGEN AVENUE	0	formork at the foundation level when he was hit in the head by a plece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoh Hospital, where he was treated fi a concussion. Two ECB Violations were issued: one Aggravated Level 2 Violation for a failure to safeguard and one violation for work that was not conforming to the approved plan, as the contractor was using playous as formwork. A full Stop Work Order (FSWO) was issued for all stripping operations and for the erection concrete formwork. The contractor has been directed bring the construction documents in for review. A Mas	e or od of to to	35319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Construction & development
018		600	BERGEN AVENUE	0	formoork at the foundation level when he was hit in it head by a place of metal that field approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoh hospital, where he was treated a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a failure to saleguard and one violation for work that was not conforming to the approved plan, as the contractor resulting plywood sites and the plant of the contractor of the section issued for all stripping operations and for the exciton concrete formore. The contractor has been directed the section of the section of the section concrete formore. The contractor has been directed the section of the section of the section concrete formore. The contractor has been directed the section of the section of the section concrete formore. The contractor has been directed the section of the section of the section concrete formore. The contractor has been directed the section of the section of the section concrete the the section concrete the section concrete th	e or od of to to	35319497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrution & development
2018		600	BERGEN ÄVENUE	0	formoork at the foundation level when he was hit in the head by a place of metal that field approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoh hospital, where he was treated fi a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a failure to saleguard and one violation for work that was not conforming to the approved plan, as the contractor for submit plant issued for all stronging operations and for the enclino concrete formwork. The contractor has been directed bring the construction documents in for review. A New and Methods for the erection and removal of concrete	e or od of to to	35319497R		FO	220151868	Material Foll	COMUNILIFE LA CENTRAL HOUSING	MountCo Construition & development
2018		600	BERGEN AVENUE	0	formoork at the foundation level when he was hit in the head by a place of metal that field approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoh hospital, where he was treated fi a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a failure to saleguard and one violation for work that was not conforming to the approved plan, as the contractor for submit plant issued for all stronging operations and for the enclino concrete formwork. The contractor has been directed bring the construction documents in for review. A New and Methods for the erection and removal of concrete	e or od of to to	36519497R		FO	220151868	Material Fell	COMUNILIFE LA CENTRAL HOUSING	MountCo Construction & developmen
				0	formork at the foundation level when he was hit in the head by a piece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin hospital, where he was treated f a concussion. Two ECB Violations were issued: one Aggravated Level 2 Violation for a failure to safeguard and one violation for work that was not conforming to the approved plan, as the contractor was using plywo as formwork. A full Stop Work Order (FSWO) was issued for all stripping operations and for the erection concrete formwork. The contractor has been directed bring the construction documents in for review. A Mes and Methods for the erection and removal of concrete form work must be provided.	e or od of to ns			FO	220151868			MountCo Construction & developmen
	Brocklyn	600	BERGEN AVENUE	0	formvork at the foundation level when he was hit in the head by a place of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoh hospital, where he was treated f a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a failure to safeguard and one violation for work that was not conforming to the approved plant, as the contractor was using plwow as formwork. A full Stop Work Order (F2WO) was issued for all stopping operations and for the arection bring the construction documents in for review. A Mae and Methods for the erection and removal of concrete form work must be provided.	e or	35319497R 35342748J	0821188501KA01	F0	220151868	Material Fell Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MountCo Constrution & development
				0	formoork at the foundation level when he was hit in the head by a piece of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoh hospital, where he was treated f a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a laiure to saleguard and one violation for work that was not conforming to the approved plan, as the contractor was using plwow as formwork. A full Stop Work Order (FSWO) was issued for all singping operations and for the erection concrete formwork. The contractor has been directed and Methods for the exerction and removal of concrete form work must be provided.	e ECB Violation		082118BS01KA01	FO	220151868			MountCo Construction & development
				0	formoork at the foundation level when he was hit in the head by a place of metal that field approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin hospital, where he was treated fi a concussion. Two ECB Violations were issued: one Aggravated Level 2 vieldon for a laince to safeguard the approved plan, as the contractor was using playous as formoved. A full Stop Wink Order (FSWO) was issued for all streping operations and for the erection concrete formwork. The contractor has been directed bring the construction documents in for review. A Net and Methods for the erection and removal of concrete form work must be provided.	e e or		082118BS01KAD1	FO	220151868			MountCo Construction & development
2018				0	formoork at the foundation level when he was hit in the head by a place of metal that field approximately ten to fifteen feet. The worker was waning his hard hat and was taken to Lincoin hospital, where he was was tradefind a concussion. Two ECB Violations were issued: The Approximate Level 2 violation for a laince to saleguard and one violation to work that was not contorming to us as formoved. A full Stop WinK Otter (FSWO) was issued for all strates of the more that a strate of the end of the end of the construction documents in for the endited bring the construction documents in for review. A Nee and Methods for the endition and removal of concrete form work must be provided.	e ECB Violation		082118BS01KA01	F0	220151868			MountCo Constrution & development
				0	formoork at the foundation level when he was hit in the head by a piace of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoh hospital, where he was treated f a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a failure to safeguard and one violation for work that was not conformigo to the approved plan, as the contractor was using plwow as formwork. A full Stop Work Order (FSWO) was issued for all stopping operations and for the erection concrete formwork. The contractor has been directed and the formwork. The contractor has been directed and the formwork. The contractor has been directed and the form work must be provided.	e ECB Violation		082118BS01KA01	FO	220151868			MountCo Construction & developmen
2018	Brooklyn	277	SOUTH 5 STREET		formoork at the foundation level when he was hit in the head by a place of metal that field approximately ten to fifteen feet. The worker was waning his hard hat and was taken to Lincoh holghail, where he was treated fi a concussion. Two ECB Violations were issued: one Aggravated Level 2 vieldon for a failure to subguard the approved plan, as the contractor was using playous as formoved. A full Stop Wink Order (FSWO) was issued for all strepsing operations and for the erection concrete formwork. The contractor has been directed bring the construction documents in for the erection concrete formwork. The contractor has been directed bring the construction documents in for review. A Mea and Methods for the erection and removal of concrete form work must be provided.	e ECB Violation	35342740J	082118BS01KAD1	FO	220151868	Other Construction Related Incidents	HAVEMEYER OWNER LLC	MountCo Construction & development
2018				0 0	formoork at the foundation level when he was hit in the head by a place of metal that field approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin hospital, where he was treated fi a concussion. Two ECB Violations were issued: one Agginavated Level 2 vielation for a lature to salinguard and one violation for work that was not controming to as formoved. A full Sigo Wink Order (FSWO) was issued for all strepting operations and for the enclion concrete formover. The contractor has been directed bring the construction documents in for review. A Nee and Methods for the enclion and removal of concrete form work must be provided.	e ECB Violation		082118BS01KA01	F0	220151868			MountCo Construction & development
	Brooklyn	277	SOUTH 5 STREET	0 0	formoork at the foundation level when he was hit in the head by a piece of metal that fell approximately ten to lifteen feet. The worker was wearing his hard hat and was taken to Lincoh hospital, where he was treated f a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a laiure to safeguard and one violation for work that was not conforming to the approved plan, as the contractor was using phywor as formwork. A full Stop Work Order (FSWO) was issued for all shopping operations and for the erection concrete formwork. The contractor has using phywor as formwork. The contractor has using phywor concrete formwork. The contractor has been directed and Methods for the erection and removal of concrete form work must be provided.	e ECB Violation	35342740J	082118BS01KA01	FO	220151868	Other Construction Related Incidents	HAVEMEYER OWNER LLC	MountCo Construction & development
2018	Brooklyn	277	SOUTH 5 STREET	0	formoork at the foundation level when he was hit in the head by a piece of metal that fell approximately ten to lifteen feet. The worker was wearing his hard hat and was taken to Lincoh hospital, where he was treated f a concussion. Two ECB Violations were issued: one Aggravated Level 2 violation for a laiure to safeguard and one violation for work that was not conforming to the approved plan, as the contractor was using phywor as formwork. A full Stop Work Order (FSWO) was issued for all shopping operations and for the erection concrete formwork. The contractor has using phywor as formwork. The contractor has using phywor concrete formwork. The contractor has been directed and Methods for the erection and removal of concrete form work must be provided.	e ECB Violation	35342740J	082118BS01KAD1	FO FO	220151868	Other Construction Related Incidents	HAVEMEYER OWNER LLC	MountCo Construction & development
2018	Brooklyn	277	SOUTH 5 STREET	0	formoork at the foundation level when he was hit in the head by a place of metal that field approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin hospital, where he was treated fi a concussion. Two ECB Violations were issued: one Aggravated Level 2 Violation for a failure to safeguard and one violation for work that was not conforming to the additional concurrence. The violation for the erection concrete formwork. The contractor has been directed bring the construction documents in for the erection concrete formwork. The contractor has been directed bring the construction documents in for review. A Nee and Methods for the erection and removal of concrete form work must be provided.	e ECB Violation ECB Violatio	35342740J	082118BS01KA01	FO	220151868	Other Construction Related Incidents	HAVEMEYER OWNER LLC	MountCo Construction & development
018	Brooklyn	277	SOUTH 5 STREET	0 0	formoork at the foundation level when he was hit in the head by a piace of metal that fell approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin hiospital, where he was treated fi a concussion. Two ECB Violations were issued one and the approved pian, as the contractor was using physical and the approved pian, as the contractor was using physical and the approved pian, as the contractor was using physical and the approved pian, as the contractor has been directed bring the construction documents in for the erection concrete formwork. The contractor has been directed bring the construction documents in for review. A Neal Sol Weak of the erection documents in for review. A Neal Sol Weak and Methods for the erection and removal of concrete form work must be provided.	e ECB Violation ECB Violatio	35342740J	082118BS01KA01	FO	220151868	Other Construction Related Incidents	HAVEMEYER OWNER LLC	MountCo Construction & developmen
018	Brooklyn	277	SOUTH 5 STREET	0	formoork at the foundation level when he was hit in the head by a place of metal that field approximately ten to fifteen feet. The worker was wearing his hard hat and was taken to Lincoin hospital, where he was treated fi a concussion. Two ECB Violations were issued: one Aggravated Level 2 Violation for a failure to safeguard and one violation for work that was not conforming to the additional concurrence. The violation for the erection concrete formwork. The contractor has been directed bring the construction documents in for the erection concrete formwork. The contractor has been directed bring the construction documents in for review. A Nee and Methods for the erection and removal of concrete form work must be provided.	e ECB Violation ECB Violatio	35342740J	082118BS01KA01	FO	220151868	Other Construction Related Incidents	HAVEMEYER OWNER LLC	MountCo Construction & developmen



ncident Date	Borough	Address Numb		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/21/2018	Manhattan	215	PEARL STREET	0	1 The Site Safety Manager reported that a worker was performing tile work when he cut his finger on a piece of tile. The worker went to urgent care.						Other Construction Related Incidents	LAM PEARL STREET HOTEL LLC	
1/2018	Manhattan	316	WEST 88 STREET	0		No Dispatch					Other Construction Related Incidents	316 WEST 88TH ST, LLC	
1/2018	Manhattan	441	9 AVENUE	0	1 The Site Safety Manager reported that two workers were lifting a power trowel when one of the workers lost his grip, causing the power trowel to fall on his hand. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
2/2018	Manhattan	100	FRANKLIN STREET	0	1 The Site Safety Manager reported that a worker was using a drill to cut a hole in the wall when he slipped and cut his hand. The worker left the site and went to a City M D.	No Dispatch					Other Construction Related Incidents	DDG 100 FRANKLIN LLC	
2/2018	Manhattan	1865	BROADWAY	0	1 The Site Safety Manager reported that a worker claimed to have tripped and fell during a plumbing inspection on the thirty second floor. The worker claimed to have failen around 11:00 AM, but did not report the incident until 2:00 PM. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
2/2018	Manhattan	315	EAST 46 STREET	0	1 The Site Safety Manager reported that an electrician accidentally cut his left palm with a razor knife while cutting tubing. The worker went to see an off-site medic.	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
/22/2018	Manhattan	688	BROADWAY	0	1 The Site Safety Manager reported that a pedestrian tripped on an NFA steel plate that was on a pedestrian walkway. The pedestrian suffered an injury to their left knee. A DOB inspector responded to the incident and visited the site and reported that the pedestrian of their need pedestrian to then. The area was being repaired as of the time of inspection. An ECB Violation for a failure to safeguard was issued. A DOB Violation was also issued.		35345025H	082218B502KA01			Other Construction Related Incidents	NOT ON FILE	
3/2018	Brooklyn	243	4 AVENUE	0	1 The Site Safety Manager reported that a worker claimed that a piece of plywood fell on his right hand and bruised his knuckle. The worker went to urgent care for treatment	No Dispatch					Other Construction Related Incidents	243 DEVELOPMENT LLC	
5/2018	Manhattan	180	BROOME STREET	0	The Site Safety Manager reported that a worker was performing stripping work on the second floor when his forearm was punctured by a piece of a nail. The worker was taken to Bellevue Hospital.	No Dispatch			NB - NEW BUILDING	121191110	Other Construction Related Incidents	SITE 4 DSA OWNER LLC	T.G. NICKEL & ASSOCIATES
5/2018	Brooklyn	535	4 AVENUE	0	<ol> <li>The Site Satety Coordinator reported that a plumber was using a cord drill on the second floor when he hit a piece of steel. The machine twisted and cut the plumber's right forearm. The worker was transported to a hospital by ambulance.</li> </ol>				NB - NEW BUILDING	320626612	Other Construction Related Incidents	XYZ PROPERTIES INC	DYNATEC CONTRACTING INC
8/2018	Brooklyn	535	4 AVENUE	0	1 The Site Safety Manager reported that a worker was moving a ladder when he slipped on a piece of BX cable and fell. The worker suffered an injury to his back. An ambulance was called.	No Dispatch					Other Construction Related Incidents	XYZ PROPERTIES INC	
8/2018	Brooklyn	840	FULTON STREET	0		No Dispatch			NEW BUILDING	320596565-01-NB	Worker Fell	840 FULTON, LLC	TITAN REALTY & CONSTRUCTI
8/2018	Manhattan	110	CHARLTON STREET	0		No Dispatch					Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	
8/2018	Manhattan	264	WEST STREET	0	1 The Site Safety Manager reported that a worker was using a gas saw to cut a granite curb stone when the stone kicked back and lacerated his shoulder. EMS was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/28/2018	Manhattan	301	EAST 117 STREET	0	Lealed. 1 The Site Safety Manager reported that a worker was changing position on a rebar. The worker was wearing this harness, and removed his hummers to be able to more a different leat, include the set of the more and the set of the set of the set of the set of the more and the set of the set of the set of the set of the more and the set of the set of the set of the set of the more and the set of the set of the set of the set of the more and the set of the set of the set of the set of the independent on the incident and visited the site and reported that there was no enforcement action necessary, as the incident occurred as the result of a worker's error.	No Action Necessary			NB	121190460	Worker Fell	AMP HOLDINGS LLC	TRANS COUNTY CORP
/29/2018	Brooklyn	170	BUFFALO AVENUE	0	1 A DOB inspector reported that an elevator worker claimed that he was struck by debris that fell from the eighth floor while he was as working on top of an elevator car at the seventh floor. The worker was transported to a hoopital, where he received one stitch and was released. The inspector observed an enclosed elevator core with block and core board from the cellar to the machine room with no penetrations at the machine room and no active work at other cars. No debris or other materials were found at the top of the car and elevator JT. The inspector also found permits for temporary work for the elevators that were current. No enforcement action was deemed necessary.	No Action Necessary			A1 - ALTERATION TYPE 1	321482418	Material Fell	BUFFALO AVE. REALTY ASSOCIATES	CFSC MAINTENANCE, LLC



ncident Date 3/29/2018	Brooklyn	Address Numbe	COLUMBIAHEIGHTS	Fatalities Injurie	EOC Final Description     The Site Safety manager reported that a worker was	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit ALTERATION -1	Permit No 321194346	Incident Type Worker Fell	Owner's Name	Contractor Name ARCHSTONE BUILDERS LLC
29/2016	BIOUKIYI	30	COLUMBIANEIGNIS	0	coming down from the bulkhead to the roof on a ladder while holding some objects. The worker missed a step and fell on his knee on the third rung of the ladder. The worker went home to see a doctor. It was not known	No Dispatch			ALTERATION -1	321194340	WUIKEI PEII		ARCHSTONE BUILDERS LLC
0/004.0		425			what the worker was holding as he was coming down the ladder.	505 10 10						T-C 425 PARK AVENUE, LLC	
29/2018	Manhattan	425	PARK AVENUE	0	1 A DOB inspector reported that during a stripping operation on the wall on the cellar floor, a panel of formwork that was approximately 4 X 3 popped out and hit a worker. There was no Controlled Access Zone and no safety measures in place at the lower level while the overhead operation was in progress, which created a hazardous condition. Two ECB Violations were issued: one violation for a work platform that was improper- encided. Two partial Skp0 Work Orders (FSWO) were issued: One for stripping operations, and one for the eraction. Two kplatforms. The General Contractor is to provide a Means and Methods for the safe operation of the job.		3535378K, 79M		NEW BUILDING	121333921	Material Fell	1-C 425 PARK AVENUE, LLC	TISHMAN CONSTRUCTION CORP
9/2018	Manhattan	553	WEST 30 STREET	0	1 The Site Safety Manager reported that an electrician tripped on a piece of plywood that was being used to cover a hole on the floor. The electrician injured his lower back. An ambulance took the electrician to the hospital for a check up.	No Dispatch			NEW BUILDING	121184208	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	HUDSON YARDS CONSTRUCTION
30/2018	Bronx	2760	BRIGGS AVENUE			No Dispoteb					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
/30/2018	Bronx	2760		0	1 The Site Safety Manager reported that a worker had got his finger pinched between a scissor lift cage and a steel beam during the removal of fire retardant material. An ambulance was called.	No Dispatch					Uther Construction Related Incidents		
8/30/2018	Queens	81-10	135 STREET	0	1 A DOB inspector reported that while the double deck platform of a nulliple-fixed cataloid that was not top of a sidwark shed was being assembled, the scafeld platform in his knees. The worker was taken to Jamaica Hospital, where it was reported that the worker stretch and suff are y token bornes. The worker was taken to Jamaica and a valied scafeld card. Four ECB Volations were issued, one violation for an failure to saleguard, and one violation for a failure to saleguard, and one violation for the absence of guard rais and secure pins. Two partial Stay Work Orders (PSWO) were issued, one PSWO for the use of a supported scaffold, end one PSWO for the use of a supported scaffold.		35351752P, 35351753R,35351754Z, 35351755K		AR 1	429652387	Scaffold/Shed/Fence/Shoring/Installation	BRIARWOOD MP LLC	Pav-Lak Contracting Inc
/31/2018	Brooklyn	2007	SURF AVENUE	0	A DOB inspector reported that while workers were assembling and becuring a backres caldiol to a steal column, the baker scalifold was pushed by strong wind and struck a worker in the head. The worker was taken down from the building by the New York City Fire Department's emergency team and transported to Consy Island Hospital by ambutance. All scalifold users at the site were found to have been in possession of a valid training card. An ECB Violation was issued for a failure to safeguard persons and property. A partial Stop Work Order (PSWO) was issued for the use of a baker scalifold. A Means and Methods must be provided.	ECB Violation	36351756M		Ali 2	340190046	Scaffold/Shed/Fence/Shoring/Installation	NYC HOUSING AUTHORITY	Forte Construction Corp
3/31/2018	Manhattan	100	VARICK STREET	0	1 The Site Safety Manager reported that a worker was unloading a shower glass panel when the glass broke and cut the worker's hand and knee. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	BROOME PROPERTY OWNER JV LLC	
/31/2018	Manhattan	215	PEARL STREET	0	The Site Safety Manager reported that a worker was picking up a bag of mortar when he injured his back. EMS was called.	No Dispatch					Other Construction Related Incidents	LAM PEARL STREET HOTEL LLC	
9/1/2018	Manhattan	540	MADISON AVENUE		Child was calladu. O ADDB inspector reported that an electrician was working on a twenty-second floor and hooking up an air conditioning pump when the worker was electroal and conditioning pump when the worker was electroal and the second second second the second second second Violations were issued one violation for after-hours work being performed without an after-hours variance, and one violation issued for a failure to atlequard. A full Stop Work forder (FSWO) and two DDB Violations were also issued. The Department Of Buildings' Electrical Unit performed a follow up inspection and reported that the electrician had failed to de-energize the electrical circuit while the work was in progress, and that there was an active permit for work between the twenty second and twenty fourth floors. The Electrical Unit did int issue a violation, because the incident was determined to have been caused by a worker's error.	ECB Violation	35322857X, 35322958H	080118CERND01, 080118CERND02		M00048913	Other Construction Related Incidents	540 MADISON VENTURES LLC	



/4/2018	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	242	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch	1		NEW BUILDING	121185966	Other Construction Related Incidents	ROSELAND DEVELOPMENT ASSOCIATE	PAVARINI MCGOVERN LLC
					stripping caulking from the windows on the cellar floor								
					with a box cutting knife when the knife slipped and caused a cut to the worker's left arm. An ambulance								
					transported the worker to a hospital for treatment								
018	Queens	21-26	45 ROAD	0	1 The Site Safety Manager reported that a worker claimed	No Dispatch					Other Construction Related Incidents	SALM PROPERTIES LLC	
					to have fallen approximately six feet from a ladder. The worker suffered a shoulder injury. No one saw the								
					worker suffered a shoulder injury. No one saw the worker fall. An ambulance was called.								
					Nonce fail. / In ambalance was caned.								
2018	Manhattan	111	MURRAY STREET	0	1 The Site Safety Manager reported that a worker slipped	No Action Necessary					Worker Fell	NOT ON FILE	
					while going down the stairs on the thirty-third floor. A								
					DOB inspector responded to the incident and visited the site and determined that no enforcement action was								
					site and determined that no enforcement action was necessary.								
2018	Manhattan	301	EAST 81 STREET	0	1 The Site Safety Manager reported that a worker tripped	No Action Necessary			NEW BUILDING.	122143377	Worker Fell	1562/1564 SECOND REALTY LLC	CM AND ASSOCIATES CONSTRU
					and fell on rebar. The worker suffered an injury to his	,,							
					pinky finger and went to a hospital on his own. A DOB								
					inspector visited the site and determined that no enforcement action was necessary, as the incident was								
					caused by a worker's error. The inspector issued two								
					ECB Violations for infractions that were not related to								
					the incident: one violation for work being performed contrary to the approved Site Safety Plan, and one								
					violation for the presence of horizontal netting that was								
					not in code compliance. A partial Stop Work Order (PSWO) was also issued, but not in relation to the								
					(PSWO) was also issued, but not in relation to the								
					incident.								
2018	Manhattan	514	WEST 24 STREET	0	1 The Site Safety Manager reported that an electrician	No Dispatch			NEW BUILDING	121186858	Other Construction Related Incidents	514 WEST 24TH OWNER LLC	JDS CONSTRUCTION GROUP*
					was working on a pull box when he cut his finger by the edge of the box. The electrician panicked and called an								
					edge of the box. The electrician panicked and called an ambulance.								
2018	Manhattan	138	EAST 50 STREET	0	1 The Site Safety Manager reported that a worker sat on a	No Dispatch			NEW BUILDING	121186028	Other Construction Related Incidents	50 LEX DEVELOPMENT LLC	TISHMAN CONSTRUCTION CORP
				-	gang box and cut his left ring finger by the gang box. The worker went to a hospital on his own for treatment.								
					The worker went to a hospital on his own for treatment. The incident occurred on September 7, 2018, but was								
					not reported until September 10, 2018.								
/2018	Brooklyn	714	39 STREEET	1	0 The New York City Fire Department requested that an	DOB Violation		091218EX0704RV	Alteration	321481703	Excavation/Soil Work		Ground to sky city builders
					inspection please be performed due to a trench								
					collapse. A DOB inspector, as well as DOB engineers, responded to the incident and visited the site, and								
					reported that a partial support of excavation system								
					collapse had occurred. The collapse resulted in the								
					fatality of a worker. The inspector reported that the								
					collapse due to the presence of improper shoring of an unbalanced masonry wall and improper underpinning								
					work. A DOB Violation and a full Stop Work Order were								
					issued.								
2/2018	Manhattan	113	WEST 24 STREET	0	1 The Site Safety Manager reported that a worker	No Dispatch					Other Construction Related Incidents	LG CHELSEA LLC	
					scratched his shin on rebar. The worker went to urgent								
/2018			WEST 18 STREET		care. An ambulance was not called.					122736762		NOT ON FILE	ARTIMUS CONSTRUCTION INC
2/2018	Manhattan	425	WEST 18 STREET	0	<ol> <li>The Site Safety Manager reported that a worker was drilling in concrete when the tool jammed, soun around.</li> </ol>	No Dispatch			NEW BUILDING	122736762	Other Construction Related Incidents	NOT ON FILE	ARTIMUS CONSTRUCTION INC
					and struck the worker above the eye. The worker went								
					home for the day to see his doctor. The incident								
					occurred on September 12, 2018, but was not reported								
					until Centember 12, 2010								
					until September 13, 2018.								
2019	Brooklan	109 A	VENT STREET		until September 13, 2018.	No Dispatch			NEW RUILDING	220008201		KENT RUILDING DEVELORMENT LLC	RECOKLYN & COMPANY CROUP
/2018	Brooklyn	198 A	KENT STREET	0	until September 13, 2018. 1 The Construction Superintendent reported that a worker	No Dispatch			NEW BUILDING.	320908201	Other Construction Related Incidents	KENT BUILDING DEVELOPMENT LLC	BROOKLYN B COMPANY GROUP
2018	Brooklyn	198 A	KENT STREET	0	until September 13, 2018.  1 The Construction Superintendent reported that a worker was performing carving work on a stucco when he was cut under his shin by a trowel. The worker was taken to	No Dispatch			NEW BUILDING.	320908201	Other Construction Related Incidents	KENT BUILDING DEVELOPMENT LLC	BROOKLYN B COMPANY GROUP
/2018	Brooklyn	198 A	KENT STREET	0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was performing carving work on a stucco when he was	No Dispatch			NEW BUILDING.	320908201	Other Construction Related Incidents	KENT BUILDING DEVELOPMENT LLC	BROOKLYN B COMPANY GROUP
				0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was performing carving work on a stucco when he was cut under his sin by a trovel. The worker was taken to a hospital by ambulance for treatment.								
	Brooklyn Manhattan	198 A 53	KENT STREET	0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was performing carving work on a stucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safetv Manacer recorded that an iron worker	No Dispatch			NEW BUILDING.	320908201	Other Construction Related Incidents Other Construction Related Incidents	KENT BUILDING DEVELOPMENT LLC	BROOKLYN B COMPANY GROUP
				0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was performing carving work on a strucce when he was cut under his shin by a trowel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his finger by the choker while regging a piece of metal. The on site medic treated the worker and sent	No Dispatch							
/2018	Manhattan	53	WEST 53 STREET	0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was performing carving work on a stucco when he was cut under his sin by a trowel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his finge by the choker while raging a piece of metal. The on site medic treated the worker and sent him to urgent care.	No Dispatch			NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018				0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was parforming caving work on a strucce when he was cut under his shin by a trowel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his finger by the choker while rigging a piece of metal. The on site medic treated the worker and sent him to urgent care.	No Dispatch	3533294H	091418CNEGS01.					
/2018	Manhattan	53	WEST 53 STREET	0	until September 13, 2018.  The Construction Superintendent reported that a worker was performing caving work on a slucco when he was cut under his sin by a trovel. The worker was taken to a hospital by ambulance for treatment. The Site Safety Manager reported that an iron worker pinched his flegs by the choker while raging a piece of metal. The on site medic treated the worker and sent him to urgent care. The Construction Superintendent reported that a worker fell conct the fourth floor working platform from a height	No Dispatch	3533294H	091418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018	Manhattan	53	WEST 53 STREET	0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was performing carving work on a stucco when he was cut under his sinh by a trowel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his finge by the choker while raging a piece of matal. The on site medic treated the worker and sent him to urgent care. 1 The Construction Superintendent reported that a worker fell onto the fourth floor working aufform from a height between the fifth and sith floor. The worker suffered a broken aftew and was taken to a hospital	No Dispatch	35333294H	091418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018	Manhattan	53	WEST 53 STREET	0 0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was parforming carving work on a strucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Managar reported that an iron worker prinched his finger by the chaker while rigging a price of metal. The on site medic treated the worker and sent him to urgent care. 1 The Construction Superintendent reported that a worker fell onto the fourth floor working glatform from a height between the fifth and sixth floor. The worker suffered a broken eibow and was taken to a hospital. The Department of Building E Emergency Response Team	No Dispatch	3533294H	091418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018	Manhattan	53	WEST 53 STREET	0 0	until September 13, 2018.  1 The Construction Superintendent reported that a worker was performing caving work on a stucco when he was cut under his sinh by a trowel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his finger by the choker while raging a piece of metal. The on site medic treated the worker and sent him to urgent care. 1 The Construction Superintendent reported that a worker fell cnot the four thin or updatom from a height between the fifth and sish floor. The worker suffered a broken eitbow and was taken to a hospital. The Department of Building 5 Emergency Response Team responded to the incident and wisited the site, but was	No Dispatch	3533329414	001418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
2018	Manhattan	53	WEST 53 STREET	0 0	until September 13, 2018. 1 The Construction Supprintendent reported that a worker was parforming earling work on a stucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his linger by the choker while reging a piece of him to urgent care. 1 The Construction Superintendent reported that a worker and sent him to urgent care. 1 The function of the worker properties of the safety devices the safety for the safety of the safety devices and sent him to urgent care. 1 The Construction Superintendent reported that a worker piece on the function to function platform from a height between the fifth and safety for the worker suffered a under the function the found the functions. A function of the indicates the work and a A field on the foundent and visited the site, but was unable to lineact the work and A field on was a field by the indicate and waited the site, but was the field on the foundent and visited the site, but was the field on the foundent and visited the site, but was the field on the foundent and visited the site. But was the field on the foundent and visited the site, but was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and the site. But was the site and the site. But was the site and the si	No Dispatch	35333294H	091418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018	Manhattan	53	WEST 53 STREET	0 0	until September 13, 2018. 1 The Construction Superintendent topoted that a worker was parforming carring work on a strucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker printed this finge by the chocker while regging a piece of printed. The source and sent him to urgent care. 1 The Construction Superintendent reported that a worker printed the forth floor working platform from a height broken albow and the fourth floor working platform from a height broken albow and was taken to a hospital. The Department of Building 5 memory Response Team responded to the incident and visited the site, but was issued for a failure to asfeguard. A DCB Violation was issued for a failure to asfeguard. A DCB Violation was	No Dispatch	3533294H	091418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
2018	Manhattan	53	WEST 53 STREET	0	until September 13, 2018. 1 The Construction Supprintendent reported that a worker was parforming earling work on a stucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his linger by the choker while reging a piece of him to urgent care. 1 The Construction Superintendent reported that a worker and sent him to urgent care. 1 The function of the worker properties of the safety devices the safety for the safety of the safety devices and sent him to urgent care. 1 The Construction Superintendent reported that a worker piece on the function to function platform from a height between the fifth and safety for the worker suffered a under the function the found the functions. A function of the indicates the work and a A field on the foundent and visited the site, but was unable to lineact the work and A field on was a field by the indicate and waited the site, but was the field on the foundent and visited the site, but was the field on the foundent and visited the site, but was the field on the foundent and visited the site. But was the field on the foundent and visited the site, but was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and visited the site. But was the field on the foundent and the site. But was the site and the site. But was the site and the si	No Dispatch	35333294H	091418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018	Manhattan	53	WEST 53 STREET	0	until September 13, 2018. 1 The Construction Superintendent topoted that a worker was parforming carring work on a strucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker printed this finge by the chocker while regging a piece of printed. The source and sent him to urgent care. 1 The Construction Superintendent reported that a worker printed the forth floor working platform from a height broken albow and the fourth floor working platform from a height broken albow and was taken to a hospital. The Department of Building 5 memory Response Team responded to the incident and visited the site, but was issued for a failure to asfeguard. A DCB Violation was issued for a failure to asfeguard. A DCB Violation was	No Dispatch	35333294H	091418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018 /2018	Manhattan Manhattan	53 228	WEST 53 STREET EAST 20 STREET	0 0	until September 13, 2018.  1 The Construction Superintendent sported that a worker was performing carring work of a student state to a hospital by a neutre IT at the state to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an inco worker pinched his flager by the choker while rigging a piece of matat. The on site medic treated the worker and sent him to urgent case. 1 The Construction Superintendent reported that a worker is a construction Superintend his flager by the choker while rigging a piece of matat. The on site medic treated the worker and sent him to urgent case. 1 The Construction Superintendent reported that a worker is broken elbow and was taken to a hospital. The Department of Building's Emergency Reports to the indeknt and visited the site, but was unable to inspect the work area. An EOB Voltation was also issued for a hospital State (PSWO) was issued for a work on the exposure 3 facade.	No Dispatch	3533294H	091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018 /2018	Manhattan	53	WEST 53 STREET		until September 13, 2018. 1 The Construction Superintendent reported that a worker was parforming carving work on a strucco when he was cut under his shin by a trowel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Managar reported that an ion worker pinched his finger by the choker while ragging a piece of metal. The on site medic treated the worker and seen to site medic treated the worker and seen to site medic treated the worker and seen the total the order of the site of the sit	No Dispatch	3533294H	091418CNEGS01.	NEW BUILDING	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018	Manhattan Manhattan	53 228	WEST 53 STREET EAST 20 STREET	0 0	until September 13, 2018.     International september 13, 2018.     International september 14, 2018.     Internatin september 14, 2018.     International september 14, 2018.	No Dispatch	3533294H	091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
/2018	Manhattan Manhattan	53 228	WEST 53 STREET	0 0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was parforming carving work on a strucco when he was cut under his shin by a trowel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Managar reported that an ion worker pinched his finger by the choker while ragging a piece of metal. The on site medic treated the worker and seen to site medic treated the worker and seen to site medic treated the worker and seen the total the order of the site of the sit	No Dispatch	35332944	091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
V2018 V2018 V2018	Manhattan Manhattan Manhattan	53 228 221	WEST 53 STREET EAST 20 STREET WEST 17 STREET	0 0	until September 13, 2018. 1 The Construction Superintendent teoretal that a woher was parforming carving work on a source when he was cut under his shin by a trowel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Managar reported that an ion worker prinched his finger by the choker while ragging a piece of metal. The on site medic treated the worker and same the teoret of the teoret and the second of the second teoret and the teoret fell onto the fourth floor working platform from a height between the fifth and sixth floor. The worker walfered a broken elbow and was taken to a hospital. The Department of Building 5 Emerginery Response Team responded to the incident and visited the site, but was issued for a failure to safeguard. A DOB Violation was issued for work on the exposure 3 facade. 1 The Site Safety Managar reported that a worker was cutify a piece of metal in the or was called to take the worker to a hospital for a check up.	No Dispatch ECB Violation		091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB 121186965	Other Construction Related Incidents Worker Fell Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION GRAMERCY SQUARE LLC OTL ENTERPRISES LLC
4/2018 4/2018 4/2018	Manhattan Manhattan	53 228	WEST 53 STREET	0 0	until September 13, 2018. 1 The Construction Superintendent reported that a worker was parforming carving work on a slucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his finger by the choker while rigging a piece of metal. The on ist medic treated the worker and sent him to urgent care. 1 The Construction Superintendent reported that a worker fell onto the fouth floor working platform from a height between the fittin and skift horor. The worker suffered a broker allow and was laken to a hospital. The other working platform from a height between the fittin and skift horor. The worker suffered a broker allow and was laken to a hospital. The other suffered a broker allow and was laken to a hospital. The suffered a broker allow and was laken to a hospital. The suffered a broker allow and was laken to a hospital the site, but was unable to impact the work area. An ECB Violation was also issued. A partial Stop Work Order (PSWO) was issued for a factor of sheet metal when he got a piece of metal in his eye. An ambulance was called to take the worker in a hospital for a chock up. 1 A DOB inspector reported that four workers were	No Dispatch	35333294H	091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION
3/2018 4/2018 4/2018 4/2018	Manhattan Manhattan Manhattan	53 228 221	WEST 53 STREET EAST 20 STREET WEST 17 STREET		<ul> <li>until September 13, 2018.</li> <li>The Construction Superintendent toprated that a worker was parforming carving work on a strucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment.</li> <li>The Site Safety Managar reported that an ion worker pinched his finger by the choker while regging a piece of metal. The on site medic treated the worker and same the under the safety for the site of the si</li></ul>	No Dispatch ECB Violation		001418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB 121186965	Other Construction Related Incidents Worker Fell Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION GRAMERCY SQUARE LLC OTL ENTERPRISES LLC
/2018 /2018 /2018	Manhattan Manhattan Manhattan	53 228 221	WEST 53 STREET EAST 20 STREET WEST 17 STREET		<ul> <li>until September 13, 2018.</li> <li>The Construction Superintendent reported that a worker was parforming carving work on a stucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment.</li> <li>The Site Safety Managar reported that an iorn worker pinched his finger by the choker while reginging a piece of metal. The on site mode treated the worker and sent him to urgent care.</li> <li>The Construction Superintendent reported that a worker fell onto the fouth floor working platform from a height between the fill than sixth floor. The worker working not be incident reported that a worker fell onto the fouth floor working platform from a height between the fluiding is Emergine Response Team responded to the incident and visiter fDB without a barbattat. The Deparimeter of Building is Samegron Response Team responded to the incident and visiter fDB without a ADB Violation was also issued. A partial Stop Work Order (PSWO) was issued for a height be to state worker to a hospital for a check up worker to a hospital for a check up of the to a barbattar for a barbattar to a visiter the a barbattar or the exclusion was also be date metal which he got a piece of metal in his eye. An ambulance was called to take the worker to a hospital for a check up.</li> <li>A DOB inspectra force reported that four workers were dragging a scaffolding frame that had platks on it when one of the plates fell of the activity and the order worker one and the start of a scaffold more than the plates of the metal work in the exclusion was also be activity and the four workers were dragging a scaffolding frame that had platks on it when one of the plates fell of the activity and the exclusion and the order exclusion and the order to a hospital for a check up.</li> </ul>	No Dispatch ECB Violation		091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB 121186965	Other Construction Related Incidents Worker Fell Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION GRAMERCY SQUARE LLC OTL ENTERPRISES LLC
/2018 /2018 /2018	Manhattan Manhattan Manhattan	53 228 221	WEST 53 STREET EAST 20 STREET WEST 17 STREET		<ul> <li>until September 13, 2018.</li> <li>The Construction Superintendent reported that a worker was parforming caving work to a stucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment.</li> <li>The Site Safety Manager reported that an incre worker prinched his finger by the choker while rigging a piece of metal. The on site medic treated the worker and sent him to urgent care.</li> <li>The Construction Superintendent reported that a worker fell onto the fouth floor working platform from a height between the fifth and sixth floor. The worker was taken to a hospital. The Department of Building &amp; Emergency Response Team responded to the indent and visited the site, but was also issued. A partial Stop Work Order (PSWO) was issued for work on the exposure 3 facade.</li> <li>The Site Safety Manager reported that a worker was clutted to take the worker to a hospital. The Department of e. An ambulance was called to take the worker to a hospital the new calculates the work was called to take the worker to a hospital of a check up.</li> <li>A DOB inspector reported that floor workers were dragping a scaffolding fisme that had planks on it when he got a substitute to a two the exposure 3 facade.</li> </ul>	No Dispatch ECB Violation		091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB 121186965	Other Construction Related Incidents Worker Fell Other Construction Related Incidents	THE MUSEUM OF MODERN ART	CRAMERCY SQUARE LLC
2018 2018 2018	Manhattan Manhattan Manhattan	53 228 221	WEST 53 STREET EAST 20 STREET WEST 17 STREET		<ul> <li>until September 13, 2018.</li> <li>1 The Construction Supprintendent teported that a worker was parforming carving work on a strucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment.</li> <li>1 The Site Safety Manager reported that an ion worker of instant. The on site medic treated the worker and sent him to urgent care.</li> <li>1 The Construction Supprintendent teported that a worker find that an iso in a site medic treated the worker and sent him to urgent care.</li> <li>1 The Construction Superintendent teported that a worker find on the fund that and site find to the fourth floor working gladform from a height between the tift and sixth floor. The worker walfered a broken albow and was taken to a hospital. The Department of Building E Emergency Response Team responded to the indext and visited the site, but was issued for a failure to safeguard. A DOB Violation was issued for a work on the exposure 3 facade.</li> <li>1 The Site Safety Manager reported that a worker was called to take the worker to a hospital for a check up.</li> <li>1 A Dogi repeator reported that the Joinka con it whon ne got to picco of the pictored that picco on it worker on the ospital for a check up.</li> <li>1 A Dogi repeator reported that four worker was called to take the worker to a hospital for a check was called to take the worker to a hospital for a check was called to take the worker to a hospital for a check was called to the worker to a hospital for a check was called and the work worker on the piccheck mark waring this personal Protection Equipment (PPE) and was in stable condition, but flat dary. KM was called and the worker worker on the worker work was called to the worker to a hospital for a check was called and the worker to a hospital for a check was called to the worker to a hospital for a check was called to the worker to a hospital for a check was called to the worker to a hospital for a check was called to the worker to a hospital for a check was c</li></ul>	No Dispatch ECB Violation		091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB 121186965	Other Construction Related Incidents Worker Fell Other Construction Related Incidents	THE MUSEUM OF MODERN ART	CRAMERCY SQUARE LLC
/2018 /2018 /2018	Manhattan Manhattan Manhattan	53 228 221	WEST 53 STREET EAST 20 STREET WEST 17 STREET		<ul> <li>until September 13, 2018.</li> <li>The Construction Superintendent reported that a worker was parforming caving work to a stucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment.</li> <li>The Site Safety Manager reported that an incre worker prinched his finger by the choker while rigging a piece of metal. The on site medic treated the worker and sent him to urgent care.</li> <li>The Construction Superintendent reported that a worker fell onto the fouth floor working platform from a height between the fifth and sixth floor. The worker was taken to a hospital. The Department of Building &amp; Emergency Response Team responded to the indent and visited the site, but was also issued. A partial Stop Work Order (PSWO) was issued for work on the exposure 3 facade.</li> <li>The Site Safety Manager reported that a worker was clutted to take the worker to a hospital. The Department of e. An ambulance was called to take the worker to a hospital the new calculates the work was called to take the worker to a hospital of a check up.</li> <li>A DOB inspector reported that floor workers were dragping a scaffolding fisme that had planks on it when he got a substitute to a two the exposure 3 facade.</li> </ul>	No Dispatch ECB Violation		091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB 121186965	Other Construction Related Incidents Worker Fell Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION GRAMERCY SQUARE LLC OTL ENTERPRISES LLC
/2018 /2018 /2018	Manhattan Manhattan Manhattan	53 228 221	WEST 53 STREET EAST 20 STREET WEST 17 STREET		<ul> <li>until September 13, 2018.</li> <li>The Construction Superintendent reported that a worker was performing carving work on a stucco when he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment.</li> <li>The Site Safety Manager reported that an ione worker pinched his finger by the choker while rigging a piece of metal. The on site medic treated the worker and sent his to urgent care.</li> <li>The Construction Superintendent reported that a worker fell onto the fouth floor working platform from a height between the fifth and sixth floor. The worker unstaled the site of the addition was also in a hospital. The Department of Building 5 Emergency Response Team responded to the indent and visited the site, but was also issued, a partial Siop Work. A disr (PSVO) was issued for work on the exposure 3 facade.</li> <li>The Site Safety Manager reported that a worker was clutted to take the worker to a hospital to a check up.</li> <li>A DOB inspector reported that a worker was clutted to take the worker to a hospital the plasment of the reporter 5 facade.</li> <li>A DOB inspector reported that a worker was clutted to take the worker to a hospital to a the check up.</li> <li>A DOB inspector reported that a bark so it who now called to take the worker to a hospital to a the LEC Worker was called to take the worker to a hospital to a the call of a dat and of a the part of the scaled and at one of personal Protocol Protocol Topuro the DEP and that a coll worker was called to take the worker to a hospital to a the LEC Worker was instable condition, but field tables, LEC Worker was called to a hospital to</li></ul>	No Dispatch ECB Violation		091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB 121186965	Other Construction Related Incidents Worker Fell Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION GRAMERCY SQUARE LLC OTL ENTERPRISES LLC
2018 2018 2018	Manhattan Manhattan Manhattan	53 228 221	WEST 53 STREET EAST 20 STREET WEST 17 STREET		until September 13, 2018. 1 The Construction Superintendent reported that a worker was parforming carving work on a succow hen he was cut under his shin by a trovel. The worker was taken to a hospital by ambulance for treatment. 1 The Site Safety Manager reported that an iron worker pinched his finger by the choker while rigging a piece of metal. The on site medic treated the worker and sent him to urgent care. 1 The Construction Superintendent reported that a worker fell onto the fouth floor working platform from a height between the fith and skith floor. The worker suffered a broken rebow and was laken to a hospital. The the construction Superintendent reported that a worker fell onto the fouth floor working platform from a height between the fith and skith floor. The worker suffered a broken rebow and was laken to a hospital. The three productions to be a hospital. The the construction is been be a hospital to the set unable to impact the work area. An ECB Violation was also issued. A partial Stop Work Order (PSWO) was issued for a field the set and the a box for a set outting a piece of sheet metal when he got a piece of metal in his eye. An ambulance was called to take the worker is a hospital for a check up. 1 A DOB inspector reported that four workers were dragging a scaffolding frame that had plataks on it when one of the planks fell of the scaffold and hi to re of the worker is in the head. The worker was in stable was transported to a hospital Ar A ECB Violation was issued for the presence of un-scaffold and hi tore of the worker is hospital Ar A ECB Violation was issued for the presence of un-scaffold and his con of the worker is not presence of un-scaffold and his one is stable was transported to a hospital Ar A ECB Violation was issued for the presence of un-scaffold and his con of the worker is not presence of un-scaffold and his one of the worker is an the head and A ECB Violation was issued for the presence of un-scaffold and his one of the worker is an the	No Dispatch ECB Violation		091418CNEGS01.	NEW BUILDING	121327224 121958480-01-NB 121186965	Other Construction Related Incidents Worker Fell Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LENDLEASE(US)CONSTRUCTION GRAMERCY SQUARE LLC OTL ENTERPRISES LLC



cident Date		Address Numbe		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	138	EAST 50 STREET	0	1 The Site Safety Manager reported that a worker was walking towards a stairway when he turned his head and hit he threaded rod of a beach pulley system that was being used for a curtain wall installation. The worker suffered a cut to his head and was taken to a hospital by ambulance for treatment.	1			NEW BUILDING	121186028	Other Construction Related Incidents	50 LEX DEVELOPMENT LLC	TISHMAN CONSTRUCTION CORP
2018	Manhattan	105	WEST 28 STREET	0	1 A DOB inspector reported that there were workers cleaning a concrete pump after concrete was pourd onto the stairs on the first floor when pressure bill up and a hose knocked one of the workers down. The worker was found conscious and was taken to a hospital by ambulance. Three ECB Violations were issued: one violation for the failure to maintain safety measures, as a safety orientation was not conducted before the concrete operation began, a second violation for the absence of an adequate concrete washout box, and a third violation's specification comply washing of the concrete pump was not performed before it was used. Two partial Skop Work Orders (PWO) were its used and concrete pouring and pumping operations. The General Contractor must provide a Maema and Methods for safe concrete pouring and pumping.	a 1	35363639L, 40Z, 41K		NEW BUILDING	121184529	Mechanical Construction Equipment	LSG 105 WEST 28TH LLC	FLINTLOCK CONSTR SERV LLC
2018	Brooklyn	422	FULTON STREET	0	1 A DOB inspector reported that a worker was doing ductwork in the celler floor for an air conditioning unit in the basement. The worker was standing on top of the air conditioning unit and fell backwards approximately seven feet, landing on a concrete floor. The worker was found conscious, but suffered a compound fracture to his left ankle and was taken to a hospital by ambulance. The worker was not using a safety harness at the time of the incident, and there was no fail protection in place. The order was not using a safety harness at the time of the incident, and there was no fail protection in place. The order was not using a safety harness at the time of the incident, and there was not partial Stop Work Order (PSWO) was also isaud on all duct and air conditioning work. The General Contractor is to provide a Means and Methods for the safe operation of the job, as well as Tool Box Talks.	f	35353393L, 94N		ALTERATION-1	320908899	Worker Fell	NOT ON FILE	TRANSPARENT CONSTRUCTION
D18	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker was walking on a stripping floor when something went into the worker's eye. The on-site medic cleaned the worker's eye and sent him to a City M.D. for a check up. The worker returned to work.	No Dispatch			NEW BUILDING	321197085	Other Construction Related Incidents	NYC HPD	LEND LEASE (US) CONSTRUCT
2018	Bronx	886	EAST 180 STREET	0	1 A DOB inspector reported that a worker was moving a cart that was loaded with thirteen sheet rocks. The cart was overloaded and unbalanced, and toppled while the worker was trying to move it. The worker suffered an injury to his left leg and was taken to a hospital. An ECB Violation was issued for the unsafe handling of materials. A partial Stop Work Order (PSWO) was also issued. The General Contractor is to provide a Means and Methods for safe material handlings with a worker's orientation.		35360602P		NEW BUILDING	220152233	Material Fell	988 EAST 180 STREET HOUSING DE	MONADNOCK CONSTRUCTION IN
018	Manhattan	527	WEST 27 STREET	0	1 The Site Safety Manager reported that a worker got dust in his eye. The worker went to a first med.	t No Dispatch			NEW BUILDING	_	Other Construction Related Incidents	WC 28 REALTY LLC	PIZZAROTTI LLC
018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker was dismantling a baker scaffold when a plank fell and pinched his foot. The worker was taken to a hospital by a co-worker.	No Dispatch			NEW BUILDING	520601968	Material Fell	STATEN ISLAND GLOBAL LOGISTIC	MATRIX CONSTRUCTION SERVI
018	Staten Island	546	GULF AVENUE	0	A DOB inspector reported that a worker removed temporary barricades that were bolled to the floor, and then tripped to one of the bolts and hh inis head. An ambulance was called to take the worker to a hospital. The inspector did not observe any hazardous conditions in the area, and determined that the incident occurred as a result of a worker's error. However, an ECB Violation was issued for the removing of the bolts from the area before the inspection was performed.	ECB Violation	35360641M		NEW BUILDING	520301968	Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	MATRIX CONSTRUCTION SERVI
2018	Queens	22-18	JACKSON AVENUE	0	1 The Site Safety Manager reported that a plumber cut his finger while cutting a pipe. The worker went to urgent care by taxi.	No Dispatch			NEW BUILDING	420655838	Other Construction Related Incidents	22-12 JACKSON OWNER LLC	BRITT REALTY LLC
7/2018	Queens	195-06	111 AVENUE	0	care by tax. 1 A DOB inspector reported that at a one family, two story not for profit building, the property owner cut the foundation wall at rear exposure 4 in order to create an opening for a doorway to the cellar. The foundation wall was 6 X 6 X 14'. However, while in the process of cutting the wall, the wall field on the property owner. The owner suffered a broken log. Three ECB Violations were issued: one violation for a failure to safeguard, one violation for work heing performed without a DOB-issued permit, and one violation for the presence of inadequate housekeeping. A full Stop Work Order (FSWO) was issued. Three DOB Violations were also issued.	•					Material Fell	ADAM A PERRY	



ncident Date	Borough	Address Number	Street	Fatalitice Invision	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
17/2018	Manhattan	138	EAST 50 STREET	o atanties injurie	1 The Site Safety Manager reported that a worker cut his	No Dispatch	Los riolation numbers	DOD FIORUGI NUMBERS	remilt	r er mit NO	Other Construction Related Incidents	50 LEX DEVELOPMENT LLC	TISHMAN CONSTRUCTION CORP
					forearm while using a box cutting knife. The worker went to urgent care and will return to work.								
18	Brooklyn	266	KENT AVENUE	0	2 A DOB inspector reported that during a pumping operation, pressure had built up inside of a hose,	ECB Violation	35316269L, 70Z		NEW BUILDING	320916407	Mechanical Construction Equipment	260 KENT LLC	260 KENT CONSTRUCTION LLC
					causing the hose to bounce and knock down two								
					workers. One of the two workers went to a hospital; the								
					other worker remained on-site. Two ECB Violations were issued: one violation for the failure to maintain								
					safety measures during pumping operations, as the								
					pump was not inspected before use, which caused the								
					incident, and a second violation for the use of a concrete pump contrary to the manufacturer's								
					specifications. A partial Stop Work Order (PSWO) was								
					also issued.								
2018	Brooklyn	123	MELROSE STREET	0	2 A DOB inspector reported that workers were using a pallet iack to move a component of a boiler unit inside of	ECB Violation	353162267H, 68J		NEW BUILDING	320717140	Material Fell	EVERGREENS GARDENS I LLC	BROOKLYN GC, LLC
					the boiler room on the roof. The component was								
					approximately 4' X 2' and 7' high. Balance was lost, and								
					the component of the boiler unit fell over onto two workers. One worker suffered a shoulder injury, and the								
					second worker suffered a broken leg. Two ECB								
					Violations were issued: one violation for a failure to safeguard persons and property affected by construction								
					operations, and one violation for the failure to provide a								
					safety orientation on the hazardous conditions of the								
					job. A partial Stop Work Order (PSWO) was also issued.								
018	Bronx	2028	CRESTON AVENUE	0	1 A DOB inspector reported that while in the processing of dismantling an exterior personal hoist, the worker went	ECB Violation	35350606M, 07Y, 08X, 09H.		NEW BUILDING	220392858	Worker Fell	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MNGMT
					on top of a hoist car that was at grade level to close the								
					latch of the hatch door. The worker fell from the hoist and suffred an injury to his arm. The worker was taken								
					to a hospital by ambulance, where he was reported to								
					be in stable condition. The worker had his safety								
					harness on, but was not tied off. Four ECB Violations were issued: two violations (one to the General								
					Contractor, one to the hoist company) for the absence of								
					an effective fall protection system, one violation for the removing of equpment involved in an incident before								
					inspection, and one violation for the presence of								
					inadequate guard rails. A partial Stop Work Order								
					(PSWO) for all work within six feet of the leading edge was also issued.								
2018	Manhattan	545	WEST 30 STREET	0	1 A DOB inspector reported that a worker was moving pipes from a rack when the pipes rolled over and hit the worker in his eye. The worker was treated by the on-site	ECB Violation	35366613R		ALTERATION-1	121192397	Material Fell	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
					worker in his eye. The worker was treated by the on-site medic before being sent to urgent care. The incident								
					occurred on September 18, 2018, but was not reported								
					until September 19, 2018. This incident, as well as								
					Incident Number 26743 and Incident Number 26744, all occurred during the same job. In response to all three of								
					these incidents, an ECB Violation was issued for the								
					unsafe handling of materials. A partial Stop Work Order								
					(PSWO) was issued on all material handling, including deliveries. The General Contractor is to provide a								
					Means and Methods, with a Tool Box Talk, for safe								
					material handling and the safe operation of the job.								
018	Manhattan	590	EAST 83 STREET	0	1 The Site Safety Manager reported that a worker was working on an "A"-Frame ladder when he missed a step				NEW BUILDING	121190987	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
					and fell from the ladder. The worker suffered an injury to								
					his leg. The worker walked down and his foreman took him to urgent care for a check up.								
018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that an electrician	No Dispatch			NEW BUILDING	520301968	Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	MATRIX CONSTRUCTION SERVI
2010	Statest folding	040	SOLI AVLINGE	0	was installing an electric sign when he received a	no Dispaidi			NEW BUILDING	320301300	Gater Construction Related incluents	STATEN ISEAND SEOBAE EOGISTIC	MATRIX CONSTRUCTION SERVI
					shock. The electrician went with a co-worker to urgent care for a check up.								
018	Manhattan	550	WEST 34 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NEW BUILDING	121184841	Other Construction Related Incidents	ONE HUDSON YARDS OWNER LLC	GILBANE BUILDING COMPANY
					walking through an area where concrete was poured the previous day when he tripped on a piece of form work.								
					The worker did not fall, but he hit his head on form work.								
					The worker walked to the on-site medic, and the on-site medic sent the worker to a hospital for evaluation.								
018	Manhattan	545	WEST 30 STREET	0	1 The Site Safety Manager, and a DOB inspector,	No Action Necessary			ALTERATION-1	121192397	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
					reported that a worker was cut his finger while cutting sheet rock. The worker went to urgent care. This								
					incident, as well as Incident Number 26742 and Incident								
					Number 26743, all occurred during the same job. In response to all three of these incidents, an ECB								
					Violation was issued for the unsafe handling of								
					materials. A partial Stop Work Order (PSWO) was								
					issued on all material handling, including deliveries. The General Contractor is to provide a Means and Methods.								
					with a Tool Box Talk, for safe material handling and the								
					safe operation of the job.								



ident Date		Address Number			EOC Final Description		ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
V2018	Manhattan	545	WEST 30 STREET		A DOB inspector reported that a worker's left index linger got prinched while loading materials. The worker was treated by the on-site medic, and the medic then sent the worker to uprent care. This incident, save all as incident Number 26742 and incident Number 26744, all occurred during the same job. In response to all three du- unsate handling of materials. A partial Stop Work Order (PSWO) was issued on all material handling, including deliveries. The General Contractor is to provide a Means and Methods, with a Tool Box Taik, for safe material handling and the safe operation of the job.	No Action Necessary			ALTERATION-1	121192397	Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	SCIAME CONSTRUCTION LLC
2018	Manhattan	525	WEST 122 STREET		A DOB inspector reported that a worker was hoising, by hand, a 4 X 4' section of prelabicated form work into place when the section of prelabicated form work fell onto the worker. The worker suffered a lacentation to his head and was examined by an on-site medical facility. The worker was then escorted to a local urgent care center. An EGD Violation was issued for a failure to sisteguard. A partial Stop Work. Order (PSWO) was issued for the area where the incident occurred. A DOB Violation was also issued.	ECB Violation	35355256Y	001918CERJM01	NEW BUILDING	121191628-01-NB	Other Construction Related Incidents	WEST 122ND STREET PROPERTY INV	Pinnacle Contracing
2018	Manhattan	110	UNIVERSITY PLACE		The Site Safety Manager reported that a worker suffered a cut to his right finger while picking up a bundle of metal. The worker walked to an urgent care center for treatment.	No Dispatch			NEW BUILDING	121187241	Other Construction Related Incidents	NOT ON FILE	CNY CONSTRUCTION LLC
2018	Brooklyn	3514	SURF AVENUE		The Site Safety Manager reported that a delivery truck was entering the site when it ran over the foot of the flagman. The flagman suffered a minor injury. An ambulance was called.	No Dispatch					Other Construction Related Incidents	RED APPLE SURF REALTY III LLC	
/2018	Manhattan	233	WEST 125 STREET		The Site Safety Manager reported that a worker was doing form work on the sixth floor deck when the worker slipped and tell about there level into a beam porket. The worker this back. An ambulance was called, A DGB and issued an ECE Voltation for a faulture to maintain safety measures. A partial Bop Work Order (PSWO) and a DGB Voltation were also suscer. The General Contractor is to provide a Means and Methods for the covering of beam pockets during form work operations.		35350611r failure to provide safety measures	092018ce10vp01			Worker Feil	HARLEM URBAN DVLPMNTCP	
018	Manhattan	1865	BROADWAY		The Site Safety Manager reported that workers were loading windows on an 'A'-Frame at the loading dock when a window slid and a worker got his hand caught between windows. The worker suffered a cut to his hand and went to a hospital for treatment.				NB	121190219	Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	LEND LEASE (US) CONSTRUCT
2018	Manhattan	161	MAIDEN LANE		A DOB inspector reported that during a material delivery at the thirty-ninh floor, a palet of cement on a floor jack was accidentally overed onto another worker's hand. The injured worker's finger was swollen, and the injured worker went to a brogstall with another worker to have 2- the incident occurred due to a miscommunication between a worker that was installing 2-X 4 criting and worker that was lowering the pallet of cement. As of the inter of inspector, all adelguards were in place at the hitry-inith floor and no hazardous conditions were observed. No enforcement action was deemed necessary.				NEW BUILDING	121185680-01-NB	Other Construction Related Incidents	FPG MAIDEN LANE, LLC	PIZZAROTTI LLC
2018	Manhattan	115	DELANCEY STREET		The Site Safety Manager reported that a worker in the sub-cellar tripped and suffered a cut to his left arm. An ambulance was called.	No Dispatch				_	Other Construction Related Incidents	NOT ON FILE	
/2018	Manhattan	100	EAST END AVENUE	0 1	antiobartice was celled. A DOB inspector reported that during a stair installation at the tenth floor level, a steel spreader that was approximately 0.57 x 50 ± X 2 bill from the tenth floor and struck a worker that was on the sixth floor are back. The struck worker compliand of back pain and was laken to a hospital by ambulance. A controlled access pathomed at the static floor set back and the tenth floor periormed at the statin floor set back and the tenth floor periormed at the same time. An ECB Violation was issued for a failure to maintain an after measures at the job site. A partial Stop Work Order (PSWO) and a DOB Violation were also issued.	ECB Violation	35350614m	092118ce08vp01			Other Construction Related Incidents	THE CHAPIN SCHOOL LTD	
/2018	Manhattan	147	EAST 86 STREET		The Site Safety Manager reported that a brick layer dropped a concrete masonry unit (CMU) on his hand. The tip of the brick layer's hand was severed. The brick layer was transported to a local hospital by the job foreman.	No Dispatch			NEW BUILDING	122668648-01-NB	Other Construction Related Incidents	NOT ON FILE	GILBANE RESIDENTIAL CONST



cident Date	Borough	Address Number		Fatalities Injuries		DOB Action		DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
V2018	Bronx	2365	HOFFMAN STREET	0	1 A DOB inspector reported that a worker was standing on loose dir while collecting debits when the pile of dirt moved, which caused the worker to fall approximately six feer tint oa pit. The worker suffered a broken leg and was taken to a hospital. The incident occurred because there was an unsel demonitor on persiton taking place. Eight total ECB Violations were issued: one violation for balance to range branches one of port housekeeping, as there was accurately and the site, one violation for the presence of poor housekeeping, as there was accuracive debits at the site, one violation for the brasence of guard rails, one violation for the presence of poor housekeeping, as there was accurate the taken of the presence of storage on a sidewalk shed that was contray to the approved plan, and one violation for the presence of missing light buils under the sidewalk shed. A partial the site, and the violation for the second of the violation is the site of the sociality of the work area. The General Contractor is to make the area safe and provide a Means and Methods for the safe operation of the job.		35316196N, 99P, 35353130J, 31L, 32N, 33P, 34R & 352		DEMOLITION	220582929	Worker Fell	HOFFMAN PROPERTIES NY LLC	KING DEMOLITION SERVICES
2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	<ol> <li>The Construction Superintendent reported that a worker fell off of a six foot "A"-Frame liadder. The worker suffered pain to his back and ankle, and was taken to a hospital by ambune. A DOB inspector responded to the incident and reported that the incident occurred as the result of a worker's error. No enforcement action was necessary.</li> </ol>	No Action Necessary			NB	320622894	Worker Fell	ATLANTIC 2644, LLC	Cauldwell Wingste co. llc.
/2018	Manhattan	12	EAST 48 STREET	0	1 The Site Safety Manager reported that a worker was passing a piece of plywood to another worker when the phywood silped out of his hand and struck the worker on the nose. A co-worker took the struck worker to a clinic. The worker received treatment and then returned to work. The incident occurred on Thursday, September 27, 2018. Lut was not reported until Fiday. September 28, 2018.	No Dispatch			NEW BUILDING	121190816	Material Fell	1248 ASSOCIATES LLC	ANTHONY T. RINALDI LLC
/2018	Manhattan	25	PARK ROW	0	1 The Site Safety Manager reported that a worker dislocated his shoulder while lifting a bundle of insulation. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	
2018	Queens	148-10	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker hurt his finger while loading shores onto racks. The worker was driven to a first med.	No Dispatch			NEW BUILDING	420654517-01-NB	Other Construction Related Incidents	BRP JAMSTA TWO TC OWNER LLC	CNY CONSTRUCTION LLC
/2018	Manhattan	108	LEONARD STREET	0	1 The Site Safety Manager reported that there were workers that were moving metal rails near an elevator when one of the workers lost control of a rail and the rail fell on his toe. The worker had blood clotting under the nail and went to a hospital by ambulance for a check up.	No Dispatch			ALTERATION-1	121185831	Other Construction Related Incidents	CIVIC CENTER COMMUNITY GROUP B	NEW LINE STRUCTURES & DEV
3/2018	Manhattan	11	GREENE STREET	0	<sup>1</sup> The Site Safety Manager reported that an iron worker was shaking out C-Decking when he stepped back and left from the lift hoor C-Deck to the fourth floor concrete floor. The worker was found baseding from the head, but the stepped back and the lift has a stepped back and inspector resourced to the incident and visited the site and issued an ECB Violation for a failer to safeguard A LUI Stop Work Order (FSWO) and a DOB Violation were also issued. Four additional ECB Violations will be issued: one Violation for the failure to provide protection for the adjacent property, one violation for the presence of inadequate usurdails, one violation for the failure to use Presonal Protection Equipment (PPE) while working on the fifth floor Q-Deck.		35366852J	082818CE02MA01			Worker Fell	335 CANAL STREET	
/2018	Manhattan	685	1 AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker hurt his back while picking up materials. The worker was taken to a hospital by a co-worker. An ambulance was not called.</li> </ol>	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
2018	Manhattan	500	WEST 33 STREET	0	<ol> <li>The Site Safety Manager reported that a worker was carrying material when he slipped and suffered an arm injury. The worker was taken to a hospital.</li> </ol>	No Dispatch			NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORP
2018	Manhattan	15	EAST 30 STREET	0	<ol> <li>The Site Safety Manager reported that a worker was inserting a fastening pin when he hit his hand with a hammer. The worker was transported to a local hospital by a co-worker.</li> </ol>	No Dispatch			NEW BUILDING	122128679	Other Construction Related Incidents	MADISON 30 31 OWNER LLC	RC STRUCTURES INC
/2018	Brooklyn	418 A	LEWIS AVENUE	0	1 The Construction Superintendent reported that a worker was carrying a concrete block when he tripped, fell, and this face on the pavement. An anoulance was called. Another that he worker tripped over an electrical wire. An ECB Violation was insued for poor housekeeping. A DOB Violation was also issued.	ECB Violation	35353474N	100118CE03MH03	ALT-1	321376346	Worker Fell	GAF REALTY HOLDINGS, LLC	ACHILLE & SON INC



ident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/2018	Manhattan	200	AMSTERDAM AVENUE		1 A DDB inspector reported that there were contractors performing stripping operations on the first floor when a worker removed a reahore that was supporting a temporary platform that was used to access a ladder leading to the cellar. When the platform gave out, a worker fill levels leat to the floor. The worker was found conscious and was taken to a nearby hospital, where it CEB Violation was insued for the fulline to maintain safe operations. A partial Stop Work Order (PSWO) was issued for all stopping work. No other violating conditions were observed, and all of the workers at the its were in possession of OSHA cards. The contractor is to provide a Means and Methods for safe stripping operations.	r.	35350860h		NB	122887224	Worker Fell	AMSTERDAM AVENUE REDEVELOPMENT	Pavarni Mogovern IIc
1/2018	Manhattan	301	EAST 117 STREET	0	1 The Site Safety Manager reported that a worker was using a hammer on form work on the first floor when the hammer deflected and hit the worker in the head. The worker had his hard hat on, but suffered a minor cut. An ambulance was called.						Other Construction Related Incidents	AMP HOLDINGS LLC	
1/2018	Manhattan	68	TRINITY PLACE	0	1 The Site Safety Manager reported that a worker was tightening a bolt with a wrench when the wrench slipped in his hand and hit him on the lips. The on-site medic examined the worker and recommended that he be sent to a hospital for further evaluation.				NEW BUILDING	121186855	Other Construction Related Incidents		HUNTER ROBERTS CONST. GRP
2/2018	Bronx	2568	PARK AVENUE	0	<ol> <li>The Site Safety Manager reported that an iron worker was pulling up a "Q"-Deck when a nail hit him in the eye. The worker went to urgent care with another co-worker.</li> </ol>	No Dispatch					Other Construction Related Incidents	2568 BRONX PARK LLC	
	Bronx	690	EAST 183 STREET	0	1A DGB inspector reported that a first story elementary backet while a custodian user cleaning out of the classocors for the next day. While the concrete was being removed from the window header, the custodian was struck on the head and shoulder by the interior plaster above the window header. The custodian was taken to Sinit Bamabas Hospital by ambulance. An Aggravated Level 2 EGB Violation was issued for a faiture to safeguard. A partial Size Work Order (FSWO) was issued for the second level action reast courtyard area. A DGB Violation was also issued.		35355680X	100218CERTQ01	Alt 3 Façade Restoration		Material Feil	DEPARTMENT OF EDUCATION	Ansu Construction
2/2018	Manhattan	511	EAST 86 STREET	0	1 The Site Safety Manager reported that an elderly woman was walking up a map that was underneath the sidewalk shed when she fell. The woman fell, but did no rip. The woman denied medical attention. A DOB inspector visited the site and reported that the evidence of the incident was tampered with. Four ECB Violations were issued: one violation for the failure to protect pedestrians form material storage in the roadway, one violation the absence of a Department Of Transportation permit for the disence of rebar caps, and one violation for the absence of rebar caps. and one violation for the material storage in roadway No DOT permit for closing pedestrian valkway Missing rebar caps Missing guardraits.		35353141P,42R,432,44K	100219CE08WZ01.02.03.04	NB	123062078	Other Construction Related Incidents	CARRERA RS LLC	K S K CONSTRUCTION GROUP
3/2018	Brooklyn	61	BOND STREET	0	1 The Site Safety Coordinator reported that a worker was climbing down from a ladder when he fell approximately ten feet. The worker suffered a minor injury. An ambulance was called.	No Dispatch			NB	320914221	Worker Fell	BOND STREET OWNER LLC	BROADWAY CONSTRUCTION GR
//2018	Queens	21-20	45 ROAD	0			35355282K	100418CERJM01	NEW BUILDING	421369227-01-NB	Worker Fell	SALM PROPERTIES LLC	1 OAK CONTRACTING LLC
\$/2018	Manhattan	301	PARK AVNUE	0	1 The Site Safety Manager reported that a worker hurt his finger while pushing a mini-dumpster. An ambulance was called to send the worker for treatment.	No Dispatch			ALTERATION	123021238	Other Construction Related Incidents		TISHMAN CONSTRUCTION CORP



ncident Date	Borough	Address Number	r Street	Fatalities Injuries			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0/4/2018	Manhattan	139	EAST 56 STREET	0	1 A DOB inspector reported that there were two workers that were moving a steel reshow when a collar slid and hit a worker's hand. The worker suffered a cut to his finger and wert to an emergency center, where he received two switches to his thumb. The worker wanted to return to work tater in the day, but was given two days off. The collar was not properly threaded down to prevent movement during handling. It was determined that this incident occurred as the result of a worker's error, and no enforcement action was taken.	No Action Necessary			NB	212-3216800	Other Construction Related Incidents	140 E S6TH ST CONDO	hunter roberts const
0/4/2018	Brooklyn	3514	SURFAVENUE	0	A DOB inspector reported that a worker was using a lull to unload heating units and equipment from a truck. As a heating unit was placed on the ground, Thied and fell a heating unit was placed on the ground. Thied and fell suffered cuts and bruises to his leg and black and was sent to Coney sliand hospital by ambulance. The worker was that was operating the lull was inexperienced and id not have contribution to reviolation for a failure to safeguard persons and progeny, one violation for the absence of a safety zone around the hazardous operation, and one violation for the absence of a flag person. A partial Stop Work Order (/FSWO) was issued for all equipment and material handling, including deliveries. The General Contractor is to provide a Means and Methods for the safe operation of the job.		35363433X, 34H & 35J		NEW BUILDING	321189842	Material Fell	RED APPLE SURF REALTY III LLC	HUDSON MERIDIAN CONSTRUCT
0/5/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was making repairs to a cocoon system when he fail from the sisteenth floor to the fifteenth floor and landed on unprotected rebuilts. The worker suffered non life- threatening injuries and was transported to a nearby hospital. A DOB Inspector responded to the incident and reported that the worker fail through an eighteen inch opening from Doka form work that was contrary to the plant that was no site. Four ECB Violations were issued: one Aggravated Level 2 violation for a failure to safeguard, one violation for work being performed contrary to the approved plan, one violation for the absence of and larger system. The General Absence of and larger system. The General Cosing out will on the plan own of the plan based (PSWQ) was issued on all concrete work. Four DOB Violations were also issued.		353676633X,654H,655J,656L	100518CE02MH01,02,03,04	NB	321197478	Worker Fell	CADMAN ASSOCIATES LLC	T.G NICKEL
0/5/2018	Brooklyn	30	COLUMBIA HEIGHTS	0	<sup>1</sup> The Site Safety Manager reported that a worker was on the sidewalk shed performing demolition work when a rolf-down gate that was approximately seven hundred pounds shell approximately six feet and rolled onto the worker's shell and lag. The worker was found in stable worker's shell and lag. The worker was found in stable taken to a hospital by ambulance. A DOB impector responded to the incdent and visited the site and issued an ECB Violation for the performance of an unsafe demolition operation. A parall Slop Work Order (PSIVO) was issued on all demolition operations and material handing. A DOB Violation was also issued. The General Contractor is to provide a Means and Methods and a safety orentation.		35366763M	100518CE02BG01	ALT-1	321194346	Material Fell	25-30 COLUMBIA HEIGHTS BROOKLY	ARCHSTONE BUILDERS LLC
0/5/2018	Brooklyn	420	KENT AVENUE	0	2 ADDB inspector reported that on the hearth first floor, the workers were using a doly to transport sheatrock when the workers load control and the sheatrock field and hit both of the workers. One of the workers suffered a broken wrist, and the second worker injured his leg. Both workers were transported to a hospital. An ECB Violation was issued for a failure to maintain safe operations. A parial Stop Work Order (PSWO) was issued to stop all material handling, including delivities. There to stop all material handling, including delivities. Methods for safe operations, along with a Tool Box Talk.	ECB Violation	353508871N		NB	320597476	Material Fell	420 KENT ÄVENUE LLC	20G, LLC
)/5/2018	Manhattan	90	WASHINGTON STREET	0	<ol> <li>The Site Safety Manager reported that a worker cut their finger while picking up metal studs. The worker went to a hospital. This incident occurred on 10/5/2018, but was not reported until 10/8/2018.</li> </ol>	No Dispatch			ALTERATION TYPE 2	121160028-01-EW-OT	Other Construction Related Incidents	65 WAVERLY LLC	SRCC CORP
3/5/2018	Queens	22-43	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker hurt his leg while picking up a piece of plywood form work. The worker had a small red mark on his leg. The worker called an ambulance himself. This incident tock place early in the morning, but was not reported until 11:30 AM.	No Dispatch			NB	420659406	Other Construction Related Incidents	CIRCLE F 2243 JACKSON DE LLC	U-BUILD CONSTRUCTION LLC
/8/2018	Queens	22-18	JACKSON AVENUE	0	1 The Site Safety Coordinator reported that a worker was swinging a sledgehammer when he hit a metal stud and cut his finger. The worker went to a hospital.	No Dispatch			NEW BUILDING	420655838-01-NB	Other Construction Related Incidents	22-12 JACKSON OWNER LLC	BRITT REALTY LLC



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0(8/2018	Manhattan	233	WEST 125 STREET		1 A DOB inspector reported that a concrete worker was etripping forms around the elevator shaft on the fifth floor mezzanine level when the upper portion of form, which was approximately seven/why five to one hundred pounds, fell on the worker, causing injuries to the worker's right shoulder, rbb, high, and forearm. The worker sing the solution, and the should be the solution receiver medical attention, but then returned to work to inform the Site Safety Manager of the incident. A Tool work is the safety manager of the incident. A Tool work is the safety manager of the incident. A Tool work is the safety manager of the incident. A Tool work is the safety manager of the incident is a trans- tigued the meeting notes. However, the Means and Wethods were to followed or enforced, which resulted in the injury to the worker. Two ECB Violations were issued: one violation for a failure to safeguard, and one violation for the failure to notify the Department Of Buildings of the incident in a tainey manner. A partial Stop Work Order (FSWO) and two DOB Violations were also issued.	ECB Violation	35355661H-62J	100818CERTQ01-TQ02	NB	121187447	Material Fell	HARLEM URBAN DVLPMNTCP	Flintlock Construction Serv LLC
/8/2018	Manhattan	209	EAST 19 STREET	0	The Site Safety Manager reported that a worker was cutting drywail with a sheetrock hand saw when her hand slipped and he worker cut her hand with the sheetrock saw. The worker went to an area hospital, received sithches, and was then utild by the doctor to return to work. It was determined that this incident occurred as a result of the worker's error. No enforcement action was necessary.	No Action Necessary			NEW BUILDING	121958480-01-NB	Other Construction Related Incidents	NOT ON FILE	GRAMERCY SQUARE LLC
/9/2018	Manhattan	685	1 AVENUE	0	1 The Site Safety Manager reported that a worker cut his elbow on a door frame. The worker went to urgent care	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
/9/2018	Queens	23-15	44 DRIVE	0	on his own. 1 The Site Safety Manager reported that a worker injured his ankle while coming down a gang ladder. An	No Dispatch					Other Construction Related Incidents	BGY CITYVIEW LLC	
0/10/2018	Manhattan	34	HUDSON BOULEVARD EAST	0	ambulance was called. 1 The Site Safety Manager reported that a worker was sliding a steel raker beam when his finger got pinched. The worker went to a walk-in clinic, received stitches, and returned to work.	No Dispatch			NEW BUILDING	122885422-01-NB	Other Construction Related Incidents	509 W 34, L.L.C.	TURNER CONSTRUCTION COMPA
J/11/2018	Manhattan	251	EAST 32 STREET	1	1 A DOB inspector reported that there was facade repair work in progress that was using "C-Hook suppended scaffolding. The coping stone that was underneal the "C-Hook suppended scaffolding came loose, fell, and hit two workers that were on the scaffold then fell onto the sidewalk sheet, causing damage. Both workers was in critical condition, and eventually succumbed to bis injuries. A full Stop Work Order was issued to stop all work at the side works the except for the performance of safety work, which includes the repair of the sidewalk sheet. A DOB Violation for a failure to safeguard was also issued Many unsale conditions will be addressed by issuing the appropriate violations. The General Contractor is to provide an inclear tepot.			101118BS06DH01	FAÇADE REPAIR	123227686	Material Fell	RIVERVIEW EAST OWNERS CORP.	DNA CONTRACTING LLC
/12/2018	Manhattan	701	7 AVENUE	0	1 The Site Safety Manager reported that a worker was climbing down an "A"-Frame ladder when he missed the third step up from the ladder and fell approximately three feet. An ambulance was called. This injury occurred as the result of a worker's error.						Worker Fell	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
/12/2018	Manhattan	110	CHARLTON STREET	0	The Site Safety Manager reported that a platform ladder on a delivery truck blew off of the truck due to high wind and struck a worker's right ankle. The worker suffered a minor injury went to a City M.D. with the Site Safety Manager.				NB	121191263	Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	PLAZA CONSTRUCTION LLC
/12/2018	Brooklyn	428	WYTHE AVE	0	The Site Safety Manager reported that a worker was erecting steel when he cut a finger on his left hand. The worker suffered a minor injury. An ambulance was called				ALT-1	321262897	Other Construction Related Incidents		SNBD ENTERPRISES LLC
/12/2018	Brooklyn	19	KENT AVENUE	0	<ol> <li>The Site Safety Manager reported that a worker twisted his back while chipping concrete on the roof. The worker was taken to a hospital by ambulance.</li> </ol>	No Dispatch			NB	320591944	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
/12/2018	Bronx	16	EAST 204 STREET	0	1 The Site Safety Manager reported that a worker was loading a small concrete mix tub onto a full when the concrete mix tub tilted onto the worker's foot. The worker suffered a bruised foot. The worker was able to walk. An ambulance was called.	No Dispatch			NB	220415012	Other Construction Related Incidents		GALAXY G.C. GROUP LLC
D/15/2018	Manhattan	13	LAIGHT STREET	0	A DOB inspector reported that a worker fell off of a ladder located at the basement level. The worker was suffering from back pain and was taken to a local hospital. Four ECB Violations were issued: one violation for the presence of unsafe conditions, one violation for working with an expired sidewalk shed permit, one violation for working without a permit for a pipe scaffold, and one violation for a failure to safeguard all persons and propert, A partial Stop Work Order (PSWO) was also issued.	ECB Violation	35352065H, 35352066J, 35352067J, 35352068N		Alt 2	123149994	Worker Fell	13-17 LAIGHT NY LLC	Parazini McGovern LLC



ncident Date	Borough	Address Numbe		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0/16/2018	Brooklyn	424	ALBEE SQUARE	0	1 A DOB inspector reported that during an excavation operation, there were contractors that hit an electrical cable that was encased in concrete. A piece of concrete hit the worker in the face and caused a cut below the worker's eye. The worker was taken to a waik-in clinic. Con Edison was notified of the incident and was en route as of the time of the inspector's with cadress the	ECB Violation	35351361H		NB	321191027	Excavation/Soil Work	JEMB ALBEE SQUARE LLC	Gilbane Building
					exposed electrical cable. An ECB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWG) was issued for the entire site. Additional violating conditions were also observed during the inspection.								
0/16/2018	Manhattan	227	CHERRY STREET	0	1 The Site Safety Manager at 250 South Street, John Denora, reported on 1024/2018 that a worker was pulling on an energized wire react to a pull box when he received a shock and suffered second degree bursts to before he was transported to a boxplint A DOB inspector. It is unspectived and not popular A DOB inspector responder to the incident and the time of inspector. It is inspection of and the any infractions. The contractor at the site had all of the appropriate paperwork and a work permit in place. No enforcement action was taken.	No Action Necessary			NEW BUILDING	121185528	Other Construction Related Incidents	NOT ON FILE	LENDLEASE (US) CONSTRUCTION
D/16/2018	Manhattan	250	WEST 43 STREET	0	1 A DOB inspector reported that a worker was working at the street level at a garage that was approximately fifteen feet above grade to remove concrete and/or freprocing from steel. The worker let to the grade and conscious and was taken to a hospital. The area in question did not have any file ince or the orth points for guardinal at the allable adge. An ECB Violation was issued for a failure to safeguard A partial Stop Work Order (PSWO) was issued for all work at the garage level. A DOB Violation was also issued.	ECB Violation	35355832N	101618CERFC01	ALTERATION TYPE 1	120272025-01-AL	Worker Fell	250 WEST 43 OWNER LLC	PARK PREMIUM ENTERPRISES
/17/2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that an electrician was walking and carrying some material when he fell and injured his wrist. The electrician drove himself to a hospital to receive further examination.	No Dispatch			NB	520301968	Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	MATRIX CONSTRUCTION SERVICE
/17/2018	Manhattan	550	WEST 34 STREET	0	1 The Site Safety Manager reported that a worker fell and injured his ankle while pulling wire from the ceiling. An ambulance was called.	No Dispatch					Other Construction Related Incidents	ONE HUDSON YARDS OWNER LLC	
/17/2018	Manhattan	500	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was getting into a man lift when he twisted his knee and the knee buckled. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
0/17/2018	Manhattan	180	BROOME STREET	0	1 The Site Safety Manager reported that a worker was moving form work when the form work fell while the corner end was being lifted up. The worker's finger was pinched. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	SITE 4 DSA OWNER LLC	
/17/2018	Brooklyn	30	MORGAN AVENUE	0	1 The Construction Superintendent reported that a worker fell off a ladder and fractured his knee. The worker was taken to Columbian Presbyterian-Methodist Hospital.	No Dispatch			ALTERATION TYPE 1	320596324-01-AL	Worker Fell	INDUSTRIOUS LLC	THINK CONSTRUCTION LLC
0/18/2018	Manhattan	1912	1 AVENUE	0	1 The Site Safety Manager reported that a worker was erecting a scaffold when he got a splinter while moving the scaffold planks. The worker went to a hospital.	No Dispatch			NEW BUILDING	122879233-01-NB	Scaffold/Shed/Fence/Shoring/Installation	HEALTH AND HOSPITALS CORPORATI	PROCIDA CONSTRUCTION CORP
)/18/2018	Manhattan	685	1 AVENUE	0	The Site Safety Manager reported that a plumber was installing a duct when he cut his right hand on a metal ceiling track. The plumber went to a doctor via taxi to be further extended.	No Dispatch			NB	121189784	Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	SECOND AVENUE SOLOW DEV CORP
0/19/2018	Queens	41-62	BOWNE STREET	0	Inther evaluated. 1 A DOB inspector reported that a worker was pushing a wagon that was carrying about ten pieces of plywood when the wagon tipped over and the worker was cut by a piece of plywood. The worker was taken to a City MD. by a co-worker. Twe EOB Violations were issued, one violation for ataliums to manifain safety measures at the of the tailure to designate a Site State(> Coordinator as required. A full Stop Work Order (FSWO) and two DOB Violations were also issued.	ECB Violation	35366929N/30K	102218CE07DH01/02	NB	421210022	Other Construction Related Incidents	EPIC TOWER LLC	AAA GENERAL CONSTRUCTION
0/19/2018	Manhattan	2395	FREFERICK DOUGLAS BLVD	0	1 The Site Safety Manager reported that a rigger was on a truck unloading concrete plank when he fell off of the truck and broken is wrist. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that the rigger missateped, causing him to fail off of the task of the truck. No enforcement action was necessary.	No Action Necessary			NB	121191557	Worker Fell		SUMMIT JV LLC
0/19/2018	Manhattan	1912	1 AVENUE	0	1 The Site Safety Manager reported that a brick layer dropped a brick from his hand onto his foot. The worker went to the emergency room with a foreman.	No Dispatch					Other Construction Related Incidents	HEALTH AND HOSPITALS CORPORATI	
0/19/2018	Manhattan	180	EAST 88 STREET	0	1 The Site Safety Manager reported that a worker was lifting a debris cart when he felt his elbow pop. The worker went to see his doctor to be further examined.	No Dispatch			121186518	NB - NEW BUILDING	Other Construction Related Incidents	180 EAST 88TH STREET REALTY LL	DDG DEVELOPMENT LLC
0/19/2018	Manhattan	180	BROOME STREET	0	1 The Site Safety Manager reported that a worker cut his finger while using a grinder. The worker went to a City M D	No Dispatch	Page 56 of				Other Construction Related Incidents	SITE 4 DSA OWNER LLC	



cident Date	Borough	Address Number		Fatalities Injuri		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/22/2018	Manhattan	150	5 AVENUE	0	1 The Site Safety Manager reported that an iron worker was using a magnetic drill underneath a beam when he lost contact with the beam and was hit on the chin. The worker was found conscious and was transported to a hospital by ambulance.	No Dispatch			ALT1	122700292	Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SERVICE
2/2018	Manhattan	301	EAST 80 STREET	0	1 The Site Safety Manager reported that a worker injured	No Dispatch					Other Construction Related Incidents	301 EAST 80TH REALTY LLC	
					his back while picking up a bucket. The worker went to see his own doctor for a follow up.								
23/2018	Manhattan	550	west 34 street	0	2. A DOB inspector reported that three workers were performing winkow glazing work on a hung scallod at the thirty eighth floor of the south exposure when a heavy gust of wind blew the 12-10 eng working platform of the rig to the east exposure. The workers broke a water work of the south exposure the broke of glazing the the proken glazing of the workers and where taken to a hospital. The working platform of the suspended scalford was at a vertical position at the thirty separation the New York CBy Fire Department lashed and ted back the platform and secured the platform and ted back the platform and secured the platform and ted back the platform and secured the platform back the distribu- tion of elements and secured the platform back into the structure to determine scalfold as an exclusion zone that is inaccessible to the public. An ECB Violation was issued or a failute to saleguard. A partial Stop Work Order (PSWO) was also issued on all exterior glazing work. A DOB Violation was also issued on all exterior glazing work. A DOB Violation was also issued on all exterior glazing work. A DOB Violation was also issued on all exterior glazing work. A DOB Violation was also issued on all exterior glazing work. A DOB Violation was also issued on all exterior glazing work. A DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and DOB Violation was also issued on all exterior glazing work and and was allower allower allower and work and was allower all	ECB Violation	35244333R	102318CNEDG01	NEW BUILDING	121184841-01-NB	Scaffold/Shed/Fence/Shoring/Installation	ONE HUDSON YARDS OWNER LLC	GLBANE BUILDING COMPANY
3/2018	Queens	47-15	PEARSON PLACE	0	1 A DOB inspector reported that a worker fell approximately eighteen feet from a supported scattidd and landed on a roof settack. The worker suffered minor injuries and was taken to a local hospital. An EOB Volation was issued for the presence of a supported scattidd that does not meet code specifications. A partial SCM VMAC Oder (PSVIQ) was issued on chimey repairs and on the use of a supported scattidd. The only work that is allowed at the site is work to secure the site.		35354116H		Alt 2	Q00033065	Worker Fell	BLDG 4715 PEARSON LLC	New Generation Construction
3/2018	Staten Island	22	ZEBRA PLACE	0	1 The Construction Superintendent reported that a worker was climbing a ladder from the second floor to the third floor when he slipped and fill approximately seven feet. The worker claimed to be experiencing pain in his shoulder. An ambulance was called. This injury occurred as the result of a worker error.						Worker Fell	ZEBRA PLACE LLC	HOLLISTER CONSTRUCTION SE
24/2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker stepped on rebar and was struck in the nose by the rebar. The worker went for treatment at an off-site medical facility.	No Dispatch			NB	420654508	Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	CNY Construction
4/2018	Manhattan	221	WEST 17 Street	0	1 A DOB inspector reported that during the dismantaling and loading of a sidewalk shed part, one of the temporary platforms that was being used was pulled over and the platform fiell on a worker's hand. The worker was taken to a City MD. An ECB Violation for a failure to safeguard all persons and property was issued.		35354135N		AL	121186965	Scaffold/Shed/Fence/Shoring/Installation	221 W. 17th Street LLC	OTL Enterprises LLC
4/2018	Manhattan	110	CHARLTON STREET	0	<ol> <li>The Site Safety Manager reported that a worker got his finger pinched between rebar and metal shore. The worker went to a City M.D.</li> </ol>	No Dispatch					Other Construction Related Incidents	STRATEGIC GREENWICH EQUITY, LL	
24/2018	Brooklyn	187	COOK STREET	0	1 A DOB inspector reported that a delivery of rebar from a boom truck was in prograss when a load of rebar was dropped on the wooden horse of the third floor deck. The wooden horse itiled and the load of rebar flexing and the second seco		3536685K, 96M, 87Y, 88X, 89H, 90P, 91R, 92Z, 93K, 94M.		NEW BUILDING	321702136	Material Fell	187 COOK ST. LLC	PACIFIC RIM



Incident Date	Bereuch	Address Number	Chront	Estalities Iniusia	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
0/25/2018		300	LAFAYETTE STREET	0	A DOB inspector reported that a sidewalk shed was being dismarked when a three foor threaded rod fell through a crack in the sidewalk shed and hi a pedestrian. The pedsetrian suffered a laceration to the top of her head and her shoulder and was taken to a hospital. Three CEO Violations were issued: one violation to the General Contractor for a failure to safeguard, one violation to the scaffold company for a failure to safeguard, and one violation to the General Contractor for the absence of an approved design drawing. A partial Stop Work Order (PSWQ) on the use of a sidewalk shed was issued. It was recommended that the scaffold should not be used or removed and the a Means and Methods must be provided in order to prevent a future incident of this nature from occurring in the future.	ECB Violation	35354185L, 35354186N, 35354187P		NB	121186992	Material Foil	LVC 298, LLC	March Assoc Const Inc
10/26/2018	Brooklyn	11	HOYT STREET	0	1 The Site Safety Manager reported that a pedestrian passed flaggers during a temporary sidewalk closure and tripped in front of the site. The pedestrian suffered a minor foot injury and was treated by the on-site medic.	No Dispatch			ALTERATION TYPE 1	321197058-01-AL	Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	TRITON CONSTRUCTION CO.
10/27/2018	Manhattan	1776	BROADWAY	0	1 The Site Safety Manager reported that two electricians were pulling wires for temporary lighting when one of the workers' hands slipped over the wire and his elbow hit the wall, acusing swelling to his elbow. The worker was sent to a doctor for a check up.	No Dispatch			ALTERATION	123118349	Other Construction Related Incidents	ILLERTISSEN HOLDINGCORP	JT MAGEN + CO INC
10/29/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 A DOB inspector reported that during a stripping operation of concrete form work, a worker entered the stripping zone and bent down to tick up a piece of material when a panel of formwork was lowered from a worker allow its eight. The works was lowered town a worker allow its eight. The work was under a stripping CEB Violations were issued on eviolation for a failure to maintain safety measures, as the worker was injured during a stripping operation that did not have a Controlled Access Zone (CAZ), one violation for the adsence of overhead protection for eights of the adsence of overhead protection for regress of the adsence property on exposure three, one violation for the use of a workhorse with a counter weight that was not shown on the Site Safety Pian, and one violation for the presence of an unlawd using on the sidewalk shed. A partial Sitop Work Order (PSWO) was issued to stop all forming and stripping operation that during. The General Contractor is to provide a Means and Methods for the safe operation of the job, including a Worker's Orientation and a Controlled Access Zone.	ECB Violation	35367076P, 35367079K, 35367080H, 35367081J.		NEW BUILDING	321197085	Material Fell	NYC HPD	LEND LEASE (US) CONSTRUCTION
10/29/2018	Manhattan	787	11 AVENUE	0	The Site Safety Manager reported that a worker was carrying a bag of grout mixer when he pulled a muscle in his shoulder. The worker walked to a City M.D. to be examined as a precaution. The worker was expected to return to work.	No Dispatch			ALTERATION-1	121190399	Other Construction Related Incidents	GEORGETOWN ELEVENTH AVENUE OWN	CAULDWELL WINGATE CO LLC
10/30/2018	Bronx	1880	BATHGATE AVENUE	0	1 The Construction Superintendent reported that a mason was walking when he bruised his shin on a block. The mason suffered a minor injury and went to an off-site medical facility for treatment.	No Dispatch					Other Construction Related Incidents	WILFRED REALTY CORP.	Mega Contracting
10/30/2018	Brooklyn	9	DEKALB AVENUE	0	1 The Site Safety Manager reported that a worker was using a grinder to cut pipe when the grinder kicked back and cut the worker's wrist. The worker suffered a small laceration. An ambulance was called.	No Dispatch					Other Construction Related Incidents	9 DEKALB OWNER LLC	
10/30/2018	Manhattan	200	AMSTERDAM AVENUE	0	1 The Site Safety Manager reported that a worker was stacking forms when he suffered a back injury. The worker walked to a nearby City M.D.	No Dispatch			NEW BUILDING	122887224-01-NB	Worker Fell	AMSTERDAM AVENUE REDEVELOPMENT	PAVARINI MCGOVERN LLC
10/31/2018	Manhattan	110	CHARLTON STREET	0	1 The Site Safety Manager reported that a worker was installing column clamps on a formwork when he attempted to hit a pin with a harmner. The worker did no hit the pin directly, and the hammer slipped and hit the worker's right knee. The worker walked to urgent care.				NEW BUILDING	121191263-01-NB	Worker Fell		PLAZA CONSTRUCTION LLC
10/31/2018	Manhattan	49	CHAMBERS STREET	0	1 The Site Safety Manager reported that a worker was helping to lift a steel beam when he lost his gip and the beam fell approximately seven inches and landed on hi foot. The worker suffered a mixed right hole in the lost and a mbulance was called. A DOB inspector response to the incident and inside the site and reported that workers. The CB Violations was inside the violation for a failure to safeguard, and one violation for unable material handling. A partial BOV Work Order (PSWO) and two DOB Violations were also issued. A Means and Methods for material handling and receiving is to be provided.		35366899L, 35367275H	103118CE01LJ01.02	ALT	121186621	Other Construction Related Incidents	49-51 CHAMBERS LLC	NY DEVELOPERS & MANAGEMENT
10/31/2018	Queens	27-17	42 STREET	0	1 The Site Safety Manager reported that a worker was cutting wood flooring on a table saw when he cut his middle finger. The worker went to urgent care.	No Dispatch			NB	402654971	Other Construction Related Incidents		MILSTONE CONSTRUCTION



cident Date	Borough	Address Number	Street	Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/31/2018	Queens	38-39	9 STREET	0	1 A DOB inspector reported that there were contractors that were installing wooden forms of a new foundation when a worker fell while trying to climb into the wood box plt. The worker fell four fele and landed on rebar. The worker suffered minor injuries and was taken to a nearby hospital by ambulance. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (PSWO) was issued for all foundation form work. The contractor is to provide a Maens and Methods for safe ingress and egress into wooden forms.	ECB Violation	35366910N		NB	421634020	Worker Fell	9TH STREET LIC LLC	Urban Foundation
0/31/2018	Staten Island	2601	VETERANS ROAD WEST	0	1 A DOB inspector reported that a worker was installing a metal deck on the third floor and was adjusting the 'Or- Deck when the deck slipped from the beam, causing the worker to fall from the deck. The worker was using a safety hamess, but the largrad was not of the appropriate height and was not properly field. The largrad wapped around a column and slipped downward when the worker fell, and the worker fallend downward worker fell, and the worker fallend to a boging downing for the hamess the off, and one violation for the absence of manufacturer's specifications for the self-retracting laryard. At 148 Stop Work Order (FSWO) and three DOB Violations were also issued. A design drawing for the hamess te off and manufacturer's specifications for the self-retracting laryard must be provided.		36366703K,04M,05Y	103118CE03AS01,02,03	NB	520135746	Worker Fell	ZEBRA PLACE LLC	HOLLISTER CONSTRUCTION SE
1/1/2018	Bronx	443	EAST 162 STREET	0	1 The Site Safety Manager reported that a window installer was unpacking a bundle of windows when he tripped on a 4 X 4 section of dunnage, fell, and hurt his back and left arm. The worker was found conscious and was taken to a hospital.	No Dispatch			NB	2201521444	Other Construction Related Incidents	BRONX COMMONS HOUSING DEVELOPN	BRONX COMMON BUILDERS LL
1/1/2018	Bronx	4511	3 AVENUE	0	1 The Site Safety Manager reported that a worker was officiating awards of the section of the source of the pallet tipped over and the doors landed on the workers leg. An ambuince was called to the site. A DOB inspector responded to the incident and visited the site and issued an EQB Visitation for a failure to safeguard and unsafe material handling. A DOB Violation was also issued. A Means and Methods for safe material handling operations must be provided.		35366936L	110118CE08DH01	NB	220152117	Other Construction Related Incidents	STB HOUSING DEVELOPMENT FUND C	CHATSWORTH BUILDERS LLC
1/1/2018	Brooklyn	112	ST EDWARDS STREET	0	1 The Site Safety Manager reported that a worker was pushing a debris cart when he slipped and suffered a cut to his index finger. The worker went to the emergency room with a co-worker. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/1/2018	Manhattan	222	WEST 23 STREET	0	The Site Safety Coordinator reported that a worker was pulling wires for an HVAC Unit when he hit his hand against a metal box and suffered a minor cut to the back of his hand. The worker was taken to an nearby clinic for a follow up.	No Dispatch					Mechanical Construction Equipment	CHELSEA HOTEL OWNER LLC	Omnibuild construction
1/5/2018	Brooklyn	394	VANDERBILT AVENUE	0	1 A DOB inspector reported that a worker was in the process of installing plywood on second floor joists when he fell through plywood to the first floor. The worker sustained broken ribs and was taken to a hospital. An EQ Volation was issued to the Construction Superintendent for a failure to notify the Department Of Buildings of the incident in a timely manner. A full Slop Work Order (SWO) was issued to seal the building from weather elements. The roof remained open. A DOB Violation was also issued.	ECB Violation	35374625Y	110518CNEDB01	A1 - ALTERATION TYPE 1	321197799	Worker Fell	394-396 VANDERBILT AVE NY CORP	IFATHOM CONSTRUCTION CORP
1/6/2018	Manhattan	112	EAST 11 STREET	0	1 The Site Safety Manager reported that a worker was installing a piece of sheetrock to the ceiling when he cut his left wrist on a piece of metal. An ambulance was called.	No Dispatch			NB - NEW BUILDING	121191085	Other Construction Related Incidents	UD-DEV ASSOCIATES LLC	LEEDING BUILDERS GROUP LL
1/6/2018	Manhattan	15	EAST 30 STREET	0	1 A DOB inspector reported that a worker was lowering a glass prior when his hind rad part pinched between a leage and a notiler. The worker was taken to a local urgent care conter and was tracted for minor injuries. The worker than returned to work. The inspector observed that the manufacturing leage for supporting a window pane had a detect and was not fully extinded. The contractor at the site provided evidence that during heardmout whethods were in place prior to the debunking and setting of panels into place. No enforcement action was necessary.	No Action Necessary			NEW BUILDING	122128679-01-NB	Other Construction Related Incidents	MADISON 30 31 OWNER LLC	MADISON 30 31 OWNER LLC
1/6/2018	Manhattan	301	EAST 80 STREET	0	1 The Site Safety Manager reported that a worker picked up a box that slipped, fell out of his hands, and hit him on the bridge of his nose. The worker walked to a clinic.	No Dispatch			NB - NEW BUILDING	122847241	Other Construction Related Incidents	301 EAST 80TH REALTY LLC	CM AND ASSOCIATES CONSTRU
1/6/2018	Manhattan	301	EAST 80 STREET	0	<ol> <li>The Site Safety Manager reported that a worker suffered a hand injury while unloading a truck in front of the site. An ambulance was called.</li> </ol>	No Dispatch			NEW BUILDING	122847241-01-NB	Worker Fell	301 EAST 80TH REALTY LLC	CM AND ASSOCIATES CONSTRU



cident Date		Address Number	Street	Fatalities Injur	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	91	LEONARD STREET	0	1 The Site Safety Manager reported that a worker tripped on a piece of insulation and hit his head. An ambulance was called.	No Dispatch			NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
2018	Manhattan	685	1 AVENUE	0	was called. 1 A DB inspector reported that a worker was working on a window and performing aluminum work when a piece of aluminum moding tell on him. The worker suffered a cut to his finger. An ambutance was called. The messait of a worker's error. No enforcement action was necessary.	No Action Necessary			NB	121189784	Other Construction Related Incidents		SECOND AVE SOLOW DEV CORP.
2018	Manhattan	351	BROADWAY	0	1 The Site Safety Manager reported that a worker tripped while walking down stairs. The worker suffered a minor injury to his ankle and received off-site medical treatment at an urgent care center.	No Dispatch					Other Construction Related Incidents	353-357 BROADWAY LLC	Toll GC
2018	Brooklyn	41	BLUE SLIP	0	1 The Site Safety Manager reported that a carpenter fell off of a six foot ladder, landed on his hammer, and hurt his back. An ambulance was called and the worker was transported to a hospital for further observation.	No Dispatch			NB	320597449	Worker Fell	BOP GREENPOINT F LLC	TG NICKELS & ASSOCIATED
3/2018	Brooklyn	1443	LINCOLN PLACE	0	The Construction Superintendent reported that a worker was installing a sidewalk shed when he fell ten feet down the stativary shaft into the cellar. The worker was found conscious and was taken to a hospital by ambulance. A DOB inspector responded to the incident and reported that the guardrails that were around the indewalk shed, and the worker tost his balance. An ECB Violation was issued for the failure to maintain proper safety equipment. A full Stop Work Order (FSWO) was issued for the entire site.		35367353Y		Alteration	321148931	Worker Fell	LINCOLN ESTATE HOLDINGS LLC	El Jay Group
/2018	Manhattan	27	EAST 79 STREET	0	1 A DOB inspector reported that during a stripping operation, a worker lost his balance and hit his head on a concrete column. The worker was conscious and membulance. The worker was strained to the strained of ambulance for uthrer evaluation. Four ECB Volations were issued: one violation for a failure to institute anticly measures, one violation for for the failure to have permanent staris in place at a building that was six stories and over forty fest tail, one violation for the failure to provide a pre-shift satisfy meeting, and one violation for the presence of shoring that was not in failer to provide a pre-shift satisfy meeting, and one sized. Four DOB Violations were also its auch. A Means and Methods must be provided to prevent a similar incident going forward.	ECB Violation	36366660,J/61L/62N/63P	1110818CE08MA01/02/03/04	NB	121190852	Other Construction Related Incidents	27E79 PROPERTY LLC	PRESS BUILDERS INC
2/2018	Manhattan	209	EAST 19 STREET	0	1 A DOB inspector reported that a worker was using a handheld grinder to cut an T-Beam while attempting to dismantie a pipe scaffold when he lost his ging no he ginther and dropped the grinder onto the lower portion o his leg. The worker suffered a three inch wide laceration. Parametics were called and the worker was taken to a nearby hospital in an ambulance. An Aggravated Level 2 ECB Violation was issued for a failure to safegurad all persons and properly affected by construction. A a partial Stop Work Order (PSWO) and a DOB Violation were also issued.		36365388X	111218CERDV01			Other Construction Related Incidents	NOT ON FILE	SPRING SCAFFOLDING LLC
2/2018	Queens	23-15	44 DRIVE	0	1 The Site Safety Manager reported that a worker was handling planks off of a truck when he suffered a laceration to his finger. The worker went to an emergency care center.	No Dispatch			NEW BUILDING	420655954-01-NB	Other Construction Related Incidents	BGY CITYVIEW LLC	NEW LINE STRUCTURES & DEV
4/2018	Manhattan	138	EAST 50 STREET	0	emergency user correspondent that a worker was waiking on a loading dock when he tripped and fell approximately four feat to the ground. The worker suffered a minor hp ingluy and was taken to a hospital. The loading dock was created a tripping hazard. A Tel CED Violation was insued for a failure to maintain safe operations. A partial Stop Work Order (PSWO) was issued for work on the loading dock.		35367164P		NB	121186028	Worker Fell	60 LEX DEVELOPMENT LLC	Tishman Construction
4/2018	Manhattan	40	IRVING PLACE	0	1 A DOB inspector reported that a worker climbed onto the "x"-Brace of a supported scaffold when he fell backwards approximately four elect. The worker hunt his back, but was found conscious and on his feet. The worker was taken to a hospital. The worker was in the worker was taken to a hospital. The worker was in the the hour O/SHA cards. No hazardous conditions were observed at the site. No enforcement action was necessary.	No Action Necessary			A2 - ALTERATION TYPE 2	103647706	Warker Fell	DEPARTMENT OF EDUCATION	ADAM'S EUROPEAN CONTRACTI
16/2018	Manhattan	525	WEST 25 STREET	0	The Construction Superintendent reported that a worker was staking plywoods on the fifth floor when he slipped and fell on the floor. The worker was found conscious responded to the incident and visited the site and concluded that the incident courced as the result of a worker's error. No enforcement action was necessary.	No Action Necessary			ALT-1	122928289	Other Construction Related Incidents	511 WEST 25TH STREET OWNER LP	INTEGRITY CONTRACTING INC.



cident Date	Borough	Address Number	Street	Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/16/2018	Manhattan	200	AMSTERDAM AVENUE	0	1 The Site Safety Manager reported that a plumber was installing a pipe that was approximately eight feet long and with a four inch diameter. The pipe was about a foot off of the floor when a got split from another pipe and fell on the plumber's hand. The plumber did not appear to have any visible injuries, but his hand let numb. The worker went to an urgent care center on his own.	No Dispatch			NEW BUILDING	122887224	Material Fell	AMSTERDAM AVENUE REDEVELOPMENT	PAVARINI MCGOVERN LLC
6/2018	Brooklyn	61	MOFFAT STREET	0	1 The Construction Superintendent reported that a worker was cutting a piece of lumber with a circular saw when the saw kicked back and the worker suffered a cut to his right thigh. The worker was transported to a hospital by ambulance. The worker was released after treatment.	No Dispatch			NEW BUILDING	321189940	Other Construction Related Incidents	1411 BUSHWICK AVENUE DEVELOPME	M-TEK DEVELOPMENT LLC
/17/2018	Manhattan	77	CHARLTON STREET	0	1 A DOB inspector reported that a flag man was on the sidewalk between two concrete planters that were what was parked in the parking law was walling to pull into the work area. The driver of the concrete truck began to back up when the flag man stepped into the stareet to direct the delivery. The flag man was struck by the truck and fell, and the concrete truck may over the worker's legs. There were three flag man on each side of the side at the time of the incident. The worker was transported to Bellevue Hospital. The worker's condition was not known at the time of negacion. The work at the site was being performed under an after-bours variance. No enforcement action was deemed necessary at the time of inspection.				NEW BUILDING	121187731-01-NB	Worker Fell	TOLL NY IIL P.	TOLL &C LLC
17/2018	Queens	36-18	MAIN STREET	0	1 The Site Safety Manager reported that a worker was moving duct work when a piece of duct work cut into his hand. The worker went to an urgent care center.	No Dispatch			NB - NEW BUILDING	401816923	Other Construction Related Incidents	134-22 35TH AVE., LLC	W & L GROUP CONSTRUCTION
/21/2018	Brooklyn	138	WILLOUGHBY STREET	0	1 The Site Safety Manager reported that a worker was on a man lift by himself when he went up and hit his head. The worker was taken to a hospital by ambulance. The worker was okay and was responsive. A DOB inspector responded to the incident and issued three ECB Violations: one violation for the failure to provide safety measures for man lift operations, one violation for there being no log book for the manufacture's specifications, and one violation for the presence of an inadequate Controlled Access Zone. A partial Stop Work Order (PSWO) and there DOB Violations were also issued. A Means and Methods for the safe operations of a man lift must be provided.	ECB Violation	35367517L18N,19P	112118CE02LJ01,02.03	NB	321197085	Other Construction Related Incidents	NYC HPD	Lend Lease Construction
21/2018	Brooklyn	1618	BROOKLYN AVENUE	0	1 The Site Safety Manager reported that flag men were directing traffic when an eldery man driving a vehicle moved forward and hi at flaggar. The flagger suffered a back injury and went to a hospital. The New York City Police Department was on the site to make reports, as this was a vehicular accident.	No Dispatch					Other Construction Related Incidents	JACQUES, FRANCINE JEAN	
221/2018	Brooklyn	859	MYRTLE AVENUE	1	0 A DOB inspector reported that there was a load of prefabricated wood panels that were delivered by a boom truck at the fourth floor of the site, near the edge of the site. The prefabricated wood panels were along a foldit to move the panels toward the center of the site. The were site to the site of the site of the site of the was about 16's 10' was pilod on a forkit. A particular position while another worker was walking by, and the workers that were using at forkith tost control, which caused the forkith and the panel to fail down and cush the worker that was walking by. The injured worker was taken to a hospital, where he succumbed to his injures. The vorkers coreladed the forkith, which caused the forkith and wood panel to fail. A DOB Violation was issued for a failute to safeguard. A full Stop Work Order (FSWO) was issued for the entire site.	DOB Violation		112118CE301RV	NB	321042590	Material Fell	CASCADE 553 LLC	Empire ID construction
21/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker was climbing a ladder with materials in hand when he lost his balance and fell approximately five feet onto his back. The worker was found conscious and was taken to a hospital by ambulance for further evaluation.				NB	121328205	Worker Fell	SOLOVIEFF REALTY CO. II, LL.C	LENDLEASE(US) CONSTRUCTION
23/2018	Bronx	1471	WATSON AVENUE	0	1 The Site Safety Manager reported that an emergency sidewalk shed was being taken down when a worker hit a piece of concrete with a hammer and a small particle fell into the worker's eye. The worker went to a hospital to receive a check up.	No Dispatch			EQ-SH	240054418	Scaffold/Shed/Fence/Shoring/Installation	NYC HOUSING AUTHORITY	SHARAN BUILDERS INC
26/2018	Staten Island	55 B	RICHMOND TERRACE	0	<ol> <li>The Site Safety Manager reported that a worker was not paying attention when the worker stepped on a piece of waterproofing sheet and suffered a twisted ankle. The worker was transported to a hospital by ambulance for a check uo.</li> </ol>				NEW BUILDING	520208828	Other Construction Related Incidents	ST. GEORGE OUTLET DEV LLC	EMPIRE OUTLET BUILDERS



	Borough	Address Number		Fatalities Injuri		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	25	PARK ROW	0	A DOB inspector reported that there was equipment on a truck that was being prepared to be hotstet by a crane when a worker got his finger caught in a chokelsing that was being used to secure the equipment. The worker went to a clinic on his own. An ECB Violation and a DOB Violation were issued for the failure to perform a pre-task safety meeting. A partial Stop Work Order (FSWO) was used for material handling and picking operations.	ECB Violation	35363682R	112618CE01MS01			Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	URBAN ATELIER GROUP LLC
/26/2018	Brooklyn	1595	BROADWAY	0	<ol> <li>The Construction Superintendent reported that a window installer cut his pinky by glass. The worker was taken to a hospital by ambulance. The worker received a few stitches and then returned to work.</li> </ol>	No Dispatch			NEW BUILDING	321651164	Other Construction Related Incidents	1595 BROADWAY LLC	TRIPLE C BUILDERS LLC
27/2018	Bronx	2065	RYER AVENUE	0	1 A DOB inspector reported that the job site fence collapsed and struck a pedestriam that was passing by the site. The Site Safety Coordinate stated that the site site Site Safety Coordinate stated that the was issued for a failure to maintain safety measures at the site. A full Sop Work Order (FSWO) and a DOB Violation were also issued.	ECB Violation	35366848L	112718CE05WZ01			Other Construction Related Incidents	RYER AVE HOLDINGS, LLC	UA BUILDERS CORP
27/2018	Manhattan	22	NORTH LOOP ROAD	0	<ol> <li>The Site Safety Manager reported that a worker felt pain in his arm while working with a hammer. The worker went to a City M.D.</li> </ol>	No Dispatch				_	Other Construction Related Incidents	NOT ON FILE	Hunter Roberts
/27/2018	Manhattan	515	WEST 36 STREET	0	1 A DOE inspector reported that the fence gate disloged from the finespot and struck predication. The job cits fence was not constructed as per the approved design drawings at the site. An ECE Valiation was issued for a failure to safeguard the public. A partial Stop Work Order (PSWO) and a DOB Violation were also issued.		35351545M	112718CE04JK01			Other Construction Related Incidents	HUDSON 36 LLC	HUDSON 37 LLC
/28/2018	Brooklyn	266	KENT AVENUE	0	1 A DOB inspector reported that a worker was using a liader to go up from the twerty-duft floor to the heverty-fifth floor. The lader was installed on a Doka form works system on the elevator shart. The ladder was narrow and there was an ib beam above the opening where the ladder enters the upper floor. The worker's head hit the beam, he suffered a neck cramp, and fell three esteps from the ladder. The Worker was found conscious, but was suffering from back pain and a stift hore beam of a suffering from back pain and a stift to be an dward in which has for the DEB Volvent was done which worker was found conscious, but was suffering from back pain and a stift hor be and used in the Abab. The DEB Volvent were issued one violation for the failure to safeguard persons and property, as a worker was injuried dus to an improperty placed lader, one violation for the failure to saccurely install horizontal netiting, as the nets were tied to formwork resons. The Cell Svolvent PSWOW was also lasker. The Generator is no provide a Means and Methods for the safe operation of the job and to maintain adequate genes.		36366994J 35366996L, 35366996N, 36366997P		NEW BUILDING	320916407	Worker Feil	260 KENT LLC	260 KENT CONSTRUCTION LLC
9/2018	Brooklyn	41	BLUE SLIP	0	1 The Site Safety Manager reported that a worker was mixing mottar when his finger got cut in the mixer. The worker was found conscious and was taken to a hospital by ambulance to receive stitches.				NB	320597449	Other Construction Related Incidents	BOP GREENPOINT F LLC	T.G NICKELS AND ASSOCIATES
29/2018	Manhattan	1	WALL STREET	0	1 The Site Safety Manager reported that a worker was pulling netting when he felt pain in his right shoulder. The worker got an ice pack and then went to a City M.D. to be further evaluated.	No Dispatch			ALT 1	121190086	Other Construction Related Incidents	NOT ON FILE	JT MAGEN CO INC
/29/2018	Manhattan	180	BROOME STREET	0	b) De nulline evaluated: 1 A DOB inspector reported that the foreman of a stripping operation was standing below while workers were removing Doba beam. The fight shoulder by a failing Dota beam. The foreman was taken by antibulance to a Dota beam. The foreman was taken by antibulance to a Dota beam. The foreman was taken by antibulance to a lissued one violation for a failure to institute safely measures, as a Means and Methods was not provided for the stripping operations, and one violation for the concrete contractor at this sile being in possession of expired worker's compensation and disability insurance. Two partial Sigo Work. Orders (PSWO) and two DDB Violations were issued. A Means and Methods for stripping operations and valid insurance must be provided.	ECB Violation	35363686Y-DISABILITY AND COMP INS EXPIRED. ECB#35363687X- SAFETY MEASURES	112918CE03MS01/02	NB	121191110	Other Construction Related Incidents	SITE 4 DSA OWNER LLC	T.G. NICKEL & ASSOCIATES



cident Date	Borough	Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhatian	316	WEST 135 STREET	0	A DOB engineer reported that at a three story building that feature a celler a, one story extension, and an active demolition permit, the exposure three wall between the third story section and the first story section collapsed, and the impact resulted in the failure of the acjousure two trick wall. The wall collapsed into the acjousure two trick wall. The wall collapsed into the acjousure two trick wall. The wall collapsed into the acjouser the volt wall. The wall collapsed into the acjouser the volt of the wall. A power that the trick wall the wall collapsed into the acjouser the volt of the wall. A power that the trick wall the wall collapsed into the acjouser the volt of the wall. A power the trick wall the wall the trick wall the wall collapsed into the acjouser the volt of the wall. A power the trick wall the wall the trick wall. The wall the trick wall t	n 3 3	353669228				Meterial Foll	MT ARARAT BAPTIST CH	Granite Environment
1/30/2018	Manhattan	217	WEST 57 STREET	0	1 The Site Safety Manager reported that a worker was drilling to install duct work when a piece of metal shaving got into his eye. The worker was taken to a nearby clinic to have his eye washed. The worker then returned to work.						Other Construction Related Incidents	SMITELL SPONSOR LLC	Lend Lease
/30/2018	Manhattan	500	WEST 25 STREET	0	1 The Site Safety Manager reported that a worker was bending rebars when he was struck on his knee by rebar, which caused a cut. The worker was found conscious and was taken to a hospital by ambulance to be further evaluated.	No Dispatch			NB	121190932	Other Construction Related Incidents	500 W25TH OWNER LLC	AVO CONSTRUCTION LLC