

PROJECT LOCATION:

541 BROADWAY

BLOCK: 498

LOT: 18

PERMIT FOR:

- **ENTRANCE ACCESSIBILITY RAMP INSTALLATION**
- **BUTTON LEGALIZATION**
- **DIAMOND PLATE LEGALIZATION**
- **INTERCOM LEGALIZATION**

PRESENTATION:

**LANDMARKS PRESERVATION COMMISSION
CERTIFICATE OF APPROPRIATENESS
APPLICATION**

DATE:

APRIL 5, 2016




HOWARD L.
ZIMMERMAN
ARCHITECTS PC

SoHo-Cast Iron



541 BROADWAY



1910
Courtesy Cathy Weis Projects
<http://www.cathyweis.org/weisacres/about/>



1982
City Museum of New York
[http://collections.mcny.org/Collection/\[537-541,-543-and-545-Broadway-\]-24UAKVGZUQN.html](http://collections.mcny.org/Collection/[537-541,-543-and-545-Broadway-]-24UAKVGZUQN.html)




2016

498-20, 18.
#537-539, #541 (through to Mercer)
Commenced: 9/1/1868
Completed: 4/30/1869
Architect: Charles Mettam
Original Owner: Gilsey & Beekman
Original Function: Store
Facade: Iron
5 stories; 8 bays
Comments: Ground floor altered, 1883
alteration to #537-539 as a result
of fire.

Nos. 537-539 and 541 are two picturesque cast-iron buildings with a common facade designed by Charles Mettam in 1868 for Gilsey and Beekman. The five-story, eight-bay facade is defined by a rhythmic series of columns separating the windows. The columns are plain, but have Corinthianesque capitals. A rope-molding edges the windows. Above the columns a rosette motif decorates the spandrels. A balustrade adds interest to the base of the second-story windows on No. 541. After a fire in 1883 the balustrade was removed from No. 537-539, and the first floor entablature was replaced by a highly foliated one, also of cast iron. The ground floor has been completely altered. The most eye-catching element of the eight-bay facade is the main entablature and roof line. A panelled frieze is interspersed by scrolled brackets supporting the cornice with its modillions. A large pediment with an urn at its peak crowns the two central bays. Two smaller curved pediments emphasize the side bays. Two urns at the ends of the main pediment and another two above the cornice terminal blocks at the ends of the facade further emphasize the roof line. The urns themselves have unique center finials.

*EXCERPTS FROM 1973
SOHO CAST IRON HISTORIC DISTRICT DESIGNATION REPORT*




541 BROADWAY



541 BROADWAY


CONTEXT





541 BROADWAY
ENTRANCE RAMP INSTALLATION

EXISTING CONDITIONS




1 SITE PLAN
1/4" = 1'-0"



A SITE PHOTO 1



B SITE PHOTO 2




C SITE PHOTO 3

LOCATION OF WORK




541 BROADWAY
ENTRANCE RAMP INSTALLATION

PLANS



1 EXISTING PLAN
1/4" = 1'-0"


BROADWAY



1 PROPOSED PLAN
1/4" = 1'-0"

BROADWAY






1 PROPOSED PLAN
1/4" = 1'-0"




541 BROADWAY
ENTRANCE RAMP INSTALLATION

PLANS



BROADWAY ELEVATION - EXISTING




BROADWAY ELEVATION – PROPOSED RAMP




541 BROADWAY
ENTRANCE RAMP INSTALLATION

ELEVATIONS




BROADWAY ENLARGED ELEVATION – EXISTING




BROADWAY ENLARGED ELEVATION – PROPOSED RAMP







1 RAMP SECTION A-A
1/2" = 1'-0"




2 RAMP SECTION B-B
1/2" = 1'-0"



NEW DIAMOND PLATE TO BE UNFINISHED STEEL TO MATCH EXISTING.



541 BROADWAY – EXISTING CONDITIONS



50 WOOSTER ST. – EXAMPLE OF STEEL HANDRAIL STYLE SIMILAR TO PROPOSED



45 CROSBY ST.



35 MERCER ST.



49 MERCER ST.



50 HOWARD ST.



541 BROADWAY
ENTRANCE RAMP INSTALLATION

SOHO CAST IRON HISTORIC
DISTRICT RAMP PRECEDENTS



541 BROADWAY – LOOKING SOUTH



541 BROADWAY – LOOKING NORTH






**SIDEWALK VAULT - AFTER COLLAPSE - (JULY 2001)
NOTE DAMAGED VAULT LIGHTS & STEPS.**



**SIDEWALK VAULT- AFTER COLLAPSE (JULY 2001)
NOTE DAMAGED VAULT LIGHTS.**



WEST SIDE OF BROADWAY –
LOOKING SOUTH FROM PRINCE STREET



EAST SIDE OF BROADWAY –
LOOKING SOUTH FROM PRINCE STREET



541 BROADWAY
DIAMOND PLATE LEGALIZATION

CONTEXT



BROADWAY ENTRANCE – ASSISTANCE PUSH
BUTTON AS CURRENTLY INSTALLED



BROADWAY ENTRANCE – PROPOSED BUTTON
PAINTED TO MATCH EXISTING BUILDING
EXTERIOR COLOR



541 BROADWAY
BUTTON LEGALIZATION

EXISTING & PROPOSED CONDITIONS



MERCER STREET ENTRANCE –
INTERCOM AS CURRENTLY INSTALLED



541 BROADWAY
INTERCOM LEGALIZATION

EXISTING LOCATION



MERCER STREET ENTRANCE –
INTERCOM PROPOSED RELOCATION



541 BROADWAY
INTERCOM LEGALIZATION

PROPOSED RELOCATION

THANK YOU



HOWARD L.
ZIMMERMAN
ARCHITECTS PC