

Monthly Accident Details: January 2018

		Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2018	Manhattan	13	EAST 7 STREET	0	1 The New York City Police Department reported that an exterminator fail into a six for deep excavation in the basement. A DOB inspector reported that the worker suffered minor injuries and was taken to Bellevue Hospital and that there was unpermitted execution work being performed in the basement. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard and	k 2	35309613X		No Permit	No Permit	Worker Fell	TRIAD CAPITAL, LLC	No Permit
/2018	Manhattan	269	WEST 87 STREET	0	work without a permit. A full Stop Work Order was issued. 1 The Site Safety Manager reported that a worker was	ECB Violation	35285606Y, 35285607X, 35285608H, 35285609J				Worker Fell	RIVERVIEW OPERATING CO., LLC	Leeding Builders Group LLC
					cleaning a platform from a multipoint scaffold when he slipped and fell five feet onto the ground, hitting his right elbow. An ambulance was on site. Four ECB Violations and a partial Stop Work Order were issued.								
2018	Manhattan	430	EAST 58 STREET	0	1 The Site Safety Manager reported that a worker got his hand stuck between a steel plate and a frame and got two of his fingers crushed. The worker was sent to Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	SUTTON 58 HOLDING COMPANY LLC	
/2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that a worker was loading garbage into a truck when he slipped on snow and hurt his arm. The worker walked to urgent care.	No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
/2018	Manhattan	301	FREEDOM PLACE SOUTH	0	and much is and in the worker waked to update care. 1 The Site Safety Coordinator reported that a worker was unloading glass from a crate when a piece of glass fell and injured his leg. The worker was taken to a hospital. The extent of the worker's injuries was not known.	No Dispatch			NEW BUILDING	121192501-01-NB	Worker Fell	301 FREEDOM PLACE SOUTH, LLC	SCIAME CONSTRUCTION LLC
2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker on the twenty fourth floor slipped on a patch of ice and hurt his shoulder. An ambulance was called to the site. A DOB inspector responded to the incident and reported that diamond plates on the outside of a hoist had water and ice on them, which caused the worker to slip. An ECB Viralinion and a DOB Viralenou were issued.	ECB Violation	35301051R	010618BS02DH03			Worker Fell	G & M REALTY, L.P.	
/2018	Manhattan	40	10 AVENUE	0	1 The Site Safety Manager reported that a worker slipped on a second floor concrete deak. Inaded on his back, and hurt his shoulder. The worker slipped because of snow. The worker walked to a City MD. A DOB inspector visited the site and confirmed that the deck was covered with snow, which caused the worker to fall. An ECB Violation, a DOB Violation, and a partial Sity Work Order		35301164N	010918BS02VP01			Worker Fell	40-56 TENTH OWNER LLC	
2018	Manhattan	400	WEST 33 STREET	0	were issued. 1 The Site Safety Manager reported that a worker was handing down a screw-jack to another worker when the screw-jack slipped out of his hands and hit the other worker. The worker suffered a minor injury and went to a hospital by amoulance for a check up. A DOB inspector issued an ECB Violation, a DOB Violaton, and a partial Partial		35301055Y	010918BS04DH03			Material Fell	BOP NE LLC	
/2018	Manhattan	118	FULTON STREET	0	Ston Work Order 1 A DOB ispector reported that a worker attempted to move an "A"-Frame cart that was loaded with about twenty flat stock metal sheets when the metal sheets fell onto his leg. The worker may have possibly suffered a broken leg. An EMT was on site. An ECB Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Methods		35300526R				Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	
0/2018	Staten Island	55	RICHMOND TERRACE	0	for cafe nonations 1 The Site Safety Manager reported that a worker slipped on ice. An ambulance was called. A DOB inspector reported that the worker slipped on ice that was located in an area that was closed off and where there was no work in progress. No enforcement action necessary.	No Action Necessary					Worker Fell	ST. GEORGE OUTLET DEV LLC	
/2018	Queens	27-17	42 ROAD	0	1 The Side Safety Manager reported that a worker was installing sheet rock when he cut his left hand on a metal duct. The worker went to urgent care with another	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
2018	Manhattan	130	EAST 82 STREET	0	worker. The Site Safety Coordinator reported that an electrician was pulling cables in a box when he pulled his hand back and cut it on a piece of Chicago Bar. The incident occurred on 1/10/2018, but was not reported until 1/11/2018. The worker were to a doctor on his own. 	No Dispatch			NEW BUILDING	121328027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
/2018		305	EAST 61 STREET	0	1 The Site Safety Manager reported that a worker tripped over a board that was on the floor and twisted his right ankle. An ambulance was called to the site and took the worker to a hospital.						Worker Fell	305 EAST 61ST STREET GROUP LLC	
/2018	Manhattan	151	MAIDEN LANE	0	1 A DOB inspector reported that a worker was using an "A-"Frame cart to move scaffolding elements when he twisted his wrist while pulling the cart. The worker did not want to go in an ambulance and went to see a doctor on his own. There were no unsafe or hazardous conditions at the work area. No enforcement action was necessary.				New Building	121186769	Other Construction Related Incidents	151 MAIDEN LLC	PIZZAROTTI IBC LLC
1/2018	Queens	27-13	21 STREET	0	at the work area. No enforcement action was necessary 1 The Site Safety Manager reported that a carpenter was hitting a nail when the nail popped out and hit the worker in the face. The worker has no visible cut or injuries. An	No Dispatch			NEW BUILDING	420993740	Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	DISANO DEMOLITION CO, INC



Monthly Accident Details: January 2018

		Address Number		Fatalities Injurie	es EOC Final Description		ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/11/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that a pedestrian	ECB Violation	35300326M	011118BS05MA03			Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	
					stepped on a piece of plywood under the upper sidewalk and slipped, injuring his right ankle. The pedestrian went to see a doctor on his own. An ECB Violation was								
1/2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager and a DOB inspector reported	No. Antina Managana			New Building	121333440	Worker Fell	CP V TS FULTON OWNER, LLC	CP V TS FULTON OWNER LLC
/11/2018	Mannattan	110	FULTON STREET	0	that a carpenter was standing on an "A" Frame ladder to				New Building	121333440	WORKER Fell	CP V IS FOLION OWNER, LLC	CP V IS FULTON OWNER LLC
					remove the door frame from an electrical closet on the								
					51st floor when a piece of plywood that was behind the								
					door frame came loose and hit him in the shoulder,								
					causing him to fall off of the ladder. The worker complained of back pain and was transported to a								
					hospital by ambulance. A DOB inspector reported that								
					there were no unsafe or hazardous conditions at the								
					1 The Site Safety Manager reported that a worker was								
/12/2018	Manhattan	45	PARK PLACE	0	 The Site Safety Manager reported that a worker was pumping concrete into a wheelbarrow when the concrete 	ECB Violation	35263168X	011218CERMR01	NEW BUILDING	121185635-01-NB	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
					pump shifted and snagged his finger between the pump								
					clamp and the concrete cleaning basin, causing a large								
					cut. The worker was taken to a hospital. A DOB								
					inspector reported that according to the inspection of the								
					logs, the injured worker did not attend the concrete pre- pump meeting and did not know why he was part of the								
					operations. An Aggravated 2 ECB Violation, a DOB								
					Violation and a partial Stop Work Order were issued								
/15/2018	Manhattan	590	EAST 83 STREET	0		ECB Violation	35294740J	011518CERFC01	Alt 1 NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
					performing waterproofing work inside of a high concrete tank. When the worker was using a chemical sealant to								
					waterproof the inside of the tank, he became								
					overwhelmed by the fumes and passed out. The worker								
					was taken to a hospital by an amulance. An ECB								
					Violation, a DOB Violation, and a partial Stop Work Order								
/15/2018	Manhattan	130	EAST 82 STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch			alt 1 NB	121325027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
				-	cutting a piece of aluminum with a saw when the								
					aluminum got caught in the saw and pierced his hand.								
/15/2018		53	WEST 53 STREET		The worker took a cab to a hospital.				alt 1 NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	
/15/2018	Manhattan	53	WEST 53 STREET	0	1 The Site Safety Manager reported that a worker pulled his groin while lifting a pipe. The worker went to a	No Dispatch			ait 1 NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LEND LEASE (US) CONSTRUCT
					MedRite.								
1/16/2018	Brooklyn	179	THROOP AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	NYC HHC	1
					unloading a piece of pipe scaffold off of a truck when he								
					lost control of the piece and the section fell onto his left								
/17/2018	Manhattan	125	GREENWICH STREET	0	leg. The worker was taken to a hospital by a friend. 1 The Site Safety Manager reported that a piece of	ECB Violation	35300553M				Other Construction Related Incidents	VS 125 LLC	
	in a nation	120	oncentron officer	Ŭ	plywood fell onto a worker's hand during a stripping	LOD Holdson						10 120 220	
					operation. There were two workers working one above								
					the other, and the piece of plywood fell from above onto								
					the worker below. An ambulance was called. An ECB Violation and a partial Stop Work Order were issued. The								
					General Contractor at the site is to provide a Means and								
					Methods								
/17/2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker was				NEW BUILDING	420651912	Other Construction Related Incidents	G & M REALTY, L.P.	G & M REALTY L.P
					unpacking windows from a crate and was using a 2 X 4 piece of wood as a lever to move the crate when the								
					piece of wood as a level to move the crate when the								
					a scratch. An ambulance was called and the worker								
					walked to the ambulance to do for a check up								
/17/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that an iron worker	No Dispatch			NEW BUILDING	121186849	Mechanical Construction Equipment	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
					was using a grinder to cut a piece of metal bar when the grinder kicked back and caused a cut to the worker's								
					thumb. The grinder had all of its safety guards in place.								
					The worker went to an urgent care facility for treatment								
/18/2018	Manhattan	650	5 AVENUE	0	1 The Site Safety Manager reported that a flagger was	No Dispatch					Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
					almost struck by a vehicle in the middle of the street and that he twisted his right ankle while moving out of the								
					way. The flagger went to a hospital.								
/18/2018	Manhattan	200	AMSTERDAM AVENUE	0	1 The Site Safety Manager reported that a worker was	ECB Violation	3530559M 353055		NB	122887224	Mechanical Construction Equipment	AMSTERDAM AVENUE	Marc Depaul
					unhooking the chain from an excavator that was lifting							REDEVELOPMENT	
					oxygen tanks when his gloves got stuck between the								
					chain and the excavator's hook, pinching the worker's								
					finger. The worker was taken to a hospital by a co- worker. Two ECB Violations and a full Stop Work Order								
					were issued. The contractor at the site was directed by a								
					DOB inspector to provide a Means and Methods to								
/18/2019	Brooklan	1601	KINGS HIGHWAY		DOB inspector to provide a Means and Methods to nerform lifting operations 2 A DOB inspector reported that a vahiala atruat a mention	ECB Violation	35300560K				Other Construction Related Inside-t-	KINGSWAY REALTY U.C.	
/18/2018	Brooklyn	1601	KINGS HIGHWAY	0	2 A DOB inspector reported that a vehicle struck a manlift	ECB Violation	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
1/18/2018	Brooklyn	1601	KINGS HIGHWAY	0	DOB inspector to provide a Means and Methods to nerform tiffing negations 2 A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not filled with water and a flagge		35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
/18/2018	Brooklyn	1601	KINGS HIGHWAY	0	nerform lifting operations 2 A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not filled with water and a flagge was not present. The manifit was not damaged, but one		35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
/18/2018	Brooklyn	1601	KINGS HIGHWAY	0	perform lifting nonerations. 2 A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not filled with water and a flagge was not present. The manifit was not damaged, but one of the workers complained of leg pain, and the other		35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
/18/2018	Brooklyn	1601	KINGS HIGHWAY	0	nerform litting overations. 2: A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not filled with water and a flagge was not present. The manifit was not damaged, but one of the workers complained of leg pain, and the other worker was shock up by the incident. Both of the		35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
/18/2018	Brooklyn	1601	KINGS HIGHWAY	0	nerform lifting coversions. 2 A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not filled with water and a flagge was not present. The manifu was not damaged, but one of the workers complained of leg pain, and the other workers was shook up by the incident. Both of the workers were sent to a hospital for a check up. An ECB		35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
	Brooklyn	3003	KINGS HIGHWAY	0	hardrom littino non-attions. 2: A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not tilled with water and a flagge was not present. The manifit was not damaged, but one of the workers complained of leg pain, and the other workers was shook up by the incident. Both of the workers was end to a hospital for a check up. An ECB Violation and a nartial Stron. Work Order ware issued 1 The Site Safety Manager reported that a worker twisted		35300560K				Other Construction Related Incidents Other Construction Related Incidents	KINGSWAY REALTY LLC	
				0	nerform litting overations. 2.1 A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not filled with water and a flagge was not present. The manifit was not damaged, but one of the workers complained of leg pain, and the other worker was shock up by the incident. Both of the Worker's were sent to a hospital for a check up. An EOB Violation and namiel Sirow Work Christer were issued 1 The Site Safety Manager reported that a worker twisted her ankle while pushing a min-dumpster. An ambulance		35300560K						
19/2018	Brooklyn	3003	WEST 21 STREET	0	hardrom littino overations. 2: A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not tilled with water and a flagge was not present. The manifit was not damaged, but one of the workers complained of leg pain, and the other workers was shock up by the incident. Both of the workers were sent to a hospital for a check up. An ECB Violation and a nartial Stron. Work Order were issued 1 The Site Safety Manager reported that a worker twisted her ankle while pushing a min-dumpster. An ambulance was called and took the worker to a hospital.	No Dispatch	35300560K				Other Construction Related Incidents	CONCERN SURF VETS PLACE HOUSIN	
/18/2018 /19/2018 /19/2018				0	nerform litting overations. 2.1 A DOB inspector reported that a vehicle struck a manifit with two workers in it that was parked in an occupied lane. The yodocks were not filled with water and a flagge was not present. The manifit was not damaged, but one of the workers complained of leg pain, and the other worker was shock up by the incident. Both of the Worker's were sent to a hospital for a check up. An EOB Violation and namiel Sirow Work Christer were issued 1 The Site Safety Manager reported that a worker twisted her ankle while pushing a min-dumpster. An ambulance	No Dispatch	35300560K						



Monthly Accident Details: January 2018

Incident Date	Borough	Address Number	Street	Fatalities	Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/19/2018	Manhattan	445	WEST 35 STREET	0	1	1 The Site Safety Manager reported that a worker was moving a wooden plank while taking down a single frame scaffold when he twisted his knee and complained of pain. The worker went to see a doctor on his own.						Other Construction Related Incidents	CARE REALTY CORP.	
1/19/2018	Brooklyn	19	KENT AVENUE	0	1	The Site Safety Manager reported that a worker was setting up a mobile crane when his finger got pinched between the hook of the crane and a road barrier, causing the finger to detach. A co-worker took him to a hospital. Five ECB Violations and a partial Stop Work Order were issued.	ECB Violation	3505625p, 26r, 27z, 28k, 29m		CRANE NOTICE	871 17	Mechanical Construction Equipment	19 KENT ACQUISITION LLC	ALL ISLAN MASONRY & CONCRETE
1/22/2018	Queens	29-22	NORTHERN BOULEVARD	0	1	1.4 DOB inspector reported that a worker was pushing an "A"-Frame cart that was loaded with stone when the cart overturned, causing stone to fail onto the worker's foot and possibly breaking the foot. An EMT was on site. An ECB Violation and a partial Stop Work order were issued. The General Contractor is to provide a Means and Method's and a Tool Rox Talk.		35289063P				Material Fell	QSB NORTHERN LLC	