

Lafayette Ave and Morrison Ave

Pedestrian Safety and Access Improvements




Background

- Missing crosswalks across Lafayette Ave and Morrison
- New Assembly Member Crespo requested the intersection of Lafayette Ave and Morrison Ave studied for all way stop control and crosswalks
- Bio-swales and angled parking installed on the south side of Lafayette Ave in 2012
- High speeds: 85% of vehicles above the limit

Location

- At the entrance to Soundview Park and near the Bronx River Parkway
- Copied from SIP



Before: Lafayette Ave and Morrison Ave

Improvements

- All-way stop control and crosswalks at Lafayette Ave and Morrison Ave
- Install painted pedestrian spaces adjacent to the bioswale on Lafayette Ave and at the park entrance on Morrison Ave

Benefits

- Reduces speeding
- Safer, shorter pedestrian crossing