

# 568 Broadway

## SoHo-Cast Iron Historic District

Landmarks Preservation Commission


LPC 17-4909

Block: 511 Lot: 1

Request For Certificate of Appropriateness For:

Legalizing alterations to storefront without Landmarks  
Preservation Commission permit(s).

# Storefront – Corner View



# SoHo-Cast Iron Historic District



**568 Broadway**

## Designation Photograph



**568 Broadway**

## Store Opening December 1991 - Storefront



**568 Broadway**



## Broadway Storefront – Exterior View



Existing Conditions Photographs

**568 Broadway**

# Exterior Storefront View

Entry Door



Window Adjacent to Door Entry



Existing Conditions Photographs

**568 Broadway**


## Exterior View of Broadway Windows



Existing Conditions Photographs

**568 Broadway**

# Broadway Storefront – Interior Window Bulkhead



Existing Conditions Photographs

**568 Broadway**

## Broadway – Interior Storefront View

Left of Entry Door



Right of Entry Door



Existing Conditions Photographs

**568 Broadway**

## Prince Street – Corner View



Existing Conditions Photographs

**568 Broadway**

## Prince Street – Exterior View



Existing Conditions Photographs

**568 Broadway**

**Prince Street - Exterior Corner Window  
Above Subway Entrance – View into Store**



Existing Conditions Photographs

**568 Broadway**

**Prince Street – Center Window Video Graphic  
No View Into Store**




Existing Conditions Photographs

**568 Broadway**

**Prince Street – 3<sup>rd</sup> Window Exterior View  
No View Into Store**

**Exterior View**



**Exterior Bulkhead View**



Existing Conditions Photographs

**568 Broadway**

## Prince Street – Interior View of Windows Adjacent to Corner Window

2<sup>nd</sup> Window (Video Graphic) - No Exterior View



3<sup>rd</sup> Window – No Exterior View



Existing Conditions Photographs


# 568 Broadway

## Prince Street – Interior View of Windows Adjacent to Corner Window

2<sup>nd</sup> Window (Video Graphic) - No Exterior View



3<sup>rd</sup> Window – No Exterior View



Existing Conditions Photographs

# 568 Broadway

# Broadway & Prince Street – Interior View

Broadway Storefront



Broadway & Prince Street Corner



Existing Conditions Photographs

**568 Broadway**

# Corner of Prince Street & Broadway – Interior View of Windows

Broadway – Storefront Corner Window



Prince Street – Corner Window above subway entrance.  
View into store



Existing Conditions Photographs

**568 Broadway**

## Broadway – Interior Corner Window Bulkhead



Existing Conditions Photographs

**568 Broadway**