85 Sullivan Street, New York, NY Presentation to Community Board 2 Landmarks Committee 11 July 2019





S,g,V:a.

1

Sullivan-Thompson Historic District






Existing Context






Sullivan Street between Spring and Broome Streets, east








85 Sullivan Street: Historic Photos









85 Sullivan Street, New York NY

Typical Federal Characteristics



25 Harrison Street, 1804 (formerly 314 Washington Street) Individual Landmark, designated 1969

Typical historical characteristics:

- Red brick
- Modest decoration
- Six over six windows
- Brownstone window and door details
- Painted wood door trim and cornice, typically white
- Painted wood clapboard on exposed side facade (white) •






37 Charlton Street, 1820s Charlton-King-Vandam Historic District, designated 1966

Typical historical characteristics:

- White painted windows
- Light colored door trim and cornice
- Contrasting dark parinted wood shutters and door




20 Charlton Street, 1820s

Typical historical characteristics: • Painted wood clapboard at dormer windows (white)

Charlton-King-Vandam Historic District, designated 1966


Historic Precedents: Clapboard Siding



Unknown

Unknown







213-215 Elizabeth Street

Historic Precedents: Clapboard Siding



203 East 29th Street No Landmarks designation



Current Photos: Front Facade



85 Sullivan Street



83 Sullivan Street








Existing entry door



Existing windows



Proposed Restoration: Front Facade

Scope of work includes:

- Repointing of existing brick •
- New wood windows with historic profile and configuration
- New painted wood shutters
- Restoration of brownstone lintels and sills •
- Restoration of original wood door and lead transom ٠

T.O. BULKHEAD +44'-11" *T.O. ROOF* +36'-8" CORNICE TO REMAIN, REPAIR +23'-6" REMOVAL OF MTL CLADDING -AT LINTELS AND SILLS, CLEANING AND REPAIR AT **BROWNSTONE TO REMAIN** NEW PTD WD SHUTTERS AT *SECOND FLOOR* +13'-6" EXISTING TRANSOM WINDOW EXISTING DOOR TO REMAIN *FIRST FLOOR* +3'-6" GROUND +0'-0"

> REPAIR OF BROWNSTONE STOOP AS NEEDED; SCRAPE AND PAINT OF EXISTING IRON










Current Photos: Side Facade




metal panel, view from neighboring lot





metal panel, view from rear




metal panel, view from street

Current Photos: Clapboard Siding



view of clapboard siding under metal panel




view of clapboard siding under metal panel






typical height of clapboard siding

85 Sullivan Street, New York NY





view of flat siding at 83 Sullivan Street

Proposed Restoration: Side Facade

Scope of work includes:

S,g,V:a.

- Construction of new side wall
- New painted Hardie Board siding
- New parging at existing brick base



Current Photos: Rear Facade




Two-story extension at 83 Sullivan Street






Rear view of 85 Sullivan Street



probe at rear f under stucco



probe at rear facade showing evidence of clapboard siding

Proposed Restoration: Rear Facade


Scope of work includes:

- Construction of new rear wall
- New wood windows with historic profile and configuration
- New painted Hardie Board siding
- New parging at existing brick base









Sullivan-Thompson Historic District







Sanborn Maps: Original Back House



1894 Evidence of 3 story back house at rear of site








1922 Emergence of warehouses on west side of Sullivan Street

85 Sullivan Street, New York NY



2005 Gas station at west side of Sullivan Street 1970s through 2012

Sanborn Maps: Original Back House



1894 Sanborn Map






Three-story back house at 81 Sullivan Street




Proposed Alteration: Restoring the Back House



Historic Back House Location





Shifting of Back House to Comply with Current Regulations


85 Sullivan Street, New York NY

YARD COURT ADDITION ORIGINAL BUILDING

SMALL INNER

Proposed Back House Location

Existing Block Plan







85 Sullivan Street, New York NY

SULLIVAN STREET






























Existing Block Diagram






















































Heights of Neighboring Buildings






Proposed Alteration: View from Sullivan Street






Proposed Addition: Side Facade





85 Sullivan Street, New York NY








• T.O. ROOF +36'-8"

S,g,V:a.



Proposed Addition: Front and Rear Facades

Sullivan Street

i 🔺


T.O. BULKHEAD +44'-11" *T.O. PARPAPET* +39'-8" ROOF +36-2"


+25'-6"

SECOND FLOOR +15'-6"

FIRST FLOOR +5'-6"


GROUND +0'-0"





85 Sullivan Street, New York NY







– NEW STANDING SEAM MTL BULKHEAD AT STAIR TO ROOF

25

Proposed Alteration: Building Section




Proposed Alteration: Visibility Plan
















Proposed Alteration: Floor Plans





Cellar/Basement Level









Proposed Alteration: Floor Plans