

Local Law 78 of 2017 Incident Reports - June 2018

ID	Incident_Date_ Occured	House_ Num	Street_Name	Borough	Bin_Number	Incident_Description	Incident_Person_Reporting_By	Incident_Person_Reportin g_Org_Name	n_Reporting_B y_Type	Incident_Perso n_Reporting_B Control_Of_Other_ Desc	Incident_Pers on_In_Contro l_Of_Site	Incident_Violat ions_Issued_C ount	Incident_Location_ Union_Site_Desc	Incident _Injury_ Count	Incident _Fatality_ Count	Incident_Contra ctor_License_N umber	Incident_Contractor_Org_ Name
1000000021	6/1/2018 7:00	1	Liberty Plaza	Manhattan	1001068	Injured was lifting a piece of sheetrock when his back locked up.	General Contractor	J.T. Magen & Company Inc.	Business			0	Union	1	0	2571	J.T. Magen & Company
1000000022	6/1/2018 13:25	701	7Th Ave	Manhattan	1083718	While move a piece shower enclosure glass onto an A-frame the glass shattered.	Person in Control of Site				Site Safety Manager	0	Open Shop	1	0		Jerome Glass
1000000020	6/1/2018 13:25	701	7th Ave.	Manhattan	1083718	While moving a piece of shower enclosure glass onto an A-frame the glass shattered.	Person in Control of Site				Site Safety Manager	0	Open Shop	1	0		Jerome Glass
1000000025	6/4/2018 11:00	108	Leonard Street	Manhattan	1001835	Two sprinkler fitters were attempting to install their sprinkler pipe. The first step is to install the pipe hangers from the existing structural steel. They were working in a hall way and there was already pipe installed. The two men attempted to spread the pipe apart and the pipe clamp failed and cracked, causing the pipe section to fall. Kevin O'Melly was working on a man lift and the section of pipe fell and crushed his Right hand on the top rail of the lift.	Person in Control of Site				Site Safety Manager	1	Open Shop	1	0		Stat Fire Sprinkler NYC
1000000023	6/4/2018 14:15	233	W. 125th Street	Manhattan	1058657	Employee advised that he was in the process of stripping wooden forms / formwork from concrete structure, when he lost his footing / balance and stumbled and fell backwards, falling onto his "left hip". As a precaution, Employee was taken by ambulance to Harlem Hospital to be evaluated.	Subcontractor	Sky Materials Corp	Business			0	Non-Union	1	0	607190	Sky Materials Corp.
1000000024	6/6/2018 11:50	26-09	1st Street	Queens	4617681	The incident occur at 11: 50am today on the # 7 elevator Alfonso knight and Thomas Williams were working on the elevator platform install hoist way entrance. While the elevator was moving up the shaft, Mr knight had his right arm resting over the fall protection on the rear of the working platform his arm came in contact with one of the rail bracket. He suffered a laceration to his right forearm. Site medic cleaned and bandage the injury then sent him to Mount Sinai Hospital in Queens. He has since been released from the hospital with 12 stitches.	Person in Control of Site				Site Safety Manager	0	Non-Union	1	0		Rotavele
1000000026	6/8/2018 9:00	767	5th Ave	Manhattan	1036082	Worker Stated they walked into an object and struck their nose. Worker was performing waterproofing at time of incident on the Plaza level of the project. Project is an Alteration project of the Plaza level for existing building. Worker went to ER and LSSM #2505 notified DOB BEST squad of incident and spoke to DOB Inspector #2342 to report incident.	General Contractor	Turner Construction Company	Business			0	Union	1	0		Wolkow Braker
1000000027	6/8/2018 12:00	123	Linden Blvd	Brooklyn	3116661	Worker was installing a hoist machine. A rolling cart with a single piece of formwork fell into the hoist shaft and fell on top of the workers arm. The worker sustained no cuts, but was complaining of a sore, swollen wrist.	Person in Control of Site			Manager	Other	0	Open Shop	1	0		Cor Scaffolding
1000000028	6/13/2018 11:45	701	7TH AVENUE	Manhattan	1083718	Apparently, while working on the 29th floor cutting material with a utility knife/"breakaway knife", it broke and stabbed him in the left forearm. IP was treated at 42nd Urgent Care and returned to work.	Person in Control of Site				Site Safety Manager	0	Open Shop	1	0		Component Assembly Systems,Inc

Local Law 78 of 2017 Incident Reports - June 2018

ID	Incident_Date_Occured	House_Num	Street_Name	Borough	Bin_Number	Incident_Description	Incident_Person_Reporting_By	Incident_Person_Reporting_By_Type	Incident_Person_Reporting_By_Desc	Incident_Person_Reporting_By_Org_Name	Incident_Person_Reporting_By_Type	Incident_Person_Reporting_By_Desc	Incident_Violations_Issued_Count	Incident_Location_Union_Site_Desc	Incident_Injury_Count	Incident_Fatality_Count	Incident_Contractor_License_Number	Incident_Contractor_Org_Name
1000000029	6/18/2018 12:00	110	University Place	Manhattan	1009386	Allegedly during the process of cutting a ENT conduit for installation in the elevator lobby on the ninth floor Mr. Wanderson cut his left index finger with a sheetrock knife. He came to the Site Safety Managers office to report it escorted to ER by his co-worker as per his Foreman Martin.	Person in Control of Site						0	Open Shop	1	0		Team Electric
1000000030	6/20/2018 7:00	328	east 62nd Street	Manhattan	1044231	I was informed that the laborer was bringing down a jack hammer in to the trench that he and a co-worker were digging to expose a buried raker that was leaking water into the sub-cellar so it could be sealed and made water tight. Upon entering the excavation the worker was picking up the hammer with his back to the hole and slipped backward into the hole, falling on his back. A call to 911 went out and FDNY came and removed the worker and took him to Cornell Hospital (68th Street and York Avenue).	Person in Control of Site						2	Non-Union	1	0		North Eastern Precast LLC
1000000031	6/25/2018 15:00	505	West 43rd Street	Manhattan	1806360	While grinding concrete wall at the 14th floor North tower, worker horizontally extended himself past the step ladder, causing ladder and worker to fall less than 5' on same level	Person in Control of Site						1	Open Shop	1	0	614561	Perimeter Building System
1000000038	6/27/2018 9:30	170	jordalemon	Brooklyn	3391484	Jeffrey Brooks was at premises of 170 Jordalemon Brooklyn Ny in room F109 cutting a sprinkler pipe with sawzall while standing on a ladder. He fell down from a ladder from height of approximately 8'. Room was well lit. He was wearing hard hat and work boots.	Person in Control of Site						0	Non-Union	1	0	3021	Eurostruct inc