



The current proposal is:

Preservation Department – Item 9, LPC-22-08398

177 East 104th Street - 28th Police Precinct Station

House – Individual Landmark Borough of Manhattan

To Testify Please Join Zoom

Webinar ID: 867 3241 5521


Passcode: 532169

By Phone: 1 646-558-8656 US (New York)

877-853-5257 (Toll free) US

888 475 4499 (Toll free)

Note: If you want to testify on an item, join the Zoom webinar at the agenda's "Be Here by" time (about an hour in advance). When the Chair indicates it's time to testify, "raise your hand" via the Zoom app if you want to speak (*9 on the phone). Those who signed up in advance will be called first.





177 East 104th Street, Manhattan

Current Photo and Plot Plan

Roberta Washington . **architects pc** 8 West 126th Street New York , NY 10027

177 EAST 104th STREET

Hope Community, Inc 174 East 104th Street New York, NY 10029

Preservation/Renovation and Change of Use from Police Station to Community Facility:

- Selective interior demolition and removals with the restoration of selective historic architectural features
- New interior walls and finishes on ceilings and floors where existing cannot be restored
- Installation of new LPC conforming wood windows on primary facades; new aluminum windows with historic sizes and openings at other areas
- Two new fire-rated exit stairs within building and elevator
- Restoration of exterior metal railings, fencing, balcony and cornices
- Restoration of main wood entrance doors, sidewalls, steps and railings
- Installation of new floodproof protections as required
- New ADA compliant wheelchair lift in westside areaway




1940 NYC Tax Lot Photo

Architectural Scope of Work

Previously: 28th Police Precinct Station House

Proposed: Hope Community Hall

- The 28th Police Precinct station House, located on the north side of East 104th Street between Lexington and Third Avenues, was built between 1892 –1893 and based on the designs of architect Nathaniel D. Bush.
- The building, a five story plus cellar structure, is clad in red brick with grey granite detailing.
- The building was occupied as the Police Precinct until 1974. Since 1981, the building has been owned by Hope Community, Inc. a non-profit organization.
- The building was designated an individual land-mark on February 23, 1999.



Architectural Background

Roberta Washington . architects pc

8 West 126th Street


New York, NY 10027

177 EAST 104th STREET

Hope Community, Inc

174 East 104th Street








CELLAR



SECOND FLOOR



FOURTH FLOOR



FIRST FLOOR

THIRD FLOOR



FIFTH FLOOR

- The five-story building currently has one stair and no elevator
- The new layout will include two new fire stairs and an elevator
- The site is landlocked and there is no rear access or exit
- The existing front entrance access includes six steps from the sidewalk to the first floor entrance doors (outside entrance to the cellar will be through a new sidewalk-to-cellar stair)
- The new wheelchair lift will be located at the westside planter at the cellar level until 'called' to the sidewalk level for use.



Analysis of Building ADA Options

Roberta Washington . architects pc


8 West 126th Street

New York, NY 10027

177 EAST 104th SREET

Hope Community, Inc

174 East 104th Street



EXISTING CONDITIONS

PROPOSED SOLUTION

Wheelchair Lift as ADA Solution

Roberta Washington . architects pc

8 West 126th Street

New York, NY 10027

177 EAST 104th SREET

Hope Community, Inc

174 East 104th Street



IRON FENCE AND STONE BASE RESTORATION SCOPE

- 1. The existing metal fence located at the building's front will be restored while any elements beyond repair are replaced with in-kind materials .
- 2. The metal fence will be removed from its existing stone base and cleaned of rust, dirt and other particles from the fence elements. New and existing fence members will be painted with appropriate paint in its historically identified color.
- 3. The existing stone bases will be removed, cleaned and reset, with no stone placed at the wheelchair entrance.
- 4. The contractor will rebuild the fences to accommodate the new fence gates—for the wheelchair lift and for the entrance to the cellar stair—via the gate at the top of the new eastside stair.
- 5. The new wheelchair lift entrance gate operator system will be coordinated with the wheelchair lift manufacturer and the building's electronic access program.

Fence Restoration and New Gate Creation

177 EAST 104th STREET

Roberta Washington . architects pc

Hope Community, Inc


8 West 126th Street

174 East 104th Street


New York, NY 10027



Existing utility tunnel to street to be replaced with wheelchair lift



Existing Cellar Level



New Cellar Level



Proposed location for new wheelchair lift pit between historic iron fence and cellar windows

Wheelchair Lift Location Within West Areaway

Roberta Washington . architects pc

8 West 126th Street

New York, NY 10027


177 EAST 104th STREET

Hope Community, Inc

174 East 104th Street




Corner of west planter in front of window which becomes the new door.



Interior Elevation of Partial Cellar — Existing



Interior Elevation of Partial Cellar - Proposed



Interior cellar wall where previous window and tunnel will be replaced with floodproof door (with built-in window). The wheelchair pit will be outside, while the corridor leads to the elevator on the cellar level


New Wheelchair Access for Building

Roberta Washington . **architects pc** 8 West 126th Street

New York, NY 10027

est 126th Street 177 EAST 104th STREET

Hope Community, Inc 174 Fast 104th Street



ADA Wheelchair Lift Positions

Roberta Washington . architects pc

8 West 126th Street New York , NY 10027 177 EAST 104th STREET

Hope Community, Inc 174 East 104th Street

INCORPORATION OF WHEELCHAIR ACCESS INTO BUILDING FRONT SUMMARY

A 36" x 48" wheelchair lift is required to provide ADA/Wheelchair access to the building. The lift will travel from the sidewalk level to the Cellar floor level where a corridor connects with the building's elevator. The elevator is accessible to all floors.

The black wheelchair access door (the westside gate) will incorporate much of the existing wrought iron fencing which will be restored.

When not in use, the black wheelchair lift will rest at the cellar level six feet below. Only a portion of the wheelchair lift mast will be visible behind the wrought iron railing.



ADA/Wheelchair Access Lift

Roberta Washington . architects pc

8 West 126th Street

New York, NY 10027

177 EAST 104th STREET

Hope Community, Inc - Owner

174 East 104th Street





The current proposal is:

Preservation Department – Item 9, LPC-22-08398

177 East 104th Street - 28th Police Precinct Station

House – Individual Landmark Borough of Manhattan

To Testify Please Join Zoom

Webinar ID: 867 3241 5521

Passcode: 532169

By Phone: 1 646-558-8656 US (New York)

877-853-5257 (Toll free) US

888 475 4499 (Toll free)

Note: If you want to testify on an item, join the Zoom webinar at the agenda's "Be Here by" time (about an hour in advance). When the Chair indicates it's time to testify, "raise your hand" via the Zoom app if you want to speak (*9 on the phone). Those who signed up in advance will be called first.