New York City Housing Authority Department of

RECOVERY AND RESILIENCE

GOOD

SHEPHERD

SERVICES

We see what can be.

NYCHA'S SUPERSTORM SANDY RECOVERY PROGRAM





STATE OF BRIDE

Department of Youth & Community Development





Red Hook Project Progress (5 minutes)

Current Status (10 minutes)



~)

 \checkmark

Construction and Mitigation (10 minutes)

Careers in Construction (3 minutes)



Superstorm Sandy Investment


4 boroughs

35 sites

200+ buildings

60,000 residents

+\$3 billion of investment





	covery & Re nding and S	RESILIENCE \$1.3B			
Recovery Res			ence		
01	MEP Repairs	0 1.	Surge Protection		
02	Playgrounds	02.	Building Reinforcement		
03	. Site Restoration	03.	Infrastructure Upgrade		



Program Status

Status of Funds







2 developments complete




33 major projects in progress (234 buildings benefitting from active construction)

Work Completed

139	roofs replaced	142	new hot water
1,148	exterior lights installed	Γ 4	heaters installed new boilers set in
931	CCTV cameras	54	place
	installed	3	new boilers systems operational
33	entrance doors with		(200 apartments served)
	new security systems		full power
26	new MEP annex	99	emergency
	buildings completed		generators installed back up generators
50	new annex buildings	26	operational
0	in progress		operational







Red Hook East & West Progress Overview



Superstorm Sandy





Superstorm Sandy Damage





NYCHA R&R Scope of Work





Ongoing/Upcoming Construction Timeline


Building 27: Senior Center Renovation (Completed)

Phase 1: Roof Replacement

Building 29: Retail Space and Residential Units Renovation (Completed)

Phase 2 and 3: East & West Plants, MEP Pods and Distribution, Flood Protection, Basement and Site Restoration

Local Law 11: Repair of Building Facades









Current Status

Phase 1- Roof Replacement



Roof Restoration



Construction Progress



Roof Restoration






Substantially Complete Buildings: Red Hook East: 2-13 Red Hook West: 15-18



Construction Progress







Ongoing Work Red Hook West: Buildings **1W, 2W**, **3W, 19W - 25W**



Ongoing Work Red Hook East Buildings: **1E, 14E**






Additional Investment in Building Facades: Addressing Local Law 11Issues









Current Status Major Resilience Work







Plants, Pods, and Utility Distribution


























Mechanical, Electrical, and Plumbing Pods









4. Passive barriers deployed in floods





















Renovated Building Entryways







Construction Impact and Mitigation



Red Hook Site Plan





Site-wide Excavation Service Interruptions Entrance and Pathway Closures Tree Removal Parking Area Closures



Construction Impact



Site-Wide Excavation

Mitigation measures:



Ground Penetrating Radar (GPR) surveys

Utility mark outs

Coordination with utility company

Hand-digging to identify lines





Planned Service Interruptions

Mitigation measures:

1 2 3 Flyer postings and phone calls at least **48 hours in** advance

Coordination and planning

Accommodation spaces, as needed







Mitigation measures:

Site-specific pest management plan

EPA-approved pesticides, as needed

Bait traps

Daily cleanup of work areas





Temporary Entrance/ Pathway Closures

Mitigation measures:

Clear wayfinding signage

2

3

Flyer postings and phone calls at least **48 hours in advance**, **as needed**

Coordination with NYCHA property management and resident association





Dust-Producing Work


Mitigation measures:



Wetting of work surface areas, as needed

Utilization of HEPA vacuums

Protective tarp, as needed, to contain dust





Debris-Producing Work


Mitigation measures:



Sidewalk sheds

Fencing and netting

Plywood walls







Existing Parking to Be Affected





Parking After Construction





Tree Removal

Mitigation measures:

2

3

Removal total reduced from 572 to <u>457 trees</u>.

Original design scope at Red Hook included the removal of **572 trees**.

Significant effort was made to avoid tree removal, resulting in the saving of **115 trees**.

NYCHA strives for 1 for 1 replacement at the end of each project as space constraints and funding permit.

EXISTING TREES




MINIMUM FUTURE TREES CALIPER SIZE TED











Careers in Construction



Rebuilding Together

Program benefits:

OSHA 30 Certification	Personal Protective	
Direct Union Entry	Equipment	
	Visit Union Facilities	
Flagger & Scaffolding Certification	MetroCard Option	



Applicants must:

1	Must be an On-Lease NYCHA resident of a hurricane Sandy- impacted development	4	Must provide proof of address
2	Be 18 years of age or older	5	Must be interested in a union career in
3	Must possess High School Diploma or HSE		construction

For information:

Call (718) 488-8840 x18 or email phil.galeazzi@rebuildingtogethernyc.org





Let's Connect!

Meet us at the next Resident Association meeting (East and West) or reach us through phone or email!

NYCHA Recovery & Resilience Team

- disaster.recovery@nycha.nyc.gov
- 2 Hotline: 212-306-8532

3

Check out our website, too!

Tinyurl.com/SandyRecovery



Questions?



Stop by one of our tables:

- Recovery & Resilience
 - NYCHA Red Hook
 Property Management
- Adam's European Contracting
 Inc.
 - Rebuilding Together NYC



tinyurl.com/SandyRecovery



Disaster.Recovery@nycha.nyc.gov



212-306-8532



THANK YOU

NYCHA's Department of Recovery and Resilience Disaster.Recovery@nycha.nyc.gov - 212-306-8532 tinyurl.com/SandyRecovery



enne el li

Department of Youth & Community Development



