

Commissioner Janette Sadik-Khan New York City Department of Transportation Queens Borough Commissioner's Office, Office of Research, Implementation and Safety

Project Background

- High Pedestrian Crash Location (2011)
- Pedestrian fatality in 2011
 - North crosswalk
 - Pedestrian crossing with signal
 - Hit & Run
- Community request for intersection improvements



Skewed intersection

Crash Data

Metropolitan Avenue At 71st Avenue, QN

Injury Summary, 2007-2011 (5 Years)

	Total	Severe	Fatalities	KSI	
	Injuries	Injuries		4	
Pedestrian	8	3	1	4	
Bicyclist	1	0	0	0	
Motor Vehicle Occupant	8	2	0	2	
Total	17	5	1	6	

Fatalities, 01/01/2007-8/19/2013: 1					
	T				
Pedestrian:			1		
Bicyclist:			0		
Motor Vehicle Occupant			0		

17 injuries (2007-11)


60% pedestrian injuries while crossing with signal (turning car failing to yield)

1 pedestrian fatality (2011)

Car traveling EB made left turn from Metropolitan on to 71st Ave; struck and killed pedestrian crossing in north crosswalk; hit & run




Proposal




Existing Parking

- Sample time lapse parking survey showed only small fraction of spaces occupied (both week and weekend days)
- Muni-meter data shows only 16% of parking occupied on the south curb east of 71st
 Ave (71 Ave-71 Rd) 45% south curb west of 71 Ave (71 Ave-70 Dr)
- Many businesses have parking lots along Metropolitan Ave




Benefits

- Provides safer pedestrian crossings
- Creates simpler, safer left turns
- Turn lanes reduce "back pressure" for left turning vehicles
- Improves through traffic flow and eases congestion



Existing and Proposed Design







Contact:

Queens Borough Commissioner's Office at qbc@dot.nyc.gov or 212-839-2510