

Cooper Ave/73rd Pl/78th Ave




Commissioner Janette Sadik-Khan, New York City Department of Transportation
Presented to Community Board 5, April 24th, 2012
Pedestrian Projects Group



Project Location




I.S. 119
THE GLENDALE



NORTH

Project Background

- CB5 requested pedestrian safety improvements.
- I.S.119 is East of intersection of 73rd PI and 78th Ave.
- Many students cross intersection daily to and from school.
- Irregular, offset intersection: Cooper Ave and 78th Ave both T into 73rd PI.
- Truck route on Cooper Ave connecting through 73rd PI.






Large number of pedestrians crossing where there is no crosswalk.



Pedestrian Counts

No crosswalk at point
of highest volume


Mostly children
crossing after I.S. 119
lets out



March 20
Midday/PM
Midday (2:15-3:15)
PM (4:30-5:30)

Cooper Ave Proposal

New island for pedestrian safety + blocks straight movement from 78th Avenue



Shorten crossing with expanded curb

New Crosswalk

www.nyc.gov/dot

**Thank
You**