## **Union Avenue – East 166th Street Quick Facts**









**277**Residents


**120** Apartments

**b** Buildings

37 Boilers


**O** Elevator

Part of Union Avenue Consolidated



## **Major Repair Costs: Union Avenue – East 166<sup>th</sup> Street**





- Bathrooms
- Floor
- Ceiling
- Stairs
- Windows
- Ramps
- Flectrical
- Heating
- · Hot water
- Playgrounds
- · Parking lots
- Sidewalks

## **Total Repair Cost Per Unit**



Lead Test: Depending on finding from PACT inspections, a lead abatement plan will be included as part of the PACT project at Union Ave. - E 166th St.

Data reflects five-year physical needs assessment (2017)